

Pay Estimate Created Date: April 16, 2024

Progress Estimate Number	Contract ID	231117-F01	Pay Period Sta	rt April 2, 2024	Original Contract Amount	\$18,458,387.36
6	Prime Contracto	r Gershenson Construction Co., I	nc. Pay Period En	d April 15, 2024	4 Net Change Order Amount	\$0.00
0					Current Contract Amount	\$18,458,387.36

Approval Date		By User
April 16, 2024	Generated and Approved (and should be considered Draft) at the Project Office Level by	thursw1
April 17, 2024	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	amburs1
April 18, 2024	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Original Completion Date Current Completion Date		% of Current Contract Amount Complete		
October 1, 2025	October 1, 2025		8.74%		

	Milestones					
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract			
Acceptance Date						
Awarded Date	December 6, 2023	December 6, 2023				
Letting Date	November 17, 2023	November 17, 2023				
Notice to Proceed Date	January 8, 2024	January 8, 2024				
Open to Traffic Date						
Work Began Date	January 8, 2024	January 8, 2024				

Contract Total P	ay For Estimate No. 6			
		This Estimate	Previous	To Date
231117-F01				
	Total Posted Items Pay	\$176,414.57	\$1,437,521.91	\$1,613,936.48
	Gross Item Adjustments	\$19,031.25	\$120,941.75	\$139,973.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$1,558,463.66	\$1,753,909.48
Contract Total Pa	ayable This Estimate:	\$195.445.82		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3280	0070	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$13.600	840.88	\$11,435.97
	0800	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$16.000	78	\$1,248.00
	0140	6042010	ADJUSTING MANHOLE	EA	\$200.000	1	\$200.00
	0150	6042020	ADJUSTING BASIN OR INLET	EA	\$200.000	4	\$800.00
	0190	6049902	MISC.CURB INLET TOP REPAIR/REPLACEMENT	EA	\$500.000	1	\$500.00
	0210	6081012	TRUNCATED DOMES	SQFT	\$38.000	10	\$380.00
	0260	6085008	PAVED APPROACH, 8 IN.	SQYD	\$117.000	386.2	\$45,185.40
	0270	6086004	CONCRETE SIDEWALK, 4 IN.		\$58.000	353.58	\$20,507.64
	0280	6089902	MISC.ADA CURB RAMP	EA	\$1,700.000	15	\$25,500.00
	0290	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	LF	\$46.000	10	\$460.00
	0300	6091052	CURB AND GUTTER TYPE B	LF	\$57.000	537.8	\$30,654.60
	0500	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	EA	\$3,300.000	1	\$3,300.00
	0800	8031000A	TURF TYPE TALL FESCUE SODDING	SQYD	\$12.000	1,750	\$21,000.00
	0840	8061007A	CURB INLET CHECK	EA	\$25.000	8	\$200.00
	1080	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	LF	\$17.630	6	\$105.78
	1160	9028810	PULL BOX, PREFORMED CLASS 1	EA	\$1,470.000	1	\$1,470.00
	1170	9028811	PULL BOX, PREFORMED CLASS 2	EA	\$2,400.000	1	\$2,400.00
	1190	9029100	BASE, CONCRETE	CUYD	\$2,092.000	0.84	\$1,757.28
	1270	9029902	MISC.ADJUSTING PULL BOX AND FRAME REPLACEMENT	EA	\$1,116.000	1	\$1,116.00

Revision 3/23/2023 Page 1 of 24



Pay Estimate Created Date: April 16, 2024

F	Progress Estimate Number	Contract ID	231117-F01	Pay Period Star	t April 2, 2024	Original Contract Amount	\$18,458,387.36
	6	Prime Contracto	r Gershenson Construction Co., Ir	c. Pay Period End	April 15, 2024	Net Change Order Amount	\$0.00
	0					Current Contract Amount	\$18,458,387.36

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount								
J6S3280	1380	9105200	CONDUIT, 2 IN., RIGID, IN TRENCH	LF	\$15.300	19	\$290.70								
	1410	9109902	MISC.CONDUIT SYSTEM ADJUSTMENT OR REPAIR	EA	\$530.000	1	\$530.00								
	1420	9109902	MISC.FUSION SPLICE	EA	\$71.000	38	\$2,698.00								
	1460	9109902	MISC.ITS PULL BOX WITH CONCRETE PAD, PREFORMED CLASS 5	EA	\$2,725.000	1	\$2,725.00								
	1490	9109902	MISC.SM FIBER OPTIC JUMPER	EA	\$26.000	4	\$104.00								
	1500	9109902	MISC.SM FIBER OPTIC PIGTAIL	EA	\$26.000	4	\$104.00								
	1510	9109902	MISC.WALL-MOUNT FIBER INTERCONNECT CENTER	EA	\$1,150.000	1	\$1,150.00								
	1540	9109903	MISC.RELOCATE FIBER OPTIC CABLE, 24 STRAND, SINGLE MODE	LF	\$4.700	126	\$592.20								
Project J6S3280 - Total															
Overall - T	otal					Overall - Total									

Contract Adjustments This Estimate

nio ot	Line	Itam Description	A divistment	Other Item	Comments	A directment	Line Item	Adiustment
oject mber	Line No.	Item Description	Adjustment Type	Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3280	0070	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-5,202.28	\$13.60	(\$70,751.01
	0070	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user thursw1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	5,202.28	\$13.60	\$70,751.01
	0800	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-211.6	\$16.00	(\$3,385.60
	0080	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	211.6	\$16.00	\$3,385.60
	0260	PAVED APPROACH, 8 IN.	Material			-1,720.6	\$117.00	(\$201,310.20
	0260	PAVED APPROACH, 8 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user thursw1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	1,720.6	\$117.00	\$201,310.20
	0270	CONCRETE SIDEWALK, 4 IN.	Material			-3,150.75	\$58.00	(\$182,743.50
	0270	CONCRETE SIDEWALK, 4 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user thursw1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	3,150.75	\$58.00	\$182,743.50
	0290	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material			-947	\$46.00	(\$43,562.00
	0290	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user thursw1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	947	\$46.00	\$43,562.00
	0300	CURB AND GUTTER TYPE B	Material			-1,418.2	\$57.00	(\$80,837.40
	0300	CURB AND GUTTER TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user thursw1 overridding Payment Estimate Exception 13	1,418.2	\$57.00	\$80,837.40

Revision 3/23/2023 Page 2 of 24



Pay Estimate Created Date: April 16, 2024

Progress Estimate Number
6
Contract ID 231117-F01 Pay Period Start April 2, 2024 Original Contract Amount \$18,458,387.36
Prime Contractor Gershenson Construction Co., Inc. Pay Period End April 15, 2024 Net Change Order Amount \$0.00
Current Contract Amount \$18,458,387.36

Project umber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
S3280					on the current Payment Estimate.			
	0340	MISC.	Material			-144	\$85.00	(\$12,240.00
	0340	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user thursw1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	144	\$85.00	\$12,240.00
	0470	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)	Material			-5	\$1,470.00	(\$7,350.00
	0470	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user thursw1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	5	\$1,470.00	\$7,350.00
	0750	12 IN. PIPE GROUP A	Material			-65	\$115.00	(\$7,475.00
	0750	12 IN. PIPE GROUP A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user thursw1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	65	\$115.00	\$7,475.00
	0770	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	Material			-10	\$1,050.00	(\$10,500.00
	0770	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user thursw1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	10	\$1,050.00	\$10,500.00
	0790	12 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material			-6	\$1,125.00	(\$6,750.00
	0790	12 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user thursw1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	6	\$1,125.00	\$6,750.00
	1080	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material			-6	\$17.63	(\$105.78
	1080	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	6	\$17.63	\$105.78
	1160	PULL BOX, PREFORMED CLASS 1	Material			-1	\$1,470.00	(\$1,470.00
	1160	PULL BOX, PREFORMED CLASS 1	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user thursw1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	1	\$1,470.00	\$1,470.00
	1170	PULL BOX, PREFORMED CLASS 2	Material			-1	\$2,400.00	(\$2,400.00
	1170	PULL BOX, PREFORMED CLASS 2	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user thursw1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	1	\$2,400.00	\$2,400.00
	1190	BASE, CONCRETE	Material			-0.84	\$2,092.00	(\$1,757.28
	1190	BASE, CONCRETE	Material		This adjustment offsets the original system-	0.84	\$2,092.00	\$1,757.28

Revision 3/23/2023 Page 3 of 24



Pay Estimate Created Date: April 16, 2024

Progress Estimate Number
6
Contract ID 231117-F01 Pay Period Start April 2, 2024 Original Contract Amount \$18,458,387.36
Prime Contractor Gershenson Construction Co., Inc. Pay Period End April 15, 2024 Net Change Order Amount \$0.00
Current Contract Amount \$18,458,387.36

roject umber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
S3280					generated Material Payment Estimate Item Adjustment (0016) due to user thursw1 overridding Payment Estimate Exception 24 on the current Payment Estimate.			
	1270	MISC.	Material			-1	\$1,116.00	(\$1,116.00
	1270	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user thursw1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	1	\$1,116.00	\$1,116.00
	1300	2 IN. PSST POST - 12 GA.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$6,654.48
	1310	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$936.51
	1320	2.5 IN. PSST POST - 12 GA.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$3,539.20
	1330	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$2,525.46
	1340	SH-FLAT SHEET	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$4,068.90
	1340	SH-FLAT SHEET	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$1,306.70
	1380	CONDUIT, 2 IN., RIGID, IN TRENCH	Material			-19	\$15.30	(\$290.70
	1380	CONDUIT, 2 IN., RIGID, IN TRENCH	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user thursw1 overridding Payment Estimate Exception 27 on the current Payment Estimate.	19	\$15.30	\$290.70
	1410	MISC.	Material			-1	\$530.00	(\$530.00
	1410	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user thursw1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	1	\$530.00	\$530.00
	1420	MISC.	Material			-38	\$71.00	(\$2,698.00
	1420	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0025) due to user thursw1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	38	\$71.00	\$2,698.00
	1460	MISC.	Material			-1	\$2,725.00	(\$2,725.00
	1460	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user thursw1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	1	\$2,725.00	\$2,725.00
	1490	MISC.	Material			-4	\$26.00	(\$104.00
	1490	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user thursw1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	4	\$26.00	\$104.00
	1500	MISC.	Material			-4	\$26.00	(\$104.00
	1500	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0028) due to user thursw1 overridding Payment Estimate Exception 32	4	\$26.00	\$104.00

Revision 3/23/2023 Page 4 of 24



Pay Estimate Created Date: April 16, 2024

Progress Estimate Number

6

Contract ID 231117-F01 Pay Period Start April 2, 2024 Original Contract Amount \$18,458,387.36 Prime Contractor Gershenson Construction Co., Inc. Pay Period End April 15, 2024 Net Change Order Amount \$0.00 Current Contract Amount \$18,458,387.36

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3280					on the current Payment Estimate.			
	1510	MISC.	Material			-1	\$1,150.00	(\$1,150.00)
	1510	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user thursw1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	1	\$1,150.00	\$1,150.00
	1540	MISC.	Material			-126	\$4.70	(\$592.20)
	1540	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0030) due to user thursw1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	126	\$4.70	\$592.20
Total								\$19,031.25

Revision 3/23/2023 Page 5 of 24



					(Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J6S3280	FAF-67-3(134)	Bridge replacement, resurface, and ADA improvements	67	ST LOUIS	from Route D (Page	Ave) to Swan Ave.	
Γotals by J	Job Numbers						
J6S3280					This Estimate	Previous	To Date
	Posted Iten	n Pay			\$176,414.57	\$1,437,521.91	\$1,613,936.48
	Gross Item	Adjustments			\$19,031.25	\$120,941.75	\$139,973.00
		Gro	ss Item F	Pay	\$195,445.82	\$1,558,463.66	\$1,753,909.48
	Incentive				\$0.00	\$0.00	\$0.00
	Disincentiv	е			\$0.00	\$0.00	\$0.00
	Liquidated				\$0.00	\$0.00	\$0.00

Revision 3/23/2023 Page 6 of 24



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 3040504, Project Item Line Number 0070, Material Set 304050496, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 3040506, Project Item Line Number 0080, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 3040506, Project Item Line Number 0080, Material Set 304050696, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 6085008, Project Item Line Number 0260, Material Set 608500896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 6085008, Project Item Line Number 0260, Material Set 608500896, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 6085008, Project Item Line Number 0260, Material Set 608500896, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 6085008, Project Item Line Number 0260, Material Set 608500896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 6086004, Project Item Line Number 0270, Material Set 608600496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 6086004, Project Item Line Number 0270, Material Set 608600496, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 6086004, Project Item Line Number 0270, Material Set 608600496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 6091010, Project Item Line Number 0290, Material Set 609101096, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 6091010, Project Item Line Number 0290, Material Set 609101096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 6091052, Project Item Line Number 0300, Material Set 609105296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 6091052, Project Item Line Number 0300, Material Set 609105296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 6091052, Project Item Line Number 0300, Material Set 609105296, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 6099903, Project Item Line Number 0340, Material Set 6099903, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 6141120, Project Item Line Number 0470, Material Set 614112096, Material 0614DFGTCV - Curved Vane Grate and Frame, Acceptance Action Generic 0614DFGTCV is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 7261012, Project Item Line Number 0750, Material Set 726101296, Material 1026CPRCC3.012 - Reinf Conc Culv Pipe Cl3 12" (300 mm), Acceptance Action Generic 1026CPRCC3.012 is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 7311022, Project Item Line Number 0770, Material Set 731102296, Material 1033DIRCPK - Precast Conc Drop Inlet, Acceptance Action Generic 1033DIRCPK is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 7320612A, Project Item Line Number 0790, Material Set 7320612A96, Material 1032ESRCF - Conc End Section for Round Pipe, Acceptance Action Generic 1032ESRCF is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 9025300, Project Item Line Number 1080, Material Set 902530096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 9028810, Project Item Line Number 1160, Material Set 902881096, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 9028811, Project Item Line Number 1170, Material Set 902881196, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 9029100, Project Item Line Number 1190, Material Set 902910096, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden

Revision 3/23/2023 Page 7 of 24



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
@, Acceptance Action Generic ReSteelBars is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 9029100, Project Item Line Number 1190, Material Set 902910096, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 9029902, Project Item Line Number 1270, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 9105200, Project Item Line Number 1380, Material Set 910520096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 9109902, Project Item Line Number 1410, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 9109902, Project Item Line Number 1420, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 9109902, Project Item Line Number 1460, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 9109902, Project Item Line Number 1490, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 9109902, Project Item Line Number 1500, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 9109902, Project Item Line Number 1510, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3280, Item 9109903, Project Item Line Number 1540, Material Set 9109903, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	Working with MoDOT Materials & QC to enter the correct sample records with testing.	thursw1	Overridden

Revision 3/23/2023 Page 8 of 24



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted amo Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
31117-F01	J6S3280	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$1,300,000.00	\$390,000.00
		0001	0020	2035500	EMBANKMENT IN PLACE	145.00	0.00	145.00	CUYD	0.00	\$61.00	\$0.00
		0001	0030	2063000	CLASS 3 EXCAVATION	141.00	0.00	141.00	CUYD	44.70	\$30.00	\$1,341.00
		0001	0040	2063500	CULVERT CLEANOUT	26.00	0.00	26.00	EA	0.00	\$100.00	\$0.00
		0001	0050	2079909	MISC.MODIFIED LINEAR GRADING CLASS 2	476.80	0.00	476.80	STA	72.50	\$2,170.00	\$157,325.00
		0001	0060	2153000	SHAPING SLOPES, CLASS III	17.00	0.00	17.00	100F	0.00	\$1,880.00	\$0.00
		0001	0070	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	31,181.00	0.00	31,181.00	SQYD	5,302.68	\$13.60	\$72,116.45
		0001	0080	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	1,202.00	0.00	1,202.00	SQYD	211.60	\$16.00	\$3,385.60
		0001	0090	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	1,971.90	0.00	1,971.90	TONS	0.00	\$135.00	\$0.00
		0001	0100	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	25,221.40	0.00	25,221.40	TONS	0.00	\$154.00	\$0.00
		0001	0110	4031057	ASPHALT PERFORMANCE TESTING REPORTING	1.00	0.00	1.00	LS	0.00	\$6,500.00	\$0.00
		0001	0120	4071007	TACK COAT - NON-TRACKING	28,333.00	0.00	28,333.00	GAL	0.00	\$3.50	\$0.00
		0001	0130	5041000	CONCRETE APPROACH PAVEMENT	207.50	0.00	207.50	SQYD	0.00	\$192.00	\$0.00
		0001	0140	6042010	ADJUSTING MANHOLE	55.00	0.00	55.00	EA	4.00	\$200.00	\$800.00
		0001	0150	6042020	ADJUSTING BASIN OR INLET	36.00	0.00	36.00	EA	6.00	\$200.00	\$1,200.00
		0001	0160	6044011	PIPE COLLAR, TYPE A	3.00	0.00	3.00	EA	0.00	\$1,115.00	\$0.00
		0001	0170	6049902	MISC.ADJUSTING VALVES	100.00	0.00	100.00	EA	3.00	\$50.00	\$150.00
		0001	0180	6049902	MISC.CONCRETE MANHOLE COLLAR	23.00	0.00	23.00	EA	0.00	\$500.00	\$0.00
		0001	0190	6049902	MISC.CURB INLET TOP REPAIR/REPLACEMENT	42.00	0.00	42.00	EA	7.00	\$500.00	\$3,500.00
		0001	0200	6049903	MISC.GRATED INLET REPAIR/REPLACEMENT	17.00	0.00	17.00	LF	0.00	\$500.00	\$0.0
		0001	0210	6081012	TRUNCATED DOMES	2,280.00	0.00	2,280.00	SQFT	146.00	\$38.00	\$5,548.00
		0001	0220	6082024	HAND-RAILING FOR STEPS WITH BALUSTERS	18.00	0.00	18.00	LF	0.00	\$294.00	\$0.00
		0001	0230	6083006	6 IN. CONCRETE MEDIAN STRIP	155.00	0.00	155.00	SQYD	0.00	\$216.00	\$0.0
		0001	0240	6084024	SIDEWALK HAND-RAILING WITH BALUSTERS	178.00	0.00	178.00	LF	0.00	\$250.00	\$0.0
		0001	0250	6085007	PAVED APPROACH, 7 IN.	875.00	0.00	875.00	SQYD	0.00	\$115.00	\$0.0
		0001	0260	6085008	PAVED APPROACH, 8 IN.	8,347.60	0.00	8,347.60	SQYD	1,751.00	\$117.00	\$204,867.0
		0001	0270	6086004	CONCRETE SIDEWALK, 4 IN.	21,829.60	0.00	21,829.60	SQYD	3,150.75	\$58.00	\$182,743.50
		0001	0280	6089902	MISC.ADA CURB RAMP	320.00	0.00	320.00	EA	39.00	\$1,700.00	\$66,300.0
		0001	0290	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	3,883.00	0.00	3,883.00	LF	963.00	\$46.00	\$44,298.0
		0001	0300	6091052	CURB AND GUTTER TYPE B	6,692.00	0.00	6.692.00	LF	1,628.20	\$57.00	\$92,807.4
		0001	0310	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	116.00	0.00	116.00	CUYD	0.00	\$58.00	\$0.00
		0001	0320	6096042	PLACING TYPE 2 ROCK DITCH LINER	116.00		116.00		0.00	\$48.00	\$0.0
		0001	0330	6097000	ROCK LINING	21.00	0.00	21.00	CUYD	0.00	\$300.00	\$0.0
		0001	0340	6099903	MISC.VARIABLE HEIGHT CURB	4.700.00	0.00	4,700.00	LF	144.00	\$85.00	\$12,240.0
		0001	0350	6122008	IMPACT ATTENUATOR 40 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.00
		0001	0360	6122020	REPLACEMENT SAND BARREL	18.00	0.00	18.00	EA	0.00	\$200.00	\$0.0
			0370	6122030	IMPACT ATTENUATOR (RELOCATION)	4.00	0.00	4.00	EA	0.00	\$500.00	\$0.0
		0001	0370	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$0.0
		0001	0390	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL	570.70	0.00	570.70	SQYD	0.00	\$440.00	\$0.0
		0001	0390	6131010	DEPTH PAVEMENT REPAIR	570.70	0.00	570.70	SQYD	0.00	\$440.00	\$0.0
		0001	0400	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	571.00	0.00	571.00	SQYD	0.00	\$1.00	\$0.0
		0001	0410	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	571.00	0.00	571.00	SQYD	0.00	\$1.00	\$0.00
		0001	0420	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	1,624.00	0.00	1,624.00	LF	0.00	\$12.00	\$0.00
		0001	0430	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	512.00	0.00	512.00	EA	0.00	\$1.00	\$0.0
		0001	0440	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	28.00	0.00	28.00	EA	0.00	\$1.00	\$0.00
		0001	0450	6133018	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR	532.00	0.00	532.00	TONS	0.00	\$235.00	\$0.00

Revision 3/23/2023 Page 9 of 24



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
31117-F01	J6S3280	0001	0460	6133019	REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	3,285.60	0.00	3,285.60	SQYD	0.00	\$24.00	\$0.0
		0001	0470	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)	8.00	0.00	8.00	EA	5.00	\$1,470.00	\$7,350.0
		0001	0480	6143014	MANHOLE FRAME AND COVER, TYPE 4	1.00	0.00	1.00	EA	0.00	\$530.00	\$0.0
		0001	0490	6169901	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.25	\$100,000.00	\$25,000.0
		0001	0500	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	12.00	0.00	12.00	EA	2.00	\$3,300.00	\$6,600.0
		0001	0510	6171000	CONCRETE TRAFFIC BARRIER, TYPE A	195.00	0.00	195.00	LF	0.00	\$250.00	\$0.0
		0001	0520	6173103	CONCRETE TRAFFIC BARRIER, TYPE D (MOMENT SLAB)	28.00	0.00	28.00	LF	0.00	\$700.00	\$0.0
		0001	0530	6173200	CONCRETE TRAFFIC BARRIER, TYPE E	110.00	0.00	110.00	LF	0.00	\$282.00	\$0.0
		0001	0540	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	125.00	0.00	125.00	LF	0.00	\$25.00	\$0.0
		0001	0550	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$1,850,000.00	\$0.0
		0001	0551	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.50	\$1,739,152.00	\$869,576.0
		0001	0560	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	2.00	0.00	2.00	EA	0.00	\$600.00	\$0.0
		0001	0570	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	3,810.00	0.00	3,810.00	LF	0.00	\$7.05	\$0.0
		0001	0580	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	1,165.00	0.00	1,165.00	LF	0.00	\$23.51	\$0.0
		0001	0590	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING,	86.00	0.00	86.00	EA	0.00	\$329.11	\$0.0
		0001	0600	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING,	1.00	0.00	1.00	EA	0.00	\$587.70	\$0.0
		0001	0610	6200036	COMBINATION STR/LT/RT PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN	434.00	0.00	434.00	EA	0.00	\$211.57	\$0.0
		0001	0620	6200042	WHITE MIDBLOCK PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN	122.00	0.00	122.00	EA	0.00	\$76.40	\$0.0
		0001	0630	6205901A	WHITE, YIELD LINE TRIANGLES 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	65,573.00	0.00	65,573.00	LF	0.00	\$0.29	\$0.0
		0001	0640	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING	122,350.00	0.00	122,350.00	LF	0.00	\$0.29	\$0.0
		0001	0650	6205906A	PAINT, TYPE L BEADS 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,847.00	0.00	2,847.00	LF	0.00	\$1.18	\$0.0
		0001	0660	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$500.00	\$0.0
		0001	0670	6209902	MISC.18 IN. WHITE ISLAND TUBULAR MARKERS	41.00	0.00	41.00	EA	0.00	\$94.03	\$0.0
		0001	0680	6209902	MISC.CURB REFLECTORS	340.00	0.00	340.00	EA	0.00	\$29.38	\$0.0
		0001	0690	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	283,330.00	0.00	283,330.00	SQYD	0.00	\$3.17	\$0.0
		0001	0700	6240103A	SURFACING (3 IN. THICK OR LESS) PERMANENT EROSION CONTROL GEOTEXTILE	62.00	0.00	62.00	SQYD	0.00	\$5.69	\$0.0
		0001	0710	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.10	\$17,388.19	\$1,738.8
		0001	0720	7032002	CLASS B CONCRETE (MISC)	105.30	0.00	105.30	CUYD	0.00	\$430.00	\$0.0
		0001	0730	7069902	MISC.6.5 FT X 4 FT DRAINAGE FLUME	1.00	0.00	1.00	EA	1.00	\$6,675.00	\$6,675.0
		0001	0740	7101000	REINFORCING STEEL (EPOXY COATED)	3,140.00	0.00	3,140.00	LB	0.00	\$2.30	\$0.0
		0001	0750	7261012	12 IN. PIPE GROUP A	386.00	0.00	386.00	LF	65.00	\$115.00	\$7,475.0
		0001	0760	7269903	MISC.10 IN. SMOOTH WALL PIPE WITH FILTER SOCK	193.00	0.00	193.00	LF	0.00	\$66.00	\$0.0
		0001	0770	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	14.00	0.00	14.00	FT	10.00	\$1,050.00	\$10,500.0
		0001	0780	7319902	MISC.MANHOLE TOP REPLACEMENT	1.00	0.00	1.00	EA	0.00	\$6,830.00	\$0.0
		0001	0790	7320612A	12 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END	7.00	0.00	7.00	EA	6.00	\$1,125.00	\$6,750.0
		0001	0800	8031000A	SECTION TURF TYPE TALL FESCUE SODDING	16,500.00	0.00	16,500.00	SQYD	1,750.00	\$12.00	\$21,000.0
		0001	0810	8051000A	SEEDING - COOL SEASON GRASSES	1.00	0.00	1.00	ACRE	0.00	\$5,700.00	\$0.0
		0001	0820	8061005	ROCK DITCH CHECK	150.00	0.00	150.00	LF	0.00	\$5.00	\$0.0
		0001	0830	8061006	ALTERNATE DITCH CHECK	300.00	0.00	300.00	LF	0.00	\$5.00	\$0.0
		0001	0840	8061007A	CURB INLET CHECK	258.00	0.00	258.00	EA	27.00	\$25.00	\$675.0
		0001	0850	8061016	SEDIMENT REMOVAL	310.00	0.00	310.00	CUYD	0.00	\$1.00	\$0.0
		0001	0860	8061019	SILT FENCE	1,536.00	0.00	1,536.00	LF	0.00	\$4.70	\$0.0
			MGS GUARDRAIL	3,550.00	0.00	3,550.00	LF	0.00	\$38.00	\$0.0		

Revision 3/23/2023 Page 10 of 24



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract n.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
1117-F01	J6S3280	0010	0880	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	13.00	0.00	13.00	LF	0.00	\$47.00	\$0.00
		0010	0890	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	3.00	0.00	3.00	EA	0.00	\$5,650.00	\$0.0
		0010	0900	6061070	MGS VERTICAL CONCRETE BARRIER TRANSITION	9.00	0.00	9.00	EA	0.00	\$5,400.00	\$0.0
		0010	0910	6061080	MGS END ANCHOR	13.00	0.00	13.00	EA	0.00	\$2,115.00	\$0.0
		0010	0920	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	21.00	0.00	21.00	EA	0.00	\$4,466.00	\$0.0
		0010	0930	6063022	TYPE E CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$45,800.00	\$0.0
		0020	0940	9011010	RELOCATED POLE	1.00	0.00	1.00	EA	0.00	\$1,765.00	\$0.0
		0020	0950	9011115	BRACKET ARM, 15 FT. OR 4.6 M	1.00	0.00	1.00	EA	0.00	\$1,765.00	\$0.0
		0020	0960	9011311	LUMINAIRE, LED-A	1.00	0.00	1.00	EA	0.00	\$294.00	\$0.0
		0020	0970	9017008	CABLE, 8 AWG 1 CONDUCTOR	50.00	0.00	50.00	LF	0.00	\$0.76	\$0.0
		0020	0980	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	1.00	0.00	1.00	EA	0.00	\$2,115.71	\$0.0
		0030	0990	9020213	SIGNAL HEAD, TYPE 3S	2.00	0.00	2.00	EA	0.00	\$1,880.00	\$0.0
		0030	1000	9020513	SIGNAL HEAD, TYPE 3B	11.00	0.00	11.00	EA	0.00	\$1,512.00	\$0.0
		0030	1010	9020833	SH-FLAT SHEET - SIGNAL SIGN	97.00	0.00	97.00	SQFT	0.00	\$41.00	\$0.0
		0030	1020	9020834	SIGNAL SIGN, MOUNTING HARDWARE	23.00	0.00	23.00	EA	0.00	\$141.00	\$0.0
		0030	1030	9022708	POST, SIGNAL 8 FT.	7.00	0.00	7.00	EA	0.00	\$1,210.00	\$0.0
		0030	1040	9023235	POST, TYPE C, 35 FT. ARM OR 10.7 M ARM	1.00	0.00	1.00	EA	0.00	\$12,840.00	\$0.0
		0030	1050	9023245	POST, TYPE C, 45 FT. ARM OR 13.7 M ARM	1.00	0.00	1.00	EA	0.00	\$14,400.00	\$0.0
		0030	1060	9023255	POST, TYPE C, 55 FT. ARM	2.00	0.00	2.00	EA	0.00	\$18,500.00	\$0.0
		0030	1070	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	1.00	0.00	1.00	EA	0.00	\$27,500.00	\$0.0
		0030	1080	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	116.00	0.00	116.00	LF	6.00	\$17.63	\$105.7
		0030	1090	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	457.00	0.00	457.00	LF	0.00	\$30.56	\$0.0
		0030	1100	9028100	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	150.00	0.00	150.00	LF	0.00	\$0.53	\$0.0
		0030	1110	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	410.00	0.00	410.00	LF	0.00	\$1.18	\$0.0
		0030	1120	9028302	CABLE, 12 AWG 2 CONDUCTOR	30.00	0.00	30.00	LF	0.00	\$1.47	\$0.0
		0030	1130	9028308	CABLE, 16 AWG 2 CONDUCTOR	5,630.00	0.00	5,630.00	LF	0.00	\$1.76	\$0.0
		0030	1140	9028310	CABLE, 16 AWG 5 CONDUCTOR	3,120.00	0.00	3,120.00	LF	0.00	\$2.06	\$0.0
		0030	1150	9028311	CABLE, 16 AWG 7 CONDUCTOR	3,310.00	0.00	3,310.00	LF	0.00	\$2.35	\$0.0
		0030	1160	9028810	PULL BOX, PREFORMED CLASS 1	4.00	0.00	4.00	EA	1.00	\$1,470.00	\$1,470.0
		0030	1170	9028811	PULL BOX, PREFORMED CLASS 2	4.00	0.00	4.00	EA	1.00	\$2,400.00	\$2,400.0
		0030	1180	9028812	PULL BOX, PREFORMED CLASS 3	1.00	0.00	1.00	EA	0.00	\$2,940.00	\$0.0
		0030	1190	9029100	BASE, CONCRETE	14.80	0.00	14.80	CUYD	0.84	\$2,092.00	\$1,757.2
		0030	1200	9029901	MISC.TRAFFIC SIGNAL MAINTENANCE AND PROGRAMMING	1.00	0.00	1.00	LS	0.00	\$15,280.00	\$0.0
		0030	1210	9029902	MISC.AUDIBLE PEDESTRIAN PUSHBUTTON AND SIGNING	24.00	0.00	24.00	EA	0.00	\$1,057.00	\$0.0
		0030	1220	9029902	MISC.COMBINATION PAD MOUNTED 120V/240V POWER	1.00	0.00	1.00	EA	0.00	\$14,700.00	\$0.0
					SUPPLY AND LIGHTING CONTROLLER WITH UPS							
		0030	1230	9029902	MISC.COUNTDOWN PEDESTRIAN SIGNAL HEAD, TYPE 1S	16.00	0.00	16.00	EA	0.00	\$650.00	\$0.0
		0030	1240	9029902	MISC.EXTENSIONS FOR PUSHBUTTON (14-INCH MAX)	7.00	0.00	7.00	EA	0.00	\$200.00	\$0.0
		0030	1250	9029902	MISC.PULL BOX REMOVE AND REPLACE	9.00	0.00	9.00	EA	0.00	\$1,645.00	\$0.0
		0030	1260	9029902	MISC.SL DISTRICT TRAFFIC SIGNAL DETECTION SYSTEM	10.00	0.00	10.00	EA	0.00	\$49,475.00	\$0.0
		0030	1270	9029902	MISC.ADJUSTING PULL BOX AND FRAME REPLACEMENT	35.00	0.00	35.00	EA	1.00	\$1,116.00	\$1,116.0
		0040	1280	9031010	CONCRETE FOOTINGS, EMBEDDED	0.30	0.00	0.30	CUYD	0.00	\$3,525.00	\$0.0
		0040	1290	9031210	STRUCTURAL STEEL POSTS	1,590.00	0.00	1,590.00	LB	0.00	\$10.60	\$0.0
		0040	1300	9031270A	2 IN. PSST POST - 12 GA.	699.00	0.00	699.00	LF	0.00	\$30.50	\$0.0
		0040	1310	9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	31.00	0.00	31.00	EA	0.00	\$294.00	\$0.0
		0040	1320	9031280	2.5 IN. PSST POST - 12 GA.	316.00	0.00	316.00	LF	0.00	\$33.00	\$0.0
		0040	1330	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	21.00	0.00	21.00	EA	0.00	\$411.00	\$0.0

Revision 3/23/2023 Page 11 of 24



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT No.	004	N	o. Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
231117-F01 J6S3	004	134	9035004A								
			000000111	SH-FLAT SHEET	411.00	0.00	411.00	SQFT	0.00	\$38.00	\$0.00
		135	9035011A	ST-STRUCTURAL	73.00	0.00	73.00	SQFT	0.00	\$45.00	\$0.00
	005	136	9027200	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	202.00	0.00	202.00	LF	0.00	\$37.00	\$0.00
	005	137	9103700	CCTV CAMERA ASSEMBLY, INSTALLED	1.00	0.00	1.00	EA	0.00	\$952.00	\$0.00
	005	138	9105200	CONDUIT, 2 IN., RIGID, IN TRENCH	1,117.00	0.00	1,117.00	LF	19.00	\$15.30	\$290.70
	005	139	9109901	MISC.ITS ASSET MANAGEMENT TOOL	1.00	0.00	1.00	LS	0.00	\$705.00	\$0.00
	005	140	9109902	MISC.CCTV CAMERA ASSEMBLY	1.00	0.00	1.00	EA	0.00	\$5,759.43	\$0.00
	005	141	9109902	MISC.CONDUIT SYSTEM ADJUSTMENT OR REPAIR	3.00	0.00	3.00	EA	1.00	\$530.00	\$530.00
	005	142	9109902	MISC.FUSION SPLICE	76.00	0.00	76.00	EA	38.00	\$71.00	\$2,698.00
	005	143	9109902	MISC.INSTALL MoDOT FURNISHED IP-ADDRESSABLE POWER STRIP	1.00	0.00	1.00	EA	0.00	\$141.00	\$0.00
	005) 144	9109902	MISC.INSTALL OR RELOCATE EXISTING COMMUNICATION	1.00	0.00	1.00	EA	0.00	\$470.00	\$0.00
	005) 145	9109902	EQUIPMENT MISC.ITS PULL BOX WITH CONCRETE PAD, PREFORMED	6.00	0.00	6.00	EA	0.00	\$2,400.00	\$0.00
				CLASS 2							
	005	146	9109902	MISC.ITS PULL BOX WITH CONCRETE PAD, PREFORMED CLASS 5	2.00	0.00	2.00	EA	1.00	\$2,725.00	\$2,725.00
	005	147	9109902	MISC.MODOT BURIED CABLE DRIVEABLE DELINEATOR POST	115.00	0.00	115.00	EA	0.00	\$123.00	\$0.00
	005	148	9109902	MISC.REMOVE IN-PAVEMENT WIRELESS DETECTION SYSTEM PER INTERSECTION	4.00	0.00	4.00	EA	0.00	\$2,915.00	\$0.00
	005	149	9109902	MISC.SM FIBER OPTIC JUMPER	12.00	0.00	12.00	EA	4.00	\$26.00	\$104.00
	005	150	9109902	MISC.SM FIBER OPTIC PIGTAIL	10.00	0.00	10.00	EA	4.00	\$26.00	\$104.00
	005	151	9109902	MISC.WALL-MOUNT FIBER INTERCONNECT CENTER	3.00	0.00	3.00	EA	1.00	\$1,150.00	\$1,150.00
	005	152	9109903	MISC.CABLE CCTV CAMERA (CAT-5e)	60.00	0.00	60.00	LF	0.00	\$1.76	\$0.00
	005	153	9109903	MISC.FIBER OPTIC CABLE, 24 STRAND, SINGLE MODE	1,490.00	0.00	1,490.00	LF	0.00	\$2.94	\$0.00
	005	154	9109903	MISC.RELOCATE FIBER OPTIC CABLE, 24 STRAND, SINGLE MODE	220.00	0.00	220.00	LF	126.00	\$4.70	\$592.20
	007) 155	2061000	CLASS 1 EXCAVATION	350.00	0.00	350.00	CUYD	0.00	\$178.00	\$0.00
	007) 156	5031010A	BRIDGE APPROACH SLAB (MAJOR)	321.00	0.00	321.00	SQYD	0.00	\$406.00	\$0.00
	007) 157	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	400.00	0.00	400.00	LF	0.00	\$220.00	\$0.00
	007) 158	7026000	PRE-BORE FOR PILING	320.00	0.00	320.00	LF	0.00	\$180.00	\$0.00
	007) 159	7027000	PILE POINT REINFORCEMENT	20.00	0.00	20.00	EA	0.00	\$150.00	\$0.00
	007) 160	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	115.80	0.00	115.80	CUYD	0.00	\$1,260.00	\$0.00
	007) 161	7033013	PENETRATING CONCRETE SEALER	73.00	0.00	73.00	SY	0.00	\$32.00	\$0.00
	007	162	7034219A	TYPE D BARRIER	125.00	0.00	125.00	LF	0.00	\$223.00	\$0.00
	007	163	7034222	SLAB ON CONCRETE BEAM	536.00	0.00	536.00	SQYD	0.00	\$820.00	\$0.00
	007	164	7034410	TYPE A BARRIER	103.00	0.00	103.00	LF	0.00	\$242.00	\$0.00
	007	165	7034430	SIDEWALK (BRIDGES)	1,315.00	0.00	1,315.00	SQFT	0.00	\$25.00	\$0.00
	007	166	7056049	21 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	607.00	0.00	607.00	LF	0.00	\$417.00	\$0.00
	007	167	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	0.00	\$14,100.00	\$0.00
	007	168	7079901	MISC.CONDUIT SYSTEM ON STRUCTURE AT&T	1.00	0.00	1.00	LS	0.00	\$96,970.00	\$0.00
	007	169	7123610	SLAB DRAIN	12.00	0.00	12.00	EA	0.00	\$610.00	\$0.00
	007	170	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$5,615.00	\$0.00
	007) 171	7161002	LAMINATED NEOPRENE BEARING PAD	10.00	0.00	10.00	EA	0.00	\$475.00	\$0.00
	007) 172	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	10.00	0.00	10.00	EA	0.00	\$660.00	\$0.00
	007	1 173	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	3.00	0.00	3.00	SQFT	0.00	\$1,410.00	\$0.00
	007	1 174	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.00	\$30,000.00	\$0.00
	007	1 175	2169904	MISC.REMOVAL OF EXISTING SUPERSTRUCTURE	3,262.00	0.00	3,262.00	SQFT	0.00	\$45.00	\$0.00
	007	1 176	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	6.40	0.00	6.40	CUYD	0.00	\$3,065.00	\$0.00
	007	1 177	7040110	EPOXY PRESSURE INJECTING	20.00	0.00	20.00	LF	0.00	\$88.00	\$0.00
	007	1 178	7061060	REINFORCING STEEL (BRIDGES)	890.00	0.00	890.00	LB	0.00	\$4.00	\$0.00

Revision 3/23/2023 Page 12 of 24



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
231117-F01	J6S3280	0071	1790	7129902	MISC.CORED WALLED DRAINS	20.00	0.00	20.00	EA	0.00	\$925.00	\$0.00
		0072	1800	7039902	MISC.END POST MODIFICATION	2.00	0.00	2.00	EA	0.00	\$18,850.00	\$0.00
		0001	5001	6189901	MISC.MOBILIZATION (Payment for Contract Bond)	0.00	1.00	1.00	LS	1.00	\$108,348.00	\$108,348.00
		0001	5002	6189901	MISC.MOBILIZATION (Payment for Railroad Liability Insurance)	0.00	1.00	1.00	LS	1.00	\$2,500.00	\$2,500.00
	Project J	6S3280 - To	tal Value	Posted to D	ate as of Report Generated Date							\$2,327,852.73
231117-F01 Ove	rall - Total	Value Post	ed to Dat	te as of Repo	ort Generated Date							\$2,327,852.73

Revision 3/23/2023 Page 13 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6S3280

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0070	3040504	TYPE 5 AGGREGATE FOR BASE	4/2/24	4/4/24	4.89		Under New Bus Pad at Polarity	336+40	RT RT	336+46		
				4/4/24	15.56	SQYD	28'X5' Under Sidewalk South Ramp for the entrance of Krilogy.	330+00	KI	330+28		
				4/4/24	32.33	SQYD	48.5'X6' Under sidewalk South of the entrance for optometric	335+70	RT	336+19		
			4/3/24	4/5/24	28.70	SQYD	135 N. Lindbergh	342+11	RC	342+97	RC	under line no. 0300 (86'X3')
				4/5/24	42.60	SQYD	221 N. Lindbergh (North half of approach) Norther entrance	339+25	RC			under line no. 0260
			4/4/24	4/5/24	4.60	SQYD	227 N. Lindbergh	337+00	RC	337+07	RC	7'x6' under line no. 0270
				4/5/24	19.70		between 135 N. Lindbergh & 211 N. Lindbergh	341+50	RC		RC	under line no. 0300 (59'X3')
				4/5/24	24.00 32.20	SQYD	227 N. Lindbergh 221 N. Lindbergh (sidewalk is North of the paved	337+37 335+40	RC RC	337+72 335+55	RC RC	36'X6' under line no. 0270 58'X5' under line no. 0270
				4/3/24	32.20	SQTD	approach, around the radius of the approach)	333740	NC	333+33	NC	
			415104	4/5/24		SQYD	135 N. Lindbergh (just South of the exit only entrance)	342+97	RC	344+52	RC	under line no. 0300 (155'X3')
			4/5/24	4/10/24	2.00	SQYD	South of 243 N. Lindbergh paved approach 135 N. Lindbergh (entire paved approach)	336+06 341+90	RC RC	336+12	RC	under line no. 0300 (6LF X 3') under line no. 0260
				4/10/24	68.40		243 N. Lindbergh (southern half of the paved approach)	335+70				under line no. 0260
			4/8/24	4/10/24	6.10	SQYD	From the resale shop heading south	328+55	RT	328+73	RT	under line no. 0300
				4/10/24	7.80		South of the approach at the vet center	329+20	RT	329+43	RT	under line no. 0300
				4/10/24	21.40	SQYD	Under South Half of the Paved Approach South Entrance of the Resale Shop	328+55	RT			
				4/10/24	25.60	SQYD	under South Half of the Approach at the Vet Shop	329+20	RC			
				4/10/24	49.60		under North half of the approach at Krilogy	330+00				
			4/9/24	4/12/24	30.68	SQYD	North half of approach @ Lawrence Dr South half of approach @ 227 N. Lindbergh	326+50 337+60	RC RC			under line no. 0260
				4/12/24	42.57	SQYD	South half of approach @ 211 N. Lindbergh	339+25	RC			
			4/10/24	4/16/24	30.40	SQYD	North half of approach @ 105 N. Lindbergh	344+80	RC			under line no. 0260
			4/11/24	4/15/24	7.70	SQYD	227 N. Lindbergh (heading North from the Northern curb ramp of the paved approach)	337+25	RC	337+35	RC	under line no. 0270
				4/15/24	15.00	SQYD	243 N. Lindbergh (heading South from the southern curb ramp of the paved approach)	335+90	RC	336+10	RC	under line no. 0270
				4/15/24	64.00			342+30	RC		RC	under line no. 0270 (this + the aggregated on line no. 0080 = 101.7 SQYD which is the total for sidewalk today.)
			4/12/24	4/15/24	36.30 69.60		135 N. Lindbergh 135 N. Lindbergh	342+81 343+50	RC RC	343+90 344+50	RC RC	under line no. 0300 under line no. 0270
			4/15/24			SQYD	Under sidewalk between Resale Shop and Veterans	328+70	RT	328+80		5'5" X 6'4" + 6'X5' + 5'2" X 6'5" + 5' X 6'2" + 83' X 6' =
				4/16/24	7.00	SQYD	Under Curb and Gutter @AT&T	343+53.65	DT	343+74.65	PT	
				4/16/24	20.00		@ Quailways intersection under Curb and gutter	320+05			RT	
0080	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	4/4/24	4/5/24	16.80	SQYD	227 N. Lindbergh (bump out)	336+97	RC	337+20	RC	6'X8' + 5'X4', +12'X7' under line no. 0270
				4/5/24	22.90		227 N. Lindbergh	337+07	RC	337+37	RC	10'X7, + 4'X5', + 6'X8', + 10'X7' = under line no. 0270
			4/11/24	4/15/24	15.00	SQYD	135 N. Lindbergh (bump out section) under line no. 0270 (part of the 79 SQYD total)	342+30	RC	342+50	RC	6' 9" X 4' 6" + 8' X 3' 6" + 5' X 4' + 8' X 3' 6" + 6' 9" + 4' 9" =
			4/15/24	4/16/24	23.30	SQYD		338+14.36	RT	338+40.86	RT	
0140		ADJUSTING MANHOLE	4/4/24	4/5/24	1.00		227 N. Lindbergh ((within the paved approach)	335+70				
0150	6042020	ADJUSTING BASIN OR INLET	4/3/24	4/5/24	1.00		135 N. Lindbergh ((just south of the approach,) 135 N. Lindbergh (curved vane grate in the shoulder that	342+30 342+90				
				4/5/24	2.00		is adjusted) 221 N. Lindbergh (within the 8" payed approach. There	339+25	RC.			
0190	6049902	MISC. DRAINAGE ITEM	4/3/24	4/5/24	1.00		are 2 grated inlets at this location.) 135 N. Lindbergh (curb inlet top replaced)	342+90				
0210		TRUNCATED DOMES	4/15/24	4/16/24	10.00	SQFT	South of Lawrence Dr	326+50	RT			
0260	6085008	PAVED APPROACH, 8 IN.	4/3/24	4/5/24	42.60	SQYD	221 N. Lindbergh (North half of approach) Norther entrance	339+25	RC			
			4/5/24	4/10/24		SQYD		341+90				
			4/8/24	4/10/24	68.40	SQYD	243 N. Lindbergh (southern half of the paved approach) South Half of the Paved Approach South Entrance of the	335+70 328+55			RT	
			4/0/24	4/10/24	21.40	SQTD	Resale Shop	328+33	KI		KI	
				4/10/24			South Half of the Approach at the Vet Shop	329+20				
			4/9/24	4/10/24 4/12/24			North half of the approach at Krilogy North half of approach @ Lawrence Dr	330+00 326+50				
				4/12/24			South half of approach @ 227 N. Lindbergh	337+60				
				4/12/24	42.57		South half of approach @ 211 N. Lindbergh	339+25				
	00	annabere orden	4/10/24	4/16/24			North half of approach @ 105 N. Lindbergh	344+80				
0270	6086004	CONCRETE SIDEWALK, 4 IN.	4/2/24	4/4/24		SQYD	New Bus Pad at Polarity 28'X5'	336+40 330+00		336+46 330+28		
				4/4/24			South Ramp for the entrance of Krilogy. 48.5'X6'	335+70		336+19		
			4/4/24				South of the entrance for optometric 221 N. Lindbergh (sidewalk is North of the paved	335+40		335+55	RC	58'X5'
				4/5/24	68 30	SOVE	approach, around the radius of the approach) 227 N. Lindbergh	337+00	RC	337+72	RC	
			4/11/24				227 N. Lindbergh 227 N. Lindbergh (heading North from the Northern curb ramp of the paved approach)	337+00		337+72		
				4/15/24	15.00	SQYD	243 N. Lindbergh (heading South from the southern curb ramp of the paved approach)	335+90	RC	336+10	RC	15' X 7' + 6' X 5' =
				4/15/24			135 N. Lindbergh	342+30		344+25		96' x 6' + 6' 9" X 4' 6" + 8' X 3' 6" + 5' X 4' + 8' X 3' 6" + 6' 9" + 4' 9" =
			4/12/24				135 N. Lindbergh	343+50		344+50		5'5" X 6'4" + 6'X5' + 5'2" X 6'5" + 5' X 6'2" + 83' X 6' =
			4/15/24	4/16/24		SQYD	5x6 North of 211 N Lindbergh 10"X5" Sidewalk between veterans Center and Resale Shop	339+00 328+70		339+05 328+80		
				4/16/24	9.40	SQYD	17X5 North of 211 N Lindbergh	339+00	RT	339+17	RT	
				4/16/24	10.80	SQYD	19.5'X10.8' between Veterans center and Lawrence Drive	329+50	RT	329+69.5	RT	
0280	6089902	MISC. CONCRETE	4/2/24	4/4/24	1.00	EA	North of the approach at kind body	321+50	RT			

Revision 3/23/2023 Page 14 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line umber	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0280	6089902	MISC. CONCRETE	4/2/24	4/4/24	1.00	EA	North side of the south entrance of the resale shop.	328+65	RT			
				4/4/24	1.00	EA	South Entrance to Jos A Bank North Curb Ramp	325+80	RT			
				4/4/24	1.00	EA	South Ramp at the resale shop	328+45	RT			
				4/4/24	1.00	EA	South Ramp for the entrance of Krilogy.	330+00	RT			
				4/4/24	1.00	EA	South of the entrance for optometric	335+70	RT			
			4/11/24	4/15/24	1.00	EA	227 N. Lindbergh (North of the paved approach)	337+35	RC			
				4/15/24	1.00	EA	227 N. Lindbergh (South of the paved approach)	337+84	RC			
				4/15/24	1.00	EA	243 N. Lindbergh (south of the paved approach)	335+90	RC			
			4/15/24	4/16/24	1.00	EA		326+50	RT			
				4/16/24	1.00	EA	North of 211 N Lindbergh	339+00	RT			
				4/16/24	2.00	FA	Between Lawrence and Veterans center	329+50	RT			
				4/16/24	2.00	FA	small sidewalk between veterans center and resale shop	328+70	RT			
0290	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER)	4/15/24	4/16/24	10.00	LF	Sidewalk between Resale Shop and Veterans Center	328+70		328+80	RT	
0300	6091010	CURB AND GUTTER TYPE B	4/3/24	4/5/24	86.00	LF	135 N. Lindbergh	342+11	RC	342+97	RC	
3300	3001032	OSAS AND SOTTEN THE B	4/4/24	4/5/24	59.00	LF	*	341+50		342+09	RC	
			4/4/24	4/5/24	155.00	LF	* *				rc	
			4/5/24	4/10/24		LF	135 N. Lindbergh (just South of the exit only entrance)	342+97	rc RC	344+52 336+12		
					6.00	-	South of 243 N. Lindbergh paved approach	336+06			RC	
			4/8/24	4/10/24	18.30	LF		328+55	RT	328+73.3		
				4/10/24	23.50	LF	South of the approach at the vet center	329+20		329+43.5		
			4/12/24		109.00		135 N. Lindbergh	342+81	RC	343+90	RC	
			4/15/24	4/16/24	21.00	LF	@ AT&T	343+53.65			RT	
				4/16/24	60.00	LF	• •	320+05		320+65	RT	
0500		MISC. TRAFFIC CONTROL DEVICES	4/15/24	4/16/24	1.00	EA	North Side of Thornwood Dr.	405+15	LT			
0800	8031000A	TURF TYPE TALL FESCUE SODDING	4/8/24	4/10/24	1,260.00	SQYD	North of Oxford Hill> Lou Fusz Kia SB 61/67	239+00				
			4/10/24	4/16/24		SQYD	Lou Fusz Kia> Quailways intersection (just North of the intersection)	269+50	RC	321+50	RC	
0840		CURB INLET CHECK	4/5/24	4/10/24	8.00		SB 61/67 Quailways> Lawernce Dr.	334+00	RC	326+50	RC	
1080	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	4/8/24	4/10/24	6.00		PB 1> P 1 (NW quadrant of Quailways/Lindbergh)	319+78		319+75	RC	
1160		PULL BOX, PREFORMED CLASS 1	4/15/24	4/16/24	1.00	EA	Schuetz/Lindbergh	236+59	RC			NW island / PB #1
1170		PULL BOX, PREFORMED CLASS 2	4/8/24	4/10/24	1.00	EA		319+78	RC			
1190	9029100	BASE, CONCRETE	4/5/24	4/10/24	-0.04	CUYD	Rounding to correct unit @ Quailways/Tealbrook					
				4/10/24	0.44	CUYD	P #1 @ Quailways/Tealbrook	319+75	RC			NE quadrant
			4/15/24	4/16/24	0.44	CUYD	Schuetz/Lindbergh	236+59	RC			NW island / P #1
1270	9029902	MISC.	4/15/24	4/16/24	1.00	EA	Quailways/Lindbergh	320+30	RC			SW corner (discovered an old 2X2 pullbox not noted of the plans. Had to remove this box due to it being in the way of the to be installed sidewalk.
1380	9105200	CONDUIT, 2 IN., RIGID, IN TRENCH	4/8/24	4/10/24	8.00		PB #2> Conduit Intercepts / SW quadrant at Quailways/Lindbergh	320+36		320+40		
				4/10/24	11.00	LF	C.A> PB #2 / SW quadrant at Quailways/Lindbergh	320+53	RC	320+62	RC	
1410	9109902	MISC. ITS	4/15/24	4/16/24	1.00	EA	Quailways/61-67	320+45	RC			This is for the extra fiber work that was needing a new bore shot due to the shallow conduit North of Kindbod approach (343 N. Lindbergh)
1420	9109902	MISC. ITS	4/15/24		12.00		Quailways/61-67	320+45				This is for the extra fiber work that was needing a new bore shot due to the shallow conduit North of Kindbod approach (343 N. Lindbergh)
				4/16/24	26.00		Quailways/61-67	320+45	RC			
1460	9109902	MISC. ITS	4/5/24	4/10/24	1.00	EA	PB #2 @ Quailways/Tealbrook (SW quadrant)	320+36	RC			
1490	9109902	MISC. ITS	4/15/24	4/16/24	4.00	EA	Quailways/61-67 (C.A.)	320+45	RC			
1500	9109902	MISC. ITS	4/15/24	4/16/24	4.00	EA	Quailways/61-67 (C.A.)	320+45	RC			
1510	9109902	MISC. ITS	4/15/24	4/16/24	1.00	EA	Quailways/61-67 (C.A.)	320+45	RC			
1540	0100003	MISC. ITS	4/15/24	4/16/24	126.00	LF	Quailways/61-67	319+78	RC	321+04	rc	

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 3/23/2023 Page 15 of 24



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3280	0070	TYPE 5 AGGREGATE FOR BASE	Material		1	Feb 2, 2024	SYSTEM	\$5,684.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user colemp1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Feb 2, 2024	SYSTEM	(\$5,684.80)	
					2	Feb 16, 2024	SYSTEM	\$20,784.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user thursw1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Feb 16, 2024	SYSTEM	(\$20,784.88)	
					3	Mar 4, 2024	SYSTEM	\$35,900.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thursw1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Mar 4, 2024	SYSTEM	(\$35,900.46)	
					4	Mar 18, 2024	SYSTEM	\$45,780.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user thursw1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Mar 18, 2024	SYSTEM	(\$45,780.46)	
					5	Apr 2, 2024	SYSTEM	\$59,315.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user colemp1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Apr 2, 2024	SYSTEM	(\$59,315.04)	
					6	Apr 16, 2024	SYSTEM	\$70,751.01	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thursw1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Apr 16, 2024	SYSTEM	(\$70,751.01)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
								44.44	
	0070 -							\$0.00	
	0070 -	TYPE 5 AGGREGATE FOR BASE (6 IN.	Material		3	Mar 4, 2024	SYSTEM	\$0.00 \$1,737.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		TYPE 5 AGGREGATE	Material		3		SYSTEM SYSTEM		Estimate Item Adjustment (0003) due to user thursw1 overridding Payment
		TYPE 5 AGGREGATE FOR BASE (6 IN.	Material			2024 Mar 4,		\$1,737.60	Estimate Item Adjustment (0003) due to user thursw1 overridding Payment
		TYPE 5 AGGREGATE FOR BASE (6 IN.	Material		3	2024 Mar 4, 2024 Mar 18,	SYSTEM	\$1,737.60 (\$1,737.60)	Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thursw1 overridding Payment
		TYPE 5 AGGREGATE FOR BASE (6 IN.	Material		3	2024 Mar 4, 2024 Mar 18, 2024	SYSTEM	\$1,737.60 (\$1,737.60) \$1,737.60	Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thursw1 overridding Payment
		TYPE 5 AGGREGATE FOR BASE (6 IN.	Material		3 4	2024 Mar 4, 2024 Mar 18, 2024 Mar 18, 2024 Apr 2,	SYSTEM SYSTEM	\$1,737.60 (\$1,737.60) \$1,737.60 (\$1,737.60)	Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user colemp1 overridding Payment
		TYPE 5 AGGREGATE FOR BASE (6 IN.	Material		3 4 4 5	2024 Mar 4, 2024 Mar 18, 2024 Mar 18, 2024 Apr 2, 2024 Apr 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$1,737.60 (\$1,737.60) \$1,737.60 (\$1,737.60) \$2,137.60	Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user colemp1 overridding Payment
		TYPE 5 AGGREGATE FOR BASE (6 IN.	Material		3 4 4 5 5 5	2024 Mar 4, 2024 Mar 18, 2024 Mar 18, 2024 Apr 2, 2024 Apr 2, 2024 Apr 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$1,737.60 (\$1,737.60) \$1,737.60 (\$1,737.60) \$2,137.60	Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user colemp1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Item Adjustment (0003) due to user thursw1 overridding Payment
		TYPE 5 AGGREGATE FOR BASE (6 IN.		- Total	3 4 4 5 5 5 6	2024 Mar 4, 2024 Mar 18, 2024 Mar 18, 2024 Apr 2, 2024 Apr 2, 2024 Apr 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,737.60 (\$1,737.60) \$1,737.60 (\$1,737.60) \$2,137.60 (\$2,137.60) \$3,385.60 (\$3,385.60)	Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user colemp1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Item Adjustment (0003) due to user thursw1 overridding Payment
	0080	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material Material - To		3 4 4 5 5 5 6	2024 Mar 4, 2024 Mar 18, 2024 Mar 18, 2024 Apr 2, 2024 Apr 2, 2024 Apr 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,737.60 (\$1,737.60) \$1,737.60 (\$1,737.60) \$2,137.60 (\$2,137.60) \$3,385.60 (\$3,385.60) \$0.00	Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user colemp1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Item Adjustment (0003) due to user thursw1 overridding Payment
	0080	TYPE 5 AGGREGATE FOR BASE (6 IN.			3 4 4 5 5 5 6	2024 Mar 4, 2024 Mar 18, 2024 Mar 18, 2024 Apr 2, 2024 Apr 2, 2024 Apr 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,737.60 (\$1,737.60) \$1,737.60 (\$1,737.60) \$2,137.60 (\$2,137.60) \$3,385.60 (\$3,385.60)	Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user colemp1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Item Adjustment (0003) due to user thursw1 overridding Payment
	0080	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material - To		3 4 4 5 5 5 6	2024 Mar 4, 2024 Mar 18, 2024 Mar 18, 2024 Apr 2, 2024 Apr 16, 2024 Mar 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,737.60 (\$1,737.60) \$1,737.60 (\$1,737.60) \$2,137.60 (\$2,137.60) \$3,385.60 (\$3,385.60) \$0.00	Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user colemp1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Item Adjustment (0003) due to user thursw1 overridding Payment
	0080	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) Total PAVED APPROACH, 8	Material - To		3 4 4 5 5 6 6 6	2024 Mar 4, 2024 Mar 18, 2024 Mar 18, 2024 Apr 2, 2024 Apr 16, 2024 Mar 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,737.60 (\$1,737.60) \$1,737.60 (\$1,737.60) \$2,137.60 (\$2,137.60) \$3,385.60 (\$3,385.60) \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user colemp1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user thursw1 overridding Payment Estimate Item Adjustment (0004) due to user thursw1 overridding Payment
	0080	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) Total PAVED APPROACH, 8	Material - To		3 4 4 5 5 6 6 6 3 3	2024 Mar 4, 2024 Mar 18, 2024 Apr 2, 2024 Apr 2, 2024 Apr 16, 2024 Mar 4, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,737.60 (\$1,737.60) \$1,737.60 (\$1,737.60) \$2,137.60 (\$2,137.60) \$3,385.60 (\$3,385.60) \$0.00 \$0.00 \$45,922.50	Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user colemp1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user thursw1 overridding Payment Estimate Item Adjustment (0004) due to user thursw1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
6S3280	0260	PAVED	Material			2024			
		APPROACH, 8 IN.			5	Apr 2, 2024	SYSTEM	\$156,124.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user colemp1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Apr 2, 2024	SYSTEM	(\$156,124.80)	
					6	Apr 16, 2024	SYSTEM	\$201,310.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user thursw1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Apr 16, 2024	SYSTEM	(\$201,310.20)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0260 -	Total						\$0.00	
	0270	CONCRETE SIDEWALK, 4 IN.	Material		1	Feb 2, 2024	SYSTEM	\$24,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user colemp1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Feb 2, 2024	SYSTEM	(\$24,244.00)	
					2	Feb 16, 2024	SYSTEM	\$87,261.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user thursw1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Feb 16, 2024	SYSTEM	(\$87,261.00)	
					3	Mar 4, 2024	SYSTEM	\$118,128.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user thursw1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	Mar 4, 2024	SYSTEM	(\$118,128.60)	
					4	Mar 18, 2024	SYSTEM	\$124,033.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user thursw1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Mar 18, 2024	SYSTEM	(\$124,033.00)	
					5	Apr 2, 2024	SYSTEM	\$162,235.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user colemp1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	Apr 2, 2024	SYSTEM	(\$162,235.86)	
					6	Apr 16, 2024	SYSTEM	\$182,743.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user thursw1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Apr 16, 2024	SYSTEM	(\$182,743.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0270 -	Total						\$0.00	
	0280	MISC. CONCRETE	Material		2	Feb 16, 2024	SYSTEM	\$5,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user thursw1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					2	Feb 16, 2024	SYSTEM	(\$5,100.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0280 -	Total						\$0.00	
	0290	CONCRETE CURB (6 IN. HEIGHT AND	Material		1	Feb 2, 2024	SYSTEM	\$1,702.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user colemp1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		UNDER)			1	Feb 2, 2024	SYSTEM	(\$1,702.00)	
					2	Feb 16, 2024	SYSTEM	\$11,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user thursw1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					2	Feb 16,	SYSTEM	(\$11,040.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3280	0290	CONCRETE	Material			2024			
		CURB (6 IN. HEIGHT AND UNDER)			3	Mar 4, 2024	SYSTEM	\$5,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					3	Mar 4, 2024	SYSTEM	(\$5,244.00)	
					4	Mar 18, 2024	SYSTEM	\$5,244.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user thursw1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					4	Mar 18, 2024	SYSTEM	(\$5,244.00)	
					5	Apr 2, 2024	SYSTEM	\$43,102.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user colemp1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					5	Apr 2, 2024	SYSTEM	(\$43,102.00)	
					6	Apr 16, 2024	SYSTEM	\$43,562.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user thursw1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					6	Apr 16, 2024	SYSTEM	(\$43,562.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0290 -	· Total						\$0.00	
	0300	CURB AND GUTTER TYPE B	Material		3	Mar 4, 2024	SYSTEM	\$45,429.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user thursw1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					3	Mar 4, 2024	SYSTEM	(\$45,429.00)	
					4	Mar 18, 2024	SYSTEM	\$46,249.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user thursw1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					4	Mar 18, 2024	SYSTEM	(\$46,249.80)	
					5	Apr 2, 2024	SYSTEM	\$50,182.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user colemp1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					5	Apr 2, 2024	SYSTEM	(\$50,182.80)	
					6	Apr 16, 2024	SYSTEM	\$80,837.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user thursw1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					6	Apr 16, 2024	SYSTEM	(\$80,837.40)	
				- Total				\$0.00	
			Material - To	Material - Total				\$0.00	
	0300	· Total						\$0.00	
	0340	MISC. PAVED DRAINAGE	Material		3	Mar 4, 2024	SYSTEM	\$12,240.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user thursw1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					3	Mar 4, 2024	SYSTEM	(\$12,240.00)	
					4	Mar 18, 2024	SYSTEM	\$12,240.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user thursw1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					4	Mar 18, 2024	SYSTEM	(\$12,240.00)	
					5	Apr 2, 2024	SYSTEM	\$12,240.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user colemp1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					5	Apr 2, 2024	SYSTEM	(\$12,240.00)	
					6	Apr 16, 2024	SYSTEM	\$12,240.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user thursw1 overridding Payment Estimate Exception 16 on the current Payment Estimate.



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks							
,			Туре	Adjustment Type	Number	Date	Ву									
6S3280	0340	MISC. PAVED DRAINAGE	Material		6	Apr 16, 2024	SYSTEM	(\$12,240.00)								
				- Total												
			Material - To	tal				\$0.00								
	0340 -	· Total						\$0.00								
	0470	CURVED VANE GRTE AND FRAME(2 FT. X 2	Material		4	Mar 18, 2024	SYSTEM	\$7,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user thursw1 overridding Payment Estimate Exception 15 on the current Payment Estimate.							
		FT)			4	Mar 18, 2024	SYSTEM	(\$7,350.00)								
					5	Apr 2, 2024	SYSTEM	\$7,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user colemp1 overridding Payment Estimate Exception 16 on the current Payment Estimate.							
					5	Apr 2, 2024	SYSTEM	(\$7,350.00)								
					6	Apr 16, 2024	SYSTEM	\$7,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user thursw1 overridding Payment Estimate Exception 17 on the current Payment Estimate.							
					6	Apr 16, 2024	SYSTEM	(\$7,350.00)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	0470 -	· Total						\$0.00								
	0750	12 IN. PIPE GROUP A	Material		4	Mar 18, 2024	SYSTEM	\$7,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user thursw1 overridding Payment Estimate Exception 16 on the current Payment Estimate.							
					4	Mar 18, 2024	SYSTEM	(\$7,475.00)								
					5	Apr 2, 2024	SYSTEM	\$7,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user colemp1 overridding Payment Estimate Exception 17 on the current Payment Estimate.							
					5	Apr 2, 2024	SYSTEM	(\$7,475.00)								
					6	Apr 16, 2024	SYSTEM	\$7,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user thursw1 overridding Payment Estimate Exception 18 on the current Payment Estimate.							
					6	Apr 16, 2024	SYSTEM	(\$7,475.00)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	0750 -	· Total						\$0.00								
	0770	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	Material		4	Mar 18, 2024	SYSTEM	\$10,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user thursw1 overridding Payment Estimate Exception 17 on the current Payment Estimate.							
		11/211										4	Mar 18, 2024	SYSTEM	(\$10,500.00)	
					5	Apr 2, 2024	SYSTEM	\$10,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user colemp1 overridding Payment Estimate Exception 18 on the current Payment Estimate.							
					5	Apr 2, 2024	SYSTEM	(\$10,500.00)								
					6	Apr 16, 2024	SYSTEM	\$10,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user thursw1 overridding Payment Estimate Exception 19 on the current Payment Estimate.							
					6	Apr 16, 2024	SYSTEM	(\$10,500.00)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	0770 -	· Total						\$0.00								
	0790	12 IN. GROUP A FLARED END SECT	Material		4	Mar 18, 2024	SYSTEM	\$6,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user thursw1 overridding Payment Estimate Exception 18 on the current Payment Estimate.							
					4	Mar 18,	SYSTEM	(\$6,750.00)								



20 20 12 12 13 13 13 14 15 15 15 15 15 15 15	ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
Sect	280	0790	FLARED END	Material			2024			
STOP						5		SYSTEM	\$6,750.00	Estimate Item Adjustment (0011) due to user colemp1 overridding Payment
Estimate Execution (1997) Secretarial construction Secretarial S						5		SYSTEM	(\$6,750.00)	
Total						6		SYSTEM	\$6,750.00	Estimate Item Adjustment (0012) due to user thursw1 overridding Payment
Material - Total						6		SYSTEM	(\$6,750.00)	
CURB INLET CHECK Material					- Total				\$0.00	
DR40 CURB NIET Meterial CHECK Meterial CHECK 1				Material - To	tal				\$0.00	
CHECK		0790 -	Total						\$0.00	
Construction Cons		0840		Material		1		SYSTEM	\$350.00	Estimate Item Adjustment (0004) due to user colemp1 overridding Payment
Material - Total						1		SYSTEM	(\$350.00)	
Construction Stockpile STM -Total S49,842.00 S49,842.00 S49,842.00 STM -Total S49,842.00 S49,842.00 STM -Total S49,842.00 S49,842.00 S49,842.00 STM -Total S49,842.00 S49,84					- Total				\$0.00	
MGS Construction Stockpile STMI - Total S49,842.00 Payment Estimate Item Adjustment generated Stockpile Transaction S49,842.00 S49				Material - To	tal				\$0.00	
Construction Stockpile STMI -Total S49,842.00		0840 -	Total						\$0.00	
Construction Stockpile STMI Total \$49,842.00		0870		Stockpile		3		SYSTEM	\$49,842.00	Payment Estimate Item Adjustment generated Stockpile Transaction
Stystem Stys					- Total				\$49,842.00	
Construction Stockpile STMI - Total Stockp				Construction	Stockpile S	MI - Total			\$49,842.00	
SUARDRAIL, 8 FT. OSTS, 6 FT3 IN		0870 -	Total						\$49,842.00	
Second S		0880	GUARDRAIL, 8	Stockpile		3		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
New York Secretary Secre					- Total				\$209.75	
MGS BRIDGE APP. TRANS SEC (EXT) CURB Total Total SS,925.00 MGS VERTICAL CONSTRUCTION Stockpile STMI - Total SS,925.00 MGS VERTICAL CONCRETE BARRIER TRANSITION MGS VERTICAL CONCRETE TRANSITION Total Construction Stockpile STMI - Total SS,925.00 MGS VERTICAL CONCRETE BARRIER TRANSITION Total Construction Stockpile STMI - Total S17,010.00 MGS VERTICAL CONCRETE STMI Total Total S17,010.00 Payment Estimate Item Adjustment generated Stockpile Transaction S10,010.00 Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-genera				Construction	Stockpile S	MI - Total				
APP. TRANS SCO (EXT) CURB) Construction Stockpile STMI - Total S5,925.00 MGS VERTICAL CONCRETE BARRIER TRANSITION Construction Stockpile STMI - Total S17,010.00 Payment Estimate Item Adjustment generated Stockpile Transaction S17,010.00 Payment	J	0880 -	880 - Total						\$209.75	
Construction Stockpile STMI - Total S5,925.00 0900 MGS VERTICAL CONCRETE BARRIER STMI - Total STMI - Total Construction Stockpile STMI - Total S17,010.00 0900 - Total 0900 - Total 0910 MGS END ANCHOR STMI - Total Construction Stockpile STMI - Total Construction Stockpile STMI - Total S17,010.00 0910 - Total Construction Stockpile STMI - Total S17,010.00 0910 - Total Construction Stockpile STMI - Total S8,580.00 0910 - Total Construction Stockpile STMI - Total S8,580.00 0910 - Total 0920 - Total 0920 - Total Construction Stockpile STMI - Total S8,580.00 0920 - Total Construction Stockpile STMI - Total S9,9375.00 0920 - Total 0920 - Total Construction Stockpile STMI - Total S9,9375.00 0920 - Total 1080 CONDUIT, 3 IN., TRENCH WITH TRACER WIRE 6 Apr 16, SYSTEM \$105.78 2024 SYSTEM \$105.78 S105.78 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Item Adjustment (0013) due to user thursw1 ov		0890	APP. TRANS SEC (EXT	Stockpile	Total	3		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
September Stockpile STM -Total Standard Stockpile StM -Total Standard Stockpile StM -Total Standard Stockpile StM -Total Standard Standard Stockpile StM -Total Standard Stockpile -Total Standard Stockpile -Total Standard -Total -Total Standard -Total -To			CURB)	0 1 1						
MGS VERTICAL CONCRETE SARRIER TRANSITION		0000				IMI - Total				
CONCRETE BARRIER TRANSITION Construction Stockpile STMI - Total \$17,010.00 9900 - Total 9910 MGS END ANCHOR Stockpile STMI - Total \$17,010.00 9910 - Total Construction Stockpile STMI - Total \$8,580.00 Payment Estimate Item Adjustment generated Stockpile Transaction \$8,580.00 9910 - Total \$9,9375.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total \$39,375.00 9910 - Total \$39,375.00						-				
Construction Stockpile STMI - Total S17,010.00 MGS END ANCHOR ANCHOR STMI - Total S8,580.00 Construction Stockpile STMI - Total S8,580.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Transaction Stockpile Transaction Stockpile STMI - Total S39,375.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Transaction Stockpile Transaction Stockpile STMI - Total CONSTRUCTION STOCKPILE STMI - Total S39,375.00 D820 - Total CONDUIT, 3 IN., TRENCH WITH TRACER WIRE 6 Apr 16, SYSTEM \$105.78 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Exception 21 on the current Payment Estimate.		0900	CONCRETE	Stockpile		3		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
Signature Sign			TRANSITION	O a made — di						
MGS END ANCHOR MGS END STMI MGS END MGS END ANCHOR MGS END ANCHO		0000	Takal	Construction	Stockpile S	Wii - Total				
ANCHOR Stockpile STMI - Total \$8,580.00 Construction Stockpile STMI - Total \$8,580.00 0910 - Total \$8,580.00 0920 TYPE A CRASHWORTHY END TERMINAL (MASH) - Total \$39,375.00 Construction Stockpile STMI - Total \$39,375.00 0920 - Total \$39,375.00 1080 CONDUIT, 3 IN., TRENCH WITH TRACER WIRE 6 Apr 16, 2024 SYSTEM \$105.78 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	ı			0 : ::		0	Ma d	OVOTE		December 1 September 1 September 1 September 2 Septemb
Construction Stockpile STMI - Total \$8,580.00 TYPE A CRASHWORTHY END TERMINAL (MASH) Construction Stockpile STMI - Total Total Construction Stockpile STMI - Total S39,375.00 Total S39,375.00 Construction Stockpile STMI - Total S39,375.00 Construction Stockpile STMI - Total S39,375.00 Construction Stockpile STMI - Total S39,375.00 Construction Stockpile Transaction S39,375.00 Total S39,375.00 Construction Stockpile Transaction S10,000		0910		Stockpile		3		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
System S										
O920 TYPE A CRASHWORTHY END TERMINAL (MASH) Total Construction Stockpile STMI - Total Construction Stockpile STMI - Total S39,375.00 Construction Stockpile STMI - Total S39,375.00 O920 - Total CONDUIT, 3 IN., TRENCH WITH TRACER WIRE Apr 16, 2024 Apr 16, 2024 SYSTEM \$39,375.00 Payment Estimate Item Adjustment generated Stockpile Transaction S39,375.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Exception 21 on the current Payment Estimate.				Construction	Stockpile S	MI - Total				
CRASHWORTHY END TERMINAL (MASH) Total Construction Stockpile STMI - Total S39,375.00 Construction Stockpile STMI - Total \$39,375.00 Construction Stockpile STMI - Total \$39,375.00 CONDUIT, 3 IN., TRENCH WITH TRACER WIRE 6 Apr 16, 2024 SYSTEM Find adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Exception 21 on the current Payment Estimate. 6 Apr 16, 2024 SYSTEM S	J	0910 -	Total						\$8,580.00	
(MASH) Construction Stockpile STMI - Total \$39,375.00 0920 - Total \$39,375.00 0920 - Total \$39,375.00 CONDUIT, 3 IN., TRENCH WITH TRACER WIRE 6 Apr 16, 2024 SYSTEM \$105.78 TRENCH WITH TRACER WIRE 6 Apr 16, 2024 CONDUIT (\$105.78)		0920	CRASHWORTHY	Stockpile		3		SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
1080 CONDUIT, 3 IN., TRENCH WITH TRACER WIRE 6 Apr 16, 2024 6 Apr 16, 2024 1080 CONDUIT, 3 IN., TRENCH WITH TRACER WIRE 6 Apr 16, 2024 6 Apr 16, 2024 (\$105.78)										
1080 CONDUIT, 3 IN., TRENCH WITH TRACER WIRE 6 Apr 16, 2024 \$105.78 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Exception 21 on the current Payment Estimate. 6 Apr 16, 2024 \$105.78 (\$105.78)				Construction	Stockpile S	MI - Total				
TRENCH WITH TRACER WIRE 2024 Estimate Item Adjustment (0013) due to user thursw1 overridding Payment Estimate Exception 21 on the current Payment Estimate. 6 Apr 16, 2024 (\$105.78)		0920 -							\$39,375.00	
2024		1080	TRENCH WITH	Material		6		SYSTEM	\$105.78	Estimate Item Adjustment (0013) due to user thursw1 overridding Payment
- Total \$0.00						6		SYSTEM	(\$105.78)	
					- Total				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3280	1080	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material - To	tal				\$0.00	
	1080 -	· Total						\$0.00	
	1160	PULL BOX, PREFORMED CLASS 1	Material		6	Apr 16, 2024	SYSTEM	\$1,470.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user thursw1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					6	Apr 16, 2024	SYSTEM	(\$1,470.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1160 -	· Total						\$0.00	
	1170	PULL BOX, PREFORMED CLASS 2	Material		6	Apr 16, 2024	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user thursw1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					6	Apr 16, 2024	SYSTEM	(\$2,400.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1170 -	· Total						\$0.00	
	1190	BASE, CONCRETE			6	Apr 16, 2024	SYSTEM	\$1,757.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user thursw1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					6	Apr 16, 2024	SYSTEM	(\$1,757.28)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1190 -	· Total						\$0.00	
	1270	MISC.	Material		6	Apr 16, 2024	SYSTEM	\$1,116.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user thursw1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					6	Apr 16, 2024	SYSTEM	(\$1,116.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1270 -	· Total						\$0.00	
	1300	2 IN. PSST POST - 12 GA.	2 GA. Stockpile STMI		6	Apr 16, 2024	SYSTEM	\$6,654.48	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$6,654.48	
			Construction	Stockpile S	TMI - Total			\$6,654.48	
	1300 -	· Total						\$6,654.48	
	1310	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12	Stockpile		6	Apr 16, 2024	SYSTEM	\$936.51	Payment Estimate Item Adjustment generated Stockpile Transaction
		GA.		- Total				\$936.51	
			Construction	Stockpile S	IMI - Total			\$936.51	
		Total						\$936.51	
	1320	2.5 IN. PSST POST - 12 GA.	Construction Stockpile STMI		6	Apr 16, 2024	SYSTEM	\$3,539.20	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$3,539.20	
			Construction	Stockpile S	IMI - Total			\$3,539.20	
		Total						\$3,539.20	
	1330	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7	Construction Stockpile STMI	- Total	6 4		SYSTEM	\$2,525.46	Payment Estimate Item Adjustment generated Stockpile Transaction
		GA.	Oamat 1					\$2,525.46	
	1000	Total	Construction	Stockpile S	IMI - Total			\$2,525.46	
		Total					2) (2)	\$2,525.46	
	1340	SH-FLAT SHEET	Construction Stockpile STMI		6	Apr 16, 2024	SYSTEM	\$5,375.60	Payment Estimate Item Adjustment generated Stockpile Transaction



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J6S3280	1340	SH-FLAT SHEET	Construction Stockpile STMI	- Total				\$5,375.60	
			Construction	Stockpile S	ΓMI - Total			\$5,375.60	
	1340 -	· Total						\$5,375.60	
	1380	CONDUIT, 2 IN., RIGID, IN TRENCH	Material		6	Apr 16, 2024	SYSTEM	\$290.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user thursw1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					6	Apr 16, 2024	SYSTEM	(\$290.70)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1380 -	· Total						\$0.00	
	1410	MISC. ITS	Material		6	Apr 16, 2024	SYSTEM	\$530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user thursw1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					6	Apr 16, 2024	SYSTEM	(\$530.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1410 -	· Total						\$0.00	
	1420	MISC. ITS	Material		6	Apr 16, 2024	SYSTEM	\$2,698.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user thursw1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					6	Apr 16, 2024	SYSTEM	(\$2,698.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1420 -	· Total						\$0.00	
	1460	MISC. ITS	Material		6	Apr 16, 2024	SYSTEM	\$2,725.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user thursw1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					6	Apr 16, 2024	SYSTEM	(\$2,725.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1460 -	· Total						\$0.00	
	1490	MISC. ITS	6 Material		6	Apr 16, 2024	SYSTEM	\$104.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user thursw1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					6	Apr 16, 2024	SYSTEM	(\$104.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1490 - 1500	Total MISC. ITS	Material		6	Apr 16, 2024	SYSTEM	\$0.00 \$104.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user thursw1 overridding Payment
					6	Apr 16, 2024	SYSTEM	(\$104.00)	Estimate Exception 32 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To					\$0.00	
	15 <u>00</u> -	· Total						\$0.00	
	1510	MISC. ITS	Material		6	Apr 16, 2024	SYSTEM	\$1,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user thursw1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					6	Apr 16, 2024	SYSTEM	(\$1,150.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3280	1510 -	Total						\$0.00	
	1540 MISC. ITS Ma		Material		6	Apr 16, 2024	SYSTEM	\$592.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user thursw1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					6	Apr 16, 2024	SYSTEM	(\$592.20)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	1540 -	Total					\$0.00		
J6S3280 -	- Total						\$139,973.00		
Overall -	Total						\$139,973.00		

MoDOT

Contract Adjustments for Contract - 231117-F01

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 24 of 24