

Pay Estimate Created Date: June 17, 2024

Progress Estimate 11	Number	Contract ID Prime Contracto	231117-F05 or Gerstner Electi	ric, Inc.	Pay Period Start Pay Period End	June 2, 2024 June 15, 202	0	\$1,595,781.00 \$185,675.00 \$1,781,456.00
Approval Date								By User
June 17, 2024			Generated and A	Approved	(and should be co	nsidered Draft) at the Project Office Level by	norton1
June 17, 2024		Re	viewed and Appro	ved (and	should be conside	ered Draft) at tl	ne Resident Engineer Level by	gibbon1
June 18, 2024			F	Reviewed	and Approved at	the Central Of	fice Controllers Office Level by	ramses1
Original Completio	n Date	Current Con	pletion Date	Act	ual Completion D	ate	% of Current Contract Amou	nt Complete
December 31, 2)24	Decembe	r 31, 2024				35.68%	
	Contract	Informational Dat	es		Mile	stones		
Date Description	Original	Completion Date	Current Comple	tion Dat	e No Milestones	Exist for Cont	ract	
Acceptance Date								
Awarded Date	Decembe	er 6, 2023	December 6, 202	23				
Letting Date	Novembe	er 17, 2023	November 17, 20)23				
Notice to Proceed Date	January 8	3, 2024	January 8, 2024					
Open to Traffic Date								
Work Began Date	January 7	11, 2024	January 11, 2024	Ļ				

Contract Total Pay For Estimate No. 11

	Other Contract Adjustments	\$0.00	\$0.00 \$543.999.60	\$0.00 \$630,381.50	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Gross Item Adjustments	(\$5,330.00)	\$0.00	(\$5,330.00)	
231117-F05	Total Posted Items Pay	\$91,711.90	\$543,999.60	\$635,711.50	
231117-F05		This Estimate	Previous	To Date	

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6Q3174E	0010	2019902	MISCCLEARING, GRUBBING, MOWING & TREE CLEARING	EA	\$2,000.000	1	\$2,000.00
	0090	9029902	MISC.INSTALL & CONFIGURE VIDEO DETECTION CAMERA	EA	\$650.000	1	\$650.00
	0140	9103700	CCTV CAMERA ASSEMBLY, INSTALLED	EA	\$830.000	4	\$3,320.00
	0210	9109902	MISC.ADVANCED DIAGNOSTICS	EA	\$150.000	108	\$16,200.00
	0250	9109902	MISC.F&I FIBER OPTIC FUSION SPLICE, SINGLE MODE	EA	\$20.000	164	\$3,280.00
	0280	9109902	MISC.F&I ITS PULL BOX CLASS 5 WITH CONCRETE PAD	EA	\$3,800.000	2	\$7,600.00
	0350	9109902	MISC.FIBER OPTIC TERMINATION	EA	\$30.000	132	\$3,960.00
	0630	9109902	MISC.REMOVE CCTV CAMERA & ASSEMBLY	EA	\$120.000	3	\$360.00
	0820	9109902	MISC.TROUBLESHOOTING	EA	\$200.000	5	\$1,000.00
	0990	9109903	MISC.F&I FIBER OPTIC CABLE, 24-STRAND SINGLE MODE	LF	\$3.150	3,226	\$10,161.90
	1000	9109903	MISC.F&I FIBER OPTIC CABLE, 72-STRAND SINGLE MODE	LF	\$3.750	3,280	\$12,300.00
	1010	9109903	MISC.F&I TRACE WIRE	LF	\$2.000	1,630	\$3,260.00
	1040	9109902	MISC.PM CCTV CAMERA, ASSEMBLY, POLE, & FIELD CABINET	EA	\$390.000	64	\$24,960.00
	1130	9109902	MISC.PM VIDEO DETECTION CAMERAS	EA	\$140.000	19	\$2,660.00
Project J6Q3	174E - Total						\$91,711.90

Pay Estimate Created Date: June 17, 2024

Progres	s Estimate N 11	umber	Contract ID Prime Contra		I7-F05 ner Electric, Inc.	Pay Period Start Pay Period End		5, 2024 Ne t	Chang	ontract Am ge Order An ontract Am	nount \$18	95,781.00 5,675.00 81,456.00
Project Number		Iter r Cod		I	tem Description		Unit	Unit Price	Curre	ent Installed Qty		Installed ount
Overall - T	otal											\$91,711.90
	Adjustments I Ijustments T Line No.		<u>nte</u>	Adjustment Type	Adjustment	Con	nments		/	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustmei amount
J6Q3174E	0280		MISC.	Overrun	Туре					-1	\$3,800.00	(\$3,800.0
	0350		MISC.	Overrun						-2	\$30.00	(\$60.0
	1000		MISC.	Overrun						-392	\$3.75	(\$1,470.0
Fotal												(\$5,330.0



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					C	Contract Project Information	on					
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work					
J6Q3174E	FAS S503(89)	ITS Maintenance	Various	ST LOUIS	at various locations in th	e St Louis District						
Totals by Job Numbers												
J6Q3174E		Item Pay tem Adjustmer	nts Gross Ite	em Pay	This Estimate \$91,711.90 (\$5,330.00) \$86,381.90	Previous \$543,999.60 \$0.00 \$543,999.60	To Date \$635,711.50 (\$5,330.00) \$630,381.50					
			ments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Item Overrun: Contract 231117-F05, Contract Project J6Q3174E, Project Item Line Number 0280, Contract Line Item Number 0280, Item 9109902, Minor Item.	A change order is in the works to correct this issue.	norton1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 231117-F05, Contract Project J6Q3174E, Project Item Line Number 0350, Contract Line Item Number 0350, Item 9109902, Minor Item.	A change order is in the works to correct this issue.	norton1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 231117-F05, Contract Project J6Q3174E, Project Item Line Number 1000, Contract Line Item Number 1000, Item 9109903, Minor Item.	A change order is in the works to correct this issue.	norton1	Acknowledged

Total Paid / All Items / All Estimates (Including this Estimate)

date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project	Category	Line	Item Code	Description	Bid Quantity	Net Change	Total	Unit	Total Posted	Unit Price	Total Value POSTED
NM.CONTRACT	No.		No.	Code		Quantity	Order	Current Quantity		Approved Qty		To Date (See report generated date)
231117-F05	J6Q3174E	0001	0010	2019902	MISCCLEARING, GRUBBING, MOWING & TREE CLEARING	5.00	0.00	5.00	EA	1.00	\$2,000.00	\$2,000.00
		0001	0020	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	3.00	0.00	3.00	EA	0.00	\$1,000.00	\$0.00
		0001	0030	6169901	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.00	\$30,000.00	\$0.00
		0001	0040	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED & RETAINED)	3.00	0.00	3.00	EA	0.00	\$100.00	\$0.00
		0001	0050	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.25	\$70,000.00	\$17,500.00
		0030	0060	9028308	CABLE, 16 AWG 2 CONDUCTOR	500.00	0.00	500.00	LF	0.00	\$2.00	\$0.00
		0030	0070	9028309	CABLE, 16 AWG 3 CONDUCTOR	500.00	0.00	500.00	LF	0.00	\$2.00	\$0.00
		0030	0080	9028310	CABLE, 16 AWG 5 CONDUCTOR	500.00	0.00	500.00	LF	0.00	\$2.25	\$0.00
		0030	0090	9029902	MISC.INSTALL & CONFIGURE VIDEO DETECTION CAMERA	40.00	0.00	40.00	EA	15.00	\$650.00	\$9,750.00
		0030	0100	9029902	MISC.INSTALL AND CONFIGURE AUDIBLE PEDESTRIAN SYSTEM	70.00	0.00	70.00	EA	12.00	\$950.00	\$11,400.00
		0030	0110	9029902	MISC.REMOVAL OF AUDIBLE PEDESTRIAN SYSTEM	70.00	0.00	70.00	EA	12.00	\$90.00	\$1,080.00
		0030	0120	9029902	MISC.REMOVAL OF VIDEO DETECTION CAMERA	40.00	0.00	40.00	EA	16.00	\$350.00	\$5,600.00
		0030	0130	9029903	MISC.CABLE, 18 AWG 4 CONDUCTOR	500.00	0.00	500.00	LF	0.00	\$2.25	\$0.00
		0050	0140	9103700	CCTV CAMERA ASSEMBLY, INSTALLED	30.00	0.00	30.00	EA	14.00	\$830.00	\$11,620.00
		0050	0150	9105200	CONDUIT, 2 IN., RIGID, IN TRENCH	250.00	0.00	250.00	LF	189.00	\$11.00	\$2,079.00
		0050	0160	9105201	CONDUIT, 3 IN., RIGID, IN TRENCH	100.00	0.00	100.00	LF	13.00	\$14.00	\$182.00
		0050	0170	9105202	CONDUIT, 4 IN., RIGID, IN TRENCH	100.00	0.00	100.00	LF	0.00	\$17.00	\$0.00
		0050	0180	9107201	CONDUIT, 3 IN., RIGID, PUSHED	50.00	0.00	50.00	LF	0.00	\$24.00	\$0.00
		0050	0190	9107202	CONDUIT, 4 IN., RIGID, PUSHED	50.00	0.00	50.00	LF	0.00	\$26.00	\$0.00
		0050	0200	9108352	FIBER OPTIC CABLE, 24-STRAND, 18 SINGLE MODE, 6 MULTIMODE	500.00	0.00	500.00	LF	0.00	\$3.75	\$0.00
		0050	0210	9109902	MISC.ADVANCED DIAGNOSTICS	500.00	400.00	900.00	EA	815.00	\$150.00	\$122,250.00
		0050	0220	9109902	MISC.DAKTRONICS' VANGUARD VX-2420 (DYNAMIC TRAIL BLAZER SIGN) PURCHASE	1.00	0.00	1.00	EA	0.00	\$15,750.00	\$0.00
		0050	0230	9109902	MISC.F&I CAMERA POLE (60FT) AND LOWERING SYSTEM	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0050	0240	9109902	MISC.F&I FIBER OPTIC FUSION SPLICE, MULTI MODE	50.00	0.00	50.00	EA	0.00	\$30.00	\$0.00
		0050	0250	9109902	MISC.F&I FIBER OPTIC FUSION SPLICE, SINGLE MODE	1,250.00	750.00	2,000.00	EA	1,556.00	\$20.00	\$31,120.00
		0050	0260	9109902	MISC.F&I ITS PULL BOX CLASS 1	2.00	0.00	2.00	EA	0.00	\$1,920.00	\$0.00
		0050	0270	9109902	MISC.F&I ITS PULL BOX CLASS 2 WITH CONCRETE PAD	2.00	0.00	2.00	EA	2.00	\$3,200.00	\$6,400.00
		0050	0280	9109902	MISC.F&I ITS PULL BOX CLASS 5 WITH CONCRETE PAD	2.00	2.00	4.00	EA	5.00	\$3,800.00	\$19,000.00
		0050	0290	9109902	MISC.F&I NON-INTRUSIVE VEHICLE DETECTOR POLE	5.00	0.00	5.00	EA	0.00	\$1,000.00	\$0.00
		0050	0300	9109902	MISC.F&I TYPE 1 ITS CABINET	1.00	0.00	1.00	EA	0.00	\$5,000.00	\$0.00
		0050	0310	9109902	MISC.F&I TYPE 2 ITS CABINET	1.00	0.00	1.00	EA	0.00	\$2,500.00	\$0.00
		0050	0320	9109902	MISC.F&I TYPE 5 ITS CABINET	1.00	0.00	1.00	EA	0.00	\$500.00	\$0.00
		0050	0330	9109902	MISC.F&I TYPE 7 ITS CABINET	1.00	0.00	1.00	EA	1.00	\$1,000.00	\$1,000.00
		0050	0340	9109902	MISC.FIBER OPTIC SPLICE ENCLOSURE	6.00	14.00	20.00	EA	14.00	\$925.00	\$12,950.00
		0050	0350	9109902	MISC.FIBER OPTIC TERMINATION	150.00	0.00	150.00	EA	152.00	\$30.00	\$4,560.00
		0050	0360	9109902	MISC.INSTALL IN-PAVEMENT WIRELESS SENSORS	50.00	0.00	50.00	EA	0.00	\$50.00	\$0.00
		0050	0370	9109902	MISC.INSTALL NON-INTRUSIVE ACCESS POINT & ASSEMBLY	5.00	0.00	5.00	EA	0.00	\$325.00	\$0.00
		0050	0380	9109902	MISC.INSTALL NON-INTRUSIVE VEHICLE DETECTOR ASSEMBLY	15.00	0.00	15.00	EA	3.00	\$720.00	\$2,160.00
		0050	0390	9109902	MISC.INSTALL NON-INTRUSIVE WIRELESS REPEATER	5.00	0.00	5.00	EA	0.00	\$250.00	\$0.00
		0050	0400	9109902	MISC.INSTALL SALVAGED CAMERA POLE	1.00	0.00	1.00	EA	0.00	\$1,290.00	\$0.00
		0050	0410	9109902	MISC.INSTALL SALVAGED FIELD CABINET (DUAL)	1.00	0.00	1.00	EA	0.00	\$950.00	\$0.00
		0050	0420	9109902	MISC.INSTALL SALVAGED FIELD CABINET (SINGLE)	10.00	0.00	10.00	EA	0.00	\$650.00	\$0.00
		0050	0430	9109902	MISC.INSTALL SALVAGED NON-INTRUSIVE VEHICLE DETECTOR POLE	10.00	0.00	10.00	EA	2.00	\$1,000.00	\$2,000.00
		0050	0440	9109902	MISC.INSTALL SOLAR POWER SYSTEM	1.00	0.00	1.00	EA	0.00	\$5,300.00	\$0.00
		0050	0450	9109902	MISC.INSTALL SPREAD SPECTRUM WIRELESS COMMUNICATION EQUIPMENT	2.00	0.00	2.00	EA	0.00	\$120.00	\$0.00

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

MatcheNote	Note: Posted Q	uantities a				port Generated date and can differ from the posted amou	nt at the ti	me the Es	timate was (Generat	ed.		
Norm 1000NOR-0000000NOR-00000000NOR-00000000NOR-0000000NOR-0000000000000NOR-000000000000000000000000000000000000			Category			Description		Change	Current	Unit	Posted Approved	Unit Price	To Date (See report
100010101010000101000010100001010000101000010100001010000101000001010000000001010000000000000000000000000000000000	231117-F05	J6Q3174E	0050	0460	9109902	MISC.INSTALL UPS AUTOMATIC GENERATOR SWITCH	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
No.No			0050	0470	9109902	MISC.INSTALL UPS AUTOMATIC TRANSFER SWITCH	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
Nome 00010000100000010000001000000100000010000001000000100000010000001000000100000010000001000000100000001000000010000000100000001000000010000000010000000001000000000000000000000000000000000000			0050	0480	9109902	MISC.INSTALL UPS BATTERY	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
00001090109000000000000000000000000000000000000			0050	0490	9109902	MISC.INSTALL UPS BATTERY MONITOR	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
Image: Note of the set of th			0050	0500	9109902	MISC.INSTALL UPS POWER INVERTER	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
Image: Control incluminant Image: Control incluminant <th< td=""><td></td><td></td><td>0050</td><td>0510</td><td>9109902</td><td>MISC.INSTALL UPS SYSTEM ASSEMBLY</td><td>10.00</td><td>0.00</td><td>10.00</td><td>EA</td><td>0.00</td><td>\$685.00</td><td>\$0.00</td></th<>			0050	0510	9109902	MISC.INSTALL UPS SYSTEM ASSEMBLY	10.00	0.00	10.00	EA	0.00	\$685.00	\$0.00
Norm 100016401800, TB PALL BOX LD REPLACEMENT [16, S MCH DLAMETER5.000.006.000.006.00<			0050	0520	9109902		5.00	0.00	5.00	EA	3.00	\$1,200.00	\$3,600.00
100060691680MICL PLA MALINED POINER SUPPLY, 120V ITS11061111000<			0050	0530	9109902	MISC.ITS PULL BOX LID REPLACEMENT (32-INCH DIAMETER)	5.00	0.00	5.00	EA	0.00	\$800.00	\$0.00
1000600919000MICE ABOLESTAL BASE FOR SERVIN REPEATER POLE1.000.001.00EA0.001720001720001000607919000MICE ABOLK MULTERIN TREECOBRECT ESTRFF5.006.006.001.006.001.006.001.00 </td <td></td> <td></td> <td>0050</td> <td>0540</td> <td>9109902</td> <td>MISC.ITS PULL BOX LID REPLACEMENT (40.5 INCH DIAMETER)</td> <td>5.00</td> <td>0.00</td> <td>5.00</td> <td>EA</td> <td>0.00</td> <td>\$800.00</td> <td>\$0.00</td>			0050	0540	9109902	MISC.ITS PULL BOX LID REPLACEMENT (40.5 INCH DIAMETER)	5.00	0.00	5.00	EA	0.00	\$800.00	\$0.00
Nome 1990RescMach Asck Multinet Interconnect centern1.000.000.000.000.00000.00			0050	0550	9109902	MISC.PAD MOUNTED POWER SUPPLY, 120V ITS	2.00	0.00	2.00	EA	1.00	\$5,000.00	\$5,000.00
000 10000 Mich Resource AREA VE DIR DYNAMIC TONL BLAZERY 1.00 0.00 1.00 6.00 5.00 5.000 0000 0000 100000 Mich RESAVE DIR DYNAMIC TANL BLAZERY 1.00 0.00 1.00 5.00 5.000 5.000 0000 0100 100000 Mich RESAVE DIR DYNAMIC TANL BLAZERY 1.00 0.00 1.00 5.00 5.000 5.000 0000 0100 100000 Mich RESAVE DIR DYNAMIC TANL BLAZERY 1.00 0.00 1.00 5.00 5.000			0050	0560	9109902	MISC.PEDESTAL BASE FOR SENSYS REPEATER POLE	1.00	0.00	1.00	EA	0.00	\$720.00	\$0.00
International International International International International International International International			0050	0570	9109902	MISC.RACK MOUNTED INTERCONNECT CENTER	5.00	0.00	5.00	EA	0.00	\$800.00	\$0.00
Index 0999 0909000 SiGN FOLMART, REPLACE UP BLATTERY 100 0.00 1.00<			0050	0580	9109902		1.00	0.00	1.00	EA	0.00	\$5,865.00	\$0.00
0000010000MSC.REMOVE REPLACE UPB BATTERY10000001007.007.606.009.00009.00000			0050	0590	9109902		1.00	0.00	1.00	EA	0.00	\$5,865.00	\$0.00
No. 000000000100000001000EA0.0001000EA0.0001000 <td></td> <td></td> <td>0050</td> <td>0600</td> <td>9109902</td> <td></td> <td>1.00</td> <td>0.00</td> <td>1.00</td> <td>EA</td> <td>0.00</td> <td>\$4,000.00</td> <td>\$0.00</td>			0050	0600	9109902		1.00	0.00	1.00	EA	0.00	\$4,000.00	\$0.00
Conce 			0050	0610	9109902	MISC.REMOVE AND REPLACE UPS BATTERY	4.00	0.00	4.00	EA	0.00	\$120.00	\$0.00
9690 9640 919902 MISC.REMOVE COMMUNICATION FIELD CABINET (DOUBLE 1.0 0.00 1.00 EA 0.00 95902 0.000 0060 96690 919902 MISC.REMOVE COMMUNICATION NODE FIELD CABINET 1.00 0.00 1.00 EA 0.00 53700 0.000 0060 906902 MISC.REMOVE NON-INTRUSIVE ACCESS POINT & ASSEMBLY 0.00 0.00 EA 0.00 910902 910902 MISC.REMOVE NON-INTRUSIVE VEHICLE OFFECTOR 1.00 0.00 1.00 EA 0.00 910902 910902 MISC.REMOVE NON-INTRUSIVE VEHICLE OFFECTOR 1.00 0.00 1.00 EA 0.00 91090 910902 MISC.REMOVE NON-INTRUSIVE VEHICLE OFFECTOR 1.00 0.00 1.00 EA 0.00 910902 MISC.REMOVE SIGLAR POWER SYSTEM 1.00 0.00 1.00 EA 0.00 91000 910002 MISC.REMOVE UPS AUTOMATIC GENERATOR SWITCH 1.00 0.00 1.00 EA 0.00 91000 91000 910002 MISC.REMOVE UPS AUTOMATIC GENERATOR SWITCH 1.00 0.00 <t< td=""><td></td><td></td><td>0050</td><td>0620</td><td>9109902</td><td>MISC.REMOVE CAMERA POLE</td><td>1.00</td><td>0.00</td><td>1.00</td><td>EA</td><td>0.00</td><td>\$750.00</td><td>\$0.00</td></t<>			0050	0620	9109902	MISC.REMOVE CAMERA POLE	1.00	0.00	1.00	EA	0.00	\$750.00	\$0.00
Internet Conditient Conditien			0050	0630	9109902	MISC.REMOVE CCTV CAMERA & ASSEMBLY	30.00	0.00	30.00	EA	12.00	\$120.00	\$1,440.00
NoteImageImageImageImageImageImageImageImageImageImageImage00 <td></td> <td></td> <td>0050</td> <td>0640</td> <td>9109902</td> <td></td> <td>1.00</td> <td>0.00</td> <td>1.00</td> <td>EA</td> <td>0.00</td> <td>\$650.00</td> <td>\$0.00</td>			0050	0640	9109902		1.00	0.00	1.00	EA	0.00	\$650.00	\$0.00
065006509109902MISC REMOVE IN-PAVEMENT WIRELESS SENSORS9000			0050	0650	9109902		1.00	0.00	1.00	EA	0.00	\$375.00	\$0.00
00000800910902MISC.REMOVE NON-INITRUSIVE VEHICLE DETECTOR MISC.REMOVE NON-INITRUSIVE VEHICLE DETECTOR POLE10.00.0011.00EA2.205120.005230.000000070910902MISC.REMOVE NON-INITRUSIVE VEHICLE DETECTOR POLE10.000.0010.00EA0.005150.005590.0000000710910902MISC.REMOVE NON-INITRUSIVE WIRELESS REPEATER5.000.0010.00EA0.00550.00550.0000000710910902MISC.REMOVE UPS AUTOMATIC GENERATOR SWITCH10.000.0010.00EA0.0005120.00550.0000000700910902MISC.REMOVE UPS AUTOMATIC TRANSFER SWITCH10.000.0010.00EA0.0005120.005120.0000000700910902MISC.REMOVE UPS AUTOMATIC TRANSFER SWITCH10.000.0010.00EA0.0005120.005120.0000000700910902MISC.REMOVE UPS AUTOMATIC TRANSFER SWITCH10.000.0010.00EA0.0005120.005120.0000000700910902MISC.REMOVE UPS AUTOMATIC TRANSFER SWITCH10.000.0010.00EA0.0005120.00520.0000000700910902MISC.REMOVE UPS AUTOMATIC TRANSFER SWITCH10.000.0010.00EA0.005120.00520.0000000700910902MISC.REMOVE UPS AUTOMATIC TRANSFER SWITCH10.000.0010.00EA0.005120.00520.00 <t< td=""><td></td><td></td><td>0050</td><td>0660</td><td>9109902</td><td>MISC.REMOVE IN-PAVEMENT WIRELESS SENSORS</td><td>50.00</td><td>0.00</td><td>50.00</td><td>EA</td><td>0.00</td><td>\$20.00</td><td>\$0.00</td></t<>			0050	0660	9109902	MISC.REMOVE IN-PAVEMENT WIRELESS SENSORS	50.00	0.00	50.00	EA	0.00	\$20.00	\$0.00
Image: Biole Construction Im			0050	0670	9109902	MISC.REMOVE NON-INTRUSIVE ACCESS POINT & ASSEMBLY	5.00	0.00	5.00	EA	0.00	\$125.00	\$0.00
Late OTOM OTOM <th< td=""><td></td><td></td><td>0050</td><td>0680</td><td>9109902</td><td></td><td>15.00</td><td>0.00</td><td>15.00</td><td>EA</td><td>2.00</td><td>\$120.00</td><td>\$240.00</td></th<>			0050	0680	9109902		15.00	0.00	15.00	EA	2.00	\$120.00	\$240.00
Interview Interview <t< td=""><td></td><td></td><td>0050</td><td>0690</td><td>9109902</td><td>MISC.REMOVE NON-INTRUSIVE VEHICLE DETECTOR POLE</td><td>10.00</td><td>0.00</td><td>10.00</td><td>EA</td><td>2.00</td><td>\$475.00</td><td>\$950.00</td></t<>			0050	0690	9109902	MISC.REMOVE NON-INTRUSIVE VEHICLE DETECTOR POLE	10.00	0.00	10.00	EA	2.00	\$475.00	\$950.00
Loc 10000 1000 1000 <th< td=""><td></td><td></td><td>0050</td><td>0700</td><td>9109902</td><td>MISC.REMOVE NON-INTRUSIVE WIRELESS REPEATER</td><td>5.00</td><td>0.00</td><td>5.00</td><td>EA</td><td>0.00</td><td>\$150.00</td><td>\$0.00</td></th<>			0050	0700	9109902	MISC.REMOVE NON-INTRUSIVE WIRELESS REPEATER	5.00	0.00	5.00	EA	0.00	\$150.00	\$0.00
Not Nick			0050	0710	9109902	MISC.REMOVE SOLAR POWER SYSTEM	1.00	0.00	1.00	EA	0.00	\$900.00	\$0.00
0050 0740 9109902 MISC.REMOVE UPS BATTERY 10.00 0.00 10.00 EA 0.00 \$12.00 \$32.00 0050 0750 9109902 MISC.REMOVE UPS BATTERY MONITOR 1.00 0.00 1.00 0.00 1.00 0.00 1.00 EA 0.00 \$12.00 \$32.00 0050 0760 9109902 MISC.REMOVE UPS SYTEM ASSEMBLY 1.00 0.00 1.00 0.00 1.00 EA 0.00 \$32.00 \$30.00			0050	0720	9109902	MISC.REMOVE UPS AUTOMATIC GENERATOR SWITCH	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
Note Note <th< td=""><td></td><td></td><td>0050</td><td>0730</td><td>9109902</td><td>MISC.REMOVE UPS AUTOMATIC TRANSFER SWITCH</td><td>10.00</td><td>0.00</td><td>10.00</td><td>EA</td><td>0.00</td><td>\$120.00</td><td>\$0.00</td></th<>			0050	0730	9109902	MISC.REMOVE UPS AUTOMATIC TRANSFER SWITCH	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
Note Note MISC. REMOVE UPS POWER INVERTER 1.00 0.000 1.00 EA 0.000 \$120.00 \$120.00 \$120.00 0050 0770 9109902 MISC. REMOVE UPS SYSTEM ASSEMBLY 10.00 0.00 10.00 EA 0.00 \$300.00 \$235.00 0050 0780 9109902 MISC. REMOVE WIRELESS COMMUNICATION EQUIPMENT 2.00 0.00 EA 1.00 \$235.00 \$235.00 \$235.00 0050 0790 9109902 MISC. SENSYS REPEATER POLE BASE ALUMINUM SQUARE 1.00 0.00 EA 1.00 \$240.00 \$270.00 \$200.00			0050	0740	9109902	MISC.REMOVE UPS BATTERY	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
Note Note <th< td=""><td></td><td></td><td>0050</td><td>0750</td><td>9109902</td><td>MISC.REMOVE UPS BATTERY MONITOR</td><td>1.00</td><td>0.00</td><td>1.00</td><td>EA</td><td>0.00</td><td>\$120.00</td><td>\$0.00</td></th<>			0050	0750	9109902	MISC.REMOVE UPS BATTERY MONITOR	1.00	0.00	1.00	EA	0.00	\$120.00	\$0.00
Note Note <th< td=""><td></td><td></td><td>0050</td><td>0760</td><td>9109902</td><td>MISC.REMOVE UPS POWER INVERTER</td><td>1.00</td><td>0.00</td><td>1.00</td><td>EA</td><td>0.00</td><td>\$120.00</td><td>\$0.00</td></th<>			0050	0760	9109902	MISC.REMOVE UPS POWER INVERTER	1.00	0.00	1.00	EA	0.00	\$120.00	\$0.00
Note Note <th< td=""><td></td><td></td><td>0050</td><td>0770</td><td>9109902</td><td>MISC.REMOVE UPS SYSTEM ASSEMBLY</td><td>10.00</td><td>0.00</td><td>10.00</td><td>EA</td><td>0.00</td><td>\$300.00</td><td>\$0.00</td></th<>			0050	0770	9109902	MISC.REMOVE UPS SYSTEM ASSEMBLY	10.00	0.00	10.00	EA	0.00	\$300.00	\$0.00
No. No. <td></td> <td></td> <td>0050</td> <td>0780</td> <td>9109902</td> <td>MISC.REMOVE WIRELESS COMMUNICATION EQUIPMENT</td> <td>2.00</td> <td>0.00</td> <td>2.00</td> <td>EA</td> <td>1.00</td> <td>\$235.00</td> <td>\$235.00</td>			0050	0780	9109902	MISC.REMOVE WIRELESS COMMUNICATION EQUIPMENT	2.00	0.00	2.00	EA	1.00	\$235.00	\$235.00
No. No. <td></td> <td></td> <td>0050</td> <td>0790</td> <td>9109902</td> <td>MISC.SENSYS REPEATER POLE BASE ALUMINUM SQUARE</td> <td>1.00</td> <td>0.00</td> <td>1.00</td> <td>EA</td> <td>0.00</td> <td>\$720.00</td> <td>\$0.00</td>			0050	0790	9109902	MISC.SENSYS REPEATER POLE BASE ALUMINUM SQUARE	1.00	0.00	1.00	EA	0.00	\$720.00	\$0.00
Note Note <th< td=""><td></td><td></td><td>0050</td><td>0800</td><td>9109902</td><td>MISC.TB1-17 ALUMINUM BASE FOR RTMS POLE</td><td>1.00</td><td>1.00</td><td>2.00</td><td>EA</td><td>1.00</td><td>\$800.00</td><td>\$800.00</td></th<>			0050	0800	9109902	MISC.TB1-17 ALUMINUM BASE FOR RTMS POLE	1.00	1.00	2.00	EA	1.00	\$800.00	\$800.00
Note Note <th< td=""><td></td><td></td><td>0050</td><td>0810</td><td>9109902</td><td>MISC.TB3-17 ALUMINUM BASE FOR RTMS POLE</td><td>1.00</td><td>1.00</td><td>2.00</td><td>EA</td><td>1.00</td><td>\$875.00</td><td>\$875.00</td></th<>			0050	0810	9109902	MISC.TB3-17 ALUMINUM BASE FOR RTMS POLE	1.00	1.00	2.00	EA	1.00	\$875.00	\$875.00
Note Note <th< td=""><td></td><td></td><td>0050</td><td>0820</td><td>9109902</td><td>MISC.TROUBLESHOOTING</td><td>100.00</td><td>0.00</td><td>100.00</td><td>EA</td><td>43.00</td><td>\$200.00</td><td>\$8,600.00</td></th<>			0050	0820	9109902	MISC.TROUBLESHOOTING	100.00	0.00	100.00	EA	43.00	\$200.00	\$8,600.00
Note Note <th< td=""><td></td><td></td><td>0050</td><td>0830</td><td>9109902</td><td>MISC.WALL MOUNTED INTERCONNECT CENTER</td><td>5.00</td><td>0.00</td><td>5.00</td><td>EA</td><td>0.00</td><td>\$800.00</td><td>\$0.00</td></th<>			0050	0830	9109902	MISC.WALL MOUNTED INTERCONNECT CENTER	5.00	0.00	5.00	EA	0.00	\$800.00	\$0.00
No. No. <td></td> <td></td> <td>0050</td> <td>0840</td> <td>9109902</td> <td>MISC.WRONG WAY ALERT SYSTEMS EQUIPMENT PURCHASE</td> <td>2.00</td> <td>0.00</td> <td>2.00</td> <td>EA</td> <td>0.00</td> <td>\$66,850.00</td> <td>\$0.00</td>			0050	0840	9109902	MISC.WRONG WAY ALERT SYSTEMS EQUIPMENT PURCHASE	2.00	0.00	2.00	EA	0.00	\$66,850.00	\$0.00
Certification By TAPCO OF NEW INSTALLATION 0050 0870 9109903 MISC.CONDUIT, 2 IN., RIGID, PUSHED 250.00 0.000 250.00 LF 0.00 \$11.00 \$0.00 0050 0880 9109903 MISC.CONDUIT, HIGH-DENSITY POLYETHYLENE, 2 IN., IN 50.00 0.000 50.00 LF 0.00 \$11.00 \$0.00 0050 0890 9109903 MISC.CONDUIT, HIGH-DENSITY POLYETHYLENE, 2 IN., IN 300.00 0.000 300.00 LF 0.00 \$11.00 \$0.00			0050	0850	9109902	MISC.WRONG WAY ALERT SYSTEMS INSTALLATION	2.00	0.00	2.00	EA	0.00	\$7,500.00	\$0.00
Image: Note of the second se			0050	0860	9109902		2.00	0.00	2.00	EA	0.00	\$9,915.00	\$0.00
Other TRENCH 300.00 0.000 300.00 LF 0.000 \$19.00 \$10.00 \$0.00			0050	0870	9109903	MISC.CONDUIT, 2 IN., RIGID, PUSHED	250.00	0.00	250.00	LF	0.00	\$19.00	\$0.00
			0050	0880	9109903		50.00	0.00	50.00	LF	0.00	\$11.00	\$0.00
			0050	0890	9109903		300.00	0.00	300.00	LF	0.00	\$19.00	\$0.00



Total Paid / All Items / All Estimates (Including this Estimate)

Number		uantities a	nd Value	s are ba	sed on Re	port Generated date and can differ from the posted amou							
Part Part Part Part Part Part Part Part	Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity			Unit	Approved	Unit Price	Total Value POSTED To Date (See report generated date)
International Internat	231117-F05	J6Q3174E	0050	0900	9109903		500.00	0.00	500.00	LF		\$4.20	\$0.00
Image Image <th< td=""><td></td><td></td><td>0050</td><td>0910</td><td>9109903</td><td></td><td>250.00</td><td>0.00</td><td>250.00</td><td>LF</td><td>0.00</td><td>\$2.00</td><td>\$0.00</td></th<>			0050	0910	9109903		250.00	0.00	250.00	LF	0.00	\$2.00	\$0.00
Image Image <th< td=""><td></td><td></td><td>0050</td><td>0920</td><td>9109903</td><td></td><td>100.00</td><td>2,900.00</td><td>3,000.00</td><td>LF</td><td>2,770.00</td><td>\$3.50</td><td>\$9,695.00</td></th<>			0050	0920	9109903		100.00	2,900.00	3,000.00	LF	2,770.00	\$3.50	\$9,695.00
Image Image <th< td=""><td></td><td></td><td>0050</td><td>0930</td><td>9109903</td><td></td><td>100.00</td><td>0.00</td><td>100.00</td><td>LF</td><td>0.00</td><td>\$4.75</td><td>\$0.00</td></th<>			0050	0930	9109903		100.00	0.00	100.00	LF	0.00	\$4.75	\$0.00
Image Image <th< td=""><td></td><td></td><td>0050</td><td>0940</td><td>9109903</td><td></td><td>100.00</td><td>0.00</td><td>100.00</td><td>LF</td><td>0.00</td><td>\$2.50</td><td>\$0.00</td></th<>			0050	0940	9109903		100.00	0.00	100.00	LF	0.00	\$2.50	\$0.00
International and the conduct room of the conduct condu			0050	0950	9109903		500.00	0.00	500.00	LF	0.00	\$2.00	\$0.00
Intend Stand & Integer Stand & Index & Internet offic Caller 3-Attribute Bindle Model Stand & Index			0050	0960	9109903		1,000.00	0.00	1,000.00	LF	0.00	\$1.50	\$0.00
CABLE CABLE <th< td=""><td></td><td></td><td>0050</td><td>0970</td><td>9109903</td><td>MISC.F&I CABLE IN CONDUIT, VIDEO COAXIAL CABLE</td><td>250.00</td><td>0.00</td><td>250.00</td><td>LF</td><td>0.00</td><td>\$2.00</td><td>\$0.00</td></th<>			0050	0970	9109903	MISC.F&I CABLE IN CONDUIT, VIDEO COAXIAL CABLE	250.00	0.00	250.00	LF	0.00	\$2.00	\$0.00
Image Image <th< td=""><td></td><td></td><td>0050</td><td>0980</td><td>9109903</td><td></td><td>5,000.00</td><td>0.00</td><td>5,000.00</td><td>LF</td><td>260.00</td><td>\$2.00</td><td>\$520.00</td></th<>			0050	0980	9109903		5,000.00	0.00	5,000.00	LF	260.00	\$2.00	\$520.00
Mode Mode Mode CPAI TRACE WIRE 7000.0 Mode 7000.0 FL 6.300 6.200			0050	0990	9109903	MISC.F&I FIBER OPTIC CABLE, 24-STRAND SINGLE MODE	17,000.00	7,000.00	24,000.00	LF	21,390.00	\$3.15	\$67,378.50
0001 1020 0199920 MSC.NCOOT BURIED CABLE DENIAGE CABRIETS 04.00 0.00 70.00 64.00			0050	1000	9109903	MISC.F&I FIBER OPTIC CABLE, 72-STRAND SINGLE MODE	5,000.00	15,000.00	20,000.00	LF	20,392.00	\$3.75	\$76,470.00
001 0000 00000 MBCPM ARCONDITIONING UNITS FOR NOCE CABINETS 04.0 04.			0050	1010	9109903	MISC.F&I TRACE WIRE	7,000.00	0.00	7,000.00	LF	6,330.00	\$2.00	\$12,660.00
0x1 1000 100000 MSC PM CCTV CAMERA, ASSEMBLY, POLE & FELD CABINET 01.00 01.00 01.00 02.			0051	1020	9109902	MISC.MODOT BURIED CABLE DRIVABLE DELINEATOR POST	70.00	0.00	70.00	EA	1.00	\$115.00	\$115.00
Model 1969 19690000 MSC PM COMMUNICATION LINK AND ASSEMBLY 333.00 0.00 333.00 EA 0.00 51400 514000 0051 1060 9199800 MSC PM COMMUNICATION NOCE FIELD CABINET 33.00 0.00 33.00 EA 0.00 5440.00 5440.00 5440.00 5440.00 5440.00 5440.00 5440.00 5440.00 5440.00 5440.00 5440.00 5440.00 5440.00 5440.00 5440.00 5440.00 5440.00 5440.00 5440.00 5400.00			0051	1030	9109902	MISC.PM AIR CONDITIONING UNITS FOR NODE CABINETS	64.00	0.00	64.00	EA	32.00	\$276.00	\$8,832.00
0651 0669 919992 MSC.PM COMMUNICATION NODE FIELD CABINET 33.00 0.00 33.00 EA 0.00 5440.00 5440.00 0051 1070 919902 MSC.PM COMPLASEMELY, POLES, FOLMDATION, AND 2.00 0.00 0.00 1600 0.00 440.00 440.00 640.00			0051	1040	9109902	MISC.PM CCTV CAMERA, ASSEMBLY, POLE, & FIELD CABINET	618.00	0.00	618.00	EA	441.00	\$390.00	\$171,990.00
Note 1070 9109802 MSG_CPM DMP, ASSEMBLY, POLES, FOUNDATION, AND 2.00 0.00 12.00 EA 0.00 54.00 0051 1006 9109802 MGG_CPM DMA, ASSEMBLY, POLE, FOUNDATION, AND 1500 0.00 160.00 EA 0.00 545.00 55.			0051	1050	9109902	MISC.PM COMMUNICATION LINK AND ASSEMBLY	333.00	0.00	333.00	EA	0.00	\$145.00	\$0.00
International and the set of the			0051	1060		MISC.PM COMMUNICATION NODE FIELD CABINET	33.00	0.00	33.00	EA	0.00	\$440.00	\$0.00
Image: Calibre Torm Calibr			0051	1070	9109902		2.00	0.00	2.00	EA	0.00	\$440.00	\$0.00
Internal 1100 9199902 MISC PM NON-NITRUSIVE VEHICLE DETECTOR STATIONS 297.00 0.00 297.00 EA 0.00 331.00 <			0051	1080	9109902		180.00	0.00	180.00	EA	0.00	\$450.00	\$0.00
India 0051 1110 9109002 MISCPM SOLAR POWER SYSTEM 34.00 0.00 34.00 EA 0.00 32.00 0.00 32.00 0.00 32.00 0.00 32.00 0.00 32.00 0.00 32.00 0.00 32.00 0.00 32.00 0.00 32.00 0.00 0.00 10.00 0.			0051	1090	9109902	MISC.PM DTB (DYNAMIC TRAIL BLAZER) SIGN ASSEMBLY	15.00	0.00	15.00	EA	0.00	\$240.00	\$0.00
Lat. International International <td></td> <td></td> <td>0051</td> <td>1100</td> <td>9109902</td> <td></td> <td>297.00</td> <td>0.00</td> <td>297.00</td> <td>EA</td> <td>0.00</td> <td>\$310.00</td> <td>\$0.00</td>			0051	1100	9109902		297.00	0.00	297.00	EA	0.00	\$310.00	\$0.00
International according to a product of the			0051	1110	9109902	MISC.PM SOLAR POWER SYSTEM	34.00	0.00	34.00	EA	0.00	\$220.00	\$0.00
Index Index <th< td=""><td></td><td></td><td>0051</td><td>1120</td><td>9109902</td><td></td><td>32.00</td><td>0.00</td><td>32.00</td><td>EA</td><td>0.00</td><td>\$220.00</td><td>\$0.00</td></th<>			0051	1120	9109902		32.00	0.00	32.00	EA	0.00	\$220.00	\$0.00
International Internat			0051	1130	9109902	MISC.PM VIDEO DETECTION CAMERAS	645.00	0.00	645.00	EA	19.00	\$140.00	\$2,660.00
Obs 1160 9109902 MISC.PM WITH REPAIRS - MODOT APPROVED CCTV CAMERA, ASSEMBLY, POLE, & FIELD CABINET 1.00 0.00 1.00 EA 0.00 \$1,000.00			0051	1140	9109902		1.00	0.00	1.00	EA	0.00	\$440.00	\$0.00
Note ASSEMBLY, POLE, & FIELD CABINET Image: Commentation of the comme			0051	1150	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV CAMERA	1.00	0.00	1.00	EA	1.00	\$1,000.00	\$1,000.00
Instrume Instrume Instrume Instrume Instrume Instrume Instrume 0051 1180 9109902 MISC.PM WITH REPAIRS - MODOT APPROVED CCTV 1.00 0.00 1.00 EA 0.00 \$1.00 <t< td=""><td></td><td></td><td>0051</td><td>1160</td><td>9109902</td><td></td><td>1.00</td><td>0.00</td><td>1.00</td><td>EA</td><td>0.00</td><td>\$1,000.00</td><td>\$0.00</td></t<>			0051	1160	9109902		1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
Inscription SERVER Inscription Inscription <t< td=""><td></td><td></td><td>0051</td><td>1170</td><td>9109902</td><td></td><td>1.00</td><td>0.00</td><td>1.00</td><td>EA</td><td>0.00</td><td>\$375.00</td><td>\$0.00</td></t<>			0051	1170	9109902		1.00	0.00	1.00	EA	0.00	\$375.00	\$0.00
Image: Note of the image: No			0051	1180	9109902		1.00	0.00	1.00	EA	0.00	\$1.00	\$0.00
International Interna International International<			0051	1190	9109902		1.00	0.00	1.00	EA	0.00	\$1.00	\$0.00
Initial Initial Supply Suppl			0051	1200	9109902		1.00	0.00	1.00	EA	0.00	\$440.00	\$0.00
OOD OOD PROTECTOR OOD PROTECTOR OOD EA OOD State State OOD State			0051	1210	9109902		1.00	0.00	1.00	EA	0.00	\$440.00	\$0.00
No. No. <td></td> <td></td> <td>0051</td> <td>1220</td> <td>9109902</td> <td></td> <td>1.00</td> <td>0.00</td> <td>1.00</td> <td>EA</td> <td>0.00</td> <td>\$390.00</td> <td>\$0.00</td>			0051	1220	9109902		1.00	0.00	1.00	EA	0.00	\$390.00	\$0.00
Image: Note of the image: Controller Controler Controler<			0051	1230	9109902		1.00	0.00	1.00	EA	0.00	\$440.00	\$0.00
Image: Note of the second se			0051	1240	9109902		1.00	0.00	1.00	EA	0.00	\$665.00	\$0.00
0051 1260 9109902 MISC.PM WITH REPAIRS - MODOT APPROVED DMS FAN 1.00 0.00 1.00 EA 0.00 \$550.00 \$550.00 \$0.00 0.00 0051 1270 9109902 MISC.PM WITH REPAIRS - MODOT APPROVED DMS LCA 1.00 0.00 1.00 EA 0.00 \$550.00 \$550.00 \$500			0051	1250	9109902		1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
Image: Note of the state of the st			0051	1260	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED DMS FAN	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
BOARD BOARD Image: Constraint of the second			0051	1270	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED DMS LCA	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
0051 1300 9109902 MISC.PM WITH REPAIRS - MODOT APPROVED IP 1.00 0.00 1.00 EA 0.00 \$440.00 \$0.00			0051	1280	9109902		1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
			0051	1290	9109902		1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
ADDRESSABLE FOWER STRIP			0051	1300	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED IP ADDRESSABLE POWER STRIP	1.00	0.00	1.00	EA	0.00	\$440.00	\$0.00

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
231117-F05	J6Q3174E	0051	1310	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED SIGNAL VIDEO DETECTION CAMERA	1.00	0.00	1.00	EA	0.00	\$130.00	\$0.00
		0051	1320	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED UPS DEVICE AND COMPONENTS	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
		0051	1330	9109902	MISC.PM WITH REPAIRS - MODOT SOLAR POWER SYSTEM	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
		0051	1340	9109902	MISC.REMOVE AND REPLACE NODE CABINET AIR CONDITIONER SYSTEM	2.00	0.00	2.00	EA	0.00	\$12,100.00	\$0.00
		0051	1350	9109902	MISC.WRONG WAY ALERT SYSTEMS PREVENTATIVE MAINTENANCE, SOFTWARE & RECERTIFICATION	12.00	0.00	12.00	EA	0.00	\$7,900.00	\$0.00
	Project J60	23174E - To	tal Value	Posted to D	ate as of Report Generated Date							\$635,711.50
31117-F05 Ove	rall - Total V	alue Postec	I to Date	as of Repor	t Generated Date							\$635,711.50



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line lumber	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2019902	MISC.	6/13/24	6/14/24	1.00	EA	W. Clay at Zumbehl					Grub/Brush Clearing at RTMS Power Supply along W. Clay at Zumbehl for CCTV/RTMS along EB I-70 at Zumbehl Removed Brush at Power Supply for EB I-70 E/O Zumbehl RTMS Site
0090	9029902	MISC.	6/12/24	6/17/24	1.00	EA	MO100W102.6 MO-100 @ Baxter-Sulphur Springs - Per IssueTrak Ticket #2001					-Installed Gridsmart Video Detection System at MO 100 @ Sulphur Springs/Baxter - Will Program and Remove Old System Tomorrow 6/13 - Per IssueTrak Ticket #200 - NOT COMPLETE
0120	9029902	MISC.	6/13/24	6/14/24		EA	MO100W102.6 MO 100 @ Baxter/Sulphur Springs - Per IssueTrak Ticket #2001					-Working on Gridsmart/Camera Removals at MO 100 @ Baxter/Sulphur Springs - Per IssueTrak Ticket #2001 - NOT COMPLETE
0140	9103700	CCTV CAMERA ASSEMBLY, INSTALLED	6/3/24	6/5/24	1.00	EA	IS064W011.0 I-64 @ Route 94 - Per IssueTrak Ticket #2407					-Removed and Replaced CCTV at I-64 @ Route 94 - Pe IssueTrak Ticket #2407 - COMPLETE
				6/5/24	1.00	EA	MO094E098.3 Route 94 @ Route D - Per IssueTrak Ticket #2325					-Removed and Replaced CCTV at Rotue 94 @ Route D Per IssueTrak Ticket #2325 - COMPLETE
			6/4/24		1.00	EA	#2231					-Replaced CCTV with New Axis from TMC at I-70 @ Fe Fee Rd - Per IssueTrak Ticket #2231 - COMPLETE
			6/12/24	6/17/24	1.00	EA	IS270N013.6 - 270 @ AB - Per IssueTrak Ticket #1991					-Installed Axis PTZ/Radar Test Camera at NB I-270 @ Route AB-Ladue - Per IssueTrak Ticket #1991 - COMPLETE
0210	9109902	MISC. ITS	6/3/24	6/5/24	4.00	EA	IS070E243.0 I-70 @ Jennings Station CCTV Cabinet - Per IssueTrak Ticket #2411					-Troubleshoot Broken Fiber in I-70 @ Jennings Station CCTV Cabinet. Repaired Broken Pigtail, Work Complete Per IssueTrak Ticket #2411 - COMPLETE
				6/5/24	27.00	EA	IS270N022.9 Node 11 I-270 @ MO Bottom - Per IssueTrak Ticket#2354					-Uncovered Class 5 PB in Gore Point West of Node 11, Traced Fiber back towards Node and Found Roden Damage on 72 Fiber. There is a splice enclosure in PB gore point. Installed Rope for NEW 72 Fiber to be installed 6/4 - Per IssueTrak Ticket #2354 - NOT COMPLETE
			6/5/24	6/10/24	5.00	EA	IS055N202.7 - 55 @ Carondelet - Per IssueTrak Ticket #2417					-Repaired Broken Pigtail at I-55 @ Carondelet Signal Cabinet - Per IssueTrak Ticket #2417 - COMPLETE
				6/10/24	5.00	EA	IS070E235.2 - Node 20 - I-70 @ 67 - Per IssueTrak Ticket #2430					-Repaired Broken Pigtail at Node 20 - Per IssueTrak Ticket #2430 - COMPLETE
				6/10/24	18.00	EA	RT0CCE002.7 - CC @ Edison - Per IssueTrak Ticket #2005					-Excavated to Cutover Conduit from Old Meter Socket to New Power Supply, Setup Temp Generator to run signa on flash, Disconned/Reconned performed by Ameren and then GEI crews brought the Signal back on Amerer power, backflied, seeded & Strawed, All work at Long R @ Edison Ave - Per Issue Trak Ticket #2005 - COMPLETE
			6/6/24	6/10/24	11.00	EA	MO100W098.3 - 100 @ Strecker- Ruck - Per IssueTrak Ticket #2436					-Trace out 24 SM Fiber along MO 100 between Strecke and Westglen Farms, Found Possible Damaged Spot. V Install NEW 24 SM Fiber on 6/7 - Per IssueTrak Ticket #2436 - NOT COMPLETE
			6/11/24	6/14/24	16.00	EA	IS070W223.7 Node 19 I-70 at I-64 Per IssueTrak Ticket #2359					-Continued Investigation of Fiber Issue between Node and TMC, Traced out Damage along I-70 in St. Charles County. Will Continue Tracing Next Week - Per IssueTr Ticket #2359 - NOT COMPLETE
				6/14/24	16.00	EA	Ticket #2437					-Completed Pullbox Installation, Setup, Poured Box Pac and Cleaned up Site along Node 6 at I-170 @ Galleria Parkway - Per IssueTrak Ticket #2437 - NOT COMPLE
			6/12/24		6.00		IS270N013.6 - 270 @ AB - Per IssueTrak Ticket #1991					-Installed Axis PTZ/Radar Test Camera at NB I-270 @ Route AB-Ladue - Per IssueTrak Ticket #1991 - COMPLETE
0250	9109902	MISC. ITS		6/10/24	36.00	EA	IssueTrak Ticket #2354					-36 Splices in Existing Coyote on 72 SM in Class 5 P8 (MO 370 @ I-270 Interchange South of Node 11, Will Complete Friday/Monday - Per IssueTrak Ticket #2354 NOT COMPLETE
				6/14/24	12.00		IS270N022.9 Node 11 I-270 @ MO Bottom - Per IssueTrak Ticket #2354					-Completed 12 Splices before finding out 72 SM Fiber was Damage at Node 11 - Per IssueTrak Ticket #2354 NOT COMPLETE
			6/10/24		72.00		IS270N022.9 Node 11_I-270 @ MO Bottom - Per IssueTrak Ticket #2437					-Completed 72 Splices in Class 5 Pullbox at Gore Southwest of Node 11 - Per IssueTrak Ticket #2354 - COMPLETE
			6/11/24		44.00		MO100W098.3 100 @ Strecker- Ruck - Per IssueTrak Ticket #2436					-Completed Splicing in Signal Cabinets at Ellisville Town Center and Strucker/Ruck along MO 100 - 44 Splices, 8 Pigtails - Per IssueTrak Ticket #2436 - COMPLETE
0280	9109902	MISC. ITS	6/10/24		1.00		IS170N000.6G Node 6_I-170 @ Galleria - Per IssueTrak Ticket #2437					-Installed NEW Class 5 Pullbox at Node 6 along I-170 (Galleria Pkwy - Per IssueTrak Ticket #2437 - NOT COMPLETE
			6/12/24	6/17/24	1.00	EA	IS064E001.6 64 EO Prospect - Per IssueTrak Ticket #2479					-Installed Class 5 Pullbox with Concrete Pad over Damage location between I-64 and Interstate Dr in Wentzville - Per IssueTrak Ticket #2479 - NOT COMPLETE
0350	9109902	MISC. ITS	6/3/24	6/5/24	2.00	EA	IS070E243.0 I-70 @ Jennings Station CCTV Cabinet - Per IssueTrak Ticket #2411					-Troubleshoot Broken Fiber in I-70 @ Jennings Station CCTV Cabinet. Repaired Broken Pigtail, Work Complete Per IssueTrak Ticket #2411 - COMPLETE
			6/5/24	6/10/24	1.00	EA	IS055N202.7 - 55 @ Carondelet - Per IssueTrak Ticket #2417					-Repaired Broken Pigtail at I-55 @ Carondelet Signal Cabinet - Per IssueTrak Ticket #2417 - COMPLETE
				6/10/24	1.00	EA	#2430					-Repaired Broken Pigtail at Node 20 - Per IssueTrak Ticket #2430 - COMPLETE
			6/6/24	6/10/24	36.00	EA	IS270N022.9 - Node 11_I-270 @ MO Bottom - Per IssueTrak Ticket #2354					-36 Terminations in Node 11 at I-270 @ MO Bottom Rd Per IssueTrak Ticket #2354 - NOT COMPLETE
			6/7/24	6/14/24	12.00	EA	IS270N022.9 Node 11 I-270 @ MO Bottom - Per IssueTrak Ticket #2354					-Completed 12 Terminations before finding out 72 SM Fiber was Damage at Node 11 - Per IssueTrak Ticket #2354 - NOT COMPLETE
			6/10/24	6/14/24	72.00	EA	IS270N022.9 Node 11_I-270 @ MO Bottom - Per IssueTrak Ticket #2437					-Completed 72 Terminations in Class 5 Pullbox at Gore Southwest of Node 11 - Per IssueTrak Ticket #2354 - COMPLETE
			6/11/24	6/14/24	8.00		MO100W098.3 100 @ Strecker- Ruck - Per IssueTrak Ticket #2436					-Completed Splicing in Signal Cabinets at Ellisville Town Center and Strucker/Ruck along MO 100 - 44 Splices, 8 Pigtails - Per IssueTrak Ticket #2436 - COMPLETE
0630	9109902	MISC. ITS	6/3/24	6/5/24	1.00	EA	IS064W011.0 I-64 @ Route 94 - Per IssueTrak Ticket #2407					-Removed and Replaced CCTV at I-64 @ Route 94 - Pe IssueTrak Ticket #2407 - COMPLETE
				6/5/24	1.00	EA	MO094E098.3 Route 94 @ Route D - Per IssueTrak Ticket #2325					-Removed and Replaced CCTV at Rotue 94 @ Route E Per IssueTrak Ticket #2325 - COMPLETE
			6/4/24	6/5/24	1.00	EA	IS070W235.0 I-70 @ Fee Fee Rd - Per IssueTrak Ticket #2231					-Replaced CCTV with New Axis from TMC at I-70 @ Fe Fee Rd - Per IssueTrak Ticket #2231 - COMPLETE
0820	9109902	MISC. ITS	6/3/24	6/5/24	1.00	EA	IS070E243.0 I-70 @ Jennings Station CCTV Cabinet - Per IssueTrak Ticket #2411					-Troubleshoot Broken Fiber in I-70 @ Jennings Station CCTV Cabinet. Repaired Broken Pigtail, Work Complet Per IssueTrak Ticket #2411 - COMPLETE
			6/5/24	6/10/24	1.00	EA	IS055N202.7 - 55 @ Carondelet - Per IssueTrak Ticket #2417					-Repaired Broken Pigtail at I-55 @ Carondelet Signal Cabinet - Per IssueTrak Ticket #2417 - COMPLETE



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0820	9109902	MISC. ITS	6/5/24	6/10/24	1.00	EA	IS070E235.2 - Node 20 - I-70 @ 67 - Per IssueTrak Ticket #2430					-Repaired Broken Pigtail at Node 20 - Per IssueTrak Ticket #2430 - COMPLETE
			6/6/24	6/10/24	1.00	EA	MO100W098.3 - 100 @ Strecker- Ruck - Per IssueTrak Ticket #2436					-Trace out 24 SM Fiber along MO 100 between Strecke and Westglen Farms, Found Possible Damaged Spot. V Install NEW 24 SM Fiber on 6/7 - Per IssueTrak Ticket #2436 - NOT COMPLETE
			6/12/24	6/17/24	1.00	EA	IS270N013.6 - 270 @ AB - Per IssueTrak Ticket #1991					-Installed Axis PTZ/Radar Test Camera at NB I-270 @ Route AB-Ladue - Per IssueTrak Ticket #1991 - COMPLETE
0990	9109903	MISC. ITS	6/7/24	6/14/24	3,226.00	LF	MO100W098.3 100 @ Strecker- Ruck - Per IssueTrak Ticket #2436					-Installed 24 SM Fiber from Strucker/Ruck to Ellisville Towne Center Dr along MO 100 (3,226 LF) - Per IssueTrak Ticket #2436 - NOT COMPLETE
1000	9109903	MISC. ITS	6/4/24	6/5/24	1,630.00	LF	IS270N022.9 Node 11 - I-270 @ MO Bottom - Per IssueTrak Ticket #2354					-Installed 1,630 LF of 72 SM Fiber and 1,630 LF of Tra Wire from Node 11 Cabinet to Class 5 Pullbox West/South West of Node 11 at Gore Point in 370/270 Interchange, Will Begin 72 Fiber Cutover on Thursday - Per IssueTrak Ticket #2354 - NOT COMPLETE
			6/7/24	6/14/24	1,650.00	LF	IS270N022.9 Node 11 I-270 @ MO Bottom - Per IssueTrak Ticket #2354					-Installed NEW 72 SM Fiber from Node 11 to Class 5 a Gore Point - Per IssueTrak Ticket #2354 - NOT COMPLETE
1010	9109903	MISC. ITS	6/4/24	6/5/24	1,630.00	LF	IS270N022.9 Node 11 - I-270 @ MO Bottom - Per IssueTrak Ticket #2354					-Installed 1,630 LF of 72 SM Fiber and 1,630 LF of Tra Wire from Node 11 Cabinet to Class 5 Pullbox West/South West of Node 11 at Gore Point in 370/270 Interchange. Will Begin 72 Fiber Cutover on Thursday - Per IssueTrak Ticket #2354 - NOT COMPLETE
1040	9109902	MISC. ITS	6/3/24	6/5/24	4.00	EA	IS070W244.4 I-70 at Union WB Ramp IS070W246.1 I-70 at Carrie-O'Fallon Park IS070W246.3 I-70 at Carrie IS070W247.3 I-70 at Grand WB Ramp/Broadway					IS070W244.4 Camera - 40' I-70 at Union WB Ramp IS070W246.1 Sig Post ext I-70 at Carrie-O'Fallon Park IS070W246.3 Camera - 50' I-70 at Carrie IS070W247.3 Sig Post ext I-70 at Grand WB Ramp/Broadway
			6/4/24	6/5/24	7.00	EA	IS070W235.0 1-70 at Fee Fee IS070W236.1 1-70 East of Cypress NEO IS070W238.1 1-70 East of Cypress NEO IS070W239.8 1-70 at NeInorissant Ramps IS070W233.1 1-70 at Goodfellow WB Ramp MO180W002-5 US 67 at NO 180 US067NU14.1 US 67 at 1-270					IS070W235.0 Camera - 50' I-70 at Fee Fee IS070W235.1 Camera - 50' I-70 East of Cypress NEQ IS070W239.8 CL Post I-70 at Hanley WB Ramps IS070W243.4 CL Post I-70 at Goodfellow WB Ramp MC18070W243.1 CL Post I-70 at Goodfellow WB Ramp MC18070W263.2 Currenta - 50' US 67 at MC 180 US067N014.1 US 67 at I-270
			6/5/24	6/10/24	8.00	EA	US067N0054 US 67 at Sunswept Park US067N0153 US 67 at Marnesa US067N0155 US 67 at McDonnell US067N0155 US 67 at McDonnell US067N0156 US 67 at Missouri Bottom-Banshee US067N0180 US 67 at Old St Charles Rd US067S0054 US 67 Wet Or Robbins Mill US067S0054 US 67 at Old Halls Ferry					US067N0064 ACL Pole NWQ US 67 at Sunswept Park US067N0130 Camera - 67 US 67 at Mannesa US067N0152 Camera - 66 US 67 at McDonnell US067N0158 Camera - 30 * US 67 at Missouri Bottor Banshee US067N0180 Camera - 30 * JO 567 at Old St Charles Fi US067N0189 Camera - 50 US 67 at Old St Charles Fi US067N0189 Camera - 50 US 67 at Old St Anles Ferry US067S0068 Camera - 50 US 67 at Old Halls Ferry
			6/6/24	6/10/24	9.00	EA	US0675011 0 US 67 at New Florisant US0675012 0 US 67 at Patterson US0675013 8 US 67 at Lynn Haven-Dunn US0675014 0 US 67 at L270 US0675014 0 US 67 at L270 US0675025 1 US 67 at Ladue US0675025 2 US 67 at Clayton US0675025 2 US 67 at Clayton US0675025 2 US 67 at Plaza Frontenac-Driftwood IS170N001.3 I-170 at Forest Park					US06750110 Camera - 50' US 67 at New Florisant US06750120 Camera - 50' US 67 at Patterson US06750130 Camera - 50' US 67 at Patterson US06750140 US 67 at 1-210 US067502140 US 67 at 1-210 US06750251 Camera - 50' US 67 at Ladue US06750252 Camera - 60' US 67 at Clayton US06750252 Camera - 60' US 67 at Plaza Frontenac Driftwood IS1710N001.3 Camera - 60' '-170 at Forest Park
			6/7/24	6/14/24	3.00	EA	IS170N002.4 I-170 at Delmar IS170N004.4 I-170 at D IS170N005.1 I-170 S of Midland					IS170N002.4 Camera - 60' * I-170 at Delmar IS170N004.4 Camera - 60' I-170 at D IS170N005.1 Camera - 60' I-170 S of Midland
			6/10/24	6/14/24	7.00	EA	IS 170N006.0 I-170 at MO 180 IS 170N009.1 I-170 at Airport IS 170N010.1 I-170 at Frost IS 170N010.6 I-170 at Ryflot IS 170S002.9 I-170 S of MO 340 IS 170S003.3 I-170 S tMO 340 IS 170S003.3 I-170 N of Soudder					IS170N006.0 Camera - 60* 1-170 at MO 180 IS170N009.1 Camera - 60* 1-170 at Airport IS170N010.1 Camera - 60* 1-170 at Frost IS170N010.6 Camera - 60* 1-170 at Nyflot IS170S002.8 Camera - 50* 1-170 sf MO 340 IS170S003.3 Camera - 60* 1-170 st MO 340 IS170S003.7 Camera - 60* 1-170 N of Scudder
			6/11/24	6/14/24	8.00	EA	MQ367N000.0 MO 367 at US 67 MQ367S002.8 MO 367 at Dum MQ3770002.6 MO 367 at Dum MQ3700006.1 MO 370 at elm-New Town WB Ramp MQ37000067.0 MO 370 Vest of MO 94 MQ3700007.9 MO 370 at MO 94 MQ3700017.1 MO 370 Vest of SL Louis Milis MQ3700017.4 MO 370 at SL Louis Milis					MQ387N000.0 MO 367 at US 67 MQ387S002.8 MO 367 at Dum MQ377W005.1 MO 370 at elm-New Town WB Ramp MQ37W0062.5 WO 370 at Bochertown MQ37W0007.0 MO 370 West of MO 94 MQ37W0017.7 MO 370 West of SL Louis Mills MQ37W0011.7 MO 370 West of SL Louis Mills
			6/12/24	6/17/24	4.00	EA	MO340E015.9 MO 340 at Dielman MO366E002.0 MO 366 at Sturdy MO366E003.4 MO 366 at Pardee MO366E004.1 MO 366 at Rock Hill-elm					MO340E015.9 Sig pole ext MO 340 at Dielman MO366E002.0 MO 366 at Sturdy MO366E003.4 MO 366 at Pardee MO366E004.1 MO 366 at Rock Hillelm
			6/13/24	6/14/24	5.00	EA	MO366E006.1 MO 366 at Trianon MO366E006.8 MO 366 at P MO366W002.6 MO 366 at NeWest Sappington MO366W003.0 MO 366 at Crestwood Plaza ent. West MO366W0051 MO 366 at LacledEast Sta.					MO366E006.1 MO 366 at Trianon MO366E006.8 MO 366 at P MO366W002.6 MO 366 at NeWest Sappington MO366W003.0 MO 366 at Crestwood Plaza ent. West MO366W005.1 MO 366 at LacledEast Sta.
			6/14/24	6/17/24	9.00	EA	MO370E008.8 MO 370 East of MO River MO370E009.4 MO 370 at MO 141-Missouri Bottom MO370W001.2 MO 370 at Spencer Rd MO370W002.6 MO 370 at Lakeside Park WB Ramp MO370W002.6 MO 370 at Larry S Truman MO370W004.2 MO 370 West of elm RT00KS002.1 Route K at Hutchings Farm RT00KS002.8 Route K at Route N RT00KS003.2 Route K at Route N					M0370E008.8 M0 370 East of MO River M0370E009.4 M0 370 at M0 141-Missouri Bottom M0370W001.2 M0 370 at Spencer Rd M0370W002.6 M0 370 at Lakeside Park WB Ramp M0370W002.6 M0 370 at Larry S Truman M0370W004.2 M0 370 West of eim RT00K5002.1 CL Post DEQ Route K at Ryalsprings Fallon RT00K5002.8 CL Post NEQ Route K at Ryalsprings Fallon RT00K5003.2 CL Post Route K at Route N
1130	9109902	MISC. ITS	6/13/24	6/14/24	3.00		MO100W097.8 St. Louis MO 100 at Ellisville Town Center					MO100W097.8 St. Louis MO 100 at Ellisville Town Ce
			6/14/24	6/17/24	16.00	EA	MO100W103.9 St. Louis MO 100 at Braeshire MO100E101.7 St. Louis MO 100 at Ries-Seven Trails Dr MO100E104.9 St. Louis MO 100 at Mason Rd MO109S005.2 St. Louis MO 109 at Old Manchester					MO100W103-9 St. Louis MO 100 at Braeshire (4 cameras) MO100E101.7 St. Louis MO 100 at Ries-Seven Trails (4 cameras) MO100E104.9 St. Louis MO 100 at Mason Rd (4 cameras) MO100SJ05.2 St. Louis MO 109 at Old Manchester (4 cameras)

The information below this line are details for Construction Signs (if applicable). No Data Available



ect	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks		
3174E	0150	CONDUIT,	Material	Туре	2	Feb 1,	SYSTEM	\$55.00	This adjustment offsets the original system-generated Material Payment		
		2 IN., RIGID, IN TRENCH				2024			Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
		ITTENOIT			2	Feb 1, 2024	SYSTEM	(\$55.00)			
					3	Feb 16, 2024	SYSTEM	\$55.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					3	Feb 16, 2024	SYSTEM	(\$55.00)			
					4	Mar 4, 2024	SYSTEM	\$1,045.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					4	Mar 4, 2024	SYSTEM	(\$1,045.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	0150 -	Total						\$0.00			
	0160	CONDUIT, 3 IN., RIGID, IN TRENCH	Material		3	Feb 16, 2024	SYSTEM	\$182.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					3	Feb 16, 2024	SYSTEM	(\$182.00)			
					4	Mar 4, 2024	SYSTEM	\$182.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					4	Mar 4, 2024	SYSTEM	(\$182.00)			
				- Total				\$0.00			
			Material - Total					\$0.00			
	0160 -	Total						\$0.00			
	0210	MISC. ITS	Material		1	Jan 16, 2024	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					1	Jan 16, 2024	SYSTEM	(\$600.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
			Overrun	Overrun	9	May 16, 2024	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
							9	May 16, 2024	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	May 16, 2024	SYSTEM	(\$4,200.00)			
				Overrun - Total				\$0.00			
			Overrun - Total					\$0.00			
	0210 -	Total						\$0.00			
	0250	MISC. ITS	Overrun	Overrun	9	May 16, 2024	SYSTEM	\$2,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user norton1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					9	May 16, 2024	SYSTEM	(\$2,120.00)			
				Overrun - Total				\$0.00			
			Overrun - T								
		Total						\$0.00 \$0.00			
	0250							φ0.00			



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
004745	0000			Туре				(\$7,000,00)	
6Q3174E	0280	MISC. ITS	Material		3	Feb 16, 2024	SYSTEM	(\$7,600.00)	
					4	Mar 4, 2024	SYSTEM	\$7,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Mar 4, 2024	SYSTEM	(\$7,600.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
			Overrun	Overrun	11	Jun 17, 2024	SYSTEM	(\$3,800.00)	
				Overrun - T	otal			(\$3,800.00)	
			Overrun - T	otal				(\$3,800.00)	
	0280 -	- Total						(\$3,800.00)	
	0330	MISC. ITS	Material		8	May 2, 2024	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	May 2, 2024	SYSTEM	(\$1,000.00)	
					9	May 16, 2024	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	May 16, 2024	SYSTEM	(\$1,000.00)	
				- Total				\$0.00	
			Material - To	Material - Total					
	0330 -	- Total						\$0.00	
	0340	MISC. ITS	Overrun	Overrun	8	May 2, 2024	SYSTEM	\$925.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	May 2, 2024	SYSTEM	(\$925.00)	
					9	May 16, 2024	SYSTEM	(\$925.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					9	May 16, 2024	SYSTEM	(\$925.00)	
					10	Jun 3, 2024	SYSTEM	\$1,850.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',925.00000 - 925.00000, 'i applied (if non-zero).
			Overrun - Total					\$0.00	
			Overrun - Total					\$0.00	
	0340 -	Total						\$0.00	
	0350	MISC. ITS	Overrun	Overrun	11	Jun 17, 2024	SYSTEM	(\$60.00)	
				Overrun - Total				(\$60.00)	
			Overrun - Total					(\$60.00)	
	0 <u>350</u> -	- Total						(\$60.00)	
	0820	MISC. ITS	Material		1	Jan 16, 2024	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
							SYSTEM	(\$600.00)	Lounded Exception 2 on the output Latinate.
					1	Jan 16, 2024	OTOTEM	(1.1.1.1.1)	
				Total	1	Jan 16, 2024	GTOTEM	. ,	
				- Total	1		OTOTEM	\$0.00	
			Material - To		1			\$0.00 \$0.00	
	0820 - 0920	- Total MISC. ITS			1		SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J6Q3174E	0920	MISC. ITS	Material	Туре	4	Mar 4,	SYSTEM	(00.090\$)	
J0Q3174E	0920	10130.113	Material		4	2024	STOTEM	(\$280.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	7	Apr 16, 2024	SYSTEM	\$7,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Apr 16, 2024	SYSTEM	(\$7,980.00)	
					9	May 16, 2024	SYSTEM	\$595.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	May 16, 2024	SYSTEM	(\$595.00)	
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0920	- Total						\$0.00	
	0990	MISC. ITS	Material		3	Feb 16,	SYSTEM	\$7,490.70	This adjustment offsets the original system-generated Material Payment
		Total				2024			Estimate Item Adjustment (0004) due to user norton1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Feb 16, 2024	SYSTEM	(\$7,490.70)	
					4	Mar 4, 2024	SYSTEM	\$33,660.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Mar 4, 2024	SYSTEM	(\$33,660.90)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0990 -	Total						\$0.00	
	0990 - 1000	Total MISC. ITS	Material		3	Feb 16, 2024	SYSTEM	\$0.00 \$17,670.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			Material		3 3		SYSTEM SYSTEM		Estimate Item Adjustment (0005) due to user norton1 overridding Payment
			Material			2024 Feb 16,		\$17,670.00	Estimate Item Adjustment (0005) due to user norton1 overridding Payment
			Material		3	2024 Feb 16, 2024 Mar 4,	SYSTEM	\$17,670.00 (\$17,670.00)	Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			Material	- Total	3	2024 Feb 16, 2024 Mar 4, 2024 Mar 4,	SYSTEM SYSTEM	\$17,670.00 (\$17,670.00) \$22,012.50	Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			Material Material - Te		3	2024 Feb 16, 2024 Mar 4, 2024 Mar 4,	SYSTEM SYSTEM	\$17,670.00 (\$17,670.00) \$22,012.50 (\$22,012.50)	Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3 4 4	2024 Feb 16, 2024 Mar 4, 2024 Mar 4,	SYSTEM SYSTEM	\$17,670.00 (\$17,670.00) \$22,012.50 (\$22,012.50) \$0.00	Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			Material - To	otal	3 4 4	2024 Feb 16, 2024 Mar 4, 2024 Mar 4, 2024	SYSTEM SYSTEM SYSTEM	\$17,670.00 (\$17,670.00) \$22,012.50 (\$22,012.50) \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			Material - To	otal	3 4 4 4 4	2024 Feb 16, 2024 Mar 4, 2024 Mar 4, 2024 Mar 4, 2024	SYSTEM SYSTEM SYSTEM	\$17,670.00 (\$17,670.00) \$22,012.50 (\$22,012.50) (\$22,012.50) \$0.00 \$0.00 \$3,262.50	Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			Material - To	otal	3 4 4 4 4 4	2024 Feb 16, 2024 Mar 4, 2024 Mar 4, 2024 Mar 4, 2024 Mar 4, 2024 Mar 4, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$17,670.00 (\$17,670.00) \$22,012.50 (\$22,012.50) (\$22,012.50) \$0.00 \$0.00 \$3,262.50 (\$3,262.50)	Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 7 on the current Payment Estimate.
			Material - To	otal	3 4 4 4 4 4 9	2024 Feb 16, 2024 Mar 4, 2024 Mar 4, 2024 Mar 4, 2024 Mar 4, 2024 May 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$17,670.00 (\$17,670.00) \$22,012.50 (\$22,012.50) (\$22,012.50) \$0.00 \$3,262.50 (\$3,262.50) (\$3,262.50) \$1,125.00	Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0008) due to user norton1 overridding Payment
			Material - To	otal	3 4 4 4 4 9 9	2024 Feb 16, 2024 Mar 4, 2024 Mar 4, 2024 Mar 4, 2024 Mar 4, 2024 May 16, 2024 May 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$17,670.00 (\$17,670.00) \$22,012.50 (\$22,012.50) (\$22,012.50) \$0.00 \$0.00 (\$3,262.50) (\$3,262.50) (\$3,262.50) \$1,125.00 \$6,795.00	Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0008) due to user norton1 overridding Payment
			Material - To	otal	3 4 4 4 9 9 9 9 9	2024 Feb 16, 2024 Mar 4, 2024 Mar 4, 2024 Mar 4, 2024 May 16, 2024 May 16, 2024 May 16, 2024 May 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$17,670.00 (\$17,670.00) \$22,012.50 (\$22,012.50) (\$22,012.50) \$0.00 \$0.00 \$3,262.50 (\$3,262.50) (\$3,262.50) \$1,125.00 \$6,795.00 (\$7,920.00)	Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0008) due to user norton1 overridding Payment
			Material - To	Overrun - T	3 4 4 4 9 9 9 9 9	2024 Feb 16, 2024 Mar 4, 2024 Mar 4, 2024 Mar 4, 2024 May 16, 2024 May 16, 2024 May 16, 2024 May 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$17,670.00 (\$17,670.00) \$22,012.50 (\$22,012.50) (\$22,012.50) \$0.00 \$0.00 \$3,262.50 (\$3,262.50) (\$3,262.50) \$1,125.00 \$6,795.00 (\$7,920.00) (\$1,470.00)	Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0008) due to user norton1 overridding Payment
	1000		Material - Te	Overrun - T	3 4 4 4 9 9 9 9 9	2024 Feb 16, 2024 Mar 4, 2024 Mar 4, 2024 Mar 4, 2024 May 16, 2024 May 16, 2024 May 16, 2024 May 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$17,670.00 (\$17,670.00) \$22,012.50 (\$22,012.50) (\$22,012.50) \$0.00 \$0.00 (\$3,262.50) (\$3,262.50) (\$3,262.50) (\$3,262.50) (\$1,125.00) (\$7,920.00) (\$1,470.00)	Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Item Adjustment (0008) due to user norton1 overridding Payment



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6Q3174E	1010	MISC. ITS	Material		1	Jan 16, 2024	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user norton1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Jan 16, 2024	SYSTEM	(\$700.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	1010	Total						\$0.00	
J6Q3174E	- Total						(\$5,330.00)		
Overall - To	otal							(\$5,330.00)	



There are no contract adjustments to display for this contract.