

## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 2, 2024

Progress Estim	nate Number	Contract ID 231117-F05 Prime Contractor Gerstner Ele	Pay Period Start March 1 ectric, Inc. Pay Period End April 1,	16, 2024 Original Contract Amount 2024 Net Change Order Amount Current Contract Amount	\$1,595,781.00 \$48,575.00 \$1,644,356.00			
Approval Date					By User			
April 2, 2024		Generated and	Approved (and should be considered	Draft) at the Project Office Level by	norton1			
April 2, 2024		Reviewed and Appro	oved (and should be considered Draft	t) at the Resident Engineer Level by	HELLET			
April 3, 2024			Reviewed and Approved at the Centr	ral Office Controllers Office Level by	ramses1			
Original Comp	letion Date	<b>Current Completion Date</b>	Actual Completion Date	% of Current Contract Amour	nt Complete			
December 31, 2024 December 31, 2024 16.18%								

	Contract Informational Dates													
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract											
Acceptance Date														
Awarded Date	December 6, 2023	December 6, 2023												
Letting Date	November 17, 2023	November 17, 2023												
Notice to Proceed Date	January 8, 2024	January 8, 2024												
Open to Traffic Date														
Work Began Date	January 11, 2024	January 11, 2024												

Contract Total Pay For Estimate No. 6										
		This Estimate	Previous	To Date						
231117-F05										
	Total Posted Items Pay	\$47,159.00	\$218,873.40	\$266,032.40						
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00						
	Incentive	\$0.00	\$0.00	\$0.00						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
	•		\$218,873.40	\$266,032.40						
Contract Total Pa	yable This Estimate:	\$47,159.00								

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6Q3174E	0140	9103700	CCTV CAMERA ASSEMBLY, INSTALLED	EA	\$830.000	2	\$1,660.00
	0210	9109902	MISC.ADVANCED DIAGNOSTICS	EA	\$150.000	36	\$5,400.00
	0250	9109902	MISC.F&I FIBER OPTIC FUSION SPLICE, SINGLE MODE	EA	\$20.000	6	\$120.00
	0280	9109902	MISC.F&I ITS PULL BOX CLASS 5 WITH CONCRETE PAD	EA	\$3,800.000	1	\$3,800.00
	0350	9109902	MISC.FIBER OPTIC TERMINATION	EA	\$30.000	6	\$180.00
	0520	9109902	MISC.INSTALL WIRELESS ETHERNET BRIDGE COMMUNICATION EQUIPMENT	EA	\$1,200.000	1	\$1,200.00
	0630	9109902	MISC.REMOVE CCTV CAMERA & ASSEMBLY	EA	\$120.000	2	\$240.00
	0820	9109902	MISC.TROUBLESHOOTING	EA	\$200.000	6	\$1,200.00
	0980	9109903	MISC.F&I CABLE IN CONDUIT: CAT5E OUTDOOR RATED CABLE	LF	\$2.000	260	\$520.00
	0990	9109903	MISC.F&I FIBER OPTIC CABLE, 24-STRAND SINGLE MODE	LF	\$3.150	900	\$2,835.00
	1030	9109902	MISC.PM AIR CONDITIONING UNITS FOR NODE CABINETS	EA	\$276.000	9	\$2,484.00
	1040	9109902	MISC.PM CCTV CAMERA, ASSEMBLY, POLE, & FIELD CABINET	EA	\$390.000	68	\$26,520.00
	1150	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV CAMERA	EA	\$1,000.000	1	\$1,000.00
Project J6Q	3174E - To	tal					\$47,159.00
Overall - To	tal						\$47,159.00

Revision 3/23/2023 Page 1 of 14



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 2, 2024

Progress Estimate Number
6
Contract ID 231117-F05 Pay Period Start March 16, 2024 Original Contract Amount \$1,595,781.00
Prime Contractor Gerstner Electric, Inc. Pay Period End April 1, 2024 Net Change Order Amount Current Contract Amount \$1,595,781.00
\$48,575.00\$

### **Contract Adjustments This Estimate**

No Contract Adjustments Exist on Contract

### Line Item Adjustments This Estimate

No Data Available

Revision 3/23/2023 Page 2 of 14



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information	1
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J6Q3174E	FAS S503(89)	ITS Maintenance	Various	ST LOUIS	at various locations in th	e St Louis District	
Γotals by Jo	b Numbers	ì					
J6Q3174E					This Estimate	Previous	To Date
		Item Pay tem Adjustmer	nts		\$47,159.00 \$0.00	\$218,873.40 \$0.00	\$266,032.40 \$0.00
			Gross Ite	m Pay	\$47,159.00	\$218,873.40	\$266,032.40
	Incentiv	re			\$0.00	\$0.00	\$0.00
	Disince	ntive			\$0.00	\$0.00	\$0.00
		ted Damages			\$0.00	\$0.00	\$0.00
	Other C	ontract Adjust	monto		\$0.00	\$0.00	\$0.00

Revision 3/23/2023 Page 3 of 14





# Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Revision 3/23/2023 Page 4 of 14



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ote: Posted Q	uantities a	nd Values	s are ba	sed on Re	port Generated date and can differ from the posted amou	unt at the t	ime the E	stimate was	Genera	ated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
231117-F05	J6Q3174E	0001	0010	2019902	MISCCLEARING, GRUBBING, MOWING & TREE CLEARING	5.00	0.00	5.00	EA	0.00	\$2,000.00	\$0.00
		0001	0020	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	3.00	0.00	3.00	EA	0.00	\$1,000.00	\$0.00
		0001	0030	6169901	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.00	\$30,000.00	\$0.00
		0001	0040	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN	3.00	0.00	3.00	EA	0.00	\$100.00	\$0.00
		0001	0050	6181000	(CONTRACTOR FURNISHED & RETAINED)  MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$70,000.00	\$0.00
		0030	0060	9028308	CABLE, 16 AWG 2 CONDUCTOR	500.00	0.00	500.00	LF	0.00	\$2.00	\$0.00
		0030	0070	9028309	CABLE, 16 AWG 3 CONDUCTOR	500.00	0.00	500.00	LF	0.00	\$2.00	\$0.00
		0030	0080	9028310	CABLE, 16 AWG 5 CONDUCTOR	500.00	0.00	500.00	LF	0.00	\$2.25	\$0.00
		0030	0090	9029902	MISC.INSTALL & CONFIGURE VIDEO DETECTION CAMERA	40.00	0.00	40.00	EA	8.00	\$650.00	\$5,200.00
		0030	0100	9029902	MISC.INSTALL AND CONFIGURE AUDIBLE PEDESTRIAN SYSTEM	70.00	0.00	70.00	EA	0.00	\$950.00	\$0.00
		0030	0110	9029902	MISC.REMOVAL OF AUDIBLE PEDESTRIAN SYSTEM	70.00	0.00	70.00	EA	0.00	\$90.00	\$0.00
		0030	0120	9029902	MISC.REMOVAL OF VIDEO DETECTION CAMERA	40.00	0.00	40.00	EA	8.00	\$350.00	\$2,800.00
		0030	0130	9029903	MISC.CABLE, 18 AWG 4 CONDUCTOR	500.00	0.00	500.00	LF	0.00	\$2.25	\$0.00
		0050	0140	9103700	CCTV CAMERA ASSEMBLY, INSTALLED	30.00	0.00	30.00	EA	7.00	\$830.00	\$5,810.00
		0050	0150	9105200	CONDUIT, 2 IN., RIGID, IN TRENCH	250.00	0.00	250.00	LF	95.00	\$11.00	\$1,045.00
		0050	0160	9105201	CONDUIT, 3 IN., RIGID, IN TRENCH	100.00	0.00	100.00	LF	13.00	\$14.00	\$182.00
		0050	0170	9105202	CONDUIT, 4 IN., RIGID, IN TRENCH	100.00	0.00	100.00	LF	0.00	\$17.00	\$0.00
		0050	0180	9107201	CONDUIT, 3 IN., RIGID, PUSHED	50.00	0.00	50.00	LF	0.00	\$24.00	\$0.00
		0050	0190	9107202	CONDUIT, 4 IN., RIGID, PUSHED	50.00	0.00	50.00	LF	0.00	\$26.00	\$0.00
		0050	0200	9108352	FIBER OPTIC CABLE, 24-STRAND, 18 SINGLE MODE, 6	500.00	0.00	500.00	LF	0.00	\$3.75	\$0.00
		0050	0210	9109902	MULTIMODE MISC.ADVANCED DIAGNOSTICS	500.00	100.00	600.00	EA	312.00	\$150.00	\$46,800.00
		0050	0220	9109902	MISC.DAKTRONICS' VANGUARD VX-2420 (DYNAMIC TRAIL BLAZER SIGN) PURCHASE	1.00	0.00	1.00	EA	0.00	\$15,750.00	\$0.00
		0050	0230	9109902	MISC.F&I CAMERA POLE (60FT) AND LOWERING SYSTEM	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0050	0240	9109902	MISC.F&I FIBER OPTIC FUSION SPLICE, MULTI MODE	50.00	0.00	50.00	EA	0.00	\$30.00	\$0.00
		0050	0250	9109902	MISC.F&I FIBER OPTIC FUSION SPLICE, SINGLE MODE	1,250.00	0.00	1,250.00	EA	492.00	\$20.00	\$9,840.00
		0050	0260	9109902	MISC.F&I ITS PULL BOX CLASS 1	2.00	0.00	2.00	EA	0.00	\$1,920.00	\$0.00
		0050	0270	9109902	MISC.F&I ITS PULL BOX CLASS 2 WITH CONCRETE PAD	2.00	0.00	2.00	EA	0.00	\$3,200.00	\$0.00
		0050	0280	9109902	MISC.F&I ITS PULL BOX CLASS 5 WITH CONCRETE PAD	2.00	2.00	4.00	EA	3.00	\$3,800.00	\$11,400.00
		0050	0290	9109902	MISC.F&I NON-INTRUSIVE VEHICLE DETECTOR POLE	5.00	0.00	5.00	EA	0.00	\$1,000.00	\$0.00
		0050	0300	9109902	MISC.F&I TYPE 1 ITS CABINET	1.00	0.00	1.00	EA	0.00	\$5,000.00	\$0.00
		0050	0310	9109902	MISC.F&I TYPE 2 ITS CABINET	1.00	0.00	1.00	EA	0.00	\$2,500.00	\$0.00
		0050	0320	9109902	MISC.F&I TYPE 5 ITS CABINET	1.00	0.00	1.00	EA	0.00	\$500.00	\$0.00
		0050	0330	9109902	MISC.F&I TYPE 7 ITS CABINET	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0050	0340	9109902	MISC.FIBER OPTIC SPLICE ENCLOSURE	6.00	6.00	12.00	EA	6.00	\$925.00	\$5,550.00
		0050	0350	9109902	MISC.FIBER OPTIC TERMINATION	150.00	0.00	150.00	EA	20.00	\$30.00	\$600.00
		0050	0360	9109902	MISC.INSTALL IN-PAVEMENT WIRELESS SENSORS	50.00	0.00	50.00	EA	0.00	\$50.00	\$0.00
		0050	0370	9109902	MISC.INSTALL NON-INTRUSIVE ACCESS POINT & ASSEMBLY	5.00	0.00	5.00	EA	0.00	\$325.00	\$0.00
		0050	0380	9109902	MISC.INSTALL NON-INTRUSIVE VEHICLE DETECTOR ASSEMBLY	15.00	0.00	15.00	EA	3.00	\$720.00	\$2,160.00
		0050	0390	9109902	MISC.INSTALL NON-INTRUSIVE WIRELESS REPEATER	5.00	0.00	5.00	EA	0.00	\$250.00	\$0.00
		0050	0400	9109902	MISC.INSTALL SALVAGED CAMERA POLE	1.00	0.00	1.00	EA	0.00	\$1,290.00	\$0.00
		0050	0410	9109902	MISC.INSTALL SALVAGED FIELD CABINET (DUAL)	1.00	0.00	1.00	EA	0.00	\$950.00	\$0.00
		0050	0420	9109902	MISC.INSTALL SALVAGED FIELD CABINET (SINGLE)	10.00	0.00	10.00	EA	0.00	\$650.00	\$0.00
		0050	0430	9109902	MISC.INSTALL SALVAGED NON-INTRUSIVE VEHICLE DETECTOR POLE	10.00	0.00	10.00	EA	2.00	\$1,000.00	\$2,000.00
		0050	0440	9109902	MISC.INSTALL SOLAR POWER SYSTEM	1.00	0.00	1.00	EA	0.00	\$5,300.00	\$0.00
		0050	0450	9109902	MISC.INSTALL SPREAD SPECTRUM WIRELESS	2.00	0.00	2.00	EA	0.00	\$120.00	\$0.00

Page 5 of 14 Revision 3/23/2023



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	port Generated date and can differ from the posted amou Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
231117-F05	J6Q3174E				COMMUNICATION EQUIPMENT							
		0050	0460	9109902	MISC.INSTALL UPS AUTOMATIC GENERATOR SWITCH	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0470	9109902	MISC.INSTALL UPS AUTOMATIC TRANSFER SWITCH	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0480	9109902	MISC.INSTALL UPS BATTERY	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0490	9109902	MISC.INSTALL UPS BATTERY MONITOR	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0500	9109902	MISC.INSTALL UPS POWER INVERTER	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0510	9109902	MISC.INSTALL UPS SYSTEM ASSEMBLY	10.00	0.00	10.00	EA	0.00	\$685.00	\$0.00
		0050	0520	9109902	MISC.INSTALL WIRELESS ETHERNET BRIDGE COMMUNICATION EQUIPMENT	5.00	0.00	5.00	EA	2.00	\$1,200.00	\$2,400.00
		0050	0530	9109902	MISC.ITS PULL BOX LID REPLACEMENT (32-INCH DIAMETER)	5.00	0.00	5.00	EA	0.00	\$800.00	\$0.00
		0050	0540	9109902	MISC.ITS PULL BOX LID REPLACEMENT (40.5 INCH DIAMETER)	5.00	0.00	5.00	EA	0.00	\$800.00	\$0.00
		0050	0550	9109902	MISC.PAD MOUNTED POWER SUPPLY, 120V ITS	2.00	0.00	2.00	EA	0.00	\$5,000.00	\$0.00
		0050	0560	9109902	MISC.PEDESTAL BASE FOR SENSYS REPEATER POLE	1.00	0.00	1.00	EA	0.00	\$720.00	\$0.00
		0050	0570	9109902	MISC.RACK MOUNTED INTERCONNECT CENTER	5.00	0.00	5.00	EA	0.00	\$800.00	\$0.00
		0050	0580	9109902	MISC.REMOVE & REPLACE DTB (DYNAMIC TRAIL BLAZER)	1.00	0.00	1.00	EA	0.00	\$5,865.00	\$0.00
					SIGN ASSEMBLY (16.5'-18' AT POLE)							
		0050	0590	9109902	MISC.REMOVE & REPLACE DTB (DYNAMIC TRAIL BLAZER) SIGN ASSEMBLY (30' AT POLE)	1.00	0.00	1.00	EA	0.00	\$5,865.00	\$0.00
		0050	0600	9109902	MISC.REMOVE & REPLACE DTB (DYNAMIC TRAIL BLAZER) SIGN FOUNDATION	1.00	0.00	1.00	EA	0.00	\$4,000.00	\$0.00
		0050	0610	9109902	MISC.REMOVE AND REPLACE UPS BATTERY	4.00	0.00	4.00	EA	0.00	\$120.00	\$0.00
		0050	0620	9109902	MISC.REMOVE CAMERA POLE	1.00	0.00	1.00	EA	0.00	\$750.00	\$0.00
		0050	0630	9109902	MISC.REMOVE CCTV CAMERA & ASSEMBLY	30.00	0.00	30.00	EA	6.00	\$120.00	\$720.00
		0050	0640	9109902	MISC.REMOVE COMMUNICATION FIELD CABINET (DOUBLE	1.00	0.00	1.00	EA	0.00	\$650.00	\$0.00
		0050	0650	9109902	CABINET) MISC.REMOVE COMMUNICATION NODE FIELD CABINET	1.00	0.00	1.00	EA	0.00	\$375.00	\$0.00
		0030			(SINGLE CABINET)							
		0050	0660	9109902	MISC.REMOVE IN-PAVEMENT WIRELESS SENSORS	50.00	0.00	50.00	EA	0.00	\$20.00	\$0.00
		0050	0670	9109902	MISC.REMOVE NON-INTRUSIVE ACCESS POINT & ASSEMBLY	5.00	0.00	5.00	EA	0.00	\$125.00	\$0.00
		0050	0680	9109902	MISC.REMOVE NON-INTRUSIVE VEHICLE DETECTOR ASSEMBLY	15.00	0.00	15.00	EA	2.00	\$120.00	\$240.00
		0050	0690	9109902	MISC.REMOVE NON-INTRUSIVE VEHICLE DETECTOR POLE	10.00	0.00	10.00	EA	1.00	\$475.00	\$475.00
		0050	0700	9109902	MISC.REMOVE NON-INTRUSIVE WIRELESS REPEATER	5.00	0.00	5.00	EA	0.00	\$150.00	\$0.00
		0050	0710	9109902	MISC.REMOVE SOLAR POWER SYSTEM	1.00	0.00	1.00	EA	0.00	\$900.00	\$0.00
		0050	0720	9109902	MISC.REMOVE UPS AUTOMATIC GENERATOR SWITCH	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0730	9109902	MISC.REMOVE UPS AUTOMATIC TRANSFER SWITCH	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0740	9109902	MISC.REMOVE UPS BATTERY	10.00	0.00	10.00	EA	0.00	\$120.00	\$0.00
		0050	0750	9109902	MISC.REMOVE UPS BATTERY MONITOR	1.00	0.00	1.00	EA	0.00	\$120.00	\$0.00
		0050	0760	9109902	MISC.REMOVE UPS POWER INVERTER	1.00	0.00	1.00	EA	0.00	\$120.00	\$0.00
		0050	0770	9109902	MISC.REMOVE UPS SYSTEM ASSEMBLY	10.00	0.00	10.00	EA	0.00	\$300.00	\$0.00
		0050	0780	9109902	MISC.REMOVE WIRELESS COMMUNICATION EQUIPMENT	2.00	0.00	2.00	EA	0.00	\$235.00	\$0.00
		0050	0790	9109902	MISC.SENSYS REPEATER POLE BASE ALUMINUM SQUARE	1.00	0.00	1.00	EA	0.00	\$720.00	\$0.00
		0050	0800	9109902	MISC.TB1-17 ALUMINUM BASE FOR RTMS POLE	1.00	1.00	2.00	EA	1.00	\$800.00	\$800.00
		0050	0810	9109902	MISC.TB3-17 ALUMINUM BASE FOR RTMS POLE	1.00	1.00	2.00	EA	1.00	\$875.00	\$875.00
		0050	0820	9109902	MISC.TROUBLESHOOTING	100.00	0.00	100.00	EA	23.00	\$200.00	\$4,600.00
		0050	0830	9109902	MISC.WALL MOUNTED INTERCONNECT CENTER	5.00	0.00	5.00	EA	0.00	\$800.00	\$0.00
		0050	0840	9109902	MISC.WRONG WAY ALERT SYSTEMS EQUIPMENT PURCHASE	2.00	0.00	2.00	EA	0.00	\$66,850.00	\$0.00
		0050	0850	9109902	MISC.WRONG WAY ALERT SYSTEMS INSTALLATION	2.00	0.00	2.00	EA	0.00	\$7,500.00	\$0.00
			0860	9109902	MISC.WRONG WAY ALERT SYSTEMS SOFTWARE AND	2.00	0.00	2.00	EA	0.00	\$9,915.00	\$0.00
		0050			CERTIFICATION BY TAPCO OF NEW INSTALLATION							
		0050	0870	9109903	MISC.CONDUIT, 2 IN., RIGID, PUSHED	250.00	0.00	250.00	LF	0.00	\$19.00	\$0.00
		0050	0880	9109903	MISC.CONDUIT, HIGH-DENSITY POLYETHYLENE, 2 IN., IN TRENCH	50.00	0.00	50.00	LF	0.00	\$11.00	\$0.00

Revision 3/23/2023 Page 6 of 14



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uanililes a	ind values	s are ba	ised on Re	port Generated date and can differ from the posted amou	int at the i	ime me E	stimate was	Genera	ileu.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
231117-F05	J6Q3174E	0050	0890	9109903	MISC.CONDUIT, HIGH-DENSITY POLYETHYLENE, 2 IN., PUSHED	300.00	0.00	300.00	LF	0.00	\$19.00	\$0.00
		0050	0900	9109903	MISC.F&I CABLE IN CONDUIT, #1/0 WIRE, VARIABLE CONDUCTORS	500.00	0.00	500.00	LF	0.00	\$4.20	\$0.00
		0050	0910	9109903	MISC.F&I CABLE IN CONDUIT, #14 WIRE, VARIABLE CONDUCTORS	250.00	0.00	250.00	LF	0.00	\$2.00	\$0.00
		0050	0920	9109903	MISC.F&I CABLE IN CONDUIT, #2 WIRE, VARIABLE CONDUCTORS	100.00	0.00	100.00	LF	80.00	\$3.50	\$280.00
		0050	0930	9109903	MISC.F&I CABLE IN CONDUIT, #2/0 WIRE, VARIABLE CONDUCTORS	100.00	0.00	100.00	LF	0.00	\$4.75	\$0.00
		0050	0940	9109903	MISC.F&I CABLE IN CONDUIT, #4 WIRE, VARIABLE CONDUCTORS	100.00	0.00	100.00	LF	0.00	\$2.50	\$0.00
		0050	0950	9109903	MISC.F&I CABLE IN CONDUIT, #6 WIRE, VARIABLE CONDUCTORS	500.00	0.00	500.00	LF	0.00	\$2.00	\$0.00
		0050	0960	9109903	MISC.F&I CABLE IN CONDUIT, #8 WIRE, VARIABLE CONDUCTORS	1,000.00	0.00	1,000.00	LF	0.00	\$1.50	\$0.00
		0050	0970	9109903	MISC.F&I CABLE IN CONDUIT, VIDEO COAXIAL CABLE	250.00	0.00	250.00	LF	0.00	\$2.00	\$0.00
		0050	0980	9109903	MISC.F&I CABLE IN CONDUIT: CAT5E OUTDOOR RATED CABLE	5,000.00	0.00	5,000.00	LF	260.00	\$2.00	\$520.00
		0050	0990	9109903	MISC.F&I FIBER OPTIC CABLE, 24-STRAND SINGLE MODE	17,000.00	0.00	17,000.00	LF	11,586.00	\$3.15	\$36,495.90
		0050	1000	9109903	MISC.F&I FIBER OPTIC CABLE. 72-STRAND SINGLE MODE		5,000.00	10,000.00	LF	5,870.00	\$3.75	\$22,012.50
			1010	9109903	MISC.F&I TRACE WIRE	7,000.00	0.00		LF			
		0050						7,000.00		1,400.00	\$2.00	\$2,800.00
		0051	1020	9109902	MISC.MODOT BURIED CABLE DRIVABLE DELINEATOR POST	70.00	0.00	70.00	EA	1.00	\$115.00	\$115.00
		0051	1030	9109902	MISC.PM AIR CONDITIONING UNITS FOR NODE CABINETS	64.00	0.00	64.00	EA	32.00	\$276.00	\$8,832.00
		0051	1040	9109902	MISC.PM CCTV CAMERA, ASSEMBLY, POLE, & FIELD CABINET	618.00	0.00	618.00	EA	232.00	\$390.00	\$90,480.00
		0051	1050	9109902	MISC.PM COMMUNICATION LINK AND ASSEMBLY	333.00	0.00	333.00	EA	0.00	\$145.00	\$0.00
		0051	1060	9109902	MISC.PM COMMUNICATION NODE FIELD CABINET	33.00	0.00	33.00	EA	0.00	\$440.00	\$0.00
		0051	1070	9109902	MISC.PM DMP, ASSEMBLY, POLES, FOUNDATION, AND CABINET	2.00	0.00	2.00	EA	0.00	\$440.00	\$0.00
		0051	1080	9109902	MISC.PM DMS, ASSEMBLY, POLE, FOUNDATION & FIELD CABINET	180.00	0.00	180.00	EA	0.00	\$450.00	\$0.00
		0051	1090	9109902	MISC.PM DTB (DYNAMIC TRAIL BLAZER) SIGN ASSEMBLY	15.00	0.00	15.00	EA	0.00	\$240.00	\$0.00
		0051	1100	9109902	MISC.PM NON-INTRUSIVE VEHICLE DETECTOR STATIONS (MICROWAVE)	297.00	0.00	297.00	EA	0.00	\$310.00	\$0.00
		0051	1110	9109902	MISC.PM SOLAR POWER SYSTEM	34.00	0.00	34.00	EA	0.00	\$220.00	\$0.00
		0051	1120	9109902	MISC.PM UNINTERRUPTIBLE POWER SUPPLY (UPS) AND ASSEMBLY	32.00	0.00	32.00	EA	0.00	\$220.00	\$0.00
		0051	1130	9109902	MISC.PM VIDEO DETECTION CAMERAS	645.00	0.00	645.00	EA	0.00	\$140.00	\$0.00
		0051	1140	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV CABLES AND WIRES	1.00	0.00	1.00	EA	0.00	\$440.00	\$0.00
		0051	1150	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV CAMERA	1.00	0.00	1.00	EA	1.00	\$1,000.00	\$1,000.00
		0051	1160	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV CAMERA, ASSEMBLY, POLE, & FIELD CABINET	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0051	1170	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV CONNECTORS	1.00	0.00	1.00	EA	0.00	\$375.00	\$0.00
		0051	1180	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV DEVICE SERVER	1.00	0.00	1.00	EA	0.00	\$1.00	\$0.00
		0051	1190	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV ENCODER	1.00	0.00	1.00	EA	0.00	\$1.00	\$0.00
		0051	1200	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV POLE ACCESS PANEL	1.00	0.00	1.00	EA	0.00	\$440.00	\$0.00
		0051	1210	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV POWER SUPPLY	1.00	0.00	1.00	EA	0.00	\$440.00	\$0.00
		0051	1220	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED CCTV SURGE PROTECTOR	1.00	0.00	1.00	EA	0.00	\$390.00	\$0.00
		0051	1230	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED DMP, ASSEMBLY, POLE, FOUNDATION, & FIELD CABINET	1.00	0.00	1.00	EA	0.00	\$440.00	\$0.00
		0051	1240	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED DMS CONTROLLER	1.00	0.00	1.00	EA	0.00	\$665.00	\$0.00
		0051	1250	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED DMS DRIVER BOARD	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
		0051	1260	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED DMS FAN	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
		0051	1270	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED DMS LCA	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
		0051	1280	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED DMS PIXEL BOARD	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
		0051	1290	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED DMS POWER	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
2					SUPPLY							

Page 7 of 14 Revision 3/23/2023



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
231117-F05	J6Q3174E	0051	1300	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED IP ADDRESSABLE POWER STRIP	1.00	0.00	1.00	EA	0.00	\$440.00	\$0.00
		0051	1310	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED SIGNAL VIDEO DETECTION CAMERA	1.00	0.00	1.00	EA	0.00	\$130.00	\$0.00
		0051	1320	9109902	MISC.PM WITH REPAIRS - MODOT APPROVED UPS DEVICE AND COMPONENTS	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
		0051	1330	9109902	MISC.PM WITH REPAIRS - MODOT SOLAR POWER SYSTEM	1.00	0.00	1.00	EA	0.00	\$550.00	\$0.00
		0051	1340	9109902	MISC.REMOVE AND REPLACE NODE CABINET AIR CONDITIONER SYSTEM	2.00	0.00	2.00	EA	0.00	\$12,100.00	\$0.00
		0051	1350	9109902	MISC.WRONG WAY ALERT SYSTEMS PREVENTATIVE MAINTENANCE, SOFTWARE & RECERTIFICATION	12.00	0.00	12.00	EA	0.00	\$7,900.00	\$0.00
	Project J60	Q3174E - To	tal Value	Posted to E	Date as of Report Generated Date							\$266,032.40
231117-F05 Ove	rall - Total V	alue Poste	d to Date	as of Repor	t Generated Date							\$266,032.40

Page 8 of 14 Revision 3/23/2023



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Project: J6Q3174E

-,	J6Q317	YL										
Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0140	9103700	CCTV CAMERA ASSEMBLY, INSTALLED	3/21/24	3/25/24	1.00	EA	IS270S020.8 SB I-270 at St. Charles Rock Road - Per IssueTrak Ticket #1886					-Remove and Replace CCTV along Southbound I-270 at St. Charles Rock Rd - Per IssueTrak Ticket #1886 - COMPLETE New S/N: BBA44F50C206
				3/25/24	1.00	EA	MO030W042.0 MO 30 at Sappington Rd - Per IssueTrak Ticket #1891					-Remove and Replace CCTV MO 30 @ Sappington - Per IssueTrak Ticket #1891 - COMPLETE -New S/N: B8A44F50C218
0210	9109902	MISC. ITS	3/18/24	3/21/24	5.00	EA	141S021.6 MO 141 North of Bowles - Per IssueTrak Ticket #2007					-Repair damaged Fiber at Southbound 141 DMS North of Bowles - Per IssueTrak Ticket #2007 - COMPLETE >Re-Terminated Control Cable, DMS is communicating now.
			3/20/24	3/25/24	2.00	EA	MO115E000.5 Route 115 @ Brown Road - Per IssueTrak Ticket #2034					-Arrived On-Site to Route 115 @ Brown Road for Class S ITS Pullbox Repair. HydroVac around Existing Box, Removed Existing Concrete Pad. Will Install New Box and Pour Pad tomorrow 3/21 - Per IssueTrak Ticket #2034 - NOT C
			3/21/24	3/25/24	4.00	EA	MO115E000.5 MO 115 at Brown Road - Per IssueTrak Ticket #2034					-Replaced ITS Class 5 Pullbox, Poured Box Pad at Rout 115 @ Brown Rd - Per IssueTrak Ticket #2034 - NOT COMPLETE
			3/27/24	4/1/24	2.00	EA	I-70 at Shady Springs Dr Per IssueTrak Ticket #2087					Investigate Fiber Damage along I-70 between CCTV Pole wio Cave Springs and Shady Springs Dr Signal Cabinet. Found Rodent damage inside a damaged Class Pullbox. Installed 900 LF of 24 Single Mode Fiber Optic. Cable, and Terminated 24 SM Fiber in Shady Springs Signal Cabinet. Will Complete splicing in CCTV Pole on 3/29 - Per Issue Trak Ticket Ey087 - NOT COMPLETE
			3/29/24	4/1/24	4.00	EA	MO141N012.6 Northbound 141 South of Woods Mill Rd - Per IssueTrak Ticket #2088					-Visited DMS Site NB MO 141 S/O Woods Mill Rd to Replace Pixel Boards, unable to access without TMA. Found 11 Panels with some pixels missing. Per IssueTrak Ticket #2088 - NOT COMPLETE
				4/1/24	8.00	EA	I-70 NOR at Shady Springs - Per IssueTrak Ticket #2087					-Completed Splicing along I-70 NOR at Shady Springs, Will need to Repair/Replace Class 2 Pull box to close out ticket Per IssueTrak Ticket #2087 - NOT COMPLETE
				4/1/24	11.00	EA	MO 100 East of Bopp Rd - Per IssueTrak Ticket #2094					Attempted to Install Tracer Wire along MO 100 between Bopp Rd and Lockett Rd (PB is located in front of shopping center). Span is roughly 875 LF. Gerstner Electric found a damaged conduit spot roughly 300 LF West of the Pullbox in front of the shopping center and were unable to install tracer despite multiple efforts. Will Return and Install Class 2 Pull Box in the middle of the span next week Per IssueTrak Ticket #2094 - NOT COMPLETE
0250	9109902	MISC. ITS	3/18/24	3/21/24	2.00	EA	141S021.6 MO 141 North of Bowles - Per IssueTrak Ticket #2007					-Repair damaged Fiber at Southbound 141 DMS North o Bowles - Per IssueTrak Ticket #2007 - COMPLETE >Re-Terminated Control Cable, DMS is communicating now.
			3/27/24	4/1/24	2.00	EA	I-70 at Shady Springs Dr Per IssueTrak Ticket #2087					-Investigate Fiber Damage along I-70 between CCTV Pole wlo Cave Springs and Shady Springs Dr Signal Cabinet. Found Rodent damage inside a damaged Class 2 Pullbox. Installed 900 LF of 24 Single Mode Fiber Optic Cable, and Terminated 24 SM Fiber in Shady Springs
			3/29/24	4/1/24	2.00	EA	I-70 NOR at Shady Springs - Per IssueTrak Ticket #2087					Signal Cabinet. Will Complete splicing in CCTV Pole on 3/29 - Per IssueTrak Ticket #2087 - NOT COMPLETE  -Completed Splicing along I-70 NOR at Shady Springs, Will need to Repair/Replace Class 2 Pull box to close ou ticket - Per IssueTrak Ticket #2087 - NOT
0280	9109902	MISC. ITS	3/20/24	3/25/24	0.00	EA	MO115E000.5 Route 115 @ Brown Road - Per IssueTrak Ticket #2034					COMPLETE  Arrived On-Site to Route 115 @ Brown Road for Class 5 ITS Pullbox Repair. HydroVac around Existing Box, Removed Existing Concrete Pad. Will Install New Box and Pour Pad tomorrow 3/21 - Per IssueTrak Ticket
			3/21/24	3/25/24	1.00	EA	MO115E000.5 MO 115 at Brown Road - Per IssueTrak Ticket #2034					#2034 - NOT COMPLETE  -Replaced ITS Class 5 Pullbox, Poured Box Pad at Rout 115 @ Brown Rd - Per IssueTrak Ticket #2034 - NOT COMPLETE
0350	9109902	MISC. ITS	3/18/24	3/21/24	2.00	EA	141S021.6 MO 141 North of Bowles - Per IssueTrak Ticket #2007					Repair damaged Fiber at Southbound 141 DMS North or Bowles - Per IssueTrak Ticket #2007 - COMPLETE >Re-Terminated Control Cable, DMS is communicating now.
			3/27/24	4/1/24	2.00	EA	I-70 at Shady Springs Dr Per IssueTrak Ticket #2087					-Investigate Fiber Damage along I-70 between CCTV Pole w/o Cave Springs and Shady Springs Dr Signal Cabinet. Found Rodent damage inside a damaged Class 2 Pullibox. Installed 900 LF of 24 Single Mode Fiber Optic
												Cable, and Terminated 24 SM Fiber in Shady Springs Signal Cabinet. Will Complete splicing in CCTV Pole on 3/29 - Per IssueTrak Ticket #2087 - NOT COMPLETE
			3/29/24	4/1/24	2.00	EA	I-70 NOR at Shady Springs - Per IssueTrak Ticket #2087					-Completed Splicing along I-70 NOR at Shady Springs, Will need to Repair/Replace Class 2 Pull box to close out ticketPer IssueTrak Ticket #2087 - NOT COMPLETE
0520	9109902	MISC. ITS	3/18/24	3/21/24	1.00	EA	IS044E289.6 I-44 @ Jefferson Ave / MO 100 @ Jefferson Ave					>Installed 2 EA Ubiquiti Radios, 190LF of Cat5E at MO 100 @ Jefferson Ave and 60LF of CAt5E at I-44 @ Jefferson Ave.
0630	9109902	MISC. ITS	3/21/24	3/25/24	1.00	EA	IS270S020.8 SB I-270 at St. Charles Rock Road - Per IssueTrak Ticket #1886					-Remove and Replace CCTV along Southbound I-270 at St. Charles Rock Rd - Per IssueTrak Ticket #1886 - COMPLETE New S/N: B8A44F50C206
				3/25/24	1.00	EA	MO030W042.0 MO 30 at Sappington Rd - Per IssueTrak Ticket #1891					-Remove and Replace CCTV MO 30 @ Sappington - Pe IssueTrak Ticket #1891 - COMPLETE -New S/N: B8A44F50C218
0820	9109902	MISC. ITS	3/18/24	3/21/24	1.00	EA	141S021.6 MO 141 North of Bowles - Per IssueTrak Ticket #2007					-Repair damaged Fiber at Southbound 141 DMS North o Bowles - Per IssueTrak Ticket #2007 - COMPLETE - Re-Terminated Control Cable, DMS is communicating now.
				3/21/24	1.00	EA	IS044E289.6 I-44 @ Jefferson Ave / MO 100 @ Jefferson Ave					>Installed 2 EA Ubiquiti Radios, 190LF of Cat5E at MO 100 @ Jefferson Ave and 60LF of CAt5E at I-44 @ Jefferson Ave.
			3/20/24	3/25/24	1.00	EA	MO115E000.5 Route 115 @ Brown Road - Per IssueTrak Ticket #2034					Arrived On-Site to Route 115 @ Brown Road for Class 5 ITS Pullbox Repair. HydroVac around Existing Box, Removed Existing Concrete Pad. Will Install New Box and Pour Pad tomorrow 3/21 - Per IssueTrak Ticket #2034 - NOT COMPLETE
			3/27/24	4/1/24	1.00	EA	I-70 at Shady Springs Dr Per IssueTrak Ticket #2087					-Investigate Fiber Damage along I-70 between CCTV Pole w/o Cave Springs and Shady Springs Dr Signal Cabinet. Found Rodent damage inside a damaged Class 2 Pullbox. Installed 900 LF of 24 Single Mode Fiber Optic Cable, and Terminated 24 SM Fiber in Shady Springs

Revision 3/23/2023 Page 9 of 14



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity		tion of detail, location and quantity of work.  Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0820	9109902	MISC. ITS						Mile		Mile		Signal Cabinet. Will Complete splicing in CCTV Pole on
			3/29/24	4/1/24	1.00	EA	MO 100 East of Bopp Rd - Per IssueTrak Ticket #2094					3/29 - Per IssueTrak Ticket #2087 - NOT COMPLETE Attempted to Install Tracer Wire along MO 100 between Bopp Rd and Lockett Rd (PB is located in front of shopping center). Span is roughly 875 LF. Gerstler shopping center). Span is roughly 875 LF. Gerstler where the property of the shopping center and we were unable to install tracer despite multiple efforts. Will Return and Install Class 2 PUII Box in the middle of the span next week Per IssueTrak Ticket #2094 - NOT COMPLETE
				4/1/24	1.00	EA	MO141N012.6 Northbound 141 South of Woods Mill Rd - Per IssueTrak Ticket #2088					-Visited DMS Site NB MO 141 S/O Woods Mill Rd to Replace Pixel Boards, unable to access without TMA. Found 11 Panels with some pixels missing - Per IssueTrak Ticket #2088 - NOT COMPLETE
0980	9109903	MISC. ITS	3/18/24	3/21/24	260.00	LF	IS044E289.6 I-44 @ Jefferson Ave / MO 100 @ Jefferson Ave					>Installed 2 EA Ubiquiti Radios, 190LF of Cat5E at MO 100 @ Jefferson Ave and 60LF of CAt5E at I-44 @ Jefferson Ave.
0990	9109903	MISC. ITS	3/27/24	4/1/24	900.00	LF	I-70 at Shady Springs Dr Per IssueTrak Ticket #2087					-Investigate Fiber Damage along I-70 between CCTV Pole w/o Cave Springs and Shady Springs D' Signal Cabinet, Found Rodent damage inside a damaged Class 2 Pullbox, Installed 900 LF of 24 Single Mode Fiber Optic Cable, and Terminated 24 SM Fiber in Shady Springs Signal Cabinet. Will Complete splicing in CCTV Pole on 329 - Per Issuze Triak Ticket 2937 - NOT COMPLETE
1030	9109902	MISC. ITS	3/27/24	4/1/24	6.00	EA	IS064E013.8 Node 14 I-64 e/o Missouri River IS270N016.6 Node 22 I-270 @ MO 364 SEQ IS044E261.3 Node 24 I-44 @ Six Flags IS044E247.0 Node 30 I-44 @ US 50 US050W217.6 Aux Node 01 MO 50 @ MO 47 North MO100E070.4 Aux Node 02 MO100 @ MO 47 SWQ					NO14 ISO64E013.8 I-64 e/o Missouri River Type 1 & 2 N024 ISS70ND16.6 I-270 @ M0 364 SEC Type 1 & 2 N024 ISO44E261.3 I-44 @ Six Flags Type 1 & 2 N030 ISO44E247.0 I-44 @ US 50 Type 1 & 2 Aux Node 01 US050W217.6 M0 50 @ M0 47 North Type 1 Aux Node M0 02 100E070.4 M0 100 @ M0 47 SWQ Type 1
			3/29/24	4/1/24	3.00	EA	IS270S019.9 Node 01 I-270 @ I-70 SWQ IS070W223.7 Node 15 I-70 @ MO 370 IS064E027.6 Node 27 I-64 @ Spoede					N001 IS270S019.9 I-270 @ I-70 SWQ N015 IS070W223.7 I-70 @ MO 370 N027 IS064E027.6 I-64 @ Spoede
1040	9109902	MISC. ITS	3/18/24	3/21/24	5.00	EA	IS044E289.6 I-44 at Jefferson SWQ MO180E007:9 MO 180 at Normandy MO180E008.3 MO 180 at Pennsylvania MO180E008.3 MO 180 at Kingsland MO180E009.6 MO 180 at Ogden					IS044E289.6 Camera - 60' I-44 at Jefferson SWQ MO180E007.9 Sig pole ext MO 180 at Normandy MO180E008.3 Sig pole ext NWQ MO 180 at Pennsylvania MO180E008.9 CL pole SEQ MO 180 at Kingsland MO180E009.6 Sig pole ext NEQ MO 180 at Ogden
			3/19/24	3/25/24	8.00	EA	MO180W002.2 MO 180 at Fee Fee MO180W005.1 MO 180 at Woodson MO180W005.7 MO 180 at Brown MO180W005.7 MO 180 at Brown MO180W005.0 MO 180 at McKlibbon MO180W0005.0 MO 180 at McKlibbon MO340W010.2 MO 340 at Timber Runo MO340W010.8 MO 340 at Ross-Questover MO340W010.8 MO 340 at Ross-Questover MO340W010.8 MO 340 at McKnight-Woodson					MO180W002.2 Sig pole ext MO 180 at Fee Fee MO180W005.1 CL pole NWO MO 180 at Woodson MO180W005.7 CL pole NEQ MO 180 at Swin MO180W005.7 CL pole NWO MO 180 at Brown MO180W005.0 CL pole NWO MO 180 at McKibbon MO380W006.0 CL pole NWO 4M at Timber Run MO340W010.8 Sig pole ext MO 340 at Timber Run MO340W012.9 Sig pole ext MO 340 at Schullte - Many MO340W016.8 Sig pole ext MO 340 at Schullte - Many MO340W016.8 Sig pole ext MO 340 at Schullte - Many MO340W016.8 Sig post ext MO 340 at McKnight-Woodson
			3/20/24	3/25/24	8.00	EA	IS064W021.9 I-64 at MO 141 NWQ IS064W022.9 I-64 at MO 141 NWQ IS064W022.6 I-64 at Ballas IS064W022.6 I-64 at Ballas IS064W032.0 I-64 at Big Bend IS064W033.7 I-64 at McCausland WB Ramps IS064W033.7 I-64 at McCausland WB Ramps IS064W034.1 I-64 at Causland IS064W036.1 I-64 at Kingshighway					18064W017.1 Camera - 50' I-64 East of Boones Crossing 18064W021.9 Camera - 60' I-64 at MO 141 NWQ 18064W021.9 Camera - 60' I-64 at Ballas 18064W026.9 Camera - 60' I-64 at Ballas 18064W026.9 Camera - 60' I-64 at Calyoto 18064W023.0 Camera - 60' I-64 at Kogato 18064W033.7 Sig Post ext I-64 at McCausland WB Ramps 18064W034.1 Camera - 50' I-64 at Cakland 18064W034.1 Camera - 50' I-64 at Kingshighway
			3/21/24	3/25/24	12.00	EA	IS2700200 A L270 at St Charles Rock Rd IS044E266 30 1-44 at Lewis Rd, IS044E266 30 1-44 at Lewis Rd, IS044E261 0 1-44 at Artire Rd, IS044E270 5 1-44 w/o MO 1-41 IS044E270 5 1-44 w/o MO 1-41 IS044E274 0 1-44 at Bowles Ave. IS044E284 1-44 at Jamieson Ave IS044V264 7 MO 109 at 5th IS044W270 0 1-44 East of Antire IS044W270 0 1-44 West of Ladded Station IS044W273 3 1-44 west of MO 141 IS044W273 3 1-44 west of Ladded Station					IS270S120 8 L-270 at St Chartes Rock Rd IS344E268-8 C Amer - 50" 1-44 at Lewis Rd . IS944E268-8 C Amer - 50" 1-44 at Lewis Rd . IS944E268-8 C Amer - 50" 1-44 at Arthris Rd . IS944E270.5 C Amera - 40" 1-44 w/o MO 141 . IS944E270.5 C Amera - 40" 1-44 w/o MO 141 . IS944E270.5 C Amera - 50" 1-44 at Bowles Ave . IS944E284.4 C Amera - 50" 1-44 at Bowles Ave . IS944E284.4 C Amera - 50" 1-44 at Jamieson Ave . IS944W270.0 C Amera - 40" 1-44 East of Antire . IS944W270.0 C Amera - 60" 1-44 West of MO 141 . IS944W273.3 C Amera - 60" 1-44 at Maritz North . IS944W273.3 C Amera - 60" 1-44 at West of MO 141 . IS944W273.3 C Amera - 60" 1-44 West of Mo 141 . IS944
			3/22/24	3/27/24	7.00	EA	ISO44256.8 I-44 at Pacific/Viaduct St ISO44W257.9 I-44 East of Pacific-Viaduct ISO44W259.2 I-44 West of St. Piags MO100W095.5 MO 100 at MO 109 MO10SN007.9 MO 109 at Old State MO10SN007.8 MO 109 at Legends MO10SN011.8 MO 109 at Legends MO10SN011.1 MO 109 at FF-W					IS044E256.8 Camera - 70" 1-44 at Pacific/Viaduct St IS044W257.9 Camera - 70" 1-44 East of Pacific-Viaduct IS044W259.2 Camera - 70" 1-44 West of Six Flags MO100W095.9 Camera - 50" MO 100 at MO 109 MO109M007.9 Sig pole ext Nec MO 109 at Old State MO109M017.3 ISg Pole ext MO 109 at Legends MO109M017.3 ISg Pole ext MO 109 at FF-W
			3/25/24	4/1/24	7.00	EA	ISO44E253.6 I-44 Statewide at MO 100, Gray Summit S044W252.2 I-44 East of MO 100-AT ISO44W255.1 I-44 East of MO 100 Gray Summit ISO44W255.0 I-44 West of Lamar Pkw 15044W255.0 I-44 West of Lamar Pkw 15044W251.3 I-44 at Alleinton/Six Flags Upper CCTV ISO44W251.3 I-44 at Alleinton/Six Flags Lower CCTV ISO44W254.1 I-44 West of MO 109					ISO44E253.8 Camera - 50' wILD I-44 Statewide at MO 100, Gray Summit 100, Gray Summit 150.44W/252.2 Camera - 60' I-44 East of MO 100-AT 150.44W/255.1 Camera - 60' I-44 East of MO 100 Gray Summit 150.44W/256.0 Camera - 60' I-44 West of Lamar Pkwy 150.44W/256.1 Camera - 50' I-44 at Allenton/Six Flags Upper CCTV 150.44W/256.1 Camera - 50' I-44 at Allenton/Six Flags Lower CCTV 150.44W/256.1 Camera - 40' I-44 West of MO 109
			3/26/24	4/1/24	6.00	EA	IS044W247.0 I-44 at US 50 Union exit IS044W251.7 I-44 at MO 100-AT IS044E225.0 I-44 at Sullivan MM225.0 IS044E225.9 I-44 at MO 185/AF EB Ramps MO185S031.2 MO 185 at elmont MO185S031.2 MO 185 at Springfield					IS044W247.0 Camera - 50' w/LD I-44 at US 50 Union exit IS044W251.7 Camera - 50' w/LD I-44 at MO 100-AT IS044E25.0 I-44 at SUlfox MM225.0 IS044E225.9 I-44 at MO 185/AF EB Ramps MO185S031.2 Camera - 50' w/LD MO 185 at elmont MO185S031.2 Sig Pole Ext MO 185 at Springfield
			3/27/24	4/1/24	9.00	EA	ISO44E280.8 I-44 West of MO 100 - AT ISO44E283.3 I-44 East of Six Flags ISO44E284.7 I-44 at MO 109 ISO44E286.0 I-44 West of Lewis Rd. ISO44E286.0 I-44 elo LS 61-US 67 ISO44E280.1 I-44 elo LS 61-US 67 ISO44E280.1 I-44 elo LS 61-US 67 ISO44E280.3 I-44 at Elm Ave lower ISO44E280.3 I-44 at Elm Ave lower ISO44E280.3 I-44 elo Elm Ave lower ISO44E280.3 I-44 elo Elm Ave ISO44E281.3 ISO44					IS044E250.8 Camera - 50' I-44 West of MO 100 - AT IS044E283.3 Camr - 60' (CA-2956) I-44 East of Six Flags IS044E284.7 Camera - 50' I-44 at MO 109 IS044E286.0 Camera - 60' I-44 West of Lewis Rd. IS044E278.2 Camera - 50' I-44 elo Borry Rd IS044E278.0 Camera - 40' I-144 elo Borry Rd IS044E280.1 Camera - 40' I-44 elo Borry Rd IS044E280.9 Colo (CAS250 75) I-44 at Elim Ave IS044E280.9 lower on 60' pole I-44 at Elim Ave IS044E280.9 Lowera - 60' I-44 elo Elim Ave
				4/1/24	6.00	EA	MO340E002.6 MO 340 lat Wilson-Clarkson Woods MO340E009.9 MO 340 at Fee Fee / Rue La Ville MO340E011.8 MO 340 at New Ballas MO340W002.2 MO 340 at Frosei MO340W002.2 MO 340 at Clayton MO340W002.0 MO 340 at Kehrs Mill					MO340E002.6 Sig pole ext MO 340 at Wilson-Clarkson Woods MO340E009.9 Sig pole ext MO 340 at Fee Fee / Rue La Ville MO340E011.8 Camera - 50' MO 340 at New Ballas MO340W002.4 MO 340 at Freesel MO340W000.8 Sig pole ext SEO MO 340 at Clayton MO340W000.0 Sig pole ext MO 340 at Kehs Mili
1150	9109902	MISC. ITS	3/18/24	3/21/24	1.00	EA	MO180W009.4 CL pole MO 180 at Lucas-Hunt					-Arrived at CCTV Location Route 180 @ Lucas and Hunt, found Axis Q6315-LE was malfunctioning after hitting preset buttons. Camera would go to preset location and float towards the sky. Verified that MoDOT wanted to

Revision 3/23/2023 Page 10 of 14



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Line Number	Item Code	Description	DWR Date	Quantity Posted	Location	From Station/ Log Mile	Offset/ Distance	Offset/ Distance	Comments
									replace with Q6075. -New Camera S/N: B8A44F50C03C

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 3/23/2023 Page 11 of 14



## Line Item Adjustments by Estimate

Contract ID: 231117-F05

Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J6Q3174E	0150	CONDUIT, 2 IN., RIGID, IN TRENCH	Material		2	Feb 1, 2024	SYSTEM	\$55.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Feb 1, 2024	SYSTEM	(\$55.00)	
					3	Feb 16, 2024	SYSTEM	\$55.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Feb 16, 2024	SYSTEM	(\$55.00)	
					4	Mar 4, 2024	SYSTEM	\$1,045.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Mar 4, 2024	SYSTEM	(\$1,045.00)	
				- Total				\$0.00	
			Material - To	Material - Total				\$0.00	
	0150	- Total						\$0.00	
	0160	CONDUIT, 3 IN., RIGID, IN TRENCH	Material		3	Feb 16, 2024	SYSTEM	\$182.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Feb 16, 2024	SYSTEM	(\$182.00)	
					4	Mar 4, 2024	SYSTEM	\$182.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Mar 4, 2024	SYSTEM	(\$182.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0160 -	- Total						\$0.00	
	0210	MISC. ITS	Material		1	Jan 16, 2024	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Jan 16, 2024	SYSTEM	(\$600.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0210 -	- Total						\$0.00	
	0280	MISC. ITS	Material		3	Feb 16, 2024	SYSTEM	\$7,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user norton1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Feb 16, 2024	SYSTEM	(\$7,600.00)	
					4	Mar 4, 2024	SYSTEM	\$7,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Mar 4, 2024	SYSTEM	(\$7,600.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0280 -	- Total							
	0820	MISC. ITS	Material		1	Jan 16, 2024	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Jan 16, 2024	SYSTEM	(\$600.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0820 - Total						\$0.00		



## Line Item Adjustments by Estimate

Contract ID: 231117-F05

Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
			,,	Type			,		
6Q3174E	0920	MISC. ITS	Material		4	Mar 4, 2024	SYSTEM	\$280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user norton1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Mar 4, 2024	SYSTEM	(\$280.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0920 -	0920 - Total						\$0.00	
	0990	MISC. ITS	Material		3	Feb 16, 2024	SYSTEM	\$7,490.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user norton1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Feb 16, 2024	SYSTEM	(\$7,490.70)	
					4	Mar 4, 2024	SYSTEM	\$33,660.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Mar 4, 2024	SYSTEM	(\$33,660.90)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0990 -	· Total						\$0.00	
	1000	MISC. ITS	Material		3	Feb 16, 2024	SYSTEM	\$17,670.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user norton1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Feb 16, 2024	SYSTEM	(\$17,670.00)	
					4	Mar 4, 2024	SYSTEM	\$22,012.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user norton1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	Mar 4, 2024	SYSTEM	(\$22,012.50)	
				- Total				\$0.00	
			Material - Total					\$0.00	
			Overrun	Overrun	4	Mar 4, 2024	SYSTEM	\$3,262.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user norton1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Mar 4, 2024	SYSTEM	(\$3,262.50)	
				Overrun - Total				\$0.00	
			Overrun - To	Overrun - Total				\$0.00	
	1000 - Total							\$0.00	
	1010	MISC. ITS	Material		1	Jan 16, 2024	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user norton1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Jan 16, 2024	SYSTEM	(\$700.00)	
			- Total					\$0.00	
			Material - Total					\$0.00	
	1010 - Total							\$0.00	
J6Q3174E - Total									
Overall - To								\$0.00 \$0.00	
							Ų0.00		

## MoDOT

## Contract Adjustments for Contract - 231117-F05

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 14 of 14