

Pay Estimate Created Date: October 16, 2024

Progress Estir 6			119-C01 er Electric Co	mpany, Inc.		October 15, 2024 Ne	iginal Contract Amoun It Change Order Amour Irrent Contract Amount	nt \$0.00			
Approval Date								By User			
October 16, 2024		Generated and Approved (and should be considered Draft) at the Project Office Level by									
October 16, 2024		Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by									
October 17, 2024		Reviewed and Approved at the Central Office Controllers Office Level by									
Original Com	pletion Date	Current Complet	ion Date	Actua	Completion Date	% of Cu	rrent Contract Amount	Complete			
Novembe	r 1, 2024	November 1,	2024	1			94.72%				
Co	ontract Informati	onal Dates		Milestones							
Date Description	Original Completion D	Current cate Completion Date		Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days			
Acceptance Date			Milestor Calenda		October 9, 2024	October 9, 2024	Milestone Complete				
Awarded Date	February 14, 20	)24 February 14, 2024	4								
Letting Date	January 19, 202	24 January 19, 2024									
Notice to Proceed Date	March 11, 2024	March 11, 2024									
Open to Traffic Date	March 11, 2024	March 11, 2024									
Work Began Date	July 17, 2024	July 17, 2024									

Contract Total Pay	For Estimate No. 6				
		This Estimate	Previous	To Date	
240119-C01					
	Total Posted Items Pay	\$33,811.50	\$788,570.00	\$822,381.50	
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$788,570.00	\$822,381.50	
<b>Contract Total Pay</b>	able This Estimate:	\$33,811.50			

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J3P3085H	0180	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$2.100	353	\$741.30
	0190	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$2.100	242	\$508.20
	0360	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	LF	\$12.000	592	\$7,104.00
	0380	9015010	TRENCHING TYPE I	LF	\$6.500	376	\$2,444.00
	0400	9017002	CABLE, 2 AWG 1 CONDUCTOR	LF	\$3.100	60	\$186.00
	0410	9017008	CABLE, 8 AWG 1 CONDUCTOR	LF	\$1.450	3,358	\$4,869.10
	0420	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	LF	\$1.000	120	\$120.00
	0430	9017202	WIRE, 2 AWG, BARE NEUTRAL		\$3.100	30	\$93.00
	0440	9017208	WIRE, 8 AWG, BARE NEUTRAL	LF	\$1.450	1,674	\$2,427.30
	0450	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	LF	\$5.520	455	\$2,511.60
	0580	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	LF	\$14.000	367	\$5,138.00
	0600	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	LF	\$1.450	1,060	\$1,537.00
	0610	9028311	CABLE, 16 AWG 7 CONDUCTOR	LF	\$1.400	4,380	\$6,132.00
roject J3P	<mark>3085Н - То</mark>	tal					\$33,811.50
Overall - To	tal						\$33,811.50

Revision 3/23/2023 Page 1 of 28



Pay Estimate Created Date: October 16, 2024

**Progress Estimate Number** 6

Contract ID240119-C01Pay Period StartOctober 1, 2024Original Contract Amount\$868,231.65Prime ContractorMeyer Electric Company, Inc.Pay Period EndOctober 15, 2024Net Change Order Amount\$0.00Current Contract Amount\$868,231.65

#### **Contract Adjustments This Estimate**

Project	Line	Item Description	Adjustment	Other Item	Comments	Adjustment	Line Item	Adjustment
Number	No.		Туре	Adjustment Type		Quantity	Adjustment Unit Price	amount
3P3085H	0030	EMBANKMENT IN PLACE	Material			-1,439	\$36.80	(\$52,955.20
	0030	EMBANKMENT IN PLACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 1 on the current Payment Estimate.	1,439	\$36.80	\$52,955.20
	0040	COMPACTING EMBANKMENT	Material			-125	\$37.00	(\$4,625.00
	0040	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.	125	\$37.00	\$4,625.00
	0050	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-285	\$21.00	(\$5,985.00
	0050	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 3 on the current Payment Estimate.	285	\$21.00	\$5,985.00
	0070	IMPACT ATTENUATOR 45 MPH (SAND BARREL ARRAY)	Material			-1	\$1,890.00	(\$1,890.00
	0070	IMPACT ATTENUATOR 45 MPH (SAND BARREL ARRAY)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 8 on the current Payment Estimate.	1	\$1,890.00	\$1,890.00
	0800	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	Material			-1	\$3,990.00	(\$3,990.00
	0080	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.	1	\$3,990.00	\$3,990.00
	0100	CONSTRUCTION SIGNS	Material			-303	\$20.00	(\$6,060.00
	0100	CONSTRUCTION SIGNS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user hargrr overridding Payment Estimate Exception 10 on the current Payment Estimate.	303	\$20.00	\$6,060.00
	0110	CHANNELIZER (TRIM LINE)	Material			-80	\$55.00	(\$4,400.00)
	0110	CHANNELIZER (TRIM LINE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user hargrr overridding Payment Estimate Exception 11 on the current Payment Estimate.	80	\$55.00	\$4,400.00
	0120	FLASHING ARROW PANEL	Material			-1	\$1,800.00	(\$1,800.00
	0120	FLASHING ARROW PANEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user hargrr overridding Payment Estimate Exception 12 on the current Payment Estimate.	1	\$1,800.00	\$1,800.00
	0130	TEMPORARY TRAFFIC BARRIER ANCHORED,	Material			-412	\$58.80	(\$24,225.60)



Pay Estimate Created Date: October 16, 2024

Progress Estimate Number 6

Contract ID 240119-C01 Pay Period Start October 1, 2024 Original Contract Amount \$868,231.65

Prime Contract ID 240119-C01 Pay Period End October 15, 2024 Net Change Order Amount \$0.00

Current Contract Amount \$868,231.65

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3P3085H		CONTRACTOR FURNISHED / RETAINED						
	0130	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user hargrr overridding Payment Estimate Exception 13 on the current Payment Estimate.	412	\$58.80	\$24,225.60
	0160	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-163	\$28.90	(\$4,710.70
	0160	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user hargrr overridding Payment Estimate Exception 14 on the current Payment Estimate.	163	\$28.90	\$4,710.70
	0170	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			-6	\$345.00	(\$2,070.00
	0170	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate.	6	\$345.00	\$2,070.00
	0180	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-1,761	\$2.10	(\$3,698.10
	0180	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user hargrr overridding Payment Estimate Exception 16 on the current Payment Estimate.	1,761	\$2.10	\$3,698.10
	0190	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-1,210	\$2.10	(\$2,541.00
	0190	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user hargrr overridding Payment Estimate Exception 18 on the current Payment Estimate.	1,210	\$2.10	\$2,541.00
	0240	MULCHING	Material			-0.1	\$10,000.00	(\$1,000.00
	0240	MULCHING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user hargrr overridding Payment Estimate Exception 20 on the current Payment Estimate.	0.1	\$10,000.00	\$1,000.00
	0255	SEEDING - COOL SEASON GRASSES	Material			-0.4	\$7,500.00	(\$3,000.00
	0255	SEEDING - COOL SEASON GRASSES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user hargrr overridding Payment Estimate Exception 21 on the current Payment Estimate.	0.4	\$7,500.00	\$3,000.00
	0260	SEDIMENT TRAP ROCK	Material			-1	\$385.00	(\$385.00
	0260	SEDIMENT TRAP ROCK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user hargrr	1	\$385.00	\$385.00

Revision 3/23/2023 Page 3 of 28



Pay Estimate Created Date: October 16, 2024

Progress Estimate Number 6

Contract ID 240119-C01 Pay Period Start October 1, 2024 Original Contract Amount \$868,231.65

Prime Contract ID 240119-C01 Pay Period End October 15, 2024 Net Change Order Amount \$0.00

Current Contract Amount \$868,231.65

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3P3085H					overridding Payment Estimate Exception 23 on the current Payment Estimate.			
	0300	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material			-375	\$34.20	(\$12,825.00
	0300	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user hargrr overridding Payment Estimate Exception 5 on the current Payment Estimate.	375	\$34.20	\$12,825.00
	0310	MGS HEIGHT AND BLOCK TRANSITION	Material			-1	\$735.00	(\$735.00
	0310	MGS HEIGHT AND BLOCK TRANSITION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate.	1	\$735.00	\$735.00
	0320	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	Material			-4	\$3,527.00	(\$14,108.00
	0320	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user hargrr overridding Payment Estimate Exception 24 on the current Payment Estimate.	4	\$3,527.00	\$14,108.00
	0330	BRACKET ARM, 15 FT. OR 4.6 M	Material			-4	\$1,352.00	(\$5,408.00
	0330	BRACKET ARM, 15 FT. OR 4.6 M	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user hargrr overridding Payment Estimate Exception 25 on the current Payment Estimate.	4	\$1,352.00	\$5,408.00
	0350	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	Material			-1	\$8,500.00	(\$8,500.00)
	0350	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user hargrr overridding Payment Estimate Exception 26 on the current Payment Estimate.	1	\$8,500.00	\$8,500.00
	0400	CABLE, 2 AWG 1 CONDUCTOR	Material			-60	\$3.10	(\$186.00
	0400	CABLE, 2 AWG 1 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user hargrr overridding Payment Estimate Exception 27 on the current Payment Estimate.	60	\$3.10	\$186.00
	0410	CABLE, 8 AWG 1 CONDUCTOR	Material			-5,626	\$1.45	(\$8,157.70
	0410	CABLE, 8 AWG 1 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user hargrr overridding Payment Estimate Exception 28 on the current Payment Estimate.	5,626	\$1.45	\$8,157.70
	0420	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material			-480	\$1.00	(\$480.00
	0420	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0025) due to user hargrr overridding Payment Estimate Exception 29	480	\$1.00	\$480.00

Revision 3/23/2023 Page 4 of 28



Pay Estimate Created Date: October 16, 2024

Progress Estimate Number
6
Contract ID 240119-C01 Pay Period Start October 1, 2024 Original Contract Amount \$868,231.65
Pay Period End October 15, 2024 Net Change Order Amount \$0.00
Current Contract Amount \$868,231.65

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3P3085H					on the current Payment Estimate.			
	0430	WIRE, 2 AWG, BARE NEUTRAL	Material			-30	\$3.10	(\$93.00)
	0430	WIRE, 2 AWG, BARE NEUTRAL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user hargrr overridding Payment Estimate Exception 30 on the current Payment Estimate.	30	\$3.10	\$93.00
	0440	WIRE, 8 AWG, BARE NEUTRAL	Material			-2,808	\$1.45	(\$4,071.60)
	0440	WIRE, 8 AWG, BARE NEUTRAL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Exception 31 on the current Payment Estimate.	2,808	\$1.45	\$4,071.60
	0450	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	Material			-4,370	\$5.52	(\$24,122.40)
	0450	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0028) due to user hargrr overridding Payment Estimate Exception 32 on the current Payment Estimate.	4,370	\$5.52	\$24,122.40
	0470	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING AND SIGNALS	Material			-1	\$8,500.00	(\$8,500.00)
	0470	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING AND SIGNALS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user hargrr overridding Payment Estimate Exception 33 on the current Payment Estimate.	1	\$8,500.00	\$8,500.00
	0480	SIGNAL HEAD, TYPE 3S	Material			-1	\$977.00	(\$977.00)
	0480	SIGNAL HEAD, TYPE 3S	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Exception 34 on the current Payment Estimate.	1	\$977.00	\$977.00
	0490	SIGNAL HEAD, TYPE 3B	Material			-13	\$1,215.00	(\$15,795.00)
	0490	SIGNAL HEAD, TYPE 3B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0030) due to user hargrr overridding Payment Estimate Exception 35 on the current Payment Estimate.	13	\$1,215.00	\$15,795.00
	0500	SIGNAL HEAD, TYPE 4B	Material			-2	\$1,418.00	(\$2,836.00)
	0500	SIGNAL HEAD, TYPE 4B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0031) due to user hargrr overridding Payment Estimate Exception 36 on the current Payment Estimate.	2	\$1,418.00	\$2,836.00
	0510	SH-FLAT SHEET - SIGNAL SIGN	Material			-15	\$45.00	(\$675.00)
	0510	SH-FLAT SHEET - SIGNAL SIGN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0032) due to user hargrr overridding Payment Estimate Exception 37 on the current Payment Estimate.	15	\$45.00	\$675.00
	0530	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	Material			-2	\$14,500.00	(\$29,000.00)

Revision 3/23/2023 Page 5 of 28



Pay Estimate Created Date: October 16, 2024

Progress Estimate Number 6 Contract ID 240119-C01 Pay Period Start October 1, 2024 Original Contract Amount \$868,231.65 Pay Period End October 15, 2024 Net Change Order Amount \$0.00 Current Contract Amount \$868,231.65

nber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
085H	0530	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0033) due to user hargrr overridding Payment Estimate Exception 38 on the current Payment Estimate.	2	\$14,500.00	\$29,000.00
	0540	POST, TYPE B, LONGEST ARM 40 FT. OR 12.2 M	Material			-1	\$22,345.00	(\$22,345.00
	0540	POST, TYPE B, LONGEST ARM 40 FT. OR 12.2 M	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0034) due to user hargrr overridding Payment Estimate Exception 39 on the current Payment Estimate.	1	\$22,345.00	\$22,345.00
	0550	POST, TYPE B, LONGEST ARM 55 FT.	Material			-1	\$26,036.00	(\$26,036.00
	0550	POST, TYPE B, LONGEST ARM 55 FT.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0035) due to user hargrr overridding Payment Estimate Exception 40 on the current Payment Estimate.	1	\$26,036.00	\$26,036.00
	0560	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	Material			-1	\$20,495.00	(\$20,495.00
	0560	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0036) due to user hargrr overridding Payment Estimate Exception 41 on the current Payment Estimate.	1	\$20,495.00	\$20,495.00
	0570	VIDEO DETECTION SYSTEM	Material			-1	\$47,798.00	(\$47,798.00
	0570	VIDEO DETECTION SYSTEM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0037) due to user hargrr overridding Payment Estimate Exception 42 on the current Payment Estimate.	1	\$47,798.00	\$47,798.00
	0600	CABLE, 8 AWG 1 CONDUCTOR, POWER	Material			-1,060	\$1.45	(\$1,537.00
	0600	CABLE, 8 AWG 1 CONDUCTOR, POWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0038) due to user hargrr overridding Payment Estimate Exception 43 on the current Payment Estimate.	1,060	\$1.45	\$1,537.00
	0610	CABLE, 16 AWG 7 CONDUCTOR	Material			-4,380	\$1.40	(\$6,132.00
	0610	CABLE, 16 AWG 7 CONDUCTOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0039) due to user hargrr overridding Payment Estimate Exception 44 on the current Payment Estimate.	4,380	\$1.40	\$6,132.00
	0620	POWER SUPPLY ASSEMBLY, TYPE 2	Material			-1	\$8,500.00	(\$8,500.00
C	0620	POWER SUPPLY ASSEMBLY, TYPE 2	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0040) due to user hargrr overridding Payment Estimate Exception 45 on the current Payment Estimate.	1	\$8,500.00	\$8,500.00
	0690	SH-FLAT SHEET	Material			-45	\$22.50	(\$1,012.50)
	0690	SH-FLAT SHEET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0041) due to user hargrr overridding Payment Estimate Exception 46	45	\$22.50	\$1,012.50

Revision 3/23/2023 Page 6 of 28



Pay Estimate Created Date: October 16, 2024

Progress Estimate Number  6 Contract ID 240119-C01  Prime Contractor Meyer Electric Compan				Pay Period Start October 1, 2024 Orny, Inc. Pay Period End October 15, 2024 Ne Cu	\$868,231.65 \$0.00 \$868,231.65				
Project Number	Line No.	Item De	scription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J3P3085H						on the current Payment Estimate.			
	0700	ST-	STRUCTURAL	Material			-264	\$32.80	(\$8,659.20)
	0700	ST-	STRUCTURAL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0042) due to user hargrr overridding Payment Estimate Exception 47 on the current Payment Estimate.	264	\$32.80	\$8,659.20
Total									\$0.00

Revision 3/23/2023 Page 7 of 28



					(	Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J3P3085H	FAF - 13-3(89)	Intersection improvements	I-70	LAFAYETTE	at Route 13		
Totals by J	ob Number	s					
J3P3085H					This Estimate	Previous	To Date
		Item Pay Item Adjustmen	ts		\$33,811.50 \$0.00	\$788,570.00 \$0.00	\$822,381.50 \$0.00
				em Pay	\$33,811.50	\$788,570.00	\$822,381.50
	Incenti				\$0.00	\$0.00	\$0.00
	Incenti Disince	ve			\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00
	Disince Liquida	ve					

Revision 3/23/2023 Page 8 of 28



**Exceptions (Discrepancies) This Estimate Period** 

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 2035500, Project Item Line Number 0030, Material Set 203550096, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 2036000, Project Item Line Number 0040, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 3040506, Project Item Line Number 0050, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 3040506, Project Item Line Number 0050, Material Set 304050696, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 6061061, Project Item Line Number 0300, Material Set 606106196, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 6061061, Project Item Line Number 0300, Material Set 606106196, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 6061074, Project Item Line Number 0310, Material Set 606107496, Material 1040GRTS - Transition Section, Acceptance Action Generic 1040GRTS is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 6122009, Project Item Line Number 0070, Material Set 612200996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 6122019, Project Item Line Number 0080, Material Set 612201996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 6161005, Project Item Line Number 0100, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 6161025, Project Item Line Number 0110, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 6161040, Project Item Line Number 0120, Material Set 616104096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 6173700B, Project Item Line Number 0130, Material Set 6173700B96, Material 0617TCRCTF - Type F Concrete Traffic Barrier, Acceptance Action Generic 0617TCRCTF is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 6200015, Project Item Line Number 0160, Material Set 620001596, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 6200021, Project Item Line Number 0170, Material Set 620002196, Material 1048PMPFWH - Preformed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 6205902A, Project Item Line Number 0180, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 6205902A, Project Item Line Number 0180, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 6205903A, Project Item Line Number 0190, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 6205903A, Project Item Line Number 0190, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 8025006, Project Item Line Number 0240, Material Set 8025006, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 8051000A, Project Item Line Number 0255, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 8051000A, Project Item Line Number 0255, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 8061004, Project Item Line Number 0260, Material Set 806100496, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9011062, Project Item Line Number 0320, Material Set 901106296, Material 0901LHXX - Highway Lighting Material, Acceptance	Material is accepted and will be entered into the system.	hargrr	Overridden

Revision 3/23/2023 Page 9 of 28



**Exceptions (Discrepancies) This Estimate Period** 

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Action Generic 0901LHXX is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9011115, Project Item Line Number 0330, Material Set 901111596, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9012230, Project Item Line Number 0350, Material Set 901223096, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9017002, Project Item Line Number 0400, Material Set 901700296, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9017008, Project Item Line Number 0410, Material Set 901700896, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9017110, Project Item Line Number 0420, Material Set 901711096, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9017202, Project Item Line Number 0430, Material Set 901720296, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9017208, Project Item Line Number 0440, Material Set 901720896, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9017407, Project Item Line Number 0450, Material Set 901740796, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9018613, Project Item Line Number 0470, Material Set 901861396, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9020213, Project Item Line Number 0480, Material Set 902021396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9020513, Project Item Line Number 0490, Material Set 902051396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9020514, Project Item Line Number 0500, Material Set 902051496, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9020833, Project Item Line Number 0510, Material Set 902083396, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9023250, Project Item Line Number 0530, Material Set 902325096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9023340, Project Item Line Number 0540, Material Set 902334096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9023355, Project Item Line Number 0550, Material Set 902335596, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9024283, Project Item Line Number 0560, Material Set 902428396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9024975, Project Item Line Number 0570, Material Set 902497596, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9028208, Project Item Line Number 0600, Material Set 902820896, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9028311, Project Item Line Number 0610, Material Set 902831196, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9028620, Project Item Line Number 0620, Material Set 902862096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9035004A, Project Item Line Number 0690, Material Set 9035004A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3085H, Item 9035011A, Project Item Line Number 0700, Material Set 9035011A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Material is accepted and will be entered into the system.	hargrr	Overridden

Revision 3/23/2023 Page 10 of 28



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
10119-C01	J3P3085H	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$26,000.00	\$26,000.0
		0001	0020	2031000	CLASS A EXCAVATION	157.00	0.00	157.00	CUYD	157.00	\$43.10	\$6,766.7
		0001	0030	2035500	EMBANKMENT IN PLACE	1,439.00	0.00	1,439.00	CUYD	1,439.00	\$36.80	\$52,955.2
		0001	0040	2036000	COMPACTING EMBANKMENT	125.00	0.00	125.00	CUYD	125.00	\$37.00	\$4,625.
		0001	0050	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	285.00	0.00	285.00	SQYD	285.00	\$21.00	\$5,985.
		0001	0060	5029905	MISC.Optional Pavement	285.00	0.00	285.00	SQYD	285.00	\$110.00	\$31,350.
		0001	0070	6122009	IMPACT ATTENUATOR 45 MPH (SAND BARREL ARRAY)	1.00	0.00	1.00	EA	1.00	\$1,890.00	\$1,890.
		0001	0800	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	1.00	0.00	1.00	EA	1.00	\$3,990.00	\$3,990.
		0001	0090	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$6,000.00	\$0.
		0001	0100	6161005	CONSTRUCTION SIGNS	303.00	0.00	303.00	SQFT	303.00	\$20.00	\$6,060
		0001	0110	6161025	CHANNELIZER (TRIM LINE)	80.00	0.00	80.00	EA	80.00	\$55.00	\$4,400
		0001	0120	6161040	FLASHING ARROW PANEL	1.00	0.00	1.00	EA	1.00	\$1,800.00	\$1,800.
		0001	0130	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR	412.00	0.00	412.00	LF	412.00	\$58.80	\$24,225.
		0001	0140	6181000	FURNISHED / RETAINED  MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$129,000.00	\$129,000
		0001	0150	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	1.00	0.00	1.00	EA	0.00	\$600.00	\$0.
		0001 0160 6	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	163.00	0.00	163.00	LF	163.00	\$28.90	\$4,710.	
			0170	6200021	WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING.	6.00	0.00	6.00	EA	6.00	\$345.00	\$2.070
					LEFT/RIGHT ARROW							. ,
		0001	0180	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,761.00	0.00	1,761.00	LF	1,761.00	\$2.10	\$3,698
		0001	0190	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,210.00	0.00	1,210.00	LF	1,210.00	\$2.10	\$2,541
		0001	0200	6207001	PAVEMENT MARKING REMOVAL	2,205.00	0.00	2,205.00	LF	2,205.00	\$2.10	\$4,630
		0001	0210	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	344.00	0.00	344.00	LF	344.00	\$6.50	\$2,236
		0001	0220	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$6,000.00	\$6,000
		0001	0230	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	1.00	\$41,268.00	\$41,268
		0001	0240	8025006	MULCHING	0.10	0.00	0.10	ACRE	0.10	\$10,000.00	\$1,000
		0001	0255	8051000A	SEEDING - COOL SEASON GRASSES	0.60	0.00	0.60	ACRE	0.40	\$7,500.00	\$3,000
		0001	0260	8061004	SEDIMENT TRAP ROCK	1.00	0.00	1.00	CUYD	1.00	\$385.00	\$385
		0001	0270	8061016	SEDIMENT REMOVAL	21.00	0.00	21.00	CUYD	0.00	\$100.00	\$0
		0001	0280	8061019	SILT FENCE	1,104.00	0.00	1,104.00	LF	888.00	\$3.30	\$2,930
		0001	0290	8064134	TYPE 1D EROSION CONTROL BLANKET	2,345.00	0.00	2,345.00	SQYD	1,876.00	\$2.35	\$4,408
		0010	0300	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	375.00	0.00	375.00	LF	375.00	\$34.20	\$12,825
		0010	0310	6061074	MGS HEIGHT AND BLOCK TRANSITION	1.00	0.00	1.00	EA	1.00	\$735.00	\$735
		0020	0320	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	4.00	0.00	4.00	EA	4.00	\$3,527.00	\$14,108
		0020	0330	9011115	BRACKET ARM, 15 FT. OR 4.6 M	4.00	0.00	4.00	EA	4.00	\$1,352.00	\$5,408
		0020	0340	9011312	LUMINAIRE, LED-B	4.00	0.00	4.00	EA	4.00	\$398.00	\$1,592
		0020	0350	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	1.00	0.00	1.00	EA	1.00	\$8,500.00	\$8,500
		0020	0360	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	1,186.00	0.00	1,186.00	LF	1,186.00	\$12.00	\$14,232
		0020	0370	9014004	CONDUIT, 4 IN. RIGID, PUSHED	1,780.00	0.00	1,780.00	LF	799.00	\$23.00	\$18,377
		0020	0380	9015010	TRENCHING TYPE I	4,047.00	0.00	4,047.00	LF	4,047.00	\$6.50	\$26,305
		0020	0390	9016110	PULL BOX, PREFORMED CLASS 1	18.00	0.00	18.00	EA	18.00	\$1,616.00	\$29,088
		0020	0400	9017002	CABLE, 2 AWG 1 CONDUCTOR	60.00	0.00	60.00	LF	60.00	\$3.10	\$186
		0020	0410	9017008	CABLE, 8 AWG 1 CONDUCTOR	8,050.00	0.00	8,050.00	LF	5,626.00	\$1.45	\$8,157
		0020	0420	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	480.00	0.00	480.00	LF	480.00	\$1.00	\$480
		0020	0430	9017202	WIRE, 2 AWG, BARE NEUTRAL	30.00	0.00	30.00	LF	30.00	\$3.10	\$93
			0.110	0047000	WIRE, 8 AWG, BARE NEUTRAL	4,020.00	0.00	4,020.00	LF	2,808.00	\$1.45	\$4,071
		0020	0440	9017208	WINE, O AWG, DAILE NEO INAL	4,020.00	0.00	.,		,	Ψ1.10	ψ 1,01 1

Revision 3/23/2023 Page 11 of 28



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ontract ONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
9-C01	J3P3085H				NEUTRAL, 8 AWG							
		0020	0460	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	4.00	0.00	4.00	EA	4.00	\$1,700.00	\$6,800.0
		0020	0470	9018613	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING AND SIGNALS	1.00	0.00	1.00	EA	1.00	\$8,500.00	\$8,500.0
		0030	0480	9020213	SIGNAL HEAD, TYPE 3S	\$977.0						
		0030	0490	9020513	SIGNAL HEAD, TYPE 3B	\$15,795.0						
		0030	0500	9020514	SIGNAL HEAD, TYPE 4B	2.00	0.00	2.00	EA	2.00	\$1,418.00	\$2,836.0
		0030	0510	9020833	SH-FLAT SHEET - SIGNAL SIGN	15.00	0.00	15.00	SQFT	15.00	\$45.00	\$675.0
		0030	0520	9020834	SIGNAL SIGN, MOUNTING HARDWARE	2.00	0.00	2.00	EA	2.00	\$318.00	\$636.0
		0030	0530	9023250	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	2.00	0.00	2.00	EA	2.00	\$14,500.00	\$29,000.0
		0030	0540	9023340	POST, TYPE B, LONGEST ARM 40 FT. OR 12.2 M	1.00	0.00	1.00	EA	1.00	\$22,345.00	\$22,345.0
		0030	0550	9023355	POST, TYPE B, LONGEST ARM 55 FT.	1.00	0.00	1.00	EA	1.00	\$26,036.00	\$26,036.0
		0030	0560	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	1.00	0.00	1.00	EA	1.00	\$20,495.00	\$20,495.0
		0030	0570	9024975	VIDEO DETECTION SYSTEM	1.00	0.00	1.00	EA	1.00	\$47,798.00	\$47,798.0
		0030	0580	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	412.00	0.00	412.00	LF	412.00	\$14.00	\$5,768.0
		0030	0590	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	367.00	0.00	367.00	LF	367.00	\$22.00	\$8,074.0
		0030	0600	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	1,060.00	0.00	1,060.00	LF	1,060.00	\$1.45	\$1,537.0
		0030	0610	9028311	CABLE, 16 AWG 7 CONDUCTOR	4,380.00	0.00	4,380.00	LF	4,380.00	\$1.40	\$6,132.0
		0030	0620	9028620	POWER SUPPLY ASSEMBLY, TYPE 2	1.00	0.00	1.00	EA	1.00	\$8,500.00	\$8,500.0
		0030	0630	9028811	PULL BOX, PREFORMED CLASS 2	9.00	0.00	9.00	EA	9.00	\$1,900.00	\$17,100.0
		0030	0640	9028812	PULL BOX, PREFORMED CLASS 3	1.00	0.00	1.00	EA	1.00	\$2,300.00	\$2,300.0
		0030	0650	9029100	BASE, CONCRETE	15.80	0.00	15.80	CUYD	15.80	\$1,500.00	\$23,700.0
		0040	0660	9031010	CONCRETE FOOTINGS, EMBEDDED	1.40	0.00	1.40	CUYD	1.40	\$1,840.00	\$2,576.0
		0040	0670	9031210	STRUCTURAL STEEL POSTS	976.00	0.00	976.00	LB	976.00	\$5.30	\$5,172.8
		0040	0680	9031220	PIPE POSTS	500.00	0.00	500.00	LB	500.00	\$7.50	\$3,750.0
		0040	0690	9035004A	SH-FLAT SHEET	45.00	0.00	45.00	SQFT	45.00	\$22.50	\$1,012.5
		0040	0700	9035011A	ST-STRUCTURAL	264.00	0.00	264.00	SQFT	264.00	\$32.80	\$8,659.2
	Project J3F	23085H - To	tal Value	Posted to D	late as of Report Generated Date							\$822,381.
9-C01 Ove	erall - Total V	alue Poste	d to Date	as of Repor	t Generated Date							\$822,381.

Revision 3/23/2023 Page 12 of 28



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J3P3085H

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location From Statio Log M	on/ Dista		Offset/ Distance	Comments
0180	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	10/15/24	10/16/24	353.00	LF	258+65	5.78	264+61.40		
0190	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	10/15/24	10/16/24	242.00	LF	258+65	5.78	264+61.40		
0360	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	10/15/24	10/16/24	592.00	LF	258+65	5.78	264+61.40		
0380	9015010	TRENCHING TYPE I	10/15/24	10/16/24	376.00	LF	258+65	5.78	264+61.40		
0400	9017002	CABLE, 2 AWG 1 CONDUCTOR	10/15/24	10/16/24	60.00	LF	258+65	5.78	264+61.40		
0410	9017008	CABLE, 8 AWG 1 CONDUCTOR	10/15/24	10/16/24	3,358.00	LF	258+65	5.78	264+61.40		
0420	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE & BRACKE	10/15/24	10/16/24	120.00	LF	258+65	5.78	264+61.40		
0430	9017202	WIRE, 2 AWG, BARE NEUTRAL	10/15/24	10/16/24	30.00	LF	258+65	5.78	264+61.40		
0440	9017208	WIRE, 8 AWG, BARE NEUTRAL	10/15/24	10/16/24	1,674.00	LF	258+65	5.78	264+61.40		
0450	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS	10/15/24	10/16/24	455.00	LF	258+65	5.78	264+61.40		
0580	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	10/15/24	10/16/24	367.00	LF	258+65	5.78	264+61.40		
0600	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	10/15/24	10/16/24	1,060.00	LF	258+65	5.78	264+61.40		
0610	9028311	CABLE, 16 AWG 7 CONDUCTOR	10/15/24	10/16/24	4,380.00	LF	258+65	5.78	264+61.40		

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 3/23/2023 Page 13 of 28



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J3P3085H	0030	EMBANKMENT IN PLACE	Material		3	Sep 3, 2024	SYSTEM	\$52,955.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargr overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					3	Sep 3, 2024	SYSTEM	(\$52,955.20)								
					4	Sep 16, 2024	SYSTEM	\$52,955.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					4	Sep 16, 2024	SYSTEM	(\$52,955.20)								
					5	Oct 1, 2024	SYSTEM	\$52,955.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hargr overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					5	Oct 1, 2024	SYSTEM	(\$52,955.20)								
					6	Oct 16, 2024	SYSTEM	\$52,955.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					6	Oct 16, 2024	SYSTEM	(\$52,955.20)								
				- Total				\$0.00								
			Material - T	otal				\$0.00								
		· Total						\$0.00								
	0040	COMPACTING EMBANKMENT	Material		3	Sep 3, 2024	SYSTEM	\$4,625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.							
					3	Sep 3, 2024	SYSTEM	(\$4,625.00)								
					4	Sep 16, 2024	SYSTEM	\$4,625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.							
					4	Sep 16, 2024	SYSTEM	(\$4,625.00)								
					5	Oct 1, 2024	SYSTEM	\$4,625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.							
					5	Oct 1, 2024	SYSTEM	(\$4,625.00)								
						6	Oct 16, 2024	SYSTEM	\$4,625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					6	Oct 16, 2024	SYSTEM	(\$4,625.00)								
				- Total				\$0.00								
			Material - To	otal				\$0.00								
		- Total						\$0.00								
	0050	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material	Material	Material	Material	Material	Material	Material	Material		3	Sep 3, 2024	SYSTEM	\$5,985.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment Estimate Exception 3 on the current Payment Estimate.
		THIOR		3	3	Sep 3, 2024	SYSTEM	(\$5,985.00)								
			4		4	Sep 16, 2024	SYSTEM	\$5,985.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment Estimate Exception 3 on the current Payment Estimate.							
					4	Sep 16, 2024	SYSTEM	(\$5,985.00)								
			5	5	Oct 1, 2024	SYSTEM	\$5,985.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 3 on the current Payment Estimate.								
					5	Oct 1, 2024	SYSTEM	(\$5,985.00)								
				6	Oct 16, 2024	SYSTEM	\$5,985.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 3 on the current Payment Estimate.								
					6	Oct 16,	SYSTEM	(\$5,985.00)								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J3P3085H	0050	TYPE 5	Material			2024										
		AGGREGATE FOR BASE (6 IN.		- Total				\$0.00								
		THICK)	Material - T	otal				\$0.00								
	0050	- Total						\$0.00								
	0070	IMPACT ATTENUATOR 45 MPH (SAND BARREL ARRAY)	Material		2	Aug 16, 2024	SYSTEM	\$1,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Exception 1 on the current Payment Estimate.							
		DAINCE ANIVAL)			2	Aug 16, 2024	SYSTEM	(\$1,890.00)								
					3	Sep 3, 2024	SYSTEM	\$1,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 5 on the current Payment Estimate.							
					3	Sep 3, 2024	SYSTEM	(\$1,890.00)								
					4	Sep 16, 2024	SYSTEM	\$1,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 8 on the current Payment Estimate.							
					4	Sep 16, 2024	SYSTEM	(\$1,890.00)								
					5	Oct 1, 2024	SYSTEM	\$1,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 8 on the current Payment Estimate.							
					5	Oct 1, 2024	SYSTEM	(\$1,890.00)								
												6	Oct 16, 2024	SYSTEM	\$1,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$1,890.00)								
				- Total				\$0.00								
			Material - T	otal				\$0.00								
	0070 -	- Total	Material					\$0.00								
	0070	IMPACT ATTENUATOR 70 MPH (SAND	Material		2	Aug 16, 2024	SYSTEM	<b>\$0.00</b> <b>\$3,990.00</b>	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.							
		IMPACT ATTENUATOR	Material		2		SYSTEM SYSTEM		Estimate Item Adjustment (0002) due to user hargrr overridding Payment							
		IMPACT ATTENUATOR 70 MPH (SAND	Material			2024 Aug 16,		\$3,990.00	Estimate Item Adjustment (0002) due to user hargrr overridding Payment							
		IMPACT ATTENUATOR 70 MPH (SAND	Material		2	2024 Aug 16, 2024 Sep 3,	SYSTEM	\$3,990.00 (\$3,990.00)	Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment							
		IMPACT ATTENUATOR 70 MPH (SAND	Material		3	2024 Aug 16, 2024 Sep 3, 2024 Sep 3,	SYSTEM SYSTEM	\$3,990.00 (\$3,990.00) \$3,990.00	Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment							
		IMPACT ATTENUATOR 70 MPH (SAND	Material		3	2024  Aug 16, 2024  Sep 3, 2024  Sep 3, 2024  Sep 16,	SYSTEM SYSTEM SYSTEM	\$3,990.00 (\$3,990.00) \$3,990.00 (\$3,990.00)	Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment							
		IMPACT ATTENUATOR 70 MPH (SAND	Material		3 3 4	2024 Aug 16, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM	\$3,990.00 (\$3,990.00) \$3,990.00 (\$3,990.00)	Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment							
		IMPACT ATTENUATOR 70 MPH (SAND	Material		2 3 3 4	2024 Aug 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$3,990.00 (\$3,990.00) \$3,990.00 (\$3,990.00) \$3,990.00	Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment							
		IMPACT ATTENUATOR 70 MPH (SAND	Material		2 3 3 4 4 5	2024 Aug 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16, 2024 Oct 1, 2024 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$3,990.00 (\$3,990.00) \$3,990.00 (\$3,990.00) (\$3,990.00) \$3,990.00	Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment							
		IMPACT ATTENUATOR 70 MPH (SAND	Material		2 3 3 4 4 5	2024 Aug 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16, 2024 Oct 1, 2024 Oct 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$3,990.00 (\$3,990.00) \$3,990.00 (\$3,990.00) (\$3,990.00) (\$3,990.00)	Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.							
		IMPACT ATTENUATOR 70 MPH (SAND	Material	- Total	2 3 3 4 4 5 5	2024 Aug 16, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Oct 1, 2024 Oct 16, 2024 Oct 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$3,990.00 (\$3,990.00) \$3,990.00 (\$3,990.00) \$3,990.00 (\$3,990.00) (\$3,990.00)	Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.							
		IMPACT ATTENUATOR 70 MPH (SAND	Material - T		2 3 3 4 4 5 5	2024 Aug 16, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Oct 1, 2024 Oct 16, 2024 Oct 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$3,990.00 (\$3,990.00) \$3,990.00 (\$3,990.00) \$3,990.00 (\$3,990.00) \$3,990.00 (\$3,990.00)	Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.							
	0080	IMPACT ATTENUATOR 70 MPH (SAND			2 3 3 4 4 5 5	2024 Aug 16, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Oct 1, 2024 Oct 16, 2024 Oct 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$3,990.00 (\$3,990.00) \$3,990.00 (\$3,990.00) \$3,990.00 (\$3,990.00) \$3,990.00 (\$3,990.00)	Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.							
	0080	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)			2 3 3 4 4 5 5	2024 Aug 16, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Oct 1, 2024 Oct 16, 2024 Oct 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$3,990.00 (\$3,990.00) \$3,990.00 (\$3,990.00) \$3,990.00 (\$3,990.00) (\$3,990.00) (\$3,990.00) \$3,990.00	Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J3P3085H	0100	CONSTRUCTION	Material			2024			
		SIGNS			2	Aug 16, 2024	SYSTEM	\$6,060.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Aug 16, 2024	SYSTEM	(\$6,060.00)	
					3	Sep 3, 2024	SYSTEM	\$6,060.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargr overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	Sep 3, 2024	SYSTEM	(\$6,060.00)	
					4	Sep 16, 2024	SYSTEM	\$6,060.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargr overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$6,060.00)	
					5	Oct 1, 2024	SYSTEM	\$6,060.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hargrr overridding Payment Estimate Exception 10 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$6,060.00)	
					6	Oct 16, 2024	SYSTEM	\$6,060.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hargrr overridding Payment Estimate Exception 10 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$6,060.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0100 -	Total						\$0.00	
	0110	CHANNELIZER (TRIM LINE)	Material		1	Aug 2, 2024	SYSTEM	\$1,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hargrr overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Aug 2, 2024	SYSTEM	(\$1,375.00)	
					2	Aug 16, 2024	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hargrr overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	Aug 16, 2024	SYSTEM	(\$4,400.00)	
					3	Sep 3, 2024	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hargr overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	Sep 3, 2024	SYSTEM	(\$4,400.00)	
					4	Sep 16, 2024	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hargrr overridding Payment Estimate Exception 11 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$4,400.00)	
					5	Oct 1, 2024	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hargrr overridding Payment Estimate Exception 11 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$4,400.00)	
					6	Oct 16, 2024	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hargrr overridding Payment Estimate Exception 11 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$4,400.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0110 -	Total						\$0.00	
	0120	FLASHING ARROW PANEL	Material		2	Aug 16, 2024	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hargrr overridding Payment Estimate Exception 5 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
J3P3085H	0120	FLASHING ARROW PANEL	Material		2	Aug 16, 2024	SYSTEM	(\$1,800.00)							
					3	Sep 3, 2024	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hargrr overridding Payment Estimate Exception 9 on the current Payment Estimate.						
					3	Sep 3, 2024	SYSTEM	(\$1,800.00)							
					4	Sep 16, 2024	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hargrr overridding Payment Estimate Exception 12 on the current Payment Estimate.						
					4	Sep 16, 2024	SYSTEM	(\$1,800.00)							
					5	Oct 1, 2024	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hargrr overridding Payment Estimate Exception 12 on the current Payment Estimate.						
					5	Oct 1, 2024	SYSTEM	(\$1,800.00)							
					6	Oct 16, 2024	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hargrr overridding Payment Estimate Exception 12 on the current Payment Estimate.						
					6	Oct 16, 2024	SYSTEM	(\$1,800.00)							
				- Total				\$0.00							
			Material - To	otal				\$0.00							
	0120 -	Total						\$0.00							
	0130	TEMP. TRAFFIC BARRIER ANCHORED., CONT	Material		2	Aug 16, 2024	SYSTEM	\$24,225.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hargrr overridding Payment Estimate Exception 6 on the current Payment Estimate.						
		CONT			2	Aug 16, 2024	SYSTEM	(\$24,225.60)							
						3	Sep 3, 2024	SYSTEM	\$24,225.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hargrr overridding Payment Estimate Exception 10 on the current Payment Estimate.					
						3	Sep 3, 2024	SYSTEM	(\$24,225.60)						
					4	Sep 16, 2024	SYSTEM	\$24,225.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hargrr overridding Payment Estimate Exception 13 on the current Payment Estimate.						
					4	Sep 16, 2024	SYSTEM	(\$24,225.60)							
					5	Oct 1, 2024	SYSTEM	\$24,225.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hargrr overridding Payment Estimate Exception 13 on the current Payment Estimate.						
					5	Oct 1, 2024	SYSTEM	(\$24,225.60)							
											6	Oct 16, 2024	SYSTEM	\$24,225.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hargrr overridding Payment Estimate Exception 13 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$24,225.60)							
				- Total				\$0.00							
			Material - To	otal				\$0.00							
	0130 -	Total						\$0.00							
	0160	PREF THERMO PVMT MARK, 24 IN WHIT	Material		5	Oct 1, 2024	SYSTEM	\$4,710.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hargrr overridding Payment Estimate Exception 14 on the current Payment Estimate.						
					5	Oct 1, 2024	SYSTEM	(\$4,710.70)							
					6	Oct 16, 2024	SYSTEM	\$4,710.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hargrr overridding Payment Estimate Exception 14 on the current Payment Estimate.						
					6	Oct 16, 2024	SYSTEM	(\$4,710.70)							
				- Total				\$0.00							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J3P3085H	0160	PREF THERMO PVMT MARK, 24 IN WHIT	Material - T	otal				\$0.00					
	0160 -	· Total						\$0.00					
	0170	PREF THERMO PVMT MARK, LT/RT ARROW	Material		5	Oct 1, 2024	SYSTEM	\$2,070.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate.				
					5	Oct 1, 2024	SYSTEM	(\$2,070.00)					
					6	Oct 16, 2024	SYSTEM	\$2,070.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate.				
					6	Oct 16, 2024	SYSTEM	(\$2,070.00)					
				- Total				\$0.00					
			Material - T	otal				\$0.00					
	0170 -	· Total						\$0.00					
	0180	6 IN. WHITE HIGH BUILD WATERBORNE	Material		5	Oct 1, 2024	SYSTEM	\$2,956.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hargrr overridding Payment Estimate Exception 16 on the current Payment Estimate.				
		PAINT			5	Oct 1, 2024	SYSTEM	(\$2,956.80)					
					6	Oct 16, 2024	SYSTEM	\$3,698.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hargrr overridding Payment Estimate Exception 16 on the current Payment Estimate.				
					6	Oct 16, 2024	SYSTEM	(\$3,698.10)					
				- Total				\$0.00					
			Material - T	otal				\$0.00					
	0180 -	· Total						\$0.00					
	0190	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	Material		5	Oct 1, 2024	SYSTEM	\$2,032.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hargrr overridding Payment Estimate Exception 18 on the current Payment Estimate.				
		PAINT				5	Oct 1, 2024	SYSTEM	(\$2,032.80)				
					6	Oct 16, 2024	SYSTEM	\$2,541.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hargrr overridding Payment Estimate Exception 18 on the current Payment Estimate.				
					6	Oct 16, 2024	SYSTEM	(\$2,541.00)					
				- Total				\$0.00					
			Material - T	otal				\$0.00					
	0190 -	· Total						\$0.00					
	0240	MULCHING	Material		4	Sep 16, 2024	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hargrr overridding Payment Estimate Exception 14 on the current Payment Estimate.				
									4	Sep 16, 2024	SYSTEM	(\$1,000.00)	
					5	Oct 1, 2024	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hargrr overridding Payment Estimate Exception 20 on the current Payment Estimate.				
			5	5	Oct 1, 2024	SYSTEM	(\$1,000.00)						
				6	6	Oct 16, 2024	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hargrr overridding Payment Estimate Exception 20 on the current Payment Estimate.				
					6	Oct 16, 2024	SYSTEM	(\$1,000.00)					
				- Total				\$0.00					
			Material - T	otal				\$0.00					
	0240 -	· Total						\$0.00					
	0255	SEEDING - COOL SEASON	Material		4	Sep 16, 2024	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hargrr overridding Payment				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J3P3085H	0255	GRASSES	Material	.,,,,,					Estimate Exception 15 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$3,000.00)	
					5	Oct 1, 2024	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hargrr overridding Payment Estimate Exception 21 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$3,000.00)	
					6	Oct 16, 2024	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hargrr overridding Payment Estimate Exception 21 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$3,000.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0255 -	Total						\$0.00	
	0260	SEDIMENT TRAP ROCK	Material		2	Aug 16, 2024	SYSTEM	\$385.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hargrr overridding Payment Estimate Exception 7 on the current Payment Estimate.
					2	Aug 16, 2024	SYSTEM	(\$385.00)	
					3	Sep 3, 2024	SYSTEM	\$385.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hargrr overridding Payment Estimate Exception 11 on the current Payment Estimate.
					3	Sep 3, 2024	SYSTEM	(\$385.00)	
					4	Sep 16, 2024	SYSTEM	\$385.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hargrr overridding Payment Estimate Exception 17 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$385.00)	
					5	Oct 1, 2024	SYSTEM	\$385.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hargrr overridding Payment Estimate Exception 23 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$385.00)	
					6	Oct 16, 2024	SYSTEM	\$385.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hargrr overridding Payment Estimate Exception 23 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$385.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
		Total						\$0.00	
	0280	SILT FENCE	Material		2	Aug 16, 2024	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hargrr overridding Payment Estimate Exception 8 on the current Payment Estimate.
					Aug 16, 2024	SYSTEM	(\$1,320.00)		
				- Total				\$0.00	
			Material - To	otal				\$0.00	
		Total			,		0)/2==:	\$0.00	
	0300	MGS GUARDRAIL, 8 FT. POSTS, 6 FT. - 3 IN	Material		4	Sep 16, 2024	SYSTEM	\$12,825.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hargrr overridding Payment Estimate Exception 5 on the current Payment Estimate.
		3	4 Sep 16, SYSTEM (\$	(\$12,825.00)					
					5	Oct 1, 2024	SYSTEM	\$12,825.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hargrr overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$12,825.00)	
					6	Oct 16, 2024	SYSTEM	\$12,825.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hargrr overridding Payment



2006   1000	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
FT FOSTS, 6TT   100	J3P3085H	0300		Material	, ,,					Estimate Exception 5 on the current Payment Estimate.										
Material - Total			FT. POSTS, 6 FT.			6		SYSTEM	(\$12,825.00)											
1000   Total			0 114		- Total				\$0.00											
A				Material - To	otal				\$0.00											
AADB_LOCK   150		0300 -	Total						\$0.00											
2024   SYSTEM   \$735.00   This adjustment offsets the original system-generated Material Payment Estimate Ecosption 7 on the outriest Payment Estimate Ecosption 8 on the outriest Payment Estimate Ecosption 8 on the State of Estimate Ecosption 8 on the State Outriest Payment Estimate Ecosption 8 on the Estimate Ecosption 8 on the Estimate Ecosption 8 on the Outriest Payment Estimate Ecosption 8 on the Estimate Ecosption 8 on the Outriest Payment Estimate Estimate Estimate Ecosption 8 on the Outriest Payment Estimate Es		0310	AND BLOCK	Material		4		SYSTEM	\$735.00	Estimate Item Adjustment (0014) due to user hargrr overridding Payment										
2024   Estimate Item Adjustment (0019) due to user harger overridding Playment						4		SYSTEM	(\$735.00)											
2004   2024   3735-00   This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate.   2024   202						5		SYSTEM	\$735.00	Estimate Item Adjustment (0019) due to user hargrr overridding Payment										
2024   Estimate Exception 7 on the current Payment Estimate.						5		SYSTEM	(\$735.00)											
						6		SYSTEM	\$735.00	Estimate Item Adjustment (0019) due to user hargrr overridding Payment										
						6		SYSTEM	(\$735.00)											
					- Total				\$0.00											
			Material - To	otal				\$0.00												
A5 FT. OR 13.5			Total						\$0.00											
2024   3   Sep 3, 2024   4   Sep 16, 2024   5   Sep 16, 2024   5   Oct 1, 2024   5		0320	45 FT. OR 13.5	Material		2		SYSTEM	\$10,581.00	Estimate Item Adjustment (0009) due to user hargrr overridding Payment										
2024   Estimate Item Adjustment (0011) due to user harger overridding Payment Estimate Exception 12 on the current Payment Estimate.							2		SYSTEM	(\$10,581.00)										
2024   4   Sep 16,   SYSTEM   2024   5   SYSTEM   2024   2024   5   SYSTEM   2024   5   SYSTEM   2024   2024   2024   2024   2   SYSTEM   2						3		SYSTEM	\$10,581.00	Estimate Item Adjustment (0011) due to user hargrr overridding Payment										
2024   Estimate Item Adjustment (0015) due to user harger overridding Payment Estimate Exception 18 on the current Payment Estimate.						3		SYSTEM	(\$10,581.00)											
2024							4		SYSTEM	\$14,108.00	Estimate Item Adjustment (0015) due to user hargrr overridding Payment									
2024   Estimate Item Adjustment (0020) due to user harger overridding Payment Estimate Exception 24 on the current Payment Estimate.					4		SYSTEM	(\$14,108.00)												
2024   6						5		SYSTEM	\$14,108.00	Estimate Item Adjustment (0020) due to user hargrr overridding Payment										
2024   Estimate Item Adjustment (0020) due to user hargrr overridding Payment Estimate Exception 24 on the current Payment Estimate.						5		SYSTEM	(\$14,108.00)											
- Total  So.00  Material - Total  Sycono  Syco																6		SYSTEM	\$14,108.00	Estimate Item Adjustment (0020) due to user hargrr overridding Payment
Solution						6		SYSTEM	(\$14,108.00)											
Substitute   Sub					- Total				\$0.00											
BRACKET ARM, 15 FT. OR 4.6 M  16 FT. OR 4.6 M  16 FT. OR 4.6 M  17 It is adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user harger overridding Payment Estimate Exception 13 on the current Payment Estimate.  16 FT. OR 4.6 M  17 It is adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate.  17 FT. OR 4.6 M  18 FT. OR 4.6 M  19 FT. OR 4.6 M  18 FT. OR 4.6 M  19 FT. OR 4.6 M  10 FT. OR 4.6 M				Material - To	otal				\$0.00											
15 FT. OR 4.6 M  2024  Estimate Item Adjustment (0010) dué to user hargrr overridding Payment Estimate Exception 10 on the current Payment Estimate.  2 Aug 16, 2024  3 Sep 3, 2024  Sep 3, 2024  Sep 3, SYSTEM (\$4,056.00)  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hargrr overridding Payment Estimate Exception 13 on the current Payment Estimate.  3 Sep 3, 2024  Sep 16, SYSTEM (\$4,056.00)  This adjustment offsets the original system-generated Material Payment  Sep 16, SYSTEM \$5,408.00  This adjustment offsets the original system-generated Material Payment		0320 -	Total						\$0.00											
2024  3 Sep 3, 2024  \$4,056.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hargrr overridding Payment Estimate Exception 13 on the current Payment Estimate.  3 Sep 3, 2024  \$4 Sep 16, SYSTEM \$5,408.00 This adjustment offsets the original system-generated Material Payment		0330		Material		2		SYSTEM	\$4,056.00	Estimate Item Adjustment (0010) due to user hargrr overridding Payment										
2024 Estimate Item Adjustment (0012) due to user hargrr overridding Payment Estimate Exception 13 on the current Payment Estimate.  3 Sep 3, 2024 (\$4,056.00)  4 Sep 16, SYSTEM \$5,408.00 This adjustment offsets the original system-generated Material Payment						2	2		SYSTEM	(\$4,056.00)										
2024  4 Sep 16, SYSTEM \$5,408.00 This adjustment offsets the original system-generated Material Payment						3		SYSTEM	\$4,056.00	Estimate Item Adjustment (0012) due to user hargrr overridding Payment										
						3		SYSTEM	(\$4,056.00)											
						4		SYSTEM	\$5,408.00											



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J3P3085H	0330	BRACKET ARM,	Material						Estimate Exception 19 on the current Payment Estimate.					
		15 FT. OR 4.6 M			4	Sep 16, 2024	SYSTEM	(\$5,408.00)						
					5	Oct 1, 2024	SYSTEM	\$5,408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hargrr overridding Payment Estimate Exception 25 on the current Payment Estimate.					
					5	Oct 1, 2024	SYSTEM	(\$5,408.00)						
					6	Oct 16, 2024	SYSTEM	\$5,408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hargrr overridding Payment Estimate Exception 25 on the current Payment Estimate.					
					6	Oct 16, 2024	SYSTEM	(\$5,408.00)						
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0330 -	Total						\$0.00						
	0350	BASE MOUNTED CONTROL STATION	Material		3	Sep 3, 2024	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hargrr overridding Payment Estimate Exception 14 on the current Payment Estimate.					
					3	Sep 3, 2024	SYSTEM	(\$8,500.00)						
					4	Sep 16, 2024	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hargrr overridding Payment Estimate Exception 20 on the current Payment Estimate.					
					4	Sep 16, 2024	SYSTEM	(\$8,500.00)						
					5	Oct 1, 2024	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hargrr overridding Payment Estimate Exception 26 on the current Payment Estimate.					
										5	Oct 1, 2024	SYSTEM	(\$8,500.00)	
									6	Oct 16, 2024	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hargrr overridding Payment Estimate Exception 26 on the current Payment Estimate.	
					6	Oct 16, 2024	SYSTEM	(\$8,500.00)						
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0350 -	Total						\$0.00						
	0400	CABLE, 2 AWG 1 CONDUCTOR	Material		6	Oct 16, 2024	SYSTEM	\$186.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hargrr overridding Payment Estimate Exception 27 on the current Payment Estimate.					
					6	Oct 16, 2024	SYSTEM	(\$186.00)						
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0400 -	Total  CABLE, 8 AWG 1  CONDUCTOR	Material		2	Aug 16, 2024	SYSTEM	<b>\$0.00</b> \$1,856.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hargrr overridding Payment					
		SONDOCIOR			2		SYSTEM	(¢1 856 00)	Estimate term Adjustment (0011) due to user hargn overhooning Payment Estimate Exception 11 on the current Payment Estimate.					
						Aug 16, 2024	SISIEM	(\$1,856.00)						
					3	Sep 3, 2024	SYSTEM	\$3,288.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hargrr overridding Payment Estimate Exception 15 on the current Payment Estimate.					
					3	Sep 3, 2024	SYSTEM	(\$3,288.60)						
					4	Sep 16, 2024	SYSTEM	\$3,288.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hargrr overridding Payment Estimate Exception 21 on the current Payment Estimate.					
					4	Sep 16, 2024	SYSTEM	(\$3,288.60)						
					5	Oct 1, 2024	SYSTEM	\$3,288.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hargrr overridding Payment					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J3P3085H	0410	CABLE, 8 AWG 1	Material						Estimate Exception 27 on the current Payment Estimate.							
		CONDUCTOR			5	Oct 1, 2024	SYSTEM	(\$3,288.60)								
					6	Oct 16, 2024	SYSTEM	\$8,157.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hargrr overridding Payment Estimate Exception 28 on the current Payment Estimate.							
					6	Oct 16, 2024	SYSTEM	(\$8,157.70)								
				- Total				\$0.00								
			Material - To	otal				\$0.00								
	0410 -	Total						\$0.00								
	0420	CABLE, 10 AWG 1 CONDUCTOR, POLE & BRACKE	Material		2	Aug 16, 2024	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hargrr overridding Payment Estimate Exception 12 on the current Payment Estimate.							
					2	Aug 16, 2024	SYSTEM	(\$360.00)								
					3	Sep 3, 2024	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hargrr overridding Payment Estimate Exception 16 on the current Payment Estimate.							
					3	Sep 3, 2024	SYSTEM	(\$360.00)								
					4	Sep 16, 2024	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hargrr overridding Payment Estimate Exception 22 on the current Payment Estimate.							
					4	Sep 16, 2024	SYSTEM	(\$360.00)								
					5	Oct 1, 2024	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hargrr overridding Payment Estimate Exception 28 on the current Payment Estimate.							
					5	Oct 1, 2024	SYSTEM	(\$360.00)								
										6	Oct 16, 2024	SYSTEM	\$480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hargrr overridding Payment Estimate Exception 29 on the current Payment Estimate.		
					6	Oct 16, 2024	SYSTEM	(\$480.00)								
				- Total				\$0.00								
			Material - To	otal				\$0.00								
	0420 -	Total						\$0.00								
	0430	WIRE, 2 AWG, BARE NEUTRAL	Material	Material	Material	Material	Material	Material	waterial	iviaterial		6	Oct 16, 2024	SYSTEM	\$93.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hargrr overridding Payment Estimate Exception 30 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$93.00)								
				- Total				\$0.00								
			Material - To	otal				\$0.00								
	0430 - 0440	Total WIRE, 8 AWG,	Material		2	Aug 16,	SYSTEM	<b>\$0.00</b> <b>\$928.00</b>	This adjustment offsets the original system-generated Material Payment							
		BARE NEUTRAL				2024	OVOTER	(0000 00)	Estimate Item Adjustment (0013) due to user hargrr overridding Payment Estimate Exception 13 on the current Payment Estimate.							
					2	Aug 16, 2024	SYSTEM	(\$928.00)								
				3		Sep 3, 2024	SYSTEM	\$1,644.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hargrr overridding Payment Estimate Exception 17 on the current Payment Estimate.							
					3	Sep 3, 2024	SYSTEM	(\$1,644.30)								
					4	Sep 16, 2024	SYSTEM	\$1,644.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hargrr overridding Payment Estimate Exception 23 on the current Payment Estimate.							
					4	Sep 16, 2024	SYSTEM	(\$1,644.30)								
					5	Oct 1, 2024	SYSTEM	\$1,644.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hargrr overridding Payment							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J3P3085H	0440	WIRE, 8 AWG,	Material						Estimate Exception 29 on the current Payment Estimate.
		BARE NEUTRAL			5	Oct 1, 2024	SYSTEM	(\$1,644.30)	
					6	Oct 16, 2024	SYSTEM	\$4,071.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Exception 31 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$4,071.60)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0440 -	Total						\$0.00	
	0450	CABLE- CONDUIT, 1 IN., 2 CONDUCTORS	Material		1	Aug 2, 2024	SYSTEM	\$15,814.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hargrr overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Aug 2, 2024	SYSTEM	(\$15,814.80)	
					2	Aug 16, 2024	SYSTEM	\$16,797.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hargrr overridding Payment Estimate Exception 14 on the current Payment Estimate.
					2	Aug 16, 2024	SYSTEM	(\$16,797.36)	
					3	Sep 3, 2024	SYSTEM	\$21,610.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hargrr overridding Payment Estimate Exception 18 on the current Payment Estimate.
					3	Sep 3, 2024	SYSTEM	(\$21,610.80)	
					4	Sep 16, 2024	SYSTEM	\$21,610.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hargrr overridding Payment Estimate Exception 24 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$21,610.80)	
					5	Oct 1, 2024	SYSTEM	\$21,610.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hargrr overridding Payment Estimate Exception 30 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$21,610.80)	
					6	Oct 16, 2024	SYSTEM	\$24,122.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hargrr overridding Payment Estimate Exception 32 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$24,122.40)	
				- Total				\$0.00	
			Material - To	ial - Total				\$0.00	
	0450 -	Total						\$0.00	
	0470	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120	Material		3	Sep 3, 2024	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hargrr overridding Payment Estimate Exception 19 on the current Payment Estimate.
					3	Sep 3, 2024	SYSTEM	(\$8,500.00)	
					4	Sep 16, 2024	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hargrr overridding Payment Estimate Exception 25 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$8,500.00)	
					5	Oct 1, 2024	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Exception 31 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$8,500.00)	
					6	Oct 16, 2024	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hargrr overridding Payment Estimate Exception 33 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$8,500.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J3P3085H	0470	POWER SUPPLY ASSEMBLY,	Material - Total					\$0.00	
		TYPE 2, 240/120	Material - To	otal				\$0.00	
	0470 -	· Total						\$0.00	
	0480	SIGNAL HEAD, TYPE 3S	Material		5	Oct 1, 2024	SYSTEM	\$977.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Exception 32 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$977.00)	
					6	Oct 16, 2024	SYSTEM	\$977.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Exception 34 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$977.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0480 -	· Total						\$0.00	
	0490	SIGNAL HEAD, TYPE 3B	Material		5	Oct 1, 2024	SYSTEM	\$15,795.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hargrr overridding Payment Estimate Exception 33 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$15,795.00)	
					6	Oct 16, 2024	SYSTEM	\$15,795.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hargrr overridding Payment Estimate Exception 35 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$15,795.00)	
				- Total		2021		\$0.00	
			Material - Total					\$0.00	
	0490 - Total							\$0.00	
	0500	SIGNAL HEAD, TYPE 4B	Material		5	Oct 1, 2024	SYSTEM	\$2,836.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hargrr overridding Payment Estimate Exception 34 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$2,836.00)	
					6	Oct 16, 2024	SYSTEM	\$2,836.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user hargrr overridding Payment Estimate Exception 36 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$2,836.00)	
				- Total				\$0.00	
			Material - To	terial - Total				\$0.00	
	0500 -	· Total						\$0.00	
	0510	SH-FLAT SHEET - SIGNAL SIGN	Material		5	Oct 1, 2024	SYSTEM	\$675.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hargrr overridding Payment Estimate Exception 35 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$675.00)	
				6	6	Oct 16, 2024	SYSTEM	\$675.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user hargrr overridding Payment Estimate Exception 37 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$675.00)	
			- Total					\$0.00	
			Material - To	otal				\$0.00	
	0510 -	· Total						\$0.00	
	0530	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	Material		3	Sep 3, 2024	SYSTEM	\$29,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hargrr overridding Payment Estimate Exception 20 on the current Payment Estimate.
					3	Sep 3, 2024	SYSTEM	(\$29,000.00)	
					4	Sep 16, 2024	SYSTEM	\$29,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hargrr overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J3P3085H	0530	POST, TYPE C, 50 FT. ARM OR	Material						Estimate Exception 26 on the current Payment Estimate.
		15.2 M ARM			4	Sep 16, 2024	SYSTEM	(\$29,000.00)	
					5	Oct 1, 2024	SYSTEM	\$29,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user hargrr overridding Payment Estimate Exception 36 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$29,000.00)	
					6	Oct 16, 2024	SYSTEM	\$29,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user hargrr overridding Payment Estimate Exception 38 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$29,000.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0530 -	Total						\$0.00	
	0540	POST, TYPE B, LONGEST ARM 40 FT. OR 12.	Material		3	Sep 3, 2024	SYSTEM	\$22,345.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hargrr overridding Payment Estimate Exception 21 on the current Payment Estimate.
					3	Sep 3, 2024	SYSTEM	(\$22,345.00)	
					4	Sep 16, 2024	SYSTEM	\$22,345.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hargrr overridding Payment Estimate Exception 27 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$22,345.00)	
					5	Oct 1, 2024	SYSTEM	\$22,345.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user hargrr overridding Payment Estimate Exception 37 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$22,345.00)	
					6	Oct 16, 2024	SYSTEM	\$22,345.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user hargrr overridding Payment Estimate Exception 39 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$22,345.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0540 -	Total						\$0.00	
	0550	POST, TYPE B, LONGEST ARM 55 FT.	Material		3	Sep 3, 2024	SYSTEM	\$26,036.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hargrr overridding Payment Estimate Exception 22 on the current Payment Estimate.
					3	Sep 3, 2024	SYSTEM	(\$26,036.00)	
					4	Sep 16, 2024	SYSTEM	\$26,036.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hargrr overridding Payment Estimate Exception 28 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$26,036.00)	
					5	Oct 1, 2024	SYSTEM	\$26,036.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user hargrr overridding Payment Estimate Exception 38 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$26,036.00)	
					6	Oct 16, 2024	SYSTEM	\$26,036.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user hargrr overridding Payment Estimate Exception 40 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$26,036.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0550 -	Total						\$0.00	
	0560	CONTROLLER ASSEMBLY	Material		3	Sep 3, 2024	SYSTEM	\$20,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hargrr overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J3P3085H	0560	HOUSING,	Material						Estimate Exception 23 on the current Payment Estimate.
					3	Sep 3, 2024	SYSTEM	(\$20,495.00)	
					4	Sep 16, 2024	SYSTEM	\$20,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hargrr overridding Payment Estimate Exception 29 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$20,495.00)	
					5	Oct 1, 2024	SYSTEM	\$20,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user hargrr overridding Payment Estimate Exception 39 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$20,495.00)	
					6	Oct 16, 2024	SYSTEM	\$20,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user hargrr overridding Payment Estimate Exception 41 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$20,495.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0560 -	Total						\$0.00	
	0570	VIDEO DETECTION SYSTEM	Material		5	Oct 1, 2024	SYSTEM	\$47,798.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user hargrr overridding Payment Estimate Exception 40 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$47,798.00)	
					6	Oct 16, 2024	SYSTEM	\$47,798.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user hargrr overridding Payment Estimate Exception 42 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$47,798.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
		Total						\$0.00	
	0600	CABLE, 8 AWG 1 CONDUCTOR, POWER	Material		6	Oct 16, 2024	SYSTEM	\$1,537.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user hargrr overridding Payment Estimate Exception 43 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$1,537.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0600 -	Total						\$0.00	
	0610	CABLE, 16 AWG 7 CONDUCTOR	Material		6	Oct 16, 2024	SYSTEM	\$6,132.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user hargrr overridding Payment Estimate Exception 44 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$6,132.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0610 -							\$0.00	
	0620	POWER SUPPLY ASSEMBLY, TYPE 2	Material		3	Sep 3, 2024	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hargrr overridding Payment Estimate Exception 24 on the current Payment Estimate.
					3	Sep 3, 2024	SYSTEM	(\$8,500.00)	
					4	Sep 16, 2024	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hargrr overridding Payment Estimate Exception 30 on the current Payment Estimate.
					4	Sep 16, 2024	SYSTEM	(\$8,500.00)	
					5	Oct 1, 2024	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user hargrr overridding Payment Estimate Exception 41 on the current Payment Estimate.





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J3P3085H	0620	POWER SUPPLY ASSEMBLY,	Material		5	Oct 1, 2024	SYSTEM	(\$8,500.00)	
		TYPE 2			6	Oct 16, 2024	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hargrr overridding Payment Estimate Exception 45 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$8,500.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0620 -	Total						\$0.00	
	0690	SH-FLAT SHEET	Material		5	Oct 1, 2024	SYSTEM	\$1,012.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user hargrr overridding Payment Estimate Exception 42 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$1,012.50)	
					6	Oct 16, 2024	SYSTEM	\$1,012.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user hargrr overridding Payment Estimate Exception 46 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$1,012.50)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0690 -	Total						\$0.00	
	0700	ST- STRUCTURAL	Material		5	Oct 1, 2024	SYSTEM	\$8,659.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user hargrr overridding Payment Estimate Exception 43 on the current Payment Estimate.
					5	Oct 1, 2024	SYSTEM	(\$8,659.20)	
					6	Oct 16, 2024	SYSTEM	\$8,659.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hargrr overridding Payment Estimate Exception 47 on the current Payment Estimate.
					6	Oct 16, 2024	SYSTEM	(\$8,659.20)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0700 -	Total						\$0.00	
							\$0.00		
J3P3085H -	- Total								

# MoDOT

### Contract Adjustments for Contract - 240119-C01

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 28 of 28