

#### Missouri Department of Transportation Contractor's Pay Estimate Summary

240119-D03

Pay Estimate Created Date: November 18, 2024

Contract ID

Progress Estimate Number

	By User
Generated and Approved (and should be considered Draft) at the Project Office Level by	stokez1
Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	beckc2
Reviewed and Approved at the Central Office Controllers Office Level by	ramses1
	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2024	December 1, 2024		88.99%

Conti	Contract Informational Dates											
Date Description	Original Completion Date	Current Completion Date										
Acceptance Date												
Awarded Date	February 14, 2024	February 14, 2024										
Letting Date	January 19, 2024	January 19, 2024										
Notice to Proceed Date	March 11, 2024	March 11, 2024										

July 10, 2024

July 10, 2024

Date Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days
Milestone - Calendar Time - JSP B - Contract Liquidated Damages J5S3464 Route B	November 27, 2024	November 27, 2024	8	
Milestone - Calendar Time - JSP J - Bridge Closure Days J5P3467	October 12, 2024	November 9, 2024	-10	

Milestones

Pay Period Start November 2, 2024 Original Contract Amount \$3,309,174.67

Contract Total Pay	y For Estimate No. 9				
		This Estimate	Previous	To Date	
240119-D03					
	Total Posted Items Pay	\$222,181.67	\$2,901,768.41	\$3,123,950.08	
	Gross Item Adjustments	(\$70,927.33)	(\$61,697.79)	(\$132,625.12)	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$2,840,070.62	\$2,991,324.96	
<b>Contract Total Pay</b>	yable This Estimate:	\$151,254.34			

#### Items Paid This Estimate Period

Open to Traffic Date Work Began

Date

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3467	0130	6161055	SEQUENTIAL FLASHING WARNING LIGHT	EA	\$56.510	14	\$791.14
	0170	6171000	CONCRETE TRAFFIC BARRIER, TYPE A	LF	\$115.310	338	\$38,974.78
	0180	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	LF	\$27.130	-944.38	(\$25,621.03)
	0183	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	LF	\$50.860	0.44	\$22.38
	0185	6173706	TEMPORARY TRAFFIC BARRIER STIFFNESS TRANSITION SECTION, CONTRACTOR FURNISHED / RETAINED	LF	\$41.820	7.44	\$311.14
	0210	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$1.130	4,381.36	\$4,950.94
	0220	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$1.130	2,538.64	\$2,868.66
	0230	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$1.130	1,322.08	\$1,493.95

Revision 3/23/2023 Page 1 of 17



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 18, 2024

Progress Estimate Number 9				· · · · · · · · · · · · · · · · · · ·			
Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3467	0350	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	CY	\$700.000	14	\$9,800.00
	0410	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	SQFT	\$253.870	8	\$2,030.96
	0500	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	CY	\$700.000	64	\$44,800.00
	0530	7034214	CLASS B-2 CONCRETE	CUYD	\$512.520	26.3	\$13,479.28
	5003	7040104	HALF-SOLE REPAIR	SQFT	\$320.190	28	\$8,965.32
	5006	6122040	WORK ZONE CRASH CUSHION (NARROW)	EA	\$10,700.000	1	\$10,700.00
	5007	5059901		LS	\$11,709.800	1	\$11,709.80
Project J	5P3467 - T	otal					\$125,277.32
J5S3464	0830	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	SQFT	\$1,356.290	2	\$2,712.58
	0840	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	LS	\$67,553.090	0.5	\$33,776.55
	0850	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	LF	\$1,515.130	22	\$33,332.86
	0870	2169902	MISC.REMOVAL OF EXISTING BEARINGS	EA	\$114.940	6	\$689.64
	0890	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	CUYD	\$2,464.780	10	\$24,647.80
	0940	7161002	LAMINATED NEOPRENE BEARING PAD	EA	\$290.820	6	\$1,744.92
Project J	5S3464 - T	otal					\$96,904.35
Overall -	Total						\$222,181.67

#### Contract Adjustments This Estimate

		tments Exist on Contract						
Line Item	<u>Adjustr</u>	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3467	0170	CONCRETE TRAFFIC BARRIER, TYPE A	Material			-338	\$115.31	(\$38,974.78)
	0180	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',27.13000 - 27.13000, 'is applied (if non-zero).	880.38	\$27.13	\$23,884.71
	0185	TEMPORARY TRAFFIC BARRIER STIFFNESS TRANSITION SECTION, CONTRACTOR FURNISHED / RETAINED	Overrun			-7.44	\$41.82	(\$311.14)
	0210	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-8,250.56	\$1.13	(\$9,323.13)
	0210	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	8,250.56	\$1.13	\$9,323.13
	0220	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-5,905.28	\$1.13	(\$6,672.97)
	0220	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	5,905.28	\$1.13	\$6,672.97
	0230	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT	Material			-1,322.08	\$1.13	(\$1,493.95)

Page 2 of 17 Revision 3/23/2023



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 18, 2024

Progress Estimate Number
9
Contract ID 240119-D03 Pay Period Start November 2, 2024 Original Contract Amount \$3,309,174.67
Pay Period End November 15, 2024 Original Contract Amount \$201,420.95
Current Contract Amount \$3,309,174.67

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3467		MARKING PAINT, TYPE L BEADS						
	0230	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	1,322.08	\$1.13	\$1,493.95
	0350	SUPPLEMENTARY WEARING SURFACE MATERIAL	Overrun			-14	\$700.00	(\$9,800.00)
	0350	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material			-24	\$700.00	(\$16,800.00)
	0350	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	24	\$700.00	\$16,800.00
	0360	LATEX MODIFIED CONCRETE WEARING SURFACE	Material			-1,575	\$134.78	(\$212,278.50)
	0360	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	1,575	\$134.78	\$212,278.50
	0500	SUPPLEMENTARY WEARING SURFACE MATERIAL	Overrun			-64	\$700.00	(\$44,800.00)
	0500	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material			-104	\$700.00	(\$72,800.00)
	0500	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	104	\$700.00	\$72,800.00
	0510	LATEX MODIFIED CONCRETE WEARING SURFACE	Material			-2,796	\$134.78	(\$376,844.88)
	0510	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	2,796	\$134.78	\$376,844.88
	5006	WORK ZONE CRASH CUSHION (NARROW)	Overrun			-1	\$10,700.00	(\$10,700.00)
J5S3464	0880	MISC.	MaterialCredit			5.5	\$1,777.07	\$9,773.88
Total								(\$70,927.33)

Revision 3/23/2023 Page 3 of 17



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

						Santraat Dusiaat Information	_			
					C	Contract Project Information	n			
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work			
J5P3467	FAF 54-3(210)	2 Bridge rehabilitations	54	COLE	over W. McCarty and Rout	rer W. McCarty and Route 50				
J5S3464	FAS S403(13)	Bridge rehabilitation	В	COLE	over the Moreau River sou	uth of Jefferson City				
Totals by .	Job Numbe	rs								
J5P3467	J5P3467  Posted Item Pay Gross Item Adjustments Gross Item Pay				This Estimate \$125,277.32 (\$80,701.21) <b>\$44,576.11</b>	Previous \$2,211,062.57 (\$51,923.91) \$2,159,138.66	To Date \$2,336,339.89 (\$132,625.12) <b>\$2,203,714.77</b>			
	Incentive Disincentive Liquidated Damages Other Contract Adjustments				\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			
J5S3464  Posted Item Pay Gross Item Adjustments Gross Item Pay					This Estimate \$96,904.35 \$9,773.88 \$106,678.23	Previous \$690,705.84 (\$9,773.88) \$680,931.96	To Date \$787,610.19 \$0.00 \$787,610.19			
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			

Revision 3/23/2023 Page 4 of 17



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Number CSSS, Material Set 5600004, Material DGSSCCLATX - Bridge Deck Cornorse, Latex, Acceptance Action Genetic DGSCCLATX is insufficient. Set 5600004. White of DGSSCLATX - Bridge Deck Cornorse, Latex, Acceptance Action Genetic DGSSCCLATX is set with the Contract from submitting test results. Issues with CRE20 prevented Nation Genetic DGSSCCLATX is Bridge Deck Cornorse, Latex, Acceptance Action Genetic DGSSCCLATX - Bridge Deck Cornorse, Latex, Acceptance Action Genetic DGSSCCLATX - Bridge Deck Cornorse, Latex, Acceptance Action Genetic DGSSCCLATX - Bridge Deck Cornorse, Latex, Acceptance Action Genetic DGSSCCLATX - Bridge Deck Cornorse, Latex, Acceptance Action Genetic DGSSCCLATS, BCB Latex and Latex - Bridge Wearing Carther Grade Extended Control Cornor Cornors - Bridge Wearing Carther Grade Extended Cornors - Bridge Wearing Carther - Bridge Deck Ca	EXCEPTIONS (DISCREPANCIES) I NIS ESTIMATE PERIOD			
Number CSSS, Material Set 5600004, Material DGSSCCLATX - Bridge Deck Cornorse, Latex, Acceptance Action Genetic DGSCCLATX is insufficient. Set 5600004. White of DGSSCLATX - Bridge Deck Cornorse, Latex, Acceptance Action Genetic DGSSCCLATX is set with the Contract from submitting test results. Issues with CRE20 prevented Nation Genetic DGSSCCLATX is Bridge Deck Cornorse, Latex, Acceptance Action Genetic DGSSCCLATX - Bridge Deck Cornorse, Latex, Acceptance Action Genetic DGSSCCLATX - Bridge Deck Cornorse, Latex, Acceptance Action Genetic DGSSCCLATX - Bridge Deck Cornorse, Latex, Acceptance Action Genetic DGSSCCLATX - Bridge Deck Cornorse, Latex, Acceptance Action Genetic DGSSCCLATS, BCB Latex and Latex - Bridge Wearing Carther Grade Extended Control Cornor Cornors - Bridge Wearing Carther Grade Extended Cornors - Bridge Wearing Carther - Bridge Deck Ca	Exceptions / Discrepencies	Explanation		Status
Number 0000. Material Set 5500004. Material 05050CCLATX : Bridge Deck Concrete, Latex. Acceptance Materials: Stocked State (Concrete). The Contractor from submiting test results: Issues with CRE20 prevented the Contractor from submiting test results: Issues with CRE20 prevented the Contractor from submiting test results: Issues with CRE20 prevented the Contractor from submiting test results: Issues with CRE20 prevented the Contractor from submiting test results: Issues with CRE20 prevented the Contractor from submiting test results: Issues with CRE20 prevented the Contractor from submiting test results of CRE20 Contractors (CRE20 Contractors of CRE20 Contractors (CRE20 Contractors of CRE20 Contractors (CRE20 Contractors of CRE20 Contr	Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 5050004, Project Item Line Number 0350, Material Set 5050004, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	Waiting on 28 day test results. Issues with CRE20 prevented	stokez1	Overridden
Number 0300, Material Stel 505004, Material 1005GECMLSBD - Bridge Wearing Surface Grade E  SIDO, Acceptance Action Genetic 1005GECMLSBD - Bridge Wearing Surface Grade E  SISOD, Acceptance Action Genetic 1005GECMLSBD - Bridge Wearing Surface Grade E  SISOD, Acceptance Action Genetic 1005GECMLSBD - Bridge Wearing Surface Grade E  SISOD, Acceptance Action Genetic 1005GECMLSBD - Bridge Wearing Surface Grade E  SISOD, Acceptance Action Genetic 1005GECMLSBD - Bridge Wearing Surface Grade E  SISOD, Acceptance Action Genetic 1005GECMLSBD - Bridge Wearing Surface Grade E  SISOD, Acceptance Action Genetic 1005GECMLSBD - Bridge Wearing Surface Grade E  SISOD, Acceptance Action Genetic 1005GECMLSBD - Bridge Wearing Surface Grade E  SISOD, Acceptance Action Genetic 1005GECMLSBD - Bridge Wearing Surface Grade E  SISOD, Acceptance Action Genetic 1005GECMLSBD - Bridge Wearing Surface Grade E  SISOD, Acceptance Action Genetic 1005GECMLSBD - Bridge Wearing Surface Grade E  SISOD, Acceptance Action Genetic 1005GECMLSBD - Bridge Wearing Surface Grade E  SISOD, Acceptance Action Genetic 1005GECMLSBD - Bridge Wearing Surface Grade E  SISOD, Acceptance Action Genetic 1005GECMLSBD - Bridge Wearing Surface Grade E  SISOD, Acceptance Action Genetic 1005GECMLSBD - Bridge Wearing Surface Grade E  SISOD, Acceptance Action Genetic 1005GECMLSBD - Bridge Wearing Surface Grade E  SISON Acceptance Action Genetic 1005GECMLSBD - Bridge Wearing Surface Grade E  SISON Acceptance Action Genetic 1005GECMLSBD - Bridge Mean Line  Number 0170, Material Sct 91700006, Material 1005GMMD-SISOD, Material 1005MMD-SISOD, Material 1005MM	Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 5050004, Project Item Line Number 0500, Material Set 5050004, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	Waiting on 28 day test results. Issues with CRE20 prevented	stokez1	Overridden
Sumber 0380. Material Set 605020066, Material 1056ECMLSBD - Bindge Wearing Surface Grade E SEMO. Acceptance Action Generio 1056ECMLSBD - Bindge Wearing Surface Grade E Coment rock test needs to associated with this line item in CKE20 Sumber 6100. Material 1056ECMLSBD - Bindge Wearing Surface Grade E Coment rock test needs to be associated with this line item in CKE20 Sumber 6100. Material 1056ECMLSBD - Bindge Wearing Surface Grade E Coment rock test needs to be associated with this line item in CKE20 Sumber 6100. Material Set 61700096, Material 1056ECMLSBD - Bindge Wearing Surface Grade E Coment rock test needs to be associated with this line item in CKE20 Sumber 6107. Material Set 617100096, Material 1056CMLDST as insufficient Materials: Project JSP3467, Item 6171000, Project Item Line Number 0107. Material Set 617100096, Material 1056CMMLDST2 is insufficient. Purple Sumber 6107. Material Set 617100096, Material 1057AMDBECG 10 - Dowel Bar Epoxy Cld Gr60 1* g. Acceptance Action Generic 1055CMMLDST2 is insufficient. Purple Sumber 6107. Material Set 617100096, Material 1057AMDBECG 10 - Dowel Bar Epoxy Cld Gr60 1* g. Acceptance Action Generic 1055CMMLDST2 is insufficient. Purple Sumber 6107. Material Set 61700096, Material 1057AMDBECG 10 - Dowel Bar Epoxy Cld Gr60 1* g. Acceptance Action Generic 1048PMREMENT is insufficient. Purple Sumber 6107. Material Set 61505000AG, Material 1045PMREEMT is insufficient. Purple Sumber 6107. Material Set 6150500AG, Material 1045PMREMENT is insufficient. Purple Sumber 6107. Material Set 6150500AG, Material 1045PMREMENT is insufficient. Purple Sumber 6107. Material Set 615050AGA, Material 1045PMREMENT is insufficient. Purple Sumber 6107AMDBECG 1046PMREMENT is insufficient. Purple Sumber 6107AMDBECG 1046PMRE	Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 5050004, Project Item Line Number 0500, Material Set 5050004, Material 1005GECMLSBD - Bridge Wearing Surface Grade E LS/DO, Acceptance Action Generic 1005GECMLSBD is insufficient.	Current rock test needs to be associated with this line item in	stokez1	Overridden
Number 0750, Material Set 690500066, Material 1005GECMLSBID is instificient.   Science Exception Type: Insufficient Materials: Project J5P3467, Item 6171000, Project Item Line Number 0720, Material Set 617100066, Material 105GECMLSBID is insufficient.   Stokez1 Waiting on strength test.   Stokez1 Number 0710, Material Set 617100066, Material 105GECMMLDST2 - Write Pavement-Bridge Dissipating Out @ @. Acceptance Action Generic 105GECMMLDST2 is insufficient.   Stokez1 Number 0710, Material Set 617100066, Material 105GECMMLDST2 is insufficient.   Stokez1 Number 0710, Material Set 617100066, Material 105GECMMLDST2 is insufficient.   Stokez1 Number 0710, Material Set 617100066, Material 105GECMMLDST2 is insufficient.   Stokez1 Number 0710, Material Set 617100066, Material 105GECMMLDST2 is insufficient.   Stokez1 Number 0710, Material Set 617100066, Material 105GECMMLDST2 is insufficient.   Stokez1 Number 0710, Material Set 6205002A66, Material 105GECMMLDST2 is insufficient.   Stokez1 Number 0720, Material Set 6205002A66, Material 105GECMMLDST2 is insufficient.   Stokez1 Number 0720, Material Set 6205002A66, Material 105GECMMLDST3 is insufficient.   Stokez1 Number 0720, Material Set 6205002A66, Material 105GECMMLDST3 is insufficient.   Stokez1 Number 0720, Material Set 6205002A66, Material 105GECMMLDST3 is insufficient.   Stokez1 Number 0720, Material Set 6205002A66, Material 105GECMMLDST3 is insufficient.   Stokez1 Number 0720, Material Set 6205002A66, Material 105GECMMLDST3 is insufficient.   Stokez1 Number 0720, Material Set 6205002A66, Material 105GECMMLDST3 is insufficient.   Stokez1 Number 0720, Material Set 6205002A66, Material 105GECMMLDST3 is insufficient.   Stokez1 Number 0720, Material Set 6205002A66, Material 105GECMMLDST3 is insufficient.   Stokez1 Number 0720, Material Set 6205002A66, Material 105GECMMLDST3 is insufficient.   Stokez1 Number 0720, Material Set 6205002A66, Material 105GECMMLDST3 is	Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 5052000, Project Item Line Number 0360, Material Set 505200096, Material 1005GECMLSBD - Bridge Wearing Surface Grade E LS/DO, Acceptance Action Generic 1005GECMLSBD is insufficient.	current rock test needs to associated with this line item in	stokez1	Overridden
Number 0170, Material Set 617100096, Material S01CCB1 A concrete, Class B-1 wAir, Acceptance Action Generic 0501CCB1 A is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSPA67, Item 6171000, Project Item Line Number 0170, Material Set 617100006, Material 1050CMMLDST2 is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSPA67, Item 6171000, Project Item Line Number 0170, Material Set 617100006, Material 1050CMMLDST2 is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSPA67, Item 6205902A, Project Item Line Number 0170, Material Set 61700006, Material 1057MMDECOs 10 - Dowel Bair Epoxy Cld G60 1*  8 Acceptance Action Generic Reinforcing/Misc is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSPA67, Item 6205902A, Project Item Line Number 0210, Material Set 6205902A66, Material 1048PMREBMTL + Reflective Glass Beads Type L Embedm Cld, Acceptance Action Generic 1048PMREBMTL is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSPA67, Item 6205903A, Project Item Line Number 0210, Material Set 6205903A66, Material 1048PMREBMTL is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSPA67, Item 6205903A, Project Item Line Number 0210, Material Set 6205903A66, Material 1048PMREBMTL is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSPA67, Item 6205903A, Project Item Line Number 020, Material Set 6205903A66, Material 1048PMREBMTL is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSPA67, Item 6205903A, Project Item Line Number 020, Material Set 6205903A66, Material 1048PMREBMTL is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSPA67, Item 6205906A, Project Item Line Number 0206, Material Set 6205903A66, Material 1048PMREBMTL is insufficient.  Estimate Exception Type: Item Overrun: Contract 240119-MBCMTL insufficient.  Estimate Exception Type: Item Overrun: Contract 240119-MBCMTL insufficient.  Estimate Exception	Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 5052000, Project Item Line Number 0510, Material Set 505200096, Material 1005GECMLSBD - Bridge Wearing Surface Grade E LS/DO, Acceptance Action Generic 1005GECMLSBD is insufficient.	Current rock test needs to be associated with this line item in	stokez1	Overridden
Number 0170, Material Set 617100096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Genetic 1055CMMLDST2 is insufficient.  Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6171000, Project Item Line PAL needed for dowel bars PAL needed for dowel bars PAL needed for dowel bars Stokez1 Acknowledged Number 0170, Material Set 617700956, Material Set 6170095020, Project Item Line Number 0120, Material Set 61770095020, Project J5P3467, Item 6205902A, Project Item Line Number 0170, Material Set 617009502A, Project J5P3467, Item 6205903A, Project Item Line Number 0170, Material Set 617009502A, Project J5P3467, Item 6205903A, Project Item Line Number 0170, Material Set 617009503A, Material Set 617009503A, Project J5P3467, Item 6205903A, Project Item Line Number 0170, Material Set 617009503A, Material Set 617009503A, Project J5P3467, Item 6205903A, Project Item Line Number 0170, Material Set 617009503A, Material Set 617009503A, Material Set 617009503A, Project J5P3467, Item 61700950A, Project Item Line Number 0170, Material Set 61700950A, Project J5P3467, Item 61700950A, Project Item Line Number 0170, Material Set 61700950A, Material Set 61700950A, Project J5P3467, Item 61700950A, Project Item Line Number 0170, Material Set 61700950A, Project Item Line Number 0170, Material Set 61700950A, Material Set 61	Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6171000, Project Item Line Number 0170, Material Set 617100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.		stokez1	Acknowledged
Number 0170, Material Set 617100096, Material 1057JMDBECB.10 - Dowel Bar Epoxy Cld Gr60 1"  @. Acceptance Action Generic inelinforing/Miss is insufficient.  Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205902A, Project Item Line Number 0210, Material Set 6205902A96, Material 1046PMRBEMTL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205902A, Project Item Line Number 0210, Material Set 6205902A96, Material 1046PMRBEMTL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205902A, Project Item Line Number 0210, Material Set 6205903A96, Material 1046PMRBEMTL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205903A, Project Item Line Number 0220, Material Set 6205903A96, Material 1046PMRBEMTL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205903A, Project Item Line Number 0220, Material Set 6205903A96, Material 1046PMRBEMTL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205903A, Project Item Line Number 0230, Material Set 6205903A96, Material 1046PMRBEMTL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205906A, Project Item Line Number 0230, Material Set 6205903A96, Material 1046PMRBEMTL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205906A, Project Item Line Number 0230, Material Set 6205906A96, Material 1046PMRBEMTL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205906A, Project Item Line Number 0230, Material Set 6205906A96, Material 1046PMRBEMTL is insufficient.  Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Line Number 0230, Material Set 6205906A96, Material 1046PMRBEMTL is insufficient.  Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Line Number 030	Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6171000, Project Item Line Number 0170, Material Set 617100096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.		stokez1	Acknowledged
Number 02:10, Material Set 62:05902A96, Material 1048PMREBEMTL - Reflective Glass Beads Type L Estimate Exception Type: Insufficient Materials: Project JSP3467, Item 62:05902A, Project Item Line Number 02:20, Material Set 62:05902A96, Material 1048PMRTRHBWBWH - Marking Paint Acrylic Watr Itellidi White, Acceptance Action Generio 1048PMREBEMTL is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSP3467, Item 62:05903A, Project Item Line Number 02:00, Material Set 62:05903A96, Material 1048PMREBEMTL is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSP3467, Item 62:05903A, Project Item Line Number 02:00, Material Set 62:05903A96, Material 1048PMREBEMTL is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSP3467, Item 62:05903A, Project Item Line Number 02:00, Material Set 62:05903A96, Material 1048PMREBEMTL is insufficient.  Estimate Exception Type: Insufficient Materials: Project JSP3467, Item 62:05903A, Project Item Line Number 02:00, Material Set 62:05903A96, Material 1048PMREBEMTL is Materials: Project JSP3467, Item 62:05906A, Project Item Line Number 02:03, Material Set 62:05906A96, Material 1048PMREBEMTL is Reflective Glass Beads Type L Entimate Exception Type: Insufficient Materials: Project JSP3467, Item 62:05906A, Project Item Line Number 02:03, Material Set 62:05906A96, Material 1048PMREBEMTL is Insufficient.  Estimate Exception Type: Insufficient Materials: Project JSP3467, Item 62:05906A, Project Item Line Number 02:03, Material Set 62:05906A96, Material 1048PMREBEMTL is Insufficient.  Estimate Exception Type: Item Overrur: Contract 24:0119-03, Contract Project JSP3467, Project Item Line Number 0185, Contract Line Item Number 0185, Item 6173706, Minor Item.  Estimate Exception Type: Item Overrur: Contract 24:0119-03, Contract Project JSP3467, Project Item Line Number 05:006, Contract Line Item Number 05:006, Item 612:2040, Minor Item.  Estimate Exception Type: Item Overrur: Contract 24:0119-03, Contract Project JSP3467, Project Ite	Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6171000, Project Item Line Number 0170, Material Set 617100096, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.		stokez1	Acknowledged
Number 0210, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr Hilbild White, Acceptance Action Generic 1048PMTRHBWBWH - Marking Paint Acrylic Watr Hilbild White, Acceptance Action Generic 1048PMTRHBWBWH - Marking Paint Acrylic Watr Hilbild Verbies (205903A), Project Item Line Number 0220, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient. Is insufficient is insufficient is insufficient is insufficient is insufficient is insufficient. Is insufficient is insufficient is insufficient in Stokez 1 (Insufficient Materials: Project J5P3467, Item 6205903A, Project Item Line Number 0220, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr Hilbild Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205906A, Project Item Line Number 0230, Material Set 6205906A96, Material 1048PMTRHBWBYL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205906A, Project Item Line Number 0230, Material Set 6205906A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr Hilbild White, Acceptance Action Generic 1048PMTRHBWBWH - Marking Paint Acrylic Watr Hilbild White, Acceptance Action Generic 1048PMTRHBWBWH - Marking Paint Acrylic Watr Hilbild White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.  Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Change order is required.  Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Change order is required.  Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Change order is required.  Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Change order is required.  Estimate Exception Type: Item Overrun: Contract 240119-D03, Contr	Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205902A, Project Item Line Number 0210, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.		stokez1	Overridden
Number 0220, Material Set 8205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205903A, Project Item Line Number 0320, Material Set 6205903A, Material 1048PMTRHBWBYL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205906A, Project Item Line Number 0230, Material Set 6205906A96, Material 1048PMTRHBWBYL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205906A, Project Item Line Number 0230, Material Set 6205906A96, Material 1048PMRBEMTL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205906A, Project Item Line Number 0230, Material Set 6205906A96, Material 1048PMRBEMTL is insufficient.  Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205906A, Project Item Line Number 0230, Material Set 6205906A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Water HiBld White, Acceptance Action Generic 1048PMTRHBWBWH - Marking Paint Acrylic Water HiBld White, Acceptance Action Generic 1048PMTRHBWBWH - Marking Paint Acrylic Water HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.  Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Change order is required.  Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Change order is required.  Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Change order is required.  Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Change order is required.  Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Change order is required.  Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Change order is	Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205902A, Project Item Line Number 0210, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.		stokez1	Overridden
Number 0220, Material Set 6205903A96, Material 1048PMTRHBWBYL is insufficient.  Stokez1 Number 0230, Material Set 6205906A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.  Stokez1 Modot needs to complete the test  Stokez1 Change order is required.	Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205903A, Project Item Line Number 0220, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.		stokez1	Overridden
Number 0230, Material Set 6205906A96, Material 1048PMRBEMTL is insufficient.  Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Line Number 0350, Contract Line Item Number 0500, Item 5050004, Minor Item.  Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Line Number 0350, Contract Line Item Number 0350, Item 5050004, Minor Item.  Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Line Number 0350, Contract Line Item Number 0500, Contract Line Item Number 0500, Item 5050004, Minor Item.  Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Line Number 0500, Contract Line Item Number 0500, Item 5050004, Minor Item.  Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Change order is required.  Stokez1  Change order is required.	Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205903A, Project Item Line Number 0220, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.		stokez1	Overridden
Number 0230, Material Set 6205906A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.  Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Line Number 0350, Contract Line Item Number 0350, Contract Line Item Number 0350, Contract Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Line Number 0500, Contract Line Item Number 05000, Contract Vine Item 05000, Contract Vine Vine 05000, Contract Vine 05000, Contract Vine 05000, Contract Vine Vine 05000, Contract Vine Vine 05000, Contract Vine 05000, Contract Vine 05000, Cont	Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205906A, Project Item Line Number 0230, Material Set 6205906A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.		stokez1	Overridden
Line Number 0185, Contract Line Item Number 0185, Item 6173706, Minor Item.  Change order is required.  Stokez1 Change order is required.	Estimate Exception Type: Insufficient Materials: Project J5P3467, Item 6205906A, Project Item Line Number 0230, Material Set 6205906A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.		stokez1	Overridden
Line Number 0350, Contract Line Item Number 0350, Item 5050004, Minor Item.  Change order is required.  Stokez1 Change order is required.	Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Line Number 0185, Contract Line Item Number 0185, Item 6173706, Minor Item.		stokez1	Acknowledged
Line Number 0500, Contract Line Item Number 0500, Item 5050004, Minor Item.  Change order is required.  Stokez1 Stokez1 Change order is required.  Stokez1 Stokez1 Change order is required.  Stokez1 Stokez1 Change order is required.	Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Line Number 0350, Contract Line Item Number 0350, Item 5050004, Minor Item.		stokez1	Acknowledged
Line Number 5006, Contract Line Item Number 5006, Item 6122040, Minor Item.  Change order is required.  Change order is required.  Stokez1 Stokez1 Stokez1 Acknowledged	Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Line Number 0500, Contract Line Item Number 0500, Item 5050004, Minor Item.		stokez1	Acknowledged
Line Number 0240, Contract Line Item Number 0240, Item 6207001, Minor Item.  Change order is required.  Change order is required.  Stokez1  Stokez1  Acknowledged	Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Line Number 5006, Contract Line Item Number 5006, Item 6122040, Minor Item.		stokez1	Acknowledged
	Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Line Number 0240, Contract Line Item Number 0240, Item 6207001, Minor Item.		stokez1	Acknowledged
	Estimate Exception Type: Item Overrun: Contract 240119-D03, Contract Project J5P3467, Project Item Line Number 0250, Contract Line Item Number 0250, Item 6208076, Minor Item.	Stokez1 Change order is required.	stokez1	Acknowledged

Revision 3/23/2023 Page 5 of 17



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
240119-D03	J5P3467	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$29,661.91	\$29,661.9
		0001	0020	4030003	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095C MIX)	6.00	-6.00	0.00	TONS	0.00	\$1,723.62	\$0.0
		0001	0030	4071005	TACK COAT	8.00	0.00	8.00	GAL	8.00	\$28.26	\$226.0
		0001	0040	6122014	IMPACT ATTENUATOR 60 MPH (SAND BARREL ARRAY)	2.00	2.00	4.00	EA	3.00	\$3,390.73	\$10,172.1
		0001	0050	6122020	REPLACEMENT SAND BARREL	4.00	0.00	4.00	EA	0.00	\$339.07	\$0.0
		0001	0060	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	3.00	0.00	3.00	EA	3.00	\$11,302.42	\$33,907.2
		0001	0070	6161005	CONSTRUCTION SIGNS	2,838.00	21.00	2,859.00	SQFT	2,466.04	\$6.78	\$16,719.7
		0001	0080	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	0.00	8.00	EA	8.00	\$113.02	\$904.1
		0001	0090	6161025	CHANNELIZER (TRIM LINE)	97.00	139.00	236.00	EA	236.00	\$22.60	\$5,333.6
		0001	0100	6161030	TYPE III MOVEABLE BARRICADE	13.00	0.00	13.00	EA	13.00	\$12.43	\$161.5
		0001	0110	6161033	DIRECTIONAL INDICATOR BARRICADE	38.00	8.00	46.00	EA	46.00	\$73.47	\$3,379.6
		0001	0120	6161040	FLASHING ARROW PANEL	3.00	1.00	4.00	EA	4.00	\$847.68	\$3,390.7
		0001	0130	6161055	SEQUENTIAL FLASHING WARNING LIGHT	38.00	0.00	38.00	EA	28.00	\$56.51	\$1,582.2
		0001	0140	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	10.00	0.00	10.00	EA	10.00	\$2,825.61	\$28,256.1
		0001	0150	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	8.00	0.00	8.00	EA	8.00	\$904.19	\$7,233.5
		0001	0160	6169901	MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM	1.00	0.00	1.00	LS	0.80	\$45,209.69	\$36,167.7
		0001	0170	6171000	CONCRETE TRAFFIC BARRIER, TYPE A	338.00	0.00	338.00	LF	338.00	\$115.31	\$38,974.7
		0001	0180	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	5,237.00	-700.00	4,537.00	LF	4,473.00	\$27.13	\$121,352.4
		0001	0183	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	613.00	700.00	1,313.00	LF	1,199.00	\$50.86	\$60,981.1
		0001	0185	6173706	TEMPORARY TRAFFIC BARRIER STIFFNESS TRANSITION SECTION, CONTRACTOR FURNISHED / RETAINED	250.00	0.00	250.00	LF	300.00	\$41.82	\$12,546.0
		0001	0190	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$329,267.66	\$329,267.6
		0001	0200	6181015	RAILROAD PLAN SUBMITTAL	1.00	0.00	1.00	LS	1.00	\$12,512.36	\$12,512.3
		0001	0210	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	9,790.00	0.00	9,790.00	LF	8,250.56	\$1.13	\$9,323.1
		0001	0220	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	8,010.00	0.00	8,010.00	LF	5,905.28	\$1.13	\$6,672.9
		0001	0230	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,838.00	0.00	1,838.00	LF	1,322.08	\$1.13	\$1,493.9
		0001	0240	6207001	PAVEMENT MARKING REMOVAL	17,271.00	0.00	17,271.00	LF	17,430.00	\$1.13	\$19,695.9
		0001	0250	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	34,480.00	1,436.00	35,916.00	LF	36,075.00	\$1.13	\$40,764.7
		0001	0260	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	75.00	0.00	75.00	SQYD	75.00	\$101.72	\$7,629.0
		0040	0270	9035004A	SH-FLAT SHEET	15.00	0.00	15.00	SQFT	15.00	\$33.91	\$508.6
		0040	0280	9035069A	SHF-FLAT SHEET FLUORESCENT	89.00	0.00	89.00	SQFT	89.00	\$50.86	\$4,526.5
		0070	0290	2161000	SCARIFICATION OF BRIDGE DECK	370.00	0.00	370.00	SQYD	370.00	\$32.46	\$12,010.2
		0070	0300	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,575.00	0.00	1,575.00	SQYD	1,575.00	\$38.27	\$60,275.2
		0070	0310	2161502	REMOVAL OF CONCRETE WEARING SURFACE	10,849.00	0.00	10,849.00	SQFT	10,849.00	\$1.72	\$18,660.2
		0070	0320	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	126.00	226.00	SQFT	127.00	\$40.43	\$5,134.6
		0070	0330	2163000	PARTIAL REMOVAL OF EXISTING BRIDGE DECK	766.00	-383.00	383.00	SQFT	383.00	\$26.51	\$10,153.3
		0070	0340	2169903	MISC.PARTIAL REMOVAL OF BOTTOM OF EXISTING BRIDGE DECK	388.00	-194.00	194.00	LF	194.00	\$126.64	\$24,568.1
		0070	0350	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	5.00	0.00	5.00	CY	24.00	\$700.00	\$16,800.0
		0070	0360	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,575.00	0.00	1,575.00	SQYD	1,575.00	\$134.78	\$212,278.5
		0070	0370	7031004	DIAMOND GRINDING	1,575.00	0.00	1,575.00	SQYD	0.00	\$14.98	\$0.0
		0070	0380	7034214	CLASS B-2 CONCRETE	23.60	-11.80	11.80	CUYD	11.80	\$512.52	\$6,047.7
		0070	0390	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	50.00	0.00	50.00	SQFT	0.00	\$258.23	\$0.0
		0070	0400	7040106	FULL DEPTH REPAIR	50.00	-25.00	25.00	SQFT	0.00	\$631.28	\$0.0
		0070	0410	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	50.00	0.00	50.00	SQFT	8.00	\$253.87	\$2,030.9
		0070	0420	7049903	MISC.SUPERSTRUCTURE REPAIR (LONGITUDINAL JOINT)	390.00	-195.00	195.00	LF	0.00	\$79.18	\$0.0

Revision 3/23/2023 Page 6 of 17



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Contract	Project	Category		Item	eport Generated date and can differ from the posted amo	Bid	Net	Total	Unit	Total	Unit Price	Total Value POSTED
Im.CONTRACT	No.	Outogory	No.	Code	Besoription	Quantity	Change Order	Current Quantity	Onit	Posted Approved Qty	Office 1 Floor	To Date (See report generated date)
40119-D03	J5P3467	0070	0430	7101000	REINFORCING STEEL (EPOXY COATED)	5,280.00	0.00	5,280.00	LB	5,280.00	\$3.64	\$19,219.20
		0071	0440	2161000	SCARIFICATION OF BRIDGE DECK	655.00	0.00	655.00	SQYD	655.00	\$32.46	\$21,261.30
		0071	0450	2161001	TOTAL SURFACE HYDRO DEMOLITION	2,796.00	0.00	2,796.00	SQYD	2,796.00	\$38.27	\$107,002.93
		0071	0460	2161502	REMOVAL OF CONCRETE WEARING SURFACE	19,266.00	0.00	19,266.00	SQFT	19,266.00	\$1.72	\$33,137.52
		0071	0470	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	314.00	414.00	SQFT	248.00	\$40.43	\$10,026.64
		0071	0480	2163000	PARTIAL REMOVAL OF EXISTING BRIDGE DECK	1,419.00	-709.00	710.00	SQFT	232.00	\$26.51	\$6,150.33
		0071	0490	2169903	MISC.PARTIAL REMOVAL OF BOTTOM OF EXISTING BRIDGE DECK	698.00	-349.00	349.00	LF	349.00	\$126.64	\$44,197.3
		0071	0500	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	8.00	0.00	8.00	CY	104.00	\$700.00	\$72,800.0
		0071	0510	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	2,796.00	0.00	2,796.00	SQYD	2,796.00	\$134.78	\$376,844.8
		0071	0520	7031004	DIAMOND GRINDING	2,796.00	0.00	2,796.00	SQYD	0.00	\$14.98	\$0.00
		0071	0530	7034214	CLASS B-2 CONCRETE	52.60	-26.30	26.30	CUYD	26.30	\$512.52	\$13,479.28
		0071	0540	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	50.00	0.00	50.00	SQFT	0.00	\$258.23	\$0.00
		0071	0550	7040104	HALF-SOLE REPAIR	50.00	215.00	265.00	SQFT	265.00	\$320.19	\$84,850.3
		0071	0560	7040106	FULL DEPTH REPAIR	50.00	-25.00	25.00	SQFT	0.00	\$631.28	\$0.00
		0071	0570	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	50.00	0.00	50.00	SQFT	0.00	\$253.87	\$0.00
		0071	0580	7049903	MISC.SUPERSTRUCTURE REPAIR (LONGITUDINAL JOINT)	698.00	-349.00	349.00	LF	0.00	\$79.18	\$0.00
		0071	0590	7101000	REINFORCING STEEL (EPOXY COATED)	9,700.00	0.00	9,700.00	LB	9,700.00	\$3.64	\$35,308.00
		0001	5001	6069901	MISC.GUARDRAIL REMOVE AND REPLACE	0.00	1.00	1.00	LS	1.00	\$5,335.00	\$5,335.00
		0001	5002	4019910	MISC.BITUMINOUS PAVEMENT MIXTURE PG6422, (BP-1)	0.00	7.50	7.50	TONS	7.50	\$1,686.28	\$12,647.10
		0070	5003	7040104	HALF-SOLE REPAIR	0.00	28.00	28.00	SQFT	28.00	\$320.19	\$8,965.32
		0071	5005	1094000	FORCE ACCOUNT	0.00	250,000.00	250,000.00	EA	230,000.00	\$1.00	\$230,000.00
		0001	5006	6122040	WORK ZONE CRASH CUSHION (NARROW)	0.00	2.00	2.00	EA	3.00	\$10,700.00	\$32,100.0
		0001	5007	5059901		0.00	1.00	1.00	LS	1.00	\$11,709.80	\$11,709.80
	Project J	5P3467 - To	otal Value	Posted to D 6113020	late as of Report Generated Date FURNISHING TYPE 2 ROCK BLANKET	104.00	0.00	104.00	CUYD	0.00	\$41.55	\$2,336,339.80 \$0.00
	0000404	0001	0610	6113040	PLACING TYPE 2 ROCK BLANKET	104.00	0.00	104.00	CUYD	0.00	\$31.52	\$0.00
		0001	0620	6122014	IMPACT ATTENUATOR 60 MPH (SAND BARREL ARRAY)	4.00	0.00	4.00	EA	2.00	\$3,390.73	\$6,781.46
		0001	0630	6122020	REPLACEMENT SAND BARREL	4.00	0.00	4.00	EA	0.00	\$339.07	\$0.00
		0001	0640	6122030	IMPACT ATTENUATOR (RELOCATION)	4.00	0.00	4.00	EA	0.00	\$1,695.36	\$0.00
		0001	0650	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	1.00	\$11.302.42	\$11,302.42
		0001	0660	6161005	CONSTRUCTION SIGNS	285.00	0.00	285.00	SQFT	236.00	\$9.04	\$2,133.44
		0001	0670	6161008	ADVANCED WARNING RAIL SYSTEM	6.00	0.00	6.00	EA	4.00	\$113.02	\$452.08
		0001	0680	6161025	CHANNELIZER (TRIM LINE)	22.00	0.00	22.00	EA	22.00	\$22.60	\$497.20
		0001	0690	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE. CONTRACTOR FURNISHED. CONTRACTOR	4.00	0.00	4.00	EA	2.00	\$2,825.61	\$5,651.23
		0001	0700	6162000A	RETAINED  WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$19,666.21	\$19,666.2
			0710	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	2.00	0.00	2.00	EA	2.00	\$904.19	
		0001	0720	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED /	550.00	0.00	550.00	LF	550.00	\$27.13	\$1,808.3i \$14,921.5i
		0001	0730	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	550.00	0.00	550.00	LF	0.00	\$19.21	\$0.0
		0001	0740	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$251,808.86	\$251,808.8
		0001	0750	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	12,290.00	0.00	12,290.00	LF	4,131.00	\$0.68	\$2,809.08
		0001	0760	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	2,754.00	0.00	2,754.00	LF	2,710.00	\$1.13	\$3,062.3
		0001	0770	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	24.00	0.00	24.00	LF	24.00	\$113.02	\$2,712.48
		0001	0780	6207001	PAVEMENT MARKING REMOVAL	15,068.00	0.00	15,068.00	LF	7,853.75	\$1.13	\$8,874.74
		0001	0790	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	156.00	0.00	156.00	SQYD	0.00	\$5.21	\$0.00
		0001	0.00			100.00					7	φυ.υς

Revision 3/23/2023 Page 7 of 17

1.00

0.00

1.00

LS

0.00

\$5,651.21

\$0.00

0800

8059901 MISC.SEEDING - COOL SEASON GRASSES



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
240119-D03	J5S3464	0001	0810	8061016	SEDIMENT REMOVAL	5.00	0.00	5.00	CUYD	0.00	\$426.06	\$0.00
		0001	0820	8061019	SILT FENCE	525.00	0.00	525.00	LF	310.00	\$3.62	\$1,122.20
		0070	0830	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	2.00	0.00	2.00	SQFT	2.00	\$1,356.29	\$2,712.58
		0070	0840	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	1.00	\$67,553.09	\$67,553.09
		0070	0850	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	44.00	0.00	44.00	LF	44.00	\$1,515.13	\$66,665.72
		0070	0860	2169901	MISC.TEMPORARY FALSEWORK	1.00	0.00	1.00	LS	0.80	\$257,416.66	\$205,933.33
		0070	0870	2169902	MISC.REMOVAL OF EXISTING BEARINGS	12.00	0.00	12.00	EA	12.00	\$114.94	\$1,379.28
		0070	0880	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	11.00	0.00	11.00	LF	5.50	\$1,777.07	\$9,773.88
		0070	0890	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	20.00	0.00	20.00	CUYD	20.00	\$2,464.78	\$49,295.60
		0070	0900	7034214	CLASS B-2 CONCRETE	16.00	0.00	16.00	CUYD	8.00	\$4,696.03	\$37,568.24
		0070	0910	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	10.00	0.00	10.00	SQFT	0.00	\$317.14	\$0.00
		0070	0920	7069911	MISC.REINFORCING STEEL (GALVANIZED)	18,370.00	-9,260.00	9,110.00	LB	4,626.00	\$2.46	\$11,379.96
		0070	0930	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$9,267.99	\$0.00
		0070	0940	7161002	LAMINATED NEOPRENE BEARING PAD	12.00	0.00	12.00	EA	6.00	\$290.82	\$1,744.92
		0070	0950	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	44.00	0.00	44.00	LF	0.00	\$465.74	\$0.00
		0001	5004	6122040	WORK ZONE CRASH CUSHION (NARROW)	0.00	0.00	0.00	EA	0.00	\$10,700.00	\$0.00
	Project J	5S3464 - To	otal Value	Posted to E	Date as of Report Generated Date							\$787,610.17
240119-D03 Ove	erall - Total	Value Post	ted to Da	te as of Rep	ort Generated Date							\$3,123,950.04

Page 8 of 17 Revision 3/23/2023



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5P3467

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0130	6161055	SEQUENTIAL FLASHING WARNING LIGHT	11/15/24	11/18/24	14.00	EA	Mobile					
0170	6171000	CONCRETE TRAFFIC BARRIER, TYPE A	11/15/24	11/18/24	338.00	LF	Rte. 54 LM 168.214 - 168.278					
0180	6173600D	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	11/15/24	11/18/24	-5,417.38	LF	NA					Quantity is being removed to correctly pay for each stage of traffic
				11/18/24	2,170.50	LF	Stage 2 traffic on Rte. 54 from LM 167.886 to 168.802					
				11/18/24	2,302.50	LF	Stage 1 traffic on Rte. 54 from LM 167.886 to 168.802					
0183	6173700B	TEMP. TRAFFIC BARRIER ANCHORED., CONT	11/15/24	11/18/24	-1,198.56	LF	NA					Quantity is being removed to correctly pay for each stage of traffic
				11/18/24	554.50	LF	Stage 1 traffic on Rte. 54 from LM 167.886 to 168.802					
				11/18/24	644.50	LF	Stage 2 traffic on Rte. 54 from LM 167.886 to 168.802					
0185	6173706	TEMP. TRAF. BARR. STIFF. TRNS. SEC, CONT	11/15/24	11/18/24	-292.56	LF	NA					Quantity is being removed to correctly pay for each stage of traffic
				11/18/24	150.00	LF	Stage 1 traffic on Rte. 54 from LM 167.886 to 168.802					
				11/18/24	150.00	LF	Stage 2 traffic on Rte. 54 from LM 167.886 to 168.802					
0210	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	11/15/24	11/18/24	4,381.36	LF	WB Rte. 54 LM 102.991 - 103.592					Solid - 4657 * 0.8 = 3725.6 Int - 793.3 * 0.8 = 634.64 Dot - 26.4 * 0.8 = 21.12
0220	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	11/15/24	11/18/24	2,538.64	LF	WB Rte. 54 LM 102.991 - 103.592					3173.3*.8 = 2538.64
0230	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAINT	11/15/24	11/18/24	359.04	LF	WB Rte. 54 LM 102.991 - 103.592					Solid - 186.1 * 0.8 = 148.88 Dot - 262.7 * 0.8 = 210.16
				11/18/24	963.04	LF	EB Rte. 54 LM 167.886 to 168.802					Solid - 1045.4 * 0.8 = 836.32 Dot - 158.4 * 0.8 = 126.72
0350	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	11/15/24	11/18/24	14.00	CY	See posting from 10/28					
0410	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	11/15/24	11/18/24	8.00	SQFT	A1416 repairs on the WB lanes					
0500	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	11/15/24	11/18/24	64.00	CY	See posting from 10/25					
0530	7034214	CLASS B-2 CONCRETE	11/15/24	11/18/24	26.30	CUYD	Rte. 54 on Bridge A1417					This total payment is a place holder except for 19.63 CY that was placed at the locations that was not full depth repair/force account
5003	7040104	HALF-SOLE REPAIR	11/15/24	11/18/24	28.00	SQFT	A1416 bridge in the WB lanes					
5006	6122040	WORK ZONE CRASH CUSHION (NARROW)	11/15/24	11/18/24	1.00	EA	The South end of the Rte. 54 cross-over an additional narrow work zone crash cushion was needed to replace the sand barrel array.					
5007	5059901	MISC.	11/15/24	11/18/24	1.00	LS	Bridge header transition on and off of bridges A1416 and A1417					

#### Project: J5S3464

Line Number	Item Code	Description	DWR Date		Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0830	2024043	REMOVAL OF MISCELLANEOUS ACM NON-FRIABLE	11/13/24	11/13/24	2.00	SQFT	At Bent 4 where the railing bracket were.	22				Both NB and SB Lanes
0840	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	11/13/24	11/13/24	0.50	LS	SB Lane or West Side of the Bridge	22				
0850	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	11/13/24	11/13/24	22.00	LF	SB Lane or West Side of the Bridge	22				
0870	2169902	MISC. REMOVALS	11/13/24	11/13/24	6.00	EA	SB Lane or West Side of the Bridge	22				
0890	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	11/14/24	11/14/24	10.00	CUYD		22				Bent 4 Cap Pour for the SB Side
0940	7161002	LAMINATED NEOPRENE BEARING PAD	11/13/24	11/13/24	6.00	EA	NB Lane or East Side of the Bridge	22				

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 3/23/2023 Page 9 of 17



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
P3467	0030	TACK COAT	Material		2	Aug 2, 2024	SYSTEM	(\$226.08)	
					3	Aug 16, 2024	SYSTEM	(\$226.08)	
				- Total				(\$452.16)	
			Material - Tota	ı				(\$452.16)	
			MaterialCredit		3	Aug 16,	SYSTEM	\$226.08	
					4	2024 Sep 3,	SYSTEM	\$226.08	
				- Total		2024		\$452.16	
			MaterialCredit	- Total				\$452.16	
	0030 -	Total						\$0.00	
	0040	IMPACT ATTENUATOR 60	Overrun	Overrun	2	Aug 2, 2024	SYSTEM	(\$3,390.73)	
		MPH (SAND BARREL ARRAY)			3	Aug 16, 2024	SYSTEM	\$3,390.73	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3390.73000 - 3390.73000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0040 -	Total						\$0.00	
	0060	TRUCK OR TRAILER MOUNTED ATTEN (TMA)	Material		1	Jul 17, 2024	SYSTEM	\$22,604.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Jul 17, 2024	SYSTEM	(\$22,604.84)	
				- Total				\$0.00	
	0060 -		Material - Tota	ı				\$0.00	
		Total						\$0.00	
	0070	- Total  CONSTRUCTION SIGNS	Material		1	Jul 17, 2024	SYSTEM	\$3,254.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
						1 Jul 17, SYSTE 2024		(\$3,254.40)	
				- Total				\$0.00	
			Material - Tota	d				\$0.00	
	0070 -	Total						\$0.00	
	0090	CHANNELIZER (TRIM LINE)	Overrun	Overrun	1	Jul 17, 2024	SYSTEM	(\$3,141.40)	
					3	Aug 16, 2024	SYSTEM	\$3,141.40	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',22.60000 - 22.60000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0090 -	Total						\$0.00	
	0110	DIRECTIONAL INDICATOR	Overrun	Overrun	1	Jul 17, 2024	SYSTEM	(\$587.76)	
		BARRICADE			3	Aug 16, 2024	SYSTEM	\$587.76	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',73.47000 - 73.47000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0110 -	Total						\$0.00	
	0120	FLASHING ARROW PANEL	Overrun	Overrun	1	Jul 17, 2024	SYSTEM	(\$847.68)	
					3	Aug 16, 2024	SYSTEM	\$847.68	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',847.68000 - 847.68000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota					\$0.00	
	0120 -	Total						\$0.00	



roject	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
roject	LIIIC	Безеприоп	Туре	Adjustment Type	Number	Date	By	Amount	Kemare
P3467	0140	CMS WITH COMMUNICATION INTERFACE,	Material		1	Jul 17, 2024	SYSTEM	\$28,256.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		CONT F			1	Jul 17, 2024	SYSTEM	(\$28,256.10)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	0140 -	Total						\$0.00	
	0160	MISC.	Material		1	Jul 17, 2024	SYSTEM	\$15,823.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					1	Jul 17, 2024	SYSTEM	(\$15,823.39)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	0160 -	Total						\$0.00	
	0170	CONCRETE TRAFFIC BARRIER, TYPE A	Material		9	Nov 18, 2024	SYSTEM	(\$38,974.78)	
		,		- Total				(\$38,974.78)	
			Material - Tota	ıl				(\$38,974.78)	
	0170 -	Total						(\$38,974.78)	
	0180	TEMPORARY TRAFFIC BARRIER, CONT.	Overrun	Overrun		Oct 1, 2024	SYSTEM	(\$23,884.71)	
		FURN/RE			9	Nov 18, 2024	SYSTEM	\$23,884.71	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',27.13000 - 27.13000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
- 1	0180 -	Total						\$0.00	
	0185	TEMP. TRAF. BARR. STIFF. TRNS. SEC, CONT	Overrun	Overrun	9	Oct 1, 2024	SYSTEM	(\$1,779.86)	
				Overrun - T		Nov 18, 2024	SYSTEM	(\$311.14)	
			Overrun - Tota	Overrun - Total				(\$2,091.00)	
	0185 -	Total	Overruit - Tota	al .				(\$2,091.00)	
	0210	6 IN. WHITE HIGH BUILD WATERBORNE	Material		8	Nov 4, 2024	SYSTEM	\$4,372.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
		PAINT			8	Nov 4, 2024	SYSTEM	(\$4,372.20)	
					9	Nov 18, 2024	SYSTEM	\$9,323.13	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					9	Nov 18, 2024	SYSTEM	(\$9,323.13)	
				Total		2024		-00.00	 
			Material Toron	- Total				\$0.00	
	0240	Total	Material - Tota	11				\$0.00	
	0210 -		Madagid		0	Nin 4	OVOTE:	\$0.00	This adjustment off at the original and
	0220	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	Material		8	Nov 4, 2024	SYSTEM	\$3,804.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					8	Nov 4, 2024	SYSTEM	(\$3,804.30)	
					9	Nov 18, 2024	SYSTEM	\$6,672.97	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					9	Nov 18, 2024	SYSTEM	(\$6,672.97)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
									<del>,</del>



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
5P3467	0220 -	Total						\$0.00			
	0230	12 IN. WHITE HIGH BUILD WATERBORNE PAINT	Material		9	Nov 18, 2024	SYSTEM	\$1,493.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.		
		FAINT			9	Nov 18, 2024	SYSTEM	(\$1,493.95)			
				- Total				\$0.00			
			Material - Tota	1				\$0.00			
	0230 -	Total						\$0.00			
	0240	PAVEMENT MARKING	Overrun	Overrun	6	Oct 1, 2024	SYSTEM	(\$179.67)			
		REMOVAL		Overrun - T	otal			(\$179.67)			
			Overrun - Tota	ıl				(\$179.67)			
	0240 -	Total						(\$179.67)			
	0250	4 IN TEMPORARY PAVEMENT MARKING PAINT	Material		1	Jul 17, 2024	SYSTEM	\$3,890.59	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.		
					1	Jul 17, 2024	SYSTEM	(\$3,890.59)			
				- Total				\$0.00			
			Material - Tota					\$0.00			
			Overrun	Overrun	6	Oct 1, 2024	SYSTEM	(\$179.67)			
				Overrun - T	otal			(\$179.67)			
			Overrun - Tota	ıl				(\$179.67)			
	0250 -	· Total						(\$179.67)			
	0270	SH-FLAT SHEET	Material		2	Aug 2, 2024	SYSTEM	\$508.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
							2	Aug 2, 2024	SYSTEM	(\$508.65)	
						3	Aug 16, 2024	SYSTEM	(\$508.65)		
				- Total				(\$508.65)			
			Material - Tota	ı				(\$508.65)			
			MaterialCredit		4	Sep 3, 2024	SYSTEM	\$508.65			
				- Total				\$508.65			
			MaterialCredit	- Total				\$508.65			
	0270 -	Total						\$0.00			
	0280	SHF-FLAT SHEET FLUORESCENT	Material		2	Aug 2, 2024	SYSTEM	\$4,526.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					2	Aug 2, 2024	SYSTEM	(\$4,526.54)			
					3	Aug 16, 2024	SYSTEM	(\$4,526.54)			
				- Total				(\$4,526.54)			
			Material - Tota					(\$4,526.54)			
			MaterialCredit		4	Sep 3, 2024	SYSTEM	\$4,526.54			
				- Total				\$4,526.54			
			MaterialCredit	- Total				\$4,526.54			
	0280 -	Total						\$0.00			
	0320	REMOVAL OF EXISTING DECK REPAIR	Overrun	Overrun	2	Aug 2, 2024	SYSTEM	(\$1,091.61)			
		REPAIR			3	Aug 16, 2024	SYSTEM	\$1,091.61	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',40.43000 - 40.43000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J5P3467	0320	REMOVAL OF EXISTING DECK REPAIR	Overrun - Tota	ıl				\$0.00									
	0320 -	· Total						\$0.00									
	0350	SUPPLEMENTARY WEARING SURFACE	Material		5	Sep 16, 2024	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
		MATERIAL			5	Sep 16, 2024	SYSTEM	(\$7,000.00)									
					6	Oct 1, 2024	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					6	Oct 1, 2024	SYSTEM	(\$7,000.00)									
					7	Oct 16, 2024	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
						7	Oct 16, 2024	SYSTEM	(\$7,000.00)								
								8	Nov 4, 2024	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					8	Nov 4, 2024	SYSTEM	(\$7,000.00)									
											!		9	Nov 18, 2024	SYSTEM	\$16,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Nov 18, 2024	SYSTEM	(\$16,800.00)									
				- Total				\$0.00									
				Material - Tota	ı				\$0.00								
			Overrun	Overrun	Overrun	Overrun	Overrun	5	Sep 16, 2024	SYSTEM	(\$3,500.00)						
						9	Nov 18, 2024	SYSTEM	(\$9,800.00)								
				Overrun - T	otal			(\$13,300.00)									
			Overrun - Tota	al				(\$13,300.00)									
	0350 -	Total						(\$13,300.00)									
	0360	LATEX MODIFIED CONCRETE WEARING SURFACE	Material	Material	Material		5	Sep 16, 2024	SYSTEM	\$106,139.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.						
		SUNI ACE					5	Sep 16, 2024	SYSTEM	(\$106,139.25)							
					6	Oct 1, 2024	SYSTEM	\$106,139.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
					6	Oct 1, 2024	SYSTEM	(\$106,139.25)									
					7	Oct 16, 2024	SYSTEM	\$106,139.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
					7	Oct 16, 2024	SYSTEM	(\$106,139.25)									
					8	Nov 4, 2024	SYSTEM	\$212,278.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.								
					8	Nov 4, 2024	SYSTEM	(\$212,278.50)									
					9	Nov 18, 2024	SYSTEM	\$212,278.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.								
					9	Nov 18, 2024	SYSTEM	(\$212,278.50)									
				- Total													
			Material - Tota	l e				\$0.00									
	0360 -	· Total						\$0.00									



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J5P3467	0470	REMOVAL OF EXISTING DECK	Overrun	Overrun	2	Aug 2, 2024	SYSTEM	(\$5,983.64)						
		REPAIR			3	Aug 16, 2024	SYSTEM	\$5,983.64	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',40.43000 - 40.43000, 'is applied (if non-zero).					
				Overrun - T	otal			\$0.00						
			Overrun - Tota	ıl				\$0.00						
	0470 -	Total						\$0.00						
	0500	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material		5	Sep 16, 2024	SYSTEM	\$28,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					5	Sep 16, 2024	SYSTEM	(\$28,000.00)						
					6	Oct 1, 2024	SYSTEM	\$28,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					6	Oct 1, 2024	SYSTEM	(\$28,000.00)						
					7	Oct 16, 2024	SYSTEM	\$28,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					7	Oct 16, 2024	SYSTEM	(\$28,000.00)						
						2024 Estimate Item Adjustment (0005) due	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.							
					8	Nov 4, 2024	SYSTEM	(\$28,000.00)						
						9	Nov 18, 2024	SYSTEM	\$72,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
					9	Nov 18, 2024	SYSTEM	(\$72,800.00)						
				- Total				\$0.00						
				Material - Tota	ı				\$0.00					
			Overrun		Overrun 5		Sep 16, 2024	SYSTEM	(\$22,400.00)					
					9	Nov 18, 2024	SYSTEM	(\$44,800.00)						
				Overrun - T	otal			(\$67,200.00)						
			Overrun - Tota	ıl				(\$67,200.00)						
	0500 -							(\$67,200.00)						
	0510	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		5	Sep 16, 2024	SYSTEM	\$188,422.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.					
					5	Sep 16, 2024	SYSTEM	(\$188,422.44)						
					6	Oct 1, 2024	SYSTEM	\$188,422.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
					6	Oct 1, 2024	SYSTEM	(\$188,422.44)						
									7	7	Oct 16, 2024	SYSTEM	\$188,422.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Oct 16, 2024	SYSTEM	(\$188,422.44)						
				8	8	Nov 4, 2024	SYSTEM	\$376,844.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
					8	Nov 4, 2024	SYSTEM	(\$376,844.88)						
					9	Nov 18, 2024	SYSTEM	\$376,844.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
					9	Nov 18,	SYSTEM	(\$376,844.88)	·					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3467	0510	LATEX MODIFIED	Material			2024			
		CONCRETE WEARING		- Total				\$0.00	
		SURFACE	Material - Tota	ı				\$0.00	
	0510 -	· Total						\$0.00	
	0550	HALF-SOLE REPAIR	Material		3	Aug 16, 2024	SYSTEM	\$84,850.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Aug 16, 2024	SYSTEM	(\$84,850.35)	
					4	Sep 3, 2024	SYSTEM	\$84,850.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Sep 3, 2024	SYSTEM	(\$84,850.35)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0550 -	Total						\$0.00	
	5002	MISC.	Material		2	Aug 2, 2024	SYSTEM	(\$12,647.10)	
				- Total				(\$12,647.10)	
			Material - Tota					(\$12,647.10)	
			MaterialCredit		3	Aug 16, 2024	SYSTEM	\$12,647.10	
				- Total		2024		\$12,647.10	
			MaterialCredit					\$12,647.10	
			Overrun	Overrun	2	Aug 2,	SYSTEM	(\$2,529.42)	
			Overrain	Overruit		2024			
					3	Aug 16, 2024	SYSTEM	\$2,529.42	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1686.28000 - 1686.28000, 'is applied (if non-zero).
				Overrun - To	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	5002 -	Total						\$0.00	
	5006	WORK ZONE CRASH CUSHION (NARROW)	Overrun	Overrun 9 Nov 18, SYST 2024			SYSTEM	(\$10,700.00)	
		(WARTOW)		Overrun - Total				(\$10,700.00)	
			Overrun - Tota	ıl				(\$10,700.00)	
	5006 -	Total						(\$10,700.00)	
J5P3467 -	Total							(\$132,625.12)	
J5S3464	0750	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		6	Oct 1, 2024	SYSTEM	\$2,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		WAXXING			6	Oct 1, 2024	SYSTEM	(\$2,128.40)	
					7	Oct 16, 2024	SYSTEM	\$2,128.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					7	Oct 16, 2024	SYSTEM	(\$2,128.40)	
				- Total				\$0.00	
			Material - Tota	l e				\$0.00	
	0750 -	Total						\$0.00	
	0760	4 IN. YELLOW WATERBORNE PAVEMENT	Material		6	Oct 1, 2024	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
		MARKING			6	Oct 1, 2024	SYSTEM	(\$2,260.00)	
					7	Oct 16, 2024	SYSTEM	\$2,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					7	Oct 16,	SYSTEM	(\$2,260.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3464	0760	4 IN. YELLOW	Material			2024			
		WATERBORNE PAVEMENT		- Total				\$0.00	
		MARKING	Material - Tota					\$0.00	
	0760 -	Total						\$0.00	
	0770	24 IN. WHITE WATERBORNE PAVEMENT	Material		6	Oct 1, 2024	SYSTEM	\$2,712.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		MARKING			6	Oct 1, 2024	SYSTEM	(\$2,712.48)	
					7	Oct 16, 2024	SYSTEM	\$2,712.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	Oct 16, 2024	SYSTEM	(\$2,712.48)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0770 -	· Total						\$0.00	
	0820	SILT FENCE	Material		6	Oct 1, 2024	SYSTEM	(\$1,122.20)	
					7	Oct 16, 2024	SYSTEM	(\$1,122.20)	
				- Total				(\$2,244.40)	
			Material - Tota	ı				(\$2,244.40)	
			MaterialCredit		7	Oct 16, 2024	SYSTEM	\$1,122.20	
					8	Nov 4, 2024	SYSTEM	\$1,122.20	
				- Total	·Total			\$2,244.40	
			MaterialCredit	- Total				\$2,244.40	
	0820 -	Total						\$0.00	
	0880	MISC. REMOVALS	Material		8	Nov 4, 2024	SYSTEM	(\$9,773.88)	
				- Total				(\$9,773.88)	
			Material - Tota	l				(\$9,773.88)	
			MaterialCredit		9	Nov 18, 2024	SYSTEM	\$9,773.88	
				- Total				\$9,773.88	
			MaterialCredit	- Total				\$9,773.88	
	0880 -	Total						\$0.00	
	0920	MISC. REINFORCING STEEL FOR	Material		7	Oct 16, 2024	SYSTEM	\$5,771.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		CONCRETE			7	Oct 16, 2024	SYSTEM	(\$5,771.16)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0920 -	·Total						\$0.00	
J5S3464 -	Total							\$0.00	
Overall -	Total							(\$132,625.12)	

## MoDOT

### Contract Adjustments for Contract - 240119-D03

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 17 of 17