

Pay Estimate Created Date: November 4, 2024

Progress Estimate N 6	umber	Contract ID Prime Contractor	240419-D03 Concrete Strategi				Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,091,402.40 \$0.00 \$1,091,402.40		
Approval Date								By User		
November 5, 2024			Generated and	Approved	(and should be considere	d Draft) at	the Project Office Level by	gabelj3		
November 5, 2024		Resident Engineer Level by	gabelj3							
November 5, 2024		Controllers Office Level by	ramses1							
Original Completion	n Date	Current Cor	npletion Date	Actu	al Completion Date	%	of Current Contract Amount	ount Complete		
December 1, 20	24	Decemb	er 1, 2024				68.73%			
	Contrac	t Informational Dat	tes		Milestones					
Date Description	Original	Completion Date	Current Complet	tion Date	No Milestones Exist for	Contract				
Acceptance Date										
Awarded Date	May 1, 2	.024	May 1, 2024							
Letting Date	ng Date April 19, 2024 April 19, 2024									
Notice to Proceed Date	June 3, 2	2024	June 3, 2024							
Open to Traffic Date										
Work Began Date										

Contract Total Pa	y For Estimate No. 6				
		This Estimate	Previous	To Date	
240419-D03					
	Total Posted Items Pay	\$184,650.50	\$565,522.87	\$750,173.37	
	Gross Item Adjustments	\$0.00	(\$5,792.90)	(\$5,792.90)	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	-		\$559,729.97	\$744,380.47	
Contract Total Pa	yable This Estimate:	\$184,650.50			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3516	0200	6181000	MOBILIZATION	LS	\$94,800.000	0.25	\$23,700.00
	0270	6099901	MISC.Remove/Reinstall Existing Guardrail	LS	\$8,900.000	1	\$8,900.00
	0280	2161001	TOTAL SURFACE HYDRO DEMOLITION	SQYD	\$39.500	937	\$37,011.50
	0350	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	SQYD	\$112.000	937	\$104,944.00
	0370	7034214	CLASS B-2 CONCRETE	CUYD	\$3,450.000	2.8	\$9,660.00
	0400	7040106	FULL DEPTH REPAIR	SQFT	\$145.000	3	\$435.00
Project J5P35	16 - Total						\$184,650.50
Overall - Total							\$184,650.50

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3516	0330	BRIDGE APPROACH SLAB (MINOR ROAD)	Material			-40	\$375.00	(\$15,000.00)
	0330	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user mcpetw1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	40	\$375.00	\$15,000.00
	0350	LATEX MODIFIED	Material			-1,874	\$112.00	(\$209,888.00)



Pay Estimate Created Date: November 4, 2024

Progre		imate Number 6	Contract ID Prime Contr	240419 actor Concre		, LLC Pay Period End November 1, 2024 Net	ginal Contrac Change Ord rent Contrac	er Amount	\$1,091,402.40 \$0.00 \$1,091,402.40	
Project Number	Line No.	Item Description		Item Description Adjustment Type Other Item Comments Adjustment Type				Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3516		CONCRET	TE WEARING SURFACE							
	0350		EX MODIFIED TE WEARING SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user mcpetw1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	1,874	\$112.00	\$209,888.00	
J5P3524 058	0580	4 IN. WHITE WATERBORNE MARKING PA		Material			-3,602	\$0.70	(\$2,521.40	
	0580	4 IN. WHITE WATERBORNE MARKING PA		Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user mcpetw1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	3,602	\$0.70	\$2,521.40	
	0590	4 IN. YELLOW WATERBORNE MARKING PA		Material			-2,120	\$0.70	(\$1,484.00	
	0590	4 IN. YELLOW WATERBORNE MARKING PA	E PAVEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user mcpetw1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	2,120	\$0.70	\$1,484.00	
	0630		STRUCTURE UNFORMED)	Material			-5	\$850.00	(\$4,250.00	
	0630		STRUCTURE UNFORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user mcpetw1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	5	\$850.00	\$4,250.00	
Total									\$0.00	



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information											
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work							
J5P3516	FAF 47-1(93)	Bridge rehabilitation	47	WASHINGTON	over Mineral Fork, 7.2 miles south of Richwoods							
J5P3524	FAF 8-1(39)	Bridge wearing surface	8	WASHINGTON	over Bates creek, 1.2 miles northwest of Potosi							

Totals by Job Numbers

23516	This Estimate	Previous	To Date
Posted Item Pay	\$184,650.50	\$438,211.32	\$622,861.82
Gross Item Adjustments	\$0.00	(\$5,792.90)	(\$5,792.90)
Gross Item Pay	\$184,650.50	\$432,418.42	\$617,068.92
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
23524	This Estimate	Previous	To Date
Posted Item Pay	\$0.00	\$127,311.55	\$127,311.55
i osted itelli i ay			
Gross Item Adjustments	\$0.00	\$0.00	\$0.00
	\$0.00 \$0.00	\$0.00 \$127,311.55	\$0.00 \$127,311.55
Gross Item Adjustments			
Gross Item Adjustments Gross Item Pay	\$0.00	\$127,311.55	\$127,311.55
Gross Item Adjustments Gross Item Pay Incentive	\$0.00 \$0.00	\$127,311.55 \$0.00	\$127,311.55 \$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptione (Biodrepanolog) This Estimate Forrea			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5P3516, Item 5031011A, Project Item Line Number 0330, Material Set 5031011A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	pending due to material testing	MCPETW1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3516, Item 5031011A, Project Item Line Number 0330, Material Set 5031011A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	pending due to material testing	MCPETW1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3516, Item 5031011A, Project Item Line Number 0330, Material Set 5031011A96, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	pending due to material testing	MCPETW1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3516, Item 5031011A, Project Item Line Number 0330, Material Set 5031011A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	pending due to material testing	MCPETW1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3516, Item 5031011A, Project Item Line Number 0330, Material Set 5031011A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	pending due to material testing	MCPETW1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3516, Item 5052000, Project Item Line Number 0350, Material Set 505200096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	pending due to material testing	MCPETW1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3516, Item 5052000, Project Item Line Number 0350, Material Set 505200096, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	pending due to material testing	MCPETW1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3524, Item 6206000C, Project Item Line Number 0580, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	pending due to material testing	MCPETW1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3524, Item 6206000C, Project Item Line Number 0580, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	pending due to material testing	MCPETW1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3524, Item 6206001C, Project Item Line Number 0590, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	pending due to material testing	MCPETW1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3524, Item 6206001C, Project Item Line Number 0590, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	pending due to material testing	MCPETW1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3524, Item 7040103, Project Item Line Number 0630, Material Set 704010396, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	pending due to material testing	MCPETW1	Overridden
Estimate Exception Type: Item Overrun: Contract 240419-D03, Contract Project J5P3516, Project Item Line Number 0050, Contract Line Item Number 0050, Item 3040143, Minor Item.	pending a change order	MCPETW1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 240419-D03, Contract Project J5P3516, Project Item Line Number 0070, Contract Line Item Number 0070, Item 4013000, Minor Item.	pending a change order	MCPETW1	Acknowledged



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted amo	ount at the	time the	Estimate w	as Gene	erated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
240419-D03	J5P3516	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.50	\$49,000.00	\$24,500.00
		0001	0020	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	9.00	0.00	9.00	100F	0.00	\$1,670.00	\$0.00
		0001	0030	2111000A	SUBGRADE SCARIFYING	9.00	0.00	9.00	100F	0.00	\$480.00	\$0.00
		0001	0040	2153000	SHAPING SLOPES, CLASS III	8.00	0.00	8.00	100F	0.00	\$1,950.00	\$0.00
		0001	0050	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	602.00	0.00	602.00	SQYD	653.20	\$13.00	\$8,491.60
		0001	0060	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	118.70	0.00	118.70	TONS	77.20	\$212.00	\$16,366.40
		0001	0070	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	129.90	0.00	129.90	TONS	154.20	\$211.00	\$32,536.20
		0001	0080	4071005	TACK COAT	110.00	0.00	110.00	GAL	0.00	\$3.20	\$0.00
		0001	0090	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.00
		0001	0100	6122020	REPLACEMENT SAND BARREL	4.00	0.00	4.00	EA	0.00	\$107.00	\$0.00
		0001	0110	6161005	CONSTRUCTION SIGNS	516.00	0.00	516.00	SQFT	238.00	\$5.50	\$1,309.00
		0001	0120	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	2.00	\$21.50	\$43.00
		0001	0130	6161010	RELOCATED SIGNS	381.00	0.00	381.00	SQFT	0.00	\$4.30	\$0.00
		0001	0140	6161025	CHANNELIZER (TRIM LINE)	30.00	0.00	30.00	EA	30.00	\$16.00	\$480.00
		0001	0150	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,150.00	\$4,300.00
		0001	0160	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$10,300.00	\$10,300.00
		0001	0170	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	0.00	\$645.00	\$0.00
		0001	0180	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,170.00	0.00	1,170.00	LF	1,170.00	\$18.25	\$21,352.50
		0001	0190	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	1,170.00	0.00	1,170.00	LF	1,170.00	\$8.60	\$10,062.00
		0001	0200	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$94,800.00	\$71,100.00
		0001	0210	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	24.00	0.00	24.00	LF	24.00	\$12.90	\$309.60
		0001	0220	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,982.00	0.00	1,982.00	LF	0.00	\$1.07	\$0.00
		0001	0230	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	930.00	0.00	930.00	LF	0.00	\$1.07	\$0.00
		0001	0240	6207001	PAVEMENT MARKING REMOVAL	2,199.00	0.00	2,199.00	LF	1,450.00	\$0.80	\$1,160.00
		0001	0250	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	7,484.00	0.00	7,484.00	LF	6,468.00	\$1.99	\$12,871.32
		0001	0260	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	495.00	0.00	495.00	SQYD	0.00	\$30.00	\$0.00
		0010	0270	6099901	MISC.Remove/Reinstall Existing Guardrail	1.00	0.00	1.00	LS	1.00	\$8,900.00	\$8,900.00
		0070	0280	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,874.00	0.00	1,874.00	SQYD	1,874.00	\$39.50	\$74,023.00
		0070	0290	2161500	REMOVAL OF SEAL COAT OR POLYMER WEARING SURFACE	16,866.00	0.00	16,866.00	SQFT	16,866.00	\$2.20	\$37,105.20
		0070	0300	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	0.00	100.00	SQFT	0.00	\$38.00	\$0.00
		0070	0310	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	43.00	0.00	43.00	LF	43.00	\$505.00	\$21,715.00
		0070	0320	2169903	MISC.Remove and Replace Existing Safety Barrier Curb	8.00	0.00	8.00	LF	4.00	\$1,560.00	\$6,240.00
		0070	0330	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	187.00	0.00	187.00	SQYD	40.00	\$375.00	\$15,000.00
		0070	0340	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	15.00	0.00	15.00	CY	0.00	\$700.00	\$0.00
		0070	0350	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,874.00	0.00	1,874.00	SQYD	1,874.00	\$112.00	\$209,888.00
		0070	0360	7031004	DIAMOND GRINDING	1,874.00	0.00	1,874.00	SQYD	0.00	\$16.00	\$0.00
		0070	0370	7034214	CLASS B-2 CONCRETE	5.60	0.00	5.60	CUYD	5.60	\$3,450.00	\$19,320.00
		0070	0380	7040101	SUBSTRUCTURE REPAIR (FORMED)	50.00	0.00	50.00	SQFT	0.00	\$456.00	\$0.00
		0070	0390	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	10.00	0.00	10.00	SQFT	0.00	\$422.00	\$0.00
		0070	0400	7040106	FULL DEPTH REPAIR	300.00	0.00	300.00	SQFT	3.00	\$145.00	\$435.00
		0070	0410	7101000	REINFORCING STEEL (EPOXY COATED)	750.00	0.00	750.00	LB	0.00	\$5.75	\$0.00
		0070	0420	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$5,500.00	\$0.00
		0070	0430	7125102	(EPOXY) SURFACE PREPARATION FOR APPLYING EPOXY-MASTIC	1.00	0.00	1.00	LS	0.00	\$3,700.00	\$0.00
					PRIMER							



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
240419-D03	J5P3516	0070	0440	7125960	ALUMINUM EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	0.00	\$3,700.00	\$0.00
		0070	0450	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	43.00	0.00	43.00	LF	21.00	\$574.00	\$12,054.00
	Project J	5P3516 - To	otal Value	Posted to D	ate as of Report Generated Date							\$622,861.82
	J5P3524	0001	0460	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.00
		0001	0470	6122020	REPLACEMENT SAND BARREL	4.00	0.00	4.00	EA	2.00	\$107.00	\$214.00
		0001	0480	6161005	CONSTRUCTION SIGNS	276.00	0.00	276.00	SQFT	266.00	\$5.50	\$1,463.00
		0001	0490	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	2.00	\$21.50	\$43.00
		0001	0500	6161010	RELOCATED SIGNS	48.00	0.00	48.00	SQFT	0.00	\$4.30	\$0.00
		0001	0510	6161025	CHANNELIZER (TRIM LINE)	30.00	0.00	30.00	EA	30.00	\$16.00	\$480.00
		0001	0520	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,150.00	\$4,300.00
		0001	0530	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$5,150.00	\$5,150.00
		0001	0540	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	430.00	0.00	430.00	LF	430.00	\$18.25	\$7,847.50
		0001	0550	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	430.00	0.00	430.00	LF	430.00	\$8.60	\$3,698.00
		0001	0560	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$29,950.00	\$14,975.00
		0001	0570	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	24.00	0.00	24.00	LF	24.00	\$12.90	\$309.60
		0001	0580	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	3,602.00	0.00	3,602.00	LF	3,602.00	\$0.70	\$2,521.40
		0001	0590	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	2,120.00	0.00	2,120.00	LF	2,120.00	\$0.70	\$1,484.00
		0001	0600	6207001	PAVEMENT MARKING REMOVAL	5,472.00	0.00	5,472.00	LF	3,852.00	\$0.70	\$2,696.40
		0001	0610	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	7,600.00	0.00	7,600.00	LF	4,685.00	\$1.99	\$9,323.15
		0070	0620	6233000	EPOXY POLYMER WEARING SURFACE	863.00	0.00	863.00	SQYD	863.00	\$57.50	\$49,622.50
		0070	0630	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	5.00	0.00	5.00	SQFT	5.00	\$850.00	\$4,250.00
		0070	0640	7040110	EPOXY PRESSURE INJECTING	107.00	0.00	107.00	LF	107.00	\$86.00	\$9,202.00
		0070	0650	7172054	OPEN CELL FOAM JOINT SEAL	99.00	0.00	99.00	LF	99.00	\$68.00	\$6,732.00
	Project J	5P3524 - To	tal Value	Posted to D	ate as of Report Generated Date							\$127,311.55
40419-D03 Ove	erall - Total	Value Pos	ted to Da	te as of Repo	ort Generated Date							\$750,173.37



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Descri	ption	DWR Date	DWR Approval Date	Quantit Posted	/ Units		Locatio	n		From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance		Comments	
0200	6181000 N	MOBILIZATION		11/1/24	11/4/24	0.2	5 LS	phase 2 lt. side										
		MISC. PAVED DRAINAGE		10/16/24		1.00		all 4 corners of										
		TOTAL SURFACE HYDRO D		10/24/24														
0350		LATEX MODIFIED CONCRET	LE WEARING SURFACE		1/1/24 11/4/24 937.00 SQYD phase 2 lt. side /22/24 11/4/24 2.80 CUYD expansion joint													
		FULL DEPTH REPAIR		10/22/24		3.00		phase 2 lt. side 1' x 3' = 3 sq. ft	next to the new (0' lt. of cl.							
		low this line are detail																
Project 5P3516	Line Num	ber DWR Date September 6, 2024	Total Quantity Posted F 238	For DWR Da			ign Inform	ation 00 WORK	Station 488+10		47 rt.	Number		SF Each	Sign S	Special Sign	SF Each Special Sign	Total SF to Pos
01 00 10	0110	00010010010,2021	200		ZO	NE NO PH	IONE ZON	1E										
						NST-8 4 NE NO PH		00 WORK IE	565+40	rte.	47 lt.	1.00		12.00				12.
						20-2 48 DRK	x24 8.00	END ROAD	513+10	rte.	47 lt.	1.00	4	8.00				8
					CO WC	NST-7 4 ORK ZONE	8x24 8.0	00 RATE OUR	493+13	rte.	47 rt.	1.00	4	8.00				8.
					R1 ON	0-6 24x RED (45	36 6.00 DEGREE	STOP HERE ARROW	540+34	rte.	47 lt.	1.00	0	6.00				6.
						0-6 24x RED (45		STOP HERE ARROW	513+20	rte.	47 rt.	1.00	6	6.00				6.
						NST-5 9 ESENCE	6x48 32.	00 POINT OF	538+20	rte.	47 lt.	1.00	4	32.00				32.
					CO PR	NST-5 9 ESENCE	6x48 32.	00 POINT OF	515+38 rt.	rte.	47 rt.	1.00	:	32.00				32.
					CO WC	NST-7 7 ORK ZONE	2x36 18.	00 RATE OUR	560+40	rte.	47 lt.	1.00		18.00				18.
					WC RO	020-1 48 AD/BRIDO	8x48 16.0 SE/RAMP	0 WORK AHEAD	555+04	rte.	47 lt.	1.00		16.00				16.
					WC AH	03-3 48 EAD (SYN	x48 16.0 1BOL)) SIGNAL	545+34	rte.	47 lt.	1.00		16.00				16.
					WC CU	01-4R 4 RVE (SYN	8x48 16.0 1BOL RIG	00 REVERSE HT ARROW)	524+00	rte.	47 cl	1.00		16.00				16.
					AH	EAD (SYN	1BOL)	0 SIGNAL	505+13	rte.	47 rt.	1.00		16.00				16.
					RO	AD AHEA	D	0 ONE LANE	503+15			1.00		16.00				16
					RO		SE/RAMP	WORK AHEAD	498+15			1.00		16.00				16.
	A440 T 4					20-2 48 DRK	x24 8.00	END ROAD	540+34	rte.	. 47 rt.	1.00	4	8.00				8.
5P3524	0110 - Tota 0480	August 16, 2024	266		GO	20-2 48 DRK	x24 8.00	END ROAD	938+04.53	rte.	8 rt.	1.00	ł	8.00				8
					GO		x24 8.00	END ROAD	898+53.32	rte.	8 lt.	1.00	4	8.00				8
					R1		36 6.00 DEGREE	STOP HERE	928+04.53	rte.	8 lt.	1.00		6.00				6
					R1		36 6.00	STOP HERE	908+53.32	rte.	8 rt.	1.00		6.00				6
					CO PR	NST-5 9 ESENCE	6x48 32.	00 POINT OF	925+99.25	rte.	8 lt.	1.00	:	32.00				32
					CO PR	NST-5 9 ESENCE	6x48 32.	00 POINT OF	910+58.32	rte.	8 rt.	1.00	:	32.00				32
						NST-7 7 ORK ZONE		00 RATE OUR	888+53.32	rte.	8 rt.	1.00		18.00				18
					WC RO	020-1 48 AD/BRIDO	3x48 16.0 SE/RAMP	0 WORK AHEAD	943+04.53	rte.	8 lt.	1.00		16.00				16
					WC RO	20-4 48 AD AHEA	3x48 16.0 D	0 ONE LANE	938+04.53	rte.	8 lt.	1.00		16.00				16
)3-3 48 EAD (SYN		0 SIGNAL	933+04.53	rte.	8 lt.	1.00		16.00				16.
					WC CU	01-4R 4 RVE (SYN	8x48 16.0 1BOL RIG	00 REVERSE HT ARROW)	916+26.32	rte.	8 cl	1.00		16.00				16
					WC AH	03-3 48 EAD (SYN	x48 16.0 IBOL)) SIGNAL	903+53.32	rte.	8 rt.	1.00		16.00				16
									898+53.32	rte.	8 rt.	1.00		16.00				16.
					WC RO	020-4 48 AD AHEA	8x48 16.0 D	0 ONE LANE										
					RO WC RO	AD AHEA 020-1 48 AD/BRIDO	D 3x48 16.0 GE/RAMP	0 WORK AHEAD	893+53.32			1.00		16.00				
					RO WC RO ZO	AD AHEA 20-1 48 AD/BRIDO NST-8 4 NE NO PH	D 8x48 16.0 GE/RAMP 8x36 12. IONE ZOM	0 WORK AHEAD 00 WORK IE	893+53.32 953+04.53	rte.	8 lt.	1.00		12.00				12
					RO RO CO ZO PR	AD AHEA 020-1 48 AD/BRIDO NST-8 4 NE NO PH NST-5 3 ESENCE	D 8x48 16.0 GE/RAMP 8x36 12. IONE ZON 6x48 12.	0 WORK AHEAD 00 WORK IE 00 POINT OF	893+53.32 953+04.53 910+58.32	rte.	8 lt.	1.00		12.00				16. 12. 12.
					RO RO CO ZO PR CO WC	AD AHEA 020-1 48 AD/BRIDO NST-8 4 NE NO PH NST-5 3 ESENCE NST-7 4 ORK ZONE	D 8x48 16.0 GE/RAMP 8x36 12. IONE ZON 6x48 12. 8x24 8.0	0 WORK AHEAD 00 WORK IE	893+53.32 953+04.53	rte.	.8 lt.	1.00		12.00				12



Nov 6, 2024

Contract ID: 240419-D03

Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type		Date	Ву	(*****	
J5P3516	0050	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Overrun	Overrun		Sep 16, 2024	SYSTEM	(\$665.60)	
		· · · · ·		Overrun - T	otal			(\$665.60)	
			Overrun - T	otal				(\$665.60)	
	0050 -	Total						(\$665.60)	
	0070	BITUMINOUS PAVEMENT MIXTURE PG64-22	Overrun	Overrun		Sep 16, 2024	SYSTEM	(\$5,127.30)	
		(BAS		Overrun - T	otal			(\$5,127.30)	
			Overrun - T	otal				(\$5,127.30)	
	0070 -	Total						(\$5,127.30)	
	0180	TEMPORARY TRAFFIC BARRIER, CONT. FURN/RE	Material		3	Sep 16, 2024	SYSTEM	\$21,352.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mcpetw1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Sep 16, 2024	SYSTEM	(\$21,352.50)	
					4	Oct 2, 2024	SYSTEM	\$21,352.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcpetw1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Oct 2, 2024	SYSTEM	(\$21,352.50)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0180 -	Total						\$0.00	
	0330	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		5	Oct 16, 2024	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcpetw1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Oct 16, 2024	SYSTEM	(\$15,000.00)	
					6	Nov 4, 2024	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcpetw1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Nov 4, 2024	SYSTEM	(\$15,000.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0330 -	Total						\$0.00	
	0350	LATEX MODIFIED CONCRETE WEARING	Material		5	Oct 16, 2024	SYSTEM	\$104,944.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mcpetw1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		SURFACE			5	Oct 16, 2024	SYSTEM	(\$104,944.00)	
					6	Nov 4, 2024	SYSTEM	\$209,888.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mcpetw1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Nov 4, 2024	SYSTEM	(\$209,888.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0350 -	Total						\$0.00	
J5P3516									
		01101					0)/0777	(\$5,792.90)	
J5P3524	0510	CHANNELIZER (TRIM LINE)	Material		1	Aug 16, 2024	SYSTEM	\$480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcpetv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Aug 16, 2024	SYSTEM	(\$480.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	05 <u>10</u> -	Total						\$0.00	
	0520	CMS W/O COMMUNICATION INTERFACE, CONT	Material		1	Aug 16, 2024	SYSTEM	\$4,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mcpetw1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		INTERFACE, CONT F/			1	Aug 16,	SYSTEM	(\$4,300.00)	•



Contract ID: 240419-D03

System System<	Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
COMMUNCTION Total Formula 9900 630 - Total 9900 9900 1000000000000000000000000000000000000	J5P3524							-		
Number of participant Yaturd 1 Toda Yaturd 2 Toda Yaturd 2 Toda SISS 1 Acad FindPOARD Marcel 1 Toda Participant Siss 1 Toda		0520	COMMUNICATION	Material			2024			
OSD- Total U U U 0580 TEAPPORT Address of the control operation operating hep-opreaned definition operation operatent definition operaten				Mada Male T						
560 0 000 TOURNEE CONT. FURNEE NUMERIA TOURNEE NUMERIA STATES Material 2 28.0.3 20.0.4 5YSTEM 77.87.50 The adjustment control from the c		0520	Tetal	Material - I	otal					
Image: state in the s										
Normal Part Part Part Part Part Part Part Part		0540	TRAFFIC BARRIER,	Material						Estimate Item Adjustment (0001) due to user mcpetw1 overridding Payment
						2		SYSTEM	(\$7,847.50)	
Image: state in the s						3		SYSTEM	\$7,847.50	Estimate Item Adjustment (0004) due to user mcpetw1 overridding Payment
Image: Part of the second se						3		SYSTEM	(\$7,847.50)	
4 Ord 2 SYSTEM (37,847.50) Material - Total 50.00 Material - Total 50.00 OSS0 - Total Solution of the control by the magnetic difference of the original system generated Material Payment Elemate Exception 2 on the current Payment Elemate Exception 3 on the current Payment Elemate. 6000 VMATERIONE VMATERIONE <td< td=""><td></td><td></td><td></td><td></td><td></td><td>4</td><td></td><td>SYSTEM</td><td>\$7,847.50</td><td>Estimate Item Adjustment (0002) due to user mcpetw1 overridding Payment</td></td<>						4		SYSTEM	\$7,847.50	Estimate Item Adjustment (0002) due to user mcpetw1 overridding Payment
OS00 Total S0.00 OS00 S0.00 OS00 S0.00 OS00 S0.00 OS00 S0.00 OS00 S0.00 OS00 S0.00 VM Parally S0.00 PAVEMENT S0.00 VM Parally S0.00 S0.00 S0.00						4		SYSTEM	(\$7,847.50)	
OSE Total Standard Sta					- Total		2027		\$0.00	
OS40 - Total U 40.00 0580 WATERBORNE PARTNERSONE PAR				Material - T						
OSB0 N. Matrix VVL TERSONNET Material WVL TERSONNET Material Subscription Sep 1, 22, 224, 322, 32, 575TEM S2,221,40 This adjustment officits the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate 3 Sep 16, 3 Sep 16,		0540 -	Total	Material - 1						
1 2 Sep 3, SYSTEM (82.521.40) 3 Sop 1, SYSTEM S2.221.40 This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate. 3 Sop 1, SYSTEM S2.221.40 This adjustment offsets the original system-generated Material Payment Estimate. 3 Sop 1, SYSTEM S2.521.40 This adjustment offsets the original system-generated Material Payment Estimate. 4 Oct 2, SYSTEM S2.521.40 This adjustment offsets the original system-generated Material Payment Estimate. 4 Oct 2, SYSTEM S2.521.40 This adjustment offsets the original system-generated Material Payment Estimate. 5 Oct 16, SYSTEM S2.521.40 This adjustment offsets the original system-generated Material Payment Estimate. 6 Nov 4, SYSTEM S2.521.40 This adjustment offsets the original system-generated Material Payment Estimate. 6 Nov 4, SYSTEM S2.521.40 This adjustment offsets the original system-generated Material Payment Estimate. 6 Nov 4, SYSTEM S2.521.40 This adjustment offsets the original system-generated Material Payment Estimate. 6 Nov 4, SYSTEM S2.521.40 This adjustment offsets the original s			4 IN. WHITE WATERBORNE PAVEMENT	Material		2		SYSTEM		Estimate Item Adjustment (0002) due to user mcpetw1 overridding Payment
Image: Series of the						2		SYSTEM	(\$2,521.40)	
View View View View View 4 Oct 2, 2024 SYSTEM \$2,521.40 This adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0003) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0006) due to user mcpetive (vernidding Payment Estimate litem Adjustment (0006) due to user mcpetive (vernidding Payment E						3		SYSTEM	\$2,521.40	Estimate Item Adjustment (0005) due to user mcpetw1 overridding Payment
1 0 2024 2024 Estimate Item Adjustment (0003) due to user mopeivri overridding Payment Estimate. 4 0 2024 SYSTEM (\$2,221.40) 5 0 0 10 SYSTEM S2.521.40 6 Nov 4, SYSTEM (\$2,221.40) Material - Total Store Work 10003 due to user mopeivel overridding Payment Estimate Item Adjustment (0003) due to user mopeivri overridding Payment Estimate Item Adjustment (0003) due to user mopeivri overridding Payment Estimate Item Adjustment (0003) due to user mopeivri overridding Payment Estimate Item Adjustment (0003) due to user mopeivri overridding Payment Estimate Item Adjustment (0003) due to user mopeivri overridding Payment Estimate Item Adjustment (0003) due to user mopeivri overridding Payment Estimate Item Adjustment (0003) due to user mopeivri overridding Payment Estimate Item Adjustment (0003) due to user mopeivri overridding Payment Estimate Item Adjustment (0003) due to user mopeivri overridding Payment Estimate Item Adjustment (0003) due to user mopeivri overridding Payment Estimate Item Adjustment (0003) due to user mopeivri overridding Payment Estimate Item Adjustment (0003) due to user mopeivri overridding Payment Estimate Item Adjustment (0003) due to user mopeiv						3		SYSTEM	(\$2,521.40)	
6 0c1 6; SYSTEM \$2,521.40 This adjustment offsets the original system-generated Material Payment 5 0c1 6; SYSTEM \$2,521.40 This adjustment offsets the original system-generated Material Payment 6 Nov 4; SYSTEM \$2,521.40 This adjustment offsets the original system-generated Material Payment 6 Nov 4; SYSTEM \$2,521.40 This adjustment offsets the original system-generated Material Payment 6 Nov 4; SYSTEM \$2,521.40 This adjustment offsets the original system-generated Material Payment 6 Nov 4; SYSTEM \$2,521.40 This adjustment offsets the original system-generated Material Payment 6 Nov 4; SYSTEM \$2,521.40 This adjustment offsets the original system-generated Material Payment Material Store Store Offset Store Store Store Offset Material Store Store Offset Store Store Store Offset Store Store						4		SYSTEM	\$2,521.40	Estimate Item Adjustment (0003) due to user mcpetw1 overridding Payment
0 0 <td></td> <td></td> <td>4</td> <td></td> <td>SYSTEM</td> <td>(\$2,521.40)</td> <td></td>						4		SYSTEM	(\$2,521.40)	
0590 4 IN. YELLOW WATERBORNE PAVENERNIG Material 2 Sep 3, Sep 6, Sep 6, SYSTEM SYSTEM S1.484.00 0 Nov 4, 2024 SYSTEM S2.521.40 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 0 Nov 4, 2024 SYSTEM S2.521.40 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 0580 - Total 0590 4 IN. YELLOW WATERBORNE PAVEMENT Material 2 Sep 3, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 0590 4 IN. YELLOW WATERBORNE PAVEMENT Material Sep 3, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 0 Sep 16, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. 1 Sep 16, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. 2 Sep 16, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. <t< td=""><td></td><td></td><td>5</td><td></td><td>SYSTEM</td><td>\$2,521.40</td><td>Estimate Item Adjustment (0003) due to user mcpetw1 overridding Payment</td></t<>						5		SYSTEM	\$2,521.40	Estimate Item Adjustment (0003) due to user mcpetw1 overridding Payment
OS80 - Total OS80 - Total OS80 - Total Sum and the second						5		SYSTEM	(\$2,521.40)	
Image: Constraint of the second se						6		SYSTEM	\$2,521.40	Estimate Item Adjustment (0003) due to user mcpetw1 overridding Payment
Image: Free Partial Free Part Part Part Part Part Part Part Part						6		SYSTEM	(\$2,521.40)	
Material - Total \$0.00 0580 - Total \$0.00 0590 4 IN. YELLOW WATERBORNE PAVEMENT MARKING Material 2 Sep 3, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mcpetw1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 2 Sep 3, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 3 Sep 16, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mcpetw1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 3 Sep 16, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. 4 Oct 2, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcpetw1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					- Tot <u>al</u>				<u>\$0.00</u>	
0580 - Total \$0.00 0590 4 IN. YELLOW WATERBORNE PAVEMENT MARKING Material 2 Sep 3, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 2 Sep 3, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 3 Sep 16, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mopetw1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 3 Sep 16, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. 3 Sep 16, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. 4 Oct 2, 2024 SYSTEM \$1,484.00 This adjustment (0004) due to user mopetw1 overridding Payment Estimate Exception 5 on the current Payment Estimate.				Material - T						
0590 4 IN. YELLOW WATERBORNE PAVEMENT MARKING Material 2 Sep 3, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 2 Sep 3, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 3 Sep 16, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mcpetw1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 3 Sep 16, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. 4 Oct 2, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.		0 <u>580</u> -	Total							
2 Sep 3, 2024 SYSTEM (\$1,484.00) 3 Sep 16, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mcpetw1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 3 Sep 16, 2024 SYSTEM (\$1,484.00) 4 Oct 2, 2024 SYSTEM \$1,484.00 4 Oct 2, SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcpetw1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 4 Oct 2, SYSTEM \$1,484.00			WATERBORNE PAVEMENT	Material		2		SYSTEM		Estimate Item Adjustment (0003) due to user mcpetw1 overridding Payment
3 Sep 16, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mopetw1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 3 Sep 16, 2024 SYSTEM (\$1,484.00) 4 Oct 2, 2024 SYSTEM \$1,484.00 4 Oct 2, SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate. 4 Oct 2, SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate. 4 Oct 2, SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate.						2		SYSTEM	(\$1,484.00)	
2024 2024 Cot 2, 2024 SYSTEM \$1,484.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcpetw1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 4 Oct 2, SYSTEM \$1,484.00 C(1,484.00)						3		SYSTEM	\$1,484.00	Estimate Item Adjustment (0006) due to user mcpetw1 overridding Payment
2024 Estimate Item Adjustment (0004) due to user mcpetw1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 4 Oct 2, SYSTEM (\$1,484.00)						3		SYSTEM	(\$1,484.00)	
						4		SYSTEM	\$1,484.00	Estimate Item Adjustment (0004) due to user mcpetw1 overridding Payment
						4		SYSTEM	(\$1,484.00)	

9



Contract ID: 240419-D03

ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
24	0590	4 IN. YELLOW WATERBORNE PAVEMENT	Material		5	Oct 16, 2024	SYSTEM	\$1,484.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcpetw1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		MARKING			5	Oct 16, 2024	SYSTEM	(\$1,484.00)	
					6	Nov 4, 2024	SYSTEM	\$1,484.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcpetw1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					6	Nov 4, 2024	SYSTEM	(\$1,484.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0590 -	Total						\$0.00	
	0620	EPOXY POLYMER WEARING SURFACE	Material		2	Sep 3, 2024	SYSTEM	\$24,782.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcpetw1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					2	Sep 3, 2024	SYSTEM	(\$24,782.50)	
					3	Sep 16, 2024	SYSTEM	\$49,622.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mcpetw1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	Sep 16, 2024	SYSTEM	(\$49,622.50)	
				- Total				\$0.00	
			Material - To	Total				\$0.00	
	0620 -	Total						\$0.00	
ĺ	0630	SUPERSTRUCTURE REPAIR (UNFORMED)	Material		1	Aug 16, 2024	SYSTEM	\$4,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mcpetw1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Aug 16, 2024	SYSTEM	(\$4,250.00)	
					2	Sep 3, 2024	SYSTEM	\$4,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mcpetw1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					2	Sep 3, 2024	SYSTEM	(\$4,250.00)	
					3	Sep 16, 2024	SYSTEM	\$4,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mcpetw1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					3	Sep 16, 2024	SYSTEM	(\$4,250.00)	
					4	Oct 2, 2024	SYSTEM	\$4,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mcpetw1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Oct 2, 2024	SYSTEM	(\$4,250.00)	
					5	Oct 16, 2024	SYSTEM	\$4,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mcpetw1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					5	Oct 16, 2024	SYSTEM	(\$4,250.00)	
					6	Nov 4, 2024	SYSTEM	\$4,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mcpetw1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	Nov 4, 2024	SYSTEM	(\$4,250.00)	
				- Total				\$0.00	
			Material - To	Material - Total				\$0.00	
	0630 -	Total						\$0.00	
	0640	EPOXY PRESSURE INJECTING	Material		2	Sep 3, 2024	SYSTEM	\$9,202.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mcpetw1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					2	Sep 3,	SYSTEM	(\$9,202.00)	
						2024			



Contract ID: 240419-D03

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3524	0640	EPOXY PRESSURE INJECTING	Material			2024			Estimate Item Adjustment (0009) due to user mcpetw1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					3	Sep 16, 2024	SYSTEM	(\$9,202.00)	
					4	Oct 2, 2024	SYSTEM	\$9,202.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mcpetw1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Oct 2, 2024	SYSTEM	(\$9,202.00)	
				- Total				\$0.00	
			Material - To	Material - Total					
	0640 -	Total						\$0.00	
	0650	OPEN CELL FOAM JOINT SEAL	Material		2	Sep 3, 2024	SYSTEM	\$6,732.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mcpetw1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					2	Sep 3, 2024	SYSTEM	(\$6,732.00)	
					3	Sep 16, 2024	SYSTEM	\$6,732.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user mcpetw1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					3	Sep 16, 2024	SYSTEM	(\$6,732.00)	
					4	Oct 2, 2024	SYSTEM	\$6,732.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mcpetw1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					4	Oct 2, 2024	SYSTEM	(\$6,732.00)	
					5	Oct 16, 2024	SYSTEM	\$6,732.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mcpetw1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					5	Oct 16, 2024	SYSTEM	(\$6,732.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0650 -	Total						\$0.00	
J5P3524 ·	- Total							\$0.00	
Overall -	Total						(\$5,792.90)		



There are no contract adjustments to display for this contract.