

Pay Estimate Created Date: December 16, 2024

Progress Estimate Number	Contract ID	240419-F02	Pay Period Start	December 2, 2024	Original Contract Amount	\$6,946,514.45
12	Prime Contractor	Gershenson Construction Co., Inc.	Pay Period End	December 15, 2024	Net Change Order Amount Current Contract Amount	\$48,569.21 \$6,995,083.66

Approval Date		By User
December 16, 2024	Generated and Approved (and should be considered Draft) at the Project Office Level by	fullek2
December 17, 2024	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	BAUERD1
December 17, 2024	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
October 1, 2025	October 1, 2025		34.84%

	Contract Informational Date	tes	Milestones
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	May 1, 2024	May 1, 2024	
Letting Date	April 19, 2024	April 19, 2024	
Notice to Proceed Date	June 3, 2024	June 3, 2024	
Open to Traffic Date			
Work Began Date			

Contract Total Pa	y For Estimate No. 12			
		This Estimate	Previous	To Date
240419-F02				
	Total Posted Items Pay	\$137,254.43	\$2,300,164.76	\$2,437,419.19
	Gross Item Adjustments	\$0.00	\$27,356.68	\$27,356.68
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$2,327,521.44	\$2,464,775.87
Contract Total Pa	yable This Estimate:	\$137,254.43		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3417	0010	2013000	CLEARING AND GRUBBING	ACRE	\$10,000.000	1	\$10,000.00
	0020	2022010	REMOVAL OF IMPROVEMENTS	LS	\$600,000.000	0.05	\$30,000.00
	0800	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$13.000	470.3	\$6,113.90
	0170	6039902	WATER	EA	\$100.000	3	\$300.00
	0240	6081012	TRUNCATED DOMES	SQFT	\$28.000	10	\$280.00
	0260	6083006	6 IN. CONCRETE MEDIAN STRIP	SQYD	\$118.000	6.3	\$743.40
	0270	6085008	PAVED APPROACH, 8 IN.	SQYD	\$102.000	295.1	\$30,100.20
	0280	6086004	CONCRETE SIDEWALK, 4 IN.	SQYD	\$51.000	164.6	\$8,394.60
	0300	6089902	MISC.ADA CURB RAMP	EA	\$2,400.000	12	\$28,800.00
	0320	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	LF	\$41.000	352	\$14,432.00
	0350	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	LF	\$26.000	10	\$260.00
	0400	6116010A	SLOPE PROTECTION	SQYD	\$103.000	10	\$1,030.00
	0860	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$31,100.000	0.05	\$1,555.00
	1700	9109902	MISC.ADJUST TO GRADE MODOT PULL BOX	EA	\$953.960	2	\$1,907.92
	5003	9109902	MISC.REMOVE AND REPLACE ITS PULL BOX, PREFORMED CLASS 2	EA	\$3,337.410	1	\$3,337.41
Project J6S3	417 - Total						\$137,254.43

Revision 3/23/2023 Page 1 of 30



Pay Estimate Created Date: December 16, 2024

Progress Estimate Pay Period December 2, 2024 Original Contract Amount \$6,946,514.45 **Contract ID** 240419-F02 Start Number Pay Period End December 15, 2024 Prime Gershenson Construction Co., Net Change Order \$48,569.21 12 Contractor Amount Current Contract Amount \$6,995,083.66

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
Overall - Tot	al						\$137,254.43

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project lumber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
6S3417	0130	MISC.	Material			-1,809	\$78.00	(\$141,102.00)
	0130	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1,809	\$78.00	\$141,102.00
	0230	CONCRETE MEDIAN	Material			-536.1	\$57.00	(\$30,557.70)
	0230	CONCRETE MEDIAN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	536.1	\$57.00	\$30,557.70
	0240	TRUNCATED DOMES	Material			-162	\$28.00	(\$4,536.00)
	0240	TRUNCATED DOMES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.	162	\$28.00	\$4,536.00
	0270	PAVED APPROACH, 8 IN.	Material			-3,189.3	\$102.00	(\$325,308.60)
	0270	PAVED APPROACH, 8 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 5 on the current Payment Estimate.	3,189.3	\$102.00	\$325,308.60
	0300	MISC.	Material			-103	\$2,400.00	(\$247,200.00)
	0300	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 8 on the current Payment Estimate.	103	\$2,400.00	\$247,200.00
	0400	SLOPE PROTECTION	Material			-15	\$103.00	(\$1,545.00)
	0400	SLOPE PROTECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 9 on the current Payment Estimate.	15	\$103.00	\$1,545.00
	0480	MANHOLE FRAME AND COVER, TYPE 1-B	Material			-2	\$588.00	(\$1,176.00)
	0480	MANHOLE FRAME AND COVER, TYPE 1-B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 10 on the current Payment Estimate.	2	\$588.00	\$1,176.00
	0990	TURF TYPE TALL FESCUE SODDING	Material			-3,315	\$12.00	(\$39,780.00)
	0990	TURF TYPE TALL FESCUE SODDING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user fullerk2 overridding Payment Estimate Exception 11	3,315	\$12.00	\$39,780.00

Revision 3/23/2023 Page 2 of 30



Pay Estimate Created Date: December 16, 2024

Progress Estimate Number
12 Contract ID 240419-F02 Pay Period Start December 2, 2024 Original Contract Amount \$6,946,514.45
Prime Contractor Inc. Pay Period End December 15, 2024 Original Contract Amount \$6,946,514.45
Pay Period End December 15, 2024 Met Change Order Amount \$6,995,083.66

	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
7					on the current Payment Estimate.			
	1030	ALTERNATE DITCH CHECK	Material			-144	\$10.00	(\$1,440.00
	1030	ALTERNATE DITCH CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user fullerk2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	144	\$10.00	\$1,440.00
	1040	CURB INLET CHECK	Material			-16	\$10.00	(\$160.00
	1040	CURB INLET CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment Estimate.	16	\$10.00	\$160.00
	1170	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material			-180	\$1.07	(\$192.60
	1170	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user fullerk2 overridding Payment Estimate Exception 14 on the current Payment Estimate.	180	\$1.07	\$192.60
	1180	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	Material			-517	\$3.48	(\$1,799.16
	1180	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment Estimate Exception 15 on the current Payment Estimate.	517	\$3.48	\$1,799.16
	1590	2 IN. PSST POST - 12 GA.	Material			-188	\$27.81	(\$5,228.28
	1590	2 IN. PSST POST - 12 GA.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment Estimate.	188	\$27.81	\$5,228.28
·	1600	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	Material			-9	\$267.37	(\$2,406.33
•	1600	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate.	9	\$267.37	\$2,406.33
	1620	CONCRETE POST ANCHOR FOR 2 IN. PSST 7 GA.	Material			-11	\$641.68	(\$7,058.48
	1620	CONCRETE POST ANCHOR FOR 2 IN. PSST 7 GA.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate.	11	\$641.68	\$7,058.48
	1630	2.5 IN. PSST POST - 12 GA.	Material			-60.75	\$29.94	(\$1,818.86
	1630	2.5 IN. PSST POST - 12 GA.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate.	60.75	\$29.94	\$1,818.86
	1640	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	Material			-4	\$320.84	(\$1,283.36)

Revision 3/23/2023 Page 3 of 30



Pay Estimate Created Date: December 16, 2024

Progress Estimate Number	Contract ID	240419-F02	Pay Period Start	December 2, 2024	Original Contract Amount	\$6,946,514.45
12	Prime Contractor	Gershenson Construction Co., Inc.	Pay Period End	December 15, 2024	Net Change Order Amount	\$48,569.21
					Current Contract Amount	\$6,995,083.66

\$6,995,083.66	ract Amount	Jurrent Conti						
Adjustment amount	Line Item Adjustment Unit Price	Adjustment Quantity	Comments	Other Item Adjustment Type	Adjustment Type	Item Description	Line No.	Project Number
\$1,283.36	\$320.84	4	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 20 on the current Payment Estimate.		Material	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	1640	J6S3417
(\$1,907.92)	\$953.96	-2			Material	MISC.	1700	
\$1,907.92	\$953.96	2	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate.		Material	MISC.	1700	
(\$26,699.28)	\$3,337.41	-8			Material	MISC.	5003	
\$26,699.28	\$3,337.41	8	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 22 on the current Payment Estimate.		Material	MISC.	5003	
\$0.00								Total

Revision 3/23/2023 Page 4 of 30



	Contract Project Information									
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work					
J6S3417	FAF 115-1(47)	Coldmill and resurface, signal, lighting, drainage and ADA improvements	115	ST LOUIS	from I-70 to North Hanley					

tals by Job	y Job Numbers											
6S3417		This Estimate	Previous	To Date								
	Posted Item Pay	\$137,254.43	\$2,300,164.76	\$2,437,419.19								
	Gross Item Adjustments	\$0.00	\$27,356.68	\$27,356.68								
	Gross Item Pay	\$137,254.43	\$2,327,521.44	\$2,464,775.87								
	Incentive	\$0.00	\$0.00	\$0.00								
	Disincentive	\$0.00	\$0.00	\$0.00								
	Liquidated Damages	\$0.00	\$0.00	\$0.00								
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00								

Revision 3/23/2023 Page 5 of 30



Exceptions (Discrepancies) This Estimate Period

Estimate Exception Type: Installiciare Materials: Project JSS9417, Item 4000000, Project Item Line Number Vacion Generic 100074.CORS. CA. Natural Script Off Corp. Class A. Acceptance Action Generic 100074.CORS. CA. Natural Script Off Corp. Class A. Acceptance Action Generic 100074.CORS. CA. Natural Script Off Corp. Class A. Acceptance Action Generic 100074.CORS. CA. Natural Script Off Corp. Class C. Natural Script Off Corp. Class Corp. Class Corp. Corp. Class Corp. Clas	Exceptions (Discrepancies) This Estimate Period			
0133. Material Set 403995569, Material 1005FACCEA. Patarial Search Conc. Class A, Acceptance Action Control Type: Insufficient Materials Project JBSS417, Ilem 4039505, Project Item Line Number Coll. Material Set 60010006, Material 1007CB C-PCMLP - Project Item Line Number Coll. Material Set 60010006, Material 1007CB C-PCMLP - Project Item Line Number Coll. Material Set 60010006, Material 1007CB C-PCMLP - Project Item Line Number Coll. Material Set 60010006, Material 1007CB C-PCMLP - Project Item Line Number Coll. Material Set 60010006, Material 1007CB C-PCMLP - Project Item Line Number Coll. Material Set 60010006, Material 1007CB C-PCMLP - Project Item Line Number Coll. Material Set 60010066, Material 1007TBCD - Turcisated Domes for ADA, Acceptance Action Consens 0007TBCD - Insufficient Estimate Exception Type: Insufficient Materials: Project JBSS417, Ilem 0808006, Project Item Line Number Coll. Material Set 60010026, Material 1007TBCD - Turcisated Domes for ADA, Acceptance Action Consens 0007TBCD - Insufficient Estimate Exception Type: Insufficient Materials: Project JBSS417, Ilem 0808006, Project Item Line Number Coll. Material Set 60010026, Material 1007TBCD - Turcisated Domes for ADA, Acceptance Action Consens 0007TBCD - Insufficient Estimate Exception Type: Insufficient Materials: Project JBSS417, Ilem 0808006, Project Item Line Number Coll. Material Set 6008006, Material 1007TBCD - Turcisated Domes for ADA, Acceptance Action Consens 0007TBCD - Turcisated Domes for ADA, Acceptance Action Consens 0007TBCD - Turcisated Domes for ADA, Acceptance Action Consens 0007TBCD - Turcisated Domes for ADA, Acceptance Action Consens 0007TBCD - Turcisated Domes for ADA, Acceptance Action Consens 0007TBCD - Turcisated Domes for ADA, Acceptance Action Consens 0007TBCD - Turcisated Domes for ADA, Acceptance Action Consens 0007TBCD - Turcisated Domes for ADA, Acceptance Action Consens 0007TBCD - Turcisated Domes for ADA, Acceptance Action Consens 0007TBCD - Turcisated Domes for ADA, Acceptance Action Consens 0007TBCD - Turci	Exceptions / Discrepencies	Explanation		Status
0133. Material Set 403905598. Material 1001 C.PCMLD in PCCP or Masony 11 Max 1,500 A.copspance Action Content Oil O.PCMLD in single-index Materials (2010) C.SS 14 - Content C	0130, Material Set 403990596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance	Waiting for material reporting.	fullek2	Overridden
0230, Material Set 088100056, Material C9510CSB 14. Concrete, Class B.1 wWW, Acceptance Action Centric 10917CBC b. installiciant. Estimate Exception Type: Installicent Materials: Project J853417, Item 0895006, Project Item Line Number (10717CBC) installiciant. Estimate Exception Type: Installicent Materials: Project J853417, Item 0895006, Project Item Line Number (10717CBC) installiciant. Acceptance Action Generic 1007TBCD installiciant. Estimate Exception Type: Installiciant Materials: Project J853417, Item 0935006, Project Item Line Number (2071 Material Set 08500086, Material 1005TBCD). Accident Generic 1007TBCD installiciant. Estimate Exception Type: Installiciant Materials: Project J853417, Item 0935007, Project Item Line Number (2071 Material Set 08500086, Material 1007TBCD - Truncated Domes for ADA. Acceptance Action Generic 1007TBCD - Truncated Domes for ADA. Acceptance Action Generic 1007TBCD - Truncated Domes for ADA. Acceptance Action Generic 1007TBCD - Truncated Domes for ADA. Acceptance Action Generic 1007TBCD - Truncated Domes for ADA. Acceptance Action Generic 1007TBCD - Truncated Domes for ADA. Acceptance Action Generic 1007TBCD - Truncated Domes for ADA. Acceptance Action Generic 1007TBCD - Truncated Domes for ADA. Acceptance Action Generic 0007TBCD - Installiciant Materials: Project J853417, Item 619010AP, Project Item Line Number (2014) Froject Item Line Number (2014) Froj	0130, Material Set 403990596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance	Waiting for material reporting.	fullek2	Overridden
0240, Material Set 608101269, Material 1097TRDO - Truncated Domes for ADA, Acceptance Action Ceremic 1007TRDO in insufficient Estimate Exception Type: Insufficient Materials: Project J859417, Item 0805008, Project Item Line Number 0270, Material Set 60800088, Material 1007AIPFFFF in February (1994), Project Item Line Number 0270, Material Set 60800088, Material 1007AIPFFFF in February (1994), Project Item Line Number 0270, Material Set 60800088, Material 1005 No. CPGM. 0 - PCOP on Maconity "Max LSTOO, Acceptance 0270, Material Set 60800088, Material 1005 No. CPGM. 0 - PCOP on Maconity "Max LSTOO, Acceptance 0270, Material Set 60800088, Material 1005 No. CPGM. 0 - PCOP on Maconity "Max LSTOO, Acceptance 0270, Material Set 60800088, Material 1005 No. CPGM. 0 - PCOP on Maconity "Max LSTOO, Acceptance 0270, Material Set 60080008, Material 1005 No. CPGM. 0 - PCOP on Maconity "Max LSTOO, Acceptance 0270, Material Set 60080008, Material 1005 No. CPGM. 0 - PCOP on Maconity "Max LSTOO, Acceptance 0270, Material Set 60080008, Material 1005 No. CPGM. 0 - Natural Soud for Core Class A Acceptance 0270, Material Set 60080008, Material 1007 RDO - Truncated Domes for ADA. Acceptance Action 0270, Material Set 60080008, Material 1007 RDO - Truncated Domes for ADA. Acceptance Action 0270, Material Set 60080008, Material 1007 RDO - Truncated Domes for ADA. Acceptance Action 0270, Material Set 1007 RDO Insufficient 0770, Material Set 1010 RDO - National Set 0080008, Material 1007 RDO - Truncated Domes for ADA. Acceptance Action 0270, Material Set 1010 RDO - Material Set 1010 RDO - National RDO - National RDO	0230, Material Set 608100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action	Waiting for material reporting.	fullek2	Overridden
0270, Material Set 086500980, Material 1057 MRFRF: Preformed Fiber Expansion Joint Mall @. Estimate Exception Organic Oncoming 1057 MRFRF: in Smilliform. For Committee Exception Type: Insufficient Materials: Project 3653417, Item 8085008, Project Item Line Number Organic Materials: Project 3653417, Item 8085008, Project Item Line Number Organic Materials: Project 3653417, Item 8085008, Project Item Line Number Organic Materials: Project 3653417, Item 8085008, Project Item Line Number Organic Materials: Project 3653417, Item 8085008, Project Item Line Number Organic Materials: Project 3653417, Item 8085008, Project Item Line Number Organic Materials: Project 3653417, Item 8085008, Project Item Line Number Organic Materials: Project 3653417, Item 8085008, Project Item Line Number Organic Materials: Project 3653417, Item 8016009, Acceptance Action Committee Organic Materials: Project 3653417, Item 8116010A, Project Item Line Number Organic Materials: Project 3653417, Item 8116010A, Project Item Line Number Organic Materials: Project 3653417, Item 8116010A, Project Item Line Number Organic Materials: Project 3653417, Item 8116010A, Project Item Line Number Organic Materials: Project 3653417, Item 8113010A, Project Item Line Number Organic Materials: Project 3653417, Item 813100A, Project Item Line Number Organic Materials: Project 3653417, Item 813100A, Project Item Line Number Organic Materials: Project 3653417, Item 813100A, Project Item Line Number Organic Materials: Project 3653417, Item 81010A, Project Item Line Number Organic Materials: Project 3653417, Item 81010A, Project Item Line Number Organic Materials: Project 3653417, Item 81010A, Project Item Line Number 1030, Material Set 80510080B, Material 08030SO - Sof, Acceptance Action Generic 080350 is insufficient. Estimate Exception Type Insufficient Materials: Project 3653417, Item 80100A, Project Item Line Number 1030, Material Set 80510080B, Material 08030SO - Sof, Acceptance Action Generic 080350 is insufficient. Estimate Exception Type: Insufficient	0240, Material Set 608101296, Material 1067TRDO - Truncated Domes for ADA, Acceptance Action	Waiting for material reporting.	fullek2	Overridden
0270, Material Set 608500896, Material 100510, CPCMLD - PCCP or Masonry 1* Maix LS/IDO, Acceptance Action Generic 100510, CPCMLD is insufficient. Estimate Exception Type. Insufficient Materials: Project 4853417, Item 6085009, Project Item Line Number 0200, Material Set 608500896, Material 1005FACCNS, CA: Insufficient. Estimate Exception Type: Insufficient Materials: Project 4853417, Item 60850002, Project Item Line Number 0200, Material Set 608500968, Material 1005FACCNS, CA: Insufficient. Estimate Exception Type: Insufficient Materials: Project 4853417, Item 60850002, Project Item Line Number 0200, Material Set 608500968, Material 1005FACCNS, CA: Insufficient Materials: Project 4853417, Item 60850002, Project Item Line Number 0200, Material Set 61850057, MRFRPF - Insufficient Materials: Project 4853417, Item 60850002, Item Line Number 0200, Material Set 61850057, MRFRPF - Insufficient Materials, Project 4853417, Item 60850002, Project Item Line Number 0200, Material Set 6145014068, Material Set 6145014	0270, Material Set 608500896, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @,	Waiting for material reporting.	fullek2	Overridden
0270, Material Set 608500989, Material 1005FACCN.S. CA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCN.S. of insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 6089002, Project Item Line Number (1007TRDO is Insufficient). Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 6116010A, Project Item Line Number (200, Material Set 6116010A69, Material Set 611601A600A69, Material S	0270, Material Set 608500896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance	Waiting for material reporting.	fullek2	Overridden
0300, Material Set 6089090286, Material 1097TRDO - Truncated Domes for ADA, Acceptance Action Generic 1097TRDO is insufficient Materials: Project J853417, Item 8116010A, Project Item Line Number 1040, Material Set 616104 (100-86), Material 1057JMFRDF - Preformed Fiber Expansion Joint Matl @. Acceptance Action Generic 1057JMFRDF is insufficient. Estimate Exception Type: Insufficient Materials: Project J853417, Item 8143011, Project Item Line Number 1040, Material Set 616104, Material 614DFMNFC - Machine Frame and Cover, Acceptance Action Generic 0914DFMNFC is insufficient. Estimate Exception Type: Insufficient Materials: Project J853417, Item 8031000A, Project Item Line Number 1090, Material Set 8031000A96, Material 808350 - Soot, Acceptance Action Generic 090530 is insufficient. Estimate Exception Type: Insufficient Materials: Project J853417, Item 8061006, Project Item Line Number 1090, Material Set 8031000A96, Material 808350 - Soot, Acceptance Action Generic 0800505 is insufficient. Estimate Exception Type: Insufficient Materials: Project J853417, Item 8061007A, Project Item Line Number 1080, Material Set 806100696, Material 8086TEC - Temporary Erosion Control, Acceptance Action Generic 0800TEC is insufficient. Estimate Exception Type: Insufficient Materials: Project J853417, Item 8061007A, Project Item Line Number 1040, Material Set 8061007A96, Material 8086TEC - Temporary Erosion Control, Acceptance Action Generic 0800TEC is insufficient. Estimate Exception Type: Insufficient Materials: Project J853417, Item 9017407, Project Item Line Number 1040, Material Set 80717076, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0807110XX is insufficient. Estimate Exception Type: Insufficient Materials: Project J853417, Item 9017407, Project Item Line Number 1100, Material Set 90174076, Material 090114XX - Highway Lighting Material, Acceptance Action Generic 090114XX is insufficient. Estimate Exception Type: Insufficient Materials: Project J853417, Item 9031270A, Project Item Line Numbe	0270, Material Set 608500896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance	Waiting for material reporting.	fullek2	Overridden
Number 0400, Material 5et 6116010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Mate (g). Acceptance Action Generic 057JMFRPF is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 6143011, Project Item Line Number 0400, Material 5et 614301168, Material 6040DFMNFC - Manhole Frame and Cover, Acceptance Action Generic 0614DFMNFC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 8031000A, Project Item Line Number 1030, Material 5et 806100096, Material 5et 806100976, Project Item Line Number 1030, Material 5et 8061000976, Broject J6S3417, Item 80610074, Project Item Line Number 1030, Material 5et 8061007746, Project J6S3417, Item 80610074, Project Item Line Number 1030, Material 5et 90174006, Material 5et 90174007, Project Item Line Number 1030, Material 5et 901740796, Material 9001LHXX - Highway Lighting Material, Acceptance Action Generic 8001LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9017407, Project Item Line Number 1030, Material 5et 901740796, Material 5et 9	0300, Material Set 608990296, Material 1067TRDO - Truncated Domes for ADA, Acceptance Action	Waiting for material reporting.	fullek2	Overridden
Overridden Set 614301196, Material 0614DFMNFC in Smithicient. Estimate Exception Type: Insufficient Materials: Project J653417, Item 8031000A, Project Item Line Number 0990, Material Set 803100A86, Material 080350 - Sod, Acceptance Action Generic 0803SO is insufficient. Estimate Exception Type: Insufficient Materials: Project J653417, Item 8061006, Project Item Line Number 1030, Material Set 806100696, Material 80610596, Material 80610596, Material 80610596, Material 806100696, Material 806100740, Project Item Line Number 1030, Material Set 8061007406, Material 806100740, Project Material 806100740, Material 80610074	Number 0400, Material Set 6116010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl	Waiting for material reporting.	fullek2	Overridden
Number 0990, Material Set 8031000A96, Material 0803SO - Sod, Acceptance Action Generic 0803SO is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 8061006, Project Item Line Number 1030, Material Set 800100896, Material 0806TEC - Temporary Erosion Centrol, Acceptance Action Generic 0806TEC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 8061007A, Project Item Line Number 1040, Material Set 8061007A96, Material Set 901741096, Material Set 901740796, Material Set 9031270A, Project Item Line Number 1590, Material Set 9031270A96, Material 9093HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031270A, Project Item Line Number 1590, Material Set 9031270A, Material 9093HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031271A, Project Item Line Number 1600, Material Set 9031270A, Material 9093HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031271A, Project Item Line Number 1600, Material Set 9031271A, Material 9093HSX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031274, Project Item Line Number 1600, Material Set 9031271A, Material 9093HSX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031281A, Project Item Line Number 1600,	0480, Material Set 614301196, Material 0614DFMNFC - Manhole Frame and Cover, Acceptance Action	Waiting for material reporting.	fullek2	Overridden
1030, Material Set 806100686, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 8061007A, Project Item Line Number 1040, Material Set 8061007A96, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9017110, Project Item Line Number 1170, Material Set 901711096, Material Set 901711096, Material O8001LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9017407, Project Item Line Number 1180, Material Set 901740796, Material 901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031270A, Project Item Line Number 1590, Material Set 9031270A96, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031271A, Project Item Line Number 1600, Material Set 9031271A, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031271A, Project Item Line Number 1600, Material Set 9031271A, Material 9033HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031274, Project Item Line Number 1620, Material Set 9031274, Material 9093HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031280, Project Item Line Number 1630, Material Set 90312806, Material 9093HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Excepti	Number 0990, Material Set 8031000A96, Material 0803SO - Sod, Acceptance Action Generic 0803SO is	Waiting for material reporting.	fullek2	Overridden
Number 1040, Material Set 8061007A96, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9017110, Project Item Line Number 1170, Material Set 901711096, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9017407, Project Item Line Number 1180, Material Set 901740796, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031270A, Project Item Line Number 1590, Material Set 9031270A96, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031271A, Project Item Line Number 1600, Material Set 9031271A, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031274, Project Item Line Number 1620, Material Set 90312714, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031274, Project Item Line Number 1620, Material Set 9031274, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031280, Project Item Line Number 1640, Material Set 9031281A, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031281A, Project Item Line Number 1640, Material Set 9031281A, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient	1030, Material Set 806100696, Material 0806TEC - Temporary Erosion Control, Acceptance Action	Waiting for material reporting.	fullek2	Overridden
1170, Material Set 901711096, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031271A, Project Item Line Number 1620, Material Set 9031271A, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031271A, Project Item Line Number 1600, Material Set 9031271A, Material 0903HSXX - Tubular Steel Sign Support, Acceptance Action Generic 0903HSX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031271A, Project Item Line Number 1600, Material Set 9031271A, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSX is insufficient Materials: Project J6S3417, Item 9031274, Project Item Line Number 1620, Material Set 9031274, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient Materials: Project J6S3417, Item 9031274, Project Item Line Number 1620, Material Set 9031274, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSX is insufficient Materials: Project J6S3417, Item 9031280, Project Item Line Number 1630, Material Set 903128096, Material 0903HSXS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSX is insufficient Materials: Project J6S3417, Item 9031280, Project Item Line Number 1640, Material Set 903128096, Material 0903HSX - Tubular Steel Sign Support, Acceptance Action Generic 0903HSX is insufficient Materials: Project J6S3417, Item 9031281A, Project Item Line Number 1640, Material Set 9031281A, Material 0903HSX - Highway Signing Material, Acceptance Action Generic 0903HSX is insufficient Materials: Project J6S3417, Item 9031281A, Project Item Line Number 1640, Material Set 9031281A, Material 0903HSX - Highway Signing Material, Acceptance Action Generic 0903HSX is insufficient Materials: Project J6S3417, Item 9031281A, Acceptance Action	Number 1040, Material Set 8061007A96, Material 0806TEC - Temporary Erosion Control, Acceptance	Waiting for material reporting.	fullek2	Overridden
1180, Material Set 901740796, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031270A, Project Item Line Number 1590, Material Set 9031270A96, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031271A, Project Item Line Number 1600, Material Set 9031271A, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient Materials: Project J6S3417, Item 9031274, Project Item Line Number 1620, Material Set 9031274, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031280, Project Item Line Number 1620, Material Set 9031274, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031280, Project Item Line Number 1630, Material Set 903128096, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031281A, Project Item Line Number 1640, Material Set 9031281A, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031281A, Project Item Line Number 1640, Material Set 9031281A, M	1170, Material Set 901711096, Material 0901LHXX - Highway Lighting Material, Acceptance Action	Waiting for material reporting.	fullek2	Overridden
Number 1590, Material Set 9031270A96, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient Materials: Project J6S3417, Item 9031271A, Project Item Line Number 1600, Material Set 9031271A, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031274, Project Item Line Number 1620, Material Set 9031274, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031280, Project Item Line Number 1630, Material Set 903128096, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031281A, Project Item Line Number 1630, Material Set 9031281A, Material Set 9031281A, Material Set 9031281A, Project Item Line Number 1640, Material Set 9031281A, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031281A, Project Item Line Number 1640, Material Set 9031281A, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9030902, Project Item Line Number Waiting for material reporting. Fullek2 Overridden Vaiting for material reporting.	1180, Material Set 901740796, Material 0901LHXX - Highway Lighting Material, Acceptance Action	Waiting for material reporting.	fullek2	Overridden
Number 1600, Material Set 9031271A, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031274, Project Item Line Number 1620, Material Set 9031274, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031280, Project Item Line Number 1630, Material Set 903128096, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031281A, Project Item Line Number 1640, Material Set 9031281A, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031281A, Project Item Line Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9109902, Project Item Line Number Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9109902, Project Item Line Number Waiting for material reporting. ### Waiting for material reporting. ### Waiting for material reporting. ### Waiting for material reporting.	Number 1590, Material Set 9031270A96, Material 0903HSTS - Tubular Steel Sign Support, Acceptance	Waiting for material reporting.	fullek2	Overridden
1620, Material Set 9031274, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031280, Project Item Line Number 1630, Material Set 903128096, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031281A, Project Item Line Number 1640, Material Set 9031281A, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9109902, Project Item Line Number Waiting for material reporting. Waiting for material reporting. Fullek2 Overridden	Number 1600, Material Set 9031271A, Material 0903HSXX - Highway Signing Material, Acceptance Action	Waiting for material reporting.	fullek2	Overridden
1630, Material Set 903128096, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031281A, Project Item Line Number 1640, Material Set 9031281A, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9031281A, Acceptance Action Waiting for material reporting. Waiting for material reporting. Waiting for material reporting.	1620, Material Set 9031274, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic	Waiting for material reporting.	fullek2	Overridden
Number 1640, Material Set 9031281A, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9109902, Project Item Line Number Waiting for material reporting. fullek2 Overridden	1630, Material Set 903128096, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9109902, Project Item Line Number Waiting for material reporting. fullek2 Overridden	Number 1640, Material Set 9031281A, Material 0903HSXX - Highway Signing Material, Acceptance Action	Waiting for material reporting.	fullek2	Overridden
Action Generic 0910ITXX is insufficient.	1700, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance	Waiting for material reporting.	fullek2	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3417, Item 9109902, Project Item Line Number 5003, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Action Generic 0910ITXX is insufficient.	5003, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance	Waiting for material reporting.	fullek2	Overridden

Revision 3/23/2023 Page 6 of 30



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted amo	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
240419-F02	J6S3417	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	1.00	\$10,000.00	\$10,000.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.45	\$600,000.00	\$270,000.00
		0001	0030	2031000	CLASS A EXCAVATION	580.00	0.00	580.00	CUYD	0.00	\$48.00	\$0.00
		0001	0040	2036000	COMPACTING EMBANKMENT	285.00	0.00	285.00	CUYD	0.00	\$40.00	\$0.00
		0001	0050	2063000	CLASS 3 EXCAVATION	1,036.00	-38.00	998.00	CUYD	754.00	\$8.00	\$6,032.00
		0001	0060	2079909	MISC.LINEAR GRADING CLASS 2, MODIFIED	78.80	0.00	78.80	STA	13.80	\$2,025.00	\$27,945.00
		0001	0070	2159910	MISC.MODIFIED SHAPING SLOPES, CLASS III	2.00	0.00	2.00	100F	0.00	\$1,925.00	\$0.00
		0001	0080	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	10,902.00	0.00	10,902.00	SQYD	7,036.80	\$13.00	\$91,478.40
		0001	0090	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	3,647.00	162.00	3,809.00	SQYD	3,809.00	\$12.50	\$47,612.50
		0001	0100	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	61.80	0.00	61.80	TONS	0.00	\$295.05	\$0.00
		0001	0110	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	5,550.00	-17.70	5,532.30	TONS	0.00	\$136.50	\$0.00
		0001	0120	4030208	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP190C MIX)	3,817.40	-26.70	3,790.70	TONS	0.00	\$113.42	\$0.00
		0001	0130	4039905	MISC.OPTIONAL PAVEMENT	3,646.80	162.20	3,809.00	SQYD	3,809.00	\$78.00	\$297,102.00
		0001	0140	4079912	MISC.MISC. TACK COAT - LOW-TRACKING OR NON-TRACKING	4,483.00	-16.00	4,467.00	GAL	0.00	\$5.00	\$0.00
		0001	0150	4099912	MISC.ASPHALT SEAL EMULSION	721.00	0.00	721.00	GAL	0.00	\$6.50	\$0.00
		0001	0160	5021340	TYPE A2 SHOULDER	1,248.00	0.00	1,248.00	SQYD	1,247.00	\$67.00	\$83,549.00
		0001	0170	6039902	WATER	26.00	0.00	26.00	EA	18.00	\$100.00	\$1,800.00
		0001	0180	6039902	WATER	39.00	0.00	39.00	EA	35.00	\$100.00	\$3,500.00
		0001	0190	6042010	ADJUSTING MANHOLE	26.00	0.00	26.00	EA	5.00	\$100.00	\$500.00
		0001	0200	6042020	ADJUSTING BASIN OR INLET	25.00	0.00	25.00	EA	1.00	\$100.00	\$100.00
		0001	0210	6071012A	CHAIN-LINK FENCE (60 IN.)	122.00	0.00	122.00	LF	0.00	\$65.00	\$0.00
		0001	0220	6079903	MISC.BLACK ORNAMENTAL FENCE (42 IN.)	191.00	0.00	191.00	LF	0.00	\$193.00	\$0.00
		0001	0230	6081000	CONCRETE MEDIAN	609.00	0.00	609.00	SQYD	536.10	\$57.00	\$30,557.70
		0001	0240	6081012	TRUNCATED DOMES	800.00	0.00	800.00	SQFT	162.00	\$28.00	\$4,536.00
		0001	0250	6082024	HAND-RAILING FOR STEPS WITH BALUSTERS	93.00	0.00	93.00	LF	0.00	\$289.00	\$0.00
		0001	0260	6083006	6 IN. CONCRETE MEDIAN STRIP	730.90	0.00	730.90	SQYD	302.32	\$118.00	\$35,673.76
			0270	6085008	PAVED APPROACH, 8 IN.	4,482.80	0.00	4,482.80	SQYD	3.189.30	\$102.00	\$325,308.60
		0001	0270	6086004	CONCRETE SIDEWALK, 4 IN.	3,058.20	0.00	3.058.20	SQYD	1,809.20	\$51.00	\$92,269.20
		0001		6086007				-,,				
		0001	0290		CONCRETE SIDEWALK, 7 IN.	716.50	0.00	716.50	SQYD	29.40	\$68.00 \$2,400.00	\$1,999.20
		0001	0300	6089902	MISC TRUCK APPON	170.00	0.00	170.00		103.00		\$247,200.00
		0001	0310	6089905	MISC.TRUCK APRON	34.10	0.00	34.10	SQYD	34.10	\$169.00	\$5,762.90
		0001	0320	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	4,551.00	0.00	4,551.00	LF	2,745.00	\$41.00	\$112,545.00
		0001	0330	6091042	CONCRETE GUTTER TYPE B	156.00	0.00	156.00	LF	0.00	\$63.00	\$0.00
		0001	0340	6091052	CURB AND GUTTER TYPE B	890.00	0.00	890.00	LF	299.00	\$50.00	\$14,950.00
		0001	0350	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	383.00	0.00	383.00	LF	188.00	\$26.00	\$4,888.00
		0001	0360	6092032	CONCRETE CURB LOW PROFILE TYPE F	263.00	0.00	263.00	LF	0.00	\$34.00	\$0.00
		0001	0370	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	346.00	0.00	346.00	CUYD	9.00	\$67.00	\$603.00
		0001	0380	6096042	PLACING TYPE 2 ROCK DITCH LINER	346.00	0.00	346.00	CUYD	9.00	\$40.00	\$360.00
		0001	0390	6097000	ROCK LINING	10.00	0.00	10.00	CUYD	0.00	\$80.00	\$0.00
		0001	0400	6116010A	SLOPE PROTECTION	132.00	0.00	132.00	SQYD	15.00	\$103.00	\$1,545.00
		0001	0410	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	500.00	0.00	500.00	SQYD	0.00	\$225.00	\$0.00
		0001	0420	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	125.00	0.00	125.00	SQYD	0.00	\$1.00	\$0.00
	0001 0430 6131013 TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)				125.00	0.00	125.00	SQYD	0.00	\$5.00	\$0.00	
	0001 0440 6131014 FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)					1,914.00	0.00	1,914.00	LF	0.00	\$5.00	\$0.00
	0001 0450 6131015 DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR											

Revision 3/23/2023 Page 7 of 30



Total Paid / All Items / All Estimates (Including this Estimate)

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See report generated date)
10419-F02	J6S3417	0001	0460	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	30.00	0.00	30.00	EA	0.00	\$50.00	\$0.
		0001	0470	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	56.00	0.00	56.00	EA	0.00	\$5.00	\$0.4
		0001	0480	6143011	MANHOLE FRAME AND COVER, TYPE 1-B	2.00	0.00	2.00	EA	2.00	\$588.00	\$1,176.
		0001	0490	6143012	MANHOLE FRAME AND COVER, TYPE 2	1.00	0.00	1.00	EA	0.00	\$588.00	\$0.
		0001	0500	6149902	MISC.CONVERT INLET TO MANHOLE	2.00	0.00	2.00	EA	2.00	\$4,010.00	\$8,020.
		0001	0510	6149902	MISC.DOUBLE SIDEWALK TRENCH DRAIN	1.00	0.00	1.00	EA	0.00	\$18,890.00	\$0.
		0001	0520	6149902	MISC.SIDEWALK TRENCH DRAIN	3.00	0.00	3.00	EA	0.00	\$8,500.00	\$0.
		0001	0530	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	0.00	\$2,352.00	\$0.
		0001	0540	6169901	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$92,163.00	\$46,081
		0001	0550	6173001	CONCRETE TRAFFIC BARRIER, TYPE C (RETAINING WALL)	156.00	0.00	156.00	LF	0.00	\$291.00	\$0
		0001	0560	6173100	CONCRETE TRAFFIC BARRIER, TYPE D	547.00	0.00	547.00	LF	0.00	\$192.00	\$0
		0001	0570	6179903	MISC.CONCRETE TRAFFIC BARRIER, TYPE C (MODIFIED)	259.00	0.00	259.00	LF	0.00	\$288.00	\$0
		0001	0580	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$524,175.00	\$393,131
		0001	0590	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	6.00	0.00	6.00	EA	0.00	\$600.00	\$0
		0001	0600	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	492.00	0.00	492.00	LF	0.00	\$6.42	\$0
		0001	0610	6200012	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE	107.00	0.00	107.00	LF	0.00	\$12.83	\$0
		0001	0620	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	714.00	0.00	714.00	LF	0.00	\$19.25	\$0
		0001	0630	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	274.00	0.00	274.00	LF	0.00	\$19.25	\$0
		0001	0640	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	60.00	0.00	60.00	EA	0.00	\$299.45	\$
		0001	0650	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	24.00	0.00	24.00	EA	0.00	\$267.37	\$1
		0001	0660	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	6.00	0.00	6.00	EA	0.00	\$481.26	\$0
		0001	0670	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	2.00	0.00	2.00	EA	0.00	\$481.26	\$0
		0001	0680	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	159.00	0.00	159.00	EA	0.00	\$192.50	\$1
		0001	0690	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	112.00	0.00	112.00	EA	0.00	\$69.52	\$1
		0001	0700	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	3,725.00	0.00	3,725.00	LF	0.00	\$2.14	\$0
		0001	0710	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	5,455.00	0.00	5,455.00	LF	0.00	\$2.14	\$0
		0001	0720	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	13,944.00	0.00	13,944.00	LF	0.00	\$0.21	\$0
		0001	0730	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	38,349.00	0.00	38,349.00	LF	0.00	\$0.32	\$0
		0001	0740	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	12,202.00	0.00	12,202.00	LF	0.00	\$0.32	\$0
		0001	0750	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	191.00	0.00	191.00	LF	0.00	\$1.07	\$0
		0001	0760		4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	3,860.00	0.00	3,860.00	LF	0.00	\$1.07	\$0
		0001	0770		4 IN, YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	4,380.00	0.00	4,380.00	LF	0.00	\$1.07	\$0
		0001	0780	6207001	PAVEMENT MARKING REMOVAL	7,442.00	0.00	7,442.00	LF	0.00	\$1.07	\$0
		0001	0790	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	45.00	0.00	45.00	EA	0.00	\$58.82	\$0
		0001	0800	6209902	MISC.18 IN. WHITE TUBULAR MARKER	26.00	0.00	26.00	EA	0.00	\$80.21	\$0
		0001	0810	6209902	MISC.18 IN. YELLOW TUBULAR MARKER	63.00	0.00	63.00	EA	0.00	\$80.21	\$0
		0001	0820	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE REDUCTION ARROW	2.00	0.00	2.00	EA	0.00	\$1,604.20	\$0
		0001	0830	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	25,268.00	0.00	25,268.00	SQYD	0.00	\$3.65	\$0
		0001	0840	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	23,171.00	-162.00	23,009.00	SQYD	0.00	\$5.60	\$0
		0001	0850	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,035.00	0.00	1,035.00	SQYD	0.00	\$5.60	\$0
		0001	0860	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.45	\$31,100.00	\$13,995

Revision 3/23/2023 Page 8 of 30



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
40419-F02	J6S3417	0001	0870	7032002	CLASS B CONCRETE (MISC)	3.60	0.00	3.60	CUYD	0.00	\$2,800.00	\$0.0
		0001	0880	7061000	REINFORCING STEEL	170.00	0.00	170.00	LB	0.00	\$6.00	\$0.0
		0001	0890	7261012	12 IN. PIPE GROUP A	935.00	0.00	935.00	LF	935.00	\$98.00	\$91,630.0
		0001	0900	7261015	15 IN. PIPE GROUP A	559.00	0.00	559.00	LF	239.00	\$86.00	\$20,554.0
		0001	0910	7261018	18 IN. PIPE GROUP A	175.00	0.00	175.00	LF	4.00	\$99.00	\$396.0
		0001	0920	7310048	PRECAST CONCRETE MANHOLE - 48 IN.	5.00	0.00	5.00	FT	0.00	\$698.00	\$0.0
		0001	0930	7319902	MISC.INLET TOP REPLACEMENT (IN KIND)	1.00	0.00	1.00	EA	0.00	\$1,750.00	\$0.0
		0001	0940	7319913	MISC.SINGLE STREET INLET	25.00	0.00	25.00	FT	21.00	\$1,065.00	\$22,365.0
		0001	0950	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	9.00	0.00	9.00	EA	8.00	\$870.00	\$6,960.0
		0001	0960	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	0.00	\$1,225.00	\$0.0
		0001	0970	7320624A	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	1.00	\$1,800.00	\$1,800.
		0001	0980	8025006	MULCHING	0.10	0.00	0.10	ACRE	0.00	\$5,350.00	\$0.0
		0001	0990	8031000A	TURF TYPE TALL FESCUE SODDING	5,528.00	0.00	5,528.00	SQYD	3,315.00	\$12.00	\$39,780.0
		0001	1000	8039905A	MISC.LANDSCAPING RESTORATION	28.00	0.00	28.00	SQYD	0.00	\$105.00	\$0.0
		0001	1010	8051000A	SEEDING - COOL SEASON GRASSES	0.10	0.00	0.10	ACRE	0.00	\$5,350.00	\$0.0
		0001	1020	8061005	ROCK DITCH CHECK	120.00	0.00	120.00	LF	0.00	\$10.00	\$0.0
		0001	1030	8061006	ALTERNATE DITCH CHECK	508.00	0.00	508.00	LF	144.00	\$10.00	\$1,440.0
		0001	1040	8061007A	CURB INLET CHECK	39.00	0.00	39.00	EA	16.00	\$10.00	\$160.0
		0001	1050	8061016	SEDIMENT REMOVAL	83.00	0.00	83.00	CUYD	0.00	\$1.00	\$0.
		0001	1060	8061019	SILT FENCE	3,800.00	0.00	.00 3,800.00	LF	0.00	\$3.25	\$0
		0010	1070	6061060	MGS GUARDRAIL	182.00	0.00	182.00	LF	0.00	\$35.00	\$0.
		0010	1080	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	0.00	\$1,925.00	\$0.
		0010	1090	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$3,850.00	\$0.
		0020	1100	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	1,695.00	0.00	1,695.00	LF	505.00	\$15.00	\$7,575.
		0020	1110	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	20.00	0.00	20.00	LF	0.00	\$19.25	\$0.
		0020	1120	9014004	CONDUIT, 4 IN. RIGID, PUSHED	499.00	0.00	499.00	LF	0.00	\$25.67	\$0.
		0020	1130	9014502	CONDUIT, 2 IN. RIGID, EXTERNAL ON STRUCTURE	479.00	0.00	479.00	LF	0.00	\$21.39	\$0.
		0020	1140	9015010	TRENCHING TYPE I	1,995.00	0.00	1,995.00	LF	0.00	\$8.02	\$0.
		0020	1150	9016110	PULL BOX, PREFORMED CLASS 1	12.00	0.00	12.00	EA	3.00	\$1,653.39	\$4,960.
		0020	1160	9016112	PULL BOX, PREFORMED CLASS 3	2.00	0.00	2.00	EA	0.00	\$2,451.21	\$0.
		0020	1170	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	1,290.00	0.00	1,290.00	LF	180.00	\$1.07	\$192.
		0020	1180	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	5,350.00	0.00	5,350.00	LF	517.00	\$3.48	\$1,799.
		0020	1190	9018230	POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT)	1.00	0.00	1.00	EA	0.00	\$1,470.51	\$0.
		0020	1200	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	13.00	0.00	13.00	EA	0.00	\$2,108.98	\$0.
		0020	1210	9019902	MISC.170W TOP MOUNTED LED-B LUMINAIRE	5.00	0.00	5.00	EA	0.00	\$609.59	\$0.
		0020	1220	9019902	MISC.170W TOP MOUNTED LED-B LUMINAIRE, TYPE IV DISTRIBUTION	9.00	0.00	9.00	EA	0.00	\$609.59	\$0.
		0020	1230	9019902	MISC.30 FT. TOP MOUNT LIGHT POLE	1.00	0.00	1.00	EA	0.00	\$2,819.11	\$0.
		0020	1240	9019902	MISC.45 FT. TOP MOUNT LIGHT POLE	13.00	0.00	13.00	EA	0.00	\$3,514.26	\$0.
		0020	1250	9019902	MISC.LUMINAIRE, LED WALL PACK (UNDERPASS)	12.00	0.00	12.00	EA	0.00	\$649.16	\$0.
		0030	1260	9020113	SIGNAL HEAD, TYPE 3T	1.00	0.00	1.00	EA	0.00	\$1,071.60	\$0.
		0030	1270	9020213	SIGNAL HEAD, TYPE 3S	2.00	0.00	2.00	EA	0.00	\$1,014.92	\$0.
		0030	1280	9020513	SIGNAL HEAD, TYPE 3B	16.00	0.00	16.00	EA	0.00	\$1,341.11	\$0.
		0030	1290	9020514	SIGNAL HEAD, TYPE 4B	6.00	0.00	6.00	EA	0.00	\$1,553.93	\$0.
		0030	1300	9020833	SH-FLAT SHEET - SIGNAL SIGN	198.00	0.00	198.00	SQFT	0.00	\$43.85	\$0.
	0030 1310 9020834 SIGNAL SIGN, MOUNTING HARDWARE				SIGNAL SIGN, MOUNTING HARDWARE	22.00	0.00	22.00	EA	0.00	\$320.84	\$0.0

Page 9 of 30 Revision 3/23/2023



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted amo	Bid Quantity	Net Change Order	Total Current Quantity	unit	Total Posted Approved	Unit Price	Total Value POSTED To Date (See report generated date)
										Qty		
240419-F02	J6S3417	0030	1320	9022708	POST, SIGNAL 8 FT.	8.00	0.00	8.00	EA	0.00	\$1,233.09	\$0.00
		0030	1330	9022715	POST, SIGNAL 15 FT.	1.00	0.00	1.00	EA	0.00	\$1,835.20	\$0.00
		0030	1340	9023130	POST, TYPE CL, 30 FT. ARM OR 9.1 M ARM	1.00	0.00	1.00	EA	0.00	\$13,047.46	\$0.00
		0030	1350	9023230	POST, TYPE C, 30 FT. ARM OR 9.1 M ARM POST, TYPE C, 35 FT. ARM OR 10.7 M ARM	2.00 4.00	0.00	2.00 4.00	EA EA	0.00	\$11,665.71 \$12,034.68	\$0.00 \$0.00
		0030	1370	9023235	POST, TYPE C, 35 FT. ARM OR 10.7 M ARM POST, TYPE C, 45 FT. ARM OR 13.7 M ARM	1.00	0.00	1.00	EA	0.00	\$12,034.66	\$0.00
		0030	1380	9023243	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	2.00	0.00	2.00	EA	0.00	\$25,576.23	\$0.00
		0030	1390	9025200	CONDUIT. 2 IN TRENCH WITH TRACER WIRE	37.00	0.00	37.00	LF	0.00	\$14.97	\$0.00
		0030	1400	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	385.00	0.00	385.00	LF	0.00	\$16.04	\$0.00
		0030	1410	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	773.00	0.00	773.00	LF	0.00	\$24.60	\$0.00
			1420	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	200.00	0.00	200.00	LF	0.00	\$1.55	\$0.00
		0030							LF			
		0030	1430	9028308	CABLE, 16 AWG 2 CONDUCTOR	2,990.00	0.00	2,990.00	LF	0.00	\$1.28	\$0.00
		0030	1440	9028310	CABLE, 16 AWG 5 CONDUCTOR	3,010.00	0.00	3,010.00		0.00	\$1.44	\$0.00
		0030	1450	9028311	CABLE, 16 AWG 7 CONDUCTOR	5,890.00	0.00	5,890.00	LF	0.00	\$1.50	\$0.00
		0030	1460	9028810	PULL BOX, PREFORMED CLASS 1	1.00	0.00	1.00	EA	0.00	\$1,646.97	\$0.00
		0030	1470	9028811	PULL BOX, PREFORMED CLASS 2	5.00	0.00	5.00	EA	0.00	\$2,451.21	\$0.00
		0030	1480	9028812	PULL BOX, PREFORMED CLASS 3	5.00	0.00	5.00	EA	0.00	\$3,632.97	\$0.00
		0030	1490	9029100	BASE, CONCRETE	32.90	0.00	32.90	CUYD	0.00	\$1,550.72	\$0.00
		0030	1500	9029901	MISC.TRAFFIC SIGNAL MAINTENANCE AND PROGRAMMING	1.00	0.00	1.00	LS	0.00	\$10,052.96	\$0.00
		0030	1510	9029902	MISC.AUDIBLE PEDESTRIAN PUSH BUTTON AND SIGNING WITH VERBAL WALK MESSAGE	14.00	0.00	14.00	EA	0.00	\$1,228.81	\$0.00
		0030	1520	9029902	MISC.COMBINATION PAD MOUNTED 120V/240V POWER SUPPLY AND LIGHTING CONTROLLER WITH UPS	2.00	0.00	2.00	EA	0.00	\$22,765.68	\$0.00
		0030	1530	9029902	MISC.COUNTDOWN PEDESTRIAN SIGNAL HEAD, TYPE 1S	14.00	0.00	14.00	EA	0.00	\$915.46	\$0.00
		0030	1540	9029902	MISC.NETWORK CONNECTED SIGNAL MONITOR	2.00	0.00	2.00	EA	0.00	\$1,764.62	\$0.00
		0030	1550	9029902	MISC.POTHOLING FOR UTILITY FACILITIES	45.00	0.00	45.00	EA	0.00	\$299.45	\$0.00
		0030	1565	9029902	MISC.RECTANGULAR RAPID FLASHIG BEACON	6.00	0.00	6.00	EA	0.00	\$13,154.41	\$0.00
		0030	1570	9029902	MISC.SL DISTRICT TRAFFIC SIGNAL DETECTION SYSTEM	2.00	0.00	2.00	EA	0.00	\$50,886.16	\$0.00
		0040	1580	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL	2.00	0.00	2.00	EA	0.00	\$481.26	\$0.00
		0040	1590	9031270A	TUBE) 2 IN. PSST POST - 12 GA.	475.00	0.00	475.00	LF	188.00	\$27.81	\$5,228.28
		0040	1600	9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	27.00	0.00	27.00	EA	9.00	\$267.37	\$2,406.33
		0040	1610	9031272A	2.25 IN. PSST POST INSERT (6 FT.) - 12 GA.	2.00	0.00	2.00	EA	0.00	\$128.34	\$0.00
		0040	1620	9031274	CONCRETE POST ANCHOR FOR 2 IN. PSST 7 GA.	18.00	0.00	18.00	EA	11.00	\$641.68	\$7,058.48
		0040	1630	9031280	2.5 IN. PSST POST - 12 GA.	203.00	0.00	203.00	LF	60.75	\$29.94	\$1,818.86
		0040	1640	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	13.00	0.00	13.00	EA	4.00	\$320.84	\$1,283.36
		0040	1650	9035004A	SH-FLAT SHEET	377.00	0.00	377.00	SQFT	158.35	\$29.94	\$4,741.00
		0040	1660	9035069A	SHF-FLAT SHEET FLUORESCENT	185.00	0.00	185.00	SQFT	39.60	\$33.15	\$1,312.74
		0040	1670	9039902	MISC.REMOVE AND RELOCATE EXISTING GROUND MOUNT	1.00	0.00	1.00	EA	0.00	\$320.84	\$0.00
					SIGN				1.0			
		0050	1680	9109901	MISCRELOCATION OF ST. LOUIS COUNTY'S TRAFFIC SIGNAL	1.00	0.00	1.00	LS	0.00	\$7,379.30	\$0.00
		0050	1690	9109901	MISC.RELOCATION OF ST. LOUIS COUNTY'S TRAFFIC SIGNAL INTERCONNECT	1.00	0.00	1.00	LS	0.00	\$1,015.99	\$0.00
		0050	1700	9109902	MISC.ADJUST TO GRADE MODOT PULL BOX	8.00	0.00	8.00	EA	2.00	\$953.96	\$1,907.92
		0050	1710	9109902	MISC.CCTV CAMERA ASSEMBLY	1.00	0.00	1.00	EA	0.00	\$5,366.57	\$0.00
		0050	1720	9109902	MISC.FIBER OPTIC FUSION SPLICE	16.00	0.00	16.00	EA	0.00	\$66.31	\$0.00
		0050	1730	9109902	MISC.FIBER OPTIC JUMPER	8.00	0.00	8.00	EA	0.00	\$87.70	\$0.00
	0050 1740 9109902 MISC.FIBER OPTIC PIGTAIL				8.00	0.00	8.00	EA	0.00	\$78.07	\$0.00	
	0050 1750 9109902 MISC.INSTALL CCTV CAMERA ASSEMBLY					1.00	0.00	1.00	EA	0.00	\$1,143.26	\$0.00
		0050	1760	9109902	MISC.INSTALL MODOT FURNISHED IP-ADDRESSABLE POWER	2.00	0.00	2.00	EA	0.00	\$267.37	\$0.00

Revision 3/23/2023 Page 10 of 30



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
240419-F02	J6S3417				STRIP							
		0050	1770	9109902	MISC.ITS PULL BOX WITH CONCRETE PAD, PREFORMED CLASS 5	2.00	0.00	2.00	EA	0.00	\$3,703.55	\$0.00
		0050	1780	9109902	MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT	2.00	0.00	2.00	EA	0.00	\$1,207.42	\$0.00
		0050	1790	9109902	MISC.REMOVE IN-PAVEMENT WIRELESS DETECTION SYSTEM PER INTERSECTION	2.00	0.00	2.00	EA	0.00	\$2,027.70	\$0.00
		0050	1800	9109902	MISC.WALL-MOUNTED INTERCONNECT CENTER	2.00	0.00	2.00	EA	0.00	\$1,644.84	\$0.00
		0050	1810	9109903	MISC.CCTV CAMERA CABLE	160.00	0.00	160.00	LF	0.00	\$2.09	\$0.00
		0050	1820	9109903	MISC.CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	28.00	0.00	28.00	LF	0.00	\$16.04	\$0.00
		0050	1830	9109903	MISC.FIBER OPTIC CABLE, 24 STRAND, SINGLE MODE	5,050.00	0.00	5,050.00	LF	0.00	\$3.81	\$0.00
		0001	5001	6149902	MISC.REPLACE FRAMES AND GRATES 2' x 6' INLET	0.00	2.00	2.00	EA	0.00	\$4,399.45	\$0.00
		0001	5002	2063100	CLASS 3 EXCAVATION IN ROCK	0.00	38.00	38.00	CUYD	38.00	\$135.00	\$5,130.00
		0050	5003	9109902	MISC.REMOVE AND REPLACE ITS PULL BOX, PREFORMED CLASS 2	0.00	8.00	8.00	EA	8.00	\$3,337.41	\$26,699.28
	Project J	6S3417 - To	otal Value	Posted to D	Date as of Report Generated Date							\$2,437,419.18
240419-F02 Ove	rall - Total	Value Post	ed to Da	te as of Repo	ort Generated Date							\$2,437,419.18

Revision 3/23/2023 Page 11 of 30



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6S3417

Line lumber	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2013000	CLEARING AND GRUBBING	12/4/24	12/12/24	1.00	ACRE		00+00	CL			
0020	2022010	REMOVAL OF IMPROVEMENTS	12/9/24	12/12/24	0.05	LS		00+00	CL			
0080	3040504	TYPE 5 AGGREGATE FOR BASE	12/4/24	12/12/24	5.00	SQYD		45+71.00	RT CL	46+00.89	RT CL	
				12/12/24	72.30	SQYD	Medora South	46+79.64	RT CL			Half of approach
			12/9/24		36.00	SQYD		51+88.57				
				12/12/24	45.00	SQYD		50+87.47	RT			
				12/12/24	91.00	SQYD			RT	50+69.20	RT	
			12/11/24	12/13/24	32.00	SQYD		51+01.50	RT CL	51+63.09		
				12/13/24	45.00	SQYD		52+85.16				
			12/12/24		25.00	SQYD			RT CL			
				12/13/24	47.00	SQYD		53+64.76		54+66.07	RT CI	
			12/13/24	12/13/24	72.00	SQYD			RT CL	04-00.07	TO GE	
0170	6039902	WATER - UTILITY ITEM		12/12/24	1.00	EA		50+17.24				
0110	0000002		12/11/24		1.00	EA						
			.2.1124	12/13/24	1.00	EA			RT CL			
0240	6081012	TRUNCATED DOMES	12/4/24	12/13/24	10.00	SQFT		46+37.77		46+57.37	RT CI	
0240	6083006	6 IN. CONCRETE MEDIAN STRIP		12/12/24		SQYD			RT CL	42+77.36		
0200		PAVED APPROACH, 8 IN.		12/12/24	72.30	SQYD	Medora S		RT CL	72711.30	IVI OL	Half of approach
0210	0000000	LAVED ALL NOACH, 6 IN.		12/12/24	35.90	SQYD	medola 0	51+88.57				пап от арргодоп
			12/3/24	12/12/24	45.40	SQYD		50+87.47				
			12/11/24			SQYD		52+85.16				
				12/13/24								
								54+78.21				
0000	0000004	OONODETE ODEWAY AND		12/13/24		SQYD		46+79.64		40.00.00	DT OI	
0280	6086004	CONCRETE SIDEWALK, 4 IN.		12/12/24		SQYD			RT CL	46+00.89		
				12/12/24		SQYD			RT	50+69.20		
				12/13/24		SQYD			RT CL	51+63.09		
				12/13/24	47.00	SQYD		53+64.76	RT CL	54+66.07		
0300	6089902	MISC. CONCRETE	12/4/24		2.00	EA			RT CL	46+00.89		Between both 8730 approaches
				12/12/24	2.00	EA	W side of Medora S		RT CL	46+57.37		
				12/12/24	2.00	EA	s/w BTWN 8740 and 8730		RT CL	45+26.51		
				12/12/24	1.00	EA		43+09.31	RT CL	43+96.81	RT CL	
			12/11/24	12/13/24	1.00	EA			RT CL	50+69.20		
				12/13/24	3.00	EA		51+01.50	RT CL	51+63.09	RT CL	
				12/13/24	1.00	EA		53+64.76		54+66.07		
0320	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER)		12/12/24	23.00	LF	BTWN 8730 approaches		RT CL	45+97.81		
			12/9/24		29.00	LF			RT	48+97.68		
				12/12/24	132.00	LF			RT	50+56.16		
			12/10/24		94.00	LF		53+68.27		54+62.06		
			12/12/24	12/13/24	29.00	LF		53+02.28	RT CL	53+31.19		
				12/13/24	45.00	LF		54+96.79	RT CL	55+42.12	RT CL	
0350		INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	12/11/24	12/13/24	10.00	LF		49+13.61	RT CL	50+69.20		
0400	6116010A	SLOPE PROTECTION	12/11/24	12/13/24	10.00	SQYD		51+01.50	RT CL	51+63.09	RT CL	
0860	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	12/9/24	12/12/24	0.05	LS		00+00	CL			
1700	9109902	MISC. ITS	12/11/24	12/13/24	1.00	EA		52+50.20	LT CL			
				12/13/24	1.00	EA		53+94.59	RT CL			
5003	9109902	MISC. ITS	12/9/24	12/12/24	1.00	EA		52+46.46	RT			

The information below this line are details for Construction Signs (if applicable), No Data Available

Revision 3/23/2023 Page 12 of 30





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3417	0800	TYPE 5 AGGREGATE FOR BASE	Material		1	Jul 1, 2024	SYSTEM	\$4,773.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Jul 1, 2024	SYSTEM	(\$4,773.60)	
					2	Jul 16, 2024	SYSTEM	\$6,552.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Jul 16, 2024	SYSTEM	(\$6,552.00)	
					3	Aug 2, 2024	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Aug 2, 2024	SYSTEM	(\$13,000.00)	
					4	Aug 16, 2024	SYSTEM	\$23,956.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Aug 16, 2024	SYSTEM	(\$23,956.40)	
					5	Sep 3, 2024	SYSTEM	\$39,413.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Sep 3, 2024	SYSTEM	(\$39,413.40)	
					6	Sep 16, 2024	SYSTEM	\$55,377.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Sep 16, 2024	SYSTEM	(\$55,377.40)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0080 -	Total						\$0.00	
	0090	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		5	Sep 3, 2024	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		,			5	Sep 3, 2024	SYSTEM	(\$4,200.00)	
					6	Sep 16,	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Material Payment
						2024		, ,	Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Sep 16, 2024	SYSTEM	(\$4,200.00)	Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment
				- Total	6	Sep 16,	SYSTEM		Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment
			Material - To		6	Sep 16,	SYSTEM	(\$4,200.00)	Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment
	0090 -	Total	Material - To		6	Sep 16,	SYSTEM	(\$4,200.00) \$0.00	Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment
	0090 -	Total MISC.	Material - To		5	Sep 16,	SYSTEM	(\$4,200.00) \$0.00 \$0.00	Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment
						Sep 16, 2024		(\$4,200.00) \$0.00 \$0.00	Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment
					5	Sep 16, 2024 Sep 3, 2024 Sep 3,	SYSTEM	(\$4,200.00) \$0.00 \$0.00 \$0.00 \$26,169.00	Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment
					5	Sep 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16,	SYSTEM	(\$4,200.00) \$0.00 \$0.00 \$0.00 \$26,169.00 (\$26,169.00)	Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment
					5 5 6	Sep 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16, 2024	SYSTEM SYSTEM	(\$4,200.00) \$0.00 \$0.00 \$26,169.00 (\$26,169.00) \$26,169.00	Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment
					5 5 6	Sep 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16, 2024 Sep 16, 2024 Oct 1,	SYSTEM SYSTEM SYSTEM	(\$4,200.00) \$0.00 \$0.00 \$26,169.00 (\$26,169.00) \$26,169.00	Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.
					5 5 6 6 7	Sep 16, 2024 Sep 3, 2024 Sep 3, 2024 Sep 16, 2024 Oct 1, 2024 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,200.00) \$0.00 \$0.00 \$0.00 \$26,169.00 (\$26,169.00) \$26,169.00 (\$26,169.00) \$84,879.60	Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
417	0130	MISC.	Material			2024			
					9	Nov 4, 2024	SYSTEM	\$297,102.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Nov 4, 2024	SYSTEM	(\$297,102.00)	
					10	Nov 18, 2024	SYSTEM	\$297,102.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Nov 18, 2024	SYSTEM	(\$297,102.00)	
					11	Dec 2, 2024	SYSTEM	\$141,102.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Dec 2, 2024	SYSTEM	(\$141,102.00)	
					12	Dec 16, 2024	SYSTEM	\$141,102.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Dec 16, 2024	SYSTEM	(\$141,102.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0130 -	Total						\$0.00	
	0160	TYPE A2 SHOULDER	Material		5	Sep 3, 2024	SYSTEM	\$40,133.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Sep 3, 2024	SYSTEM	(\$40,133.00)	
					6	Sep 16, 2024	SYSTEM	\$83,549.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Sep 16, 2024	SYSTEM	(\$83,549.00)	
					7	Oct 1, 2024	SYSTEM	\$83,549.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Oct 1, 2024	SYSTEM	(\$83,549.00)	
					8	Oct 16, 2024	SYSTEM	\$83,549.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Oct 16, 2024	SYSTEM	(\$83,549.00)	
					9	Nov 4, 2024	SYSTEM	\$83,549.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Nov 4, 2024	SYSTEM	(\$83,549.00)	
					10	Nov 18, 2024	SYSTEM	\$83,549.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Nov 18, 2024	SYSTEM	(\$83,549.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0160 -							\$0.00	
	0170	WATER - UTILITY ITEM	Material		2	Jul 16, 2024	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Jul 16, 2024	SYSTEM	(\$100.00)	
					3	Aug 2, 2024	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.





ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
417	0170	WATER - UTILITY ITEM	Material		3	Aug 2, 2024	SYSTEM	(\$500.00)										
					4	Aug 16, 2024	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.									
					4	Aug 16, 2024	SYSTEM	(\$500.00)										
					5	Sep 3, 2024	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 8 on the current Payment Estimate.									
					5	Sep 3, 2024	SYSTEM	(\$600.00)										
				- Total				\$0.00										
			Material - To	tal				\$0.00										
	0170 -	Total						\$0.00										
	0180	WATER - UTILITY ITEM	Material		1	Jul 1, 2024	SYSTEM	\$700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 2 on the current Payment Estimate.									
					1	Jul 1, 2024	SYSTEM	(\$700.00)										
					2	Jul 16, 2024	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.									
					2	Jul 16, 2024	SYSTEM	(\$1,100.00)										
					3	Aug 2, 2024	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.									
					3	Aug 2, 2024	SYSTEM	(\$2,400.00)										
					4	Aug 16, 2024	SYSTEM	\$2,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.									
					4	Aug 16, 2024	SYSTEM	(\$2,600.00)										
					5	Sep 3, 2024	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user fullerk2 overridding Payment Estimate Exception 9 on the current Payment Estimate.									
					5	Sep 3, 2024	SYSTEM	(\$3,000.00)										
				- Total				\$0.00										
			Material - To	tal				\$0.00										
	0180 -							\$0.00										
	0220	MISC. FENCING	Construction Stockpile STMI		6	Sep 16, 2024	SYSTEM	\$14,796.77	Payment Estimate Item Adjustment generated Stockpile Transaction									
			J I WII	- Total				\$14,796.77										
			Construction	1 Stockpile S1	「MI - Total			\$14,796.77										
	0220 -							\$14,796.77										
	0230	CONCRETE MEDIAN	Material		9	Nov 4, 2024	SYSTEM	\$30,557.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.									
					9	Nov 4, 2024	SYSTEM	(\$30,557.70)										
					9		SYSTEM	(\$30,557.70) \$30,557.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.									
						2024 Nov 18,			Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment									
					10	2024 Nov 18, 2024 Nov 18,	SYSTEM	\$30,557.70	Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment									





Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Type	Adjustment Type	Number	Date	Ву		
J6S3417	0230	CONCRETE MEDIAN	Material		12	Dec 16, 2024	SYSTEM	\$30,557.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Dec 16, 2024	SYSTEM	(\$30,557.70)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0230 -	Total						\$0.00	
	0240	TRUNCATED DOMES	Material		2	Jul 16, 2024	SYSTEM	\$560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	Jul 16, 2024	SYSTEM	(\$560.00)	
					3	Aug 2, 2024	SYSTEM	\$560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Aug 2, 2024	SYSTEM	(\$560.00)	
					4	Aug 16, 2024	SYSTEM	\$840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Aug 16, 2024	SYSTEM	(\$840.00)	
					5	Sep 3, 2024	SYSTEM	\$840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user fullerk2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					5	Sep 3, 2024	SYSTEM	(\$840.00)	
					6	Sep 16, 2024	SYSTEM	\$840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Sep 16, 2024	SYSTEM	(\$840.00)	
					7	Oct 1, 2024	SYSTEM	\$1,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					7	Oct 1, 2024	SYSTEM	(\$1,120.00)	
					8	Oct 16, 2024	SYSTEM	\$1,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Oct 16, 2024	SYSTEM	(\$1,120.00)	
					9	Nov 4, 2024	SYSTEM	\$2,632.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Nov 4, 2024	SYSTEM	(\$2,632.00)	
					10	Nov 18, 2024	SYSTEM	\$2,632.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user fullerk2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Nov 18, 2024	SYSTEM	(\$2,632.00)	
					11	Dec 2, 2024	SYSTEM	\$4,256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					11	Dec 2, 2024	SYSTEM	(\$4,256.00)	
					12	Dec 16, 2024	SYSTEM	\$4,536.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					12	Dec 16, 2024	SYSTEM	(\$4,536.00)	
				- Total				\$0.00	
			Material - To					\$0.00	



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																				
J6S3417	0240 -	· Total						\$0.00																					
	0260	6 IN. CONCRETE MEDIAN STRIP	Material		8	Oct 16, 2024	SYSTEM	\$31,756.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 5 on the current Payment Estimate.																				
					8	Oct 16, 2024	SYSTEM	(\$31,756.16)																					
				- Total				\$0.00																					
			Material - Tot	tal				\$0.00																					
	0260 -	· Total						\$0.00																					
	0270	PAVED APPROACH, 8 IN.	Material		1	Jul 1, 2024	SYSTEM	\$25,153.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 3 on the current Payment Estimate.																				
					1	Jul 1, 2024	SYSTEM	(\$25,153.20)																					
					2	Jul 16, 2024	SYSTEM	\$37,444.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 5 on the current Payment Estimate.																				
						2	Jul 16, 2024	SYSTEM	(\$37,444.20)																				
							3	Aug 2, 2024	SYSTEM	\$68,176.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 5 on the current Payment Estimate.																		
														3	Aug 2, 2024	SYSTEM	(\$68,176.80)												
					4	Aug 16, 2024	SYSTEM	\$89,199.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 5 on the current Payment Estimate.																				
					4	Aug 16, 2024	SYSTEM	(\$89,199.00)																					
					5	Sep 3, 2024	SYSTEM	\$135,364.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Exception 11 on the current Payment Estimate.																				
					5	Sep 3, 2024	SYSTEM	(\$135,364.20)																					
					6	Sep 16, 2024	SYSTEM	\$173,542.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 9 on the current Payment Estimate.																				
						6	Sep 16, 2024	SYSTEM	(\$173,542.80)																				
						7	Oct 1, 2024	SYSTEM	\$202,918.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 4 on the current Payment Estimate.																			
					7	Oct 1, 2024	SYSTEM	(\$202,918.80)																					
							8	Oct 16, 2024	SYSTEM	\$202,918.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 6 on the current Payment Estimate.																		
					8	Oct 16, 2024	SYSTEM	(\$202,918.80)																					
					9	Nov 4, 2024	SYSTEM	\$230,173.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 6 on the current Payment Estimate.																				
								9	Nov 4, 2024	SYSTEM	(\$230,173.20)																		
																		10	Nov 18, 2024	SYSTEM	\$265,383.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user fullerk2 overridding Payment Estimate Exception 6 on the current Payment Estimate.							
																				1		10	Nov 18, 2024	SYSTEM	(\$265,383.60)				
																									11	Dec 2, 2024	SYSTEM	\$295,208.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
																					11	Dec 2, 2024	SYSTEM	(\$295,208.40)					
					12	Dec 16, 2024	SYSTEM	\$325,308.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment																				



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J6S3417	0270	PAVED APPROACH, 8	Material						Estimate Exception 5 on the current Payment Estimate.										
		IN.			12	Dec 16, 2024	SYSTEM	(\$325,308.60)											
				- Total				\$0.00											
	0270 -	Total	Material - Tot	al				\$0.00 \$0.00											
							0)/0==14												
	0280	CONCRETE SIDEWALK, 4 IN.	Material		3	Aug 2, 2024	SYSTEM	\$12,994.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 8 on the current Payment Estimate.										
					3	Aug 2, 2024	SYSTEM	(\$12,994.80)											
					4	Aug 16, 2024	SYSTEM	\$44,956.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 8 on the current Payment Estimate.										
					4	Aug 16, 2024	SYSTEM	(\$44,956.50)											
					5	Sep 3, 2024	SYSTEM	\$51,943.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 14 on the current Payment Estimate.										
					5	Sep 3, 2024	SYSTEM	(\$51,943.50)											
					6	Sep 16, 2024	SYSTEM	\$59,782.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 11 on the current Payment Estimate.										
						6	Sep 16, 2024	SYSTEM	(\$59,782.20)										
									7	Oct 1, 2024	SYSTEM	\$66,789.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user fullerk2 overridding Payment Estimate Exception 5 on the current Payment Estimate.						
					8	Oct 16, 2024	SYSTEM	\$66,789.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 7 on the current Payment Estimate.										
					8	Oct 16, 2024	SYSTEM	(\$66,789.60)											
					9	Nov 4, 2024	SYSTEM	\$72,134.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 9 on the current Payment Estimate.										
										9	Nov 4, 2024	SYSTEM	(\$72,134.40)						
															10	Nov 18, 2024	SYSTEM	\$75,638.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user fullerk2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					10	Nov 18, 2024	SYSTEM	(\$75,638.10)											
				- Total				\$0.00											
			Material - Tot	al				\$0.00											
	0280 -	Total						\$0.00											
	0300	MISC. CONCRETE	CRETE 1		1	Jul 1, 2024	SYSTEM	\$33,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 6 on the current Payment Estimate.										
				2 3	2					1	1	1	1	1	1	Jul 1, 2024	SYSTEM	(\$33,600.00)	
												2	Jul 16, 2024	SYSTEM	\$50,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
									Jul 16, 2024	SYSTEM	(\$50,400.00)								
						3	Aug 2, 2024	SYSTEM	\$98,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 9 on the current Payment Estimate.									
									3	Aug 2, 2024	SYSTEM	(\$98,400.00)							



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J6S3417	0300	MISC. CONCRETE	Material		4	Aug 16, 2024	SYSTEM	\$117,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 9 on the current Payment Estimate.					
					4	Aug 16, 2024	SYSTEM	(\$117,600.00)						
					5	Sep 3, 2024	SYSTEM	\$136,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user fullerk2 overridding Payment Estimate Exception 15 on the current Payment Estimate.					
					5	Sep 3, 2024	SYSTEM	(\$136,800.00)						
					6	Sep 16, 2024	SYSTEM	\$146,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user fullerk2 overridding Payment Estimate Exception 12 on the current Payment Estimate.					
					6	Sep 16, 2024	SYSTEM	(\$146,400.00)						
					7	Oct 1, 2024	SYSTEM	\$158,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user fullerk2 overridding Payment Estimate Exception 6 on the current Payment Estimate.					
					7	Oct 1, 2024	SYSTEM	(\$158,400.00)						
					8	Oct 16, 2024	SYSTEM	\$158,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user fullerk2 overridding Payment Estimate Exception 8 on the current Payment Estimate.					
					8	Oct 16, 2024	SYSTEM	(\$158,400.00)						
					9	Nov 4, 2024	SYSTEM	\$192,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user fullerk2 overridding Payment Estimate Exception 10 on the current Payment Estimate.					
					9	Nov 4, 2024	SYSTEM	(\$192,000.00)						
					10	Nov 18, 2024	SYSTEM	\$208,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Exception 10 on the current Payment Estimate.					
					10	Nov 18, 2024	SYSTEM	(\$208,800.00)						
					11	Dec 2, 2024	SYSTEM	\$218,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 8 on the current Payment Estimate.					
					11	Dec 2, 2024	SYSTEM	(\$218,400.00)						
										12	Dec 16, 2024	SYSTEM	\$247,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fullerk2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					12	Dec 16, 2024	SYSTEM	(\$247,200.00)						
				- Total				\$0.00						
	0000		Material - To	tal				\$0.00						
	0300 -	FURN. TYPE 2 ROCK DITCH LINER	Material		6	Sep 16, 2024	SYSTEM	\$0.00 \$603.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment Estimate.					
					6	Sep 16, 2024	SYSTEM	(\$603.00)						
				- Total				\$0.00						
			Material - To	tal				\$0.00						
	0370 -	Total						\$0.00						
	0400	SLOPE PROTECTION	Material		9	Nov 4, 2024	SYSTEM	\$515.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user fullerk2 overridding Payment Estimate Exception 11 on the current Payment Estimate.					
							9 Nov 4, 2024 SYSTEM (\$515.00)							
					10	Nov 18, 2024	SYSTEM	\$515.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user fullerk2 overridding Payment Estimate Exception 11 on the current Payment Estimate.					
					10	Nov 18,	SYSTEM	(\$515.00)						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
S3417	0400	SLOPE PROTECTION	Material			2024																	
		PROTECTION			11	Dec 2, 2024	SYSTEM	\$515.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 9 on the current Payment Estimate.														
					11	Dec 2, 2024	SYSTEM	(\$515.00)															
					12	Dec 16, 2024	SYSTEM	\$1,545.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fullerk2 overridding Payment Estimate Exception 9 on the current Payment Estimate.														
					12	Dec 16, 2024	SYSTEM	(\$1,545.00)															
				- Total				\$0.00															
			Material - To	tal				\$0.00															
	0400 -	Total						\$0.00															
	0480	FRAME AND COVER, TYPE	Material		5	Sep 3, 2024	SYSTEM	\$588.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment Estimate.														
		1-B			5	Sep 3, 2024	SYSTEM	(\$588.00)															
					6	Sep 16, 2024	SYSTEM	\$588.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Exception 14 on the current Payment Estimate.														
					6	Sep 16, 2024	SYSTEM	(\$588.00)															
					7	Oct 1, 2024	SYSTEM	\$588.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user fullerk2 overridding Payment Estimate Exception 7 on the current Payment Estimate.														
									7	Oct 1, 2024	SYSTEM	(\$588.00)											
					8	Oct 16, 2024	SYSTEM	\$1,176.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user fullerk2 overridding Payment Estimate Exception 9 on the current Payment Estimate.														
					8	Oct 16, 2024	SYSTEM	(\$1,176.00)															
					9	Nov 4, 2024	SYSTEM	\$1,176.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Exception 12 on the current Payment Estimate.														
							9	Nov 4, 2024	SYSTEM	(\$1,176.00)													
						10	Nov 18, 2024	SYSTEM	\$1,176.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment Estimate Exception 12 on the current Payment Estimate.													
					10	Nov 18, 2024	SYSTEM	(\$1,176.00)															
																			11	Dec 2, 2024	SYSTEM	\$1,176.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
							11	Dec 2, 2024	SYSTEM	(\$1,176.00)													
									12	Dec 16, 2024	SYSTEM	\$1,176.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fullerk2 overridding Payment Estimate Exception 10 on the current Payment Estimate.										
					12	Dec 16, 2024	SYSTEM	(\$1,176.00)															
				- Total				\$0.00															
			Material - To	tal				\$0.00															
	0480 -							\$0.00															
	0890	12 IN. PIPE GROUP A	Material		5	Sep 3, 2024	SYSTEM	\$91,630.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate.														
					5	Sep 3, 2024	SYSTEM	(\$91,630.00)															
					6	Sep 16, 2024	SYSTEM	\$91,630.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user fullerk2 overridding Payment Estimate Exception 15 on the current Payment Estimate.														





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J6S3417	0890	12 IN. PIPE GROUP A	Material		6	Sep 16, 2024	SYSTEM	(\$91,630.00)												
					7	Oct 1, 2024	SYSTEM	\$91,630.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 8 on the current Payment Estimate.											
					7	Oct 1, 2024	SYSTEM	(\$91,630.00)												
					8	Oct 16, 2024	SYSTEM	\$91,630.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Exception 10 on the current Payment Estimate.											
					8	Oct 16, 2024	SYSTEM	(\$91,630.00)												
					9	Nov 4, 2024	SYSTEM	\$91,630.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment Estimate.											
					9	Nov 4, 2024	SYSTEM	(\$91,630.00)												
					10	Nov 18, 2024	SYSTEM	\$91,630.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment Estimate.											
					10	Nov 18, 2024	SYSTEM	(\$91,630.00)												
				- Total				\$0.00												
			Material - To	tal				\$0.00												
	0890 -							\$0.00												
	0900	15 IN. PIPE GROUP A	Material		5	Sep 3, 2024	SYSTEM	\$20,554.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate.											
					5	Sep 3, 2024	SYSTEM	(\$20,554.00)												
					6	Sep 16, 2024	SYSTEM	\$20,554.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment Estimate.											
					6	Sep 16, 2024	SYSTEM	(\$20,554.00)												
					7	Oct 1, 2024	SYSTEM	\$20,554.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 9 on the current Payment Estimate.											
					7	Oct 1, 2024	SYSTEM	(\$20,554.00)												
																8	Oct 16, 2024	SYSTEM	\$20,554.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user fullerk2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					8	Oct 16, 2024	SYSTEM	(\$20,554.00)												
						9	Nov 4, 2024	SYSTEM	\$20,554.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment Estimate Exception 14 on the current Payment Estimate.										
					9	Nov 4, 2024	SYSTEM	(\$20,554.00)												
										10	Nov 18, 2024	SYSTEM	\$20,554.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 14 on the current Payment Estimate.						
					10	Nov 18, 2024	SYSTEM	(\$20,554.00)												
				- Total				\$0.00												
			Material - To	tal				\$0.00												
	0900 -		B4-4 : 1		-	0- 6	OVOTE	\$0.00	This allower was the state of t											
	0910	18 IN. PIPE GROUP A	Material		5	Sep 3, 2024	SYSTEM	\$396.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment Estimate Exception 20 on the current Payment Estimate.											
					5	Sep 3, 2024	SYSTEM	(\$396.00)												
					6	Sep 16, 2024	SYSTEM	\$396.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment											



Line Item Adjustments by Estimate

Type Adjustment Type Date By Type																			
18 18 18 18 18 18 18 18	Project	Line	Description	Adjustment Type		Est. Number	Created Date	Created By	Amount	Remarks									
CIRCUPA	S3417	0910	18 IN PIPE	Material	- 71-					Estimate Exception 17 on the current Payment Estimate									
7						6		SYSTEM	(\$396.00)										
2004 8						7		SYSTEM	\$396.00	Estimate Item Adjustment (0003) due to user fullerk2 overridding Payment									
						7		SYSTEM	(\$396.00)										
2024 2024						8		SYSTEM	\$396.00	Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment									
2024 SYSTEM S368.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate Extended Exception 15 on the current Payment Estimate Exception 1						8		SYSTEM	(\$396.00)										
10						9		SYSTEM	\$396.00	Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment									
2024 Estimate Exemption 15 on the current Payment Estimate.						9		SYSTEM	(\$396.00)										
2024 So.00						10		SYSTEM	\$396.00	Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment									
						10		SYSTEM	(\$396.00)										
					- Total				\$0.00										
				Material - To	tal				\$0.00										
2024 Estimate (tem Adjustment (0004) due to user fullerk2 overridding Payment Estimate Exception 11 on the current Payment Estimate Estimate Exception 11 on the current Payment Estimate Estimate Exception 11 on the current Payment Estimate Estimate Exception 13 on the current Payment Estimate Estimate Estimate Exception 13 on the current Payment Estimate Estimate Exception 13 on the current Payment Estimate Estimate Exception 13 on the current Payment Estimate Exception 16 on the current Payment Estimate Exception 17 on the current Payment Estimate Exception 18 on the current Payment Estimate Exception 18 on the current Payment Estimate Ex		0910 -	Total						\$0.00										
2024 8		0950	A FLARED END	Material		7		SYSTEM	\$6,960.00	Estimate Item Adjustment (0004) due to user fullerk2 overridding Payment									
2024 Stimate Item Adjustment (0014) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment Estimate.						7		SYSTEM	(\$6,960.00)										
10						8		SYSTEM	\$6,960.00	Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment									
2024 Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment Estimate.						8		SYSTEM	(\$6,960.00)										
10						9		SYSTEM	\$6,960.00	Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment									
Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment Estimate. 10 Nov 18, 2024 **Total*** **Su.00 **Material - Total** **Su.00 **Description** **Su.00 **Su.00 **Description** **Su.00 **Description** **Su.00 **Su.00 **Description** **Su.00 **Su.00 **Description** **Su.00 **Description** **Su.00 **Description** **Su.00 **Description** **Su.00 **Description** **Description** **Su.00 **Description** *						9		SYSTEM	(\$6,960.00)										
Total \$0.00						10		SYSTEM	\$6,960.00	Estimate Item Adjustment (0005) due to user fullerk2 overridding Payment									
Solution						10		SYSTEM	(\$6,960.00)										
\$0.00 24 IN. GROUP A FLARED END SECT Material 5 Sep 3, 2024 5 Sep 3, 2024 6 Sep 16, 2024 7 Oct 1, 2024 \$1,800.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 21 on the current Payment Estimate. \$1,800.00 This adjustment (0014) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate Exception 12 on the current Payment Estimate.				Matorial Te															
Description of the control of the co		0950	Total	material - 10	tal														
5 Sep 3, 2024 (\$1,800.00) 6 Sep 16, 2024 \$1,800.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate. 6 Sep 16, 2024 (\$1,800.00) 7 Oct 1, 2024 \$1,800.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Exception 12 on the current Payment Estimate. 7 Oct 1, SYSTEM (\$1,800.00)			24 IN. GROUP A FLARED END	Material		5		SYSTEM		Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment									
6 Sep 16, 2024 \$1,800.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate. 6 Sep 16, 2024 \$1,800.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Exception 12 on the current Payment Estimate. 7 Oct 1, SYSTEM \$1,800.00						5		SYSTEM	(\$1,800.00)										
7 Oct 1, 2024 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Exception 12 on the current Payment Estimate. Oct 1, SYSTEM (\$1,800.00)						6		SYSTEM	\$1,800.00	Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment									
2024 Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Exception 12 on the current Payment Estimate. 7 Oct 1, SYSTEM (\$1,800.00)													•	6	6		SYSTEM	(\$1,800.00)	
					7		SYSTEM	\$1,800.00	Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment										
						7		SYSTEM	(\$1,800.00)										





Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
			Турс	Туре		Date			
J6S3417	0970	24 IN. GROUP A FLARED END SECT	Material		8	Oct 16, 2024	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					8	Oct 16, 2024	SYSTEM	(\$1,800.00)	
					9	Nov 4, 2024	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					9	Nov 4, 2024	SYSTEM	(\$1,800.00)	
					10	Nov 18, 2024	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					10	Nov 18, 2024	SYSTEM	(\$1,800.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0970 -	· Total						\$0.00	
	0990	TURF TYPE TALL FESCUE SODDING	Material		8	Oct 16, 2024	SYSTEM	\$39,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user fullerk2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					8	Oct 16, 2024	SYSTEM	(\$39,780.00)	
					9	Nov 4, 2024	SYSTEM	\$39,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					9	Nov 4, 2024	SYSTEM	(\$39,780.00)	
					10	Nov 18, 2024	SYSTEM	\$39,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					10	Nov 18, 2024	SYSTEM	(\$39,780.00)	
					11	Dec 2, 2024	SYSTEM	\$39,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user fullerk2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					11	Dec 2, 2024	SYSTEM	(\$39,780.00)	
					12	Dec 16, 2024	SYSTEM	\$39,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user fullerk2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					12	Dec 16, 2024	SYSTEM	(\$39,780.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0990 -	Total						\$0.00	
	1030	ALTERNATE DITCH CHECK	Material		8	Oct 16, 2024	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					8	Oct 16, 2024	SYSTEM	(\$1,440.00)	
					9	Nov 4, 2024	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					9	Nov 4, 2024	SYSTEM	(\$1,440.00)	
					10	Nov 18, 2024	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					10	Nov 18, 2024	SYSTEM	(\$1,440.00)	
					11	Dec 2, 2024	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user fullerk2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					11	Dec 2,	SYSTEM	(\$1,440.00)	



6S3417		Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																								
	1030	ALTERNATE	Material	Туре		2024																											
		DITCH CHECK			12	Dec 16, 2024	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user fullerk2 overridding Payment Estimate Exception 12 on the current Payment Estimate.																								
					12	Dec 16, 2024	SYSTEM	(\$1,440.00)																									
				- Total				\$0.00																									
			Material - To	tal				\$0.00																									
	1030 -	· Total						\$0.00																									
	1040	CURB INLET CHECK	Material		8	Oct 16, 2024	SYSTEM	\$160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate.																								
					8	Oct 16, 2024	SYSTEM	(\$160.00)																									
					9	Nov 4, 2024	SYSTEM	\$160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user fullerk2 overridding Payment Estimate Exception 20 on the current Payment Estimate.																								
					9	Nov 4, 2024	SYSTEM	(\$160.00)																									
					10	Nov 18, 2024	SYSTEM	\$160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user fullerk2 overridding Payment Estimate Exception 20 on the current Payment Estimate.																								
					10	Nov 18, 2024	SYSTEM	(\$160.00)																									
					11	Dec 2, 2024	SYSTEM	\$160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment Estimate.																								
					11	Dec 2, 2024	SYSTEM	(\$160.00)																									
					12	Dec 16, 2024	SYSTEM	\$160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user fullerk2 overridding Payment Estimate Exception 13 on the current Payment Estimate.																								
					12	Dec 16, 2024	SYSTEM	(\$160.00)																									
				- Total				\$0.00																									
			Material - To	tal				\$0.00																									
	1040 -	Total						\$0.00																									
	1100	CONDUIT, 3 IN. RIGID, IN TRENCH	Material		9	Nov 4, 2024	SYSTEM	\$2,235.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate.																								
					9	Nov 4, 2024	SYSTEM	(\$2,235.00)																									
																													10	Nov 18,	SYSTEM	\$7,575.00	
																										2024		* ',- ' - ' - '	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate.				
					10	Nov 18, 2024	SYSTEM	(\$7,575.00)	Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment																								
				- Total	10	Nov 18,	SYSTEM		Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment																								
			Material - To		10	Nov 18,	SYSTEM	(\$7,575.00)	Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment																								
	1100 -	Total	Material - To		10	Nov 18,	SYSTEM	(\$7,575.00) \$0.00	Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment																								
	1100 - 1150	PULL BOX, PREFORMED CLASS 1	Material - To		9	Nov 18,	SYSTEM	(\$7,575.00) \$0.00 \$0.00	Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment																								
		PULL BOX, PREFORMED				Nov 18, 2024		(\$7,575.00) \$0.00 \$0.00	Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user fullerk2 overridding Payment																								
		PULL BOX, PREFORMED			9	Nov 18, 2024 Nov 4, 2024 Nov 4,	SYSTEM	(\$7,575.00) \$0.00 \$0.00 \$0.00 \$3,306.78	Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user fullerk2 overridding Payment																								
		PULL BOX, PREFORMED			9	Nov 18, 2024 Nov 4, 2024 Nov 4, 2024 Nov 18,	SYSTEM	(\$7,575.00) \$0.00 \$0.00 \$0.00 \$3,306.78	Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user fullerk2 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user fullerk2 overridding Payment Estimate Item Adjustment (0019) due to user fullerk2 overridding Payment																								
		PULL BOX, PREFORMED			9 9 10	Nov 18, 2024 Nov 4, 2024 Nov 18, 2024 Nov 18,	SYSTEM SYSTEM	(\$7,575.00) \$0.00 \$0.00 \$0.00 \$3,306.78 (\$3,306.78) \$4,960.17	Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user fullerk2 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user fullerk2 overridding Payment Estimate Item Adjustment (0019) due to user fullerk2 overridding Payment																								
		PULL BOX, PREFORMED		tal - Total	9 9 10	Nov 18, 2024 Nov 4, 2024 Nov 18, 2024 Nov 18,	SYSTEM SYSTEM	(\$7,575.00) \$0.00 \$0.00 \$3,306.78 (\$3,306.78) \$4,960.17	Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user fullerk2 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user fullerk2 overridding Payment Estimate Item Adjustment (0019) due to user fullerk2 overridding Payment																								



Miles	Drainet	Lina	Description	A dissature a mt	Other	Fot	Created	Created	Amazunt	Damanka							
CONDUCTIONS BRACKE	Project	Line	Description	Adjustment Type		Est. Number	Created Date	Created By	Amount	Remarks							
10 Nov 4, SYSTEM (\$10.00) The agreement officials the righted system-generated Material Payment Editinate Internal Payment Internal	J6S3417	1170	AWG 1 CONDUCTOR,	Material		10		SYSTEM	\$192.60	Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment							
2024 Catholic Coveration Fragment Estimate Encoylon 1 on the current Pyrament Estimate (Estimate Encoylon 1 on the current Pyrament Estimate (Estimate Encoylon 1 on the Catholic Purpose)						10		SYSTEM	(\$192.60)								
12						11		SYSTEM	\$192.60	Estimate Item Adjustment (0012) due to user fullerk2 overridding Payment							
2024 12 De 16, SYSTEM (\$19.00)						11		SYSTEM	(\$192.60)								
1100 CABLE CONDUCTORS Material Total S0.00						12		SYSTEM	\$192.60	Estimate Item Adjustment (0012) due to user fullerk2 overridding Payment							
Material - Total						12		SYSTEM	(\$192.60)								
1170 - Total					- Total				\$0.00								
180				Material - To	tal				\$0.00								
CONDUCTORS		1170 -	Total						\$0.00								
9		1180	CONDUIT, 1 IN., 2	Material		9		SYSTEM	\$518.52	Estimate Item Adjustment (0022) due to user fullerk2 overridding Payment							
2024 Stimate Item Adjustment (0021) due to user fuller/2 overridding Fayment Estimate Item Adjustment (0021) due to user fuller/2 overridding Fayment Estimate Item Adjustment (0713) due to user fuller/2 overridding Payment Estimate Item Adjustment (0713) due to user fuller/2 overridding Payment Estimate Item Adjustment (0713) due to user fuller/2 overridding Payment Estimate Item Adjustment (0713) due to user fuller/2 overridding Payment Estimate Item Adjustment (0713) due to user fuller/2 overridding Payment Item Adjustment (0713) due to user fuller/2 overridding Payment Item Adjustment (0713) due to user fuller/2 overridding Payment Item Adjustment (0713) due to user fuller/2 overridding Payment Item Adjustment (0713) due to user fuller/2 overridding Payment Item Adjustment (0713) due to user fuller/2 overridding Payment Item Adjustment (0713) due to user fuller/2 overridding Payment Item Adjustment (0713) due to user fuller/2 overridding Payment Item Adjustment (0713) due to user fuller/2 overridding Payment Item Adjustment (0713) due to user fuller/2 overridding Payment Item Adjustment (0713) due to user fuller/2 overridding Payment Item Adjustment (0713) due to user fuller/2 overridding Payment Item Adjustment (0713) due to user fuller/2 overridding Payment Item Adjustment (0713) due to user fuller/2 overridding Payment Item Adjustment generated Stockpile Transaction Stockpile			CONDUCTORS			9		SYSTEM	(\$518.52)								
11						10		SYSTEM	\$1,799.16	Estimate Item Adjustment (0021) due to user fullerk2 overridding Payment							
2024 2024 Estimate Item Adjustment (0013) due to user fuller/2 overridding Payment Estimate Exception 15 on the current Payment Estimate Exception 15 on the current Payment Estimate Exception 15 on the current Payment Estimate Exception 15 on the current Payment Estimate Item Adjustment (0013) due to user fuller/2 overridding Payment 2024 20						10		SYSTEM	(\$1,799.16)								
2024 12 Dec 16, SYSTEM 21,799.16 Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment Estimate Exception 15 on the current Payment Estimate.								11		SYSTEM	\$1,799.16	Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment					
2024 Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment Estimate Exception 15 on the current Payment Estimate.													11		SYSTEM	(\$1,799.16)	
180 - Total												12		SYSTEM	\$1,799.16	Estimate Item Adjustment (0013) due to user fullerk2 overridding Payment	
Solution Stockpile State						12		SYSTEM	(\$1,799.16)								
1580 BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE) Construction Stockpile STMI -Total S4,892.50					- Total				\$0.00								
Secondary Seco				Material - To	tal				\$0.00								
ASSEMBLY (PERFORATED SQUARE STEL TUBE) SQUARE STEL TUBE) Construction Stockpile STMI - Total		1180 -	Total						\$0.00								
SQUARE STEEL TUBE Construction Stockpile STMI - Total 5546.00 1580 - Total 2 IN. PSST POST - 12 GA. 8 Oct 16, 2024 9 Nov 4, 2024 - Total Construction Stockpile - Total Aug 16, 2024 SYSTEM \$4,892.50 Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction STMI - Total Aug 16, 2024 SYSTEM \$4,892.50 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate. 8 Oct 16, 2024 SYSTEM (\$2,495.95)		1580	ASSEMBLY	Stockpile		4		SYSTEM	\$546.00	Payment Estimate Item Adjustment generated Stockpile Transaction							
Solution Stockpile Stiml - Total System			SQUARE	OTIVII	- Total				\$546.00								
2 IN. PSST POST - 12 GA. Stockpile B			STEEL TUBE)	Construction	Stockpile S	ΓΜΙ - Total			\$546.00								
POST - 12 GA. Stockpile 2024 9 Nov 4, 2024 SYSTEM (\$1,011.97) Payment Estimate Item Adjustment generated Stockpile Transaction - Total (\$1,936.40) Construction Stockpile - Total (\$1,936.40) Construction Stockpile STMI - Total \$4,892.50 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total \$4,892.50 Payment Estimate Item Adjustment generated Stockpile Transaction Material 8 Oct 16, 2024 \$4,892.50 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate. 8 Oct 16, 2024 \$4,895.95 (\$2,495.95)		1580 -	Total						\$546.00								
- Total (\$1,936.40) Construction Stockpile - Total (\$1,936.40) Construction Stockpile - Total (\$1,936.40) Construction Stockpile STMI - Total \$4,892.50 Construction Stockpile STMI - Total \$4,892.50 Construction Stockpile STMI - Total \$4,892.50 Material 8 Oct 16, 2024 SYSTEM \$2,495.95 Backpile STMI - Total Stockpile STMI - Total Stockpile Transaction Stockpile Transaction Stockpile Transaction Stockpile STMI - Total Standard Stockpile Transaction Stock		1590				8		SYSTEM	(\$924.43)	Payment Estimate Item Adjustment generated Stockpile Transaction							
Construction Stockpile - Total Construction Stockpile STMI - Total *Aug 16, 2024 \$YSTEM \$4,892.50 Payment Estimate Item Adjustment generated Stockpile Transaction \$4,892.50 Construction Stockpile STMI - Total \$4,892.50 Material *Aug 16, 2024 \$4,892.50 *Aug 16, 2024						9		SYSTEM	(\$1,011.97)	Payment Estimate Item Adjustment generated Stockpile Transaction							
Construction Stockpile STMI - Total S4,892.50 Construction Stockpile STMI - Total 8 Oct 16, 2024					- Total				(\$1,936.40)								
Stockpile STMI - Total \$4,892.50 Construction Stockpile STMI - Total \$4,892.50 Material 8 Oct 16, 2024 \$2,495.95 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate. 8 Oct 16, 2024 \$2,495.95 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate.				Construction	Stockpile - 1	Total .			(\$1,936.40)								
- Total \$4,892.50 Construction Stockpile STMI - Total \$4,892.50 Material 8 Oct 16, 2024 \$2,495.95 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate. 8 Oct 16, 2024 \$YSTEM (\$2,495.95)						4		SYSTEM	\$4,892.50	Payment Estimate Item Adjustment generated Stockpile Transaction							
Material 8 Oct 16, 2024 \$2,495.95 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate. 8 Oct 16, 2024 \$2,495.95 This adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate.				STMI	- Total				\$4,892.5 <u>0</u>								
Material 8 Oct 16, 2024 \$2,495.95 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate. 8 Oct 16, 2024 \$2,495.95)				Construction	Stockpile S	ΓΜΙ - <u>Total</u>											
2024								Oct 16,	SYSTEM	· ·	Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment						
9 Nov 4, SYSTEM \$5,228.28 This adjustment offsets the original system-generated Material Payment					8		SYSTEM	(\$2,495.95)									
						9	Nov 4,	SYSTEM	\$5,228.28	This adjustment offsets the original system-generated Material Payment							



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	2	Boompaon	Туре	Adjustment Type		Date	Ву	, and and	, condition
J6S3417	1590	2 IN. PSST POST - 12 GA.	Material			2024			Estimate Item Adjustment (0002) due to user fullerk2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					9	Nov 4, 2024	SYSTEM	(\$5,228.28)	
					10	Nov 18, 2024	SYSTEM	\$5,228.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user fullerk2 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					10	Nov 18, 2024	SYSTEM	(\$5,228.28)	
					11	Dec 2, 2024	SYSTEM	\$5,228.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					11	Dec 2, 2024	SYSTEM	(\$5,228.28)	
					12	Dec 16, 2024	SYSTEM	\$5,228.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user fullerk2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					12	Dec 16, 2024	SYSTEM	(\$5,228.28)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1590 -	· Total						\$2,956.10	
	1600	DRIVEN POST ANCHOR FOR	Construction Stockpile		8	Oct 16, 2024	SYSTEM	(\$705.60)	Payment Estimate Item Adjustment generated Stockpile Transaction
		2 IN. PSST - 12 GA.			9	Nov 4, 2024	SYSTEM	(\$201.60)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$907.20)	
			Construction	Stockpile - 1	Γotal			(\$907.20)	
			Construction Stockpile		4	Aug 16, 2024	SYSTEM	\$2,721.60	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI						
				- Total				\$2,721.60	
			Construction	- Total o Stockpile S	ΓΜΙ - Total			\$2,721.60 \$2,721.60	
			Construction Material		ΓΜΙ - Total 8	Oct 16, 2024	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
						Oct 16,	SYSTEM	\$2,721.60	Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment
					8	Oct 16, 2024		\$2,721.60 \$1,871.59	Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment
					8	Oct 16, 2024 Oct 16, 2024 Nov 4,	SYSTEM	\$2,721.60 \$1,871.59 (\$1,871.59)	Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment
					8 8 9	Oct 16, 2024 Oct 16, 2024 Nov 4, 2024 Nov 4,	SYSTEM	\$2,721.60 \$1,871.59 (\$1,871.59) \$2,406.33 (\$2,406.33)	Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment
					8 8 9	Oct 16, 2024 Oct 16, 2024 Nov 4, 2024 Nov 4, 2024 Nov 18,	SYSTEM SYSTEM	\$2,721.60 \$1,871.59 (\$1,871.59) \$2,406.33 (\$2,406.33)	Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment
					8 8 9 9	Oct 16, 2024 Oct 16, 2024 Nov 4, 2024 Nov 4, 2024 Nov 18, 2024 Nov 18, 18, 2024	SYSTEM SYSTEM SYSTEM SYSTEM	\$2,721.60 \$1,871.59 (\$1,871.59) \$2,406.33 (\$2,406.33) \$2,406.33	Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment
					8 8 9 9 10	Oct 16, 2024 Oct 16, 2024 Nov 4, 2024 Nov 18, 2024 Nov 18, 2024 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$2,721.60 \$1,871.59 (\$1,871.59) \$2,406.33 (\$2,406.33) \$2,406.33	Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment
					8 9 9 10 10	Oct 16, 2024 Oct 16, 2024 Nov 4, 2024 Nov 18, 2024 Nov 18, 2024 Dec 2, 2024 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,721.60 \$1,871.59 (\$1,871.59) \$2,406.33 (\$2,406.33) \$2,406.33 (\$2,406.33)	Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment
					8 8 9 9 10 10 11	Oct 16, 2024 Oct 16, 2024 Nov 4, 2024 Nov 18, 2024 Nov 18, 2024 Dec 2, 2024 Dec 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,721.60 \$1,871.59 (\$1,871.59) \$2,406.33 (\$2,406.33) \$2,406.33 (\$2,406.33)	Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate.
					8 8 9 10 10 11 11 11	Oct 16, 2024 Oct 16, 2024 Nov 4, 2024 Nov 18, 2024 Nov 18, 2024 Dec 2, 2024 Dec 16, 2024 Dec 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,721.60 \$1,871.59 (\$1,871.59) \$2,406.33 (\$2,406.33) \$2,406.33 (\$2,406.33) \$2,406.33 (\$2,406.33)	Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate.
				n Stockpile S	8 8 9 10 10 11 11 11	Oct 16, 2024 Oct 16, 2024 Nov 4, 2024 Nov 18, 2024 Nov 18, 2024 Dec 2, 2024 Dec 16, 2024 Dec 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,721.60 \$1,871.59 (\$1,871.59) \$2,406.33 (\$2,406.33) \$2,406.33 (\$2,406.33) \$2,406.33 (\$2,406.33)	Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate.
	1600 -	·Total	Material	n Stockpile S	8 8 9 10 10 11 11 11	Oct 16, 2024 Oct 16, 2024 Nov 4, 2024 Nov 18, 2024 Nov 18, 2024 Dec 2, 2024 Dec 16, 2024 Dec 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,721.60 \$1,871.59 (\$1,871.59) \$2,406.33 (\$2,406.33) \$2,406.33 (\$2,406.33) \$2,406.33 (\$2,406.33) \$2,406.33 (\$2,406.33)	Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate.
	1600 - 1610	Total 2.25 IN, PSST POST INSERT (6 FT.) - 12 GA.	Material	n Stockpile S	8 8 9 10 10 11 11 11	Oct 16, 2024 Oct 16, 2024 Nov 4, 2024 Nov 18, 2024 Nov 18, 2024 Dec 2, 2024 Dec 16, 2024 Dec 16, 2024	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,721.60 \$1,871.59 (\$1,871.59) \$2,406.33 (\$2,406.33) \$2,406.33 (\$2,406.33) \$2,406.33 (\$2,406.33) \$2,406.33 (\$2,406.33)	Estimate Item Adjustment (0020) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 25 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user fullerk2 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J6S3417	1610	2.25 IN. PSST POST INSERT (6 FT.) - 12 GA.	Construction	Stockpile S	ГМI - Total			\$124.32											
	1610 -	Total						\$124.32											
	1620	CONCRETE POST ANCHOR FOR 2 IN.	Construction Stockpile		9	Nov 4, 2024	SYSTEM	(\$862.40)	Payment Estimate Item Adjustment generated Stockpile Transaction										
		PSST 7 GA.		- Total				(\$862.40)											
			Construction	Stockpile - 1	Total			(\$862.40)											
			Construction Stockpile STMI		4	Aug 16, 2024	SYSTEM	\$1,411.20	Payment Estimate Item Adjustment generated Stockpile Transaction										
			0.1111	- Total				\$1,411.20											
			Construction	Stockpile S	MI - Total			\$1,411.20											
			Material		9	Nov 4, 2024	SYSTEM	\$7,058.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user fullerk2 overridding Payment Estimate Exception 26 on the current Payment Estimate.										
					9	Nov 4, 2024	SYSTEM	(\$7,058.48)											
					10	Nov 18, 2024	SYSTEM	\$7,058.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user fullerk2 overridding Payment Estimate Exception 27 on the current Payment Estimate.										
					10	Nov 18, 2024	SYSTEM	(\$7,058.48)											
						11	Dec 2, 2024	SYSTEM	\$7,058.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate.									
					11	Dec 2, 2024	SYSTEM	(\$7,058.48)											
					12	Dec 16, 2024	SYSTEM	\$7,058.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user fullerk2 overridding Payment Estimate Exception 18 on the current Payment Estimate.										
					12	Dec 16, 2024	SYSTEM	(\$7,058.48)											
				- Total				\$0.00											
			Material - Tot	otal				\$0.00											
	1620 -	Total						\$548.80											
	1630	2.5 IN. PSST POST - 12 GA.	Construction Stockpile		8	Oct 16, 2024	SYSTEM	(\$711.38)	Payment Estimate Item Adjustment generated Stockpile Transaction										
				- Total				(\$711.38)											
			Construction	Stockpile - 1	「otal			(\$711.38)											
			Construction Stockpile STMI		4	Aug 16, 2024	SYSTEM	\$2,377.13	Payment Estimate Item Adjustment generated Stockpile Transaction										
			STIVII	- Total				\$2,377.13											
			Construction	Stockpile S	ΓΜΙ - Total			\$2,377.13											
			Material		8	Oct 16, 2024	SYSTEM	\$1,818.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user fullerk2 overridding Payment Estimate Exception 20 on the current Payment Estimate.										
					8	Oct 16, 2024	SYSTEM	(\$1,818.86)											
						9								9	Nov 4, 2024	SYSTEM	\$1,818.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user fullerk2 overridding Payment Estimate Exception 27 on the current Payment Estimate.	
								(9	Nov 4, 2024	SYSTEM	(\$1,818.86)		
							10	Nov 18, 2024	SYSTEM	\$1,818.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user fullerk2 overridding Payment Estimate Exception 28 on the current Payment Estimate.								
					10	Nov 18, 2024	SYSTEM	(\$1,818.86)											
															11	Dec 2, 2024	SYSTEM	\$1,818.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
SS3417	1630	2.5 IN. PSST POST - 12 GA.	Material	.,,,,	12	Dec 16, 2024	SYSTEM	\$1,818.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user fullerk2 overridding Payment Estimate Exception 19 on the current Payment Estimate.															
					12	Dec 16, 2024	SYSTEM	(\$1,818.86)																
				- Total				\$0.00																
			Material - Tot	tal				\$0.00																
	1630 -	Total						\$1,665.75																
	1640	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7	Construction Stockpile		8	Oct 16, 2024	SYSTEM	(\$481.04)	Payment Estimate Item Adjustment generated Stockpile Transaction															
		GA.		- Total				(\$481.04)																
			Construction	Stockpile - 1	Total			(\$481.04)																
			Construction Stockpile STMI		4	Aug 16, 2024	SYSTEM	\$1,563.38	Payment Estimate Item Adjustment generated Stockpile Transaction															
				- Total				\$1,563.38																
			Construction	Stockpile S				\$1,563.38																
			Material		8	Oct 16, 2024	SYSTEM	\$1,283.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate.															
					8	Oct 16, 2024	SYSTEM	(\$1,283.36)																
					9	Nov 4, 2024	SYSTEM	\$1,283.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user fullerk2 overridding Payment Estimate Exception 28 on the current Payment Estimate.															
					9	Nov 4, 2024	SYSTEM	(\$1,283.36)																
										10	Nov 18, 2024	SYSTEM	\$1,283.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user fullerk2 overridding Payment Estimate Exception 29 on the current Payment Estimate.										
									10	Nov 18, 2024	SYSTEM	(\$1,283.36)												
									11	Dec 2, 2024	SYSTEM	\$1,283.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 20 on the current Payment Estimate.											
																				11	Dec 2, 2024	SYSTEM	(\$1,283.36)	
															12	Dec 16, 2024	SYSTEM	\$1,283.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user fullerk2 overridding Payment Estimate Exception 20 on the current Payment Estimate.					
					12	Dec 16, 2024	SYSTEM	(\$1,283.36)																
				- Total				\$0.00																
			Material - Tot	tal				\$0.00																
	1640 -	Total						\$1,082.34																
	1650	SH-FLAT SHEET	Construction Stockpile		8	Oct 16, 2024	SYSTEM	(\$749.93)	Payment Estimate Item Adjustment generated Stockpile Transaction															
					9	Nov 4, 2024	SYSTEM	(\$817.73)	Payment Estimate Item Adjustment generated Stockpile Transaction															
				- Total				(\$1,567.66)																
			Construction	Stockpile - 1	Total			(\$1,567.66)																
			Construction Stockpile STMI		4	Aug 16, 2024	SYSTEM	\$3,732.30	Payment Estimate Item Adjustment generated Stockpile Transaction															
				- Total				\$3,732.30																
			Construction	Stockpile S	「MI - Total			\$3,732.30																
	1650 -	Total						\$2,164.64																
	1660	SHF-FLAT SHEET FLUORESCENT	Construction Stockpile		8	Oct 16, 2024	SYSTEM	(\$451.44)	Payment Estimate Item Adjustment generated Stockpile Transaction															
				- Total				(\$451.44)																
			Co	Construction S	Stockpile - 1				(\$451.44)															
			Construction		4	Aug 16,	SYSTEM	\$2,109.00	Payment Estimate Item Adjustment generated Stockpile Transaction															





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3417	1660	SHF-FLAT SHEET FLUORESCENT	Stockpile STMI			2024			
				- Total				\$2,109.00	
			Construction Stockpile STMI - Total					\$2,109.00	
	1660 - Total							\$1,657.56	
	1700	MISC. ITS	Material		12	Dec 16, 2024	SYSTEM	\$1,907.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					12	Dec 16, 2024	SYSTEM	(\$1,907.92)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	1700 -	0 - Total						\$0.00	
	5003	MISC. ITS	Material		9	Nov 4, 2024	SYSTEM	\$23,361.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user fullerk2 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					9	Nov 4, 2024	SYSTEM	(\$23,361.87)	
					10	Nov 18, 2024	SYSTEM	\$23,361.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					10	Nov 18, 2024	SYSTEM	(\$23,361.87)	
					11	Dec 2, 2024	SYSTEM	\$23,361.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					11	Dec 2, 2024	SYSTEM	(\$23,361.87)	
					12	Dec 16, 2024	SYSTEM	\$26,699.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user fullerk2 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					12	Dec 16, 2024	SYSTEM	(\$26,699.28)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5003 -	5003 - Total						\$0.00	
J6S3417 - Total								\$27,356.68	
Overall -	Overall - Total							\$27,356.68	

Contract Adjustments for Contract - 240419-F02

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 30 of 30