

#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 18, 2025

	Contract ID Prime Contrac	241018 ctor Coman	-C02 che Construction, Inc.	Pay Period S Pay Period E		August 2, 2025 August 15, 2025	Original Contract Amount Net Change Order Amount Current Contract Amount	\$3,779,953.8° \$242,869.38 \$4,022,823.19			
Approval Date								By User			
August 18, 2025			Generated and Ap	proved (and sho	ıld be	considered Draft)	at the Project Office Level by	frizzm			
August 18, 2025			Reviewed and Approve	ed (and should be	cons	sidered Draft) at th	e Resident Engineer Level by	sandis1			
August 20, 2025		ce Controllers Office Level by	ramses1								
Original Completion	on Date	Current Co	ompletion Date	Actual Comp	letion	Date	% of Current Contract Amount Complete				
December 1, 20	025	Decem	ber 1, 2025				69.79%				
	Cont	tract Informat	ional Dates				Milestones				
Date Description	Original Com	pletion Date	Current Completion	Date		No Milestones E	xist for Contract				
Acceptance Date											
Awarded Date	November 8,	2024	November 8, 2024								
Letting Date	October 18, 2	024	October 18, 2024								
Notice to Proceed Date	December 9,	2024	December 9, 2024								
Work Began Date											

Contract Total Pay For Estimate No. 12										
		This Estimate	Previous	To Date						
241018-C02										
	Total Posted Items Pay	\$89,016.93	\$2,718,581.02	\$2,807,597.95						
	Gross Item Adjustments	\$12,255.00	(\$10,805.82)	\$1,449.18						
	Incentive	\$0.00	\$0.00	\$0.00						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
	•		\$2,707,775.20	\$2,809,047.13						
<b>Contract Total Pa</b>	ayable This Estimate:	\$101,271.93								

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4P3468	0320	6207001	PAVEMENT MARKING REMOVAL	LF	\$0.530	36,905	\$19,559.65
	0330	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	LF	\$0.160	38,808	\$6,209.28
	0630	2161502	REMOVAL OF CONCRETE WEARING SURFACE	SQFT	\$4.000	7,125	\$28,500.00
	0830	2161502	REMOVAL OF CONCRETE WEARING SURFACE	SQFT	\$4.000	7,637	\$30,548.00
	5004	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$10.500	400	\$4,200.00

# Project J4P3468 - Total \$89,016.93 Overall - Total \$89,016.93

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjust	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3468	0080	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.	3,840	\$18.08	\$69,427.20
	0800	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-3,840	\$18.08	(\$69,427.20)
	0130	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.	3,840	\$84.01	\$322,598.40

Revision 5/29/2025 Page 1 of 17



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 18, 2025

Estimat	gress e Num 12	Contract ID ber Prime Contractor	241018-C02 Comanche Cons	truction, Inc.	Pay Period End August 15, 2025 Net	ginal Contract Change Order rent Contract /	Amount	\$3,779,953.81 \$242,869.38 \$4,022,823.19
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3468	0130	CONCRETE PAVEMENT ( IN. NON-REINFORCED 15 FT. JOINTS)				-3,840	\$84.01	(\$322,598.40)
	0760	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 5 or the current Payment Estimate.	792	\$207.00	\$163,944.00
	0760	LATEX MODIFIED CONCRETE WEARING SURFACE	Material			-792	\$207.00	(\$163,944.00)
	0800	DECK REPAIR WITH VOID TUBE REPLACEMENT	) Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 8 or the current Payment Estimate.	297	\$95.02	\$28,220.94
	0800	DECK REPAIR WITH VOID TUBE REPLACEMENT	) Material			-297	\$95.02	(\$28,220.94)
	0810	CLEANING AND EPOXY COATING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate.	2,162	\$2.26	\$4,886.12
	0810	CLEANING AND EPOXY COATING	Material			-2,162	\$2.26	(\$4,886.12)
	0940	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 7 or the current Payment Estimate.	849	\$207.00	\$175,743.00
	0940	LATEX MODIFIED CONCRETE WEARING SURFACE	Material			-849	\$207.00	(\$175,743.00)
	0940	LATEX MODIFIED CONCRETE WEARING SURFACE	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',207.00000 - 207.00000, 'is applied (if non-zero).	57	\$207.00	\$11,799.00
	0950	DIAMOND GRINDING	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',8.00000 - 8.00000, 'is applied (if non-zero).	57	\$8.00	\$456.00
	0980	DECK REPAIR WITH VOID TUBE REPLACEMENT	) Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.	560	\$95.02	\$53,211.20
	0980	DECK REPAIR WITH VOID TUBE REPLACEMENT	) Material			-560	\$95.02	(\$53,211.20)
	0990	CLEANING AND EPOXY COATING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 13 on the current Payment Estimate.	2,340	\$2.26	\$5,288.40
	0990	CLEANING AND EPOXY COATING	Material			-2,340	\$2.26	(\$5,288.40)
Total								\$12,255.00

Revision 5/29/2025 Page 2 of 17



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information											
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work							
J4P3468	FAS S303(69)	4 Bridge rehabilitations	I-435	CLAY	over Parvin Road and 48th Street							
Totals I	oy Job N	umbers										
J4P3468		ed Item Pay s Item Adjustme		Item Pay	This Estimate \$89,016.93 \$12,255.00 <b>\$101,271.93</b>	Previous \$2,718,581.02 (\$10,805.82) \$2,707,775.20	To Date \$2,807,597.95 \$1,449.18 \$2,809,047.13					
	Liquid	tive centive dated Damages · Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					

Revision 5/29/2025 Page 3 of 17



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4P3468, Item 3040504, Project Item Line Number 0080, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Project office staff to confer with KC Materials for resolution to the exception. frizzm 8/18/25	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3468, Item 3040504, Project Item Line Number 0080, Material Set 304050496, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Project office staff to confer with KC Materials for resolution to the exception. frizzm 8/18/25	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3468, Item 5021309, Project Item Line Number 0130, Material Set 502130996, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Project office staff to confer with KC Materials for resolution to the exception. frizzm 8/18/25	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3468, Item 5021309, Project Item Line Number 0130, Material Set 502130996, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Project office staff to confer with KC Materials for resolution to the exception. frizzm 8/18/25	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3468, Item 5052000, Project Item Line Number 0760, Material Set 505200096, Material 1054CXLE - Latex Emulsion Admixture @, Acceptance Action Generic 1054CXLE is insufficient.	Project office staff to confer with KC Materials for resolution to the exception. frizzm 8/18/25	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3468, Item 5052000, Project Item Line Number 0760, Material Set 505200096, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	Project office staff to confer with KC Materials for resolution to the exception. frizzm 8/18/25	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3468, Item 5052000, Project Item Line Number 0940, Material Set 505200096, Material 1054CXLE - Latex Emulsion Admixture @, Acceptance Action Generic 1054CXLE is insufficient.	Project office staff to confer with KC Materials for resolution to the exception. frizzm 8/18/25	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3468, Item 7040112, Project Item Line Number 0800, Material Set 704011296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Project office staff to confer with KC Materials for resolution to the exception. frizzm 8/18/25	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3468, Item 7040112, Project Item Line Number 0800, Material Set 704011296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Project office staff to confer with KC Materials for resolution to the exception. frizzm 8/18/25	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3468, Item 7040112, Project Item Line Number 0980, Material Set 704011296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Project office staff to confer with KC Materials for resolution to the exception. frizzm 8/18/25	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3468, Item 7040112, Project Item Line Number 0980, Material Set 704011296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Project office staff to confer with KC Materials for resolution to the exception. frizzm 8/18/25	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3468, Item 7040113, Project Item Line Number 0810, Material Set 704011396, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	Project office staff to confer with KC Materials for resolution to the exception. frizzm 8/18/25	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3468, Item 7040113, Project Item Line Number 0990, Material Set 704011396, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	Project office staff to confer with KC Materials for resolution to the exception. frizzm 8/18/25	frizzm	Overridden

Revision 5/29/2025 Page 4 of 17



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

9: Pos	sted Qua		d Values	s are base	d on Report Generated date and can differ from the post	ed amount	at tne tim	e the Estima	ate was	Generated.		
tract D	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
018-	J4P3468	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.50	\$221,759.02	\$110,879.5
!		0001	0020	2031000	CLASS A EXCAVATION	1,547.00	32.00	1,579.00	CUYD	651.00	\$42.54	\$27,693.5
		0001	0030	2036000	COMPACTING EMBANKMENT	1,547.00	32.00	1,579.00	CUYD	651.00	\$10.63	\$6,920.1
		0001	0040	2063000	CLASS 3 EXCAVATION	198.00	0.00	198.00	CUYD	198.00	\$10.63	\$2,104.7
		0001	0050	2063500	CULVERT CLEANOUT	1.00	0.00	1.00	EA	1.00	\$1,898.17	\$1,898.1
		0001	0060	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	18.00	0.00	18.00	100F	18.00	\$632.72	\$11,388.9
		0001	0070	2153000	SHAPING SLOPES, CLASS III	4.00	0.00	4.00	100F	0.00	\$1,063.40	\$0.0
		0001	0080	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	3,840.00	0.00	3,840.00	SQYD	3,840.00	\$18.08	\$69,427.2
		0001	0090	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	87.40	0.00	87.40	TONS	0.00	\$287.12	\$0.0
		0001	0100	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	1,741.90	356.62	2,098.52	TONS	2,098.52	\$103.15	\$216,462.3
		0001	0110	4030206	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP190C MIX)	2,763.40	128.92	2.892.32	TONS	2,892.32	\$124.95	\$361,395.3
		0001	0120	4071005	TACK COAT	3,585.00	0.00	3,585.00	GAL	2,121.00	\$3.46	\$7,338.6
		0001	0130	5021309	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT.	3,840.00	0.00	3,840.00	SQYD	3,840.00	\$84.01	\$322,598.4
			0100	0021000	JOINTS)	0,040.00	0.00	0,040.00	OQID	0,040.00	ψ04.01	ψ022,030
		0001	0140	6046012A	12 IN. SLOTTED DRAIN	261.00	0.00	261.00	LF	261.00	\$388.14	\$101,304.
		0001	0150	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	2.00	3.00	5.00	EA	4.00	\$5,848.69	\$23,394.7
		0001	0160	6122030	IMPACT ATTENUATOR (RELOCATION)	3.00	0.00	3.00	EA	0.00	\$797.55	\$0.0
		0001	0170	6161005	CONSTRUCTION SIGNS	1,193.00	142.43	1,335.43	SQFT	1,335.43	\$8.51	\$11,364.
		0001	0180	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$53.17	\$212.6
		0001	0190	6161025	CHANNELIZER (TRIM-LINE)	100.00	100.00	200.00	EA	200.00	\$79.75	\$15,950.0
		0001	0200	6161030	TYPE 3 MOVEABLE BARRICADE	8.00	4.00	12.00	EA	8.00	\$292.43	\$2,339.4
		0001	0210	6161033	DIRECTION INDICATOR BARRICADE	30.00	0.00	30.00	EA	30.00	\$106.34	\$3,190.2
		0001	0220	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	4.00	\$1.914.12	\$7,656.4
		0001	0230	6161070	TUBULAR MARKER	155.00	10.00	165.00	EA	165.00	\$186.09	\$30,704.8
		0001	0240	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	2.00	0.00	2.00	EA	2.00	\$9,570.58	\$19,141.
		0001	0250	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,900.00	1,347.00	3,247.00	LF	3,047.00	\$39.39	\$120,021.
		0001	0260	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	2,100.00	0.00	2,100.00	LF	0.00	\$7.66	\$0.
		0001	0270	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$266,952.23	\$266,952.
		0001	0280	6191000	PAVEMENT EDGE TREATMENT	3,688.00	0.00	3,688.00	LF	0.00	\$9.25	\$0.
		0001	0290	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	31,100.00	0.00	31,100.00	LF	0.00	\$0.28	\$0.
		0001	0300	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	20,600.00	0.00	20,600.00	LF	0.00	\$0.28	\$0.
		0001	0310	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,271.00	0.00	2,271.00	LF	0.00	\$0.53	\$0.
		0001	0320	6207001	PAVEMENT MARKING REMOVAL	141,099.00	0.00	141,099.00	LF	43,348.00	\$0.53	\$22,974.
		0001	0330	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	91,928.00	0.00	91,928.00	LF	79,689.00	\$0.16	\$12,750.
		0001	0340	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	17,926.00	2,133.00	20,059.00	SQYD	20,059.00	\$6.38	\$127,976.
		0001	0350	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	235.20	0.00	235.20	STA	0.00	\$26.28	\$0.
		0001	0360	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$4,253.59	\$4,253.
		0001	0370	7261012	12 IN. PIPE GROUP A	17.00	0.00	17.00	LF	17.00	\$69.12	\$1,175.
		0001	0380	7261018 7320612A	18 IN. PIPE GROUP A 12 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END	490.00 1.00	0.00	490.00 1.00	LF EA	490.00 1.00	\$74.44 \$1,520.66	\$36,475. \$1,520.
		0001	0400	7320618A	SECTION  18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END	2.00	0.00	2.00	EA	2.00	\$1,754.61	\$3,509.
		0001	0410	8025006	SECTION MULCHING	1.20	0.00	1.20	ACRE	0.00	\$1,701.44	\$0.
		0001	0420	8051000A	SEEDING - COOL SEASON GRASSES	1.20	0.00	1.20	ACRE	0.00	\$1,701.44	\$0.
		0001	0430	8061006	ALTERNATE DITCH CHECK	135.00	0.00	135.00	LF	135.00	\$30.31	\$4,091.
		0001	0440	8061019	SILT FENCE	40.00	0.00	40.00	LF	0.00	\$33.37	\$0.
		0010							LF			
		0010	0450 0460	6061069	MGS GUARDRAIL MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	225.00	0.00	225.00	EA	0.00	\$25.52 \$3,509.22	\$0. \$0.
		0010	0470	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$3,083.85	\$0.
		0010										
			0480	6064110	ANCHOR ASSEMBLY, GUARD CABLE 3-STRAND	1.00	0.00	1.00	EA	1.00	\$5,051.14	\$5,051
		0070			GUARD CABLE							\$0.
		0070										\$0.
			0510	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	15.00	0.00	15.00	CY	0.00	\$1,000.00	\$0.
			0490 0500 0510	6069902 5050004 5050004	MISC.REMOVE AND REINSTALL HIGH TENSION 3-STRAND GUARD CABLE SUPPLEMENTARY WEARING SURFACE MATERIAL SUPPLEMENTARY WEARING SURFACE MATERIAL	2.00 15.00 15.00	0.00 0.00 0.00	2.00 15.00 15.00	EA CY CY	0.00 0.00 0.00	\$5,051.14 \$1,000.00 \$1,000.00	
		0070										

Revision 5/29/2025 Page 5 of 17



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
241018-	J4P3468	0070	0530	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	12.00	0.00	12.00	CY	0.00	\$1,000.00	\$0.00
C02		0070	0540	7040104	HALF-SOLE REPAIR	1,200.00	0.00	1,200.00	SQFT	0.00	\$54.16	\$0.00
		0070	0550	7040104	HALF-SOLE REPAIR	1,200.00	-150.00	1,050.00	SQFT	1,050.00	\$54.16	\$56,868.00
		0070	0560	7040104	HALF-SOLE REPAIR	1,000.00	0.00	1,000.00	SQFT	0.00	\$54.16	\$0.00
		0070	0570	7040104	HALF-SOLE REPAIR	1,000.00	241.00	1,241.00	SQFT	1,241.00	\$54.16	\$67,212.56
		0072	0620	2161001	TOTAL SURFACE HYDRO DEMOLITION	792.00	0.00	792.00	SQYD	0.00	\$58.93	\$0.00
		0072	0630	2161502	REMOVAL OF CONCRETE WEARING SURFACE	7,125.00	0.00	7,125.00	SQFT	7,125.00	\$4.00	\$28,500.00
		0072	0640	2161503	REMOVAL OF EXISTING DECK REPAIR	200.00	0.00	200.00	SQFT	0.00	\$29.00	\$0.00
		0072	0650	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$3,000.00	\$0.00
		0072	0660	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	792.00	0.00	792.00	SQYD	0.00	\$207.00	\$0.00
		0072	0670	7031004	DIAMOND GRINDING	792.00	0.00	792.00	SQYD	0.00	\$8.00	\$0.00
		0072	0680	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	45.00	0.00	45.00	SQFT	0.00	\$201.31	\$0.00
		0072	0690	7040106	FULL DEPTH REPAIR	350.00	0.00	350.00	SQFT	0.00	\$55.00	\$0.00
		0072	0700	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	250.00	0.00	250.00	SQFT	0.00	\$95.02	\$0.00
		0072	0710	7040113	CLEANING AND EPOXY COATING	3,244.00	0.00	3,244.00	SQFT	0.00	\$2.26	\$0.00
		0073	0720	2161001	TOTAL SURFACE HYDRO DEMOLITION	792.00	0.00	792.00	SQYD	792.00	\$58.93	\$46,672.56
		0073	0730	2161502	REMOVAL OF CONCRETE WEARING SURFACE	7,125.00	0.00	7,125.00	SQFT	7,125.00	\$4.00	\$28,500.00
		0073	0740	2161503	REMOVAL OF EXISTING DECK REPAIR	1,180.00	0.00	1,180.00	SQFT	0.00	\$29.00	\$0.00
		0073	0750	2165500	REMOVAL OF CATHODIC PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,000.00	\$3,000.00
		0073	0760	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	792.00	0.00	792.00	SQYD	792.00	\$207.00	\$163,944.00
		0073	0770	7031004	DIAMOND GRINDING	792.00	0.00	792.00	SQYD	792.00	\$8.00	\$6,336.00
		0073	0780	7031004	SUBSTRUCTURE REPAIR (UNFORMED)	45.00	0.00	45.00	SQFT	0.00	\$201.31	\$0,330.00
		0073	0790		, ,	350.00	-350.00	0.00	SQFT	0.00		\$0.00
		0073		7040106	FULL DEPTH REPAIR  DECK REPAIR WITH VOID TUBE REPLACEMENT				SQFT		\$55.00	\$28,220.94
		0073	0800	7040112		250.00	47.00	297.00	SQFT	297.00	\$95.02	
		0074	0820	7040113	CLEANING AND EPOXY COATING	3,244.00	0.00	3,244.00	SQYD	2,162.00	\$2.26	\$4,886.12
		0074		2161001	TOTAL SURFACE HYDRO DEMOLITION	849.00	0.00	849.00		0.00	\$58.93	\$0.00
		0074	0830	2161502	REMOVAL OF CONCRETE WEARING SURFACE	7,637.00	0.00	7,637.00	SQFT	7,637.00	\$4.00	\$30,548.00
		0074	0840	2161503	REMOVAL OF EXISTING DECK REPAIR	850.00	0.00	850.00	SQFT	0.00	\$29.00	\$0.00
		0074	0850	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	792.00	57.00	849.00	SQYD	0.00	\$207.00	\$0.00
		0074	0860	7031004	DIAMOND GRINDING	792.00	57.00	849.00	SQYD	0.00	\$8.00	\$0.00
		0074	0870	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	15.00	0.00	15.00	SQFT	0.00	\$494.78	\$0.00
			0880	7040106	FULL DEPTH REPAIR	400.00	0.00	400.00	SQFT	0.00	\$55.00	\$0.00
		0074	0890	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	200.00	0.00	200.00	SQFT	0.00	\$95.02	\$0.00
		0074	0900	7040113	CLEANING AND EPOXY COATING	3,514.00	0.00	3,514.00	SQFT	0.00	\$2.26	\$0.00
		0075	0910	2161001	TOTAL SURFACE HYDRO DEMOLITION	849.00	0.00	849.00	SQYD	849.00	\$58.93	\$50,031.57
		0075	0920	2161502	REMOVAL OF CONCRETE WEARING SURFACE	7,637.00	0.00	7,637.00	SQFT	7,637.00	\$4.00	\$30,548.00
		0075	0930	2161503	REMOVAL OF EXISTING DECK REPAIR	550.00	0.00	550.00	SQFT	0.00	\$29.00	\$0.00
		0075	0940	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	792.00	57.00	849.00	SQYD	849.00	\$207.00	\$175,743.00
		0075	0950	7031004	DIAMOND GRINDING	792.00	57.00	849.00	SQYD	849.00	\$8.00	\$6,792.00
		0075	0960	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	15.00	0.00	15.00	SQFT	0.00	\$201.34	\$0.00
		0075	0970	7040106	FULL DEPTH REPAIR	400.00	-400.00	0.00	SQFT	0.00	\$55.00	\$0.00
		0075	0980	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	200.00	360.00	560.00	SQFT	560.00	\$95.02	\$53,211.20
		0075	0990	7040113	CLEANING AND EPOXY COATING	3,510.00	0.00	3,510.00	SQFT	2,340.00	\$2.26	\$5,288.40
		0001	5001	6161055	SEQUENTIAL FLASHING WARNING LIGHT	0.00	30.00	30.00	EA	30.00	\$199.50	\$5,985.00
		0010	5002	6069901	MISC.Misc. Guardrail	0.00	1.00	1.00	LS	0.87	\$24,262.70	\$21,108.55
		0001	5003	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	0.00	88.00	88.00	TONS	85.83	\$299.25	\$25,684.63
		0001	5004	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	0.00	800.00	800.00	SQYD	800.00	\$10.50	\$8,400.00
	Project J	4P3468 - To	otal Value	Posted to I	Date as of Report Generated Date							\$2,807,597.94
241018-C	02 Overal	I - Total Va	lue Poste	ed to Date as	of Report Generated Date							\$2,807,597.94

Revision 5/29/2025 Page 6 of 17



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4P3468

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0320	6207001	PAVEMENT MARKING REMOVAL	8/5/25	8/18/25	1	36,905.00	LF	Removals from phase 1, minus SB 48th and SB Parvin bridges and minus SY still in place beyond crossovers.	586+10		652+10		
0330	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	8/5/25	8/18/25	1	38,808.00	LF	NB temp pavement markings for phase two. (4) lines of SW including 158' of gore on SB 48th exit = 25,548' (2) lines of SY = 13,260'	586+10		652+10		
0630	2161502	REMOVAL OF CONCRETE WEARING SURFACE	8/7/25	8/18/25	1	7,125.00	SQFT	SB 48th St. bridge	596+90		598+31		
0830	2161502	REMOVAL OF CONCRETE WEARING SURFACE	8/7/25	8/18/25	1	7,637.00	SQFT	SB Parvin bridge	641+35		642+47		
5004	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	8/7/25	8/18/25	1	400.00	SQYD	bridge ends on SB 48th and SB Parvin	586+10		652+10		

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 6/5/2025 Page 7 of 17



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
68	0020	CLASS A EXCAVATION	Price FUEL	,,,	3	Apr 2, 2025	SYSTEM	(\$4.69)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
				- Total				(\$4.69)					
			Price FUEL	- Total				(\$4.69)					
	0020 -	Total						(\$4.69)					
	0800	TYPE 5 AGGREGATE	Material		3	Apr 2, 2025	SYSTEM	(\$69,427.20)					
		FOR BASE			3	Apr 2, 2025	SYSTEM	\$69,427.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					4	Apr 16, 2025	SYSTEM	(\$69,427.20)					
					4	Apr 16, 2025	SYSTEM	\$69,427.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					5	May 2, 2025	SYSTEM	(\$69,427.20)					
									5	May 2, 2025	SYSTEM	\$69,427.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	May 16, 2025	SYSTEM	(\$69,427.20)					
					6	May 16, 2025	SYSTEM	\$69,427.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					7	Jun 2, 2025	SYSTEM	(\$69,427.20)					
					7	Jun 2, 2025	SYSTEM	\$69,427.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user cockrz1 overridding Paymer Estimate Exception 1 on the current Payment Estimate.				
					8	Jun 16, 2025	SYSTEM	(\$69,427.20)					
					8	Jun 16, 2025	SYSTEM	\$69,427.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					9	Jun 30, 2025	SYSTEM	(\$69,427.20)					
					9	Jun 30, 2025	SYSTEM	\$69,427.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					10	Jul 16, 2025	SYSTEM	(\$69,427.20)					
					10	Jul 16, 2025	SYSTEM	\$69,427.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					11	Aug 4, 2025	SYSTEM	(\$69,427.20)					
					11	Aug 4, 2025	SYSTEM	\$69,427.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					12	Aug 18, 2025	SYSTEM	(\$69,427.20)					
					12	Aug 18, 2025	SYSTEM	\$69,427.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.				
				- Total				\$0.00					
		Material - To	otal				\$0.00						
	0080 -	Total						\$0.00					
	0100	ASPHALTIC CONCRETE	Other Item Adjustment	ACAD	2	Mar 17, 2025	frizzm	\$630.76	3/11 = 209.97, 3/12 = 202.68, 3/13 = 218.11				
		MIXTURE PG 70-22 (SP125C MIX)			3	Apr 2, 2025	frizzm	(\$1.20)	On Est. No. 2 the AC adjustment for Line No. 0100 on March 13 was show as 218.11. The correct adjustment for that date should have been 216.91. Leaving a difference of 1.20.				
				ACAD - Tot	al			\$629.56					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3468	0100	ASPHALTIC	Other Item	Adjustment -	Total			\$629.56	
		CONCRETE MIXTURE PG 70-22 (SP125C	Overrun	Overrun	2	Mar 17, 2025	SYSTEM	(\$37,197.95)	
		MIX)			3	Apr 2, 2025	SYSTEM	\$37,197.95	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',103.15000 - 103.15000, 'is applied (if non-zero).
				Overrun - To	otal			\$0.00	applied (if Hoti-zero).
			Overrun - T					\$0.00	
	0100 -	· Total						\$629.56	
	0110	ASPHALTIC CONCRETE	Other Item Adjustment	ACAD	2	Mar 17, 2025	frizzm	\$824.31	3/10 = 323.97, 3/11 = 279.14, 3/12 = 35.86, 3/13 = 185.34
		MIXTURE PG 64-22 (SP1		ACAD - Tota	al			\$824.31	
		,	Other Item	Adjustment -	t - Total			\$824.31	
			Overrun	Overrun	2	Mar 17, 2025	SYSTEM	(\$16,108.55)	
					3	Apr 2, 2025	SYSTEM	\$16,108.55	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',124.95000 - 124.95000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - T	- Total				\$0.00	
	0110 -	Total						\$824.31	
	0120	TACK COAT	Material		2	Mar 17, 2025	SYSTEM	(\$7,338.66)	
				3	2	Mar 17, 2025	SYSTEM	\$7,338.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Apr 2, 2025	SYSTEM	(\$7,338.66)	
					3	Apr 2, 2025	SYSTEM	\$7,338.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Apr 16, 2025	SYSTEM	(\$7,338.66)	
					4	Apr 16, 2025	SYSTEM	\$7,338.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	May 2, 2025	SYSTEM	(\$7,338.66)	
					5	May 2, 2025	SYSTEM	\$7,338.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	May 16, 2025	SYSTEM	(\$7,338.66)	
					6	May 16, 2025	SYSTEM	\$7,338.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.
					7	Jun 2, 2025	SYSTEM	(\$7,338.66)	
					7	Jun 2, 2025	SYSTEM	\$7,338.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user cockrz1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Jun 16, 2025	SYSTEM	(\$7,338.66)	
					8	Jun 16, 2025	SYSTEM	\$7,338.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Jun 30, 2025	SYSTEM	(\$7,338.66)	
					9	Jun 30, 2025	SYSTEM	\$7,338.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Jul 16, 2025	SYSTEM	(\$7,338.66)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
4P3468	0120	TACK COAT	Material		10	Jul 16, 2025	SYSTEM	\$7,338.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					11	Aug 4, 2025	SYSTEM	(\$7,338.66)			
					11	Aug 4, 2025	SYSTEM	\$7,338.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.		
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	0120 -							\$0.00			
	0130	CONCRETE PAVEMENT (9 IN. NON-	Material		4	Apr 16, 2025	SYSTEM	(\$322,598.40)			
		REINFORCED,			4	Apr 16, 2025	SYSTEM	\$322,598.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					5	May 2, 2025	SYSTEM	(\$322,598.40)			
					5	May 2, 2025	SYSTEM	\$322,598.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					6	May 16, 2025	SYSTEM	(\$322,598.40)			
					6	May 16, 2025	SYSTEM	\$322,598.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					7	Jun 2, 2025	SYSTEM	(\$322,598.40)			
					7	Jun 2, 2025	SYSTEM	\$322,598.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user cockrz1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					8	Jun 16, 2025	SYSTEM	(\$322,598.40)			
					8	Jun 16, 2025	SYSTEM	\$322,598.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					9	Jun 30, 2025	SYSTEM	(\$322,598.40)			
					9	Jun 30, 2025	SYSTEM	\$322,598.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					10	Jul 16, 2025	SYSTEM	(\$322,598.40)			
							10	Jul 16, 2025	SYSTEM	\$322,598.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.
					11	Aug 4, 2025	SYSTEM	(\$322,598.40)			
					11	Aug 4, 2025	SYSTEM	\$322,598.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					12	Aug 18, 2025	SYSTEM	(\$322,598.40)			
						12	Aug 18, 2025	SYSTEM	\$322,598.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.	
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	0130 -							\$0.00			
	0150	IMPACT ATTENUATOR 65 MPH (SAND	Overrun	Overrun	3	Apr 2, 2025	SYSTEM	(\$11,697.38)			
		BARREL ARRAY)			5	May 2, 2025	SYSTEM	\$11,697.38	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5848.69000 - 5848.69000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			



ATTENNATION 65   PAPE   CANADA	ct L	ine	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
STEIN ALTON OR 6   Superior				Туре		Number	Date	Ву		
10170   CAPATRUCTION   Material	68 0 <sup>-</sup>	150	ATTENUATOR 65 MPH (SAND	Overrun - T	otal				\$0.00	
STORN   Material			· · · · · · · · · · · · · · · · · · ·							
SIGNS										
Total	0	0170		Material				SYSTEM	(\$5,106.00)	
Material - Total						2		SYSTEM	\$5,106.00	Estimate Item Adjustment (0004) due to user frizzm overridding Payment
Overrun					- Total				\$0.00	
2026   9   Jun 30, SYSTEM   (\$308.38)									\$0.00	
9   3, m 30,   SYSTEM   (\$306.36)				Overrun	Overrun	5		SYSTEM	(\$905.72)	
11						9	Jun 30,	SYSTEM	(\$306.36)	
Part										
1710   Total   Substitute   S						11		SYSTEM	\$1,212.08	previous payment estimates. Price Adjustments of ',8.51000 - 8.51000, 'is
ADVANCED					Overrun - T	otal			\$0.00	
ADVANCED   WARNING RAIL   STATEM   SPATEM   SP				Overrun - T	otal				\$0.00	
MARNING RAIL   SYSTEM	0	170 -	Total						\$0.00	
Part	0	180	WARNING RAIL	Material		2		SYSTEM	(\$212.68)	
Material - Total   S0.00						2		SYSTEM	\$212.68	Estimate Item Adjustment (0005) due to user frizzm overridding Payment
CHANNELIZER (TRIM-LINE)									\$0.00	
CHANNELIZER (TRIM-LINE)			Material - Total							
CRIM-LINE   2025   2						_				
Company	0	0190		матепа			2025			
Material - Total   S0.00						2		SYSTEM	\$7,177.50	Estimate Item Adjustment (0006) due to user frizzm overridding Payment
Direction   Dir					- Total				\$0.00	
Direction   Dire			Material - Total							
NDICATOR BARRICADE	0	190 -	Total						\$0.00	
2 Mar 17, 2025 SYSTEM \$3,190.20 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzra overridding Payment Estimate Exception 7 on the current Payment Estimate.  90.00  0210 - Total  0220 FLASHING ARROW PANEL  Material  2 Mar 17, 2025 SYSTEM (\$7,656.48)  2 Mar 17, 2025 SYSTEM \$7,656.48 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.  - Total  0220 - Total  0220 - Total  0220 - Total  0230 TUBULAR MARKER  Overrun  Overrun  Overrun  5 May 2, 2025 SYSTEM (\$1,860.90)  11 Aug 4, 2025 SYSTEM \$1,860.90  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of 1,186.09000 - 186.09000, 1 applied (if non-zero).	02	210	INDICATOR			2		SYSTEM	(\$3,190.20)	
Material - Total   \$0.00								SYSTEM	\$3,190.20	Estimate Item Adjustment (0007) due to user frizzm overridding Payment
Solution					- Total				\$0.00	
D220   FLASHING   ARROW PANEL     D225   SYSTEM   S7,656.48				Material - To	otal				\$0.00	
ARROW PANEL  2025  2 Mar 17, 2025  2 Mar 17, 2025  37,656.48  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.  **Total***  \$0.00  **Outering**  **Ou	02	210 -	Total						\$0.00	
2025 Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.  - Total  \$0.00  Material - Total  \$0.00   0220 - Total  \$0.00   0230 TUBULAR MARKER  Overrun  Overrun  Overrun  5 May 2, 2025  SYSTEM (\$1,860.90)  Marker  11 Aug 4, 2025  SYSTEM \$1,860.90  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',186.09000 - 186.09000, 'i applied (if non-zero).	02	220		Material		2		SYSTEM	(\$7,656.48)	
Material - Total   \$0.00						2		SYSTEM	\$7,656.48	Estimate Item Adjustment (0008) due to user frizzm overridding Payment
\$0.00       10220 - Total       0230 TUBULAR MARKER     Overrun MARKER     5 May 2, 2025     SYSTEM (\$1,860.90)       11 Aug 4, 2025     SYSTEM \$1,860.90     Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',186.09000 - 186.09000, 'i applied (if non-zero).					- Total				\$0.00	
0230 TUBULAR MARKER  Overrun  Overrun  S  May 2, 2025  11  Aug 4, 2025  SYSTEM  SYSTEM  SYSTEM  SYSTEM  SYSTEM  S1,860.90  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',186.09000 - 186.09000, 'i applied (if non-zero).				Material - To	otal				\$0.00	
MARKER  2025  11 Aug 4, 2025  SYSTEM \$1,860.90 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',186.09000 - 186.09000, 'i applied (if non-zero).	02	220 -	Total						\$0.00	
previous payment estimates. Price Adjustments of ',186.09000 - 186.09000, 'i applied (if non-zero).	02	230		Overrun	Overrun	5	May 2, 2025	SYSTEM	(\$1,860.90)	
Overrun - Total \$0.00						11		SYSTEM	\$1,860.90	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',186.09000 - 186.09000, 'is applied (if non-zero).
					Overrun - T	otal			\$0.00	



et l	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
68 0	0230	TUBULAR MARKER	Overrun - T	otal				\$0.00	
0	0230 -	Total						\$0.00	
0	0240	CHANGEABLE MESSAGE SIGN	Material		2	Mar 17, 2025	SYSTEM	(\$19,141.16)	
		WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED /			2	Mar 17, 2025	SYSTEM	\$19,141.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 9 on the current Payment Estimate.
		RETAINED		- Total				\$0.00	
			Material - T	otal				\$0.00	
	0240 -							\$0.00	
0	0250	TEMPORARY TRAFFIC BARRIER, CONT.	Overrun	Overrun	3	Apr 2, 2025	SYSTEM	(\$45,180.33)	
		FURN/RE			4	Apr 16, 2025	SYSTEM	\$45,180.33	Unit price based on averaged overrun adjustments for installed quantity on al previous payment estimates. Price Adjustments of ',39.39000 - 39.39000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Total					\$0.00	
0	0250 -	Total						\$0.00	
0	0340	COLDMILLING BITUMINOUS	Overrun	Overrun	2	Mar 17, 2025	SYSTEM	(\$13,608.54)	
		PAVEMENT FOR REM			3	Apr 2, 2025	SYSTEM	\$13,608.54	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',6.38000 - 6.38000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
0	0340 -	Total						\$0.00	
0	0400	18 IN. GROUP A FLARED END SECT	Material		3	Apr 2, 2025	SYSTEM	(\$3,509.22)	
		0201			3	Apr 2, 2025	SYSTEM	\$3,509.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
0	0400 -	Total						\$0.00	
0	0480	ANCHOR ASSEMBLY, GUARD CABLE 3- STRAND	Material		2	Mar 17, 2025	SYSTEM	(\$5,051.14)	
					2	Mar 17, 2025	SYSTEM	\$5,051.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total					\$0.00	
			Material - Total					\$0.00	
0	0480 -	Total						\$0.00	
0	0570	HALF-SOLE REPAIR	Overrun	Overrun	10	Jul 16, 2025	SYSTEM	(\$13,052.56)	
					11	Aug 4, 2025	SYSTEM	\$13,052.56	Unit price based on averaged overrun adjustments for installed quantity on al previous payment estimates. Price Adjustments of ',54.16000 - 54.16000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - T		otal			\$0.00 \$0.00	
0	0570 -	Total	Overrun - T		otal				
		LATEX MODIFIED CONCRETE	Overrun - T		otal	Jul 16, 2025	SYSTEM	\$0.00	
		LATEX MODIFIED					SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.
		LATEX MODIFIED CONCRETE WEARING			10	2025 Jul 16,		\$0.00 \$0.00 (\$92,115.00)	Estimate Item Adjustment (0005) due to user frizzm overridding Payment



oject	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
3468	0760	LATEX MODIFIED CONCRETE	Material						Estimate Exception 6 on the current Payment Estimate.
		WEARING SURFACE			12	Aug 18, 2025	SYSTEM	(\$163,944.00)	
					12	Aug 18, 2025	SYSTEM	\$163,944.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0760 -	Total						\$0.00	
	0800	DECK REPAIR WITH VOID TUBE	Material		7	Jun 2, 2025	SYSTEM	(\$10,397.09)	
		REPLACEMENT			7	Jun 2, 2025	SYSTEM	\$10,397.09	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user cockrz1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Jun 16, 2025	SYSTEM	(\$13,833.96)	
					8	Jun 16, 2025	SYSTEM	\$13,833.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.
					9	Jun 30, 2025	SYSTEM	(\$28,181.98)	
					9	Jun 30, 2025	SYSTEM	\$28,181.98	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.
					10	Jul 16, 2025	SYSTEM	(\$28,220.94)	
					10	Jul 16, 2025	SYSTEM	\$28,220.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate.
					11	Aug 4, 2025	SYSTEM	(\$28,220.94)	
					11	Aug 4, 2025	SYSTEM	\$28,220.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate.
					12	Aug 18, 2025	SYSTEM	(\$28,220.94)	
					12	Aug 18, 2025	SYSTEM	\$28,220.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
			Overrun	overrun Overrun	9	Jun 30, 2025	SYSTEM	(\$4,426.98)	
					10	Jul 16, 2025	SYSTEM	(\$38.96)	
					11	Aug 4, 2025	SYSTEM	\$4,465.94	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',95.02000 - 95.02000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - T	Overrun - Total					
	0800 -	Total						\$0.00	
	0810	CLEANING AND EPOXY COATING	Material		11	Aug 4, 2025	SYSTEM	(\$4,886.12)	
					11	Aug 4, 2025	SYSTEM	\$4,886.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 15 on the current Payment Estimate.
					12	Aug 18, 2025	SYSTEM	(\$4,886.12)	
					12	Aug 18, 2025	SYSTEM	\$4,886.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3468	0810	- Total		'				\$0.00	
	0940	LATEX MODIFIED CONCRETE	Material		10	Jul 16, 2025	SYSTEM	(\$98,532.00)	
		WEARING SURFACE			10	Jul 16, 2025	SYSTEM	\$98,532.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.
					11	Aug 4, 2025	SYSTEM	(\$175,743.00)	
					11	Aug 4, 2025	SYSTEM	\$175,743.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.
				12	12	Aug 18, 2025	SYSTEM	(\$175,743.00)	
					12	Aug 18, 2025	SYSTEM	\$175,743.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
			Overrun	Overrun	11	Aug 4, 2025	SYSTEM	(\$11,799.00)	
					12	Aug 18, 2025	SYSTEM	\$11,799.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',207.00000 - 207.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0940	- Total						\$0.00	
	0950	DIAMOND GRINDING	Overrun	Overrun	11	Aug 4, 2025	SYSTEM	(\$456.00)	
					12	Aug 18, 2025	SYSTEM	\$456.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',8.00000 - 8.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0950	- Total						\$0.00	
	0980	DECK REPAIR WITH VOID TUBE REPLACEMENT	BE		7	Jun 2, 2025	SYSTEM	(\$18,338.86)	
					7	Jun 2, 2025	SYSTEM	\$18,338.86	This adjustment offsets the original system-generated Material Payment
						2020			Estimate Item Adjustment (0005) due to user cockrz1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Jun 16, 2025	SYSTEM	(\$22,045.59)	
					8	Jun 16,	SYSTEM	(\$22,045.59) \$22,045.59	
						Jun 16, 2025 Jun 16,			Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment
					8	Jun 16, 2025 Jun 16, 2025 Jun 30,	SYSTEM	\$22,045.59	Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment
					8	Jun 16, 2025 Jun 16, 2025 Jun 30, 2025 Jun 30,	SYSTEM SYSTEM	\$22,045.59 (\$22,045.59)	Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment
					9	Jun 16, 2025 Jun 16, 2025 Jun 30, 2025 Jun 30, 2025 Jul 16,	SYSTEM SYSTEM	\$22,045.59 (\$22,045.59) \$22,045.59	Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment
					9 9 10	Jun 16, 2025 Jun 16, 2025 Jun 30, 2025 Jun 30, 2025 Jul 16, 2025 Jul 16,	SYSTEM SYSTEM SYSTEM	\$22,045.59 (\$22,045.59) \$22,045.59 (\$53,211.20)	Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment
					9 9 10 10	Jun 16, 2025 Jun 16, 2025 Jun 30, 2025 Jun 30, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$22,045.59 (\$22,045.59) \$22,045.59 (\$53,211.20) \$53,211.20	Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment
					9 9 10 10	Jun 16, 2025 Jun 16, 2025 Jun 30, 2025 Jun 30, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$22,045.59 (\$22,045.59) \$22,045.59 (\$53,211.20) \$53,211.20	Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 14 on the current Payment Estimate.



Martin   Control   Chemical   Control   Cont	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
REPLACEMENT	J4P3468	0980		Material	- Total				\$0.00				
10				Material - To	otal				\$0.00				
1				Overrun	Overrun	8		SYSTEM	(\$3,041.59)				
Part						10		SYSTEM	(\$31,165.61)				
Clashing And   Property   Coating   Clashing And   Property   Clashing   Clashing And   Property						11		SYSTEM	\$34,207.20	previous payment estimates. Price Adjustments of ',95.02000 - 95.02000, 'is			
1					Overrun - T	otal			\$0.00				
Material   1				Overrun - T	otal				\$0.00				
PROVIDED   11		0980	- Total						\$0.00				
Estimate Item Aglustment (Orifo) due to user frizzar overridding Payment Estimate 2005 (2005 to user frizzar overridding Payment Estimate 2005) (2005 to user frizzar overridding Payment Estimate Estima		0990		Material		11		SYSTEM	(\$5,288.40)				
Total   South   State   South   State   South   Sout						11		SYSTEM	\$5,288.40	Estimate Item Adjustment (0016) due to user frizzm overridding Payment			
Sestimate Exception 1 on the current Payment Estimate.						12		SYSTEM	(\$5,288.40)				
Material - Total   Scout   S						12		SYSTEM	\$5,288.40	Estimate Item Adjustment (0010) due to user frizzm overridding Payment			
SOUND   SEQUENTIAL   SEQUENTI					- Total				\$0.00				
				Material - To	otal				\$0.00				
PLASHING WARNING LIGHT		0990	- Total						\$0.00				
5 May 2, 2055   SYSTEM   S5,985.00   This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate Exception 8 on the current Payment Estimate Exception 9 on the current Payment Estimate Exception 8 on the current Payment Estimate Exception 9 on the current Payment Estimate Exception 8 on the current Payment Estimate Exception 8 on the current Payment Estimate Exception 9 on the current Payment Estimate Exception 8 on the current Payment Estimate Exception 9 on the current Payment Estimate Exception 10 on the current Payment Estimate Estimate Exception 10 on the current Payment Estimate Exception 10 on the current Payment Estimate.  - Total    Aug 4, SYSTEM   S5,985.00   This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate.    Total		5001	FLASHING	Material		5		SYSTEM	(\$5,985.00)				
2025						5		SYSTEM	\$5,985.00	Estimate Item Adjustment (0007) due to user frizzm overridding Payment			
2025   SYSTEM   S5,985.00   SYSTEM   S5,985.00   This adjustment (0004) due to user frizzm overridding Payment Estimate Exception 7 on the current Payment Estimate.						6		SYSTEM	(\$5,985.00)				
2025						6		SYSTEM	\$5,985.00	Estimate Item Adjustment (0004) due to user frizzm overridding Payment			
Estimate Item Adjustment (0006) due to user cockrz1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  8						7		SYSTEM	(\$5,985.00)				
2025						7		SYSTEM	\$5,985.00	Estimate Item Adjustment (0006) due to user cockrz1 overridding Payment			
Estimate Item Adjustment (0007) dué to user frizzm overridding Páyment Estimate Exception 6 on the current Payment Estimate.  9 Jun 30, 2025  9 Jun 30, 2025  10 Jul 16, 2025  10 Jul 16, 2025  11 Aug 4, 2025  11 Aug 4, 2025  11 Aug 4, 2025  11 Aug 4, 2025  12 SYSTEM \$5,985.00  SYSTEM \$5,985.00  Estimate Exception 6 on the current Payment Estimate.  Estimate Exception 6 on the current Payment Estimate.  10 Jul 16, 2025  11 Aug 4, 2025  11 SySTEM \$5,985.00  Material - Total \$0.00  Material - Total \$0.00							8		SYSTEM	(\$5,985.00)			
2025										8		SYSTEM	\$5,985.00
Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.  10 Jul 16, 2025 SYSTEM (\$5,985.00)  10 Jul 16, 2025 SYSTEM \$5,985.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.  11 Aug 4, 2025 SYSTEM (\$5,985.00)  11 Aug 4, 2025 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user frizzm overridding Payment Estimate Item Adjustment (0017) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate Estimate Exception 10 on the current Payment Estimate.						9		SYSTEM	(\$5,985.00)				
2025  10 Jul 16, 2025 \$\$ \$\$ \$\$ \$\$ \$\$ \$\$ \$\$ \$\$ \$\$ \$\$ \$\$ \$\$ \$\$						9		SYSTEM	\$5,985.00	Estimate Item Adjustment (0008) due to user frizzm overridding Payment			
Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.  11						10		SYSTEM	(\$5,985.00)				
2025  11 Aug 4, 2025  SYSTEM \$5,985.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.  - Total \$0.00  Material - Total \$0.00						10			\$5,985.00	Estimate Item Adjustment (0011) due to user frizzm overridding Payment			
Estimate Item Adjustment (0017) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.  - Total \$0.00  Material - Total \$0.00							2025		, , ,				
Material - Total \$0.00						11		SYSTEM	\$5,985.00	Estimate Item Adjustment (0017) due to user frizzm overridding Payment			
					- Total				\$0.00				
5001 - Total \$0.00				Material - To	otal				\$0.00				
		5001	Total						\$0.00				



Aug 21, 2025

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3468	- Total							\$1,449.18	
Overall -	Total							\$1,449.18	

# MoDOT

### **Contract Adjustments for Contract - 241018-C02**

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 17 of 17