

#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 3, 2025

Progress Estimate Number 14	Contract ID Prime Contra		3-D4A Bridge, LLC		riod Start riod End			5 <b>Ne</b>	iginal Contrac t Change Ord rrent Contrac	er Amount	\$90	94,404.43 03,826.15 98,230.58		
Approval Date											By U	Iser		
November 3, 2025			Generated	d and Appr	oved (and	should be c	considere	d Draft) a	at the Project C	Office Level by	,	hensor		
November 3, 2025			Reviewed and	Approved	(and shoul	d be consid	dered Dra	ft) at the	Resident Eng	ineer Level by	,	browns1		
November 4, 2025				Revi	ewed and A	Approved a	t the Cen	tral Offic	e Controllers C	Office Level by	,	ramses1		
Original Completion	Current Co	nt Completion Date Actual (			mpletion I	Date	Q	% of Current C	ontract Amo	unt Comple	te			
December 1, 20				r 1, 2026 77.45%										
	Coi	ntract Informat	onal Dates					Milestones						
Date Description	Original Co	mpletion Date	Current Con	pletion D	ate			ate	Original	Current	Days	Diary		
Acceptance Date							Desc	ription	Completion Date	Completion Date	Remaining	Charge Days		
Awarded Date	January 8, 2	2025	January 8, 20	)25							Milestone	,		
Letting Date	December 1	3, 2024	December 13	3, 2024			Milestor		October	October	Milestone			
Notice to Proceed Date	February 10	, 2025	February 10,	2025			Calenda JSP F	ar i ime	16, 2025	16, 2025	Complete			
Work Began Date	May 5, 2025	j	May 5, 2025				Liquidat Savings							
							J5P352 Bridges	5						

0 t t T - t - I D	- For Followsky No. 44				
Contract Total Pa	y For Estimate No. 14				
		This Estimate	Previous	To Date	
241213-D4A					
	Total Posted Items Pay	\$207,734.00	\$4,360,242.27	\$4,567,976.27	
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
	Incentive	\$0.00	\$210,000.00	\$210,000.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$4,570,242.27	\$4,777,976.27	
Contract Total Pag	yable This Estimate:	\$207,734.00			

Contract Lot	ai Payable In	iis Estimat	e: \$207,734.00				
tems Paid Th	s Estimate P	<u>eriod</u>					
Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3523	0200	6169901	MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM	N LS	\$57,000.000	0.200	\$11,400.00
	0210	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	LF	\$145.000	460	\$66,700.00
	0600	2161503	REMOVAL OF EXISTING DECK REPAIR	SQFT	\$25.000	14	\$350.00
	0610	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	CUYD	\$1,000.000	11	\$11,000.00
	0640	7040104	HALF-SOLE REPAIR	SQFT	\$125.000	411	\$51,375.00
	0650	7040113	CLEANING AND EPOXY COATING	SQFT	\$7.700	1,130	\$8,701.00
	0690	2161503	REMOVAL OF EXISTING DECK REPAIR	SQFT	\$25.000	7	\$175.00
	0700	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	CUYD	\$1,000.000	18	\$18,000.00
	0730	7040104	HALF-SOLE REPAIR	SQFT	\$125.000	173	\$21,625.00
Project J5P3	523 - Total						\$189,326.00
J5P3525	1940	7040113	CLEANING AND EPOXY COATING	SQFT	\$7.080	2,600	\$18,408.00
Project J5P3	525 - Total						\$18,408.00
Overall - Tota	al						\$207,734.00
Contract Adju	stments This	<u>Estimate</u>					

No Contract Adjustments Exist on Contract

Line Item	ne Item Adjustments This Estimate												
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount					
J5P3523	0040	ULTRATHIN BONDED WEARING SURFACE, TYPE	Material			-102	\$150.00	(\$15,300.00)					

Revision 10/17/2025 Page 1 of 23



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 3, 2025

Estimat	gress e Num 14		241213-D4A E & C Bridge, L		Period Start Period End	October 16, 2025 November 1, 2025	Net Chai	Contract Amonge Order Am Contract Am	ount	\$4,994,404.43 \$903,826.15 \$5,898,230.58
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type		Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3523		С								
	0040	ULTRATHIN BONDED WEARING SURFACE, TYPE C	Material		generated M Adjustment overridding I	nent offsets the original laterial Payment Estima (0001) due to user hens Payment Estimate Exce Payment Estimate.	ate Item sor	102	\$150.00	\$15,300.00
	0210	CONCRETE TRAFFIC BARRIER, TYPE C	Material					-460	\$145.00	(\$66,700.00)
	0210	CONCRETE TRAFFIC BARRIER, TYPE C	Material		generated M Adjustment overridding I	nent offsets the original laterial Payment Estima (0002) due to user hens Payment Estimate Exce Payment Estimate.	ate Item sor	460	\$145.00	\$66,700.00
	0610	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material					-14	\$1,000.00	(\$14,000.00)
	0610	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material		generated M Adjustment overridding I	nent offsets the original laterial Payment Estima (0003) due to user hens Payment Estimate Exce Payment Estimate.	ate Item sor	14	\$1,000.00	\$14,000.00
	0620	LATEX MODIFIED CONCRETE WEARING SURFACE	Material					-474	\$220.00	(\$104,280.00)
	0620	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		generated M Adjustment overridding I	nent offsets the original laterial Payment Estima (0004) due to user hens Payment Estimate Exce Payment Estimate.	ate Item sor	474	\$220.00	\$104,280.00
	0700	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material					-21	\$1,000.00	(\$21,000.00)
	0700	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material		generated M Adjustment overridding I	nent offsets the original laterial Payment Estima (0005) due to user hens Payment Estimate Exce Payment Estimate.	ate Item sor	21	\$1,000.00	\$21,000.00
	0710	LATEX MODIFIED CONCRETE WEARING SURFACE	Material					-474	\$220.00	(\$104,280.00)
	0710	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		generated M Adjustment overridding I	nent offsets the original laterial Payment Estima (0006) due to user hens Payment Estimate Exce Payment Estimate.	ate Item sor	474	\$220.00	\$104,280.00
J5P3525	1000	CONCRETE TRAFFIC BARRIER, TYPE C	Material					-460	\$145.00	(\$66,700.00)
	1000	CONCRETE TRAFFIC BARRIER, TYPE C	Material		generated M Adjustment overridding I	nent offsets the original laterial Payment Estima (0007) due to user hens Payment Estimate Exce Payment Estimate.	até Item sor	460	\$145.00	\$66,700.00
	1060	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material					-10,000	\$0.80	(\$8,000.00)
	1060	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		generated M Adjustment overridding I	nent offsets the original laterial Payment Estima (0008) due to user hens Payment Estimate Exce nt Payment Estimate.	ate Item sor	10,000	\$0.80	\$8,000.00

Revision 10/17/2025 Page 2 of 23



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 3, 2025

Number	Line No. 1070	Item Description  6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS  6 IN. YELLOW HIGH BUILD	Adjustment Type Material	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
		WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material					
	1070	6 IN VELLOW HIGH BUILD				-7,000	\$0.80	(\$5,600.00)
		WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user hensor overridding Payment Estimate Exception 11 on the current Payment Estimate.	7,000	\$0.80	\$5,600.00
	1730	HALF-SOLE REPAIR	Material			-1,179	\$120.00	(\$141,480.00)
	1730	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user hensor overridding Payment Estimate Exception 12 on the current Payment Estimate.	1,179	\$120.00	\$141,480.00
	1830	HALF-SOLE REPAIR	Material			-1,423	\$120.00	(\$170,760.00)
	1830	HALF-SOLE REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user hensor overridding Payment Estimate Exception 13 on the current Payment Estimate.	1,423	\$120.00	\$170,760.00
	5001	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material			-101.50000	\$165.00	(\$16,747.50)
	5001	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate.	101.50000	\$165.00	\$16,747.50
Total								\$0.00

Revision 10/17/2025 Page 3 of 23



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information							
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work					
J5P3523	FAF 50-3(118)	3 Bridge rehabilitations	50	COLE	at Bolivar St. and Vetter L	n. in Jefferson City						
J5P3525	FAF 54-3(218)	8 Bridge rehabilitations	54	COLE	at various location near Je	efferson City						
Totals I	y Job Nu	ımbers										
J5P3523		I Item Pay Item Adjustme		tem Pay	This Estimate \$189,326.00 \$0.00 \$189,326.00	Previous \$635,970.25 \$0.00 \$635,970.25	To Date \$825,296.25 \$0.00 \$825,296.25					
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					
J5P3525		l Item Pay Item Adjustmer		tem Pay	This Estimate \$18,408.00 \$0.00 \$18,408.00	\$18,408.00 \$3,724,272.02 \$3,742,680.02 \$0.00 \$0.00 \$0.00						
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$210,000.00 \$0.00 \$0.00 \$0.00	\$210,000.00 \$0.00 \$0.00 \$0.00					

Revision 5/29/2025 Page 4 of 23



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

**Exceptions (Discrepancies) This Estimate Period** 

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5P3523, Item 4133200, Project Item Line Number 0040, Material Set 413320096, Material 1015EACPEM1 - Cationic Polymer Mod Emulsion CPEM-1, Acceptance Action Generic AspEmulsion is insufficient.	hensor: waiting on MoDot QA entry	hensor	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3523, Item 4133200, Project Item Line Number 0040, Material Set 413320096, Material 1015EAPEM1 - PEM-1 Anionic Polymer Mod Emulsion Membr, Acceptance Action Generic AspEmulsion is insufficient.	hensor: waiting on MoDot QA entry	hensor	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3523, Item 4133200, Project Item Line Number 0040, Material Set 413320096, Material 0413UBWSACTC - Ultrathin Bonded Asph Wear Surf Type C, Acceptance Action Generic AspUBAWS is insufficient.	hensor: waiting on MoDot QA entry	hensor	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3523, Item 5050004, Project Item Line Number 0610, Material Set 5050004, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	hensor: waiting on MoDot QA entry	hensor	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3523, Item 5050004, Project Item Line Number 0700, Material Set 5050004, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	hensor: waiting on MoDot QA entry	hensor	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3523, Item 5052000, Project Item Line Number 0620, Material Set 505200096, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	hensor: waiting on MoDot QA entry	hensor	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3523, Item 5052000, Project Item Line Number 0710, Material Set 505200096, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	hensor: waiting on MoDot QA entry	hensor	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3523, Item 6173000, Project Item Line Number 0210, Material Set 617300096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	hensor: waiting on MoDot QA entry	hensor	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 6173000, Project Item Line Number 1000, Material Set 617300096, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	hensor: waiting on MoDot QA entry	hensor	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 6205902A, Project Item Line Number 1060, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	hensor: waiting on MoDot QA entry	hensor	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 6205903A, Project Item Line Number 1070, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	hensor: waiting on MoDot QA entry	hensor	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 7040104, Project Item Line Number 1730, Material Set 704010496, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	hensor: waiting on MoDot QA entry	hensor	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 7040104, Project Item Line Number 1830, Material Set 704010496, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	hensor: waiting on MoDot QA entry	hensor	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 7040112, Project Item Line Number 5001, Material Set 704011296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	hensor: waiting on MoDot QA entry	hensor	Overridden

Revision 5/29/2025 Page 5 of 23



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ract	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
13- J	I5P3523	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.50	\$54,000.00	\$27,000.0
		0001	0020	2072000	LINEAR GRADING CLASS 2	4.60	0.00	4.60	STA	0.00	\$1,750.00	\$0.0
		0001	0030	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	92.00	0.00	92.00	SQYD	0.00	\$15.00	\$0.0
		0001	0040	4133200	ULTRATHIN BONDED WEARING SURFACE, TYPE C	102.00	0.00	102.00	SQYD	102.00	\$150.00	\$15,300.0
		0001	0050	6081000	CONCRETE MEDIAN	0.60	0.00	0.60	SQYD	0.00	\$1,500.00	\$0.0
		0001	0060	6086004	CONCRETE SIDEWALK, 4 IN.	91.10	0.00	91.10	SQYD	0.00	\$90.00	\$0.0
		0001	0070	6091052	CURB AND GUTTER TYPE B	158.00	0.00	158.00	LF	0.00	\$60.00	\$0.0
		0001	0800	6122040	WORK ZONE CRASH CUSHION (NARROW)	6.00	0.00	6.00	EA	4.00	\$7,100.00	\$28,400.0
		0001	0090	6161005	CONSTRUCTION SIGNS	4,281.00	0.00	4,281.00	SQFT	1,136.00	\$8.00	\$9,088.0
		0001	0100	6161008	ADVANCED WARNING RAIL SYSTEM	15.00	0.00	15.00	EA	15.00	\$55.00	\$825.0
		0001	0110	6161010	RELOCATED SIGNS	1,124.00	0.00	1,124.00	SQFT	631.00	\$7.25	\$4,574.7
		0001	0120	6161025	CHANNELIZER (TRIM-LINE)	250.00	0.00	250.00	EA	200.00	\$30.00	\$6,000.0
		0001	0130	6161030	TYPE 3 MOVEABLE BARRICADE	59.00	0.00	59.00	EA	40.00	\$175.00	\$7,000.0
		0001	0140	6161033	DIRECTION INDICATOR BARRICADE	29.00	0.00	29.00	EA	29.00	\$100.00	\$2,900.0
		0001	0150	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.0
		0001	0160	6161055	SEQUENTIAL FLASHING WARNING LIGHT	29.00	0.00	29.00	EA	29.00	\$100.00	\$2,900.0
		0001	0170	6161070	TUBULAR MARKER	48.00	0.00	48.00	EA	48.00	\$65.00	\$3,120.0
		0001	0180	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	8.00	0.00	8.00	EA	6.00	\$4,250.00	\$25,500.0
		0001	0190	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	8.00	0.00	8.00	EA	4.00	\$1,850.00	\$7,400.0
		0001	0200	6169901	MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM	1.00	0.00	1.00	LS	0.80	\$57,000.00	\$45,600.0
		0004	0210	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	460.00	0.00	460.00	LF	460.00	\$145.00	\$66,700.0
		0001	0220	6173100	CONCRETE TRAFFIC BARRIER, TYPE D	112.00	0.00	112.00	LF	0.00	\$225.00	\$0.0
		0001	0230	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$125,000.00	\$62,500.0
		0001	0240	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	1.00	0.00	1.00	EA	0.00	\$2,000.00	\$0.0
		0001	0250	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	8,571.00	0.00	8,571.00	LF	0.00	\$0.80	\$0.0
		0001	0260		6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,601.00	0.00	7,601.00	LF	0.00	\$0.80	\$0.0
		0001	0270	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	863.00	0.00	863.00	LF	0.00	\$5.00	\$0.
		0001	0280	6206001C 6207001	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS PAVEMENT MARKING REMOVAL	123.00 40,991.00	0.00	123.00 40,991.00	LF LF	19,000.00	\$5.00 \$0.80	\$0.i \$15,200.i
		0001										
		0001	0300	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	1.00	0.00	1.00	EA	0.00	\$500.00	\$0.
		0001	0310	6208064A	TEMPORARY RAISED PAVEMENT MARKER	96.00	0.00	96.00	EA	0.00	\$5.00	\$0.
		0001	0320	6208076 6221001	4 IN TEMPORARY PAVEMENT MARKING PAINT  COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	17,866.00 102.00	0.00	17,866.00	SQYD	16,000.00	\$0.80 \$25.00	\$12,800. \$0.
		0001	0340	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$9,000.00	\$0.
		0001	0350	8025006	MULCHING	0.40	0.00	0.40	ACRE	0.00	\$2,500.00	\$0.
		0001	0360		SEEDING - COOL SEASON GRASSES	0.40	0.00	0.40	ACRE	0.00		\$0.
		0001	0370	8061016	SEDIMENT REMOVAL	5.00	0.00	5.00	CUYD	0.00	\$5.00	\$0.
		0001	0380	8061017	TEMPORARY SEEDING	0.40	0.00	0.40	ACRE	0.00	\$2,500.00	\$0.
		0001	0390	8061019	SILT FENCE	542.00	0.00	542.00	LF	0.00	\$2.80	\$0.
		0040	0400	9035011A	ST-STRUCTURAL	160.00	0.00	160.00	SQFT	0.00	\$35.00	\$0.
		0070	0410	2024043					SQFT		\$250.00	
		0070			REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	28.00	0.00	28.00		0.00		\$0.0
		0070	0420	2161001	TOTAL SURFACE HYDRO DEMOLITION	962.00	0.00	962.00	SQYD	0.00	\$74.00	\$0.0
		0070	0430	2161501	REMOVAL OF ASPHALT WEARING SURFACE	8,655.00	0.00	8,655.00	SQFT	0.00	\$3.25	\$0.
		0070	0440	2163000	PARTIAL REMOVAL OF EXISTING BRIDGE DECK	2,791.00	0.00	2,791.00	SQFT	0.00	\$38.00	\$0.
		0070	0450	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.00	\$1,500.00	\$0.
		0070	0460	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	150.00	0.00	150.00	SQYD	0.00	\$225.00	\$0.
		0070	0470	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	5.00	0.00	5.00	CUYD	0.00	\$1,000.00	\$0.
			0480	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	708.00	0.00	708.00	SQYD	0.00	\$185.00	\$0.
		0070	0490	6071068	(120 IN.) PEDESTRIAN FENCE (STRUCTURES)	329.00	0.00	329.00	LF	0.00	\$155.00	\$0.
		0070	0500	7031004	DIAMOND GRINDING	708.00	0.00	708.00	SQYD	0.00	\$7.50	\$0.
		0070	0510	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	2.50	0.00	2.50	CUYD	0.00	\$2,500.00	\$0.
		0070	0520	7034219A	TYPE D BARRIER	657.00	0.00	657.00	LF	0.00	\$190.00	\$0.0
		0070	0530	7034430	SIDEWALK (BRIDGES)	3,395.00	0.00	3,395.00	SQFT	0.00	\$45.00	\$0.0
		0070	0540	7040104	HALF-SOLE REPAIR	1,700.00	0.00	1,700.00	SQFT	0.00	\$65.00	\$0.0

Revision 5/29/2025 Page 6 of 23



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ntract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
	J5P3523	0070	0550	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	212.00	0.00	212.00	SQFT	0.00	\$165.00	\$0.00
Α		0070	0560	7040113	CLEANING AND EPOXY COATING	3,807.00	0.00	3,807.00	SQFT	0.00	\$5.93	\$0.00
		0070	0570	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$8,500.00	\$0.00
		0071	0580	2161001	TOTAL SURFACE HYDRO DEMOLITION	474.00	0.00	474.00	SQYD	474.00	\$74.00	\$35,076.00
		0071	0590	2161501	REMOVAL OF ASPHALT WEARING SURFACE	4,261.00	0.00	4,261.00	SQFT	4,261.00	\$2.25	\$9,587.25
		0071	0600	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	14.00	114.00	SQFT	114.00	\$25.00	\$2,850.00
		0071	0610	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	11.00	14.00	CUYD	14.00	\$1,000.00	\$14,000.00
		0071	0620	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	474.00	0.00	474.00	SQYD	474.00	\$220.00	\$104,280.00
		0071	0630	7031004	DIAMOND GRINDING	474.00	0.00	474.00	SQYD	474.00	\$8.00	\$3,792.00
		0071	0640	7040104	HALF-SOLE REPAIR	100.00	411.00	511.00	SQFT	511.00	\$125.00	\$63,875.00
		0071	0650	7040113	CLEANING AND EPOXY COATING	1,130.00	0.00	1,130.00	SQFT	1,130.00	\$7.70	\$8,701.00
		0071	0660	7172054	OPEN CELL FOAM JOINT SEAL	57.00	0.00	57.00	LF	57.00	\$95.00	\$5,415.00
		0072	0670	2161001	TOTAL SURFACE HYDRO DEMOLITION	474.00	0.00	474.00	SQYD	474.00	\$74.00	\$35,076.0
		0072										
		0072	0680	2161501	REMOVAL OF ASPHALT WEARING SURFACE	4,261.00	0.00	4,261.00	SQFT	4,261.00	\$3.25	\$13,848.2
		0072	0690	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	7.00	107.00	SQFT	107.00	\$25.00	\$2,675.0
			0700	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	18.00	21.00	CUYD	21.00	\$1,000.00	\$21,000.0
		0072	0710	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	474.00	0.00	474.00	SQYD	474.00	\$220.00	\$104,280.0
		0072	0720	7031004	DIAMOND GRINDING	474.00	0.00	474.00	SQYD	474.00	\$8.00	\$3,792.0
		0072	0730	7040104	HALF-SOLE REPAIR	100.00	173.00	273.00	SQFT	273.00	\$125.00	\$34,125.0
		0072	0740	7040113	CLEANING AND EPOXY COATING	1,130.00	0.00	1,130.00	SQFT	1,130.00	\$7.70	\$8,701.0
		0072	0750	7172054	OPEN CELL FOAM JOINT SEAL	57.00	0.00	57.00	LF	57.00	\$95.00	\$5,415.0
	Project J	5P3523 - To	tal Value	Posted to D	ate as of Report Generated Date							\$825,296.2
	J5P3525	0001	0760	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$45,000.00	\$45,000.00
		0001	0770	4030003	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095C MIX)	8.20	0.00	8.20	TONS	8.20	\$1,500.00	\$12,300.00
		0001	0780	4071005	TACK COAT	8.00	0.00	8.00	GAL	0.00	\$50.00	\$0.0
		0001	0790	6113020	FURNISHING TYPE 2 ROCK BLANKET	107.00	0.00	107.00	CUYD	107.00	\$60.00	\$6,420.0
		0001	0800	6113040	PLACING TYPE 2 ROCK BLANKET	107.00	0.00	107.00	CUYD	107.00	\$40.00	\$4,280.0
		0001	0810	6122014	IMPACT ATTENUATOR 60 MPH (SAND BARREL ARRAY)	2.00	3.00	5.00	EA	5.00	\$4,130.00	\$20,650.0
		0001	0820	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	1.00	0.00	1.00	EA	1.00	\$4,625.00	\$4,625.0
		0001	0830	6122020	REPLACEMENT SAND BARREL	8.00	0.00	8.00	EA	0.00	\$495.00	\$0.0
		0001										
		0001	0840	6122030	IMPACT ATTENUATOR (RELOCATION)	8.00	0.00	8.00	EA	6.00	\$1,140.00	\$6,840.0
		0001	0850	6122040 6133018	WORK ZONE CRASH CUSHION (NARROW)  FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	6.00 5.60	0.00	6.00 5.60	TONS	0.00	\$7,100.00 \$1,200.00	\$42,600.0 \$0.0
		0001	0870	6133019	REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	35.60	0.00	35.60	SQYD	0.00	\$100.00	\$0.0
		0001	0880	6161005	CONSTRUCTION SIGNS	2,629.00	0.00	2,629.00	SQFT	2,595.00	\$8.00	\$20,760.0
		0001	0890	6161008	ADVANCED WARNING RAIL SYSTEM				EA			\$550.0
		0001	0000				0.00	14 00		10.00	\$55.00	
			0000			14.00	0.00	14.00		10.00	\$55.00	
		0001	0900	6161010	RELOCATED SIGNS	2,434.00	0.00	2,434.00	SQFT	1,327.00	\$7.25	\$9,620.7
		0001	0910	6161010 6161025	RELOCATED SIGNS CHANNELIZER (TRIM-LINE)	2,434.00 253.00	0.00	2,434.00 253.00	SQFT EA	1,327.00 253.00	\$7.25 \$30.00	\$9,620.7 \$7,590.0
		0001	0910 0920	6161010 6161025 6161030	RELOCATED SIGNS CHANNELIZER (TRIM-LINE) TYPE 3 MOVEABLE BARRICADE	2,434.00 253.00 31.00	0.00 0.00 0.00	2,434.00 253.00 31.00	SQFT EA EA	1,327.00 253.00 31.00	\$7.25 \$30.00 \$200.00	\$9,620.7 \$7,590.0 \$6,200.0
		0001	0910 0920 0930	6161010 6161025 6161030 6161033	RELOCATED SIGNS CHANNELIZER (TRIM-LINE) TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE	2,434.00 253.00 31.00 30.00	0.00 0.00 0.00 0.00	2,434.00 253.00 31.00 30.00	SQFT EA EA	1,327.00 253.00 31.00 30.00	\$7.25 \$30.00 \$200.00 \$100.00	\$9,620.7 \$7,590.0 \$6,200.0 \$3,000.0
		0001 0001 0001	0910 0920 0930 0940	6161010 6161025 6161030 6161033 6161040	RELOCATED SIGNS CHANNELIZER (TRIM-LINE) TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL	2,434.00 253.00 31.00 30.00 2.00	0.00 0.00 0.00 0.00 0.00	2,434.00 253.00 31.00 30.00 2.00	SQFT EA EA EA	1,327.00 253.00 31.00 30.00 2.00	\$7.25 \$30.00 \$200.00 \$100.00 \$3,000.00	\$9,620.7 \$7,590.0 \$6,200.0 \$3,000.0
		0001 0001 0001 0001	0910 0920 0930	6161010 6161025 6161030 6161033 6161040 6161055	RELOCATED SIGNS CHANNELIZER (TRIM-LINE) TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE	2,434.00 253.00 31.00 30.00	0.00 0.00 0.00 0.00	2,434.00 253.00 31.00 30.00	SQFT EA EA	1,327.00 253.00 31.00 30.00	\$7.25 \$30.00 \$200.00 \$100.00	\$9,620.7 \$7,590.0 \$6,200.0 \$3,000.0
		0001 0001 0001	0910 0920 0930 0940	6161010 6161025 6161030 6161033 6161040	RELOCATED SIGNS CHANNELIZER (TRIM-LINE) TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION	2,434.00 253.00 31.00 30.00 2.00	0.00 0.00 0.00 0.00 0.00	2,434.00 253.00 31.00 30.00 2.00	SQFT EA EA EA	1,327.00 253.00 31.00 30.00 2.00	\$7.25 \$30.00 \$200.00 \$100.00 \$3,000.00	\$9,620.7 \$7,590.0 \$6,200.0 \$3,000.0 \$6,000.0 \$4,745.0
		0001 0001 0001 0001 0001 0001	0910 0920 0930 0940 0950 0960	6161010 6161025 6161030 6161033 6161040 6161055 6161070	RELOCATED SIGNS CHANNELIZER (TRIM-LINE) TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00	0.00 0.00 0.00 0.00 0.00 0.00	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00	SQFT EA EA EA EA EA EA EA	1,327.00 253.00 31.00 30.00 2.00 30.00 73.00	\$7.25 \$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00	\$9,620.7 \$7,590.0 \$6,200.0 \$3,000.0 \$6,000.0 \$4,745.0
		0001 0001 0001 0001 0001 0001	0910 0920 0930 0940 0950 0960	6161010 6161025 6161030 6161033 6161040 6161055 6161070	RELOCATED SIGNS CHANNELIZER (TRIM-LINE) TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00	0.00 0.00 0.00 0.00 0.00 0.00	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00	SQFT EA EA EA EA EA EA EA EA	1,327.00 253.00 31.00 30.00 2.00 30.00 73.00	\$7.25 \$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00	\$9,620.7 \$7,590.0 \$6,200.0 \$3,000.0 \$3,000.0 \$4,745.0 \$51,000.0
		0001 0001 0001 0001 0001 0001 0001	0910 0920 0930 0940 0950 0960	6161010 6161025 6161030 6161033 6161040 6161055 6161070 6161099	RELOCATED SIGNS CHANNELIZER (TRIM-LINE) TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00	SQFT EA EA EA EA EA EA EA	1,327.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00	\$7.25 \$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00 \$65.00	\$9,620.1 \$7,590.0 \$6,200.1 \$3,000.0 \$3,000.0 \$4,745.0 \$51,000.0
		0001 0001 0001 0001 0001 0001 0001 000	0910 0920 0930 0940 0950 0960 0970	6161010 6161025 6161030 6161033 6161040 6161055 6161070 6161099 6162002	RELOCATED SIGNS CHANNELIZER (TRIM-LINE) TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED TEMPORARY LONG-TERM RUMBLE STRIPS	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00	SQFT EA EA EA EA EA EA EA EA	1,327.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00	\$7.25 \$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00	\$9,620.1 \$7,590.1 \$6,200.1 \$3,000.1 \$3,000.1 \$4,745.1 \$51,000.1 \$76,600.1
		0001 0001 0001 0001 0001 0001 0001 000	0910 0920 0930 0940 0950 0960 0970	6161010 6161025 6161030 6161033 6161040 6161055 6161070 6161099 6162002 6169901	RELOCATED SIGNS CHANNELIZER (TRIM-LINE) TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED TEMPORARY LONG-TERM RUMBLE STRIPS MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 20.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 20.00	SQFT EA EA EA EA EA EA EA LS LF	1,327.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 10.00	\$7.25 \$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00 \$1,850.00	\$9,620.1 \$7,590.0 \$6,200.1 \$3,000.0 \$3,000.0 \$4,745.0 \$51,000.0 \$76,600.0 \$66,700.0
		0001 0001 0001 0001 0001 0001 0001 000	0910 0920 0930 0940 0950 0960 0970 0980 0990 1000 1010	6161010 6161025 6161030 6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173000 6173600D	RELOCATED SIGNS CHANNELIZER (TRIM-LINE) TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED TEMPORARY LONG-TERM RUMBLE STRIPS MISC. WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM CONCRETE TRAFFIC BARRIER, TYPE C TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 20.00 460.00 688.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 20.00 460.00 1,500.00	SQFT EA EA EA EA EA EA LS LF LF	1,327.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 10.00 0.80 460.00 1,500.00	\$7.25 \$30.00 \$200.00 \$100.00 \$3,000.00 \$65.00 \$4,250.00 \$1,850.00 \$145.00 \$49.20	\$9,620.7 \$7,590.6 \$3,000.6 \$3,000.6 \$3,000.6 \$4,745.6 \$51,000.6 \$76,600.6 \$73,800.6
		0001 0001 0001 0001 0001 0001 0001 000	0910 0920 0930 0940 0950 0960 0970 0980 0990 1000 1010	6161010 6161025 6161030 6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173000 6173700B	RELOCATED SIGNS CHANNELIZER (TRIM-LINE) TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED TEMPORARY LONG-TERM RUMBLE STRIPS MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM CONCRETE TRAFFIC BARRIER, TYPE C TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 20.00 460.00 688.00 575.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 20.00 460.00 1,500.00	SQFT EA EA EA EA EA EA LS LF LF LF	1,327.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 10.00 0.80 460.00 1,500.00	\$7.25 \$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00 \$1,850.00 \$95,750.00 \$49.20	\$9,620.1 \$7,590.6 \$3,000.0 \$3,000.0 \$4,745.0 \$18,500.0 \$76,600.0 \$73,800.0 \$49,005.0
		0001 0001 0001 0001 0001 0001 0001 000	0910 0920 0930 0940 0950 0960 0970 0980 0990 1000 1010	6161010 6161025 6161030 6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173000 6173600D	RELOCATED SIGNS CHANNELIZER (TRIM-LINE) TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED TEMPORARY LONG-TERM RUMBLE STRIPS MISC. WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM CONCRETE TRAFFIC BARRIER, TYPE C TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 20.00 460.00 688.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 20.00 460.00 1,500.00	SQFT EA EA EA EA EA EA LS LF LF	1,327.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 10.00 0.80 460.00 1,500.00	\$7.25 \$30.00 \$200.00 \$100.00 \$3,000.00 \$65.00 \$4,250.00 \$1,850.00 \$145.00 \$49.20	\$9,620.1 \$7,590.6 \$3,000.0 \$3,000.0 \$4,745.0 \$18,500.0 \$76,600.0 \$73,800.0 \$49,005.0
		0001 0001 0001 0001 0001 0001 0001 000	0910 0920 0930 0940 0950 0960 0970 0980 0990 1000 1010	6161010 6161025 6161030 6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173600D 6173700B 6175010A	RELOCATED SIGNS CHANNELIZER (TRIM-LINE) TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED TEMPORARY LONG-TERM RUMBLE STRIPS MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM CONCRETE TRAFFIC BARRIER, TYPE C TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 20.00 460.00 688.00 575.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 20.00 460.00 1,500.00	SQFT EA EA EA EA EA EA LS LF LF LF	1,327.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 10.00 0.80 460.00 1,500.00 900.00	\$7.25 \$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00 \$4,250.00 \$1,850.00 \$145.00 \$49.20 \$54.45	\$9,620.7 \$7,590.0 \$3,000.0 \$3,000.0 \$3,000.0 \$4,745.0 \$18,500.0 \$76,600.0 \$73,800.0 \$49,005.0 \$22,897.5
		0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001	0910 0920 0930 0940 0950 0960 0970 0980 0990 1000 1010 1020	6161010 6161025 6161030 6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173600D 6173700B 6175010A 6175011B	RELOCATED SIGNS CHANNELIZER (TRIM-LINE) TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED TEMPORARY LONG-TERM RUMBLE STRIPS MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM CONCRETE TRAFFIC BARRIER, TYPE C TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED  TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED RELOCATING TEMPORARY TRAFFIC BARRIER RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 20.00 460.00 688.00 575.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 20.00 460.00 1,500.00 900.00	SQFT EA EA EA EA EA EA LS LF LF LF LF LF	1,327.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 10.00 0.80 460.00 1,500.00 900.00	\$7.25 \$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00 \$4,250.00 \$1,850.00 \$145.00 \$49.20 \$54.45 \$12.90 \$17.65	\$9,620.7 \$7,590.0 \$3,000.0 \$3,000.0 \$4,745.0 \$18,500.0 \$76,600.0 \$73,800.0 \$49,005.0 \$22,897.5 \$7,060.0
		0001 0001 0001 0001 0001 0001 0001 000	0910 0920 0930 0940 0950 0960 0970 0980 0990 1000 1010 1020 1030 1040 1050	6161010 6161025 6161030 6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173000 6173700B 6175010A 6175011B 6181000 6205902A	RELOCATED SIGNS CHANNELIZER (TRIM-LINE) TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED TEMPORARY LONG-TERM RUMBLE STRIPS MISC. WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM CONCRETE TRAFFIC BARRIER, TYPE C TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED RELOCATING TEMPORARY TRAFFIC BARRIER RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED MOBILIZATION 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00 575.00 1,775.00 663.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2,434.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 20.00 460.00 1,500.00 900.00 1,775.00 663.00	SQFT EA EA EA EA EA LS LF LF LF LF LF LS	1,327.00 253.00 31.00 30.00 2.00 30.00 73.00 12.00 10.00 0.80 460.00 1,500.00 900.00 1,775.00 400.00 1.00	\$7.25 \$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00 \$4,250.00 \$1,850.00 \$145.00 \$49.20 \$54.45 \$12.90 \$17.65 \$175,000.00	\$9,620.7 \$7,590.0 \$6,200.0 \$3,000.0 \$3,000.0 \$3,000.0 \$4,745.0 \$51,000.0 \$76,600.0 \$73,800.0 \$49,005.0 \$175,000.0 \$175,000.0 \$175,000.0 \$175,000.0

Revision 5/29/2025 Page 7 of 23



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

	roject No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
	P3525	0001	1090	6208064A	TEMPORARY RAISED PAVEMENT MARKER	146.00	0.00	146.00	EA	0.00	\$5.00	\$0.0
4		0001	1100	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	47,631.00	0.00	47,631.00	LF	35,491.00	\$0.80	\$28,392.8
		0001	1110	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	102.00	0.00	102.00	SQYD	102.00	\$30.00	\$3,060.0
		0001	1120	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	160.00	0.00	160.00	SQYD	160.00	\$10.00	\$1,600.0
		0001	1130	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$9,000.00	\$0.0
		0070	1140	2161000	SCARIFICATION OF BRIDGE DECK	227.00	0.00	227.00	SQYD	227.00	\$34.25	\$7,774.7
		0070	1150	2161001	TOTAL SURFACE HYDRO DEMOLITION	909.00	0.00	909.00	SQYD	909.00	\$70.00	\$63,630.0
		0070	1160	2161501	REMOVAL OF ASPHALT WEARING SURFACE	1,744.00	0.00	1,744.00	SQFT	1,744.00	\$3.25	\$5,668.0
		0070	1170	2161502	REMOVAL OF CONCRETE WEARING SURFACE	4,392.00	0.00	4,392.00	SQFT	4,392.00	\$4.50	\$19,764.0
		0070	1180	2161503	REMOVAL OF EXISTING DECK REPAIR	50.00	0.00	50.00	SQFT	19.00	\$25.00	\$475.0
		0070	1190	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	4.00	7.00	11.00	CUYD	11.00	\$1,000.00	\$11,000.0
		0070	1200	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	909.00	0.00	909.00	SQYD	909.00	\$205.00	\$186,345.0
		0070	1210	7031004	DIAMOND GRINDING	909.00	0.00	909.00	SQYD	909.00	\$7.00	\$6,363.0
		0070	1220	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	5.00	12.00	17.00	SQFT	17.00	\$225.00	\$3,825.0
		0070	1230	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	15.00	0.00	15.00	SQFT	0.00	\$400.00	\$0.0
		0070	1240	7040104	HALF-SOLE REPAIR	50.00	172.00	222.00	SQFT	222.00	\$120.00	\$26,640.0
		0070	1250	7040113	CLEANING AND EPOXY COATING	1,859.00	0.00	1,859.00	SQFT	1,859.00	\$6.51	\$12,102.0
		0070	1260	7172054	OPEN CELL FOAM JOINT SEAL	99.00	0.00	99.00	LF	99.00	\$50.00	\$4,950.0
		0071	1270	2161000	SCARIFICATION OF BRIDGE DECK	227.00	0.00	227.00	SQYD	227.00	\$34.25	\$7,774.7
		0071	1280	2161001	TOTAL SURFACE HYDRO DEMOLITION	909.00	0.00	909.00	SQYD	909.00	\$70.00	\$63,630.0
		0071	1290	2161501	REMOVAL OF ASPHALT WEARING SURFACE	1,744.00	0.00	1,744.00	SQFT	1,744.00	\$3.25	\$5,668.0
		0071	1300	2161502	REMOVAL OF CONCRETE WEARING SURFACE	4,392.00	0.00	4,392.00	SQFT	4,392.00	\$4.50	\$19,764.0
		0071	1310	2161503	REMOVAL OF EXISTING DECK REPAIR	50.00	0.00	50.00	SQFT	25.00	\$25.00	\$625.0
		0071	1320	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	4.00	9.00	13.00	CUYD	13.00	\$1,000.00	\$13,000.0
		0071	1330	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	909.00	0.00	909.00	SQYD	909.00	\$205.00	\$186,345.0
		0071	1340	7031004	DIAMOND GRINDING	909.00	0.00	909.00	SQYD	909.00	\$7.00	\$6,363.0
		0071	1350	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	15.00	30.00	45.00	SQFT	45.00	\$225.00	\$10,125.0
		0071	1360	7040104	HALF-SOLE REPAIR	50.00	460.00	510.00	SQFT	510.00	\$120.00	\$61,200.0
		0071	1370	7040113	CLEANING AND EPOXY COATING	1,859.00	0.00	1,859.00	SQFT	1,859.00	\$6.51	\$12,102.0
		0071	1380	7172054	OPEN CELL FOAM JOINT SEAL	99.00	0.00	99.00	LF	99.00	\$50.00	\$4,950.0
		0072	1390	2161001	TOTAL SURFACE HYDRO DEMOLITION	737.00	0.00	737.00	SQYD	737.00	\$70.00	\$51,590.0
		0072	1400	2161501	REMOVAL OF ASPHALT WEARING SURFACE	6,637.00	0.00	6,637.00	SQFT	6,637.00	\$3.25	\$21,570.2
		0072	1410	2161503	REMOVAL OF EXISTING DECK REPAIR	300.00	45.00	345.00	SQFT	345.00	\$15.00	\$5,175.0
		0072	1420	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	4.00	24.00	28.00	CUYD	24.00	\$1,000.00	\$24,000.0
		0072	1430	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	737.00	0.00	737.00	SQYD	737.00	\$190.00	\$140,030.0
		0072	1440	7031004	DIAMOND GRINDING	737.00	0.00	737.00	SQYD	737.00	\$7.00	\$5,159.0
		0072	1450	7040104	HALF-SOLE REPAIR	50.00	348.00	398.00	SQFT	398.00	\$120.00	\$47,760.0
		0072	1460	7040113	CLEANING AND EPOXY COATING	1,792.00	0.00	1,792.00	SQFT	1,792.00	\$4.86	\$8,709.1
		0072	1470	7172054	OPEN CELL FOAM JOINT SEAL	94.00	0.00	94.00	LF	94.00	\$50.00	\$4,700.0
		0073	1480	2161001	TOTAL SURFACE HYDRO DEMOLITION	737.00	0.00	737.00	SQYD	737.00	\$70.00	\$51,590.0
		0073	1490	2161501	REMOVAL OF ASPHALT WEARING SURFACE	6,637.00	0.00	6,637.00	SQFT	6,637.00	\$3.25	\$21,570.2
		0073	1500	2161503	REMOVAL OF EXISTING DECK REPAIR	200.00	10.00	210.00	SQFT	200.00	\$20.00	\$4,000.0
		0073	1510	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	4.00	33.00	37.00	CUYD	37.00	\$1,000.00	\$37,000.0
		0073	1520	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	737.00	0.00	737.00	SQYD	737.00	\$190.00	\$140,030.0
		0073	1530	7031004	DIAMOND GRINDING	737.00	0.00	737.00	SQYD	737.00	\$7.00	\$5,159.0
		0073	1540	7040104	HALF-SOLE REPAIR	50.00	12.00	62.00	SQFT	62.00	\$120.00	\$7,440.0
		0073	1550	7040113	CLEANING AND EPOXY COATING	1,792.00	0.00	1,792.00	SQFT	1,792.00	\$4.86	\$8,709.
		0073	1560	7172054	OPEN CELL FOAM JOINT SEAL	94.00	0.00	94.00	LF	94.00	\$50.00	\$4,700.0
		0074	1570	2161001	TOTAL SURFACE HYDRO DEMOLITION	638.00	0.00	638.00	SQYD	638.00	\$70.00	\$44,660.0
		0074	1580	2161501	REMOVAL OF ASPHALT WEARING SURFACE	5,748.00	0.00	5,748.00	SQFT	5,502.00	\$3.25	\$17,881.5
		0074	1590	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	109.00	209.00	SQFT	209.00	\$20.00	\$4,180.0
		0074	1600	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	5.00	26.00	31.00	CUYD	31.00	\$1,000.00	\$31,000.0
		0074	1610	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	638.00	0.00	638.00	SQYD	638.00	\$190.00	\$121,220.0
		0074	1620	7031004	DIAMOND GRINDING	638.00	0.00	638.00	SQYD	638.00	\$7.00	\$4,466.0
		0074	1630	7040104	HALF-SOLE REPAIR	100.00	789.00	889.00	SQFT	889.00	\$120.00	\$106,680.0
		0074	1640	7040107	SLAB EDGE REPAIR (BRIDGES)	10.00	0.00	10.00	LF	10.00	\$500.00	\$5,000.0
		0074	1650	7040113	CLEANING AND EPOXY COATING	700.00	0.00	700.00	SQFT	700.00	\$11.48	\$8,036.0

Revision 5/29/2025 Page 8 of 23



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
241213-	J5P3525	0074	1660	7172054	OPEN CELL FOAM JOINT SEAL	89.00	0.00	89.00	LF	89.00	\$50.00	\$4,450.00
04A		0075	1670	2161001	TOTAL SURFACE HYDRO DEMOLITION	611.00	0.00	611.00	SQYD	611.00	\$70.00	\$42,770.00
		0075	1680	2161501	REMOVAL OF ASPHALT WEARING SURFACE	5,502.00	0.00	5,502.00	SQFT	5,502.00	\$3.25	\$17,881.50
		0075	1690	2161503	REMOVAL OF EXISTING DECK REPAIR	250.00	574.00	824.00	SQFT	824.00	\$20.00	\$16,480.00
		0075	1700	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	26.00	29.00	CUYD	29.00	\$1,000.00	\$29,000.00
		0075	1710	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	611.00	0.00	611.00	SQYD	611.00	\$190.00	\$116,090.00
		0075	1720	7031004	DIAMOND GRINDING	611.00	0.00	611.00	SQYD	611.00	\$7.50	\$4,582.50
		0075	1730	7040104	HALF-SOLE REPAIR	50.00	1,130.00	1,180.00	SQFT	1,179.00	\$120.00	\$141,480.00
		0075	1740	7040113	CLEANING AND EPOXY COATING	500.00	0.00	500.00	SQFT	500.00	\$6.21	\$3,105.00
		0075	1750	7172054	OPEN CELL FOAM JOINT SEAL	71.00	0.00	71.00	LF	71.00	\$70.00	\$4,970.00
		0076	1760	2161001	TOTAL SURFACE HYDRO DEMOLITION	803.00	0.00	803.00	SQYD	803.00	\$70.00	\$56,210.00
		0076	1770	2161501	REMOVAL OF ASPHALT WEARING SURFACE	7,227.00	0.00	7,227.00	SQFT	7,227.00	\$3.25	\$23,487.75
		0076	1780	2161503	REMOVAL OF EXISTING DECK REPAIR	300.00	644.00	944.00	SQFT	944.00	\$18.00	\$16,992.00
		0076	1790	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	9.00	29.00	38.00	CUYD	36.00	\$1,000.00	\$36,000.00
		0076	1800	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	803.00	0.00	803.00	SQYD	803.00	\$190.00	\$152,570.00
		0076	1810	7031004	DIAMOND GRINDING	803.00	0.00	803.00	SQYD	803.00	\$7.50	\$6,022.50
		0076	1820	7040101	SUBSTRUCTURE REPAIR (FORMED)	10.00	0.00	10.00	SQFT	10.00	\$215.00	\$2,150.00
		0076	1830	7040104	HALF-SOLE REPAIR	500.00	923.00	1,423.00	SQFT	1,423.00	\$120.00	\$170,760.00
		0076	1840	7040113	CLEANING AND EPOXY COATING	750.00	0.00	750.00	SQFT	750.00	\$6.21	\$4,657.50
		0076	1850	7172054	OPEN CELL FOAM JOINT SEAL	90.00	0.00	90.00	LF	90.00	\$55.00	\$4,950.00
		0077	1860	2061000	CLASS 1 EXCAVATION	23.00	0.00	23.00	CUYD	23.00	\$250.00	\$5,750.00
		0077	1870	2161001	TOTAL SURFACE HYDRO DEMOLITION	684.00	0.00	684.00	SQYD	684.00	\$74.00	\$50,616.00
		0077	1880	2161502	REMOVAL OF CONCRETE WEARING SURFACE	6,160.00	0.00	6,160.00	SQFT	6,160.00	\$4.25	\$26,180.00
		0077	1890	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	2.00	8.00	10.00	CUYD	10.00	\$1,000.00	\$10,000.00
		0077	1900	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	684.00	0.00	684.00	SQYD	684.00	\$200.00	\$136,800.00
		0077	1910	7031004	DIAMOND GRINDING	684.00	0.00	684.00	SQYD	0.00	\$8.00	\$0.00
		0077	1920	7039907	MISC.SELF-CONSOLIDATING CONCRETE	11.00	0.00	11.00	CUYD	11.00	\$1,800.00	\$19,800.00
		0077	1930	7040104	HALF-SOLE REPAIR	100.00	453.00	553.00	SQFT	553.00	\$120.00	\$66,360.00
		0077	1940	7040113	CLEANING AND EPOXY COATING	2,600.00	0.00	2,600.00	SQFT	2,600.00	\$7.08	\$18,408.00
		0077	1950	7101000	REINFORCING STEEL (EPOXY COATED)	1,210.00	0.00	1,210.00	LB	1,210.00	\$5.00	\$6,050.00
		0077	1960	7172054	OPEN CELL FOAM JOINT SEAL	92.00	0.00	92.00	LF	92.00	\$55.00	\$5,060.00
		0075	5001	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	0.00	101.50	101.50	SQFT	101.50	\$165.00	\$16,747.50
		0001	5002	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$2,500.00	\$2,500.00
	Project J	5P3525 - <u>To</u>	tal Val <u>ue</u>	Posted to D	Date as of Report Generated Date							\$3,742,680.02
241213-0	04A Overal	II - Total Va	lue Poste	ed to Date as	s of Report Generated Date							\$4,567,976.27

Revision 5/29/2025 Page 9 of 23



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5P3523

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0200	6169901	MISC.	10/20/25	11/3/25	1	0.20	LS	Bridge A07225 A07226					
0210	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	10/20/25	11/3/25	1	460.00	LF	Bridges A07225 A07226					
0600	2161503	REMOVAL OF EXISTING DECK REPAIR	10/31/25	11/3/25	1	14.00	SQFT	Bridge A07225					
0610	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	10/31/25	11/3/25	1	11.00	CUYD	Bridge A07225					
0640	7040104	HALF-SOLE REPAIR	10/31/25	11/3/25	1	411.00	SQFT	Bridge A07225					
0650	7040113	CLEANING AND EPOXY COATING	10/20/25	11/3/25	1	1,130.00	SQFT	Bridge A07225					
0690	2161503	REMOVAL OF EXISTING DECK REPAIR	10/31/25	11/3/25	1	7.00	SQFT	Bridge A07226					
0700	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	10/31/25	11/3/25	1	18.00	CUYD	Bridge A07226					
0730	7040104	HALF-SOLE REPAIR	10/31/25	11/3/25	1	173.00	SQFT	Bridge A07226					

Project: J5P3525

Line Number	Item Code	Description			Posting Sequence No.		Units		Offset/ Distance	Offset/ Distance	Comments
1940	7040113	CLEANING AND EPOXY COATING	10/20/25	11/3/25	1	2,600.00	SQFT	Bridge A14153			

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 6/5/2025 Page 10 of 23



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3523	0040	ULTRATHIN BONDED WEARING	Material		11	Sep 16, 2025	SYSTEM	(\$15,300.00)	
		SURFACE, TYPE C			11	Sep 16, 2025	SYSTEM	\$15,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kroekj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Oct 1, 2025	SYSTEM	(\$15,300.00)	
					12	Oct 1, 2025	SYSTEM	\$15,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Oct 16, 2025	SYSTEM	(\$15,300.00)	
					13	Oct 16, 2025	SYSTEM	\$15,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kroekj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Nov 3, 2025	SYSTEM	(\$15,300.00)	
					14	Nov 3, 2025	SYSTEM	\$15,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To					\$0.00	
	0040 -	Total						\$0.00	
	0080	WORK ZONE CRASH CUSHION	Material		11	Sep 16, 2025	SYSTEM	(\$28,400.00)	
		(NARROW)			11	Sep 16, 2025	SYSTEM	\$28,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kroekj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0080 -	Total						\$0.00	
	0090	CONSTRUCTION SIGNS	Material		11	Sep 16, 2025	SYSTEM	(\$6,656.00)	
					11	Sep 16, 2025	SYSTEM	\$6,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0090 -	Total						\$0.00	
	0120	CHANNELIZER (TRIM-LINE)	Material		11	Sep 16, 2025	SYSTEM	(\$3,000.00)	
					11	Sep 16, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kroekj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0120 -	Total						\$0.00	
	0130	TYPE 3 MOVEABLE BARRICADE	Material		11	Sep 16, 2025	SYSTEM	(\$3,500.00)	
					11	Sep 16, 2025	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroek/1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0130 -	Total						\$0.00	
	0140	DIRECTION INDICATOR BARRICADE	Material		11	Sep 16, 2025	SYSTEM	(\$1,400.00)	
		S. W. WONDE			11	Sep 16, 2025	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kroek/1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
									· · · · · · · · · · · · · · · · · · ·



t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3 (	0140 -	Total						\$0.00	
(	0150	FLASHING ARROW PANEL	Material		11	Sep 16, 2025	SYSTEM	(\$6,000.00)	
					11	Sep 16, 2025	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kroekj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
(	0150 -	Total						\$0.00	
(	0160	SEQUENTIAL FLASHING	Material		11	Sep 16, 2025	SYSTEM	(\$1,400.00)	
		WARNING LIGHT			11	Sep 16, 2025	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kroekj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To					\$0.00	
	0160 -	Total						\$0.00	
		TUBULAR MARKER	Material		11	Sep 16, 2025	SYSTEM	(\$1,560.00)	
					11	Sep 16, 2025	SYSTEM	\$1,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kroekj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
(	0170 -	Total						\$0.00	
			Material		11	Sep 16, 2025	SYSTEM	(\$25,500.00)	
					11	Sep 16, 2025	SYSTEM	\$25,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kroekj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
(	0180 -	Total						\$0.00	
(	0190	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		11	Sep 16, 2025	SYSTEM	(\$7,400.00)	
					11	Sep 16, 2025	SYSTEM	\$7,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kroekj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
(	0190 -	Total						\$0.00	
(	0210	CONCRETE TRAFFIC BARRIER,	Material		14	Nov 3, 2025	SYSTEM	(\$66,700.00)	
		TYPE C			14	Nov 3, 2025	SYSTEM	\$66,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 8 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To					\$0.00	
(	0210 -	Total						\$0.00	
		4 IN TEMPORARY PAVEMENT	Material		12	Oct 1, 2025	SYSTEM	(\$12,800.00)	
		MARKING PAINT			12	Oct 1, 2025	SYSTEM	\$12,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.
					13	Oct 16, 2025	SYSTEM	(\$12,800.00)	Examete Exception 7 on the current Faymont Estimate.
					13	Oct 16, 2025	SYSTEM	\$12,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kroekj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To					\$0.00	
			waterial - 10	rtai				\$0.00	



t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
23	0320 -	Total						\$0.00						
	0610	SUPPLEMENTARY WEARING SURFACE	Material		13	Oct 16, 2025	SYSTEM	(\$3,000.00)						
		MATERIAL			13	Oct 16, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.					
					14	Nov 3, 2025	SYSTEM	(\$14,000.00)						
					14	Nov 3, 2025	SYSTEM	\$14,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.					
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0610 -	Total						\$0.00						
	0620	LATEX MODIFIED CONCRETE	Material		13	Oct 16, 2025	SYSTEM	(\$104,280.00)						
		WEARING SURFACE			13	Oct 16, 2025	SYSTEM	\$104,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kroekj1 overridding Paymen Estimate Exception 11 on the current Payment Estimate.					
					14	Nov 3, 2025	SYSTEM	(\$104,280.00)						
					14	Nov 3, 2025	SYSTEM	\$104,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate.					
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0620 -	Total						\$0.00						
	0700 \$	SUPPLEMENTARY M: WEARING SURFACE MATERIAL	Material		12	Oct 1, 2025	SYSTEM	(\$3,000.00)						
					12	Oct 1, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 7 on the current Payment Estimate.					
					13	Oct 16, 2025	SYSTEM	(\$3,000.00)						
										13	Oct 16, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroekj1 overridding Paymen Estimate Exception 10 on the current Payment Estimate.
				1		Nov 3, 2025	SYSTEM	(\$21,000.00)						
					14	Nov 3, 2025	SYSTEM	\$21,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.					
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0700 -							\$0.00						
	0710	LATEX MODIFIED CONCRETE WEARING	Material		12	Oct 1, 2025	SYSTEM	(\$104,280.00)						
		SURFACE								12	Oct 1, 2025	SYSTEM	\$104,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Paymen Estimate Exception 8 on the current Payment Estimate.
					13	Oct 16, 2025	SYSTEM	(\$104,280.00)						
						13	Oct 16, 2025	SYSTEM	\$104,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kroekj1 overridding Paymen Estimate Exception 12 on the current Payment Estimate.				
				14 Nov 3, 2025		SYSTEM	(\$104,280.00)							
					14	Nov 3, 2025	SYSTEM	\$104,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Paymen Estimate Exception 7 on the current Payment Estimate.					
				- Total				\$0.00						
			Material - To	otal				\$0.00						



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
23 - ]	Total							\$0.00	
25 (	0770	ASPH. CONC. MIXTURE PG 70-22 (SP095C)	Material		13	Oct 16, 2025	SYSTEM	(\$12,300.00)	
		(310930)			13	Oct 16, 2025	SYSTEM	\$12,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kroekj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
9	0770 -	Total						\$0.00	
-	0790	FURNISHING TYPE 2 ROCK BLANKET	Material		12	Oct 1, 2025	SYSTEM	(\$6,420.00)	
					12	Oct 1, 2025	SYSTEM	\$6,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 9 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
-	0790 -	Total						\$0.00	
(	0810	IMPACT ATTENUATOR 60	Material		3	May 16, 2025	SYSTEM	(\$8,260.00)	
		MPH (SAND BARREL ARRAY)			3	May 16, 2025	SYSTEM	\$8,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
•	0810 -	Total						\$0.00	
(	0820	IMPACT ATTENUATOR 65 MPH (SAND	Material		3	May 16, 2025	SYSTEM	(\$4,625.00)	
		BARREL ARRAY)			3	May 16, 2025	SYSTEM	\$4,625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				\$0.00	
	0000	T-4-1	Material - To	otal				\$0.00	
	0820 -		Managint		0	M 40	OVOTEM	\$0.00	
	0850	WORK ZONE CRASH CUSHION (NARROW)	Material		3	May 16, 2025	SYSTEM	(\$42,600.00)	
					3	May 16	CVCTEM	\$42,600,00	This adjustment offsets the original system generated Material Payment
					3	May 16, 2025	SYSTEM	\$42,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.
				- Total	3		SYSTEM	\$42,600.00 \$0.00	Estimate Item Adjustment (0003) due to user hensor overridding Payment
			Material - To		3		SYSTEM	, ,	Estimate Item Adjustment (0003) due to user hensor overridding Payment
	0850 -	Total	Material - To		3		SYSTEM	\$0.00	Estimate Item Adjustment (0003) due to user hensor overridding Payment
		Total  CONSTRUCTION SIGNS	Material - To		3	2025	SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0003) due to user hensor overridding Payment
		CONSTRUCTION				2025 May 16,		\$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0003) due to user hensor overridding Payment
		CONSTRUCTION			3	May 16, 2025 May 16,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$16,048.00)	Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment
		CONSTRUCTION		otal - Total	3	May 16, 2025 May 16,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$16,048.00) \$16,048.00	Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment
		CONSTRUCTION SIGNS	Material	otal - Total	3	May 16, 2025 May 16,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$16,048.00) \$16,048.00	Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment
(	0880	CONSTRUCTION SIGNS  Total  ADVANCED WARNING RAIL	Material	otal - Total	3	May 16, 2025 May 16,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$16,048.00) \$16,048.00 \$0.00	Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment
(	0880 0880 -	CONSTRUCTION SIGNS  Total  ADVANCED	Material  Material - To	otal - Total	3	May 16, 2025  May 16, 2025  May 16, 2025	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$16,048.00) \$16,048.00 \$0.00 \$0.00	Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment
	0880 0880 -	CONSTRUCTION SIGNS  Total  ADVANCED WARNING RAIL	Material  Material - To	otal - Total	3 3 3	May 16, 2025 May 16, 2025 May 16, 2025 May 16,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$16,048.00) \$16,048.00 \$0.00 \$0.00 \$0.00 (\$550.00)	Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment
	0880 0880 -	CONSTRUCTION SIGNS  Total  ADVANCED WARNING RAIL	Material  Material - To	- Total	3 3 3	May 16, 2025 May 16, 2025 May 16, 2025 May 16,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$16,048.00) \$16,048.00 \$0.00 \$0.00 \$0.00 (\$550.00)	Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment
(	0880 0880 -	CONSTRUCTION SIGNS  Total  ADVANCED WARNING RAIL SYSTEM	Material - To	- Total	3 3 3	May 16, 2025 May 16, 2025 May 16, 2025 May 16,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$16,048.00) \$16,048.00 \$0.00 \$0.00 (\$550.00) \$550.00	Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment
	0880 - 0880 - 0890 -	CONSTRUCTION SIGNS  Total  ADVANCED WARNING RAIL SYSTEM	Material - To	- Total	3 3 3	May 16, 2025 May 16, 2025 May 16, 2025 May 16,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$16,048.00) \$16,048.00 \$0.00 \$0.00 (\$550.00) \$550.00	Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment



4 1:	Description	A -11:	Otto	F-4	0	0	A t	Danierius
t Li	ne Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
25 09	10 CHANNELIZER (TRIM-LINE)	Material			2025			Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
		Material - T	otal				\$0.00	
09	10 - Total						\$0.00	
09	20 TYPE 3 MOVEABLE BARRICADE	Material		3	May 16, 2025	SYSTEM	(\$3,000.00)	
				3	May 16, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
		Material - T	otal				\$0.00	
09	20 - Total						\$0.00	
09	INDICATOR	Material		3	May 16, 2025	SYSTEM	(\$3,000.00)	
	BARRICADE			3	May 16, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hensor overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
		Material - T	otal				\$0.00	
09	30 - Total						\$0.00	
09	40 FLASHING ARROW PANEL	Material		3	May 16, 2025	SYSTEM	(\$6,000.00)	
				3	May 16, 2025	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hensor overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
		Material - T	otal				\$0.00	
09	40 - Total						\$0.00	
09	50 SEQUENTIAL FLASHING WARNING LIGHT	Material		3	May 16, 2025	SYSTEM	(\$3,000.00)	
				3	May 16, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hensor overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
		Material - T	otal				\$0.00	
09	50 - Total 60 TUBULAR MARKER	Material		3	May 16,	SYSTEM	<b>\$0.00</b> (\$4,745.00)	
				3	2025 May 16, 2025	SYSTEM	\$4,745.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hensor overridding Payment
								Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
		Material - T	otal				\$0.00	
	60 - Total						\$0.00	
09	70 CHANGEABLE MESSAGE SIGN WITH	Material		3	May 16, 2025		(\$51,000.00)	
	COMMUNICATION INTERFACE, CONTRACTOR FURNISHED /			3	May 16, 2025	SYSTEM	\$51,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hensor overridding Payment Estimate Exception 12 on the current Payment Estimate.
	RETAINED		- Total				\$0.00	
		Material - T	otal				\$0.00	
09	70 - Total						\$0.00	
09	80 TEMPORARY LONG-TERM RUMBLE STRIPS	Material		3	May 16, 2025	SYSTEM	(\$7,400.00)	
	NOWIDLE STRIPS			3	May 16, 2025	SYSTEM	\$7,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hensor overridding Payment Estimate Exception 13 on the current Payment Estimate.
		- Total					\$0.00	
		Material - T	otal				\$0.00	



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks							
,			Туре	Adjustment Type	Number	Date	Ву									
J5P3525	0980	- Total						\$0.00								
	1000	CONCRETE TRAFFIC BARRIER, TYPE C	Material		7	Jul 16, 2025	SYSTEM	(\$66,700.00)								
		TIFEC			7	Jul 16, 2025	SYSTEM	\$66,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kroekj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					8	Aug 4, 2025	SYSTEM	(\$66,700.00)								
					8	Aug 4, 2025	SYSTEM	\$66,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kroekj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					9	Aug 19, 2025	SYSTEM	(\$66,700.00)								
					9	Aug 19, 2025	SYSTEM	\$66,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					10	Sep 2, 2025	SYSTEM	(\$66,700.00)								
					10	Sep 2, 2025	SYSTEM	\$66,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kroekj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.							
					11	Sep 16, 2025	SYSTEM	(\$66,700.00)								
					11	Sep 16, 2025	SYSTEM	\$66,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kroekj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.							
					12	Oct 1, 2025	SYSTEM	(\$66,700.00)								
							12	Oct 1, 2025	SYSTEM	\$66,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 10 on the current Payment Estimate.					
													13	Oct 16, 2025	SYSTEM	(\$66,700.00)
							13	Oct 16, 2025	SYSTEM	\$66,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kroekj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.					
					14	Nov 3, 2025	SYSTEM	(\$66,700.00)								
					14	Nov 3, 2025	SYSTEM	\$66,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Exception 9 on the current Payment Estimate.							
				- Total				\$0.00								
			Material - To	otal				\$0.00								
		- Total  TEMPORARY	Material		3	May 16,	SYSTEM	<b>\$0.00</b> (\$33,849.60)								
		TRAFFIC BARRIER, CONT. FURN/RE			3	2025 May 16, 2025	SYSTEM	\$33,849.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hensor overridding Payment							
				- Total				\$0.00	Estimate Exception 14 on the current Payment Estimate.							
			Material - To					\$0.00								
	1010	- Total	material - I					\$0.00								
	1020	TEMP. TRAFFIC BARRIER	Material		3	May 16, 2025	SYSTEM	(\$31,308.75)								
		ANCHORED., CONT			3	May 16, 2025	SYSTEM	\$31,308.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hensor overridding Payment Estimate Exception 15 on the current Payment Estimate.							
				- Total				\$0.00								
			Material - To	otal				\$0.00								
	1020	- Total						\$0.00								
	1060	6 IN. WHITE HIGH BUILD	Material		7	Jul 16, 2025	SYSTEM	(\$8,000.00)								
	W	WATERBORNE PAVEMENT MARKING PAINT,			7	Jul 16, 2025	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kroekj1 overridding Payment							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J5P3525	1060	TYPE L BEADS	Material						Estimate Exception 6 on the current Payment Estimate.											
					8	Aug 4, 2025	SYSTEM	(\$8,000.00)												
					8	Aug 4, 2025	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kroekj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.											
					9	Aug 19, 2025	SYSTEM	(\$8,000.00)												
					9	Aug 19, 2025	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.											
					10	Sep 2, 2025	SYSTEM	(\$8,000.00)												
					10	Sep 2, 2025	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kroekj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.											
					11	Sep 16, 2025	SYSTEM	(\$8,000.00)												
					11	Sep 16, 2025	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kroekj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.											
					12	Oct 1, 2025	SYSTEM	(\$8,000.00)												
					12	Oct 1, 2025	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate.											
					13	Oct 16, 2025	SYSTEM	(\$8,000.00)												
					13	Oct 16, 2025	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kroekj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.											
					14	Nov 3, 2025	SYSTEM	(\$8,000.00)												
					14	Nov 3, 2025	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hensor overridding Payment Estimate Exception 10 on the current Payment Estimate.											
				- Total				\$0.00												
	1060 -	Total	Material - To	otal				\$0.00 \$0.00												
	1070	6 IN. YELLOW HIGH BUILD	Material		7	Jul 16, 2025	SYSTEM	(\$5,600.00)												
		WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS			7	Jul 16, 2025	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.											
		THE E BEADO														8	Aug 4, 2025	SYSTEM	(\$5,600.00)	
													8	Aug 4, 2025	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					9	Aug 19, 2025	SYSTEM	(\$5,600.00)												
													9	Aug 19, 2025	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					10 10 11 11									10	Sep 2, 2025	SYSTEM	(\$5,600.00)			
														10	Sep 2, 2025	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.		
								11	Sep 16, 2025	SYSTEM	(\$5,600.00)									
																	11	Sep 16, 2025	SYSTEM	\$5,600.00
					12	Oct 1, 2025	SYSTEM	(\$5,600.00)												
						2025														



					1	-			
ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3525	1070	6 IN. YELLOW HIGH BUILD WATERBORNE	Material		12	Oct 1, 2025	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hensor overridding Payment Estimate Exception 16 on the current Payment Estimate.
		PAVEMENT MARKING PAINT, TYPE L BEADS			13	Oct 16, 2025	SYSTEM	(\$5,600.00)	
					13	Oct 16, 2025	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kroekj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					14	Nov 3, 2025	SYSTEM	(\$5,600.00)	
					14	Nov 3, 2025	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hensor overridding Payment Estimate Exception 11 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To					\$0.00	
	1070	Total	Waterial - 1	otai				\$0.00	
	1120	PERMANENT EROSION	Material		12	Oct 1, 2025	SYSTEM	(\$1,600.00)	
		CONTROL GEOTEXTILE			12	Oct 1, 2025	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hensor overridding Payment
				- Total				\$0.00	Estimate Exception 17 on the current Payment Estimate.
			Material - To	otal				\$0.00	
	1120 -	Total						\$0.00	
	1200	LATEX MODIFIED CONCRETE	Material		10	Sep 2, 2025	SYSTEM	(\$186,345.00)	
		WEARING SURFACE			10	Sep 2, 2025	SYSTEM	\$186,345.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kroekj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1200 -	Total						\$0.00	
	1330	LATEX MODIFIED CONCRETE WEARING	Material		10	Sep 2, 2025	SYSTEM	(\$186,345.00)	
		SURFACE			10	Sep 2, 2025	SYSTEM	\$186,345.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroekj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1330 -	Total						\$0.00	
	1350	SUPERSTRUCTURE REPAIR	Material		10	Sep 2, 2025	SYSTEM	(\$3,375.00)	
		(UNFORMED)			10	Sep 2, 2025	SYSTEM	\$3,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kroekj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					11	Sep 16, 2025	SYSTEM	(\$10,125.00)	
					11	Sep 16, 2025	SYSTEM	\$10,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kroekj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					12	Oct 1, 2025	SYSTEM	(\$10,125.00)	
					12	Oct 1, 2025	SYSTEM	\$10,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hensor overridding Payment Estimate Exception 18 on the current Payment Estimate.
					13	Oct 16, 2025	SYSTEM	(\$10,125.00)	
					13	Oct 16, 2025	SYSTEM	\$10,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kroekj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1350 -	Total						\$0.00	
								,	



March   Marc	Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
MATERIAL	.I5P3525	1420	SUPPLEMENTARY						(\$4,000,00)	
Protect   Prot			WEARING SURFACE				2025		, , , ,	This all the sea of the size o
1420 - Total			MATERIAL			б		SYSTEM	\$4,000.00	Estimate Item Adjustment (0001) due to user hensor overridding Payment
120 - Total					- Total				\$0.00	
STOP   SUPPLEMENTARY   Makeful				Material - To	otal				\$0.00	
VICE ARING		1420 -	Total						\$0.00	
MATERIAL		1510	WEARING	Material		4		SYSTEM	(\$4,000.00)	
S						4		SYSTEM	\$4,000.00	Estimate Item Adjustment (0001) due to user hensor overridding Payment
Estimate Item Agustment (0007) use to user troversid congregative to estimate Exemption 1 on the current Payment Estimate.						5		SYSTEM	(\$37,000.00)	
2025   SYSTEM   \$37,000.00   This adjustment offices the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Payment Estimate Estimate Exception 3 on the current Payment Estimate Estimate Exception 12 on the current Payment Estimate Estimate Estimate Exception 12 on the current Payment Estimate Estimate Estimate Exception 12 on the current Payment Estimate Estimate Estimate Exception 12 on the current Payment Estimate Estimate Estimate Exception 12 on the current Payment Estimate Estimate Estimate Exception 12 on the current Payment Estimate Estimate Estimate Exception 13 on the current Payment Estimate Estimate Exception 13 on the current Payment Estimate Estimate Exception 14 on the current Payment Estimate Estimate Exception 15 on the current Payment Estimate Estimate Esc						5		SYSTEM	\$37,000.00	Estimate Item Adjustment (0001) due to user browns1 overridding Payment
Total   S0.00						6		SYSTEM	(\$37,000.00)	
1510 - Total						6		SYSTEM	\$37,000.00	Estimate Item Adjustment (0002) due to user hensor overridding Payment
1510 - Total					- Total				\$0.00	
1520   CATE MODIFIED CONCRETE   2025   202				Material - To	otal				\$0.00	
CONCRETE   WEARING   SURFACE		1510 -	Total						\$0.00	
SURFACE   4   2025   SYSTEM   \$140,030.00   This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate.   Supplementation   S		1520	CONCRETE	Material		4		SYSTEM	(\$140,030.00)	
1520 - Total						4		SYSTEM	\$140,030.00	Estimate Item Adjustment (0002) due to user hensor overridding Payment
1620 - Total								\$0.00		
1600   SUPPLEMENTARY   Waterial				Material - To	otal				\$0.00	
SURFACE   MATERIAL		1520 -	Total						\$0.00	
MATERIAL   6		1600	WEARING	Material		6		SYSTEM	(\$5,000.00)	
1600 - Total   S0.00						6		SYSTEM	\$5,000.00	Estimate Item Adjustment (0003) due to user hensor overridding Payment
1640   Total					- Total				\$0.00	
1640 SLAB EDGE REPAIR (BRIDGES)    Material   7				Material - To	otal				\$0.00	
REPAIR (BRIDGES)		1600 -	Total						\$0.00	
Estimate Item Adjustment (0004) due to user kroekj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  **Total***  **So.00**    Material - Total***   So.00**   SUPPLEMENTARY WEARING SURFACE MATERIAL**    Material   Aun 2, 2025   SYSTEM   \$3,000.00		1640		Material		7		SYSTEM	(\$5,000.00)	
Total   \$0.00						7		SYSTEM	\$5,000.00	Estimate Item Adjustment (0004) due to user kroekj1 overridding Payment
Solid Registrate   Solid Regis					- Total				\$0.00	
SUPPLEMENTARY WEARING SURFACE MATERIAL   Material   4				Material - To						
1700 SUPPLEMENTARY WEARING SURFACE MATERIAL  4 Jun 2, 2025  4 Jun 2, 2025  5 SYSTEM \$3,000.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.  5 Jun 16, 2025  5 Jun 16, 2025  5 SYSTEM \$3,000.00  This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.  6 Jul 1, SYSTEM (\$18,000.00)		1640 -	Total							
MATERIAL  4 Jun 2, 2025 SYSTEM \$3,000.00 This adjustment (0003) due to user hensor overridding Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.  5 Jun 16, 2025 SYSTEM (\$3,000.00)  5 Jun 16, 2025 SYSTEM \$3,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user browns1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  6 Jul 1, SYSTEM (\$18,000.00)			SUPPLEMENTARY WEARING	Material		4		SYSTEM		
5 Jun 16, 2025 \$\frac{1}{2025}\$ \$1						4		SYSTEM	\$3,000.00	Estimate Item Adjustment (0003) due to user hensor overridding Payment
2025 Estimate Item Adjustment (0002) due to user browns1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  6 Jul 1, SYSTEM (\$18,000.00)						5		SYSTEM	(\$3,000.00)	
						5		SYSTEM	\$3,000.00	Estimate Item Adjustment (0002) due to user browns1 overridding Payment
						6		SYSTEM	(\$18,000.00)	



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		·	Туре	Adjustment Type	Number	Date	Ву		
J5P3525	1700	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material		6	Jul 1, 2025	SYSTEM	\$18,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.
		WATERIAL		- Total				\$0.00	
			Material - To	otal				\$0.00	
	1700	Total						\$0.00	
	1710	LATEX MODIFIED CONCRETE WEARING	Material		4	Jun 2, 2025	SYSTEM	(\$57,000.00)	
		SURFACE			4	Jun 2, 2025	SYSTEM	\$57,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 9 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1710 -	Total						\$0.00	
	1730	HALF-SOLE REPAIR	Material		7	Jul 16, 2025	SYSTEM	(\$141,480.00)	
					7	Jul 16, 2025	SYSTEM	\$141,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroekj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$141,480.00)	
					8	Aug 4, 2025	SYSTEM	\$141,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kroekj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					9	Aug 19, 2025	SYSTEM	(\$141,480.00)	
					9	Aug 19, 2025	SYSTEM	\$141,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 9 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$141,480.00)	
					10	Sep 2, 2025	SYSTEM	\$141,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kroekj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					11	Sep 16, 2025	SYSTEM	(\$141,480.00)	
					11	Sep 16, 2025	SYSTEM	\$141,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kroekj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					12	Oct 1, 2025	SYSTEM	(\$141,480.00)	
					12	Oct 1, 2025	SYSTEM	\$141,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hensor overridding Payment Estimate Exception 19 on the current Payment Estimate.
					13	Oct 16, 2025	SYSTEM	(\$141,480.00)	
					13	Oct 16, 2025	SYSTEM	\$141,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kroekj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					14	Nov 3, 2025	SYSTEM	(\$141,480.00)	
					14	Nov 3, 2025	SYSTEM	\$141,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hensor overridding Payment Estimate Exception 12 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1730	Total						\$0.00	
	1790	SUPPLEMENTARY WEARING	Material		4	Jun 2, 2025	SYSTEM	(\$9,000.00)	
		SURFACE MATERIAL			4	Jun 2, 2025	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Jun 16,	SYSTEM	(\$9,000.00)	23
						2025			



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
. 10,000	20	Bessiipuon	Туре	Adjustment Type	Number	Date	Ву	7 1110 4111	
J5P3525	1790	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material		5	Jun 16, 2025	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user browns1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Jul 1, 2025	SYSTEM	(\$33,000.00)	
					6	Jul 1, 2025	SYSTEM	\$33,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Total				\$0.00		
	1790 -	Total						\$0.00	
	1800	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		4	Jun 2, 2025	SYSTEM	(\$76,570.00)	
					4	Jun 2, 2025	SYSTEM	\$76,570.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 10 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Total				\$0.00		
	1800 -	Total						\$0.00	
	1830	HALF-SOLE REPAIR	Material		7	Jul 16, 2025	SYSTEM	(\$170,760.00)	
					7	Jul 16, 2025	SYSTEM	\$170,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kroekj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$170,760.00)	
					8	Aug 4, 2025	SYSTEM	\$170,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroekj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					9	Aug 19, 2025	SYSTEM	(\$170,760.00)	
					9	Aug 19, 2025	SYSTEM	\$170,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 10 on the current Payment Estimate.
					10	Sep 2, 2025	SYSTEM	(\$170,760.00)	
					10	Sep 2, 2025	SYSTEM	\$170,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kroekj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					11	Sep 16, 2025	SYSTEM	(\$170,760.00)	
					11	Sep 16, 2025	SYSTEM	\$170,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kroekj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					12	Oct 1, 2025	SYSTEM	(\$170,760.00)	
					12	Oct 1, 2025	SYSTEM	\$170,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hensor overridding Payment Estimate Exception 20 on the current Payment Estimate.
					13	Oct 16, 2025	SYSTEM	(\$170,760.00)	
					13	Oct 16, 2025	SYSTEM	\$170,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kroekj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					14	Nov 3, 2025	SYSTEM	(\$170,760.00)	
					14	Nov 3, 2025	SYSTEM	\$170,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hensor overridding Payment Estimate Exception 13 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1830 -	330 - Total							
	5001	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		6	Jul 1, 2025	SYSTEM	(\$16,747.50)	





J5P3525 &	5001	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material							
					6	Jul 1, 2025	SYSTEM	\$16,747.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					7	Jul 16, 2025	SYSTEM	(\$16,747.50)		
					7	Jul 16, 2025	SYSTEM	\$16,747.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kroekj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
					8	Aug 4, 2025	SYSTEM	(\$16,747.50)		
					8	Aug 4, 2025	SYSTEM	\$16,747.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kroekj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
					9	Aug 19, 2025	SYSTEM	(\$16,747.50)		
					9	Aug 19, 2025	SYSTEM	\$16,747.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 11 on the current Payment Estimate.	
					10	Sep 2, 2025	SYSTEM	(\$16,747.50)		
					10	Sep 2, 2025	SYSTEM	\$16,747.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kroekj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
					11	Sep 16, 2025	SYSTEM	(\$16,747.50)		
					11	Sep 16, 2025	SYSTEM	\$16,747.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kroekj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	
					12	Oct 1, 2025	SYSTEM	(\$16,747.50)		
					12	Oct 1, 2025	SYSTEM	\$16,747.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hensor overridding Payment Estimate Exception 21 on the current Payment Estimate.	
					13	Oct 16, 2025	SYSTEM	(\$16,747.50)		
					13	Oct 16, 2025	SYSTEM	\$16,747.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kroekj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	
					1	14	Nov 3, 2025	SYSTEM	(\$16,747.50)	
					14	Nov 3, 2025	SYSTEM	\$16,747.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate.	
				- Total				\$0.00		
			Material - Total					\$0.00		
	5001 -	Total						\$0.00		
J5P3525 - Total								\$0.00		
Overall - Total								\$0.00		



#### Contract Adjustments for Contract - 241213-D4A

Estimate Number	Project	Adjustment Type	Other Adjustment Type	Adjustment Amount	Adjustment Percentage by Project	Created Date	Created By	Comments
9	J5P3525	Incentive		\$105,000.00	100	August 19, 2025	hensor	Milestone - Calendar Time JSP F Liquidated Savings 2.0 J5P3525 Bridges A13074/A13075 & A16724/A16725. The incentive payment of \$7500.00 will be paid per day for each full day the work described above is completed prior to 165 calendar days and prior to May 21, 2026. The maximum amount paid as liquidated savings for Bridges A13074/A13075 & A16724/A16725 will not exceed \$105,000.00
9 - Total				\$105,000.00				
11	J5P3525	Incentive		\$105,000.00	100	September 16, 2025	kroekj1	Milestone - Calendar Time JSP E Liquidated Savings 2.0 J5P3525 Bridges A13052/A13053 Over Business Route 50. The incentive payment of \$7500.00 will be paid per day for each full day the work described above is completed prior to 85 calendar days and prior to May 21, 2026. The maximum amount paid as liquidated savings for Bridges A13052/A13053 will not exceed \$105,000.00.
11 - Total				\$105,000.00				
Overall - Total				\$210,000.00				

Revision 5/29/2025 Page 23 of 23