

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 16, 2025

Progress Estimate Number 5	Contract ID Prime Cont		13-D4A CBridge, LLC	Pay Perio		June 2, 2025 June 15, 2025	Original Contract Amount Net Change Order Amount Current Contract Amount	\$4,994,404.43 \$219,394.00 \$5,213,798.43
Approval Date								By User
June 16, 2025			Generated a	and Approved	(and shou	ld be considered	Draft) at the Project Office Level by	browns1
June 16, 2025		F	Reviewed and A	pproved (and	should be	considered Draf	t) at the Resident Engineer Level by	browns1
June 18, 2025				Reviewed	and Appr	oved at the Centi	ral Office Controllers Office Level by	ramses1
Original Completion	on Date	Current Co	mpletion Date	Act	ual Comp	letion Date	% of Current Contract Amoun	t Complete
December 1, 2	026	Decemb	per 1, 2026				26.72%	
	Co	ontract Informat	ional Dates				Milestones	
Date Description	Original C	ompletion Date	Current Com	pletion Date		No Milest	ones Exist for Contract	
Acceptance Date								
Awarded Date	January 8,	2025	January 8, 20	25				
Letting Date	December	13, 2024	December 13	, 2024				
Notice to Proceed Date	February 1	0, 2025	February 10, 2	2025				
Work Began Date								

Contract Total Pay	For Estimate No. 5				
		This Estimate	Previous	To Date	
241213-D4A					
	Total Posted Items Pay	\$393,860.55	\$999,507.84	\$1,393,368.39	
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$999,507.84	\$1,393,368.39	
Contract Total Pay	able This Estimate:	\$393,860.55			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3525	0840	6122030	IMPACT ATTENUATOR (RELOCATION)	EA	\$1,140.000	4	\$4,560.00
	0900	6161010	RELOCATED SIGNS	SQFT	\$7.250	534	\$3,871.50
	1030	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	LF	\$12.900	887	\$11,442.30
	1040	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	LF	\$17.650	331	\$5,842.15
	1050	6181000	MOBILIZATION	LS	\$175,000.000	0.250	\$43,750.00
	1080	6207001	PAVEMENT MARKING REMOVAL	LF	\$0.800	61,381	\$49,104.80
	1100	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	LF	\$0.800	27,491	\$21,992.80
	1400	2161501	REMOVAL OF ASPHALT WEARING SURFACE	SQFT	\$3.250	6,637	\$21,570.25
	1410	2161503	REMOVAL OF EXISTING DECK REPAIR	SQFT	\$15.000	300	\$4,500.00
	1450	7040104	HALF-SOLE REPAIR	SQFT	\$120.000	50	\$6,000.00
	1510	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	CY	\$1,000.000	33	\$33,000.00
	1530	7031004	DIAMOND GRINDING	SQYD	\$7.000	737	\$5,159.00
	1540	7040104	HALF-SOLE REPAIR	SQFT	\$120.000	12	\$1,440.00
	1560	7172054	OPEN CELL FOAM JOINT SEAL	LF	\$50.000	94	\$4,700.00
	1590	2161503	REMOVAL OF EXISTING DECK REPAIR	SQFT	\$20.000	109	\$2,180.00
	1630	7040104	HALF-SOLE REPAIR	SQFT	\$120.000	190	\$22,800.00
	1680	2161501	REMOVAL OF ASPHALT WEARING SURFACE	SQFT	\$3.250	2,863	\$9,304.75
	1690	2161503	REMOVAL OF EXISTING DECK REPAIR	SQFT	\$20.000	179	\$3,580.00
	1720	7031004	DIAMOND GRINDING	SQYD	\$7.500	300	\$2,250.00
	1730	7040104	HALF-SOLE REPAIR	SQFT	\$120.000	547	\$65,640.00
	1750	7172054	OPEN CELL FOAM JOINT SEAL	LF	\$70.000	35	\$2,450.00
Revision 5/29/2	025						Page 1 of 14

Revision 5/29/2025 Page 1 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 16, 2025

Progres Estimate Nu 5		ntract ID ime Contract	241213-D4A tor E & C Bridge, LLC	Pay Period Start Pay Period End	2, 2025 15, 2025	Net Chang	ontract Amount le Order Amount ontract Amount	\$4,994,404.43 \$219,394.00 \$5,213,798.43
Project Number	Line Number	Item Code	Item De	escription	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3525	1770	2161501	REMOVAL OF ASPHALT W	EARING SURFACE	SQFT	\$3.250	3,552	\$11,544.00
	1780	2161503	REMOVAL OF EXISTING D	ECK REPAIR	SQFT	\$18.000	213	\$3,834.00
	1810	7031004	DIAMOND GRINDING		SQYD	\$7.500	400	\$3,000.00
	1820	7040101	SUBSTRUCTURE REPAIR	(FORMED)	SQFT	\$215.000	10	\$2,150.00
	1830	7040104	HALF-SOLE REPAIR		SQFT	\$120.000	381	\$45,720.00
	1850	7172054	OPEN CELL FOAM JOINT	SEAL	LF	\$55.000	45	\$2,475.00
Project J5P3	525 - Total							\$393,860.55
Overall - Tota	ıl							\$393,860.55
Contract Adius	-4							

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

roject umber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
P3525	1510	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user browns1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	37	\$1,000.00	\$37,000.00
	1510	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material			-37	\$1,000.00	(\$37,000.00)
	1700	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user browns1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	3	\$1,000.00	\$3,000.00
	1700	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material			-3	\$1,000.00	(\$3,000.00)
	1790	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user browns1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	9	\$1,000.00	\$9,000.00
	1790	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material			-9	\$1,000.00	(\$9,000.00)
tal								\$0.00

Revision 5/29/2025 Page 2 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Co	ontract Project Inform	ation			
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work			
J5P3523	FAF 50-3(118)	3 Bridge rehabilitations	50	COLE	at Bolivar St. and Vetter L	n. in Jefferson City				
J5P3525	P3525 FAF 8 Bridge rehabilitations 54 COLE at various location near Jefferson City									
Totals b	y Job Nu	ımbers								
J5P3523				tem Pay	This Estimate \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	Previous \$31,250.00 \$0.00 \$31,250.00 \$0.00	To Date \$31,250.00 \$0.00 \$31,250.00 \$0.00			
	Liquida	entive ated Damages Contract Adjust	tments		\$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00			
J5P3525		l Item Pay Item Adjustme		tem Pay	This Estimate \$393,860.55 \$0.00 \$393,860.55	Previous \$968,257.84 \$0.00 \$968,257.84	To Date \$1,362,118.39 \$0.00 \$1,362,118.39			
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			

Revision 5/29/2025 Page 3 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 5050004, Project Item Line Number 1510, Material Set 5050004, Material 1054CXLE - Latex Emulsion Admixture @, Acceptance Action Generic 1054CXLE is insufficient.	Testing to be entered at later date.	browns1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 5050004, Project Item Line Number 1700, Material Set 5050004, Material 1054CXLE - Latex Emulsion Admixture @, Acceptance Action Generic 1054CXLE is insufficient.	Testing to be entered at a later date.	browns1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 5050004, Project Item Line Number 1790, Material Set 5050004, Material 1054CXLE - Latex Emulsion Admixture @, Acceptance Action Generic 1054CXLE is insufficient.	Testing to be entered at a later date.	browns1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 5050004, Project Item Line Number 1790, Material Set 5050004, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Testing to be entered at a later date.	browns1	Overridden

Revision 5/29/2025 Page 4 of 14



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ract F	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See report generated date)
213- J5	5P3523	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$54,000.00	\$0.0
		0001	0020	2072000	LINEAR GRADING CLASS 2	4.60	0.00	4.60	STA	0.00	\$1,750.00	\$0.0
		0001	0030	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	92.00	0.00	92.00	SQYD	0.00	\$15.00	\$0.0
		0001	0040	4133200	ULTRATHIN BONDED WEARING SURFACE, TYPE C	102.00	0.00	102.00	SQYD	0.00	\$150.00	\$0.0
		0001	0050	6081000	CONCRETE MEDIAN	0.60	0.00	0.60	SQYD	0.00	\$1,500.00	\$0.0
		0001	0060	6086004	CONCRETE SIDEWALK, 4 IN.	91.10	0.00	91.10	SQYD	0.00	\$90.00	\$0.0
		0001	0070	6091052	CURB AND GUTTER TYPE B	158.00	0.00	158.00	LF	0.00	\$60.00	\$0.
		0001	0800	6122040	WORK ZONE CRASH CUSHION (NARROW)	6.00	0.00	6.00	EA	0.00	\$7,100.00	\$0.
		0001	0090	6161005	CONSTRUCTION SIGNS	4,281.00	0.00	4,281.00	SQFT	0.00	\$8.00	\$0.
		0001	0100	6161008	ADVANCED WARNING RAIL SYSTEM	15.00	0.00	15.00	EA	0.00	\$55.00	\$0.
		0001	0110	6161010	RELOCATED SIGNS	1,124.00	0.00	1,124.00	SQFT	0.00	\$7.25	\$0.
		0001	0120	6161025	CHANNELIZER (TRIM-LINE)	250.00	0.00	250.00	EA	0.00	\$30.00	\$0.
		0001	0130	6161030	TYPE 3 MOVEABLE BARRICADE	59.00	0.00	59.00	EA	0.00	\$175.00	\$0.
		0001	0140	6161033	DIRECTION INDICATOR BARRICADE	29.00	0.00	29.00	EA	0.00	\$100.00	\$0.
		0001	0150	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	0.00	\$3,000.00	\$0.
		0001	0160	6161055	SEQUENTIAL FLASHING WARNING LIGHT	29.00	0.00	29.00	EA	0.00	\$100.00	\$0.
		0001	0170	6161070	TUBULAR MARKER	48.00	0.00	48.00	EA	0.00	\$65.00	\$0.
		0001	0180	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	8.00	0.00	8.00	EA	0.00	\$4,250.00	\$0.
		0001	0190	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	8.00	0.00	8.00	EA	0.00	\$1,850.00	\$0.
		0001	0200	6169901	MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM	1.00	0.00	1.00	LS	0.00	\$57,000.00	\$0.
		0001	0210	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	460.00	0.00	460.00	LF	0.00	\$145.00	\$0.
		0001	0220	6173100	CONCRETE TRAFFIC BARRIER, TYPE D	112.00	0.00	112.00	LF	0.00	\$225.00	\$0.
		0001	0230	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.25	\$125,000.00	\$31,250.
		0001	0240	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	1.00	0.00	1.00	EA	0.00	\$2,000.00	\$0.
		0001	0250	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	8,571.00	0.00	8,571.00	LF	0.00	\$0.80	\$0.
		0001	0260	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,601.00	0.00	7,601.00	LF	0.00	\$0.80	\$0.
		0001	0270	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	863.00	0.00	863.00	LF	0.00	\$5.00	\$0.
		0001	0280	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	123.00	0.00	123.00	LF	0.00	\$5.00	\$0.
		0001	0290	6207001	PAVEMENT MARKING REMOVAL	40,991.00	0.00	40,991.00	LF	0.00	\$0.80	\$0
		0001	0300	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	1.00	0.00	1.00	EA	0.00	\$500.00	\$0
		0001	0310	6208064A	TEMPORARY RAISED PAVEMENT MARKER	96.00	0.00	96.00	EA	0.00	\$5.00	\$0
		0001	0320	6208076 6221001	4 IN TEMPORARY PAVEMENT MARKING PAINT COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	17,866.00 102.00	0.00	17,866.00	SQYD	0.00	\$0.80 \$25.00	\$0. \$0.
		0001	0340	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$9,000.00	\$0
		0001	0350	8025006	MULCHING	0.40	0.00	0.40	ACRE	0.00	\$2,500.00	\$0
		0001	0360	8051000A	SEEDING - COOL SEASON GRASSES	0.40	0.00	0.40	ACRE	0.00	\$4,000.00	\$0
		0001	0370	8061016	SEDIMENT REMOVAL	5.00	0.00	5.00	CUYD	0.00	\$5.00	\$0
		0001	0380	8061017	TEMPORARY SEEDING	0.40	0.00	0.40	ACRE	0.00	\$2,500.00	\$0
		0001	0390	8061019	SILT FENCE	542.00	0.00	542.00	LF	0.00	\$2.80	\$0
		0040	0400	9035011A	ST-STRUCTURAL	160.00	0.00	160.00	SQFT	0.00	\$35.00	\$0
		0070	0410	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	28.00	0.00	28.00	SQFT	0.00	\$250.00	\$0.
		0070	0420	2161001	TOTAL SURFACE HYDRO DEMOLITION	962.00	0.00	962.00	SQYD	0.00	\$74.00	\$0.
		0070	0430	2161501	REMOVAL OF ASPHALT WEARING SURFACE	8,655.00	0.00	8,655.00	SQFT	0.00	\$3.25	\$0.
		0070	0440	2163000	PARTIAL REMOVAL OF EXISTING BRIDGE DECK	2,791.00	0.00	2,791.00	SQFT	0.00	\$38.00	\$0
		0070	0450	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.00	\$1,500.00	\$0
		0070	0460	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	150.00	0.00	150.00	SQYD	0.00	\$225.00	\$0
		0070	0470	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	5.00	0.00	5.00	CY	0.00	\$1,000.00	\$0
		0070	0480	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	708.00	0.00	708.00	SQYD	0.00	\$185.00	\$0
		0070	0490	6071068	(120 IN.) PEDESTRIAN FENCE (STRUCTURES)	329.00	0.00	329.00	LF	0.00	\$155.00	\$0
		0070	0500	7031004	DIAMOND GRINDING	708.00	0.00	708.00	SQYD	0.00	\$7.50	\$0
		0070	0510	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	2.50	0.00	2.50	CUYD	0.00	\$2,500.00	\$0
		0070	0510	7032003 7034219A	TYPE D BARRIER	657.00	0.00	657.00	LF	0.00	\$2,500.00	\$0
		0070	0520	7034219A 7034430			0.00	3,395.00	SQFT			\$0.
			UUUU	1034430	SIDEWALK (BRIDGES)	3,395.00	0.00	3,395.00	JULI	0.00	\$45.00	\$0

Revision 5/29/2025 Page 5 of 14



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

t Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See report generated date)
- J5P3523	0070	0550	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	212.00	0.00	212.00	SQFT	0.00	\$165.00	\$0.
	0070	0560	7040113	CLEANING AND EPOXY COATING	3,807.00	0.00	3,807.00	SQFT	0.00	\$5.93	\$0.
	0070	0570	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$8,500.00	\$0.
	0071	0580	2161001	TOTAL SURFACE HYDRO DEMOLITION	474.00	0.00	474.00	SQYD	0.00	\$74.00	\$0
	0071	0590	2161501	REMOVAL OF ASPHALT WEARING SURFACE	4,261.00	0.00	4,261.00	SQFT	0.00	\$2.25	\$0
	0071	0600	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	0.00	100.00	SQFT	0.00	\$25.00	\$0
	0071	0610	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	0.00	3.00	CY	0.00	\$1,000.00	\$0
	0071	0620	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	474.00	0.00	474.00	SQYD	0.00	\$220.00	\$0
	0071	0630	7031004	DIAMOND GRINDING	474.00	0.00	474.00	SQYD	0.00	\$8.00	\$0
	0071	0640	7040104	HALF-SOLE REPAIR	100.00	0.00	100.00	SQFT	0.00	\$125.00	\$0
	0071	0650	7040113	CLEANING AND EPOXY COATING	1,130.00	0.00	1,130.00	SQFT	0.00	\$7.70	\$0
	0071	0660	7172054	OPEN CELL FOAM JOINT SEAL	57.00	0.00	57.00	LF	0.00	\$95.00	\$0
	0072	0670	2161001	TOTAL SURFACE HYDRO DEMOLITION	474.00	0.00	474.00	SQYD	0.00	\$74.00	\$0
	0072	0680	2161501	REMOVAL OF ASPHALT WEARING SURFACE	4,261.00	0.00	4,261.00	SQFT	0.00	\$3.25	\$0
	0072	0690	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	0.00	100.00	SQFT	0.00	\$25.00	\$0
	0072	0700	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	0.00	3.00	CY	0.00	\$1,000.00	\$0
	0072	0710	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	474.00	0.00	474.00	SQYD	0.00	\$220.00	\$0
	0072	0720	7031004	DIAMOND GRINDING	474.00	0.00	474.00	SQYD	0.00	\$8.00	\$(
	0072	0730	7040104	HALF-SOLE REPAIR	100.00	0.00	100.00	SQFT	0.00	\$125.00	\$I
	0072	0740	7040113	CLEANING AND EPOXY COATING	1,130.00	0.00	1.130.00	SQFT	0.00	\$7.70	\$
	0072	0750	7172054	OPEN CELL FOAM JOINT SEAL	57.00	0.00	57.00	LF	0.00	\$95.00	\$1
Project	J5P3523 - To			Date as of Report Generated Date	01.00	0.00	07.00		0.00	ψ00.00	\$31.25
J5P3525	0004	0760	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.50	\$45,000.00	\$22,500
001 0020	0001	0770	4030003	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095C MIX)	8.20	0.00	8.20	TONS	0.00	\$1,500.00	\$22,000
	0001	0780	4071005	TACK COAT	8.00	0.00	8.00	GAL	0.00	\$50.00	\$
	0001	0790	6113020	FURNISHING TYPE 2 ROCK BLANKET	\$60.00	\$1					
	0001	0800	6113040	PLACING TYPE 2 ROCK BLANKET	107.00 107.00	0.00	107.00	CUYD	0.00	\$40.00	\$1
	0001	0810				0.00					\$8,26
	0001		6122014	IMPACT ATTENUATOR 60 MPH (SAND BARREL ARRAY)	2.00		2.00	EA	2.00	\$4,130.00	
	0001	0820	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	1.00	0.00	1.00	EA	1.00	\$4,625.00	\$4,62
	0001	0830	6122020	REPLACEMENT SAND BARREL	8.00	0.00	8.00	EA	0.00	\$495.00	\$1
	0001	0840	6122030	IMPACT ATTENUATOR (RELOCATION)	8.00	0.00	8.00	EA	4.00	\$1,140.00	\$4,56
	0001	0850	6122040	WORK ZONE CRASH CUSHION (NARROW)	6.00	0.00	6.00	EA	6.00	\$7,100.00	\$42,60
	0001	0860	6133018	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	5.60	0.00	5.60	TONS	0.00	\$1,200.00	\$1
		0870	6133019	REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	35.60	0.00	35.60	SQYD	0.00	\$100.00	\$
	0001	0880	6161005	CONSTRUCTION SIGNS	2,629.00	0.00	2,629.00	SQFT	2,006.00	\$8.00	\$16,04
	0001	0890	6161008	ADVANCED WARNING RAIL SYSTEM	14.00	0.00	14.00	EA	10.00	\$55.00	\$55
	0001	0900	6161010	RELOCATED SIGNS	2,434.00	0.00	2,434.00	SQFT	534.00	\$7.25	\$3,87
	0001	0910	6161025	CHANNELIZER (TRIM-LINE)	253.00	0.00	253.00	EA	253.00	\$30.00	\$7,59
	0001	0920	6161030	TYPE 3 MOVEABLE BARRICADE	31.00	0.00	31.00	EA	15.00	\$200.00	\$3,00
	0001	0930	6161033	DIRECTION INDICATOR BARRICADE	30.00	0.00	30.00	EA	30.00	\$100.00	\$3,00
	0001	0940	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,00
	0001	0950	6161055	SEQUENTIAL FLASHING WARNING LIGHT	30.00	0.00	30.00	EA	30.00	\$100.00	\$3,000
	0001	0960	6161070	TUBULAR MARKER	73.00	0.00	73.00	EA	73.00	\$65.00	\$4,74
	0001	0970	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	12.00	0.00	12.00	EA	12.00	\$4,250.00	\$51,00
	0001	0980	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	20.00	0.00	20.00	EA	4.00	\$1,850.00	\$7,40
	0001	0990	6169901	MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM	1.00	0.00	1.00	LS	0.80	\$95,750.00	\$76,60
	0001	1000	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	460.00	0.00	460.00	LF	0.00	\$145.00	\$
	0001	1010	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	688.00	0.00	688.00	LF	688.00	\$49.20	\$33,84
	0001	1020	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	575.00	0.00	575.00	LF	575.00	\$54.45	\$31,30
	0001	1030	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	1,775.00	0.00	1,775.00	LF	887.00	\$12.90	\$11,44
	0001	1040	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	663.00	0.00	663.00	LF	331.00	\$17.65	\$5,842
	0001	1050	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$175,000.00	\$131,25
	0001	1060	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	25,010.00	0.00	25,010.00	LF	0.00	\$0.80	\$1
	0001	1070	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	18,502.00	0.00	18,502.00	LF	0.00	\$0.80	\$

Revision 5/29/2025 Page 6 of 14



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ntract Proje	ect Catego	y Line	Item	Description	Bid	Net	Total	Unit	Total	Unit Price	Total Value POSTED
ID No		No.	Code	·	Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See report generated date)
1213- J5P35	525 0001	1080	6207001	PAVEMENT MARKING REMOVAL	102,340.00	0.00	102,340.00	LF	61,381.00	\$0.80	\$49,104.8
A	0001	1090	6208064A	TEMPORARY RAISED PAVEMENT MARKER	146.00	0.00	146.00	EA	0.00	\$5.00	\$0.0
	0001	1100	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	47,631.00	0.00	47,631.00	LF	27,491.00	\$0.80	\$21,992.8
	0001	1110	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	102.00	0.00	102.00	SQYD	0.00	\$30.00	\$0.0
	0001	1120	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	160.00	0.00	160.00	SQYD	0.00	\$10.00	\$0.0
	0001	1130	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$9,000.00	\$0.0
	0070	1140	2161000	SCARIFICATION OF BRIDGE DECK	227.00	0.00	227.00	SQYD	0.00	\$34.25	\$0.0
	0070	1150	2161001	TOTAL SURFACE HYDRO DEMOLITION	909.00	0.00	909.00	SQYD	0.00	\$70.00	\$0.0
	0070	1160	2161501	REMOVAL OF ASPHALT WEARING SURFACE	1,744.00	0.00	1,744.00	SQFT	0.00	\$3.25	\$0.
	0070	1170	2161502	REMOVAL OF CONCRETE WEARING SURFACE	4,392.00	0.00	4,392.00	SQFT	0.00	\$4.50	\$0.0
	0070	1180	2161503	REMOVAL OF EXISTING DECK REPAIR	50.00	0.00	50.00	SQFT	0.00	\$25.00	\$0.0
	0070	1190	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	4.00	0.00	4.00	CY	0.00	\$1,000.00	\$0.0
	0070	1200	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	909.00	0.00	909.00	SQYD	0.00	\$205.00	\$0.0
	0070	1210	7031004	DIAMOND GRINDING	909.00	0.00	909.00	SQYD	0.00	\$7.00	\$0.0
	0070	1220	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	5.00	0.00	5.00	SQFT	0.00	\$225.00	\$0.0
	0070	1230	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	15.00	0.00	15.00	SQFT	0.00	\$400.00	\$0.0
	0070	1240	7040104	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	0.00	\$120.00	\$0.0
	0070	1250	7040113	CLEANING AND EPOXY COATING	1,859.00	0.00	1,859.00	SQFT	0.00	\$6.51	\$0.
	0070	1260	7172054	OPEN CELL FOAM JOINT SEAL	99.00	0.00	99.00	LF	0.00	\$50.00	\$0.
	0071	1270	2161000	SCARIFICATION OF BRIDGE DECK	227.00	0.00	227.00	SQYD	0.00	\$34.25	\$0.0
	0071	1280	2161001	TOTAL SURFACE HYDRO DEMOLITION	909.00	0.00	909.00	SQYD	0.00	\$70.00	\$0.
	0071	1290	2161501	REMOVAL OF ASPHALT WEARING SURFACE	1,744.00	0.00	1,744.00	SQFT	0.00	\$3.25	\$0.
	0071	1300	2161502	REMOVAL OF CONCRETE WEARING SURFACE	4,392.00	0.00	4,392.00	SQFT	0.00	\$4.50	\$0.
	0071	1310	2161503	REMOVAL OF EXISTING DECK REPAIR	50.00	0.00	50.00	SQFT	0.00	\$25.00	\$0.
	0071	1320	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	4.00	0.00	4.00	CY	0.00	\$1,000.00	\$0.
	0071	1330	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	909.00	0.00	909.00	SQYD	0.00	\$205.00	\$0.
	0071	1340	7031004	DIAMOND GRINDING	909.00	0.00	909.00	SQYD	0.00	\$7.00	\$0.
	0071	1350	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	15.00	0.00	15.00	SQFT	0.00	\$225.00	\$0.
	0071	1360	7040103	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	0.00	\$120.00	\$0.
	0071	1370	7040113	CLEANING AND EPOXY COATING	1,859.00	0.00	1,859.00	SQFT	0.00	\$6.51	\$0.
	0071	1380	7172054	OPEN CELL FOAM JOINT SEAL	99.00	0.00	99.00	LF	0.00	\$50.00	\$0.
	0072	1390	2161001	TOTAL SURFACE HYDRO DEMOLITION	737.00	0.00	737.00	SQYD	0.00	\$70.00	\$0.
	0072	1400	2161501	REMOVAL OF ASPHALT WEARING SURFACE	6,637.00	0.00	6,637.00	SQFT	6,637.00	\$3.25	\$21,570.
	0072	1410	2161503		300.00	0.00		SQFT	300.00	\$15.00	
	0072	1410	5050004	REMOVAL OF EXISTING DECK REPAIR SUPPLEMENTARY WEARING SURFACE MATERIAL		0.00	300.00	CY			\$4,500.
	0072	1430	5050004		4.00 737.00	0.00	4.00	SQYD	0.00	\$1,000.00 \$190.00	\$0. \$0.
	0072			LATEX MODIFIED CONCRETE WEARING SURFACE DIAMOND GRINDING			737.00	SQYD			
	0072	1440	7031004		737.00	0.00	737.00		0.00	\$7.00	\$0.
	0072	1450 1460	7040104 7040113	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	50.00	\$120.00	\$6,000. \$8,709.
	0072			CLEANING AND EPOXY COATING	1,792.00	0.00	1,792.00	LF	1,792.00	\$4.86	
	0073	1470	7172054	OPEN CELL FOAM JOINT SEAL	94.00	0.00	94.00		0.00	\$50.00	\$0.
	0073	1480	2161001	TOTAL SURFACE HYDRO DEMOLITION	737.00	0.00	737.00	SQYD	737.00	\$70.00	\$51,590.
	0073	1490	2161501	REMOVAL OF ASPHALT WEARING SURFACE	6,637.00	0.00	6,637.00	SQFT	6,637.00	\$3.25	\$21,570.
	0073	1500	2161503	REMOVAL OF EXISTING DECK REPAIR	200.00	10.00	210.00	SQFT	200.00	\$20.00	\$4,000.
	0073	1510	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	4.00	33.00	37.00	CY	37.00	\$1,000.00	\$37,000.
	0073	1520	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	737.00	0.00	737.00	SQYD	737.00	\$190.00	\$140,030.
	0073	1530	7031004	DIAMOND GRINDING	737.00	0.00	737.00	SQYD	737.00	\$7.00	\$5,159.
	0073	1540	7040104	HALF-SOLE REPAIR	50.00	12.00	62.00	SQFT	62.00	\$120.00	\$7,440.
	0073	1550	7040113	CLEANING AND EPOXY COATING	1,792.00	0.00	1,792.00	SQFT	1,792.00	\$4.86	\$8,709.
	0073	1560	7172054	OPEN CELL FOAM JOINT SEAL	94.00	0.00	94.00	LF	94.00	\$50.00	\$4,700
		1570	2161001	TOTAL SURFACE HYDRO DEMOLITION	638.00	0.00	638.00	SQYD	0.00	\$70.00	\$0.
	0074	1580	2161501	REMOVAL OF ASPHALT WEARING SURFACE	5,748.00	0.00	5,748.00	SQFT	5,502.00	\$3.25	\$17,881.
	0074	1590	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	109.00	209.00	SQFT	209.00	\$20.00	\$4,180.
	0074	1600	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	5.00	0.00	5.00	CY	0.00	\$1,000.00	\$0.
	0074	1610	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	638.00	0.00	638.00	SQYD	0.00	\$190.00	\$0.
	0074	1620	7031004	DIAMOND GRINDING	638.00	0.00	638.00	SQYD	0.00	\$7.00	\$0.
	0074	1630	7040104	HALF-SOLE REPAIR	100.00	190.00	290.00	SQFT	290.00	\$120.00	\$34,800.
	0074	1640	7040107	SLAB EDGE REPAIR (BRIDGES)	10.00	0.00	10.00	LF	0.00	\$500.00	\$0.

Revision 5/29/2025 Page 7 of 14



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ntract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
1213-	J5P3525	0074	1650	7040113	CLEANING AND EPOXY COATING	700.00	0.00	700.00	SQFT	700.00	\$11.48	\$8,036.00
A		0074	1660	7172054	OPEN CELL FOAM JOINT SEAL	89.00	0.00	89.00	LF	0.00	\$50.00	\$0.00
		0075	1670	2161001	TOTAL SURFACE HYDRO DEMOLITION	611.00	0.00	611.00	SQYD	0.00	\$70.00	\$0.00
		0075	1680	2161501	REMOVAL OF ASPHALT WEARING SURFACE	5,502.00	0.00	5,502.00	SQFT	5,502.00	\$3.25	\$17,881.50
		0075	1690	2161503	REMOVAL OF EXISTING DECK REPAIR	250.00	179.00	429.00	SQFT	429.00	\$20.00	\$8,580.00
		0075	1700	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	15.00	18.00	CY	3.00	\$1,000.00	\$3,000.00
		0075	1710	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	611.00	0.00	611.00	SQYD	300.00	\$190.00	\$57,000.00
		0075	1720	7031004	DIAMOND GRINDING	611.00	0.00	611.00	SQYD	300.00	\$7.50	\$2,250.00
		0075	1730	7040104	HALF-SOLE REPAIR	50.00	547.00	597.00	SQFT	597.00	\$120.00	\$71,640.00
		0075	1740	7040113	CLEANING AND EPOXY COATING	500.00	0.00	500.00	SQFT	500.00	\$6.21	\$3,105.00
		0075	1750	7172054	OPEN CELL FOAM JOINT SEAL	71.00	0.00	71.00	LF	35.00	\$70.00	\$2,450.00
		0076	1760	2161001	TOTAL SURFACE HYDRO DEMOLITION	803.00	0.00	803.00	SQYD	408.00	\$70.00	\$28,560.00
		0076	1770	2161501	REMOVAL OF ASPHALT WEARING SURFACE	7,227.00	0.00	7,227.00	SQFT	7,227.00	\$3.25	\$23,487.75
		0076	1780	2161503	REMOVAL OF EXISTING DECK REPAIR	300.00	213.00	513.00	SQFT	513.00	\$18.00	\$9,234.00
		0076	1790	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	9.00	26.00	35.00	CY	9.00	\$1,000.00	\$9,000.0
		0076	1800	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	803.00	0.00	803.00	SQYD	403.00	\$190.00	\$76,570.0
		0076	1810	7031004	DIAMOND GRINDING	803.00	0.00	803.00	SQYD	400.00	\$7.50	\$3,000.0
		0076	1820	7040101	SUBSTRUCTURE REPAIR (FORMED)	10.00	0.00	10.00	SQFT	10.00	\$215.00	\$2,150.0
		0076	1830	7040104	HALF-SOLE REPAIR	500.00	381.00	881.00	SQFT	881.00	\$120.00	\$105,720.0
		0076	1840	7040113	CLEANING AND EPOXY COATING	750.00	0.00	750.00	SQFT	0.00	\$6.21	\$0.0
		0076	1850	7172054	OPEN CELL FOAM JOINT SEAL	90.00	0.00	90.00	LF	45.00	\$55.00	\$2,475.00
		0077	1860	2061000	CLASS 1 EXCAVATION	23.00	0.00	23.00	CUYD	0.00	\$250.00	\$0.00
		0077	1870	2161001	TOTAL SURFACE HYDRO DEMOLITION	684.00	0.00	684.00	SQYD	0.00	\$74.00	\$0.00
		0077	1880	2161502	REMOVAL OF CONCRETE WEARING SURFACE	6,160.00	0.00	6,160.00	SQFT	0.00	\$4.25	\$0.00
		0077	1890	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	2.00	0.00	2.00	CY	0.00	\$1,000.00	\$0.00
		0077	1900	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	684.00	0.00	684.00	SQYD	0.00	\$200.00	\$0.00
		0077	1910	7031004	DIAMOND GRINDING	684.00	0.00	684.00	SQYD	0.00	\$8.00	\$0.00
		0077	1920	7039907	MISC.SELF-CONSOLIDATING CONCRETE	11.00	0.00	11.00	CUYD	0.00	\$1,800.00	\$0.00
		0077	1930	7040104	HALF-SOLE REPAIR	100.00	0.00	100.00	SQFT	0.00	\$120.00	\$0.00
		0077	1940	7040113	CLEANING AND EPOXY COATING	2,600.00	0.00	2,600.00	SQFT	0.00	\$7.08	\$0.00
		0077	1950	7101000	REINFORCING STEEL (EPOXY COATED)	1,210.00	0.00	1,210.00	LB	0.00	\$5.00	\$0.00
		0077	1960	7172054	OPEN CELL FOAM JOINT SEAL	92.00	0.00	92.00	LF	0.00	\$55.00	\$0.0
	Project J	5P3525 - <u>To</u>	tal Val <u>ue</u>	Posted to I	Date as of Report Generated Date							\$1,362,118.39
1213 ₋ D					s of Report Generated Date							\$1,393,368.39

Revision 5/29/2025 Page 8 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5P3525

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0840	6122030	IMPACT ATTENUATOR (RELOCATION)	6/4/25	6/13/25	1	4.00	EA	Phase 4 & 5 traffic switch Hwy 54					
0900	6161010	RELOCATED SIGNS	6/4/25	6/13/25	1	534.00	SQFT	Phase 4 & 5 traffic switch Hwy 54					
1030	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	6/4/25	6/13/25	1	887.00	LF	Phase 4 & 5 traffic switch Hwy 54					
1040	6175011B	RELOC TEMPORARY TRAFFIC BARRIER ANCHORED	6/4/25	6/13/25	- 1	331.00	LF	Phase 4 & 5 traffic switch Hwy 54					
1050	6181000	MOBILIZATION	6/4/25	6/13/25	1	0.25	LS	Phase 4 & 5 traffic switch Hwy 54					
1080	6207001	PAVEMENT MARKING REMOVAL	6/4/25	6/13/25	1	61,381.00	LF	Phase 4 & 5 traffic switch Hwy 54					
1100	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	6/4/25	6/13/25	1	27,491.00	LF	Phase 4 & 5 traffic switch Hwy 54					
1400	2161501	REMOVAL OF ASPHALT WEARING SURFACE	6/4/25	6/13/25	1	6,637.00	SQFT	Bridge A13074					
1410	2161503	REMOVAL OF EXISTING DECK REPAIR	6/10/25	6/13/25	- 1	300.00	SQFT	Bridge A13074					
1450	7040104	HALF-SOLE REPAIR	6/12/25	6/13/25	1	50.00	SQFT	Bridge A13074					
1510	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	6/12/25	6/13/25	1	33.00	CY	Bridge A13075					overrun quantity from CO 01
1530	7031004	DIAMOND GRINDING	6/3/25	6/13/25	1	737.00	SQYD	Bridge A13075					
1540	7040104	HALF-SOLE REPAIR	6/12/25	6/13/25	- 1	12.00	SQFT	Bridge A13075					overrun quantity from CO 01
1560	7172054	OPEN CELL FOAM JOINT SEAL	6/2/25	6/13/25	- 1	94.00	LF	Bridge A13075					
1590	2161503	REMOVAL OF EXISTING DECK REPAIR	6/2/25	6/13/25	- 1	109.00	SQFT	Bridge A13092					
1630	7040104	HALF-SOLE REPAIR	6/2/25	6/13/25	1	190.00	SQFT	Bridge A13092					
1680	2161501	REMOVAL OF ASPHALT WEARING SURFACE	6/4/25	6/13/25	- 1	2,863.00	SQFT	Bridge A16724 driving lane					
1690	2161503	REMOVAL OF EXISTING DECK REPAIR	6/10/25	6/13/25	1	179.00	SQFT	Bridge A16724					Phase 4 - 286 sqft Phase 5 - 538 sqft = 824 sqft total Plan quantity 250 + change order 179 = 429 sqft
1720	7031004	DIAMOND GRINDING	6/3/25	6/13/25	- 1	300.00	SQYD	Bridge A16724 Passing Lane					
1730	7040104	HALF-SOLE REPAIR	6/12/25	6/13/25	1	547.00	SQFT	Bridge A16724					Phase 4 - 398 sqft Phase 5 - 716 sqft = 1114 sqft total Plan quantity 50 + change order 547 = 597 sqft
1750	7172054	OPEN CELL FOAM JOINT SEAL	6/2/25	6/13/25	1	35.00	LF	Bridge A16724 Passing Lane					
1770	2161501	REMOVAL OF ASPHALT WEARING SURFACE	6/4/25	6/13/25	1	3,552.00	SQFT	Bridge A16725 driving lane					
1780	2161503	REMOVAL OF EXISTING DECK REPAIR	6/10/25	6/13/25	1	213.00	SQFT	Bridge A16725					Phase 4 - 342 sqft Phase 5 - 602 sqft = 944 sqft total Plan quantity 300 + change order 213 = 513 sqft
1810	7031004	DIAMOND GRINDING	6/3/25	6/13/25	1	400.00	SQYD	Bridge A16725 Passing Lane					
1820	7040101	SUBSTRUCTURE REPAIR (FORMED)	6/3/25	6/13/25	1	10.00	SQFT	Bridge A16725 at Bent 1					
1830	7040104	HALF-SOLE REPAIR	6/12/25	6/13/25	1	381.00	SQFT	Bridge A16725					Phase 4 - 754 sqft Phase 5 - 257 sqft = 1011 sqft total Plan quantity 500 + change order 381 = 881 sqft
1850	7172054	OPEN CELL FOAM JOINT SEAL	6/2/25	6/13/25	1	45.00	LF	Bridge A16724 Passing Lane					

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 6/5/2025 Page 9 of 14



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3525	0810	IMPACT ATTENUATOR 60	Material		3	May 16, 2025	SYSTEM	(\$8,260.00)	
		MPH (SAND BARREL ARRAY)			3	May 16, 2025	SYSTEM	\$8,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0810 -	- Total						\$0.00	
	0820	IMPACT ATTENUATOR 65	Material		3	May 16, 2025	SYSTEM	(\$4,625.00)	
		MPH (SAND BARREL ARRAY)			3	May 16, 2025	SYSTEM	\$4,625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0820 -	- Total						\$0.00	
	0850	WORK ZONE CRASH CUSHION	Material		3	May 16, 2025	SYSTEM	(\$42,600.00)	
		(NARROW)			3	May 16, 2025	SYSTEM	\$42,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0850 -	- Total						\$0.00	
	0880	CONSTRUCTION SIGNS	Material		3	May 16, 2025	SYSTEM	(\$16,048.00)	
					3	May 16, 2025	SYSTEM	\$16,048.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0880	- Total	Material - To	otal				\$0.00 \$0.00	
	0880 -	-Total ADVANCED WARNING RAIL SYSTEM	Material - To	otal	3	May 16, 2025	SYSTEM	\$0.00 (\$550.00)	
		ADVANCED WARNING RAIL		otal	3		SYSTEM SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.
		ADVANCED WARNING RAIL		otal - Total		2025 May 16,		\$0.00 (\$550.00)	Estimate Item Adjustment (0005) due to user hensor overridding Payment
		ADVANCED WARNING RAIL		- Total		2025 May 16,		\$0.00 (\$550.00) \$550.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment
	0890	ADVANCED WARNING RAIL	Material	- Total		2025 May 16,		\$0.00 (\$550.00) \$550.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment
	0890	ADVANCED WARNING RAIL SYSTEM	Material	- Total		2025 May 16, 2025		\$0.00 (\$550.00) \$550.00 \$0.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment
	0890	ADVANCED WARNING RAIL SYSTEM -Total CHANNELIZER	Material Material - To	- Total	3	2025 May 16, 2025	SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment
	0890	ADVANCED WARNING RAIL SYSTEM -Total CHANNELIZER	Material Material - To	- Total	3	2025 May 16, 2025 May 16, 2025 May 16,	SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00)	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment
	0890	ADVANCED WARNING RAIL SYSTEM -Total CHANNELIZER	Material Material - To	- Total otal - Total	3	2025 May 16, 2025 May 16, 2025 May 16,	SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00)	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment
	0890	ADVANCED WARNING RAIL SYSTEM - Total CHANNELIZER (TRIM-LINE)	Material Material - To	- Total otal - Total	3	2025 May 16, 2025 May 16, 2025 May 16,	SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$7,590.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment
	0890 0890 0910	ADVANCED WARNING RAIL SYSTEM - Total CHANNELIZER (TRIM-LINE) - Total TYPE 3 MOVEABLE	Material Material - To	- Total otal - Total	3	2025 May 16, 2025 May 16, 2025 May 16,	SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$7,590.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment
	0890 - 0910 - 0910 -	ADVANCED WARNING RAIL SYSTEM - Total CHANNELIZER (TRIM-LINE) - Total TYPE 3	Material - To	- Total otal - Total	3 3 3	2025 May 16, 2025 May 16, 2025 May 16, 2025	SYSTEM SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$7,590.00 \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment
	0890 - 0910 - 0910 -	ADVANCED WARNING RAIL SYSTEM - Total CHANNELIZER (TRIM-LINE) - Total TYPE 3 MOVEABLE	Material - To	- Total otal - Total	3 3 3	May 16, 2025	SYSTEM SYSTEM SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$0.00 \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment
	0890 - 0910 - 0910 -	ADVANCED WARNING RAIL SYSTEM - Total CHANNELIZER (TRIM-LINE) - Total TYPE 3 MOVEABLE	Material - To	- Total - Total otal - Total	3 3 3	May 16, 2025	SYSTEM SYSTEM SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$7,590.00 \$0.00 \$0.00 (\$3,000.00)	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment
	0890 0890 0910 0920	ADVANCED WARNING RAIL SYSTEM - Total CHANNELIZER (TRIM-LINE) - Total TYPE 3 MOVEABLE	Material - To	- Total - Total otal - Total	3 3 3	May 16, 2025	SYSTEM SYSTEM SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$7,590.00 \$0.00 \$0.00 \$3,000.00)	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment
	0890 0890 0910 0920	ADVANCED WARNING RAIL SYSTEM - Total CHANNELIZER (TRIM-LINE) - Total TYPE 3 MOVEABLE BARRICADE	Material - To	- Total - Total otal - Total	3 3 3	May 16, 2025 May 16, 2025	SYSTEM SYSTEM SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$7,590.00 \$0.00 \$0.00 (\$3,000.00) \$3,000.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
I5P3525	0930	DIRECTION	Material	Туре					Estimate Exception 8 on the current Payment Estimate.
		INDICATOR BARRICADE		- Total				\$0.00	
		B) II (I (I O) I D L	Material - T	otal				\$0.00	
	0930 -) - Total						\$0.00	
	0940	FLASHING ARROW PANEL	Material		3	May 16, 2025	SYSTEM	(\$6,000.00)	
		ANNOW PANEL			3	May 16, 2025	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hensor overridding Payment Estimate Exception 9 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0940	- Total						\$0.00	
	0950	SEQUENTIAL FLASHING	Material		3	May 16, 2025	SYSTEM	(\$3,000.00)	
		WARNING LIGHT			3	May 16, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hensor overridding Payment Estimate Exception 10 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0950	- Total						\$0.00	
	0960	TUBULAR MARKER	Material		3	May 16, 2025	SYSTEM	(\$4,745.00)	
					3	May 16, 2025	SYSTEM	\$4,745.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hensor overridding Payment Estimate Exception 11 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0960 -	- Total							
	0970	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material		3	May 16, 2025	SYSTEM	(\$51,000.00)	
			ON		3	May 16, 2025	SYSTEM	\$51,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hensor overridding Payment Estimate Exception 12 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Total					\$0.00	
	0970 -	- Total						\$0.00	
	0980	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		3	May 16, 2025	SYSTEM	(\$7,400.00)	
					3	May 16, 2025	SYSTEM	\$7,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hensor overridding Payment Estimate Exception 13 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Total					\$0.00	
	0980 -	- Total TEMPORARY	Material		3	May 16,	SYSTEM	\$0.00 (\$33,849.60)	
	1010	TRAFFIC BARRIER, CONT. FURN/RE			3	2025 May 16,	SYSTEM	\$33,849.60	This adjustment offsets the original system-generated Material Payment
						2025			Estimate Item Adjustment (0014) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
		Total TEMP. TRAFFIC	Material		3	May 16	SYSTEM	\$0.00 (\$31,308.75)	
	1020	BARRIER ANCHORED.,	Material			2025			
		CONT			3	May 16,	SYSTEM	\$31,308.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hensor overridding Payment
		CONT				2025			Estimate Exception 15 on the current Payment Estimate.
		CONT	Material - T	- Total		2025		\$0.00 \$0.00	



Dun't at	Line	December	A -1:	Other	F-4	0	0	A	Davisada
Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J5P3525	1020 -	Total		Туре				\$0.00	
			Matarial		4	lum O	OVOTEM		
	1510	SUPPLEMENTARY WEARING SURFACE	Material		4	Jun 2, 2025	SYSTEM	(\$4,000.00)	
		MATERIAL			4	Jun 2, 2025	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jun 16, 2025	SYSTEM	(\$37,000.00)	
					5	Jun 16, 2025	SYSTEM	\$37,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user browns1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1510 -	Total						\$0.00	
	1520	LATEX MODIFIED CONCRETE	Material		4	Jun 2, 2025	SYSTEM	(\$140,030.00)	
		WEARING SURFACE			4	Jun 2, 2025	SYSTEM	\$140,030.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 8 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To					\$0.00	
	1520 -	Total						\$0.00	
	1700	SUPPLEMENTARY	Material		4	Jun 2,	SYSTEM	(\$3,000.00)	
		WEARING	matorial		·	2025	0.0.2	(\$0,000.00)	
		SURFACE MATERIAL			4	Jun 2, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Jun 16, 2025	SYSTEM	(\$3,000.00)	
					5	Jun 16, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user browns1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1700 -	Total						\$0.00	
	1710	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		4	Jun 2, 2025	SYSTEM	(\$57,000.00)	
					4	Jun 2, 2025	SYSTEM	\$57,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total					\$0.00	
			Material - Total					\$0.00	
	1710 -	Total						\$0.00	
	1790	SUPPLEMENTARY WEARING SURFACE MATERIAL	Material		4	Jun 2, 2025	SYSTEM	(\$9,000.00)	
					4	Jun 2, 2025	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Jun 16, 2025	SYSTEM	(\$9,000.00)	
					5	Jun 16, 2025	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user browns1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	Material - Total					
	1790 -	Total						\$0.00	
	1800	LATEX MODIFIED CONCRETE	Material		4	Jun 2, 2025	SYSTEM	(\$76,570.00)	
		WEARING SURFACE			4	Jun 2, 2025	SYSTEM	\$76,570.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3525	1800	LATEX MODIFIED CONCRETE WEARING SURFACE	Material	- Total				\$0.00	
			Material - To	otal				\$0.00	
	1800 -	Total						\$0.00	
J5P3525 -	- Total						\$0.00		
Overall -	Total						\$0.00		

MoDOT

Contract Adjustments for Contract - 241213-D4A

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 14 of 14