

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 16, 2025

Progress Estimate Number 7	Contract ID Prime Cont		13-D4A C Bridge, LLC	Pay Perio			, 2025 5, 2025	Net C	nal Contract A hange Order nt Contract A	\$56	94,404.43 65,114.50 59,518.93	
Approval Date											By U	Iser
July 16, 2025			Generated ar	nd Approved	d (and shoul	ld be co	onsidere	d Draft) a	t the Project C	Office Level by		kroekj1
July 16, 2025			Reviewed and Ap	proved (and	d should be	consid	ered Dra	ft) at the	Resident Engi	ineer Level by		browns1
July 18, 2025				Reviewed	d and Appro	oved at	the Cen	tral Office	Controllers C	Office Level by		ramses1
Original Completion	on Date	Current Co	mpletion Date Actual Completion Date					%	of Current C	ontract Amo	unt Comple	te
December 1, 2	026	Decem	er 1, 2026						45.62%			
	C	ontract Informat	tional Dates						Mile	estones		
Date Description	Original C	ompletion Date	Current Compl	etion Date				ate	Original	Current	Days	Diary
Acceptance Date							Desc	ription	Completion Date	Completion Date	Remaining	Charge Days
Awarded Date	January 8,	2025	January 8, 2025						Juio	2410	Milestone	Dayo
Letting Date	December	13, 2024	December 13, 2	024			Milestor	-	October	October	90	
Notice to Proceed Date	February 1	0, 2025	February 10, 20	25			Calenda JSP F	ir i ime	16, 2025	16, 2025		
Work Began Date	May 5, 202	5	May 5, 2025				Liquidat Savings	2.0				
							J5P352 Bridges	5				

Contract Total Page	y For Estimate No. 7			
		This Estimate	Previous	To Date
241213-D4A				
	Total Posted Items Pay	\$515,251.55	\$2,021,125.89	\$2,536,377.44
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•	-	\$2,021,125.89	\$2,536,377.44
Contract Total Pay	yable This Estimate:	\$515,251.55		

Contract To	otal Payabl	e This Estir	nate: \$515,251.55			. ,,.	
tems Paid 1	<u> This Estima</u>	te Period					
Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3525	0760	2022010	REMOVAL OF IMPROVEMENTS	LS	\$45,000.000	0.250	\$11,250.00
	0840	6122030	IMPACT ATTENUATOR (RELOCATION)	EA	\$1,140.000	2	\$2,280.00
	0880	6161005	CONSTRUCTION SIGNS	SQFT	\$8.000	589	\$4,712.00
	0900	6161010	RELOCATED SIGNS	SQFT	\$7.250	793	\$5,749.25
	1000	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	LF	\$145.000	460	\$66,700.00
	1030	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	LF	\$12.900	687	\$8,862.30
	1060	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$0.800	10,000	\$8,000.00
	1070	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$0.800	7,000	\$5,600.00
	1080	6207001	PAVEMENT MARKING REMOVAL	LF	\$0.800	14,000	\$11,200.00
	1100	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	LF	\$0.800	8,000	\$6,400.00
	1160	2161501	REMOVAL OF ASPHALT WEARING SURFACE	SQFT	\$3.250	880	\$2,860.00
	1170	2161502	REMOVAL OF CONCRETE WEARING SURFACE	SQFT	\$4.500	2,200	\$9,900.00
	1290	2161501	REMOVAL OF ASPHALT WEARING SURFACE	SQFT	\$3.250	880	\$2,860.00
	1300	2161502	REMOVAL OF CONCRETE WEARING SURFACE	SQFT	\$4.500	2,200	\$9,900.00
	1410	2161503	REMOVAL OF EXISTING DECK REPAIR	SQFT	\$15.000	45	\$675.00
	1420	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	CY	\$1,000.000	20	\$20,000.00
	1440	7031004	DIAMOND GRINDING	SQYD	\$7.000	737	\$5,159.00
	1450	7040104	HALF-SOLE REPAIR	SQFT	\$120.000	348	\$41,760.00
	1470	7172054	OPEN CELL FOAM JOINT SEAL	LF	\$50.000	94	\$4,700.00

Revision 5/29/2025 Page 1 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 16, 2025

Progr Estimate 7		Contract II Prime Con	_	241213-D4A E & C Bridge, LLC	Pay Period Start Pay Period End	July 1, 2025 July 15, 2025	Net Net	ginal Contract Change Orde rent Contract	r Amount	\$4,994,404.43 \$565,114.50 \$5,559,518.93
Project Number	Line Number	Item Code		Item	Description		Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3525	1600	5050004	SUPPLE	MENTARY WEARING	SURFACE MATERIAL		CY	\$1,000.000	26	\$26,000.00
	1620	7031004	DIAMON	ID GRINDING			SQYD	\$7.000	638	\$4,466.00
	1630	7040104	HALF-S	OLE REPAIR			SQFT	\$120.000	599	\$71,880.00
	1640	7040107	SLAB E	DGE REPAIR (BRIDGE	S)		LF	\$500.000	10	\$5,000.00
	1660	7172054	OPEN C	ELL FOAM JOINT SEA	L		LF	\$50.000	89	\$4,450.00
	1690	2161503	REMOV	AL OF EXISTING DEC	K REPAIR		SQFT	\$20.000	395	\$7,900.00
	1700	5050004	SUPPLE	EMENTARY WEARING	SURFACE MATERIAL		CY	\$1,000.000	11	\$11,000.00
	1720	7031004	DIAMON	ID GRINDING			SQYD	\$7.500	311	\$2,332.50
	1730	7040104	HALF-S	OLE REPAIR			SQFT	\$120.000	582	\$69,840.00
	1750	7172054	OPEN C	ELL FOAM JOINT SEA	L		LF	\$70.000	36	\$2,520.00
	1780	2161503	REMOV	AL OF EXISTING DEC	K REPAIR		SQFT	\$18.000	431	\$7,758.00
	1790	5050004	SUPPLE	EMENTARY WEARING	SURFACE MATERIAL		CY	\$1,000.000	3	\$3,000.00
	1810	7031004	DIAMON	ID GRINDING			SQYD	\$7.500	403	\$3,022.50
	1830	7040104	HALF-S	OLE REPAIR			SQFT	\$120.000	542	\$65,040.00
	1850	7172054	OPEN C	ELL FOAM JOINT SEA	L		LF	\$55.000	45	\$2,475.00
Project J5F	2 <mark>3525 - Tot</mark>	al								\$515,251.55
Overall - To	otal									\$515,251.55
Contract Ad	justments	This Estima	ite							

Contract Adjustments This Estimate

No Contra	ct Adjus	stments Exist on Contract						
Line Item	<u>Adjust</u>	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3525	1000	CONCRETE TRAFFIC BARRIER, TYPE C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user kroekj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	460	\$145.00	\$66,700.00
	1000	CONCRETE TRAFFIC BARRIER, TYPE C	Material			-460	\$145.00	(\$66,700.00)
	1060	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user kroekj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	10,000	\$0.80	\$8,000.00
	1060	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-10,000	\$0.80	(\$8,000.00)
	1070	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	7,000	\$0.80	\$5,600.00
	1070	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-7,000	\$0.80	(\$5,600.00)
	1640	SLAB EDGE REPAIR (BRIDGES)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user kroekj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	10	\$500.00	\$5,000.00
	1640	SLAB EDGE REPAIR	Material			-10	\$500.00	(\$5,000.00)

Page 2 of 16 Revision 5/29/2025



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 16, 2025

Prog Estimate	gress e Num 7	Contract ID ber Prime Contractor	241213-D4A E & C Bridge,		y Period Start y Period End	Net Chang	Original Contract Amount Net Change Order Amount Current Contract Amount			
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type		Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3525		(BRIDGES)								
	1730	HALF-SOLE REPAIR	Material		generated Mate Adjustment (00 overridding Pay	nt offsets the origin erial Payment Esti (05) due to user kr yment Estimate Ex Payment Estimate	mate Item oekj1 ception 10	1,179	\$120.00	\$141,480.00
	1730	HALF-SOLE REPAIR	Material					-1,179	\$120.00	(\$141,480.00)
	1830	HALF-SOLE REPAIR	Material		generated Mate Adjustment (00 overridding Pay	nt offsets the origin erial Payment Esti (06) due to user kr yment Estimate Ex Payment Estimate	mate Item oekj1 ception 11	1,423	\$120.00	\$170,760.00
	1830	HALF-SOLE REPAIR	Material					-1,423	\$120.00	(\$170,760.00)
	5001	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		generated Mate Adjustment (00 overridding Pay	nt offsets the origin erial Payment Esti (07) due to user kr yment Estimate Ex Payment Estimate	mate Item oekj1 ception 13	101.50000	\$165.00	\$16,747.50
	5001	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material					-101.50000	\$165.00	(\$16,747.50)
Total										\$0.00

Revision 5/29/2025 Page 3 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Co	ontract Project Informa	tion
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J5P3523	FAF 50-3(118)	3 Bridge rehabilitations	50	COLE	at Bolivar St. and Vetter L	n. in Jefferson City	
J5P3525	FAF 54-3(218)	8 Bridge rehabilitations	54	COLE	at various location near Je	efferson City	
Totals I	y Job Nu	ımbers					
J5P3523	Incenti Disince Liquida		Gross I	tem Pay	This Estimate \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	Previous \$31,250.00 \$0.00 \$31,250.00 \$0.00 \$0.00 \$0.00 \$0.00	To Date \$31,250.00 \$0.00 \$31,250.00 \$0.00 \$0.00 \$0.00 \$0.00
J5P3525	Gross	l Item Pay Item Adjustmer		tem Pay	This Estimate \$515,251.55 \$0.00 \$515,251.55	Previous \$1,989,875.89 \$0.00 \$1,989,875.89	To Date \$2,505,127.44 \$0.00 \$2,505,127.44
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 5/29/2025 Page 4 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 6173000, Project Item Line Number 1000, Material Set 617300096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 6173000, Project Item Line Number 1000, Material Set 617300096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 6173000, Project Item Line Number 1000, Material Set 617300096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 6173000, Project Item Line Number 1000, Material Set 617300096, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 6173000, Project Item Line Number 1000, Material Set 617300096, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 6205902A, Project Item Line Number 1060, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 6205902A, Project Item Line Number 1060, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 6205903A, Project Item Line Number 1070, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 6205903A, Project Item Line Number 1070, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 7040104, Project Item Line Number 1730, Material Set 704010496, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 7040104, Project Item Line Number 1830, Material Set 704010496, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 7040107, Project Item Line Number 1640, Material Set 704010796, Material 4066SPSM - Special Provision Special Mortar, Acceptance Action Generic 4066SPSM is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 7040112, Project Item Line Number 5001, Material Set 704011296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden

Revision 5/29/2025 Page 5 of 16



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

act F	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
3- J	5P3523	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$54,000.00	\$0.0
		0001	0020	2072000	LINEAR GRADING CLASS 2	4.60	0.00	4.60	STA	0.00	\$1,750.00	\$0.0
		0001	0030	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	92.00	0.00	92.00	SQYD	0.00	\$15.00	\$0.0
		0001	0040	4133200	ULTRATHIN BONDED WEARING SURFACE, TYPE C	102.00	0.00	102.00	SQYD	0.00	\$150.00	\$0.0
		0001	0050	6081000	CONCRETE MEDIAN	0.60	0.00	0.60	SQYD	0.00	\$1,500.00	\$0.0
		0001	0060	6086004	CONCRETE SIDEWALK, 4 IN.	91.10	0.00	91.10	SQYD	0.00	\$90.00	\$0.0
		0001	0070	6091052	CURB AND GUTTER TYPE B	158.00	0.00	158.00	LF	0.00	\$60.00	\$0.0
		0001	0800	6122040	WORK ZONE CRASH CUSHION (NARROW)	6.00	0.00	6.00	EA	0.00	\$7,100.00	\$0.0
		0001	0090	6161005	CONSTRUCTION SIGNS	4,281.00	0.00	4,281.00	SQFT	0.00	\$8.00	\$0.0
		0001	0100	6161008	ADVANCED WARNING RAIL SYSTEM	15.00	0.00	15.00	EA	0.00	\$55.00	\$0.0
		0001	0110	6161010	RELOCATED SIGNS	1,124.00	0.00	1,124.00	SQFT	0.00	\$7.25	\$0.0
		0001	0120	6161025	CHANNELIZER (TRIM-LINE)	250.00	0.00	250.00	EA	0.00	\$30.00	\$0.0
		0001	0130	6161030	TYPE 3 MOVEABLE BARRICADE	59.00	0.00	59.00	EA	0.00	\$175.00	\$0.0
		0001	0140	6161033	DIRECTION INDICATOR BARRICADE	29.00	0.00	29.00	EA	0.00	\$100.00	\$0.0
		0001	0150	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	0.00	\$3,000.00	\$0.0
		0001	0160	6161055	SEQUENTIAL FLASHING WARNING LIGHT	29.00	0.00	29.00	EA	0.00	\$100.00	\$0.0
		0001	0170	6161070	TUBULAR MARKER	48.00	0.00	48.00	EA	0.00	\$65.00	\$0.0
		0001	0180	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	8.00	0.00	8.00	EA	0.00	\$4,250.00	\$0.0
		0001	0190	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	8.00	0.00	8.00	EA	0.00	\$1,850.00	\$0.0
		0001	0200	6169901	MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM	1.00	0.00	1.00	LS	0.00	\$57,000.00	\$0.0
		0001	0210	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	460.00	0.00	460.00	LF	0.00	\$145.00	\$0.0
		0001	0220	6173100	CONCRETE TRAFFIC BARRIER, TYPE D	112.00	0.00	112.00	LF	0.00	\$225.00	\$0.0
	0 0	0001	0230	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.25	\$125,000.00	\$31,250.0
		0001	0240	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	1.00	0.00	1.00	EA	0.00	\$2,000.00	\$0.0
		0001	0250	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	8,571.00	0.00	8,571.00	LF	0.00	\$0.80	\$0.0
		0001	0260	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,601.00	0.00	7,601.00	LF	0.00	\$0.80	\$0.0
		0001	0270	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	863.00	0.00	863.00	LF	0.00	\$5.00	\$0.0
		0001	0280	6206001C 6207001	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS PAVEMENT MARKING REMOVAL	123.00	0.00	123.00	LF LF	0.00	\$5.00 \$0.80	\$0.0 \$0.0
		0001										\$0.0
		0001	0300	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	1.00	0.00	1.00	EA	0.00	\$500.00	
		0001	0310	6208064A	TEMPORARY RAISED PAVEMENT MARKER	96.00	0.00	96.00	EA	0.00	\$5.00	\$0.0
		0001	0320	6208076 6221001	4 IN TEMPORARY PAVEMENT MARKING PAINT COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	17,866.00 102.00	0.00	17,866.00	SQYD	0.00	\$0.80 \$25.00	\$0.0 \$0.0
		0001	0340	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$9,000.00	\$0.0
		0001	0350	8025006	MULCHING	0.40	0.00	0.40	ACRE	0.00	\$2,500.00	\$0.0
		0001	0360		SEEDING - COOL SEASON GRASSES	0.40	0.00	0.40	ACRE	0.00		\$0.0
		0001	0370	8061016	SEDIMENT REMOVAL	5.00	0.00	5.00	CUYD	0.00	\$5.00	\$0.
		0001	0380	8061017	TEMPORARY SEEDING	0.40	0.00	0.40	ACRE	0.00	\$2,500.00	\$0.0
		0001	0390	8061019	SILT FENCE	542.00	0.00	542.00	LF	0.00	\$2.80	\$0.0
		0040	0400				0.00		SQFT		\$35.00	\$0.0
		0070	0400	9035011A 2024043	ST-STRUCTURAL REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	160.00		160.00	SQFT	0.00	\$35.00	\$0.0
		0070	0410	2161001	TOTAL SURFACE HYDRO DEMOLITION	28.00 962.00	0.00	28.00 962.00	SQYD	0.00	\$250.00	\$0.0
		0070										
		0070	0430	2161501	REMOVAL OF ASPHALT WEARING SURFACE	8,655.00	0.00	8,655.00	SQFT	0.00	\$3.25	\$0.0
		0070	0440	2163000	PARTIAL REMOVAL OF EXISTING BRIDGE DECK	2,791.00	0.00	2,791.00	SQFT	0.00	\$38.00	\$0.
		0070	0450	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.00	\$1,500.00	\$0.
		0070	0460	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	150.00	0.00	150.00	SQYD	0.00	\$225.00	\$0.
		0070	0470	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	5.00	0.00	5.00	CY	0.00	\$1,000.00	\$0.0
			0480	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	708.00	0.00	708.00	SQYD	0.00	\$185.00	\$0.0
		0070	0490	6071068	(120 IN.) PEDESTRIAN FENCE (STRUCTURES)	329.00	0.00	329.00	LF	0.00	\$155.00	\$0.
		0070	0500	7031004	DIAMOND GRINDING	708.00	0.00	708.00	SQYD	0.00	\$7.50	\$0.
		0070	0510	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	2.50	0.00	2.50	CUYD	0.00	\$2,500.00	\$0.0
		0070	0520	7034219A	TYPE D BARRIER	657.00	0.00	657.00	LF	0.00	\$190.00	\$0.0
		0070	0530	7034430	SIDEWALK (BRIDGES)	3,395.00	0.00		SQFT	0.00	\$45.00	\$0.0
		0070	0540	7040104	HALF-SOLE REPAIR	1,700.00	0.00	1,700.00	SQFT	0.00	\$65.00	\$0.0

Revision 5/29/2025 Page 6 of 16



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

act Proj No		Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
3- J5P3	523 0070	0550	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	212.00	0.00	212.00	SQFT	0.00	\$165.00	\$0.0
	0070	0560	7040113	CLEANING AND EPOXY COATING	3,807.00	0.00	3,807.00	SQFT	0.00	\$5.93	\$0.0
	0070	0570	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$8,500.00	\$0.0
	0071	0580	2161001	TOTAL SURFACE HYDRO DEMOLITION	474.00	0.00	474.00	SQYD	0.00	\$74.00	\$0.0
	0071	0590	2161501	REMOVAL OF ASPHALT WEARING SURFACE	4,261.00	0.00	4,261.00	SQFT	0.00	\$2.25	\$0.0
	0071	0600	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	0.00	100.00	SQFT	0.00	\$25.00	\$0.0
	0071	0610	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	0.00	3.00	CY	0.00	\$1,000.00	\$0.0
	0071	0620	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	474.00	0.00	474.00	SQYD	0.00	\$220.00	\$0.0
	0071	0630	7031004	DIAMOND GRINDING	474.00	0.00	474.00	SQYD	0.00	\$8.00	\$0.0
	0071	0640	7040104	HALF-SOLE REPAIR	100.00	0.00	100.00	SQFT	0.00	\$125.00	\$0.0
	0071	0650	7040113	CLEANING AND EPOXY COATING	1,130.00	0.00	1,130.00	SQFT	0.00	\$7.70	\$0.0
	0071	0660	7172054	OPEN CELL FOAM JOINT SEAL	57.00	0.00	57.00	LF	0.00	\$95.00	\$0.0
	0072	0670	2161001	TOTAL SURFACE HYDRO DEMOLITION	474.00	0.00	474.00	SQYD	0.00	\$74.00	\$0.0
	0072	0680	2161501	REMOVAL OF ASPHALT WEARING SURFACE	4,261.00	0.00	4,261.00	SQFT	0.00	\$3.25	\$0.0
	0072										
	0072	0690	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	0.00	100.00	SQFT	0.00	\$25.00	\$0.0
	0072	0700	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	0.00	3.00	CY	0.00	\$1,000.00	\$0.0
		0710	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	474.00	0.00	474.00	SQYD	0.00	\$220.00	\$0.0
	0072	0720	7031004	DIAMOND GRINDING	474.00	0.00	474.00	SQYD	0.00	\$8.00	\$0.0
	0072	0730	7040104	HALF-SOLE REPAIR	100.00	0.00	100.00	SQFT	0.00	\$125.00	\$0.0
	0072	0740	7040113	CLEANING AND EPOXY COATING	1,130.00	0.00	1,130.00	SQFT	0.00	\$7.70	\$0.0
	0072	0750	7172054	OPEN CELL FOAM JOINT SEAL	57.00	0.00	57.00	LF	0.00	\$95.00	\$0.0
Proje	ct J5P3523 - T	otal Value	Posted to D	Date as of Report Generated Date							\$31,250.0
J5P3	525 0001	0760	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.75	\$45,000.00	\$33,750.0
	0001	0770	4030003	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095C MIX)	8.20	0.00	8.20	TONS	0.00	\$1,500.00	\$0.0
	0001	0780	4071005	TACK COAT	8.00	0.00	8.00	GAL	0.00	\$50.00	\$0.
	0001	0790	6113020	FURNISHING TYPE 2 ROCK BLANKET	107.00	0.00	107.00	CUYD	0.00	\$60.00	\$0.
	0001	0800	6113040	PLACING TYPE 2 ROCK BLANKET	107.00	0.00	107.00	CUYD	0.00	\$40.00	\$0.
	0001	0810	6122014	IMPACT ATTENUATOR 60 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	2.00	\$4,130.00	\$8,260.
	0001	0820	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	1.00	0.00	1.00	EA	1.00	\$4,625.00	\$4,625.
	0001	0830	6122020	REPLACEMENT SAND BARREL	8.00	0.00	8.00	EA	0.00	\$495.00	\$0.
	0001	0840	6122030	IMPACT ATTENUATOR (RELOCATION)	8.00	0.00	8.00	EA	6.00	\$1,140.00	\$6,840.
	0001	0850	6122040	WORK ZONE CRASH CUSHION (NARROW)	6.00	0.00	6.00	EA	6.00	\$7,100.00	\$42,600.
	0001	0860	6133018	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	5.60	0.00	5.60	TONS	0.00	\$1,200.00	\$0.
	0001	0870	6133019	REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	35.60	0.00	35.60	SQYD	0.00	\$100.00	\$0.
	0001	0880	6161005	CONSTRUCTION SIGNS	2,629.00	0.00	2,629.00	SQFT	2,595.00	\$8.00	\$20,760.
	0001	0890	6161008	ADVANCED WARNING RAIL SYSTEM	14.00	0.00	14.00	EA	10.00	\$55.00	\$550.
	0001	0900	6161010	RELOCATED SIGNS	2,434.00	0.00	2,434.00	SQFT	1,327.00	\$7.25	\$9,620.
	0001	0000	0.0.0.0	THE SOUTH EST SHOWS	2, 10 1.00	0.00	2,101.00	O Q			
		0910	6161025	CHANNELIZER (TRIM-LINE)	253.00	0.00	253.00	FA			
	0001	0910	6161025	CHANNELIZER (TRIM-LINE) TYPE 3 MOVEABLE BARRICADE	253.00	0.00	253.00	EΑ	253.00	\$30.00	\$7,590
	0001	0920	6161030	TYPE 3 MOVEABLE BARRICADE	31.00	0.00	31.00	EA	253.00 15.00	\$30.00 \$200.00	\$7,590. \$3,000.
		0920 0930	6161030 6161033	TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE	31.00 30.00	0.00	31.00 30.00	EA EA	253.00 15.00 30.00	\$30.00 \$200.00 \$100.00	\$7,590. \$3,000. \$3,000.
	0001	0920 0930 0940	6161030 6161033 6161040	TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL	31.00 30.00 2.00	0.00 0.00 0.00	31.00 30.00 2.00	EA EA	253.00 15.00 30.00 2.00	\$30.00 \$200.00 \$100.00 \$3,000.00	\$7,590. \$3,000. \$3,000. \$6,000.
	0001 0001 0001	0920 0930 0940 0950	6161030 6161033 6161040 6161055	TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT	31.00 30.00 2.00 30.00	0.00 0.00 0.00 0.00	31.00 30.00 2.00 30.00	EA EA EA	253.00 15.00 30.00 2.00 30.00	\$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00	\$7,590. \$3,000. \$3,000. \$6,000.
	0001	0920 0930 0940	6161030 6161033 6161040	TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION	31.00 30.00 2.00	0.00 0.00 0.00	31.00 30.00 2.00	EA EA	253.00 15.00 30.00 2.00	\$30.00 \$200.00 \$100.00 \$3,000.00	\$7,590. \$3,000. \$3,000. \$6,000. \$3,000.
	0001 0001 0001 0001	0920 0930 0940 0950 0960 0970	6161030 6161033 6161040 6161055 6161070 6161099	TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	31.00 30.00 2.00 30.00 73.00 12.00	0.00 0.00 0.00 0.00 0.00	31.00 30.00 2.00 30.00 73.00 12.00	EA EA EA EA EA	253.00 15.00 30.00 2.00 30.00 73.00 12.00	\$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00	\$7,590. \$3,000. \$3,000. \$6,000. \$3,000. \$4,745.
	0001 0001 0001 0001 0001	0920 0930 0940 0950 0960 0970	6161030 6161033 6161040 6161055 6161070 6161099 6162002	TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED TEMPORARY LONG-TERM RUMBLE STRIPS	31.00 30.00 2.00 30.00 73.00 12.00	0.00 0.00 0.00 0.00 0.00 0.00	31.00 30.00 2.00 30.00 73.00 12.00	EA EA EA EA EA	253.00 15.00 30.00 2.00 30.00 73.00 12.00	\$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00	\$7,590 \$3,000 \$3,000 \$6,000 \$3,000 \$4,745 \$51,000
	0001 0001 0001 0001 0001	0920 0930 0940 0950 0960 0970	6161030 6161033 6161040 6161055 6161070 6161099 6162002 6169901	TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED TEMPORARY LONG-TERM RUMBLE STRIPS MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM	31.00 30.00 2.00 30.00 73.00 12.00 20.00	0.00 0.00 0.00 0.00 0.00 0.00	31.00 30.00 2.00 30.00 73.00 12.00 20.00	EA EA EA EA LS	253.00 15.00 30.00 2.00 30.00 73.00 12.00 4.00 0.80	\$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00 \$1,850.00	\$7,590 \$3,000 \$3,000 \$6,000 \$3,000 \$4,745 \$51,000 \$7,400
	0001 0001 0001 0001 0001 0001 0001	0920 0930 0940 0950 0960 0970 0980 0990 1000	6161030 6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173000	TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED TEMPORARY LONG-TERM RUMBLE STRIPS MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM CONCRETE TRAFFIC BARRIER, TYPE C	31.00 30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	31.00 30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00	EA EA EA EA EA EA LS LF	253.00 15.00 30.00 2.00 30.00 73.00 12.00 4.00 0.80 460.00	\$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00 \$1,850.00 \$95,750.00	\$7,590 \$3,000 \$3,000 \$6,000 \$3,000 \$4,745 \$51,000 \$7,400 \$66,700
	0001 0001 0001 0001 0001 0001	0920 0930 0940 0950 0960 0970 0980 0990 1000	6161030 6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173000 6173600D	TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED TEMPORARY LONG-TERM RUMBLE STRIPS MISC. WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM CONCRETE TRAFFIC BARRIER, TYPE C TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	31.00 30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	31.00 30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00	EA EA EA EA EA EA LS LF	253.00 15.00 30.00 2.00 30.00 73.00 12.00 4.00 0.80 460.00 688.00	\$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00 \$1,850.00 \$95,750.00 \$145.00	\$7,590 \$3,000 \$3,000 \$6,000 \$3,000 \$4,745 \$51,000 \$7,400 \$66,700
	0001 0001 0001 0001 0001 0001 0001 000	0920 0930 0940 0950 0960 0970 0980 0990 1000	6161030 6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173000	TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED TEMPORARY LONG-TERM RUMBLE STRIPS MISC. WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM CONCRETE TRAFFIC BARRIER, TYPE C TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED /	31.00 30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	31.00 30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00	EA EA EA EA EA EA LS LF	253.00 15.00 30.00 2.00 30.00 73.00 12.00 4.00 0.80 460.00	\$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00 \$1,850.00 \$95,750.00	\$7,590 \$3,000 \$3,000 \$6,000 \$4,745 \$51,000 \$7,400 \$66,700
	0001 0001 0001 0001 0001 0001 0001 000	0920 0930 0940 0950 0960 0970 0980 0990 1000	6161030 6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173000 6173700B	TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED TEMPORARY LONG-TERM RUMBLE STRIPS MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM CONCRETE TRAFFIC BARRIER, TYPE C TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR	31.00 30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	31.00 30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00	EA EA EA EA EA EA LS LF	253.00 15.00 30.00 2.00 30.00 73.00 12.00 4.00 0.80 460.00 688.00	\$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00 \$1,850.00 \$95,750.00 \$145.00	\$7,590 \$3,000 \$3,000 \$6,000 \$3,000 \$4,745 \$51,000 \$7,400 \$66,700 \$33,849
	0001 0001 0001 0001 0001 0001 0001 000	0920 0930 0940 0950 0960 0970 0980 0990 1000 1010	6161030 6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173600D 6173700B	TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED TEMPORARY LONG-TERM RUMBLE STRIPS MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM CONCRETE TRAFFIC BARRIER, TYPE C TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	31.00 30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	31.00 30.00 2.00 30.00 73.00 12.00 20.00 460.00 688.00	EA EA EA EA EA LS LF LF	253.00 15.00 30.00 2.00 30.00 73.00 12.00 4.00 0.80 460.00 688.00	\$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00 \$1,850.00 \$145.00 \$49.20	\$7,590 \$3,000 \$3,000 \$6,000 \$3,000 \$4,745 \$51,000 \$7,400 \$66,700 \$33,849 \$31,308
	0001 0001 0001 0001 0001 0001 0001 000	0920 0930 0940 0950 0960 0970 0980 0990 1000 1010	6161030 6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173600D 6173700B 6175010A	TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED TEMPORARY LONG-TERM RUMBLE STRIPS MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM CONCRETE TRAFFIC BARRIER, TYPE C TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED RELOCATING TEMPORARY TRAFFIC BARRIER	31.00 30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00 575.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	31.00 30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00 575.00	EA EA EA EA EA LS LF LF LF	253.00 15.00 30.00 2.00 30.00 73.00 12.00 4.00 0.80 460.00 688.00 575.00	\$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00 \$1,850.00 \$145.00 \$49.20 \$54.45	\$7,590 \$3,000 \$3,000 \$6,000 \$4,745 \$51,000 \$7,400 \$66,700 \$33,849 \$31,308 \$20,304
	0001 0001 0001 0001 0001 0001 0001 000	0920 0930 0940 0950 0960 0970 0980 0990 1000 1010 1020	6161030 6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173600D 6173700B 6175010A 6175011B	TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED TEMPORARY LONG-TERM RUMBLE STRIPS MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM CONCRETE TRAFFIC BARRIER, TYPE C TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED RELOCATING TEMPORARY TRAFFIC BARRIER RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	31.00 30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00 575.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	31.00 30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00 575.00	EA EA EA EA EA LS LF LF LF LF	253.00 15.00 30.00 2.00 30.00 73.00 12.00 4.00 0.80 460.00 688.00 575.00	\$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00 \$1,850.00 \$145.00 \$49.20 \$54.45	\$7,590 \$3,000 \$3,000 \$6,000 \$3,000 \$4,745 \$51,000 \$7,400 \$66,700 \$33,849 \$31,308 \$20,304 \$5,842 \$131,250
	0001 0001 0001 0001 0001 0001 0001 000	0920 0930 0940 0950 0960 0970 0980 0990 1000 1010 1020 1030 1040	6161030 6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173000 6173700B 6175010A 6175011B 6181000 6205902A	TYPE 3 MOVEABLE BARRICADE DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED TEMPORARY LONG-TERM RUMBLE STRIPS MISC. WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM CONCRETE TRAFFIC BARRIER, TYPE C TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED RELOCATING TEMPORARY TRAFFIC BARRIER RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED MOBILIZATION 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING	31.00 30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00 575.00 1,775.00 663.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	31.00 30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00 575.00 1,775.00 663.00	EA EA EA EA LS LF LF LF LF LF LS	253.00 15.00 30.00 2.00 30.00 73.00 12.00 4.00 0.80 460.00 688.00 575.00 1,574.00 331.00	\$30.00 \$200.00 \$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00 \$1,850.00 \$95,750.00 \$49.20 \$54.45 \$12.90 \$17.65 \$175,000.00	\$7,590. \$3,000. \$3,000. \$3,000. \$4,745. \$51,000. \$7,400. \$76,600. \$33,849. \$31,308. \$20,304. \$5,842. \$131,250. \$8,000.

Revision 5/29/2025 Page 7 of 16



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
	P3525	0001	1090	6208064A	TEMPORARY RAISED PAVEMENT MARKER	146.00	0.00	146.00	EA	0.00	\$5.00	\$0.00
A		0001	1100	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	47,631.00	0.00	47,631.00	LF	35,491.00	\$0.80	\$28,392.8
		0001	1110	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	102.00	0.00	102.00	SQYD	0.00	\$30.00	\$0.0
		0001	1120	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	160.00	0.00	160.00	SQYD	0.00	\$10.00	\$0.0
		0001	1130	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$9,000.00	\$0.0
		0070	1140	2161000	SCARIFICATION OF BRIDGE DECK	227.00	0.00	227.00	SQYD	0.00	\$34.25	\$0.0
		0070	1150	2161001	TOTAL SURFACE HYDRO DEMOLITION	909.00	0.00	909.00	SQYD	0.00	\$70.00	\$0.0
		0070	1160	2161501	REMOVAL OF ASPHALT WEARING SURFACE	1,744.00	0.00	1,744.00	SQFT	880.00	\$3.25	\$2,860.0
		0070	1170	2161502	REMOVAL OF CONCRETE WEARING SURFACE	4,392.00	0.00	4,392.00	SQFT	2,200.00	\$4.50	\$9,900.0
		0070	1180	2161503	REMOVAL OF EXISTING DECK REPAIR	50.00	0.00	50.00	SQFT	0.00	\$25.00	\$0.0
		0070	1190	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	4.00	0.00	4.00	CY	0.00	\$1,000.00	\$0.0
		0070	1200	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	909.00	0.00	909.00	SQYD	0.00	\$205.00	\$0.0
		0070	1210	7031004	DIAMOND GRINDING	909.00	0.00	909.00	SQYD	0.00	\$7.00	\$0.0
		0070	1220	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	5.00	0.00	5.00	SQFT	0.00	\$225.00	\$0.0
		0070	1230	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	15.00	0.00	15.00	SQFT	0.00	\$400.00	\$0.0
		0070	1240	7040104	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	0.00	\$120.00	\$0.0
		0070	1250	7040113	CLEANING AND EPOXY COATING	1,859.00	0.00	1,859.00	SQFT	0.00	\$6.51	\$0.0
		0070	1260	7172054	OPEN CELL FOAM JOINT SEAL	99.00	0.00	99.00	LF	0.00	\$50.00	\$0.0
		0071	1270	2161000	SCARIFICATION OF BRIDGE DECK	227.00	0.00	227.00	SQYD	0.00	\$34.25	\$0.0
		0071	1280	2161001	TOTAL SURFACE HYDRO DEMOLITION	909.00	0.00	909.00	SQYD	0.00	\$70.00	\$0.0
		0071	1290	2161501	REMOVAL OF ASPHALT WEARING SURFACE	1,744.00	0.00	1,744.00	SQFT	880.00	\$3.25	\$2,860.0
		0071	1300	2161502	REMOVAL OF CONCRETE WEARING SURFACE	4,392.00	0.00	4,392.00	SQFT	2,200.00	\$4.50	\$9,900.0
		0071	1310	2161503	REMOVAL OF EXISTING DECK REPAIR	50.00	0.00	50.00	SQFT	0.00	\$25.00	\$0.0
		0071	1320	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	4.00	0.00	4.00	CY	0.00	\$1,000.00	\$0.0
		0071	1330	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	909.00	0.00	909.00	SQYD	0.00	\$205.00	\$0.0
		0071	1340	7031004	DIAMOND GRINDING	909.00	0.00	909.00	SQYD	0.00	\$7.00	\$0.0
		0071	1350	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	15.00	0.00	15.00	SQFT	0.00	\$225.00	\$0.0
		0071	1360	7040104	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	0.00	\$120.00	\$0.0
		0071	1370	7040113	CLEANING AND EPOXY COATING	1,859.00	0.00	1,859.00	SQFT	0.00	\$6.51	\$0.0
		0071	1380	7172054	OPEN CELL FOAM JOINT SEAL	99.00	0.00	99.00	LF	0.00	\$50.00	\$0.0
		0072	1390	2161001	TOTAL SURFACE HYDRO DEMOLITION	737.00	0.00	737.00	SQYD	737.00	\$70.00	\$51,590.0
		0072	1400	2161501	REMOVAL OF ASPHALT WEARING SURFACE	6,637.00	0.00	6,637.00	SQFT	6,637.00	\$3.25	\$21,570.2
		0072	1410	2161503	REMOVAL OF EXISTING DECK REPAIR	300.00	45.00	345.00	SQFT	345.00	\$15.00	\$5,175.0
		0072	1420	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	4.00	24.00	28.00	CY	24.00	\$1,000.00	\$24,000.0
		0072	1430	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	737.00	0.00	737.00	SQYD	737.00	\$190.00	\$140,030.0
		0072	1440	7031004	DIAMOND GRINDING	737.00	0.00	737.00	SQYD	737.00	\$7.00	\$5,159.0
		0072	1450	7040104	HALF-SOLE REPAIR	50.00	348.00	398.00	SQFT	398.00	\$120.00	\$47,760.0
		0072	1460	7040113	CLEANING AND EPOXY COATING	1,792.00	0.00	1,792.00	SQFT	1,792.00	\$4.86	\$8,709.1
		0072	1470	7172054	OPEN CELL FOAM JOINT SEAL	94.00	0.00	94.00	LF	94.00	\$50.00	\$4,700.0
		0073	1480	2161001	TOTAL SURFACE HYDRO DEMOLITION	737.00	0.00	737.00	SQYD	737.00	\$70.00	\$51,590.0
		0073	1490	2161501	REMOVAL OF ASPHALT WEARING SURFACE	6,637.00	0.00	6,637.00	SQFT	6,637.00	\$3.25	\$21,570.2
		0073	1500	2161503	REMOVAL OF EXISTING DECK REPAIR	200.00	10.00	210.00	SQFT	200.00	\$20.00	\$4,000.0
		0073	1510	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	4.00	33.00	37.00	CY	37.00	\$1,000.00	\$37,000.0
		0073	1520	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	737.00	0.00	737.00	SQYD	737.00	\$190.00	\$140,030.0
		0073	1530	7031004	DIAMOND GRINDING	737.00	0.00	737.00	SQYD	737.00	\$7.00	\$5,159.0
		0073	1540	7040104	HALF-SOLE REPAIR	50.00	12.00	62.00	SQFT	62.00	\$120.00	\$7,440.0
		0073	1550	7040113	CLEANING AND EPOXY COATING	1,792.00	0.00	1,792.00	SQFT	1,792.00	\$4.86	\$8,709.1
		0073	1560	7172054	OPEN CELL FOAM JOINT SEAL	94.00	0.00	94.00	LF	94.00	\$50.00	\$4,700.0
		0074	1570	2161001	TOTAL SURFACE HYDRO DEMOLITION	638.00	0.00	638.00	SQYD	638.00	\$70.00	\$44,660.0
		0074	1580	2161501	REMOVAL OF ASPHALT WEARING SURFACE	5,748.00	0.00	5,748.00	SQFT	5,502.00	\$3.25	\$17,881.5
		0074	1590	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	109.00	209.00	SQFT	209.00	\$20.00	\$4,180.0
		0074	1600	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	5.00	26.00	31.00	CY	31.00	\$1,000.00	\$31,000.0
		0074	1610	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	638.00	0.00	638.00	SQYD	638.00	\$190.00	\$121,220.0
		0074	1620	7031004	DIAMOND GRINDING	638.00	0.00	638.00	SQYD	638.00	\$7.00	\$4,466.0
		0074	1630	7040104	HALF-SOLE REPAIR	100.00	789.00	889.00	SQFT	889.00	\$120.00	\$106,680.0
		0074	1640	7040107	SLAB EDGE REPAIR (BRIDGES)	10.00	0.00	10.00	LF	10.00	\$500.00	\$5,000.0
		0074	1650	7040113	CLEANING AND EPOXY COATING	700.00	0.00	700.00	SQFT	700.00	\$11.48	\$8,036.0

Revision 5/29/2025 Page 8 of 16



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ontract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
11213-	J5P3525	0074	1660	7172054	OPEN CELL FOAM JOINT SEAL	89.00	0.00	89.00	LF	89.00	\$50.00	\$4,450.00
4A		0075	1670	2161001	TOTAL SURFACE HYDRO DEMOLITION	611.00	0.00	611.00	SQYD	611.00	\$70.00	\$42,770.00
		0075	1680	2161501	REMOVAL OF ASPHALT WEARING SURFACE	5,502.00	0.00	5,502.00	SQFT	5,502.00	\$3.25	\$17,881.5
		0075	1690	2161503	REMOVAL OF EXISTING DECK REPAIR	250.00	574.00	824.00	SQFT	824.00	\$20.00	\$16,480.0
		0075	1700	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	26.00	29.00	CY	29.00	\$1,000.00	\$29,000.0
		0075	1710	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	611.00	0.00	611.00	SQYD	611.00	\$190.00	\$116,090.0
		0075	1720	7031004	DIAMOND GRINDING	611.00	0.00	611.00	SQYD	611.00	\$7.50	\$4,582.5
		0075	1730	7040104	HALF-SOLE REPAIR	50.00	1,130.00	1,180.00	SQFT	1,179.00	\$120.00	\$141,480.0
		0075	1740	7040113	CLEANING AND EPOXY COATING	500.00	0.00	500.00	SQFT	500.00	\$6.21	\$3,105.0
		0075	1750	7172054	OPEN CELL FOAM JOINT SEAL	71.00	0.00	71.00	LF	71.00	\$70.00	\$4,970.0
		0076	1760	2161001	TOTAL SURFACE HYDRO DEMOLITION	803.00	0.00	803.00	SQYD	803.00	\$70.00	\$56,210.0
		0076	1770	2161501	REMOVAL OF ASPHALT WEARING SURFACE	7,227.00	0.00	7,227.00	SQFT	7,227.00	\$3.25	\$23,487.7
		0076	1780	2161503	REMOVAL OF EXISTING DECK REPAIR	300.00	644.00	944.00	SQFT	944.00	\$18.00	\$16,992.0
		0076	1790	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	9.00	29.00	38.00	CY	36.00	\$1,000.00	\$36,000.0
		0076	1800	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	803.00	0.00	803.00	SQYD	803.00	\$190.00	\$152,570.0
		0076	1810	7031004	DIAMOND GRINDING	803.00	0.00	803.00	SQYD	803.00	\$7.50	\$6,022.5
		0076	1820	7040101	SUBSTRUCTURE REPAIR (FORMED)	10.00	0.00	10.00	SQFT	10.00	\$215.00	\$2,150.0
		0076	1830	7040104	HALF-SOLE REPAIR	500.00	923.00	1,423.00	SQFT	1,423.00	\$120.00	\$170,760.0
		0076	1840	7040113	CLEANING AND EPOXY COATING	750.00	0.00	750.00	SQFT	0.00	\$6.21	\$0.0
		0076	1850	7172054	OPEN CELL FOAM JOINT SEAL	90.00	0.00	90.00	LF	90.00	\$55.00	\$4,950.0
		0077	1860	2061000	CLASS 1 EXCAVATION	23.00	0.00	23.00	CUYD	0.00	\$250.00	\$0.0
		0077	1870	2161001	TOTAL SURFACE HYDRO DEMOLITION	684.00	0.00	684.00	SQYD	0.00	\$74.00	\$0.0
		0077	1880	2161502	REMOVAL OF CONCRETE WEARING SURFACE	6,160.00	0.00	6,160.00	SQFT	0.00	\$4.25	\$0.0
		0077	1890	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	2.00	0.00	2.00	CY	0.00	\$1,000.00	\$0.0
		0077	1900	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	684.00	0.00	684.00	SQYD	0.00	\$200.00	\$0.0
		0077	1910	7031004	DIAMOND GRINDING	684.00	0.00	684.00	SQYD	0.00	\$8.00	\$0.0
		0077	1920	7039907	MISC.SELF-CONSOLIDATING CONCRETE	11.00	0.00	11.00	CUYD	0.00	\$1,800.00	\$0.0
		0077	1930	7040104	HALF-SOLE REPAIR	100.00	0.00	100.00	SQFT	0.00	\$120.00	\$0.0
		0077	1940	7040113	CLEANING AND EPOXY COATING	2,600.00	0.00	2,600.00	SQFT	0.00	\$7.08	\$0.0
		0077	1950	7101000	REINFORCING STEEL (EPOXY COATED)	1,210.00	0.00	1,210.00	LB	0.00	\$5.00	\$0.0
		0077	1960	7172054	OPEN CELL FOAM JOINT SEAL	92.00	0.00	92.00	LF	0.00	\$55.00	\$0.0
		0075	5001	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	0.00	101.50	101.50	SQFT	101.50	\$165.00	\$16.747.5
	Project I	5P3525 - T o			Date as of Report Generated Date	5.00	101.50	101.50	OGI I	101.00	ψ100.00	\$2,505,127.
					s of Report Generated Date							\$2,536,377.4

Revision 5/29/2025 Page 9 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5P3525

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0760	2022010	REMOVAL OF IMPROVEMENTS	7/14/25	7/16/25	1	0.25	LS	Bridge A13052 A13053 A13092					
0840	6122030	IMPACT ATTENUATOR (RELOCATION)	7/14/25	7/16/25	1	2.00	EA	Bridge A13052 A13053					
0880	6161005	CONSTRUCTION SIGNS	7/14/25	7/16/25	1	589.00	SQFT	Mo Blvd ramp closure Phase 7					
0900	6161010	RELOCATED SIGNS	7/14/25	7/16/25	1	793.00	SQFT	54 EB WB Phase 7					
1000	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	7/9/25	7/16/25	1	460.00	LF	Median barrier north and south of bridges A13074 and A13075					
1030	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	7/14/25	7/16/25	1	687.00	LF	Bridge A13052 A13053					
1060	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7/14/25	7/16/25	1	10,000.00	LF	54 EB WB Phase 5					
070	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7/14/25	7/16/25	1	7,000.00	LF	54 EB WB Phase 5					
080	6207001	PAVEMENT MARKING REMOVAL	7/14/25	7/16/25	1	14,000.00	LF	54 EB WB Phase 4 5 7					
100	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	7/14/25	7/16/25	1	8,000.00	LF	54 EB WB Phase 7					
160	2161501	REMOVAL OF ASPHALT WEARING SURFACE	7/15/25	7/16/25	1	880.00	SQFT	Bridge A13052, phase 7, passing lane					
170	2161502	REMOVAL OF CONCRETE WEARING SURFACE	7/15/25	7/16/25	1	2,200.00	SQFT	Bridge A13052, phase 7, passing lane					
290	2161501	REMOVAL OF ASPHALT WEARING SURFACE	7/15/25	7/16/25	1	880.00	SQFT	Bridge A13053, phase 7, passing lane					
300	2161502	REMOVAL OF CONCRETE WEARING SURFACE	7/15/25	7/16/25	1	2,200.00	SQFT	Bridge A13053, phase 7, passing lane					
410	2161503	REMOVAL OF EXISTING DECK REPAIR	7/15/25	7/16/25	- 1	45.00	SQFT	Bridge A13074, phase 5					
420	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	7/15/25	7/16/25	- 1	20.00	CY	Bridge A13074, phase 5					
440	7031004	DIAMOND GRINDING	7/2/25	7/16/25	1	737.00	SQYD	Bridge A13074					
450	7040104	HALF-SOLE REPAIR	7/15/25	7/16/25	1	348.00	SQFT	Bridge A13074, phase 5					
470	7172054	OPEN CELL FOAM JOINT SEAL	7/1/25	7/16/25	1	94.00	LF	Bridge A13074					
600	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	7/15/25	7/16/25	1	26.00	CY	Bridge A13092, phase 5					
620	7031004	DIAMOND GRINDING	7/2/25	7/16/25	1	638.00	SQYD	Bridge A13092					
630	7040104	HALF-SOLE REPAIR	7/15/25	7/16/25	1	599.00	SQFT	Bridge A13092, phase 5					
640	7040107	SLAB EDGE REPAIR (BRIDGES)	7/2/25	7/16/25	1	10.00	LF	Bridge A13092					
660	7172054	OPEN CELL FOAM JOINT SEAL	7/1/25	7/16/25	1	89.00	LF	Bridge A13092					
690	2161503	REMOVAL OF EXISTING DECK REPAIR	7/15/25	7/16/25	1	395.00	SQFT	Bridge A16724, phase 5, driving lane					
700	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	7/15/25	7/16/25	1	11.00	CY	Bridge A16724, phase 5, driving lane					
720	7031004	DIAMOND GRINDING	7/2/25	7/16/25	1	311.00	SQYD	Bridge A16724 driving lane					
730	7040104	HALF-SOLE REPAIR	7/15/25	7/16/25	1	582.00	SQFT	Bridge A16724, phase 5, driving lane					
750	7172054	OPEN CELL FOAM JOINT SEAL	7/1/25	7/16/25	1	36.00	LF	Bridge A16724 driving lane					
780	2161503	REMOVAL OF EXISTING DECK REPAIR	7/15/25	7/16/25	1	431.00	SQFT	Bridge A16725, phase 5, driving lane					
790	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	7/15/25	7/16/25	1	3.00	CY	Bridge A16725, phase 5, driving lane					
810	7031004	DIAMOND GRINDING	7/2/25	7/16/25	1	403.00	SQYD	Bridge A16725 driving lane					
830	7040104	HALF-SOLE REPAIR	7/15/25	7/16/25	1	542.00	SQFT	Bridge A16725, phase 5, driving lane					
850	7172054	OPEN CELL FOAM JOINT SEAL	7/1/25	7/16/25	1	45.00	LF	Bridge A16725 driving lane					

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 6/5/2025 Page 10 of 16



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5P3525	0810	IMPACT ATTENUATOR 60	Material		3	May 16, 2025	SYSTEM	(\$8,260.00)	
		MPH (SAND BARREL ARRAY)			3	May 16, 2025	SYSTEM	\$8,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0810 -	- Total						\$0.00	
	0820	IMPACT ATTENUATOR 65 MPH (SAND	Material		3	May 16, 2025	SYSTEM	(\$4,625.00)	
		BARREL ARRAY)			3	May 16, 2025	SYSTEM	\$4,625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0820 -	- Total						\$0.00	
	0850	WORK ZONE CRASH CUSHION	Material		3	May 16, 2025	SYSTEM	(\$42,600.00)	
		(NARROW)			3	May 16, 2025	SYSTEM	\$42,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0850 -	- Total						\$0.00	
	0880	CONSTRUCTION SIGNS	Material		3	May 16, 2025	SYSTEM	(\$16,048.00)	
					3	May 16, 2025	SYSTEM	\$16,048.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
		- Total		otal				\$0.00	
	0880 -	ADVANCED WARNING RAIL SYSTEM	Material - To	otal	3	May 16, 2025	SYSTEM	\$0.00 (\$550.00)	
		ADVANCED WARNING RAIL		otal	3		SYSTEM SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.
		ADVANCED WARNING RAIL		otal - Total		2025 May 16,		\$0.00 (\$550.00)	Estimate Item Adjustment (0005) due to user hensor overridding Payment
		ADVANCED WARNING RAIL		- Total		2025 May 16,		\$0.00 (\$550.00) \$550.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment
	0890	ADVANCED WARNING RAIL	Material	- Total		2025 May 16,		\$0.00 (\$550.00) \$550.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment
	0890	ADVANCED WARNING RAIL SYSTEM	Material	- Total		2025 May 16, 2025		\$0.00 (\$550.00) \$550.00 \$0.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment
	0890	ADVANCED WARNING RAIL SYSTEM Total CHANNELIZER	Material Material - To	- Total	3	2025 May 16, 2025	SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment
	0890	ADVANCED WARNING RAIL SYSTEM Total CHANNELIZER	Material Material - To	- Total	3	2025 May 16, 2025 May 16, 2025 May 16,	SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00)	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment
	0890	ADVANCED WARNING RAIL SYSTEM Total CHANNELIZER	Material Material - To	- Total otal - Total	3	2025 May 16, 2025 May 16, 2025 May 16,	SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00)	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment
	0890 - 0890 - 0910	ADVANCED WARNING RAIL SYSTEM Total CHANNELIZER	Material - To	- Total otal - Total	3	2025 May 16, 2025 May 16, 2025 May 16,	SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$7,590.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment
	0890 - 0890 - 0910	ADVANCED WARNING RAIL SYSTEM - Total CHANNELIZER (TRIM-LINE) - Total TYPE 3 MOVEABLE	Material - To	- Total otal - Total	3	2025 May 16, 2025 May 16, 2025 May 16,	SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$7,590.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment
	0890 - 0890 - 0910 -	ADVANCED WARNING RAIL SYSTEM Total CHANNELIZER (TRIM-LINE) Total TYPE 3	Material - To	- Total otal - Total	3 3 3	2025 May 16, 2025 May 16, 2025 May 16, 2025	SYSTEM SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$7,590.00 \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment
	0890 - 0890 - 0910 -	ADVANCED WARNING RAIL SYSTEM - Total CHANNELIZER (TRIM-LINE) - Total TYPE 3 MOVEABLE	Material - To	- Total otal - Total	3 3 3	May 16, 2025 May 16, 2025 May 16, 2025 May 16, 2025 May 16, 2025	SYSTEM SYSTEM SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$7,590.00 \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment
	0890 - 0890 - 0910 -	ADVANCED WARNING RAIL SYSTEM - Total CHANNELIZER (TRIM-LINE) - Total TYPE 3 MOVEABLE	Material - To	- Total - Total otal - Total	3 3 3	May 16, 2025 May 16, 2025 May 16, 2025 May 16, 2025 May 16, 2025	SYSTEM SYSTEM SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$7,590.00 \$0.00 \$0.00 (\$3,000.00)	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment
	0890	ADVANCED WARNING RAIL SYSTEM - Total CHANNELIZER (TRIM-LINE) - Total TYPE 3 MOVEABLE	Material - To	- Total - Total otal - Total	3 3 3	May 16, 2025 May 16, 2025 May 16, 2025 May 16, 2025 May 16, 2025	SYSTEM SYSTEM SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$7,590.00 \$0.00 \$0.00 (\$3,000.00)	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment
	0890	ADVANCED WARNING RAIL SYSTEM - Total CHANNELIZER (TRIM-LINE) - Total TYPE 3 MOVEABLE BARRICADE	Material - To	- Total - Total otal - Total	3 3 3	May 16, 2025 May 16, 2025 May 16, 2025 May 16, 2025 May 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$7,590.00 \$0.00 \$0.00 (\$3,000.00) \$3,000.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment



				1						
oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
3525	0930	DIRECTION	Material	Туре					Estimate Exception 8 on the current Payment Estimate.	
		INDICATOR BARRICADE		- Total				\$0.00		
			Material - To	otal				\$0.00		
	0930 -) - Total						\$0.00		
	0940	FLASHING ARROW PANEL	Material		3	May 16, 2025	SYSTEM	(\$6,000.00)		
		ANNOWTANLE			3	May 16, 2025	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hensor overridding Payment Estimate Exception 9 on the current Payment Estimate.	
				- Total				\$0.00		
			Material - To	terial - Total						
	0940 -	Total						\$0.00 \$0.00		
	0950	SEQUENTIAL FLASHING	Material		3	May 16, 2025	SYSTEM	(\$3,000.00)		
		WARNING LIGHT			3	May 16, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hensor overridding Payment Estimate Exception 10 on the current Payment Estimate.	
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0950 -	· Total						\$0.00		
	0960	TUBULAR	Material		3	May 16, 2025	SYSTEM	(\$4,745.00)		
		MARKER			3	May 16, 2025	SYSTEM	\$4,745.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hensor overridding Payment Estimate Exception 11 on the current Payment Estimate.	
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0960 -	Total						\$0.00		
	0970	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material		3	May 16, 2025	SYSTEM	(\$51,000.00)		
			COMMUNICATION NTERFACE,			3	May 16, 2025	SYSTEM	\$51,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hensor overridding Payment Estimate Exception 12 on the current Payment Estimate.
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0970 -	Total						\$0.00		
	0980	TEMPORARY LONG-TERM	Material		3	May 16, 2025	SYSTEM	(\$7,400.00)		
		RUMBLE STRIPS			3	May 16, 2025	SYSTEM	\$7,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hensor overridding Payment Estimate Exception 13 on the current Payment Estimate.	
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0980 -	Total						\$0.00		
	1000	CONCRETE TRAFFIC	Material		7	Jul 16, 2025	SYSTEM	(\$66,700.00)		
		BARRIER, TYPE C			7	Jul 16, 2025	SYSTEM	\$66,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kroekj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	1000 -	Total						\$0.00		
	1010	TEMPORARY TRAFFIC	Material		3	May 16, 2025	SYSTEM	(\$33,849.60)		
		BARRIER, CONT. FURN/RE			3	May 16, 2025	SYSTEM	\$33,849.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate.	
				- Total				\$0.00		
			Material - To	otal				\$0.00		



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
5P3525	1010 -	- Total						\$0.00				
	1020	TEMP. TRAFFIC BARRIER	Material		3	May 16, 2025	SYSTEM	(\$31,308.75)				
		ANCHORED., CONT			3	May 16, 2025	SYSTEM	\$31,308.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hensor overridding Payment Estimate Exception 15 on the current Payment Estimate.			
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	1020 -	Total						\$0.00				
	1060	6 IN. WHITE HIGH BUILD WATERBORNE	Material		7	Jul 16, 2025	SYSTEM	(\$8,000.00)				
		PAVEMENT MARKING PAINT, TYPE L BEADS			7	Jul 16, 2025	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kroekj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	1060 -	- Total						\$0.00				
	1070	6 IN. YELLOW HIGH BUILD	Material		7	Jul 16, 2025	SYSTEM	(\$5,600.00)				
		WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS			7	Jul 16, 2025	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	1070 -	- Total						\$0.00				
	1420	SUPPLEMENTARY WEARING	TARY Material		6	Jul 1, 2025	SYSTEM	(\$4,000.00)				
		SURFACE MATERIAL			6	Jul 1, 2025	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.			
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	1420 -	- Total						\$0.00				
	1510	SUPPLEMENTARY WEARING	Y Material			Jun 2,	SYSTEM					
			Material		4	2025	SYSTEM	(\$4,000.00)				
		SURFACE MATERIAL	Material		4		SYSTEM	(\$4,000.00) \$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.			
		SURFACE	Material			2025 Jun 2,		,	Estimate Item Adjustment (0001) due to user hensor overridding Payment			
		SURFACE	Material		4	2025 Jun 2, 2025 Jun 16,	SYSTEM	\$4,000.00	Estimate Item Adjustment (0001) due to user hensor overridding Payment			
		SURFACE	Material		5	2025 Jun 2, 2025 Jun 16, 2025 Jun 16,	SYSTEM	\$4,000.00 (\$37,000.00)	Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user browns1 overridding Payment			
		SURFACE	Material		5 5	Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jul 1,	SYSTEM SYSTEM	\$4,000.00 (\$37,000.00) \$37,000.00	Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user browns1 overridding Payment			
		SURFACE	Material	- Total	5 5 6	Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jul 1, 2025 Jul 1,	SYSTEM SYSTEM SYSTEM	\$4,000.00 (\$37,000.00) \$37,000.00 (\$37,000.00)	Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user browns1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment			
		SURFACE	Material - To		5 5 6	Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jul 1, 2025 Jul 1,	SYSTEM SYSTEM SYSTEM	\$4,000.00 (\$37,000.00) \$37,000.00 (\$37,000.00)	Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user browns1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment			
	1510 -	SURFACE MATERIAL			5 5 6	Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jul 1, 2025 Jul 1,	SYSTEM SYSTEM SYSTEM	\$4,000.00 (\$37,000.00) \$37,000.00 (\$37,000.00) \$37,000.00	Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user browns1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment			
	1510 - 1520	SURFACE MATERIAL Total LATEX MODIFIED CONCRETE			5 5 6	Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jul 1, 2025 Jul 1,	SYSTEM SYSTEM SYSTEM	\$4,000.00 (\$37,000.00) \$37,000.00 (\$37,000.00) \$37,000.00 \$0.00	Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user browns1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment			
		SURFACE MATERIAL Total LATEX MODIFIED	Material - To		5 5 6 6	2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jul 1, 2025 Jul 1, 2025 Jul 1, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	\$4,000.00 (\$37,000.00) \$37,000.00 (\$37,000.00) \$37,000.00 \$0.00 \$0.00	Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user browns1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment			
		Total LATEX MODIFIED CONCRETE WEARING	Material - To		5 5 6 6	2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jul 1, 2025 Jul 1, 2025 Jul 2, 2025 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,000.00 (\$37,000.00) \$37,000.00 (\$37,000.00) \$37,000.00 \$0.00 \$0.00 \$0.00 (\$140,030.00)	Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user browns1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.			
		Total LATEX MODIFIED CONCRETE WEARING	Material - To	otal - Total	5 5 6 6	2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jul 1, 2025 Jul 1, 2025 Jul 2, 2025 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,000.00 (\$37,000.00) \$37,000.00 (\$37,000.00) \$37,000.00 \$0.00 \$0.00 \$0.00 (\$140,030.00)	Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user browns1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.			
		Total LATEX MODIFIED CONCRETE WEARING SURFACE	Material - To	otal - Total	5 5 6 6	2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jul 1, 2025 Jul 1, 2025 Jul 2, 2025 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,000.00 (\$37,000.00) \$37,000.00 (\$37,000.00) \$37,000.00 \$0.00 \$0.00 \$0.00 (\$140,030.00) \$140,030.00	Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user browns1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.			



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J5P3525	1600	SURFACE MATERIAL	Material		6	Jul 1, 2025	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.			
				- Total				\$0.00				
			Material - Total					\$0.00				
	1600 -	Total						\$0.00				
	1640	SLAB EDGE REPAIR (BRIDGES)	Material		7	Jul 16, 2025 Jul 16,	SYSTEM	(\$5,000.00)				
					7		SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kroekj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.			
				- Total				\$0.00				
			Material - To	Material - Total								
	1640 -	Total						\$0.00				
	1700	SUPPLEMENTARY WEARING SURFACE	Material		4	Jun 2, 2025	SYSTEM	(\$3,000.00)				
		MATERIAL			4	Jun 2, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					5	Jun 16, 2025	SYSTEM	(\$3,000.00)				
					5	Jun 16, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user browns1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					6	Jul 1, 2025	SYSTEM	(\$18,000.00)				
					6	Jul 1, 2025	SYSTEM	\$18,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.			
				- Total				\$0.00				
			Material - Total					\$0.00				
	1700 -	Total						\$0.00				
	1710	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		4	Jun 2, 2025	SYSTEM	(\$57,000.00)				
					4	Jun 2, 2025	SYSTEM	\$57,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 9 on the current Payment Estimate.			
				- Total	4		SYSTEM	\$57,000.00 \$0.00	Estimate Item Adjustment (0004) due to user hensor overridding Payment			
			Material - To		4		SYSTEM		Estimate Item Adjustment (0004) due to user hensor overridding Payment			
	1710 -	Total	Material - To		4		SYSTEM	\$0.00	Estimate Item Adjustment (0004) due to user hensor overridding Payment			
		Total HALF-SOLE REPAIR	Material - To		7		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0004) due to user hensor overridding Payment			
		HALF-SOLE				Jul 16,		\$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0004) due to user hensor overridding Payment			
		HALF-SOLE			7	Jul 16, 2025 Jul 16,	SYSTEM	\$0.00 \$0.00 \$0.00 \$141,480.00	Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroekj1 overridding Payment			
		HALF-SOLE		otal - Total	7	Jul 16, 2025 Jul 16,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$141,480.00) \$141,480.00	Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroek/1 overridding Payment			
	1730	HALF-SOLE	Material	otal - Total	7	Jul 16, 2025 Jul 16,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$141,480.00) \$141,480.00	Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroek/1 overridding Payment			
	1730	HALF-SOLE REPAIR Total SUPPLEMENTARY WEARING	Material	otal - Total	7	Jul 16, 2025 Jul 16,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$141,480.00) \$141,480.00 \$0.00	Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroekj1 overridding Payment			
	1730 -	HALF-SOLE REPAIR Total SUPPLEMENTARY	Material Material - To	otal - Total	7 7	Jul 16, 2025 Jul 16, 2025 Jul 2025	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$141,480.00) \$141,480.00 \$0.00 \$0.00	Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroek/1 overridding Payment			
	1730 -	HALF-SOLE REPAIR Total SUPPLEMENTARY WEARING SURFACE	Material Material - To	otal - Total	7 7 4	Jul 16, 2025 Jul 16, 2025 Jul 2, 2025 Jun 2, 2025 Jun 2, 2025	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$141,480.00) \$141,480.00 \$0.00 \$0.00 \$0.00 (\$9,000.00)	Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroekj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment			
	1730 -	HALF-SOLE REPAIR Total SUPPLEMENTARY WEARING SURFACE	Material Material - To	otal - Total	7 7 4 4 4	Jul 16, 2025 Jul 16, 2025 Jun 2, 2025 Jun 2, 2025 Jun 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$141,480.00) \$141,480.00 \$0.00 \$0.00 \$0.00 (\$9,000.00)	Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroekj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment			
	1730 -	HALF-SOLE REPAIR Total SUPPLEMENTARY WEARING SURFACE	Material Material - To	otal - Total	7 7 4 4 5 5	Jul 16, 2025 Jul 16, 2025 Jul 2, 2025 Jun 2, 2025 Jun 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$141,480.00) \$141,480.00 \$0.00 \$0.00 (\$9,000.00) \$9,000.00	Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroekj1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user browns1 overridding Payment Estimate Item Adjustment (0003) due to user browns1 overridding Payment			





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J5P3525	1790	SUPPLEMENTARY WEARING SURFACE	Material						Estimate Exception 5 on the current Payment Estimate.			
				- Total	al			\$0.00				
		MATERIAL	Material - To	otal				\$0.00				
	1790 -	Total						\$0.00				
	1800	LATEX MODIFIED CONCRETE WEARING	Material		4	Jun 2, 2025	SYSTEM	(\$76,570.00)				
		SURFACE			4	Jun 2, 2025	SYSTEM	\$76,570.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 10 on the current Payment Estimate.			
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	1800 -	Total						\$0.00				
	1830	HALF-SOLE REPAIR	Material		7	Jul 16, 2025	SYSTEM	(\$170,760.00)				
					7	Jul 16, 2025	SYSTEM	\$170,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kroekj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.			
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	1830 -	Total						\$0.00				
	5001	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		6	Jul 1, 2025	SYSTEM	(\$16,747.50)				
					6	Jul 1, 2025	SYSTEM	\$16,747.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					7	Jul 16, 2025	SYSTEM	(\$16,747.50)				
					7	Jul 16, 2025	SYSTEM	\$16,747.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kroekj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.			
				- Total				\$0.00				
			Material - To	otal				\$0.00				
	5001 -	Total						\$0.00				
J5P3525 -	Total							\$0.00				
Overall -	Total							\$0.00				

MoDOT

Contract Adjustments for Contract - 241213-D4A

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 16 of 16