\$301,075.00



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 4, 2025

Progress Estimate Number 8	Contract ID Prime Cont		13-D4A C Bridge, LLC	Pay Period Pay Period		,	5, 2025 1, 2025	Net (	nal Contract Change Order ent Contract	\$56	94,404.43 65,114.50 59,518.93	
Approval Date											By U	Jser
August 4, 2025			Generated a	and Approve	d (and shoul	ld be co	onsidere	d Draft) a	t the Project C	Office Level by	,	kroekj1
August 4, 2025			Reviewed and A	Approved (and	d should be	consid	ered Dra	ft) at the	Resident Engi	neer Level by	,	browns1
August 6, 2025				Reviewe	d and Appro	oved at	the Cen	tral Office	e Controllers C	Office Level by	,	ramses1
Original Completic	on Date	Current Co	mpletion Date	Act	tual Comple	etion D	ate	9/	of Current C	ontract Amo	unt Comple	te
December 1, 2	026	Decem	ber 1, 2026							51.04%		
	Co	ontract Informat	ional Dates						Mile	estones		
Date Description	Original C	ompletion Date	Current Comp	oletion Date				ate	Original	Current	Days	Diary
Acceptance Date							Desc	ription	Completion Date	Completion Date	Remaining	Charge Days
Awarded Date	January 8,	2025	January 8, 202	25							Milestone	
Letting Date	December	13, 2024	December 13,	2024			Milestor	-	October	October	71	
Notice to Proceed Date	February 1	0, 2025	February 10, 2	025			Calenda JSP F	ır rime	16, 2025	16, 2025		
Work Began Date	May 5, 202	5	May 5, 2025				Liquidat Savings					
							J5P352 Bridges	5				

Contract Total Pa	ay For Estimate No. 8			
		This Estimate	Previous	To Date
241213-D4A				
	Total Posted Items Pay	\$301,075.00	\$2,536,377.44	\$2,837,452.44
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$2,536,377.44	\$2,837,452.44
Contract Total Pa	ayable This Estimate:	\$301,075.00		

Community Forum	i ayabio iiio	_otimato.	φου 1,01 0.00				
Items Paid This	Estimate Per	<u>iod</u>					
Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3525	1150	2161001	TOTAL SURFACE HYDRO DEMOLITION	SQYD	\$70.000	460	\$32,200.00
	1180	2161503	REMOVAL OF EXISTING DECK REPAIR	SQFT	\$25.000	19	\$475.00
	1190	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	CY	\$1,000.000	2	\$2,000.00
	1200	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	SQYD	\$205.000	460	\$94,300.00
	1240	7040104	HALF-SOLE REPAIR	SQFT	\$120.000	50	\$6,000.00
	1280	2161001	TOTAL SURFACE HYDRO DEMOLITION	SQYD	\$70.000	460	\$32,200.00
	1320	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	CY	\$1,000.000	2	\$2,000.00
	1330	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	SQYD	\$205.000	460	\$94,300.00
	1360	7040104	HALF-SOLE REPAIR	SQFT	\$120.000	50	\$6,000.00
	1860	2061000	CLASS 1 EXCAVATION	CUYD	\$250.000	23	\$5,750.00
	1920	7039907	MISC.SELF-CONSOLIDATING CONCRETE	CUYD	\$1,800.000	11	\$19,800.00
	1950	7101000	REINFORCING STEEL (EPOXY COATED)	LB	\$5.000	1,210	\$6,050.00
Project J5P35	25 - Total						\$301,075.00

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item Adjustments This Estimate

Overall - Total

Revision 5/29/2025 Page 1 of 16



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 4, 2025

Pro Estimat	gress e Num 8		241213-D4A E & C Bridge,		Period Start Period End	July 16, 2025 August 1, 2025	Net Chang	ontract Amor ge Order Amor ontract Amor	unt	\$4,994,404.43 \$565,114.50 \$5,559,518.93
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type		Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3525	1000	CONCRETE TRAFFIC BARRIER, TYPE C	Material		generated Mat Adjustment (00 overridding Pa	nt offsets the origina terial Payment Estin 001) due to user kro syment Estimate Exc yment Estimate.	nate Item ekj1	460	\$145.00	\$66,700.00
	1000	CONCRETE TRAFFIC BARRIER, TYPE C	Material					-460	\$145.00	(\$66,700.00)
	1060	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		generated Mat Adjustment (00 overridding Pa	nt offsets the origina terial Payment Estin 002) due to user kro lyment Estimate Exo lyment Estimate.	naté Item ekj1	10,000	\$0.80	\$8,000.00
	1060	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material					-10,000	\$0.80	(\$8,000.00)
	1070	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		generated Mat Adjustment (00 overridding Pa	nt offsets the origina terial Payment Estin 003) due to user kro lyment Estimate Exc yment Estimate.	naté Item ekj1	7,000	\$0.80	\$5,600.00
	1070	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material					-7,000	\$0.80	(\$5,600.00)
	1730	HALF-SOLE REPAIR	Material		generated Mat Adjustment (00 overridding Pa	nt offsets the origina terial Payment Estin 004) due to user kro yment Estimate Exo yment Estimate.	naté Item ekj1	1,179	\$120.00	\$141,480.00
	1730	HALF-SOLE REPAIR	Material					-1,179	\$120.00	(\$141,480.00)
	1830	HALF-SOLE REPAIR	Material		generated Mat Adjustment (00 overridding Pa	nt offsets the origina terial Payment Estin 005) due to user kro lyment Estimate Exc Payment Estimate.	naté Item ekj1	1,423	\$120.00	\$170,760.00
	1830	HALF-SOLE REPAIR	Material					-1,423	\$120.00	(\$170,760.00)
	5001	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		generated Mat Adjustment (00 overridding Pa	nt offsets the origina terial Payment Estin 006) due to user kro lyment Estimate Exc Payment Estimate.	naté Item ekj1	101.50000	\$165.00	\$16,747.50
	5001	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material					-101.50000	\$165.00	(\$16,747.50)
Total										\$0.00

Revision 5/29/2025 Page 2 of 16



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Co	ontract Project Informa	ation
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J5P3523	FAF 50-3(118)	3 Bridge rehabilitations	50	COLE	at Bolivar St. and Vetter L	n. in Jefferson City	
J5P3525	FAF 54-3(218)	8 Bridge rehabilitations	54	COLE	at various location near Je	efferson City	
Totals b	y Job Nu	ımbers					
J5P3523				tem Pay	This Estimate \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	Previous \$31,250.00 \$0.00 \$31,250.00 \$0.00	To Date \$31,250.00 \$0.00 \$31,250.00 \$0.00
	Liquida	ated Damages Contract Adjust	tments		\$0.00 \$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00
J5P3525		l Item Pay Item Adjustme		tem Pay	This Estimate \$301,075.00 \$0.00 \$301,075.00	Previous \$2,505,127.44 \$0.00 \$2,505,127.44	To Date \$2,806,202.44 \$0.00 \$2,806,202.44
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 5/29/2025 Page 3 of 16



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 6173000, Project Item Line Number 1000, Material Set 617300096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 6173000, Project Item Line Number 1000, Material Set 617300096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 6173000, Project Item Line Number 1000, Material Set 617300096, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 6173000, Project Item Line Number 1000, Material Set 617300096, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 6205902A, Project Item Line Number 1060, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 6205902A, Project Item Line Number 1060, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 6205903A, Project Item Line Number 1070, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 6205903A, Project Item Line Number 1070, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 7040104, Project Item Line Number 1730, Material Set 704010496, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 7040104, Project Item Line Number 1830, Material Set 704010496, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3525, Item 7040112, Project Item Line Number 5001, Material Set 704011296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	kroekj1; waiting on MoDOT QA testing to be entered	kroekj1	Overridden

Revision 5/29/2025 Page 4 of 16



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ontract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
41213-	J5P3523	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$54,000.00	\$0.0
4A		0001	0020	2072000	LINEAR GRADING CLASS 2	4.60	0.00	4.60	STA	0.00	\$1,750.00	\$0.0
		0001	0030	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	92.00	0.00	92.00	SQYD	0.00	\$15.00	\$0.0
		0001	0040	4133200	ULTRATHIN BONDED WEARING SURFACE, TYPE C	102.00	0.00	102.00	SQYD	0.00	\$150.00	\$0.0
		0001	0050	6081000	CONCRETE MEDIAN	0.60	0.00	0.60	SQYD	0.00	\$1,500.00	\$0.0
		0001	0060	6086004	CONCRETE SIDEWALK, 4 IN.	91.10	0.00	91.10	SQYD	0.00	\$90.00	\$0.0
		0001	0070	6091052	CURB AND GUTTER TYPE B	158.00	0.00	158.00	LF	0.00	\$60.00	\$0.0
		0001	0080	6122040	WORK ZONE CRASH CUSHION (NARROW)	6.00	0.00	6.00	EA	0.00	\$7,100.00	\$0.0
		0001	0090	6161005	CONSTRUCTION SIGNS	4,281.00	0.00	4,281.00	SQFT	0.00	\$8.00	\$0.0
		0001	0100	6161008	ADVANCED WARNING RAIL SYSTEM	15.00	0.00	15.00	EA	0.00	\$55.00	\$0.0
		0001	0110	6161010	RELOCATED SIGNS	1,124.00	0.00	1,124.00	SQFT	0.00	\$7.25	\$0.0
		0001	0120	6161025	CHANNELIZER (TRIM-LINE)	250.00	0.00	250.00	EA	0.00	\$30.00	\$0.0
		0001	0130	6161030	TYPE 3 MOVEABLE BARRICADE	59.00	0.00	59.00	EA	0.00	\$175.00	\$0.0
		0001	0140	6161033	DIRECTION INDICATOR BARRICADE	29.00	0.00	29.00	EA	0.00	\$100.00	\$0.0
		0001	0150	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	0.00	\$3,000.00	\$0.0
		0001	0160	6161055	SEQUENTIAL FLASHING WARNING LIGHT	29.00	0.00	29.00	EA	0.00	\$100.00	\$0.0
		0001	0170	6161070	TUBULAR MARKER	48.00	0.00	48.00	EA	0.00	\$65.00	\$0.0
		0001	0180	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	8.00	0.00	8.00	EA	0.00	\$4,250.00	\$0.0
		0001	0190	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	8.00	0.00	8.00	EA	0.00	\$1,850.00	\$0.0
		0001	0200	6169901	MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM	1.00	0.00	1.00	LS	0.00	\$57,000.00	\$0.0
		0001	0210	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	460.00	0.00	460.00	LF	0.00	\$145.00	\$0.0
		0001	0220	6173100	CONCRETE TRAFFIC BARRIER, TYPE D	112.00	0.00	112.00	LF	0.00	\$225.00	\$0.0
		0001	0230	6181000	MOBILIZATION	1.00	0.00	1.00	LS		\$125,000.00	\$31,250.0
		0001	0240	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	1.00	0.00	1.00	EA	0.00	\$2,000.00	\$0.0
		0001	0250	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	8,571.00	0.00	8,571.00	LF	0.00	\$0.80	\$0.0
		0001	0260	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,601.00	0.00	7,601.00	LF	0.00	\$0.80	\$0.0
		0001	0270	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	863.00	0.00	863.00	LF	0.00	\$5.00	\$0.0
		0001	0280	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	123.00	0.00	123.00	LF	0.00	\$5.00	\$0.
		0001	0290	6207001	PAVEMENT MARKING REMOVAL	40,991.00	0.00	40,991.00	LF	0.00	\$0.80	\$0.0
		0001	0300	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	1.00	0.00	1.00	EA	0.00	\$500.00	\$0.
		0001	0310	6208064A	TEMPORARY RAISED PAVEMENT MARKER	96.00	0.00	96.00	EA	0.00	\$5.00	\$0.
		0001	0320	6208076 6221001	4 IN TEMPORARY PAVEMENT MARKING PAINT  COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	17,866.00 102.00	0.00	17,866.00 102.00	SQYD	0.00	\$0.80 \$25.00	\$0. \$0.
		0001	0340	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$9,000.00	\$0.
		0001	0350	8025006	MULCHING	0.40	0.00	0.40	ACRE	0.00	\$2,500.00	\$0.
		0001	0360	8051000A	SEEDING - COOL SEASON GRASSES	0.40	0.00	0.40	ACRE	0.00	\$4,000.00	\$0.0
		0001	0370	8061016	SEDIMENT REMOVAL	5.00	0.00	5.00	CUYD	0.00	\$5.00	\$0.
		0001	0380	8061017	TEMPORARY SEEDING	0.40	0.00	0.40	ACRE	0.00	\$2,500.00	\$0.
		0001	0390	8061019	SILT FENCE	542.00	0.00	542.00	LF	0.00	\$2.80	\$0.
		0040	0400	9035011A	ST-STRUCTURAL	160.00	0.00	160.00	SQFT	0.00	\$35.00	\$0.
		0070	0410	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	28.00	0.00	28.00	SQFT	0.00	\$250.00	\$0.
		0070	0420	2161001	TOTAL SURFACE HYDRO DEMOLITION	962.00	0.00	962.00	SQYD	0.00	\$74.00	\$0.
		0070	0430	2161501	REMOVAL OF ASPHALT WEARING SURFACE	8,655.00	0.00	8,655.00	SQFT	0.00	\$3.25	\$0.
		0070	0440	2163000	PARTIAL REMOVAL OF EXISTING BRIDGE DECK	2,791.00	0.00	2,791.00	SQFT	0.00	\$38.00	\$0.
		0070	0450	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.00	\$1,500.00	\$0.
		0070	0460	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	150.00	0.00	150.00	SQYD	0.00	\$225.00	\$0.
		0070	0470	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	5.00	0.00	5.00	CY	0.00	\$1,000.00	\$0.
		0070	0480	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	708.00	0.00	708.00	SQYD	0.00	\$185.00	\$0.
		0070	0490	6071068	(120 IN.) PEDESTRIAN FENCE (STRUCTURES)	329.00	0.00	329.00	LF	0.00	\$155.00	\$0.
		0070	0500	7031004	DIAMOND GRINDING	708.00	0.00	708.00	SQYD	0.00	\$7.50	\$0.
		0070	0510	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	2.50	0.00	2.50	CUYD	0.00	\$2,500.00	\$0.
		0070	0520	7034219A	TYPE D BARRIER	657.00	0.00	657.00	LF	0.00	\$190.00	\$0.
		0070		7034219A 7034430	SIDEWALK (BRIDGES)	3,395.00	0.00	3,395.00	SQFT	0.00	\$190.00	\$0.
		0070	0530									

Revision 5/29/2025 Page 5 of 16



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

act Proje No.	ct Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
3- J5P35	23 0070	0550	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	212.00	0.00	212.00	SQFT	0.00	\$165.00	\$0.00
	0070	0560	7040113	CLEANING AND EPOXY COATING	3,807.00	0.00	3,807.00	SQFT	0.00	\$5.93	\$0.00
	0070	0570	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$8,500.00	\$0.00
	0071	0580	2161001	TOTAL SURFACE HYDRO DEMOLITION	474.00	0.00	474.00	SQYD	0.00	\$74.00	\$0.0
	0071	0590	2161501	REMOVAL OF ASPHALT WEARING SURFACE	4,261.00	0.00	4,261.00	SQFT	0.00	\$2.25	\$0.0
	0071	0600	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	0.00	100.00	SQFT	0.00	\$25.00	\$0.0
	0071	0610	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	0.00	3.00	CY	0.00	\$1,000.00	\$0.0
	0071	0620	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	474.00	0.00	474.00	SQYD	0.00	\$220.00	\$0.0
	0071	0630	7031004	DIAMOND GRINDING	474.00	0.00	474.00	SQYD	0.00	\$8.00	\$0.0
	0071	0640	7040104	HALF-SOLE REPAIR	100.00	0.00	100.00	SQFT	0.00	\$125.00	\$0.0
	0071	0650	7040113	CLEANING AND EPOXY COATING	1,130.00	0.00	1,130.00	SQFT	0.00	\$7.70	\$0.0
	0071	0660	7172054	OPEN CELL FOAM JOINT SEAL	57.00	0.00	57.00	LF	0.00	\$95.00	\$0.0
	0072	0670	2161001	TOTAL SURFACE HYDRO DEMOLITION	474.00	0.00	474.00	SQYD	0.00	\$74.00	\$0.0
	0072	0680	2161501	REMOVAL OF ASPHALT WEARING SURFACE	4,261.00	0.00	4,261.00	SQFT	0.00	\$3.25	\$0.0
	0072										
	0072	0690	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	0.00	100.00	SQFT	0.00	\$25.00	\$0.0
	0072	0700	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	0.00	3.00	CY	0.00	\$1,000.00	\$0.0
		0710	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	474.00	0.00	474.00	SQYD	0.00	\$220.00	\$0.0
	0072	0720	7031004	DIAMOND GRINDING	474.00	0.00	474.00	SQYD	0.00	\$8.00	\$0.0
	0072	0730	7040104	HALF-SOLE REPAIR	100.00	0.00	100.00	SQFT	0.00	\$125.00	\$0.0
	0072	0740	7040113	CLEANING AND EPOXY COATING	1,130.00	0.00	1,130.00	SQFT	0.00	\$7.70	\$0.0
	0072	0750	7172054	OPEN CELL FOAM JOINT SEAL	57.00	0.00	57.00	LF	0.00	\$95.00	\$0.0
Projec	t J5P3523 - T	otal Value	Posted to D	ate as of Report Generated Date							\$31,250.0
J5P35	25 0001	0760	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.75	\$45,000.00	\$33,750.0
	0001	0770	4030003	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095C MIX)	8.20	0.00	8.20	TONS	0.00	\$1,500.00	\$0.0
	0001	0780	4071005	TACK COAT	8.00	0.00	8.00	GAL	0.00	\$50.00	\$0.0
	0001	0790	6113020	FURNISHING TYPE 2 ROCK BLANKET	107.00	0.00	107.00	CUYD	0.00	\$60.00	\$0.0
	0001	0800	6113040	PLACING TYPE 2 ROCK BLANKET	107.00	0.00	107.00	CUYD	0.00	\$40.00	\$0.0
	0001	0810	6122014	IMPACT ATTENUATOR 60 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	2.00	\$4,130.00	\$8,260.0
	0001	0820	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	1.00	0.00	1.00	EA	1.00	\$4,625.00	\$4,625.0
	0001	0830	6122020	REPLACEMENT SAND BARREL	8.00	0.00	8.00	EA	0.00	\$495.00	\$0.0
	0001	0840	6122030	IMPACT ATTENUATOR (RELOCATION)	8.00	0.00	8.00	EA	6.00	\$1,140.00	\$6,840.0
	0001	0850	6122040	WORK ZONE CRASH CUSHION (NARROW)	6.00	0.00	6.00	EA	6.00	\$7,100.00	\$42,600.0
	0001	0860	6133018	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	5.60	0.00	5.60	TONS	0.00	\$1,200.00	\$0.0
	0001	0870	6133019	REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	35.60	0.00	35.60	SQYD	0.00	\$100.00	\$0.
	0001	0880	6161005	CONSTRUCTION SIGNS	2,629.00	0.00	2,629.00	SQFT	2,595.00	\$8.00	\$20,760.0
	0001	0890	6161008	ADVANCED WARNING RAIL SYSTEM	14.00	0.00	14.00	EA	10.00	\$55.00	\$550.
	0001	0900	6161010	RELOCATED SIGNS	2,434.00	0.00	2,434.00	SQFT	1,327.00	\$7.25	\$9,620.
	0001	0910	6161025	CHANNELIZER (TRIM-LINE)	253.00	0.00	253.00	EA	253.00	\$30.00	\$7,590.
											\$3,000.
	0001	0920	6161030		31.00	0.00	31.00		15.00	\$200.00	**,***
	0001	0920	6161030	TYPE 3 MOVEABLE BARRICADE  DIRECTION INDICATOR BARRICADE	31.00	0.00	31.00	EA FA	15.00 30.00	\$200.00 \$100.00	\$3,000
		0930	6161033	DIRECTION INDICATOR BARRICADE	30.00	0.00	30.00	EA	30.00	\$100.00	
	0001	0930 0940	6161033 6161040	DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL	30.00	0.00	30.00 2.00	EA EA	30.00 2.00	\$100.00 \$3,000.00	\$3,000.0 \$6,000.0
	0001	0930 0940 0950	6161033 6161040 6161055	DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT	30.00 2.00 30.00	0.00 0.00 0.00	30.00 2.00 30.00	EA EA	30.00 2.00 30.00	\$100.00 \$3,000.00 \$100.00	\$6,000.0 \$3,000.0
	0001 0001 0001	0930 0940	6161033 6161040	DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL	30.00	0.00	30.00 2.00	EA EA	30.00 2.00	\$100.00 \$3,000.00	\$6,000.0 \$3,000.0 \$4,745.0
	0001 0001 0001 0001	0930 0940 0950 0960	6161033 6161040 6161055 6161070 6161099	DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION	30.00 2.00 30.00 73.00	0.00 0.00 0.00 0.00	30.00 2.00 30.00 73.00	EA EA EA	30.00 2.00 30.00 73.00	\$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00	\$6,000.0 \$3,000.0 \$4,745.0 \$51,000.0
	0001 0001 0001 0001 0001	0930 0940 0950 0960 0970	6161033 6161040 6161055 6161070 6161099 6162002	DIRECTION INDICATOR BARRICADE  FLASHING ARROW PANEL  SEQUENTIAL FLASHING WARNING LIGHT  TUBULAR MARKER  CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  TEMPORARY LONG-TERM RUMBLE STRIPS	30.00 2.00 30.00 73.00 12.00	0.00 0.00 0.00 0.00 0.00	30.00 2.00 30.00 73.00 12.00	EA EA EA EA	30.00 2.00 30.00 73.00 12.00	\$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00	\$6,000. \$3,000. \$4,745. \$51,000.
	0001 0001 0001 0001 0001	0930 0940 0950 0960 0970 0980 0990	6161033 6161040 6161055 6161070 6161099 6162002 6169901	DIRECTION INDICATOR BARRICADE  FLASHING ARROW PANEL  SEQUENTIAL FLASHING WARNING LIGHT  TUBULAR MARKER  CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  TEMPORARY LONG-TERM RUMBLE STRIPS  MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM	30.00 2.00 30.00 73.00 12.00 20.00	0.00 0.00 0.00 0.00 0.00 0.00	30.00 2.00 30.00 73.00 12.00 20.00	EA EA EA EA LS	30.00 2.00 30.00 73.00 12.00 4.00 0.80	\$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00 \$1,850.00 \$95,750.00	\$6,000. \$3,000. \$4,745. \$51,000. \$7,400.
	0001 0001 0001 0001 0001 0001 0001	0930 0940 0950 0960 0970 0980 0990	6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173000	DIRECTION INDICATOR BARRICADE  FLASHING ARROW PANEL  SEQUENTIAL FLASHING WARNING LIGHT  TUBULAR MARKER  CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  TEMPORARY LONG-TERM RUMBLE STRIPS  MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM  CONCRETE TRAFFIC BARRIER, TYPE C	30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00	30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00	EA EA EA LS LF	30.00 2.00 30.00 73.00 12.00 4.00 0.80 460.00	\$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00 \$1,850.00 \$95,750.00 \$145.00	\$6,000 \$3,000 \$4,745 \$51,000 \$7,400 \$66,700
	0001 0001 0001 0001 0001 0001	0930 0940 0950 0960 0970 0980 0990	6161033 6161040 6161055 6161070 6161099 6162002 6169901	DIRECTION INDICATOR BARRICADE  FLASHING ARROW PANEL  SEQUENTIAL FLASHING WARNING LIGHT  TUBULAR MARKER  CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  TEMPORARY LONG-TERM RUMBLE STRIPS  MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM	30.00 2.00 30.00 73.00 12.00 20.00	0.00 0.00 0.00 0.00 0.00 0.00	30.00 2.00 30.00 73.00 12.00 20.00	EA EA EA EA LS	30.00 2.00 30.00 73.00 12.00 4.00 0.80	\$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00 \$1,850.00 \$95,750.00	\$6,000. \$3,000. \$4,745. \$51,000. \$7,400. \$66,700.
	0001 0001 0001 0001 0001 0001 0001 000	0930 0940 0950 0960 0970 0980 0990 1000	6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173000 6173600D	DIRECTION INDICATOR BARRICADE FLASHING ARROW PANEL SEQUENTIAL FLASHING WARNING LIGHT TUBULAR MARKER CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  TEMPORARY LONG-TERM RUMBLE STRIPS MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM CONCRETE TRAFFIC BARRIER, TYPE C  TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00	EA EA EA EA EA LS LF	30.00 2.00 30.00 73.00 12.00 4.00 0.80 460.00 688.00	\$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00 \$1,850.00 \$95,750.00 \$145.00	\$6,000. \$3,000. \$4,745. \$51,000. \$7,400. \$76,600. \$66,700.
	0001 0001 0001 0001 0001 0001 0001 000	0930 0940 0950 0960 0970 0980 0990 1000	6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173000 6173700B	DIRECTION INDICATOR BARRICADE  FLASHING ARROW PANEL  SEQUENTIAL FLASHING WARNING LIGHT  TUBULAR MARKER  CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  TEMPORARY LONG-TERM RUMBLE STRIPS  MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM  CONCRETE TRAFFIC BARRIER, TYPE C  TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED  TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR	30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00	EA EA EA EA EA LS LF	30.00 2.00 30.00 73.00 12.00 4.00 0.80 460.00 688.00	\$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00 \$1,850.00 \$95,750.00 \$145.00	\$6,000 \$3,000 \$4,745 \$51,000 \$7,400 \$66,700 \$33,849
	0001 0001 0001 0001 0001 0001 0001 000	0930 0940 0950 0960 0970 0980 0990 1000 1010	6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173600D 6173700B	DIRECTION INDICATOR BARRICADE  FLASHING ARROW PANEL  SEQUENTIAL FLASHING WARNING LIGHT  TUBULAR MARKER  CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  TEMPORARY LONG-TERM RUMBLE STRIPS  MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM  CONCRETE TRAFFIC BARRIER, TYPE C  TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED  TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00	EA EA EA EA EA LS LF LF	30.00 2.00 30.00 73.00 12.00 4.00 0.80 460.00 688.00	\$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00 \$1,850.00 \$95,750.00 \$145.00 \$49.20	\$6,000 \$3,000 \$4,745 \$51,000 \$7,400 \$66,700 \$33,849 \$31,308
	0001 0001 0001 0001 0001 0001 0001 000	0930 0940 0950 0960 0970 0980 0990 1000 1010 1020	6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173600D 6173700B 6175010A	DIRECTION INDICATOR BARRICADE  FLASHING ARROW PANEL  SEQUENTIAL FLASHING WARNING LIGHT  TUBULAR MARKER  CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  TEMPORARY LONG-TERM RUMBLE STRIPS  MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM  CONCRETE TRAFFIC BARRIER, TYPE C  TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED  TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED  RELOCATING TEMPORARY TRAFFIC BARRIER	30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00 575.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00 575.00	EA EA EA EA EA LS LF LF LF	30.00 2.00 30.00 73.00 12.00 4.00 0.80 460.00 688.00 575.00	\$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00 \$1,850.00 \$95,750.00 \$145.00 \$49.20 \$54.45	\$6,000. \$3,000. \$4,745. \$51,000. \$7,400. \$66,700. \$33,849. \$31,308. \$20,304.
	0001 0001 0001 0001 0001 0001 0001 000	0930 0940 0950 0960 0970 0980 0990 1000 1010 1020	6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173000 6173700B 6175010A 6175011B	DIRECTION INDICATOR BARRICADE  FLASHING ARROW PANEL  SEQUENTIAL FLASHING WARNING LIGHT  TUBULAR MARKER  CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  TEMPORARY LONG-TERM RUMBLE STRIPS  MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM  CONCRETE TRAFFIC BARRIER, TYPE C  TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED  TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED  RELOCATING TEMPORARY TRAFFIC BARRIER  RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00 575.00 1,775.00 663.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00 575.00	EA EA EA EA LS LF LF LF LF	30.00 2.00 30.00 73.00 12.00 4.00 0.80 460.00 688.00 575.00	\$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00 \$1,850.00 \$95,750.00 \$145.00 \$49.20 \$54.45 \$12.90 \$17.65	\$6,000. \$3,000. \$4,745. \$51,000. \$7,400. \$76,600. \$66,700. \$33,849. \$31,308. \$20,304. \$5,842.
	0001 0001 0001 0001 0001 0001 0001 000	0930 0940 0950 0960 0970 0980 0990 1000 1010 1020 1030 1040	6161033 6161040 6161055 6161070 6161099 6162002 6169901 6173000 6173700B 6175010A 6175011B 6181000 6205902A	DIRECTION INDICATOR BARRICADE  FLASHING ARROW PANEL  SEQUENTIAL FLASHING WARNING LIGHT  TUBULAR MARKER  CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED  TEMPORARY LONG-TERM RUMBLE STRIPS  MISC. WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM  CONCRETE TRAFFIC BARRIER, TYPE C  TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED  TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED  RELOCATING TEMPORARY TRAFFIC BARRIER  RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED  MOBILIZATION  6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING	30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00 575.00 1,775.00 663.00 1.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	30.00 2.00 30.00 73.00 12.00 20.00 1.00 460.00 688.00 575.00 1,775.00 663.00	EA EA EA EA LS LF LF LF LF LF	30.00 2.00 30.00 73.00 12.00 4.00 0.80 460.00 688.00 575.00 1,574.00 331.00	\$100.00 \$3,000.00 \$100.00 \$65.00 \$4,250.00 \$1,850.00 \$95,750.00 \$145.00 \$49.20 \$54.45 \$12.90 \$17.65 \$175,000.00	\$6,000. \$3,000. \$4,745.

Revision 5/29/2025 Page 6 of 16



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

tract Proje D No		egory	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
213- J5P3	525 000	1	1090	6208064A	TEMPORARY RAISED PAVEMENT MARKER	146.00	0.00	146.00	EA	0.00	\$5.00	\$0.0
١.	000	1 .	1100	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	47,631.00	0.00	47,631.00	LF	35,491.00	\$0.80	\$28,392.8
	000	1	1110	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	102.00	0.00	102.00	SQYD	0.00	\$30.00	\$0.0
	000		1120	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	160.00	0.00	160.00	SQYD	0.00	\$10.00	\$0.0
	000		1130	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$9,000.00	\$0.0
	0070		1140	2161000	SCARIFICATION OF BRIDGE DECK	227.00	0.00	227.00	SQYD	0.00	\$34.25	\$0.0
	0070		1150	2161001	TOTAL SURFACE HYDRO DEMOLITION	909.00	0.00	909.00	SQYD	460.00	\$70.00	\$32,200.0
	0070		1160	2161501	REMOVAL OF ASPHALT WEARING SURFACE	1,744.00	0.00	1,744.00	SQFT	880.00	\$3.25	\$2,860.0
	0070		1170	2161502	REMOVAL OF CONCRETE WEARING SURFACE	4,392.00	0.00	4,392.00	SQFT	2,200.00	\$4.50	\$9,900.0
	0070	0	1180	2161503	REMOVAL OF EXISTING DECK REPAIR	50.00	0.00	50.00	SQFT	19.00	\$25.00	\$475.0
	0070	0	1190	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	4.00	0.00	4.00	CY	2.00	\$1,000.00	\$2,000.0
	0070		1200	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	909.00	0.00	909.00	SQYD	460.00	\$205.00	\$94,300.0
	0070		1210	7031004	DIAMOND GRINDING	909.00	0.00	909.00	SQYD	0.00	\$7.00	\$0.0
	0070	0	1220	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	5.00	0.00	5.00	SQFT	0.00	\$225.00	\$0.0
	0070	0	1230	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	15.00	0.00	15.00	SQFT	0.00	\$400.00	\$0.0
	0070	0	1240	7040104	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	50.00	\$120.00	\$6,000.0
	0070	0	1250	7040113	CLEANING AND EPOXY COATING	1,859.00	0.00	1,859.00	SQFT	0.00	\$6.51	\$0.0
	0070		1260	7172054	OPEN CELL FOAM JOINT SEAL	99.00	0.00	99.00	LF	0.00	\$50.00	\$0.0
	007		1270	2161000	SCARIFICATION OF BRIDGE DECK	227.00	0.00	227.00	SQYD	0.00	\$34.25	\$0.0
	007		1280	2161001	TOTAL SURFACE HYDRO DEMOLITION	909.00	0.00	909.00	SQYD	460.00	\$70.00	\$32,200.0
	007		1290	2161501	REMOVAL OF ASPHALT WEARING SURFACE	1,744.00	0.00	1,744.00	SQFT	880.00	\$3.25	\$2,860.0
	007		1300	2161502	REMOVAL OF CONCRETE WEARING SURFACE	4,392.00	0.00	4,392.00	SQFT	2,200.00	\$4.50	\$9,900.0
	007		1310	2161503	REMOVAL OF EXISTING DECK REPAIR	50.00	0.00	50.00	SQFT	0.00	\$25.00	\$0.0
	007		1320	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	4.00	0.00	4.00	CY	2.00	\$1,000.00	\$2,000.0
	007		1330	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	909.00	0.00	909.00	SQYD	460.00	\$205.00	\$94,300.0
	007		1340	7031004	DIAMOND GRINDING	909.00	0.00	909.00	SQYD	0.00	\$7.00	\$0.0
	007		1350	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	15.00	0.00	15.00	SQFT	0.00	\$225.00	\$0.0
	007		1360	7040104	HALF-SOLE REPAIR	50.00	0.00	50.00	SQFT	50.00	\$120.00	\$6,000.0
	007		1370	7040113	CLEANING AND EPOXY COATING	1,859.00	0.00	1,859.00	SQFT	0.00	\$6.51	\$0.0
	007		1380	7172054	OPEN CELL FOAM JOINT SEAL	99.00	0.00	99.00	LF	0.00	\$50.00	\$0.0
	0072		1390	2161001	TOTAL SURFACE HYDRO DEMOLITION	737.00	0.00	737.00	SQYD	737.00	\$70.00	\$51,590.0
	0072		1400	2161501	REMOVAL OF ASPHALT WEARING SURFACE	6,637.00	0.00	6,637.00	SQFT	6,637.00	\$3.25	\$21,570.2
	0072		1410	2161503	REMOVAL OF EXISTING DECK REPAIR	300.00	45.00	345.00	SQFT	345.00	\$15.00	\$5,175.0
	0072		1420	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	4.00	24.00	28.00	CY	24.00	\$1,000.00	\$24,000.0
	0072		1430	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	737.00	0.00	737.00	SQYD	737.00	\$190.00	\$140,030.0
	0072		1440	7031004	DIAMOND GRINDING	737.00	0.00	737.00	SQYD	737.00	\$7.00	\$5,159.0
	0072		1450	7040104	HALF-SOLE REPAIR	50.00	348.00	398.00	SQFT	398.00	\$120.00	\$47,760.0
	0072	0	1460	7040113	CLEANING AND EPOXY COATING	1,792.00	0.00	1,792.00	SQFT	1,792.00	\$4.86	\$8,709.1
	0072		1470	7172054	OPEN CELL FOAM JOINT SEAL	94.00	0.00	94.00	LF	94.00	\$50.00	\$4,700.0
	0073	0	1480	2161001	TOTAL SURFACE HYDRO DEMOLITION	737.00	0.00	737.00	SQYD	737.00	\$70.00	\$51,590.0
	0073	0	1490	2161501	REMOVAL OF ASPHALT WEARING SURFACE	6,637.00	0.00	6,637.00	SQFT	6,637.00	\$3.25	\$21,570.2
	0073	0	1500	2161503	REMOVAL OF EXISTING DECK REPAIR	200.00	10.00	210.00	SQFT	200.00	\$20.00	\$4,000.0
	0073	0	1510	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	4.00	33.00	37.00	CY	37.00	\$1,000.00	\$37,000.0
	0073		1520	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	737.00	0.00	737.00	SQYD	737.00	\$190.00	\$140,030.0
	0073	0	1530	7031004	DIAMOND GRINDING	737.00	0.00	737.00	SQYD	737.00	\$7.00	\$5,159.0
	0073	0	1540	7040104	HALF-SOLE REPAIR	50.00	12.00	62.00	SQFT	62.00	\$120.00	\$7,440.0
	0073	0	1550	7040113	CLEANING AND EPOXY COATING	1,792.00	0.00	1,792.00	SQFT	1,792.00	\$4.86	\$8,709.1
	0073		1560	7172054	OPEN CELL FOAM JOINT SEAL	94.00	0.00	94.00	LF	94.00	\$50.00	\$4,700.0
	0074		1570	2161001	TOTAL SURFACE HYDRO DEMOLITION	638.00	0.00	638.00	SQYD	638.00	\$70.00	\$44,660.0
	0074	4	1580	2161501	REMOVAL OF ASPHALT WEARING SURFACE	5,748.00	0.00	5,748.00	SQFT	5,502.00	\$3.25	\$17,881.5
	0074		1590	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	109.00	209.00	SQFT	209.00	\$20.00	\$4,180.0
	0074		1600	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	5.00	26.00	31.00	CY	31.00	\$1,000.00	\$31,000.0
	0074		1610	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	638.00	0.00	638.00	SQYD	638.00	\$190.00	\$121,220.0
	0074		1620	7031004	DIAMOND GRINDING	638.00	0.00	638.00	SQYD	638.00	\$7.00	\$4,466.0
	0074		1630	7040104	HALF-SOLE REPAIR	100.00	789.00	889.00	SQFT	889.00	\$120.00	\$106,680.0
	0074		1640	7040107	SLAB EDGE REPAIR (BRIDGES)	10.00	0.00	10.00	LF	10.00	\$500.00	\$5,000.0
	0074	4	1650	7040113	CLEANING AND EPOXY COATING	700.00	0.00	700.00	SQFT	700.00	\$11.48	\$8,036.0

Revision 5/29/2025 Page 7 of 16



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ontract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
	J5P3525	0074	1660	7172054	OPEN CELL FOAM JOINT SEAL	89.00	0.00	89.00	LF	89.00	\$50.00	\$4,450.0
1A		0075	1670	2161001	TOTAL SURFACE HYDRO DEMOLITION	611.00	0.00	611.00	SQYD	611.00	\$70.00	\$42,770.0
		0075	1680	2161501	REMOVAL OF ASPHALT WEARING SURFACE	5,502.00	0.00	5,502.00	SQFT	5,502.00	\$3.25	\$17,881.5
		0075	1690	2161503	REMOVAL OF EXISTING DECK REPAIR	250.00	574.00	824.00	SQFT	824.00	\$20.00	\$16,480.0
		0075	1700	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	3.00	26.00	29.00	CY	29.00	\$1,000.00	\$29,000.0
		0075	1710	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	611.00	0.00	611.00	SQYD	611.00	\$190.00	\$116,090.0
		0075	1720	7031004	DIAMOND GRINDING	611.00	0.00	611.00	SQYD	611.00	\$7.50	\$4,582.5
		0075	1730	7040104	HALF-SOLE REPAIR	50.00	1,130.00	1,180.00	SQFT	1,179.00	\$120.00	\$141,480.0
		0075	1740	7040113	CLEANING AND EPOXY COATING	500.00	0.00	500.00	SQFT	500.00	\$6.21	\$3,105.0
		0075	1750	7172054	OPEN CELL FOAM JOINT SEAL	71.00	0.00	71.00	LF	71.00	\$70.00	\$4,970.0
		0076	1760	2161001	TOTAL SURFACE HYDRO DEMOLITION	803.00	0.00	803.00	SQYD	803.00	\$70.00	\$56,210.0
		0076	1770	2161501	REMOVAL OF ASPHALT WEARING SURFACE	7,227.00	0.00	7,227.00	SQFT	7,227.00	\$3.25	\$23,487.7
		0076	1780	2161503	REMOVAL OF EXISTING DECK REPAIR	300.00	644.00	944.00	SQFT	944.00	\$18.00	\$16,992.0
		0076	1790	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	9.00	29.00	38.00	CY	36.00	\$1,000.00	\$36,000.0
		0076	1800	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	803.00	0.00	803.00	SQYD	803.00	\$190.00	\$152,570.0
		0076	1810	7031004	DIAMOND GRINDING	803.00	0.00	803.00	SQYD	803.00	\$7.50	\$6,022.5
		0076	1820	7040101	SUBSTRUCTURE REPAIR (FORMED)	10.00	0.00	10.00	SQFT	10.00	\$215.00	\$2,150.0
		0076	1830	7040104	HALF-SOLE REPAIR	500.00	923.00	1,423.00	SQFT	1,423.00	\$120.00	\$170,760.0
		0076	1840	7040113	CLEANING AND EPOXY COATING	750.00	0.00	750.00	SQFT	0.00	\$6.21	\$0.0
		0076	1850	7172054	OPEN CELL FOAM JOINT SEAL	90.00	0.00	90.00	LF	90.00	\$55.00	\$4,950.0
		0077	1860	2061000	CLASS 1 EXCAVATION	23.00	0.00	23.00	CUYD	23.00	\$250.00	\$5,750.0
		0077	1870	2161001	TOTAL SURFACE HYDRO DEMOLITION	684.00	0.00	684.00	SQYD	0.00	\$74.00	\$0.0
		0077	1880	2161502	REMOVAL OF CONCRETE WEARING SURFACE	6,160.00	0.00	6,160.00	SQFT	0.00	\$4.25	\$0.0
		0077	1890	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	2.00	0.00	2.00	CY	0.00	\$1,000.00	\$0.0
		0077	1900	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	684.00	0.00	684.00	SQYD	0.00	\$200.00	\$0.0
		0077	1910	7031004	DIAMOND GRINDING	684.00	0.00	684.00	SQYD	0.00	\$8.00	\$0.0
		0077	1920	7039907	MISC.SELF-CONSOLIDATING CONCRETE	11.00	0.00	11.00	CUYD	11.00	\$1,800.00	\$19,800.0
		0077	1930	7040104	HALF-SOLE REPAIR	100.00	0.00	100.00	SQFT	0.00	\$120.00	\$0.
		0077	1940	7040113	CLEANING AND EPOXY COATING	2,600.00	0.00	2,600.00	SQFT	0.00	\$7.08	\$0.
		0077	1950	7101000	REINFORCING STEEL (EPOXY COATED)	1,210.00	0.00	1,210.00	LB	1,210.00	\$5.00	\$6,050.0
		0077	1960	7172054	OPEN CELL FOAM JOINT SEAL	92.00	0.00	92.00	LF	0.00	\$55.00	\$0.0
		0075	5001	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	0.00	101.50	101.50	SQFT	101.50	\$165.00	\$16,747.
L.					Date as of Report Generated Date							\$2,806,202.

Revision 5/29/2025 Page 8 of 16



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5P3525

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
1150	2161001	TOTAL SURFACE HYDRO DEMOLITION	7/23/25	8/4/25	1	460.00	SQYD	A13052 Passing Lane					
1180	2161503	REMOVAL OF EXISTING DECK REPAIR	7/22/25	8/4/25	1	19.00	SQFT	A13052 Passing Lane					
1190	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	7/29/25	8/4/25	1	2.00	CY	Passing lane of bridge A13052					
1200	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	7/29/25	8/4/25	1	460.00	SQYD	Passing lane of bridge A13052					
1240	7040104	HALF-SOLE REPAIR	7/22/25	8/4/25	1	50.00	SQFT	A13052 Passing Lane					
1280	2161001	TOTAL SURFACE HYDRO DEMOLITION	7/23/25	8/4/25	1	460.00	SQYD	A13053 Passing Lane					
1320	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	7/29/25	8/4/25	1	2.00	CY	Passing lane of bridge A13053					
1330	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	7/29/25	8/4/25	1	460.00	SQYD	Passing lane of bridge A13053					
1360	7040104	HALF-SOLE REPAIR	7/22/25	8/4/25	1	50.00	SQFT	A13053 Passing Lane					
1860	2061000	CLASS 1 EXCAVATION	7/23/25	8/4/25	1	23.00	CUYD	A14153 around existing piles					
1920	7039907	MISC. CONCRETE CONSTRUCTION	7/28/25	8/4/25	1	11.00	CUYD	Around piles beneath bridge A14153					
1950	7101000	REINFORCING STEEL (EPOXY COATED)	7/28/25	8/4/25	1	1,210.00	LB	Around piles beneath bridge A14153					

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 6/5/2025 Page 9 of 16



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5P3525	0810	IMPACT ATTENUATOR 60	Material		3	May 16, 2025	SYSTEM	(\$8,260.00)	
		MPH (SAND BARREL ARRAY)			3	May 16, 2025	SYSTEM	\$8,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0810 -	- Total						\$0.00	
	0820	IMPACT ATTENUATOR 65 MPH (SAND	Material		3	May 16, 2025	SYSTEM	(\$4,625.00)	
		BARREL ARRAY)			3	May 16, 2025	SYSTEM	\$4,625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0820 -	- Total						\$0.00	
	0850	WORK ZONE CRASH CUSHION	Material		3	May 16, 2025	SYSTEM	(\$42,600.00)	
		(NARROW)			3	May 16, 2025	SYSTEM	\$42,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0850 -	- Total						\$0.00	
	0880	CONSTRUCTION SIGNS	Material		3	May 16, 2025	SYSTEM	(\$16,048.00)	
					3	May 16, 2025	SYSTEM	\$16,048.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
		- Total		otal				\$0.00	
	<b>0880</b> -	ADVANCED WARNING RAIL SYSTEM	Material - To	otal	3	May 16, 2025	SYSTEM	<b>\$0.00</b> (\$550.00)	
		ADVANCED WARNING RAIL		otal	3		SYSTEM SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.
		ADVANCED WARNING RAIL		otal - Total		2025 May 16,		<b>\$0.00</b> (\$550.00)	Estimate Item Adjustment (0005) due to user hensor overridding Payment
		ADVANCED WARNING RAIL		- Total		2025 May 16,		<b>\$0.00</b> (\$550.00) \$550.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment
	0890	ADVANCED WARNING RAIL	Material	- Total		2025 May 16,		\$0.00 (\$550.00) \$550.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment
	0890	ADVANCED WARNING RAIL SYSTEM	Material	- Total		2025 May 16, 2025		\$0.00 (\$550.00) \$550.00 \$0.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment
	0890	ADVANCED WARNING RAIL SYSTEM  Total  CHANNELIZER	Material  Material - To	- Total	3	2025 May 16, 2025	SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment
	0890	ADVANCED WARNING RAIL SYSTEM  Total  CHANNELIZER	Material  Material - To	- Total	3	2025 May 16, 2025 May 16, 2025 May 16,	SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00)	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment
	0890	ADVANCED WARNING RAIL SYSTEM  Total  CHANNELIZER	Material  Material - To	- Total otal - Total	3	2025 May 16, 2025 May 16, 2025 May 16,	SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00)	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment
	0890 0890 0910	ADVANCED WARNING RAIL SYSTEM  Total  CHANNELIZER	Material - To	- Total otal - Total	3	2025 May 16, 2025 May 16, 2025 May 16,	SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$7,590.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment
	0890 0890 0910	ADVANCED WARNING RAIL SYSTEM  - Total CHANNELIZER (TRIM-LINE)  - Total TYPE 3 MOVEABLE	Material - To	- Total otal - Total	3	2025 May 16, 2025 May 16, 2025 May 16,	SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$7,590.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment
	0890 - 0910 - 0910 -	ADVANCED WARNING RAIL SYSTEM  Total CHANNELIZER (TRIM-LINE)  Total TYPE 3	Material - To	- Total otal - Total	3 3 3	2025 May 16, 2025 May 16, 2025 May 16, 2025	SYSTEM SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$7,590.00 \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment
	0890 - 0910 - 0910 -	ADVANCED WARNING RAIL SYSTEM  - Total CHANNELIZER (TRIM-LINE)  - Total TYPE 3 MOVEABLE	Material - To	- Total otal - Total	3 3 3	May 16, 2025  May 16, 2025  May 16, 2025  May 16, 2025  May 16, 2025	SYSTEM SYSTEM SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$7,590.00 \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment
	0890 - 0910 - 0910 -	ADVANCED WARNING RAIL SYSTEM  - Total CHANNELIZER (TRIM-LINE)  - Total TYPE 3 MOVEABLE	Material - To	- Total  - Total otal  - Total	3 3 3	May 16, 2025  May 16, 2025  May 16, 2025  May 16, 2025  May 16, 2025	SYSTEM SYSTEM SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$7,590.00 \$0.00 \$0.00 (\$3,000.00)	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment
	0890 0890 0910 0920	ADVANCED WARNING RAIL SYSTEM  - Total CHANNELIZER (TRIM-LINE)  - Total TYPE 3 MOVEABLE	Material - To	- Total  - Total otal  - Total	3 3 3	May 16, 2025  May 16, 2025  May 16, 2025  May 16, 2025  May 16, 2025	SYSTEM SYSTEM SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$7,590.00 \$0.00 \$0.00 (\$3,000.00)	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment
	0890 0890 0910 0920	ADVANCED WARNING RAIL SYSTEM  - Total CHANNELIZER (TRIM-LINE)  - Total TYPE 3 MOVEABLE BARRICADE	Material - To	- Total  - Total otal  - Total	3 3 3	May 16, 2025  May 16, 2025  May 16, 2025  May 16, 2025  May 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$550.00) \$550.00 \$0.00 \$0.00 (\$7,590.00) \$7,590.00 \$0.00 \$0.00 (\$3,000.00) \$3,000.00	Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment



Project I	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5P3525 0	0930	DIRECTION INDICATOR	Material						Estimate Exception 8 on the current Payment Estimate.
		BARRICADE		- Total				\$0.00	
			Material - To	rial - Total					
C	0930 -	Total						\$0.00	
0	0940	FLASHING ARROW PANEL	Material		3	May 16, 2025	SYSTEM	(\$6,000.00)	
					3	May 16, 2025	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hensor overridding Payment Estimate Exception 9 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
C	0940 -	Total						\$0.00	
0	0950	SEQUENTIAL FLASHING	Material		3	May 16, 2025	SYSTEM	(\$3,000.00)	
		WARNING LIGHT			3	May 16, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hensor overridding Payment Estimate Exception 10 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
0	0950 -	Total						\$0.00	
O	0960	TUBULAR MARKER	Material		3	May 16, 2025	SYSTEM	(\$4,745.00)	
					3	May 16, 2025	SYSTEM	\$4,745.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hensor overridding Payment Estimate Exception 11 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	Material - Total					
O	0960 -	Total						\$0.00	
0	0970	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material		3	May 16, 2025	SYSTEM	(\$51,000.00)	
					3	May 16, 2025	SYSTEM	\$51,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hensor overridding Payment Estimate Exception 12 on the current Payment Estimate.
				- Total				\$0.00	
		TE IT III E E	Material - Total					\$0.00	
0	0970 -	Total						\$0.00	
0	0980	TEMPORARY LONG-TERM	Material		3	May 16, 2025	SYSTEM	(\$7,400.00)	
		RUMBLE STRIPS			3	May 16, 2025	SYSTEM	\$7,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hensor overridding Payment Estimate Exception 13 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Total					\$0.00	
C	0980 -	Total						\$0.00	
1	1000	CONCRETE TRAFFIC	Material		7	Jul 16, 2025	SYSTEM	(\$66,700.00)	
		BARRIER, TYPE C	;		7	Jul 16, 2025	SYSTEM	\$66,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kroek/1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$66,700.00)	
					8	Aug 4, 2025	SYSTEM	\$66,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kroekj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
1	1000 -	Total						\$0.00	
1	1010	TEMPORARY TRAFFIC BARRIER, CONT.	Material		3	May 16, 2025	SYSTEM	(\$33,849.60)	



P3525	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3525	1010	FURN/RE	Material		3	May 16, 2025	SYSTEM	\$33,849.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Total					\$0.00	
	1010 -	1010 - Total							
	1020	TEMP. TRAFFIC BARRIER ANCHORED., CONT	Material		3	May 16, 2025	SYSTEM	(\$31,308.75)	
					3	May 16, 2025	SYSTEM	\$31,308.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hensor overridding Payment Estimate Exception 15 on the current Payment Estimate.
				- Total	- Total			\$0.00	
			Material - To					\$0.00	
	1020 -	- Total						\$0.00	
	1060	6 IN. WHITE HIGH BUILD	Material		7	Jul 16, 2025	SYSTEM	(\$8,000.00)	
		WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS			7	Jul 16, 2025	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kroekj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		TYPE L BEAUS			8	Aug 4, 2025	SYSTEM	(\$8,000.00)	
					8	Aug 4, 2025	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kroekj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				- Total				\$0.00	
		Material - Total						\$0.00	
	1060 -	- Total						\$0.00	
	1070	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material T,		7	Jul 16, 2025	SYSTEM	(\$5,600.00)	
					7	Jul 16, 2025	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$5,600.00)	
					8	Aug 4, 2025	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				- Total	8	Aug 4,	SYSTEM	\$5,600.00 \$0.00	Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment
			Material - Te		8	Aug 4,	SYSTEM		Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment
	1070 -	- Total	Material - To		8	Aug 4,	SYSTEM	\$0.00	Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment
	<b>1070</b> - 1420	SUPPLEMENTARY WEARING			6	Aug 4,	SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment
		SUPPLEMENTARY				Aug 4, 2025		\$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment
		SUPPLEMENTARY WEARING SURFACE			6	Aug 4, 2025 Jul 1, 2025 Jul 1,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$4,000.00)	Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment
		SUPPLEMENTARY WEARING SURFACE		otal - Total	6	Aug 4, 2025 Jul 1, 2025 Jul 1,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$4,000.00)	Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment
	1420	SUPPLEMENTARY WEARING SURFACE	Material	otal - Total	6	Aug 4, 2025 Jul 1, 2025 Jul 1,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$4,000.00) \$4,000.00	Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment
	1420	SUPPLEMENTARY WEARING SURFACE MATERIAL  Total SUPPLEMENTARY WEARING	Material	otal - Total	6	Aug 4, 2025 Jul 1, 2025 Jul 1,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$4,000.00) \$4,000.00 \$0.00	Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment
	1420 1420 -	SUPPLEMENTARY WEARING SURFACE MATERIAL  Total SUPPLEMENTARY	Material  Material - To	otal - Total	6	Jul 1, 2025 Jul 1, 2025 Jul 1, 2025	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$4,000.00) \$4,000.00 \$0.00 \$0.00	Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment
	1420 1420 -	SUPPLEMENTARY WEARING SURFACE MATERIAL  Total SUPPLEMENTARY WEARING SURFACE	Material  Material - To	otal - Total	6 6 4 4 5	Jul 1, 2025 Jul 1, 2025 Jul 2, 2025 Jun 2, 2025 Jun 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$4,000.00) \$4,000.00 \$0.00 \$0.00 (\$4,000.00) \$4,000.00	Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
	1420 1420 -	SUPPLEMENTARY WEARING SURFACE MATERIAL  Total SUPPLEMENTARY WEARING SURFACE	Material  Material - To	otal - Total	6 6 4 4 4	Jul 1, 2025  Jul 1, 2025  Jul 2, 2025  Jun 2, 2025  Jun 16, 16, 16, 16, 16, 16, 16, 16, 16, 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$4,000.00) \$4,000.00 \$0.00 \$0.00 (\$4,000.00)	Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment
	1420 1420 -	SUPPLEMENTARY WEARING SURFACE MATERIAL  Total SUPPLEMENTARY WEARING SURFACE	Material  Material - To	otal - Total	6 6 4 4 5	Jul 1, 2025  Jul 1, 2025  Jul 1, 2025  Jun 2, 2025  Jun 2, 2025  Jun 16, 2025  Jun 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 (\$4,000.00) \$4,000.00 \$0.00 \$0.00 (\$4,000.00) \$4,000.00	Estimate Item Adjustment (0003) due to user kroekj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user browns1 overridding Payment Estimate Item Adjustment (0001) due to user browns1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
I5P3525	1510	SUPPLEMENTARY	Material						Estimate Exception 2 on the current Payment Estimate.
		WEARING SURFACE		- Total				\$0.00	
		MATERIAL	Material - Total					\$0.00	
	1510 -	Total						\$0.00	
	1520	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		4	Jun 2, 2025	SYSTEM	(\$140,030.00)	
					4	Jun 2, 2025	SYSTEM	\$140,030.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 8 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1520 -	Total						\$0.00	
	1600	SUPPLEMENTARY WEARING SURFACE	Material		6	Jul 1, 2025	SYSTEM	(\$5,000.00)	
		MATERIAL			6	Jul 1, 2025	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Total					\$0.00	
	1600 -	Total						\$0.00	
	1640	SLAB EDGE REPAIR	Material		7	Jul 16, 2025	SYSTEM	(\$5,000.00)	
		(BRIDGES)			7	Jul 16, 2025	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kroekj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1640 -							\$0.00	
	1700	SUPPLEMENTARY WEARING SURFACE MATERIAL	NTARY Material		4	Jun 2, 2025	SYSTEM	(\$3,000.00)	
					4	Jun 2, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Jun 16, 2025	SYSTEM	(\$3,000.00)	
					5	Jun 16, 2025	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user browns1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Jul 1, 2025	SYSTEM	(\$18,000.00)	
					6	Jul 1, 2025	SYSTEM	\$18,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1700 -	- Total						\$0.00	
	1710	LATEX MODIFIED CONCRETE	Material		4	Jun 2, 2025	SYSTEM	(\$57,000.00)	
		WEARING SURFACE			4	Jun 2, 2025	SYSTEM	\$57,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total					\$0.00	
		Material - Total						\$0.00	
	1710 -	- Total						\$0.00	
	1730	HALF-SOLE REPAIR	Material		7	Jul 16, 2025	SYSTEM	(\$141,480.00)	
					7	Jul 16, 2025	SYSTEM	\$141,480.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroekj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Aug 4, 2025	SYSTEM	(\$141,480.00)	



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J5P3525	1730	HALF-SOLE	Material	Туре	8	Aug 4,	SYSTEM	\$141,480.00	This adjustment offsets the original system-generated Material Payment
10. 0020	1730	REPAIR	Waterial		0	2025	OTOTEM	ψ141,400.00	Estimate Item Adjustment (0004) due to user kroekj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	1730	- Total						\$0.00	
	1790	SUPPLEMENTARY WEARING	Material		4	Jun 2, 2025	SYSTEM	(\$9,000.00)	
		SURFACE MATERIAL			4	Jun 2, 2025	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Jun 16, 2025	SYSTEM	(\$9,000.00)	
					5	Jun 16, 2025	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user browns1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Jul 1, 2025	SYSTEM	(\$33,000.00)	
					6	Jul 1, 2025	SYSTEM	\$33,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	1790	- Total						\$0.00	
	1800	LATEX MODIFIED CONCRETE	Material		4	Jun 2, 2025	SYSTEM	(\$76,570.00)	
		WEARING SURFACE			4	Jun 2, 2025	SYSTEM	\$76,570.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 10 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	1800	- Total	Material - T	otal					
	<b>1800</b> 1830	-Total  HALF-SOLE REPAIR	Material - T	otal	7	Jul 16, 2025	SYSTEM	\$0.00	
		HALF-SOLE		otal	7		SYSTEM SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kroekj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
		HALF-SOLE		otal		2025 Jul 16,		\$0.00 \$0.00 (\$170,760.00)	Estimate Item Adjustment (0006) due to user kroekj1 overridding Payment
		HALF-SOLE		otal	7	2025 Jul 16, 2025 Aug 4,	SYSTEM	\$0.00 \$0.00 (\$170,760.00) \$170,760.00	Estimate Item Adjustment (0006) due to user kroekj1 overridding Payment
		HALF-SOLE		otal - Total	7	2025 Jul 16, 2025 Aug 4, 2025 Aug 4,	SYSTEM	\$0.00 \$0.00 (\$170,760.00) \$170,760.00 (\$170,760.00)	Estimate Item Adjustment (0006) due to user kroekj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroekj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		HALF-SOLE		- Total	7	2025 Jul 16, 2025 Aug 4, 2025 Aug 4,	SYSTEM	\$0.00 \$0.00 (\$170,760.00) \$170,760.00 (\$170,760.00) \$170,760.00	Estimate Item Adjustment (0006) due to user kroekj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroekj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
	1830	HALF-SOLE	Material	- Total	7	2025 Jul 16, 2025 Aug 4, 2025 Aug 4,	SYSTEM	\$0.00 \$0.00 (\$170,760.00) \$170,760.00 (\$170,760.00) \$170,760.00	Estimate Item Adjustment (0006) due to user kroekj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroekj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
	1830	HALF-SOLE REPAIR  -Total  DECK REPAIR WITH VOID TUBE	Material	- Total	7	2025 Jul 16, 2025 Aug 4, 2025 Aug 4,	SYSTEM	\$0.00 \$0.00 (\$170,760.00) \$170,760.00 (\$170,760.00) \$170,760.00 \$0.00	Estimate Item Adjustment (0006) due to user kroekj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroekj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
	1830	HALF-SOLE REPAIR  - Total  DECK REPAIR	Material  Material - T	- Total	7 8 8 8	2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$170,760.00) \$170,760.00 (\$170,760.00) \$170,760.00 \$0.00 \$0.00	Estimate Item Adjustment (0006) due to user kroekj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroekj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
	1830	HALF-SOLE REPAIR  -Total  DECK REPAIR WITH VOID TUBE	Material  Material - T	- Total	7 8 8	2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Jul 1, 2025 Jul 1,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$170,760.00) \$170,760.00 (\$170,760.00) \$170,760.00 \$0.00 \$0.00 \$0.00 (\$16,747.50)	Estimate Item Adjustment (0006) due to user kroekj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroekj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment
	1830	HALF-SOLE REPAIR  -Total  DECK REPAIR WITH VOID TUBE	Material  Material - T	- Total	7 8 8 8	2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Jul 1, 2025 Jul 1, 2025 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$170,760.00) \$170,760.00 (\$170,760.00) \$170,760.00 \$0.00 \$0.00 \$0.00 \$170,760.00 \$170,760.00	Estimate Item Adjustment (0006) due to user kroekj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroekj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment
	1830	HALF-SOLE REPAIR  -Total  DECK REPAIR WITH VOID TUBE	Material  Material - T	- Total	7 8 8 8 6 6 7	2025 Jul 16, 2025 Aug 4, 2025 Aug 4, 2025 Jul 11, 2025 Jul 16, 2025 Jul 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$170,760.00) \$170,760.00 (\$170,760.00) \$170,760.00 \$0.00 \$0.00 \$0.00 (\$16,747.50) (\$16,747.50)	Estimate Item Adjustment (0006) due to user kroekj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroekj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kroekj1 overridding Payment Estimate Item Adjustment (0007) due to user kroekj1 overridding Payment
	1830	HALF-SOLE REPAIR  -Total  DECK REPAIR WITH VOID TUBE	Material  Material - T	- Total	7 8 8 8 6 6 7 7	Jul 1, 2025  Jul 16, 2025  Aug 4, 2025  Jul 1, 2025  Jul 16, 2025  Jul 16, 2025  Aug 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$170,760.00) \$170,760.00 (\$170,760.00) \$170,760.00 \$0.00 \$0.00 \$0.00 (\$16,747.50) \$16,747.50 \$16,747.50	Estimate Item Adjustment (0006) due to user kroekj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroekj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kroekj1 overridding Payment Estimate Item Adjustment (0007) due to user kroekj1 overridding Payment
	1830	HALF-SOLE REPAIR  -Total  DECK REPAIR WITH VOID TUBE	Material  Material - T	- Total	7 8 8 8 6 6 7 7 8	2025 Jul 16, 2025 Aug 4, 2025  Jul 1, 2025  Jul 16, 2025  Jul 16, 2025  Jul 16, 2025  Aug 4, 2025  Aug 4, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$170,760.00) \$170,760.00 (\$170,760.00) \$170,760.00 \$0.00 \$0.00 \$0.00 (\$16,747.50) \$16,747.50 (\$16,747.50)	Estimate Item Adjustment (0006) due to user kroekj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kroekj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kroekj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate.

Aug 7, 2025



# Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3525	5001 -	Total					\$0.00		
J5P3525 -	5 - Total								
Overall -	Total						\$0.00		

# MoDOT

## Contract Adjustments for Contract - 241213-D4A

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 16 of 16