

Pay Estimate Created Date: June 2, 2025

	Contract ID Prime Contractor	241213- Gersher	F03 nson Construction Co	o., Inc.	Pay Period Start Pay Period End	May 16, 2025 June 1, 2025	Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,083,916.57 \$6,085.96 \$1,090,002.53	
Approval Date								By User	
June 2, 2025			Generated and	Approved	d (and should be con	sidered Draft) a	t the Project Office Level by	clarkm3	
June 2, 2025			Reviewed and Appro	oved (and	d should be consider	ed Draft) at the	Resident Engineer Level by	vancef1	
June 4, 2025				Reviewe	d and Approved at th	e Central Office	e Controllers Office Level by	ramses1	
Original Completion	on Date C	Current Co	mpletion Date	Act	ual Completion Dat	e %	of Current Contract Amount	t Amount Complete	
November 1, 20	025	Novem	November 1, 2025				15.77%		
	Contrac	t Informat	ional Dates				Milestones		
Date Description	Original Comple	tion Date	Current Completi	on Date	No	Milestones Exi	ist for Contract		
Acceptance Date									
Awarded Date	January 8, 2025		January 8, 2025						
Letting Date	Letting Date December 13, 2024		December 13, 2024						
Notice to Proceed Date	February 10, 202	5	February 10, 2025						
Work Began Date									

Contract Total Pay For Estimate No. 5 This Estimate Previous To Date 241213-F03 \$171,944.20 \$17,137.25 \$0.00 \$171,944.20 \$17,137.25 Total Posted Items Pay **\$0.00 \$0.00 \$**0.00 Gross Item Adjustments Incentive \$0.00 \$0.00 Disincentive \$0.00 \$0.00 \$0.00 Liquidated Damage \$0.00 \$0.00 \$0.00 Other Contract Adjustments \$0.00 \$0.00 \$0.00 \$189,081.45 \$189,081.45 Contract Total Payable This Estimate: \$0.00

Items Paid This Estimate Period

No Items Paid This Period

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JSL0042	0080	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user clarkm3 overridding Payment Estimate Exception 1 on the current Payment Estimate.	328.90000	\$331.81	\$109,132.31
	0080	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-328.90000	\$331.81	(\$109,132.31)
	0130	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user clarkm3 overridding Payment Estimate Exception 4 on the current Payment Estimate.	75	\$11.00	\$825.00
	0130	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material			-75	\$11.00	(\$825.00)
	0140	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user clarkm3 overridding Payment Estimate Exception 5 on the current Payment Estimate.	63	\$5.04	\$317.52
	0140	TIE BAR (DRILLING, FURNISHING AND	Material			-63	\$5.04	(\$317.52)



Pay Estimate Created Date: June 2, 2025

Progress Estimate Number 5			241213-F03 Gershenson Construction Co., Inc.					0			
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comme	Comments		Line Item Adjustment Unit Price	Adjustment amount		
JSL0042	42 INSTALLATION) FOR FUL DEPTH PAVEMENT REPA (TYPE L JOINTS)										
Total									\$0.00		



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Co	ontract Project Informa	ation							
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work								
JSL0042	FAF-231-1 (10)	Coldmill and resurface	231	JEFFERSON	from Route 61 to the	e Meramec River								
Totals I	by Job Nu	mbers												
JSL0042		ltem Pay tem Adjustme		Item Pay	This Estimate \$0.00 \$0.00 \$0.00 \$0.00	Previous \$171,944.20 \$17,137.25 \$189,081.45	To Date \$171,944.20 \$17,137.25 \$189,081.45							
			tments		\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00									



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project JSL0042, Item 6131010, Project Item Line Number 0080, Material Set 613101096, Material 1055CMMLT2 - White Pavement Cure (non-dissipating) @, Acceptance Action Generic 1055CMMLT2 is insufficient.	Working with SL Materials to resolve.	clarkm3	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0042, Item 6131010, Project Item Line Number 0080, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with SL Materials to resolve.	clarkm3	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0042, Item 6131010, Project Item Line Number 0080, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with SL Materials to resolve.	clarkm3	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0042, Item 6131017, Project Item Line Number 0130, Material Set 613101796, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with SL Materials to resolve.	clarkm3	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0042, Item 6131018, Project Item Line Number 0140, Material Set 613101896, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with SL Materials to resolve.	clarkm3	Overridden
Estimate Exception Type: Insufficient Materials: Project JSL0042, Item 6131018, Project Item Line Number 0140, Material Set 613101896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with SL Materials to resolve.	clarkm3	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

0001 0020 2153000 SHAPING SLOPES, CLASS III 6.00 0.00 6.00 100F 0.00 \$1,439.89 0001 0030 3105003 GRAVEL (A) OR CRUSHED STONE (B) 108.00 0.00 108.00 SQP 0.00 \$17.27 0001 0040 4011211 BITUMINOUS PAVEMENT MIXTURE PG64-22 (BP-2) 412.70 0.00 412.70 TONS 0.00 \$17.27 0001 0060 4071005 ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP095CLP MIX) 3.783.60 0.00 3.783.00 GAL 0.00 \$10.00 \$5.01.50 0001 0060 4071005 TACK COAT 5.183.00 0.00 1.00 LS 0.00 \$5.01.50 0001 0080 6131010 FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL 30.80 20.00 328.90 SQP 328.90 SQP 328.90 SQP 30.00 \$1.03 0001 0080 6131012 SUBGRADE COMPACTION (6 IN. DEPTH / PAVEMENT REPAIR) 31.00 0.00 31.00 SQP 0.000	act Proj No		jory	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POS To Date (See re generated date
000 00000 0000 0000 <th< td=""><td>3- JSL0</td><td>042 0001</td><td>C</td><td>0010</td><td>2022010</td><td>REMOVAL OF IMPROVEMENTS</td><td>1.00</td><td>0.00</td><td>1.00</td><td>LS</td><td>0.00</td><td>\$15,427.24</td><td>9</td></th<>	3- JSL0	042 0001	C	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$15,427.24	9
0001 0002 000200 000200 000200 0002		0001	C	0020	2153000	SHAPING SLOPES, CLASS III	6.00	0.00	6.00	100F	0.00	\$1,439.88	9
0003 0004 0005 0015 00000 0000 <t< td=""><td></td><td>0001</td><td>C</td><td>0030</td><td>3105003</td><td>GRAVEL (A) OR CRUSHED STONE (B)</td><td>108.00</td><td>0.00</td><td>108.00</td><td>SQYD</td><td>0.00</td><td>\$17.27</td><td>9</td></t<>		0001	C	0030	3105003	GRAVEL (A) OR CRUSHED STONE (B)	108.00	0.00	108.00	SQYD	0.00	\$17.27	9
0001 0000 Normal Location Le monuter Parameter May 2010 0.000 1.000 1.000		0001	C	0040	4011211	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	412.70	0.00	412.70	TONS	0.00	\$199.22	9
0001 0000 0		0001	C	0050	4030010	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP095CLP MIX)	3,783.60	0.00	3,783.60	TONS	0.00	\$127.61	ç
0001 012001 <td></td> <td>0001</td> <td>C</td> <td>0060</td> <td>4071005</td> <td>TACK COAT</td> <td>5,183.00</td> <td>0.00</td> <td>5,183.00</td> <td>GAL</td> <td>0.00</td> <td>\$6.05</td> <td>5</td>		0001	C	0060	4071005	TACK COAT	5,183.00	0.00	5,183.00	GAL	0.00	\$6.05	5
Image: Note of the Depter Provement Repart Number Control Outside Outside <t< td=""><td></td><td>0001</td><td>C</td><td>0070</td><td>6123001</td><td>TRUCK MOUNTED ATTENUATOR (TMA)</td><td>1.00</td><td>0.00</td><td>1.00</td><td>LS</td><td>0.00</td><td>\$5,041.58</td><td>:</td></t<>		0001	C	0070	6123001	TRUCK MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	LS	0.00	\$5,041.58	:
0001 01010 0101 01010 01010 01010 01010 01010 01010 0101 01010 01		0001	C	080	6131010		308.30	20.60	328.90	SQYD	328.90	\$331.81	\$109,1
Initial Onlot <		0001	C	0090	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	31.00	0.00	31.00	SQYD	0.00	\$1.03	:
Initial Online Notice National Mathematical Survival (Union Presentational Status) Initial <			C	0100	6131013		31.00	0.00	31.00	SQYD	0.00	\$5.57	
Initial Construct Service Processing Services Processing Processing Services Processing Processin			C	0110	6131014		1,141.00	131.00	1,272.00	LF	1,272.00	\$6.68	\$8,4
India Control Edited Fight Oper Full DePTH FAVEMENT REPART. Fight Oper Control Figh			C	0120	6131015		520.00	-283.00	237.00	EA	237.00	\$7.51	\$1,7
Image: Notice Full DEPTH PAXWENT REPAIR (TYPE LONTS) 1000 2000 Could Could 30.00 Could 30.00 Could 30.00 30.00 Could 30.00 20.00<			C	0130	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	40.00	35.00	75.00	EA	75.00	\$11.00	\$8
0001 01000 010000 020000 02000 020000 <						FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)							\$3
Interprace Control NITTERPACE CONTRACTOR FURNISHED / RETAINED Los Los <thlos< th=""> <thlos< <="" td=""><td></td><td></td><td>C</td><td>0150</td><td>6161040</td><td>FLASHING ARROW PANEL</td><td>2.00</td><td>0.00</td><td>2.00</td><td>EA</td><td>2.00</td><td>\$874.21</td><td>\$1,7</td></thlos<></thlos<>			C	0150	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$874.21	\$1,7
Index 0001 0180 618100 Molicization 1.00 1.0							2.00	0.00	2.00		2.00	\$2,571.21	\$5,1
10100 1010000 1010000 1010000 1010000 1010000 1010000 1010000 1010000 1010000 1010000 1010000 1010000 1010000 1010000 1010000 10100000000 1010000000000000000000000000000000000			C	0170	6169901	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL	1.00		1.00		0.50	\$27,079.95	\$13,5
Original Sciences Construction Recently instruction, Cartine instruction, Cartine,													\$30,9
No. 6 Cost of the control of the line			C	0190	6200015		85.00	0.00	85.00		0.00	\$25.71	
0210 02002 PREFORMED THERMOPLASTIC PAVEMENT MARKING, 032.00 0.0			C	0200	6200018		69.00	0.00	69.00	LF	0.00	\$25.71	
0200 020000 020000 020000 02000 <						LEFT/RIGHT ARROW							
0001 0200 020042 NIMITE, VIELD LINE TRIANGLES I VENIENT MARKING PAINT (25-MIL, VIPE L BEADS) 10.00 0.00 25,034.00 LF 0.00 \$0.36 0001 0240 6205901A 1N. WHITE, VIELD (UNCLASS 2 PAVEMENT MARKING PAINT (25-MIL, VIPE L BEADS) 22,626.00 0.00 22,626.00 LF 0.00 \$0.36 0001 0260 6207002 PAVEMENT MARKING PAINT (25-MIL, TYPE L BEADS) 22,626.00 0.00 22,626.00 LF 0.00 \$10.285 0001 0260 6207002 PAVEMENT MARKING PAINT (25-MIL, TYPE L BEADS) 22,626.00 0.00 22,626.00 LF 0.00 \$10.285 0001 0260 6227002 PAVEMENT MARKING PAINT (25-MIL, SURFACING (3 IN, THICK OR LESS) 22,626.00 0.00 48,716.00 \$0.00 \$10.0 \$10.0 \$10.0 \$11.97 0001 0260 6224010 MODIFIED COLDMILING (DEPTH TRANSITIONS) 2,965.00 0.00 2,965.00 \$0.00 \$2,971.21 0010 0280 624100 MGS BAIDGE APPROACH TRANSITION SECTION 1.00 0.00 <td< td=""><td></td><td></td><td></td><td></td><td></td><td>(ONLY)</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<>						(ONLY)							
0001 0200 020001X TYPE LEGADS PAVEMENT MARKING PAINT (25-MIL, TYPE LEGADS) 20,037,00 22,037,00 21 0.00 \$0.30 0001 0250 6205902A 61N, WHITE CLASS 2 PAVEMENT MARKING PAINT (25-MIL, TYPE LEGADS) 22,00 0.00 22,626.00 LF 0.00 \$0.00						WHITE, YIELD LINE TRIANGLES							
Image: Note of the internal sector in the sector						TYPE L BEADS)							
12.00 12.00 <th< td=""><td></td><td></td><td></td><td></td><td></td><td>TYPE L BEADS)</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></th<>						TYPE L BEADS)							
No. 1 Sci. 1 </td <td></td>													
Note Note <th< td=""><td></td><td></td><td></td><td></td><td></td><td>SURFACING (3 IN. THICK OR LESS)</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></th<>						SURFACING (3 IN. THICK OR LESS)							
No.5 02.1400 CONTRIGUENCE ON MIGNED SOLVELING AND DIAMING 1.00 0.00 1.00 0.00 <th0< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></th0<>													
No.00 NO.00 NO.00 COLOR NO.00													
0010 0320 660314 TYPE A CRASHWORTHY END TERMINAL (MASH) 6.00 0.00 6.00 EA 0.00 \$3,496.84 0030 0330 9025020 CONDUIT, 1 IN., LOOP DETECTOR WITH TRACER WIRE 24.00 0.00 24.00 LF 0.00 \$88.45 0030 0340 9028500 CABLE, LOOP DETECTOR, IN DUCT 320.00 0.00 320.00 LF 0.00 \$9.98 0030 0350 9028510 CABLE, LOOP DETECTOR, ILAD-IN 60.00 0.00 66.00 LF 0.00 \$2.67 0040 0360 9031280 2.5 IN. PSST POST - 12 GA. 150.00 0.00 150.00 LF 0.00 \$3.02.91 0040 0370 9031280 2.5 IN. PSST POST - 12 GA. 150.00 0.00 150.00 LF 0.00 \$3.08.54 0040 0370 90312814 DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA. 13.00 0.00 140.00 \$3.08.54 0040 0380 90350044 SH-FLAT SHEET 167.00 0.00						MGS BRIDGE APPROACH TRANSITION SECTION							
0030 0330 9025020 CONDUIT, IN, LOOP DETECTOR WITH TRACER WIRE 24.00 0.00 24.00 LF 0.00 \$\$88.45 0030 0340 9025020 CONDUIT, IN, LOOP DETECTOR WITH TRACER WIRE 24.00 0.00 24.00 LF 0.00 \$\$88.45 0030 0340 9028500 CABLE, LOOP DETECTOR, IN DUCT 320.00 0.00 320.00 LF 0.00 \$\$9.98 0030 0350 9028510 CABLE, LOOP DETECTOR, LEAD-IN 60.00 0.00 60.00 LF 0.00 \$\$2.67 0040 0360 9031280 2.5 IN. PSST POST - 12 GA. 150.00 0.00 115.00 LF 0.00 \$\$32.91 0040 0360 9031280 DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA. 13.00 0.00 113.00 EA 0.00 \$\$30.8.54 0040 0370 9031281 DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA. 167.00 0.00 167.00 \$\$0.57 0.00 \$\$28.80 0040 0380 90350044 <td< td=""><td></td><td>0010</td><td>0</td><td>1320</td><td>6063014</td><td></td><td>6.00</td><td>0.00</td><td>6.00</td><td>F۵</td><td>0.00</td><td>\$3 496 84</td><td></td></td<>		0010	0	1320	6063014		6.00	0.00	6.00	F۵	0.00	\$3 496 84	
0030 0340 9028500 CABLE, LOOP DETECTOR, IN DUCT 320.00 0.00 320.00 LF 0.00 \$9.98 0030 0350 9028510 CABLE, LOOP DETECTOR, LEAD-IN 60.00 0.00 60.00 LF 0.00 \$2.67 0040 0360 9031280 2.5 IN. PSST POST -12 GA. 150.00 0.00 150.00 LF 0.00 \$32.91 0040 0370 9031280 DIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA. 13.00 0.00 13.00 EA 0.00 \$308.54 0040 0380 9035004A SH-FLAT SHEET 167.00 0.00 167.00 SQFT 0.00 \$22.67 0050 0390 9109903 MISC.MODOT ITS ASSETS RELOCATION 200.00 0.00 LF 0.00 \$27.77		0030											
0030 0350 9028510 CABLE, LOOP DETECTOR, LEAD-IN 60.00 0.00 60.00 LF 0.00 \$2.67 0040 0360 9031280 2.5 IN. PSST POST - 12 GA. 150.00 0.00 150.00 LF 0.00 \$32.91 0040 0370 9031281 DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA. 13.00 0.00 13.00 EA 0.00 \$308.54 0040 0380 9035004 SH-FLAT SHEET 167.00 0.00 167.00 SQFT 0.00 \$28.80 0050 0390 9109903 MISC.MODOT ITS ASSETS RELOCATION 200.00 0.00 LF 0.00 \$27.77		0030											
0040 0360 9031280 2.5 IN. PSST POST - 12 GA. 150.00 0.00 150.00 LF 0.00 \$32.91 0040 0370 9031281A DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA. 13.00 0.00 13.00 EA 0.00 \$308.54 0040 0380 9035004A SH-FLAT SHEET 167.00 0.00 167.00 SQFT 0.00 \$28.80 0050 0390 9109903 MISC.MODOT ITS ASSETS RELOCATION 200.00 0.00 200.00 LF 0.00 \$27.77													
0040 0370 9031281A DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA. 13.00 0.00 13.00 EA 0.00 \$308.54 0040 0380 9035004A SH-FLAT SHEET 167.00 0.00 167.00 SQFT 0.00 \$28.80 0050 0390 9109903 MISC.MODOT ITS ASSETS RELOCATION 200.00 0.00 200.00 LF 0.00 \$27.77		0040											
0040 0380 9035004A SH-FLAT SHEET 167.00 0.00 167.00 SQFT 0.00 \$28.80 0050 0390 9109903 MISC.MODOT ITS ASSETS RELOCATION 200.00 0.00 200.00 LF 0.00 \$27.77		0040											
0050 0390 9109903 MISC.MODOT ITS ASSETS RELOCATION 200.00 0.00 200.00 LF 0.00 \$27.77		0040										,	
		0050											
	Proje	ect JSI 004										.=	



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable). No Data Available



Line Item Adjustments by Estimate

Contract ID: 241213-F03

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JSL0042	0080	FURN & PLACE CONC MATL	Material		2	Apr 16, 2025	SYSTEM	(\$109,132.31)	
		FOR FULL DEPTH			2	Apr 16, 2025	SYSTEM	\$109,132.31	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user clarkm3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	May 1, 2025	SYSTEM	(\$109,132.31)	
					3	May 2, 2025	SYSTEM	\$109,132.31	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user clarkm3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 16, 2025	SYSTEM	(\$109,132.31)	
					4	May 16, 2025	SYSTEM	\$109,132.31	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user clarkm3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jun 2, 2025	SYSTEM	(\$109,132.31)	
					5	Jun 2, 2025	SYSTEM	\$109,132.31	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user clarkm3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	2	Apr 16, 2025	SYSTEM	(\$6,835.29)	
					3	May 1, 2025	SYSTEM	\$6,835.29	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',331.81000 - 331.81000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0080	- Total						\$0.00	
	0110	FULL DEPTH PAVEMENT REPAIR SAW		Overrun	2	Apr 16, 2025	SYSTEM	(\$875.08)	
		CUT (FOR			3	May 1, 2025	SYSTEM	\$875.08	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',6.68000 - 6.68000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0110	- Total						\$0.00	
	0120	DOWEL BAR (DRILLING, FURNISHING	Material		2	Apr 16, 2025	SYSTEM	(\$1,779.87)	
		AND INST			2	Apr 16, 2025	SYSTEM	\$1,779.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user clarkm3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0120 0130	- Total DOWEL BAR	Material		2	Apr 16,	SYSTEM	\$0.00 (\$825.00)	
		(FURNISH AND INSTALL WITH BASK				2025	SYSTEM	\$825.00	This adjustment of the table of the state of the table of ta
					2	Apr 16, 2025	OTOTEM	<i>Q</i> QQQQQQQQQQQQQ	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user clarkm3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					2 3		SYSTEM	(\$825.00)	
						2025 May 1,			Estimate Item Adjustment (0006) due to user clarkm3 overridding Payment
					3	2025 May 1, 2025 May 2,	SYSTEM	(\$825.00)	Estimate Item Adjustment (0006) due to user clarkm3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					3	2025 May 1, 2025 May 2, 2025 May 16,	SYSTEM SYSTEM	(\$825.00) \$825.00	Estimate Item Adjustment (0006) due to user clarkm3 overridding Payment Estimate Exception 6 on the current Payment Estimate.



Line Item Adjustments by Estimate

Jun 5, 2025

Contract ID: 241213-F03

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
SL0042	0130	DOWEL BAR (FURNISH AND INSTALL WITH BASK	Material		5	Jun 2, 2025	SYSTEM	\$825.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user clarkm3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		DAGK		- Total				\$0.00	
			Material - Tot	tal	1			\$0.00	
			Overrun	Overrun	2	Apr 16, 2025	SYSTEM	(\$385.00)	
					3	May 1, 2025	SYSTEM	\$385.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',11.00000 - 11.00000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - To	tal				\$0.00	
	0130 -	Total						\$0.00	
	0140	TIE BAR (DRILL, FURN & INSTAL)	Material		2	Apr 16, 2025	SYSTEM	(\$317.52)	
		(TYPE L			2	Apr 16, 2025	SYSTEM	\$317.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user clarkm3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	May 1, 2025	SYSTEM	(\$317.52)	
					3	May 2, 2025	SYSTEM	\$317.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user clarkm3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	May 16, 2025	SYSTEM	(\$317.52)	
					4	May 16, 2025	SYSTEM	\$317.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user clarkm3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Jun 2, 2025	SYSTEM	(\$317.52)	
					5	Jun 2, 2025	SYSTEM	\$317.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user clarkm3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
			Overrun	Overrun	2	Apr 16, 2025	SYSTEM	(\$115.92)	
					3	May 1, 2025	SYSTEM	\$115.92	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.04000 - 5.04000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0140 -	Total						\$0.00	
	0300	MGS GUARDRAIL	Construction Stockpile STMI		4	May 16, 2025	SYSTEM	\$6,037.25	Payment Estimate Item Adjustment generated Stockpile Transaction
			51100	- Total				\$6,037.25	
			Construction	Stockpile S	TMI - Total			\$6,037.25	
	0300 -	Total						\$6,037.25	
	0320	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile STMI		4	May 16, 2025	SYSTEM	\$11,100.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)		- Total				\$11,100.00	
			Construction	Stockpile S	TMI - Total			\$11,100.00	
	0320 -	Total						\$11,100.00	
SL0042 -	Total							\$17,137.25	
verall - 1	Total							\$17,137.25	



There are no contract adjustments to display for this contract.