\$289,833.80



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 2, 2025

-	•									
Progress Estimate Number 7	Contract ID ber Prime Contractor		H03 arger Concreters, Inc.	Pay Period Start Pay Period End	August 16, 2 September		Original Contract Amount Net Change Order Amount Current Contract Amount	\$2,720,535.7 \$0.0 \$2,720,535.7		
Approval Date								By User		
September 2, 2025		Generated and Approved (and should be considered Draft) at the Project Office Le								
September 2, 2025			Reviewed and Appro	ved (and should be c	onsidered Dra	aft) at the	e Resident Engineer Level by	leez1		
September 4, 2025			F	Reviewed and Approv	ed at the Cer	tral Offic	ce Controllers Office Level by	ramses1		
Original Completi	on Date	Current C	completion Date Actual Completion Date			ate % of Current Contract Amount Complete				
November 1, 2	025	Novem	ber 1, 2025				45.69%			
	Co	ntract Informa	tional Dates				Milestones			
Date Description	Original Co	mpletion Date	Current Completion	Date	No Miles	tones Ex	tist for Contract			
Acceptance Date										
Awarded Date	February 5,	2025	February 5, 2025							
Letting Date	January 17,	2025	January 17, 2025							
Notice to Proceed Date	March 10, 20	025	March 10, 2025							
Work Began Date										

Contract Total Pa	ay For Estimate No. 7				
		This Estimate	Previous	To Date	
250117-H03					
	Total Posted Items Pay	\$289,833.80	\$953,177.08	\$1,243,010.88	
	Gross Item Adjustments	\$19,358.35	(\$2,413.62)	\$16,944.73	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$950,763.46	\$1,259,955.61	
Contract Total Pa	avable This Estimate:	\$309.192.15			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9P3842	0090	2079909	MISC.Modified Linear Grading Class 2	0.300	\$990.00		
	0110	3109907	MISC.2 Inch Clean Rock	CUYD	\$52.000	177	\$9,204.00
	0120	4010150	TYPE A2 SHOULDER	SQYD	\$50.000	240.670	\$12,033.50
	0130	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	TONS	\$116.110	30	\$3,483.30
	0170	5021109	CONCRETE PAVEMENT (9 IN. NON-REINF)	SQYD	\$95.000	1,982.600	\$188,347.00
	0200	6085008	PAVED APPROACH, 8 IN.	SQYD	\$87.000	518.900	\$45,144.30
	0230	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	8.900	\$409.40		
	0240	6096042	PLACING TYPE 2 ROCK DITCH LINER	CUYD	\$41.000	8.900	\$364.90
	0250	6099903	MISC.Modified Concrete Curb and Gutter, Type A	LF	\$43.000	423.800	\$18,223.40
	0470	6240104A	SEPARATION GEOTEXTILE	SQYD	\$5.000	762.800	\$3,814.00
	0480	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$15,000.000	0.300	\$4,500.00
	0550	8025006	MULCHING	ACRE	\$1,250.000	0.800	\$1,000.00
	0560	8051000A	SEEDING - COOL SEASON GRASSES	ACRE	\$2,900.000	0.800	\$2,320.00
Project J9P384	\$289,833.80						

Contract Adjustments This Estimate

Overall - Total

No Contract Adjustments Exist on Contract

Line Item A	<u>.ine Item Adjustments This Estimate</u>												
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount					
J9P3842	0110	MISC.	Material			-177	\$52.00	(\$9,204.00)					
	0110	MISC.	Material		This adjustment offsets the original system-	177	\$52.00	\$9,204.00					

Revision 9/2/2025 Page 1 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 2, 2025

Pro Estimat	gress e Num 7		250117-H03 Fronabarger Con	creters, Inc.	Pay Period End September 1, 2025 Ne	iginal Contract t Change Order rrent Contract	Amount	\$2,720,535.7 \$0.0 \$2,720,535.7
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
9P3842					generated Material Payment Estimate Item Adjustment (0001) due to user brophm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
	0120	TYPE A2 SHOULDER	Material			-400.31000	\$50.00	(\$20,015.50
	0120	TYPE A2 SHOULDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user brophm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	400.31000	\$50.00	\$20,015.50
	0120	TYPE A2 SHOULDER	ULDER Other Item Adjustment Fuel Price System gave money for fuel adjustment. Contractor did not check fuel adjustment for concrete on contract.				(\$66.18)	
	0120	TYPE A2 SHOULDER	A		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	142.89000	\$0.27	\$39.29
	0120	TYPE A2 SHOULDER	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	97.78000	\$0.27	\$26.89
	0130	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	Asphalt Cement Price Adjustment	Refer to the document called, "250117-H03 J9P3842 Estimate 0007 AC Index Price Adjustment Hot Mix Asphalt Ton" on eProjects for further information.			\$24.60
	0130	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	30	\$0.87	\$26.10
	0170	CONCRETE PAVEMENT (9 IN. NON-REINF)	9 Material			-3,970.30000	\$95.00	(\$377,178.50
	0170	CONCRETE PAVEMENT (9 IN. NON-REINF)	9 Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	3,970.30000	\$95.00	\$377,178.50
	0200	PAVED APPROACH, 8 IN.	Material			-578.90000	\$87.00	(\$50,364.30
	0200	PAVED APPROACH, 8 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user brophm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	578.90000	\$87.00	\$50,364.30
	0230	FURNISHING TYPE 2 ROC DITCH LINER	K Material			-10.90000	\$46.00	(\$501.40
	0230	FURNISHING TYPE 2 ROC DITCH LINER	K Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user brophm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	10.90000	\$46.00	\$501.40
	0250	MISC.	Material			-504.40000	\$43.00	(\$21,689.20
	0250	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user brophm1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	504.40000	\$43.00	\$21,689.20
	0550	MULCHING	Material			-0.80000	\$1,250.00	(\$1,000.00
	0550	MULCHING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	0.80000	\$1,250.00	\$1,000.00
	0560	SEEDING - COOL SEASON GRASSES	Material Material			-0.80000	\$2,900.00	(\$2,320.00)
	0560	SEEDING - COOL SEASON GRASSES	Material Material		This adjustment offsets the original system- generated Material Payment Estimate Item	0.80000	\$2,900.00	\$2,320.00

Revision 9/2/2025 Page 2 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 2, 2025

Progress Estimate Nun 7		250117-H03 Fronabarger Con	creters, Inc.	Pay Period End September 1, 2025	Original Contract A Net Change Order A Current Contract A	Amount	\$2,720,535.77 \$0.00 \$2,720,535.77
Project Line Number No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
9P3842				Adjustment (0011) due to user brophm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.			
0700	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	Other Item Adjustment	Stockpiled Materials Initial Payment	Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further information. MoDOT have receive the certifications.			\$3,822.00
0710	2 IN. PSST POST - 12 GA.	Other Item Adjustment	Stockpiled Materials Initial Payment	Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further information. MoDOT have receive the certifications.			\$3,095.10
0720	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	Other Item Adjustment	Stockpiled Materials Initial Payment	Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further information. MoDOT have receive the certifications.			\$1,737.40
0730	2.25 IN. PSST POST INSER (6 FT.) - 12 GA.	Other Item Adjustment	Stockpiled Materials Initial Payment	Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further information. MoDOT have receive the certifications.			\$502.74
0740	2.5 IN. PSST POST - 12 GA	Other Item Adjustment	Stockpiled Materials Initial Payment	Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further information. MoDOT have receive the certifications.			\$2,362.49
0750	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	Other Item Adjustment	Stockpiled Materials Initial Payment	Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further information. MoDOT have receive the certifications.			\$1,731.52
0760	SH-FLAT SHEET	Other Item Adjustment	Stockpiled Materials Initial Payment	Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further information. MoDOT have receive the certifications.			\$2,754.00
0770	ST-STRUCTURAL	Other Item Adjustment	Stockpiled Materials Initial Payment	Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further information. MoDOT have receive the certifications.			\$2,440.00
0780	SHF-FLAT SHEET FLUORESCENT	Other Item Adjustment	Stockpiled Materials Initial Payment	Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further information. MoDOT have receive the certifications.			\$862.40
otal							\$19,358.35

Revision 9/2/2025 Page 3 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Co	ontract Project Informa	tion					
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work						
J9P3842	FAF 72-2(25)	Roundabout	72	BOLLINGER	at the intersection of Ro	t the intersection of Route 72 and Route 51						
Totals b	Totals by Job Numbers											
J9P3842					This Estimate	Previous	To Date					
		ed Item Pay s Item Adjustn			\$289,833.80 \$19,358.35	\$953,177.08 (\$2,413.62)	\$1,243,010.88 \$16,944.73					
			Gros	s Item Pay	\$309,192.15	\$950,763.46	\$1,259,955.61					
Incentive \$0.00 \$0.00							\$0.00					
	Disincentive \$0.00 \$0.00 \$0.00											
Liquidated Damages					\$0.00 \$0.00							
	Other Contract Adjustments \$0.00 \$0.00 \$											

Revision 5/29/2025 Page 4 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 3109907, Project Item Line Number 0110, Material Set 3109907, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 3099XX is insufficient.	Free form test has not been inputted by Inspector.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 4010150, Project Item Line Number 0120, Material Set 401015096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	QC has not performed or inputted testing.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 4010150, Project Item Line Number 0120, Material Set 401015096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	QC has not performed or inputted testing.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 5021109, Project Item Line Number 0170, Material Set 502110996, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	QC has not performed or inputted testing.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 5021109, Project Item Line Number 0170, Material Set 502110996, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Materials have PALs but have not been assigned to line-item number. Inspector is working with Materials.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 5021109, Project Item Line Number 0170, Material Set 502110996, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 50/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Materials have PALs but have not been assigned to line-item number. Inspector is working with Materials.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 6085008, Project Item Line Number 0200, Material Set 608500896, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Air, slump, strength testing have not been inputted. Waiting on 28-day breaks to inputted testing requirements.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 6085008, Project Item Line Number 0200, Material Set 608500896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	QC testing requirements have not been inputted.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 6085008, Project Item Line Number 0200, Material Set 608500896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	QC testing requirements have not been inputted.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 6085008, Project Item Line Number 0200, Material Set 608500896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 50/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Materials have PALs but have not been assigned to line-item number. Inspector is working with Materials.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 6085008, Project Item Line Number 0200, Material Set 608500896, Material 1005FACCNSCB - Natural Sand for Conc Class B, Acceptance Action Generic 1005FACCNSCB is insufficient.	QA sand QC testing requirements have not been inputted.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 6085008, Project Item Line Number 0200, Material Set 608500896, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	Inspector needs to investigate this exception.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 6096020, Project Item Line Number 0230, Material Set 609602096, Material 0609PDDL - Paved Drainage Material for Ditch Liner, Acceptance Action Generic 0609PDDL is insufficient.	Inspector needs to input test into AASHATOware.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 6099903, Project Item Line Number 0250, Material Set 6099903, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Air, slump and strength requirements have not been inputted. Waiting on 28-day breaks to input information.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 8025006, Project Item Line Number 0550, Material Set 8025006, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Inspector needs certifications from Contractor.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 8051000A, Project Item Line Number 0560, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient.	Inspector needs certification from Contractor.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 8051000A, Project Item Line Number 0560, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	Inspector needs certification from Contractor.	brophm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3842, Item 8051000A, Project Item Line Number 0560, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	Inspector needs certification from Contractor.	brophm1	Overridden
Estimate Exception Type: Item Overrun: Contract 250117-H03, Contract Project J9P3842, Project Item Line Number 0570, Contract Line Item Number 0570, Item 8061005, Minor Item.	Change Order 0001 needs to be wrote.	brophm1	Acknowledged

Revision 5/29/2025 Page 5 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract	Project No.	Category	Line No.	Item Code	d on Report Generated date and can differ from the post Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTED To Date (See report generated date)
250447	1000010	0001	0040	4044000	TEMPORARY SURFACING	000.00	0.00	000.00	0111/10	Qty	455.00	40.004.00
250117- H03	J9P3842	0001	0010	1041000	TEMPORARY SURFACING	662.00	0.00	662.00	CUYD	164.80	\$55.00	\$9,064.00
		0001	0020	2022010	SIGNET DBE REPORTING REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00 0.57	\$1,000.00 \$85,000.00	\$1,000.00 \$48,450.00
		0001	0030	2022010	CLASS A EXCAVATION	3,252.00	0.00	3,252.00	CUYD	1,988.00	\$23.00	\$45,724.00
		0001	0050	2035500	EMBANKMENT IN PLACE	1,551.00	0.00	1,551.00	CUYD	983.00	\$20.00	\$19,660.00
		0001	0060	2036000	COMPACTING EMBANKMENT	2,828.00	0.00	2,828.00	CUYD	1,602.00	\$7.00	\$11,214.00
		0001	0070	2037075	COMPACTING EMBANAMENT COMPACTING IN CUT	21.30	0.00	21.30	STA	10.36	\$1,400.00	\$14,504.0
		0001	0080	2063000	CLASS 3 EXCAVATION	75.00	0.00	75.00	CUYD	45.00	\$40.00	\$1,800.0
		0001	0090	2079909	MISC.Modified Linear Grading Class 2	24.10	0.00	24.10	STA	18.70	\$3,300.00	\$61,710.0
		0001	0100	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	11,162.00	0.00	11,162.00	SQYD	5,800.20	\$9.00	\$52,201.8
		0001	0110	3109907	MISC.2 Inch Clean Rock	177.00	0.00	177.00	CUYD	177.00	\$52.00	\$9,204.0
		0001	0120	4010150	TYPE A2 SHOULDER	839.40	0.00	839.40	SQYD	400.31	\$50.00	\$20,015.5
		0001	0130	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	1,530.60	0.00	1,530.60	TONS	631.60	\$116.11	\$73,335.0
		0001	0140	4019905	MISC.Optional Pavement	1,522.60	0.00	1,522.60	SQYD	1,356.80	\$58.58	\$79,481.3
		0001	0150	4029905	MISC.Optional Base	929.30	0.00	929.30	SQYD	929.30	\$27.91	\$25,936.7
		0001	0160	4071005	TACK COAT	412.00	0.00	412.00	GAL	412.00	\$3.99	\$1,643.8
		0001	0170	5021109	CONCRETE PAVEMENT (9 IN. NON-REINF)	8,945.80	0.00	8,945.80	SQYD	3,970.30	\$95.00	\$377,178.5
		0001	0180	5029905	MISC.Tinted 9 inch PCCP	595.20	0.00	595.20	SQYD	549.80	\$126.00	\$69,274.8
		0001	0190	6085007	PAVED APPROACH, 7 IN.	380.00	0.00	380.00	SQYD	0.00	\$82.00	\$09,274.6
		0001	0200	6085007	PAVED APPROACH, 8 IN.		0.00	1,796.00	SQYD	578.90	\$87.00	
		0001	0200	6089905	MISC.Tinted 6 inch Concrete Median	1,796.00 829.50	0.00	829.50	SQYD	0.00		\$50,364.3
		0001	0210	609905	CONCRETE GUTTER TYPE A	93.00	0.00	93.00	LF	0.00	\$120.00 \$55.00	\$0.0
		0001										\$0.0
		0001	0230	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	41.00	0.00	41.00	CUYD	10.90	\$46.00	\$501.4
		0001	0240	6096042 6099903	PLACING TYPE 2 ROCK DITCH LINER	41.00	0.00	41.00	CUYD	10.90	\$41.00	\$446.9
		0001			MISC.Modified Concrete Curb and Gutter, Type A	1,744.00	0.00	1,744.00		504.40	\$43.00	\$21,689.2
		0001	0260	6099903	MISC.Tinted 6 inch Integral Curb, Type A	503.00	0.00	503.00	LF	503.00	\$15.00	\$7,545.0
		0001	0270	6161005 6161098A	CONSTRUCTION SIGNS CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	1,081.00	0.00	1,081.00	SQFT	779.00 4.00	\$9.00 \$3,200.00	\$7,011.0 \$12,800.0
		0001	0290	6169901	MISC.Temporary Traffic Control	1.00	0.00	1.00	LS	0.75	\$7,625.00	\$5,718.7
		0001	0300	6169902	MISC.Portable Traffic Signal System	1.00	0.00	1.00	EA	1.00	\$25,500.00	\$25,500.0
		0001	0310	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,300.00	0.00	1,300.00	LF	1,300.00	\$36.44	\$47,372.0
		0001	0320	6174000A	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION, CONTRACTOR FURNISHED / RETAINED	2.00	0.00	2.00	EA	2.00	\$1,194.00	\$2,388.0
		0001	0330	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$205,000.00	\$102,500.0
		0001	0340	6200006	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN YELLOW	4,918.00	0.00	4,918.00	LF	0.00	\$5.00	\$0.0
		0001	0350	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	4,782.00 77.00	0.00	4,782.00 77.00	LF LF	0.00	\$6.00 \$25.00	\$0.0 \$0.0
			0000	0200010	YELLOW	77.00	0.00	77.00		0.00	Ψ20.00	φ0.0
		0001	0370	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	200.00	0.00	200.00	LF	0.00	\$3.00	\$0.0
		0001	0380	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	1,000.00	0.00	1,000.00	LF	0.00	\$3.00	\$0.0
		0001	0390 0400	6205309 6206000C	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	36.00 375.00	0.00	36.00 375.00	LF LF	60.00 0.00	\$10.00 \$5.00	\$600.0 \$0.0
		0001	0410	6206001C	PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	12,172.00	0.00	12,172.00	LF	3,374.00	\$0.80	\$2,699.2
		0001	0420	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	36.00	0.00	36.00	LF	0.00	\$10.00	\$0.0
		0001	0430	6207001	PAVEMENT MARKING REMOVAL	1,236.00	0.00	1,236.00	LF	476.00	\$4.00	\$1,904.0
		0001	0440	6209902	MISC.Preformed Thermoplastic Marking, 24 Inch, Yield Line	32.00	0.00	32.00	EA	0.00	\$75.00	\$0.0
		0001	0450	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	775.00	0.00	775.00	SQYD	0.00	\$8.50	\$0.0
		0001	0460	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	444.00	0.00	444.00	SQYD	334.00	\$14.83	\$4,953.2
		0001	0470	6240104A	SEPARATION GEOTEXTILE	872.00	0.00	872.00	SQYD	774.80	\$5.00	\$3,874.0
		0001	0480	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.75	\$15,000.00	\$11,250.0
	0001 0490 7250318A 18 IN. PIPE GROUP B			177.00	0.00	177.00	LF	147.00	\$85.00	\$12,495.0		
	0001 0500 7250321A 21 IN. PIPE GROUP B				71.00	0.00	71.00	LF	0.00	\$90.00	\$0.0	
		0001	0510	7261018	18 IN. PIPE GROUP A	100.00	0.00	100.00	LF	0.00	\$85.00	\$0.0
		0001	0520	7261024	24 IN. PIPE GROUP A	62.00	0.00	62.00	LF	0.00	\$95.00	\$0.0

Revision 5/29/2025 Page 6 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ontract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
50117- 03	J9P3842	0001	0530	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$650.00	\$1,300.00
		0001	0540	7320624A	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	0.00	\$750.00	\$0.00
		0001	0550	8025006	MULCHING	1.10	0.00	1.10	ACRE	0.80	\$1,250.00	\$1,000.00
		0001	0560	8051000A	SEEDING - COOL SEASON GRASSES	1.10	0.00	1.10	ACRE	0.80	\$2,900.00	\$2,320.00
		0001	0570	8061005	ROCK DITCH CHECK	180.00	0.00	180.00	LF	433.00	\$15.00	\$6,495.00
		0001	0580	8061017	TEMPORARY SEEDING	0.70	0.00	0.70	ACRE	0.30	\$2,150.00	\$645.00
		0001	0590	8061019	SILT FENCE	3,540.00	0.00	3,540.00	LF	195.00	\$2.90	\$565.50
		0020	0600	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	8.00	0.00	8.00	EA	0.00	\$2,990.00	\$0.00
		0020	0610	9011106	BRACKET ARM, 6 FT. OR 1.8 M	8.00	0.00	8.00	EA	0.00	\$562.00	\$0.00
		0020	0620	9011312	LUMINAIRE, LED-B	8.00	0.00	8.00	EA	0.00	\$359.00	\$0.00
		0020	0630	9014003	CONDUIT, 3 IN. RIGID, PUSHED	186.00	0.00	186.00	LF	0.00	\$40.00	\$0.00
		0020	0640	9015010	TRENCHING TYPE I	1,363.00	0.00	1,363.00	LF	0.00	\$8.61	\$0.00
		0020	0650	9016110	PULL BOX, PREFORMED CLASS 1	6.00	0.00	6.00	EA	0.00	\$1,232.00	\$0.00
		0020	0660	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	860.00	0.00	860.00	LF	0.00	\$1.00	\$0.00
		0020	0670	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	1,940.00	0.00	1,940.00	LF	0.00	\$3.90	\$0.00
		0020	0680	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	8.00	0.00	8.00	EA	0.00	\$1,853.00	\$0.00
		0040	0690	9031210	STRUCTURAL STEEL POSTS	260.00	0.00	260.00	LB	0.00	\$8.00	\$0.00
		0040	0700	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	14.00	0.00	14.00	EA	0.00	\$350.00	\$0.00
		0040	0710	9031270A	2 IN. PSST POST - 12 GA.	342.00	0.00	342.00	LF	0.00	\$26.00	\$0.00
		0040	0720	9031271A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	34.00	0.00	34.00	EA	0.00	\$175.00	\$0.00
		0040	0730	9031272A	2.25 IN. PSST POST INSERT (6 FT.) - 12 GA.	9.00	0.00	9.00	EA	0.00	\$200.00	\$0.00
		0040	0740	9031280	2.5 IN. PSST POST - 12 GA.	221.00	0.00	221.00	LF	0.00	\$28.00	\$0.00
		0040	0750	9031281A	DRIVEN POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	16.00	0.00	16.00	EA	0.00	\$225.00	\$0.0
		0040	0760	9035004A	SH-FLAT SHEET	340.00	0.00	340.00	SQFT	0.00	\$26.00	\$0.0
		0040	0770	9035011A	ST-STRUCTURAL	160.00	0.00	160.00	SQFT	0.00	\$36.00	\$0.0
		0040	0780	9035069A	SHF-FLAT SHEET FLUORESCENT	88.00	0.00	88.00	SQFT	0.00	\$32.00	\$0.00
	Project J	9P3842 - To	tal Value	Posted to D	ate as of Report Generated Date							\$1,255,335.13
)117-H	03 Overal	I - Total Va	lue Poste	ed to Date as	of Report Generated Date							\$1,255,335.13

Revision 5/29/2025 Page 7 of 15



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9P3842

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0090	2079909	MISC. GRADING	8/25/25	8/26/25	1	0.30	STA	MO 51 North Leg Dollar General	321+11.21	LT	321+11.21	LT	Field Measured and Verified brophm1
0110	3109907	MISC. GRAVEL OR CR. STONE	8/21/25	8/22/25	1	177.00	CUYD	Roundabout	327+00.00	CL	327+90.00	CL	(PI/4)(90)(90)(9/12)/27 = 177 CY brophm1
120	4010150	TYPE A2 SHOULDER	8/20/25	8/21/25	1	142.89	SQYD	RTE 72 BL (RANW_BL_72)	0+00.00	LT	3+21.51	LT	(321.5')*(4')/9 = 142.89 SY brophm1
			8/21/25	8/22/25	2	97.78	SQYD	RTE 51 BL (RANE_BL_51)	0+54.04	LT	2+74.05	LT	(359.2')*(4')/9 = 97.78 SY brophm1
130	4011209	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	8/26/25	8/28/25	1	30.00	TONS	MO 51 Stage 2 Bypass	329+75	CL	329+75	CL	$[(20')^*(25')^*(9.55/12')/27]^*(2.034 \text{ ton/CY}) = 30 \text{ ton brophm1}$
170	5021109	CONCRETE PAVEMENT (9 IN. NON-REINF)	8/20/25	8/21/25	1	972.40	SQYD	MO 72 West Leg	417+05.46	LT	422+13.34	LT	
			8/22/25	8/25/25	1	1,010.20	SQYD	MO 51 North Leg	321+00.00	LT	326+62.68	LT	(562.68')*(16.16')/9 = 1010.2 SY brophm1
200	6085008	PAVED APPROACH, 8 IN.	8/22/25	8/25/25	1	60.00	SQYD	MO 51 North Leg Bank of Missouri Driveway	324+80.90	LT	324+80.90	LT	(23')*(47')/9 = 120 SY/2 = 60 SY Half of the drive was poured. brophm1
			8/25/25	8/26/25	2	191.10	SQYD	MO 51 North Leg Dollar General	321+11.21	LT	321+11.21	LT	(36')*(47'.77)/9 = 191.1 SY brophm1
			8/28/25	8/29/25	1	158.90	SQYD	MO 51 North Leg	325+70.58	RT	325+70.58	RT	(21')*(68.1')/9 = 158.9 SY brophm1
				8/29/25	2	108.90	SQYD	MO 51 North Leg	324+07.01	LT	324+07.01	LT	(14')*(70')/9 = 158.9 SY brophm1
230	6096020	FURN. TYPE 2 ROCK DITCH LINER	8/21/25	8/22/25	1	5.60	CUYD	MO 51 North Leg (RANW_BL_51)	4+38.50	RT	4+38.50	RT	(10')*(10')(1.5')/27 = 5.6 CY brophm1
			8/26/25	8/28/25	1	3.30	CUYD	West Leg Route 72 (RANW_BL_72)	3+16.51	LT	3+16.51	LT	(10')*(1.5')*(5.94')/27 = 3.3 CY
240	6096042	PLACING TYPE 2 ROCK DITCH LINER	8/21/25	8/22/25	1	5.60	CUYD	MO 51 North Leg (RANW_BL_51)	4+38.50	RT	4+38.50	RT	(10')*(10')(1.5')/27 = 5.6 CY brophm1
			8/26/25	8/28/25	1	3.30	CUYD	West Leg Route 72 (RANW_BL_72)	3+16.51	LT	3+16.51	LT	(10')*(1.5')*(5.94')/27 = 3.3 CY
250	6099903	MISC. PAVED DRAINAGE	8/21/25	8/22/25	1	245.10	LF	RTE 72 BL (RANW_BL_72)	3+21.51	LT	5+66.59	LT	Field verified and measured. brophm1
				8/22/25	2	153.00	LF	RTE 51 BL (RANE_BL_51)	4+19.60	LT	5+98.32	LT	4" Field verified and measured. brophm1
				8/22/25	3	25.70	LF	RTE 51 BL (RANE_BL_51)	4+19.60	LT	5+98.32	LT	2" Field verified and measured. brophm1
470	6240104A	SEPARATION GEOTEXTILE	8/21/25	8/22/25	1	731.00	SQYD	Roundabout	327+00.00	CL	327+90.00	cl	(PI/4)(91.5)(91.5)/9 = 731 SY brophm1
				8/22/25	2	18.80	SQYD	MO 51 North Leg (RANW_BL_51)	4+38.50	RT	4+38.50	RT	(14')*(12')/9 = 18.8 SY brophm1
			8/26/25	8/28/25	1	13.00	SQYD	West Leg Route 72 (RANW_BL_72)	3+16.51	LT	3+16.51	LT	(10' + 1.5' + 1.5')*(6' + 1.5' + 1.5')/9 = 13 SY brophm
480	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	8/21/25	8/22/25	1	0.30	LS	MO 72	417+05.46	CL	431+00.00	CL	Field Verified brophm1
550	8025006	MULCHING	8/26/25	8/28/25	1	0.30	ACRE	MO 51 North Leg	321+00.00	RT	325+50.00	RT	$[(450')^*(13.5') + 0.5^*(450')(25.5')]/43560 = 0.3$ acres brophm1
				8/28/25	2	0.40	ACRE	MO 72 West Leg	417+05.46	LT	423+25.46	LT	[(620')*(30')]/43560 = 0.4 acres brophm1
				8/28/25	3	0.10	ACRE	MO 51 North Leg	321+00.00	LT	323+30.00	LT	[(230')*(20')]/43560 = 0.1 acres brophm1
560	8051000A	SEEDING - COOL SEASON GRASSES	8/26/25	8/28/25	1	0.30	ACRE	MO 51 North Leg	321+00.00	RT	325+50.00	RT	$[(450')^*(13.5') + 0.5^*(450')(25.5')]/43560 = 0.3$ acres brophm1
				8/28/25	2	0.40	ACRE	MO 72 West Leg	417+05.46	LT	423+25.46	LT	[(620')*(30')]/43560 = 0.4 acres brophm1
				8/28/25	3	0.10	ACRE	MO 51 North Leg	321+00.00	LT	323+30.00	LT	[(230')*(20')]/43560 = 0.1 acres brophm1

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 6/5/2025 Page 8 of 15



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3842	0050	EMBANKMENT IN PLACE	Material		5	Aug 1, 2025	SYSTEM	(\$19,660.00)	
					5	Aug 1, 2025	SYSTEM	\$19,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user brophm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0050 -							\$0.00	
	0060	COMPACTING EMBANKMENT	Material		5	Aug 1, 2025	SYSTEM	(\$10,528.00)	
					5	Aug 1, 2025	SYSTEM	\$10,528.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brophm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0060 -				_		01/0==1/	\$0.00	
	0100	TYPE 5 AGGREGATE FOR BASE (6 IN.	Material		5	Aug 1, 2025	SYSTEM	(\$30,231.00)	
		THICK)			5	Aug 1, 2025	SYSTEM	\$30,231.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brophm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Aug 18, 2025	SYSTEM	(\$52,201.80)	
					6	Aug 18, 2025	SYSTEM	\$52,201.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user brophm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0100 -							\$0.00	
	0110	MISC. GRAVEL OR CR. STONE	Material		7	Sep 2, 2025	SYSTEM	(\$9,204.00)	
					7	Sep 2, 2025	SYSTEM	\$9,204.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user brophm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0110 -				_		01/0==1/	\$0.00	
	0120	TYPE A2 SHOULDER	Material		7	Sep 2, 2025	SYSTEM	(\$20,015.50)	
					7	Sep 2, 2025	SYSTEM	\$20,015.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brophm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	FUEL	6	Aug 18, 2025	brophm1	(\$43.90)	All A2 shoulders on this project are concrete. The system assumed the shoulders are asphalt and took fuel out automatically.
					7	Sep 2, 2025	brophm1	(\$66.18)	System gave money for fuel adjustment. Contractor did not check fuel adjustment for concrete on contract.
				FUEL - Tota	ıl			(\$110.08)	
			Other Item /	Adjustment -	Total			(\$110.08)	
			Price FUEL		6	Aug 18, 2025	SYSTEM	\$43.90	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Sep 2, 2025	SYSTEM	\$66.18	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$110.08	
			Price FUEL	- Total				\$110.08	
	0120 -							\$0.00	
	0130	BIT. PAVEMENT C	Other Item Adjustment	ACAD	4	Jul 16, 2025	brophm1	\$493.31	Contractor selected AC adjustment on contract.
					7	Sep 2,	brophm1	\$24.60	Refer to the document called, "250117-H03 J9P3842 Estimate 0007 AC Index



t Lin	e Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
2 013		Other Item	ACAD		2025			Price Adjustment Hot Mix Asphalt Ton" on eProjects for further information.
	MIXTURE PG64-22 (BP-1)	Adjustment	ACAD - Total				\$517.91	
		Other Item	Adjustment -	Total			\$517.91	
		Price FUEL		4	Jul 16, 2025	SYSTEM	\$405.45	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				7	Sep 2, 2025	SYSTEM	\$26.10	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				\$431.55	
		Price FUEL	- Total				\$431.55	
013	0 - Total						\$949.46	
014	0 MISC.	Other Item Adjustment	ACAD	4	Jul 16, 2025	brophm1	\$331.33	Contractor selected AC adjustment on contract.
			ACAD - Total				\$331.33	
		Other Item	Adjustment -	Total			\$331.33	
014	0 - Total						\$331.33	
015	0 MISC. BITUMINOUS PAVEMENT	Other Item Adjustment	ACAD	4	Jul 16, 2025	brophm1	\$151.29	Contractor selected AC adjustment on contract.
	(SURF. LEVEL)		ACAD - Tot	al			\$151.29	
		Other Item	Adjustment -	Total			\$151.29	
	0 - Total						\$151.29	
016	0 TACK COAT	Material		4	Jul 16, 2025	SYSTEM	(\$1,643.88)	
				4	Jul 16, 2025	SYSTEM	\$1,643.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brophm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
		Material - To	Material - Total					
016	0 - Total						\$0.00	
017	0 CONCRETE PAVEMENT (9 IN. NON-REINF)	Material		6	Aug 18, 2025	SYSTEM	(\$188,831.50)	
	,			6	Aug 18, 2025	SYSTEM	\$188,831.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brophm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				7	Sep 2, 2025	SYSTEM	(\$377,178.50)	
				7	Sep 2, 2025	SYSTEM	\$377,178.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
		Material - To	otal				\$0.00	
017	0 - Total						\$0.00	
018	0 MISC.	Material		6	Aug 18, 2025	SYSTEM	(\$69,274.80)	
				6	Aug 18, 2025	SYSTEM	\$69,274.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brophm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
018	0 - Total						\$0.00	
020	0 PAVED APPROACH, 8 IN.	Material		6	Aug 18, 2025	SYSTEM	(\$5,220.00)	
				6	Aug 18, 2025	SYSTEM	\$5,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				7	Sep 2, 2025	SYSTEM	(\$50,364.30)	
				7	Sep 2, 2025	SYSTEM	\$50,364.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brophm1 overridding Payment



Material Section Polytic Material Section Se	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
	9P3842	0200								
		2000		Material - To	otal					
ROCK DITCH						_		OVOTELL		
S		0230	ROCK DITCH	Material		5		SYSTEM	(\$92.00)	
2005 6			LINER			5		SYSTEM	\$92.00	Estimate Item Adjustment (0004) due to user brophm1 overridding Payment
2025 Sep 2, SYSTEM (\$50.140) The adjustment offsets the original system-generated Material Payment Estimate.						6		SYSTEM	(\$92.00)	
2025 7 58 p. 2 29/3 TEM 500.40 This adjustment offsets the original system-penerated Material Payment Estimate Exception 13 on the current Payment Estimate Exception 14 on the current Payment Estimate Exception 15 on the current Payment Estimate Exception 16 on the current Payment Estimate Exception 17 on the current Payme						6		SYSTEM	\$92.00	Estimate Item Adjustment (0006) due to user brophm1 overridding Payment
Company Comp						7		SYSTEM	(\$501.40)	
Material - Total So.00						7		SYSTEM	\$501.40	Estimate Item Adjustment (0008) due to user brophm1 overridding Payment
					- Total				\$0.00	
Material				Material - T	otal				\$0.00	
DRAINAGE		0230 -	Total						\$0.00	
2025 Sep 2, SYSTEM \$21,689.20 Estimate lem Adjustment (0007) due to user trophm1 overridding Payment Estimate Exception 11 on the current Payment Estimate Exception 12 on the current Payment Estimate Exception 12 on the current Payment Estimate Exception 13 on the current Payment Estimate Exception 14 on the current Payment Estimate Exception 15 on the Current Payment Estimate Exception 15 on the Current Payment Estimate Exception 12 on the current Payment Estimate Exception 15 on the Current Payment Estimate Estimate Exception 2 on the Current Payment Estimate Estimate Exception		0250		Material		6		SYSTEM	(\$3,465.80)	
2025 7 Sep 2 SYSTEM \$21,688.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 14 on the current Payment Estimate.						6		SYSTEM	\$3,465.80	Estimate Item Adjustment (0007) due to user brophm1 overridding Payment
Part						7		SYSTEM	(\$21,689.20)	
Material - Total So.00						7		SYSTEM	\$21,689.20	Estimate Item Adjustment (0009) due to user brophm1 overridding Payment
Case Total Support					- Total				\$0.00	
Material G Aug 18, 2025 SYSTEM (\$7,545.00)				otal				\$0.00		
DRAINAGE 2025 6		0250 -	Total						\$0.00	
Communication Communicatio		0260		Material		6		SYSTEM	(\$7,545.00)	
D260 - Total S0.00						6		SYSTEM	\$7,545.00	Estimate Item Adjustment (0008) due to user brophm1 overridding Payment
Solid Substitution Substitutio									\$0.00	
O280 CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED O280 - Total O320 TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION, CONTRACTOR FURNISHED / RETAINED O205 SYSTEM O206 SYSTEM O207 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. O205 SYSTEM O206 SYSTEM O207 SYSTEM O208 SYSTEM O209 SYSTEM O208 SYSTEM O209 SYSTEM				Material - T	otal					
MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED **Total** **SUSTEM** \$12,800.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user brophm1 overridding Payment Estimate Exception 1 on the current Payment Estimate. **SU.00 **SUSTEM** \$0.00 **OURD TOTAL** **SUSTEM** \$0.00 **TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION, CONTRACTOR FURNISHED / RETAINED **RETAINED** **SUSTEM** \$2,388.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brophm1 overridding Payment Estimate Item Adjustment (0003) due to user brophm1 overridding Payment Estimate Exception 2 on the current Payment Estimate. **SUSTEM** \$2,388.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brophm1 overridding Payment Estimate Exception 2 on the current Payment Estimate. **SUSTEM** **SUSTE										
COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED **Total** **SUSTEM** **SYSTEM** **SUSTEM** **SUSTEM		0280	MESSAGE SIGN	Material			2025			
RETAINED Material - Total S0.00			COMMUNICATION INTERFACE, CONTRACTOR FURNISHED /			2		SYSTEM	\$12,800.00	Estimate Item Adjustment (0001) due to user brophm1 overridding Payment
Solid Contract Cont									<u> </u>	
TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION, CONTRACTOR FURNISHED / RETAINED 4 Jul 16, 2025 \$SYSTEM \$2,388.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 5 Aug 1, 2025 \$SYSTEM \$2,388.00 This adjustment (0003) due to user brophm1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 5 Aug 1, 2025 \$SYSTEM \$2,388.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.				Material - T	Гotal					
TRAFFIC BARRIER HEIGHT TRANSITION, CONTRACTOR FURNISHED / RETAINED 4 Jul 16, 2025 5 Aug 1, 2025 5 Aug 1, 2025 5 Aug 1, 2025 5 SYSTEM \$2,388.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brophm1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 5 Aug 1, 2025 5 Aug 1, 2025 5 SYSTEM \$2,388.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.										
TRANSITION, CONTRACTOR FURNISHED / RETAINED 4 Jul 16, 2025 SYSTEM \$2,388.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 5 Aug 1, 2025 SYSTEM \$2,388.00 (\$2,388.00) This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		0320	TRAFFIC	Material		4	2025		(\$2,388.00)	
5 Aug 1, 2025 (\$2,388.00) 5 Aug 1, 2025 SYSTEM \$2,388.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.			TRANSITION, CONTRACTOR FURNISHED /			4		SYSTEM	\$2,388.00	Estimate Item Adjustment (0003) due to user brophm1 overridding Payment
5 Aug 1, 2025 \$2,388.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.			VE I AINED			5		SYSTEM	(\$2,388.00)	
- Total \$0.00						5	Aug 1,	SYSTEM	\$2,388.00	Estimate Item Adjustment (0005) due to user brophm1 overridding Payment
					- Total				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
				Туре			,		
J9P3842	0320	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION, CONTRACTOR FURNISHED / RETAINED	Material - To	otal				\$0.00	
	0320 -	- Total						\$0.00	
	0390	TEMPORARY REMOVABLE MARKING TAPE.	Material		4	Jul 16, 2025	SYSTEM	(\$360.00)	
		24 IN.			4	Jul 16, 2025	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brophm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Aug 1, 2025	SYSTEM	(\$360.00)	
					5	Aug 1, 2025	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brophm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					6	Aug 18, 2025	SYSTEM	(\$360.00)	
					6	Aug 18, 2025	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brophm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0390 -	- Total						\$0.00	
	0410	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		4	Jul 16, 2025	SYSTEM	(\$2,699.20)	
					4	Jul 16, 2025	SYSTEM	\$2,699.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brophm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To					\$0.00 \$0.00	
		- Total	Material - To					\$0.00 \$0.00	
		- Total SEPARATION GEOTEXTILE	Material - To		5	Aug 1, 2025	SYSTEM	\$0.00	
		SEPARATION			5		SYSTEM SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brophm1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
		SEPARATION				2025 Aug 1,		\$0.00 \$0.00 (\$60.00)	Estimate Item Adjustment (0007) due to user brophm1 overridding Payment
		SEPARATION			5	2025 Aug 1, 2025 Aug 18,	SYSTEM	\$0.00 \$0.00 (\$60.00) \$60.00	Estimate Item Adjustment (0007) due to user brophm1 overridding Payment
		SEPARATION			5	2025 Aug 1, 2025 Aug 18, 2025 Aug 18,	SYSTEM	\$0.00 \$0.00 (\$60.00) \$60.00	Estimate Item Adjustment (0007) due to user brophm1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment
		SEPARATION		otal - Total	5	2025 Aug 1, 2025 Aug 18, 2025 Aug 18,	SYSTEM	\$0.00 \$0.00 (\$60.00) \$60.00 (\$60.00)	Estimate Item Adjustment (0007) due to user brophm1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment
	0470	SEPARATION	Material	otal - Total	5	2025 Aug 1, 2025 Aug 18, 2025 Aug 18,	SYSTEM	\$0.00 \$0.00 (\$60.00) \$60.00 \$60.00	Estimate Item Adjustment (0007) due to user brophm1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment
	0470	SEPARATION GEOTEXTILE -Total 18 IN. GROUP A FLARED END	Material	otal - Total	5	2025 Aug 1, 2025 Aug 18, 2025 Aug 18,	SYSTEM	\$0.00 \$0.00 (\$60.00) \$60.00 \$60.00 \$0.00	Estimate Item Adjustment (0007) due to user brophm1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment
	0470	SEPARATION GEOTEXTILE -Total 18 IN. GROUP A	Material Material - To	otal - Total	5 6 6	2025 Aug 1, 2025 Aug 18, 2025 Aug 18, 2025	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$60.00) \$60.00 \$60.00 \$0.00 \$0.00	Estimate Item Adjustment (0007) due to user brophm1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment
	0470	SEPARATION GEOTEXTILE -Total 18 IN. GROUP A FLARED END	Material Material - To	otal - Total	5 6 6	2025 Aug 1, 2025 Aug 18, 2025 Aug 18, 2025 Aug 1, 2025	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$60.00) \$60.00 \$60.00 \$0.00 \$0.00 \$1,300.00)	Estimate Item Adjustment (0007) due to user brophm1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brophm1 overridding Payment
	0470	SEPARATION GEOTEXTILE -Total 18 IN. GROUP A FLARED END	Material Material - To	otal - Total	5 6 6 5 5	2025 Aug 1, 2025 Aug 18, 2025 Aug 18, 2025 Aug 1, 2025 Aug 1, 2025 Aug 1, 2025 Aug 1, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$60.00) \$60.00 \$60.00 \$0.00 \$0.00 \$1,300.00	Estimate Item Adjustment (0007) due to user brophm1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brophm1 overridding Payment
	0470	SEPARATION GEOTEXTILE -Total 18 IN. GROUP A FLARED END	Material Material - To	otal - Total	5 6 6 5 5	Aug 1, 2025 Aug 18, 2025 Aug 18, 2025 Aug 18, 2025 Aug 1, 2025 Aug 1, 2025 Aug 1, 2025 Aug 18, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$60.00) \$60.00 \$60.00 \$0.00 \$0.00 \$1,300.00 \$1,300.00	Estimate Item Adjustment (0007) due to user brophm1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brophm1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brophm1 overridding Payment Estimate Item Adjustment (0011) due to user brophm1 overridding Payment
	0470	SEPARATION GEOTEXTILE -Total 18 IN. GROUP A FLARED END	Material Material - To	- Total otal	5 6 6 5 5	Aug 1, 2025 Aug 18, 2025 Aug 18, 2025 Aug 18, 2025 Aug 1, 2025 Aug 1, 2025 Aug 1, 2025 Aug 18, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$60.00) \$60.00 \$60.00 \$0.00 \$0.00 \$1,300.00 \$1,300.00 \$1,300.00	Estimate Item Adjustment (0007) due to user brophm1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brophm1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brophm1 overridding Payment Estimate Item Adjustment (0011) due to user brophm1 overridding Payment
	0470 - 0470 - 0530	SEPARATION GEOTEXTILE -Total 18 IN. GROUP A FLARED END	Material - To	- Total otal	5 6 6 5 5	Aug 1, 2025 Aug 18, 2025 Aug 18, 2025 Aug 18, 2025 Aug 1, 2025 Aug 1, 2025 Aug 1, 2025 Aug 18, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$60.00) \$60.00 (\$60.00) \$60.00 \$0.00 \$0.00 (\$1,300.00) \$1,300.00 \$1,300.00	Estimate Item Adjustment (0007) due to user brophm1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brophm1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brophm1 overridding Payment Estimate Item Adjustment (0011) due to user brophm1 overridding Payment
	0470 - 0470 - 0530 -	SEPARATION GEOTEXTILE -Total 18 IN. GROUP A FLARED END SECT	Material - To	- Total otal	5 6 6 5 5	Aug 1, 2025 Aug 18, 2025 Aug 18, 2025 Aug 18, 2025 Aug 1, 2025 Aug 1, 2025 Aug 1, 2025 Aug 18, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$60.00) \$60.00 (\$60.00) \$60.00 \$0.00 \$0.00 \$1,300.00 \$1,300.00 \$1,300.00 \$0.00	Estimate Item Adjustment (0007) due to user brophm1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brophm1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brophm1 overridding Payment Estimate Item Adjustment (0011) due to user brophm1 overridding Payment



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
42	0550	MULCHING	Material	- Total		2025		\$0.00	Estimate Item Adjustment (0010) due to user brophm1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			Material - To					\$0.00	
	0550	Total	Waterial - 1	Jiai				\$0.00	
		SEEDING - COOL SEASON GRASSES	Material		7	Sep 2, 2025	SYSTEM	(\$2,320.00)	
					7	Sep 2, 2025	SYSTEM	\$2,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brophm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0560 -	Total						\$0.00	
	0570	ROCK DITCH CHECK	Material		2	Jun 16, 2025	SYSTEM	(\$2,565.00)	
					2	Jun 16, 2025	SYSTEM	\$2,565.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brophm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To					\$0.00	
			Overrun	Overrun	5	Aug 1, 2025	SYSTEM	(\$3,795.00)	
				Overrun - T	otal			(\$3,795.00)	
			Overrun - T	otal				(\$3,795.00)	
	0570 -							(\$3,795.00)	
	0580	TEMPORARY SEEDING	Material		4	Jul 16, 2025	SYSTEM	(\$645.00)	
					4	Jul 16, 2025	SYSTEM	\$645.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brophm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Aug 1, 2025	SYSTEM	(\$645.00)	
					5	Aug 1, 2025	SYSTEM	\$645.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brophm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					6	Aug 18, 2025	SYSTEM	(\$645.00)	
					6	Aug 18, 2025	SYSTEM	\$645.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brophm1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				- Total				\$0.00	
	Material - Total							\$0.00	
	0580 - 0590	Total SILT FENCE	Material		2	Jun 16,	SYSTEM	\$0.00 (\$565.50)	
					2	2025 Jun 16, 2025	SYSTEM	\$565.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brophm1 overridding Payment
				- Total		2020		\$0.00	Estimate Exception 3 on the current Payment Estimate.
		- I otal						\$0.00	
	0590 -	0 - Total							
	0700	BREAKAWAY ASSEMBLY (PERFORATED	Other Item Adjustment	STMI	7	Sep 2, 2025	brophm1	\$0.00 \$3,822.00	Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further information. MoDOT have received the certifications.
		SQUARE STEEL TUBE)		STMI - Total				\$3,822.00	
		,	Other Item	Adjustment -	Total			\$3,822.00	
	0700 -	Total						\$3,822.00	
	0710	2 IN. PSST POST - 12 GA.	Other Item Adjustment	STMI	7	Sep 2, 2025	brophm1	\$3,095.10	Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further information.



June 2 No. Past Foot 2 No. Past Foot 2 Note Item Adjustment Total 2005 No. 17.07 17.	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1710 - Total 1710 - Total 2710 - Total 271	J9P3842	0710			STMI - Tota				\$3,095.10	
OPYION DRIVEN PORT Adjustment STMI 7 Sep 2 Drophm1 \$1,737.40 Shozpin Medical Line Ren Or 2070 on ePhojects for further information. MoDOT have received the certifications. STMI - Total Shozpin Medical Line Ren Or 2070 on ePhojects for further information. MoDOT have received the certifications. STMI - Total Shozpin Medical Line Ren Or 2070 on ePhojects for further information. MoDOT have received the certifications. Shozpin Medical Line Ren Or 2070 on ePhojects for further information. STMI - Total Shozpin Medical Line Ren Or 2005 on ePhojects for further information. STMI - Total Shozpin Medical Line Ren Or 2005 on ePhojects for further information. STMI - Total Shozpin Medical Line Ren Or 2005 on ePhojects for further information. Shozpin Medical Line Ren Or 2005 on ePhojects for further information. Shozpin Medical Line Ren Or 2005 on ePhojects for further information. Shozpin Ren Or 2005 on ePhojects for further information. Shozpin Ren Or 2005 on ePhojects for further information. Shozpin Ren Or 2005 on ePhojects for further information. Shozpin Ren Or 2005 on ePhojects for further information. Shozpin Ren Or 2005 on ePhojects for further information. Shozpin Ren Or 2005 on ePhojects for further information. Shozpin Ren Or 2005 on ePhojects for further information. Shozpin Ren Or 2005 on ePhojects for further information. Shozpin Ren Or 2005 on ePhojects for further information. Shozpin Ren Or 2005 on ePhojects for further information. Shozpin Ren Or 2005 on ePhojects for further information. Shozpin Ren Or 2005 on ePhojects for further information. Shozpin Ren Or 2005 on ePhojects for further information. Shozpin Ren Or 2005 on ePhojects for further information. Shozpin Ren Or 2005 on ePhojects for further information. Shozpin Ren Or 2005 on ePhojects for further information. Shozpin Ren Or 2005 on ePhojects for further information. Shozpin Ren Or 2005 on ePhojects for further information. Shozpin Ren Or 2005 on ePhojects for				Other Item	Adjustment -	Total			\$3,095.10	
ANCHOR FOR 2 N. PSST - 12 GA Adjustment 2025 Stockple Material Line item 0700 - 0760* on eProjects for further information. MoCOT have received the certifications. STMI - Total		0710	- Total						\$3,095.10	
Other Item Adjustment - Total S1,737.40		0720	ANCHOR FOR 2		STMI	7		brophm1	\$1,737.40	Stockpile Material Line Item 0700 - 0780" on eProjects for further information.
1,730					STMI - Tota				\$1,737.40	
0730 2.55 N PSET Other Item Adjustment Total Supplement				Other Item	Adjustment -	Total			\$1,737.40	
POST INSERT (6 Adjustment 2025 Slockpile Material Line Item 0700 - 0780* on eProjects for further information. MODOT have received the certifications. STM1 - Total		0720	- Total						\$1,737.40	
Other Item Adjustment - Total S502.74		0730	POST INSERT (6		STMI	7		brophm1	\$502.74	Stockpile Material Line Item 0700 - 0780" on eProjects for further information.
1973 7-10tal 1973					STMI - Total	ı			\$502.74	
0740 2.5 IN. PSST POST - 12 GA.				Other Item	Adjustment -	Total			\$502.74	
POST - 12 GA. Adjustment 2025 STMI - Total S2,362,49		0730 -	- Total						\$502.74	
Other Item Adjustment - Total \$2,382.49		0740			STMI	7		brophm1	\$2,362.49	Stockpile Material Line Item 0700 - 0780" on eProjects for further information.
10740 - Total					STMI - Total				\$2,362.49	
0750 DRIVEN POST				Other Item	Adjustment -	Total			\$2,362.49	
ANCHOR FOR 2.5 IN. PSST - 7 GA. Adjustment 2025 Stockpile Material Line Item 0700 - 0780" on eProjects for further information. MoDOT have received the certifications. STMI - Total S1,731.52		0740 -	- Total						\$2,362.49	
Other Item Adjustment - Total S1,731.52		0750	ANCHOR FOR 2.5		STMI	7		brophm1	\$1,731.52	Stockpile Material Line Item 0700 - 0780" on eProjects for further information.
0750 - Total SH-FLAT SHEET Other Item Adjustment - Total S2,754.00 SH-FLAT SHEET Other Item Adjustment - Total S2,754.00 S750 - Total				STMI - Total					\$1,731.52	
0760 SH-FLAT SHEET Other Item Adjustment STMI 7 Sep 2, 2025 brophm1 \$2,754.00 Stockpile Material Line Item 0700 - 0780" on eProjects for further information. MoDOT have received the certifications. STMI - Total S2,754.00				Other Item Adjustment - Total					\$1,731.52	
Adjustment 2025 Stockpile Material Line Item 0700 - 0780" on eProjects for further information. MoDOT have received the certifications. STMI - Total S2,754.00		0750 -	- Total						\$1,731.52	
Other Item Adjustment - Total \$2,754.00		0760	SH-FLAT SHEET		STMI	7		brophm1	\$2,754.00	Stockpile Material Line Item 0700 - 0780" on eProjects for further information.
10760 - Total S2,754.00 ST-STRUCTURAL Other Item Adjustment Other Item Adjustment - Total S2,440.00 ST-STRUCTURAL Other Item Adjustment - Total S2,440.00 ST-STRUCTURAL Other Item Adjustment - Total S2,440.00 Other Item Adjustment Other Item Adjustment - Total S2,440.00 Other Item Adjustment Other Item Adjustment Other Item Adjustment - Total S862.40 Other Item Adjustment - Total Other Item Adjus					STMI - Tota	ı			\$2,754.00	
O770 ST-STRUCTURAL OTHER INTERPOLATION STANDARD CONTROL STANDARD STANDARD STANDARD STANDARD STOCK PRICE STANDARD STANDA				Other Item Adjustment - Total					\$2,754.00	
Adjustment 2025 Stockpile Material Line Item 0700 - 0780" on eProjects for further information. MoDOT have received the certifications. STMI - Total \$2,440.00 Other Item Adjustment - Total \$2,440.00 O770 - Total \$2,440.00 O780 SHF-FLAT SHEET FLUORESCENT Adjustment Adjustment STMI 7 Sep 2, 2025 brophm1 S862.40 OTHER ITEM ADJUSTMENT SHEET SHEET FLUORESCENT Adjustment STMI - Total \$862.40 OTHER ITEM ADJUSTMENT - TOTAL \$862.40		0760 -	Total						\$2,754.00	
Other Item Adjustment - Total \$2,440.00		0770	ST-STRUCTURAL		STMI	7		brophm1	\$2,440.00	Stockpile Material Line Item 0700 - 0780" on eProjects for further information.
0770 - Total 0780 SHF-FLAT SHEET FLUORESCENT Adjustment STMI 7 Sep 2, 2025 brophm1 \$862.40 Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further information. MoDOT have received the certifications. STMI - Total \$862.40 Other Item Adjustment - Total \$862.40 J9P3842 - Total \$16,944.73					STMI - Tota				\$2,440.00	
0780 SHF-FLAT SHEET FLUORESCENT Adjustment STMI 7 Sep 2, 2025 brophm1 \$862.40 Refer to the document called, "250117-H03 J9P3942 Estimate 0007 D&S Stockpile Material Line Item 0700 - 0780" on eProjects for further information. MoDOT have received the certifications. STMI - Total \$862.40 O780 - Total \$862.40 J9P3842 - Total \$16,944.73				Other Item	Adjustment -	Total			\$2,440.00	
FLUORESCENT Adjustment 2025 Stockpile Material Line Item 0700 - 0780" on eProjects for further information. MoDOT have received the certifications. STMI - Total \$862.40 Other Item Adjustment - Total \$862.40 J9P3842 - Total \$16,944.73		0770 - Total							\$2,440.00	
Other Item Adjustment - Total \$862.40 0780 - Total \$862.40 J9P3842 - Total \$16,944.73		0780						brophm1	\$862.40	Stockpile Material Line Item 0700 - 0780" on eProjects for further information.
0780 - Total \$862.40 J9P3842 - Total \$16,944.73					STMI - Total	1			\$862.40	
J9P3842 - Total \$16,944.73				Other Item	Adjustment -	Total			\$862.40	
		0780 -	- Total						\$862.40	
Overall - Total \$16,944.73	J9P3842	Total							\$16,944.73	
	Overall -	Total							\$16,944.73	

MoDOT

Contract Adjustments for Contract - 250117-H03

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 15 of 15