

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 4, 2025

Progress Estimate Number 6	Contract ID Prime Contract	250314 or Emery	4-C01 Sapp & Sons, Inc.	•	Period Start Period End	July 16, 2025 August 1, 202		\$11,325,502.80 \$0.00 \$11,325,502.80
Approval Date								By User
August 4, 2025			Generated and	l Approve	ed (and should	d be considered	Draft) at the Project Office Level by	johnsm7
August 4, 2025			Reviewed and App	roved (a	nd should be	considered Draf	t) at the Resident Engineer Level by	ilesb1
August 6, 2025				Review	ed and Appro	ved at the Centi	ral Office Controllers Office Level by	ramses1
Original Completi	on Date	% of Current Contract Amoun	nt Complete					
June 30, 202	16	June	30, 2026				41.36%	
	Conti	act Informa	tional Dates				Milestones	
Date Description	Original Comp	letion Date	Current Completio	n Date		No Milesto	nes Exist for Contract	
Acceptance Date								
Awarded Date	April 2, 2025		April 2, 2025					
Letting Date	March 14, 2025	5	March 14, 2025					
Notice to Proceed Date	May 5, 2025		May 5, 2025					
Work Began Date	June 10, 2025		June 10, 2025					

Contract Total P	ay For Estimate No. 6			
		This Estimate	Previous	To Date
250314-C01				
	Total Posted Items Pay	\$2,676,607.26	\$2,007,378.08	\$4,683,985.34
	Gross Item Adjustments	\$2,126.19	\$1,120.90	\$3,247.09
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	·		\$2,008,498.98	\$4,687,232.43
Contract Total P	avable This Estimate:	\$2,678,733,45		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J3P3158	0140	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	SQYD	\$285.000	380	\$108,300.00
	0170	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	LF	\$4.900	968	\$4,743.20
	0180	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	EA	\$6.250	430	\$2,687.50
	0190	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	EA	\$17.000	40	\$680.00
	0200	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	EA	\$6.500	27	\$175.50
Project J3	P3158 - T	otal					\$116,586.20
JKR0249	0500	4011231	BITUMINOUS PAVEMENT MIXTURE PG58-28H, (BP-1)	TONS	\$80.350	25,014.030	\$2,009,877.31
	0510	4079912	MISC.MODIFIED TACK COAT	GAL	\$3.750	36,705	\$137,643.75
	0640	6181000	MOBILIZATION	LS	\$550,000.000	0.750	\$412,500.00
Project JK	R0249 - T	otal					\$2,560,021.06
Overall - T	otal						\$2,676,607.26

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item A	Adjustr	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J3P3158	0140	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 2 on	380	\$285.00	\$108,300.00

Revision 5/29/2025 Page 1 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 4, 2025

Estimate	gress e Numb 6		0314-C01 nery Sapp & S	Sons, Inc.	Pay Period End August 1, 2025 Net Cha	II Contract Amo ange Order Amo t Contract Amo	ount	\$11,325,502.8 \$0.0 \$11,325,502.8
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J3P3158					the current Payment Estimate.			
	0140	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-380	\$285.00	(\$108,300.00)
	0180	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user johnsm7 overridding Payment Estimate Exception 4 on the current Payment Estimate.	430	\$6.25	\$2,687.50
	0180	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-430	\$6.25	(\$2,687.50)
	0190	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user johnsm7 overridding Payment Estimate Exception 10 on the current Payment Estimate.	40	\$17.00	\$680.00
	0190	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material			-40	\$17.00	(\$680.00)
	0200	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user johnsm7 overridding Payment Estimate Exception 12 on the current Payment Estimate.	27	\$6.50	\$175.50
	0200	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material			-27	\$6.50	(\$175.50)
	0210	CONSTRUCTION SIGNS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user johnsm7 overridding Payment Estimate Exception 15 on the current Payment Estimate.	350	\$7.00	\$2,450.00
	0210	CONSTRUCTION SIGNS	Material			-350	\$7.00	(\$2,450.00)
	0240	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user johnsm7 overridding Payment Estimate Exception 16 on the current Payment Estimate.	2	\$3,600.00	\$7,200.00
	0240	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material			-2	\$3,600.00	(\$7,200.00)
JKR0249	0500	BITUMINOUS PAVEMENT MIXTURE PG58-28H, (BP-1)	Other Item Adjustment	Asphalt Cement Price Adjustment	AC adjustment Line number: 0500 Install quantity: 25014.03 (tons) @3.4% (virgin) * 2.5 (diff) = \$2126.19			\$2,126.19
	0510	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user johnsm7 overridding Payment Estimate Exception 1 on the current Payment Estimate.	55,310	\$3.75	\$207,412.50
	0510	MISC.	Material			-55,310	\$3.75	(\$207,412.50)
	0520	FURNISHING AND PLACING CONCRETE MATERIAL FOR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	1,390.63300	\$250.00	\$347,658.25

Revision 5/29/2025 Page 2 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 4, 2025

Prog Estimate	gress e Numl 6		60314-C01 nery Sapp & S	Sons, Inc.	Pay Period Start Pay Period End	July 16, 2025 August 1, 2025	Original Cor Net Change Current Cor	Order An	\$11,325,502.80 \$0.00 \$11,325,502.80	
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type		Comments		justment Quantity	Line Item Adjustment Unit Price	Adjustment amount
JKR0249		FULL DEPTH PAVEMENT REPAIR			Adjustment (0008) overridding Paymer the current Paymer	nt Estimate Except				
	0520	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material				-1,3	90.63300	\$250.00	(\$347,658.25)
	0560	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment off generated Material Adjustment (0009) overridding Payme the current Paymer	Payment Estimate due to user johnsn nt Estimate Except	e Item n7	2,915	\$6.25	\$18,218.75
	0560	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material					-2,915	\$6.25	(\$18,218.75)
Total										\$2,126.19

Revision 5/29/2025 Page 3 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Co	ntract Project Informa	ation
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J3P3158	FAF 24-1(96)	Resurface and ADA improvements	24	LAFAYETTE	from Lexington to Wa	verly	
JKR0249	FAF 13-3(96)	Resurface	24	LAFAYETTE	from Jackson County	line to Route 13 in Lexington	on
Totals b	y Job N	umbers					
J3P3158		ed Item Pay s Item Adjustme		Item Pay	This Estimate \$116,586.20 \$0.00 \$116,586.20	Previous \$104,712.50 \$0.00 \$104,712.50	To Date \$221,298.70 \$0.00 \$221,298.70
	Liquid	tive centive dated Damages · Contract Adjus			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00
JKR0249		ed Item Pay s Item Adjustme		Item Pay	This Estimate \$2,560,021.06 \$2,126.19 \$2,562,147.25	Previous \$1,902,665.58 \$1,120.90 \$1,903,786.48	To Date \$4,462,686.64 \$3,247.09 \$4,465,933.73
	Liquid	tive centive dated Damages · Contract Adjus			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 5/29/2025 Page 4 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 4079912, Project Item Line Number 0510, Material Set 407991296, Material 1015EASS1VH - Emulsified Asphalt - Non-Tracking Tack, Acceptance Action Generic AspEmulsion is insufficient.	Certifications have been received but not yet entered into the system.	johnsm7	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6131010, Project Item Line Number 0140, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Tests have been received but not yet entered into the system.	johnsm7	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 6131010, Project Item Line Number 0520, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Tests have been received but not yet entered into the system.	johnsm7	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6131015, Project Item Line Number 0180, Material Set 613101596, Material 1036RSDFEC42M16 - Rein Steel EC No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Certifications have been received but not yet entered into the system.	johnsm7	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6131015, Project Item Line Number 0180, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Certifications have been received but not yet entered into the system.	johnsm7	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6131015, Project Item Line Number 0180, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Certifications have been received but not yet entered into the system.	johnsm7	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 6131015, Project Item Line Number 0560, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Certifications have been received but not yet entered into the system.	johnsm7	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 6131015, Project Item Line Number 0560, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Certifications have been received but not yet entered into the system.	johnsm7	Overridden
Estimate Exception Type: Insufficient Materials: Project JKR0249, Item 6131015, Project Item Line Number 0560, Material Set 613101596, Material 1036RSDFEC42M16 - Rein Steel EC No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Certifications have been received but not yet entered into the system.	johnsm7	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6131017, Project Item Line Number 0190, Material Set 613101796, Material 1036RSDFEC42M16 - Rein Steel EC No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	District materials will enter in the information.	johnsm7	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6131017, Project Item Line Number 0190, Material Set 613101796, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	District materials will enter in the information.	johnsm7	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6131018, Project Item Line Number 0200, Material Set 613101896, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Certifications have been received but not yet entered into the system.	johnsm7	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6131018, Project Item Line Number 0200, Material Set 613101896, Material 1036RSDFEC42M16 - Rein Steel EC No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Certifications have been received but not yet entered into the system.	johnsm7	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6131018, Project Item Line Number 0200, Material Set 613101896, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Certifications have been received but not yet entered into the system.	johnsm7	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6161005, Project Item Line Number 0210, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Certifications have been received but not yet entered into the system.	johnsm7	Overridden
Estimate Exception Type: Insufficient Materials: Project J3P3158, Item 6161098A, Project Item Line Number 0240, Material Set 6161098A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Certifications have been received but not yet entered into the system.	johnsm7	Overridden

Revision 5/29/2025 Page 5 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

t Proje	ct Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See report generated date)
- J3P31	58 0001	0010	1081000	SIGNET DBE REPORTING	1.00	0.00	1.00	LS	1.00	\$1,000.00	\$1,000
	0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$250.00	\$0
	0001	0030	2063000	CLASS 3 EXCAVATION	34.00	0.00	34.00	CUYD	0.00	\$87.00	\$0
	0001	0040	2063500	CULVERT CLEANOUT	1.00	0.00	1.00	EA	0.00	\$1,200.00	\$0
	0001	0050	2071000	LINEAR GRADING CLASS 1	1.00	0.00	1.00	STA	0.00	\$5,250.00	\$0
	0001	0070	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	11,441.40	0.00	11,441.40	TONS	0.00	\$27.80	\$0
	0001	0080	4011231	BITUMINOUS PAVEMENT MIXTURE PG58-28H, (BP-1)	39,553.80	0.00	39,553.80	TONS	0.00	\$84.00	\$0
	0001	0090	4079912	MISC.MODIFIED TACK COAT	71,307.00	0.00	71,307.00	GAL	0.00	\$3.75	\$0
	0001	0100	6081010	CONCRETE CURB RAMP	8.50	0.00	8.50	SQYD	0.00	\$450.00	\$0
	0001	0110	6081012	TRUNCATED DOMES	60.00	0.00	60.00	SQFT	0.00	\$35.00	\$0
	0001	0120	6086004	CONCRETE SIDEWALK, 4 IN.	30.90	0.00	30.90	SQYD	0.00	\$185.00	\$0
	0001	0130	6097000	ROCK LINING	2.00	0.00	2.00	CUYD	0.00	\$275.00	\$0
	0001	0140	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	384.00	0.00	384.00	SQYD	380.00	\$285.00	\$108,300
	0001	0150	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	38.00	0.00	38.00	SQYD	0.00	\$1.00	\$0
	0001	0160	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	38.00	0.00	38.00	SQYD	0.00	\$4.35	\$0
	0001	0170	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	1,110.00	0.00	1,110.00	LF	968.00	\$4.90	\$4,743
	0001	0180	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	660.00	0.00	660.00	EA	430.00	\$6.25	\$2,687
	0001	0190	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	40.00	0.00	40.00	EA	40.00	\$17.00	\$680
	0001	0200	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	32.00	0.00	32.00	EA	27.00	\$6.50	\$175
	0001	0210	6161005	CONSTRUCTION SIGNS	2,292.00	0.00	2,292.00	SQFT	350.00	\$7.00	\$2,450
	0001	0220	6161025	CHANNELIZER (TRIM-LINE)	200.00	0.00	200.00	EA	0.00	\$19.00	\$0
	0001	0230	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	0.00	\$900.00	\$0
	0001	0240	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	2.00	0.00	2.00	EA	2.00	\$3,600.00	\$7,200
	0001	0250	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.25	\$376,250.00	\$94,062
	0001	0260	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	5.00	0.00	5.00	EA	0.00	\$225.00	\$0
	0001	0270	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	164,466.00	0.00	164,466.00	LF	0.00	\$0.21	\$0
	0001	0280	6205902A 6209901	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS MISC.OPTIONAL TEMPORARY PAVEMENT MARKING	196,332.00	0.00	196,332.00	LF	0.00	\$0.23 \$33,100.00	\$0
	0001	0300	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	845.00	0.00	845.00	SQYD	0.00	\$9.00	\$(
	0001	0310	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	10.115.00	0.00	10,115.00	SQYD	0.00	\$7.20	\$0
	0001	0320	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	1,952.70	0.00	1,952.70	STA	0.00	\$19.90	\$(
	0001	0330	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	976.30	0.00	976.30	STA	0.00	\$19.90	\$(
	0001	0340	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$4.500.00	\$(
	0001	0350		15 IN. PIPE GROUP B	50.00	0.00	50.00	LF	0.00	\$4,500.00	\$(
	0001	0360		15 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	1.00	0.00	1.00	EA	0.00	\$300.00	\$(
	0001	0370	8051000A	SEEDING - COOL SEASON GRASSES	0.10	0.00	0.10	ACRE	0.00	\$78,000.00	\$0
	0001	0380	8061004	SEDIMENT TRAP ROCK	2.00	0.00	2.00	CUYD	0.00	\$200.00	\$0
	0001	0390	8061005	ROCK DITCH CHECK	24.00	0.00	24.00	LF	0.00	\$42.00	\$0
	0001	0400	8061016	SEDIMENT REMOVAL	3.00	0.00	3.00	CUYD	0.00	\$45.00	\$0
	0001	0410	8064133	TYPE 1C EROSION CONTROL BLANKET	112.00	0.00	112.00	SQYD	0.00	\$6.00	\$0
	0040	0420	6161047	TYPE 3 OBJECT MARKER	12.00	0.00	12.00	EA	0.00	\$105.00	\$(
	0040	0430		2 IN. PSST POST - 12 GA.	140.00	0.00	140.00	LF	0.00	\$28.00	\$0
	0040	0440		DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA.	14.00	0.00	14.00	EA	0.00	\$136.00	\$0
	0040	0450		SH-FLAT SHEET	20.00	0.00	20.00	SQFT	0.00	\$130.00	\$0
	0040	0460	9039902	MISC.RELOCATE EXISTING SIGN ASSEMBLIES	2.00	0.00	2.00	EA	0.00	\$435.00	\$0
Projec				Pate as of Report Generated Date	2.00	0.00	2.00		0.00	ψ-100.00	\$221,298
JKR02	0004	0470	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$11,500.00	\$221,290
	0001	0470	2153000	SHAPING SLOPES, CLASS III	26.00	0.00	26.00	100F	0.00	\$11,500.00	\$0
014102		U-10U	2100000	OTHER INCOMES LO, OLAGO III	20.00	0.00	20.00	1001	0.00	ψ1,200.00	Ş.
014102	0001	0400	30/0010	MISC PERMANENT AGGREGATE EDGE TREATMENT	10 066 00	0.00	10 066 00	TONG	0.00	¢ クフ つF	60
014102		0490 0500	3049910 4011231	MISC.PERMANENT AGGREGATE EDGE TREATMENT BITUMINOUS PAVEMENT MIXTURE PG58-28H, (BP-1)	10,966.00 49,537.00	0.00	10,966.00 49,537.00	TONS	0.00 37,689.83	\$27.25 \$80.35	\$0 \$3,028,377

Revision 5/29/2025 Page 6 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

DEPTH PACKEMENT REPAIR OOS 0.530 611012 SUBSCRADE CORPACTION (6 IN LOFETH) (PACKEMENT REPAIR) 180.00 0.00 180.00 5070 0.00 54.00 54.00 1000 0.00 180.00 5070 0.00 54.00 54.00 1000 0.00	ntract I	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
)314- JI	KR0249	0001	0520	6131010		1,796.40	0.00	1,796.40	SQYD	1,390.63	\$250.00	\$347,658.
Control Cont			0001	0530	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	180.00	0.00	180.00	SQYD	0.00	\$1.00	\$0.
0001 0001 0002 0101015 0001 0002			0001	0540	6131013		180.00	0.00	180.00	SQYD	0.00	\$4.35	\$0.
0001			0001	0550	6131014		6,152.00	0.00	6,152.00	LF	4,611.00	\$4.90	\$22,593
0001 0880 6133021 REMOVAL FOR CLASS G PARTIAL DEPTH PAVEMENT REPAIR 1,62160 0.00 1,02160 SQYD 1,02160 STO 1,0001 0800 6110005 CONSTRUCTION SIGNS STO 0.00 0.0			0001	0560	6131015		4,242.00	0.00	4,242.00	EA	2,915.00	\$6.25	\$18,218
0001 0590 6161005 CONSTRUCTION SIGNS 3.582.00 0.00 3.562.00 SOFT 510.00 570.00			0001	0570	6133020		511.00	0.00	511.00	TONS	511.00	\$115.00	\$58,765
0001			0001	0580	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	1,621.60	0.00	1,621.60	SQYD	1,621.60	\$131.50	\$213,240
0001			0001	0590	6161005	CONSTRUCTION SIGNS	3,562.00	0.00	3,562.00	SQFT	510.00	\$7.00	\$3,570
0001 0620 6161040 FLASHING ARROW PANEL 2.00 0.00 2.00 EA 1.00 \$1,450.00			0001	0600	6161025	CHANNELIZER (TRIM-LINE)	150.00	0.00	150.00	EA	100.00	\$19.00	\$1,900
0001 0600 6101096A CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION 0.00 4.00 EA 2.00 \$4,760.00 0			0001	0610	6161030	TYPE 3 MOVEABLE BARRICADE	18.00	0.00	18.00	EA	0.00	\$250.00	\$0
NTERFACE, CONTRACTOR FURNISHED / RETAINED 1.00			0001	0620	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	1.00	\$1,450.00	\$1,450
0001			0001	0630	6161098A		4.00	0.00	4.00	EA	2.00	\$4,750.00	\$9,500
0001 0600 0600 060001 0600 060001 0600 060001 06000 060001 06000 060001 06000 060001 0600001 0600001 0600001 060000000000			0001	0640	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$550,000.00	\$550,000
0001 0670 0620021 PREFORMED THERMOPLASTIC PAVEMENT MARKING, 1.00 0.00 1.00 EA 0.00 \$500.00			0001	0650	6200012		42.00	0.00	42.00	LF	0.00	\$16.50	\$0
Description			0001	0660	6200018		96.00	0.00	96.00	LF	0.00	\$27.50	\$
MARKING PAINT, TYPE L BEADS 600			0001	0670	6200021		1.00	0.00	1.00	EA	0.00	\$500.00	\$
0001 0700 02059032 030590			0001	0680	6205901A		88,962.00	0.00	88,962.00	LF	0.00	\$0.23	\$
0001 0710 6205906A 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT 1,432.00 0.00 1,432.00 LF 0.00 \$1.05			0001	0690	6205902A		183,181.00	0.00	183,181.00	LF	0.00	\$0.26	\$
0001 0720 6209901 MISC.OPTIONAL TEMPORARY PAVEMENT MARKING 1.00 0.00 1.00 LS 0.00 \$1.00 0.00			0001	0700	6205903A		21,439.00	0.00	21,439.00	LF	0.00	\$0.26	\$
0001				0710	6205906A		1,432.00	0.00	1,432.00	LF	0.00	\$1.05	\$
0001			0001	0720	6209901	MISC.OPTIONAL TEMPORARY PAVEMENT MARKING	1.00	0.00	1.00	LS	0.00	\$1.00	\$
0001 0750 6261000A BITUMINOUS SHOULDER RUMBLE STRIP 1,787.00 0.00 1,787.00 STA 0.00 \$19.90			0001	0730	6221001		33,562.00	0.00	33,562.00	SQYD	0.00	\$2.25	\$
0001 0760 6261001 BITUMINOUS CENTERLINE RUMBLE STRIP 742.00 0.00 742.00 STA 0.00 \$19.90			0001	0740	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	4,838.00	0.00	4,838.00	SQYD	0.00	\$8.75	\$
0001 0770 6274000 CONTRACTOR FURNISHED SURVEYING AND STAKING 1.00 0.00 1.00 LS 0.00 \$4,500.00			0001	0750	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	1,787.00	0.00	1,787.00	STA	0.00	\$19.90	\$
0010 0780 6061060 MGS GUARDRAIL 2,628.00 0.00 2,628.00 LF 0.00 \$25.00 0010 0790 6061061 MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING 3,438.00 0.00 3,438.00 LF 0.00 \$25.00 0010 0800 6061069 MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) 8.00 0.00 8.00 EA 0.00 \$3,700.00 0010 0810 6061080 MGS END ANCHOR 4.00 0.00 4.00 EA 0.00 \$1,400.00 0010 0820 6063014 TYPE A CRASHWORTHY END TERMINAL (MASH) 27.00 0.00 27.00 EA 0.00 \$3,350.00 0040 0830 6161047 TYPE 3 OBJECT MARKER 1.00 0.00 1.00 EA 0.00 \$28.00 0040 0840 9031270A 2 IN. PSST POST - 12 GA. 6.00 0.00 1.00 EA 0.00 \$150.00			0001	0760	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	742.00	0.00	742.00	STA	0.00	\$19.90	\$
0010 0790 6061061 MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING 3,438.00 0.00 3,438.00 LF 0.00 \$29.50			0001	0770	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$4,500.00	\$
0010 0800 6061069 MGS BRIDGE APPROACH TRANSITION SECTION (REGULARINO CURB) 8.00 0.00 8.00 EA 0.00 \$3,700.00 0010 0810 6061080 MGS END ANCHOR 4.00 0.00 4.00 EA 0.00 \$1,400.00 0010 0820 6063014 TYPE A CRASHWORTHY END TERMINAL (MASH) 27.00 0.00 27.00 EA 0.00 \$3,350.00 0040 0830 6161047 TYPE 3 OBJECT MARKER 1.00 0.00 1.00 EA 0.00 \$110.00 0040 0840 9031270A 2 IN. PSST POST - 12 GA. 6.00 0.00 6.00 LF 0.00 \$28.00 0040 0850 9031271A DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. 1.00 0.00 1.00 EA 0.00 \$150.00			0010	0780	6061060	MGS GUARDRAIL	2,628.00	0.00	2,628.00	LF	0.00	\$25.00	\$
0010 0800 6061069 MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) 8.00 0.00 8.00 EA 0.00 \$3,700.00 0010 0810 6061080 MGS END ANCHOR 4.00 0.00 4.00 EA 0.00 \$1,400.00 0010 0820 6063014 TYPE A CRASHWORTHY END TERMINAL (MASH) 27.00 0.00 27.00 EA 0.00 \$3,350.00 0040 0830 6161047 TYPE 3 OBJECT MARKER 1.00 0.00 1.00 EA 0.00 \$110.00 0040 0840 9031270A 2 IN. PSST POST - 12 GA. 6.00 0.00 6.00 LF 0.00 \$28.00 0040 0850 9031271A DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. 1.00 0.00 1.00 EA 0.00 \$150.00			0010	0790	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	3,438.00	0.00	3,438.00	LF	0.00	\$29.50	\$
0010 0820 6063014 TYPE A CRASHWORTHY END TERMINAL (MASH) 27.00 0.00 27.00 EA 0.00 \$3,350.00 0040 0830 6161047 TYPE 3 OBJECT MARKER 1.00 0.00 1.00 EA 0.00 \$110.00 0040 0840 9031270A 2 IN. PSST POST - 12 GA. 6.00 0.00 6.00 LF 0.00 \$28.00 0040 0850 9031271A DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. 1.00 0.00 1.00 EA 0.00 \$150.00			0010	0800	6061069			0.00	8.00	EA	0.00	\$3,700.00	\$
0010 0820 6063014 TYPE A CRASHWORTHY END TERMINAL (MASH) 27.00 0.00 27.00 EA 0.00 \$3,350.00 0040 0830 6161047 TYPE 3 OBJECT MARKER 1.00 0.00 1.00 EA 0.00 \$110.00 0040 0840 9031270A 2 IN. PSST POST - 12 GA. 6.00 0.00 6.00 LF 0.00 \$28.00 0040 0850 9031271A DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. 1.00 0.00 1.00 EA 0.00 \$150.00			0010	0810	6061080	MGS END ANCHOR	4.00	0.00	4.00	EA	0.00	\$1,400.00	\$
0040 0830 6161047 TYPE 3 OBJECT MARKER 1.00 0.00 1.00 EA 0.00 \$110.00 0040 0840 9031270A 2 IN. PSST POST - 12 GA. 6.00 0.00 6.00 LF 0.00 \$28.00 0040 0850 9031271A DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. 1.00 0.00 1.00 EA 0.00 \$150.00			0010										\$
0040 0840 9031270A 2 IN. PSST POST - 12 GA. 6.00 0.00 6.00 LF 0.00 \$28.00 0040 0850 9031271A DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. 1.00 0.00 1.00 EA 0.00 \$150.00			0040			` '							
0040 0850 9031271A DRIVEN POST ANCHOR FOR 2 IN. PSST - 12 GA. 1.00 0.00 1.00 EA 0.00 \$150.00			0040										\$
0000 9001271A DIVERTICAT ANCHORY ON 2 IN 1 COST - 12 CA. 1.00 0.00 1.00 EA 0.00 \$100.00			0040										\$
Project JKR0249 - Total Value Posted to Date as of Report Generated Date \$4,4		rojoet H	(D0240 - E				1.00	0.00	1.00		0.00	ψ100.00	\$4,462,68
	4-C01	Overall	- Total Val	ue Poste	a to Date as	of Report Generated Date							\$4,683,

Revision 5/29/2025 Page 7 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J3P3158

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0140	6131010	FURN & PLACE CONC MATL FOR FULL DEPTH	7/21/25	8/1/25	1	54.89	SQYD		170.200		164.644		See DWR for specific details.
			7/22/25	8/1/25	1	80.89	SQYD		166.082		153.477		See DWR for details.
			7/23/25	8/1/25	1	109.78	SQYD		166.082		153.477		See DWR for details.
			7/28/25	8/1/25	1	134.44	SQYD		152.815		152.798		See DWR for details.
0170	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	7/21/25	8/1/25	1	180.00	LF		170.200		164.644		See DWR for specific details.
			7/22/25	8/1/25	1	290.00	LF		166.082		153.477		See DWR for details.
			7/23/25	8/1/25	1	336.00	LF		153.899		152.835		See DWR for details.
			7/28/25	8/1/25	1	162.00	LF		152.815		152.798		See DWR for details.
0180	6131015	DOWEL BAR (DRILLING, FURNISHING AND INST	7/21/25	8/1/25	1	94.00	EA		170.200		164.644		See DWR for specific details.
			7/22/25	8/1/25	1	156.00	EA		166.082		153.477		See DWR for details.
			7/23/25	8/1/25	1	145.00	EA		153.899		152.835		See DWR for details.
			7/28/25	8/1/25	1	35.00	EA		152.815		152.815		See DWR for details.
0190	6131017	DOWEL BAR (FURNISH AND INSTALL WITH BASK	7/28/25	8/1/25	1	40.00	EA	EB lane at 152.815	152.815		152.815		See DWR for details.
0200	6131018	TIE BAR (DRILL, FURN & INSTAL) (TYPE L	7/28/25	8/1/25	1	27.00	EA		152.815		152.815		See DWR for details.

Project: JKR0249

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
500	4011231	BIT. PAVEMENT MIXTURE PG58-28H (BP-1)	7/16/25	8/1/25	1	3,440.51	TONS	Eastbound lane 40.592 to 44.972.	40.592		44.972		
			7/18/25	8/1/25	1	3,521.30	TONS	Westbound lane 42.195 to 46.095	42.195		46.095		
			7/21/25	8/1/25	1	191.87	TONS	Eastbound lane 44.972 to 45.136.	44.972		45.136		
			7/22/25	8/1/25	1	3,385.94	TONS	Eastbound lane 45.136 to 48.976.	45.136		48.976		
			7/23/25	8/1/25	1	2,594.23	TONS	Westbound lane 48.976 to 46.095.	48.976		46.095		
			7/24/25	8/1/25	1	3,731.67	TONS	Eastbound passing lane 46.346 to 47.851 Westbound passing lane 47.851 to 46.626.	46.346		47.851		
			7/28/25	8/1/25	1	1,140.09	TONS	Westbound passing lane 46.626 to 46.375. Eastbound Exit and On ramps.	46.626		46.375		
			7/29/25	8/1/25	1	1,191.93	TONS	Westbound Exit&On ramps. Eastbound shoulder 46.053 to 44.688.	46.053		44.688		
			7/30/25	8/1/25	1	1,039.72	TONS	Eastbound shoulder 44.688 to 43.407.	44.688		43.407		
			7/31/25	8/1/25	1	2,355.29	TONS	Eastbound shoulder 43.295 to 40.931. Eastbound shoulder 40.533 to 38.717.	43.295		38.717		
			8/1/25	8/4/25	1	2,421.48	TONS	Eastbound shoulder 38.717 to 34.315	38.717		34.315		
510	4079912	MISC.	7/16/25	8/1/25	1	4,531.00	GAL	Eastbound lane 40.592 to 44.972.	40.592		44.972		
			7/18/25	8/1/25	1	4,772.00	GAL	Westbound lane 42.195 to 46.095	42.195		46.095		
			7/21/25	8/1/25	1	241.00	GAL	Eastbound lane 44.972 to 45.136.	44.972		45.136		
			7/22/25	8/1/25	1	3,422.00	GAL	Eastbound lane 45.136 to 48.976.	45.136		48.976		
			7/23/25	8/1/25	1	4,531.00	GAL	Westbound lane 48.976 to 46.095.	48.976		46.095		
			7/24/25	8/1/25	1	7,375.00	GAL	Eastbound passing lane 46.346 to 47.851 Westbound passing lane 47.851 to 46.626.	46.346		47.851		
			7/28/25	8/1/25	1	506.00	GAL	Westbound passing lane 46.626 to 46.375. Eastbound Exit and On ramps.	46.626		46.375		
			7/29/25	8/1/25	1	2,410.00	GAL	Westbound Exit&On ramps. Eastbound shoulder 46.053 to 44.688.	46.053		44.688		
			7/30/25	8/1/25	1	1,446.00	GAL	Eastbound shoulder 44.688 to 43.407.	44.688		43.407		
			7/31/25	8/1/25	1	4,290.00	GAL	Eastbound shoulder 43.295 to 40.931. Eastbound shoulder 40.533 to 38.717.	43.295		38.717		
			8/1/25	8/4/25	1	3,181.00	GAL	Eastbound shoulder 38.717 to 34.315	38.717		34.315		
640	6181000	MOBILIZATION	8/1/25	8/4/25	1	0.75	LS	Throughout the project.					

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 6/5/2025 Page 8 of 13



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J3P3158	0140	FURN & PLACE CONC MATL FOR	Material		6	Aug 4, 2025	SYSTEM	(\$108,300.00)	
		FULL DEPTH			6	Aug 4, 2025	SYSTEM	\$108,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0140 -	Total						\$0.00	
	0180	DOWEL BAR (DRILLING, FURNISHING AND	Material		6	Aug 4, 2025	SYSTEM	(\$2,687.50)	
		INST			6	Aug 4, 2025	SYSTEM	\$2,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsm7 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0180 -	Total						\$0.00	
	0190	DOWEL BAR (FURNISH AND	Material		6	Aug 4, 2025	SYSTEM	(\$680.00)	
		INSTALL WITH BASK			6	Aug 4, 2025	SYSTEM	\$680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user johnsm7 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0190 -	Total						\$0.00	
	0200	TIE BAR (DRILL, FURN & INSTAL) (TYPE L	Material		6	Aug 4, 2025	SYSTEM	(\$175.50)	
					6	Aug 4, 2025	SYSTEM	\$175.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user johnsm7 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To					\$0.00	
	0200 -		Material - To						
		Total CONSTRUCTION SIGNS	Material - To		2	Jun 2, 2025	SYSTEM	\$0.00 \$0.00 (\$2,450.00)	
		CONSTRUCTION			2		SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		CONSTRUCTION				2025 Jun 2,		\$0.00 \$0.00 (\$2,450.00)	Estimate Item Adjustment (0001) due to user hessec2 overridding Payment
		CONSTRUCTION			2	2025 Jun 2, 2025 Jun 16,	SYSTEM	\$0.00 \$0.00 (\$2,450.00) \$2,450.00	Estimate Item Adjustment (0001) due to user hessec2 overridding Payment
		CONSTRUCTION			3	2025 Jun 2, 2025 Jun 16, 2025 Jun 16,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$2,450.00) \$2,450.00 (\$2,450.00)	Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment
		CONSTRUCTION			3 3	Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jul 1,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$2,450.00) \$2,450.00 (\$2,450.00) \$2,450.00	Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment
		CONSTRUCTION			3 3 4	Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jul 1, 2025 Jul 1,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$2,450.00) \$2,450.00 (\$2,450.00) \$2,450.00	Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment
		CONSTRUCTION			2 3 3 4 4	2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jul 1, 2025 Jul 1, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$2,450.00) \$2,450.00 (\$2,450.00) \$2,450.00 (\$2,450.00)	Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment
		CONSTRUCTION			2 3 3 4 4 5	2025 Jun 2, 2025 Jun 16, 2025 Jul 1, 2025 Jul 1, 2025 Jul 1, 2025 Jul 16, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$2,450.00) \$2,450.00 (\$2,450.00) \$2,450.00 (\$2,450.00) \$2,450.00	Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment
		CONSTRUCTION		otal	2 3 3 4 4 5 5	2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jul 1, 2025 Jul 1, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$2,450.00) \$2,450.00 (\$2,450.00) \$2,450.00 (\$2,450.00) \$2,450.00 (\$2,450.00)	Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment
		CONSTRUCTION			2 3 3 4 4 5 5 6	2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jul 1, 2025 Jul 14, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$2,450.00) \$2,450.00 (\$2,450.00) \$2,450.00 (\$2,450.00) \$2,450.00 (\$2,450.00)	Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate.
		CONSTRUCTION		- Total	2 3 3 4 4 5 5 6	2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jul 1, 2025 Jul 14, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$2,450.00) \$2,450.00 (\$2,450.00) \$2,450.00 (\$2,450.00) \$2,450.00 (\$2,450.00) \$2,450.00 (\$2,450.00)	Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate.
		CONSTRUCTION SIGNS	Material	- Total	2 3 3 4 4 5 5 6	2025 Jun 2, 2025 Jun 16, 2025 Jun 16, 2025 Jul 1, 2025 Jul 14, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$2,450.00) \$2,450.00 (\$2,450.00) \$2,450.00 (\$2,450.00) \$2,450.00 (\$2,450.00) \$2,450.00 \$2,450.00 \$2,450.00	Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user johnsm7 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate.



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J3P3158	0240	WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material		2	Jun 2, 2025	SYSTEM	\$7,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Jun 16, 2025	SYSTEM	(\$7,200.00)	
					3	Jun 16, 2025	SYSTEM	\$7,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user johnsm7 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Jul 1, 2025	SYSTEM	(\$7,200.00)	
					4	Jul 1, 2025	SYSTEM	\$7,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	Jul 16, 2025	SYSTEM	(\$7,200.00)	
					5	Jul 16, 2025	SYSTEM	\$7,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					6	Aug 4, 2025	SYSTEM	(\$7,200.00)	
					6	Aug 4, 2025	SYSTEM	\$7,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user johnsm7 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
1000150	0240 -	Total						\$0.00	
J3P3158 -		DIT DAVEMENT	Matarial		-	Init 40	OVOTEM	\$0.00	
JKR0249	0500	BIT. PAVEMENT MIXTURE PG58-28H (BP-1)	Material		5	Jul 16, 2025	SYSTEM	(\$295,350.53)	
					5	Jul 16, 2025	SYSTEM	\$295,350.53	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	ACAD	5	Jul 16, 2025	hessec2	\$1,077.44	AC Adjustment Line No. 0500 Installed Quantity =
									12,675.80 (tons) @ 3.4% (Virgin) X 2.5 (difference) = \$1,077.44
					6	Aug 4, 2025	johnsm7	\$2,126.19	AC adjustment Line number: 0500 Install quantity: 25014.03 (tons) @3.4% (virgin) * 2.5 (diff) = \$2126.19
				ACAD - Tot				\$3,203.63	
			Other Item	r Item Adjustment - Total				\$3,203.63	
	0500 -				-	1.1.5	0)/0==	\$3,203.63	
	0510	MISC.	Material		5	Jul 16, 2025	SYSTEM	(\$69,768.75)	
					5	Jul 16, 2025	SYSTEM	\$69,768.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Aug 4, 2025	SYSTEM	(\$207,412.50)	
					6	Aug 4, 2025	SYSTEM	\$207,412.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user johnsm7 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00 \$0.00	
			Material - To	Material - Total					
	0510 -							\$0.00	
	0520	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		3	Jun 16, 2025	SYSTEM	(\$115,000.00)	
		I OLL DLF ITI			3	Jun 16, 2025	SYSTEM	\$115,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user johnsm7 overridding Payment Estimate Exception 1 on the current Payment Estimate.



According Acco	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
Aug. Aug. SYSTEM SP43-53.20 The adjustment offsets the original system generated Material Psyment	JKR0249	0520	CONC MATL FOR	Material		4		SYSTEM	(\$254,333.25)	
2025 SV3TEM S347.058.02 SV3TEM S347						4		SYSTEM	\$254,333.25	Estimate Item Adjustment (0003) due to user hessec2 overridding Payment
2005 Section Estimate Est						5		SYSTEM	(\$347,658.25)	
2005						5		SYSTEM	\$347,658.25	Estimate Item Adjustment (0005) due to user hessec2 overridding Payment
Page						6		SYSTEM	(\$347,658.25)	
						6		SYSTEM	\$347,658.25	Estimate Item Adjustment (0008) due to user johnsm7 overridding Payment
					- Total				\$0.00	
				Material - T	otal				\$0.00	
CRILLING, CRIL		0520 -	Total						\$0.00	
NST		0560	(DRILLING,	Material		3		SYSTEM	(\$6,225.00)	
A						3		SYSTEM	\$6,225.00	Estimate Item Adjustment (0004) due to user johnsm7 overridding Payment
2025 Selfmale Item Adjustment (0004) due to user hesses 2 overridding Payment Estimate Exception 4 on the current Payment Estimate Item Adjustment (0006) due to user hesses 2 overridding Payment Estimate Item Adjustment (0006) due to user hesses 2 overridding Payment Estimate Item Adjustment (0006) due to user phrama? Overridding Payment Estimate Exception 6 on the current Payment Estimate Exception 6 on the current Payment Estimate Exception 6 on the current Payment Estimate Exception 7 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 7 on the cu						4		SYSTEM	(\$13,506.25)	
2025 5						4		SYSTEM	\$13,506.25	Estimate Item Adjustment (0004) due to user hessec2 overridding Payment
2025 SYSTEM Estimate Item Adjustment (0006) due to user lesseac2 overidding Payment Estimate Exception 6 on the current Payment Estimate.						5		SYSTEM	(\$18,218.75)	
2025 6						5		SYSTEM	\$18,218.75	Estimate Item Adjustment (0006) due to user hessec2 overridding Payment
Protal So.00 Stimate Exception 7 on the current Payment Estimate Exception 7 on the current Payment Estimate.						6		SYSTEM	(\$18,218.75)	
Solid Soli						6		SYSTEM	\$18,218.75	Estimate Item Adjustment (0009) due to user johnsm7 overridding Payment
Solid Soli					- Total				\$0.00	
Digital Digi				Material - Total					\$0.00	
BIT. MATL FOR CL C PARTIAL		0560 -	Total							
5 Jul 16, 2025 hessec 2 \$35.48 AC Adjustment Line No. 0570 Installed Quantity = 417.40 (tons) @ 3.4% (virgin) X 2.5 (difference) = \$35.48 ACAD - Total \$43.46 Other Item Adjustment - Total \$43.46 0590 CONSTRUCTION SIGNS Material 2 Jun 2, 2025 SYSTEM (\$3,458.00) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 2 on the current Payment Estimate. 3 Jun 16, 2025 SYSTEM (\$3,458.00) This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 3 Jun 16, 2025 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.		0570	BIT. MATL FOR		ment	4		hessec2	\$7.98	Line No. 0570
Line No. 0570 Installed Quantity = 417.40 (tons) @ 3.4% (virgin) X 2.5 (difference) = \$35.48										93.60 (tons) X 2.5 (diff) @ 3.41 (virgin) = \$7.98
ACAD - Total Other Item Adjustment - Total \$43.46 O570 - Total CONSTRUCTION SIGNS Material 2 Jun 2, 2025 2 Jun 2, 2025 3 Jun 16, 2025						5		hessec2	\$35.48	Line No. 0570
Other Item Adjustment - Total S43.46										417.40 (tons) @ 3.4% (virgin) X 2.5 (difference) = \$35.48
System S										
CONSTRUCTION SIGNS A				Other Item Adjustment - Total						
SIGNS 2 Jun 2, 2025 2 Jun 2, 2025 3 Jun 16, 2025 3 Jun 16, 2025 3 Jun 16, 2025 3 Jun 16, 2025 3 SYSTEM \$3,458.00 3 SYSTEM (\$3,458.00) 3 Jun 16, 2025 3 SYSTEM \$3,458.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 3 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user johnsm7 overridding Payment Estimate Exception 7 on the current Payment Estimate.										
Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 2 on the current Payment Estimate. 3 Jun 16, 2025 3 Jun 16, 2025 3 Jun 16, 2025 3 SYSTEM \$3,458.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user johnsm7 overridding Payment Estimate Exception 7 on the current Payment Estimate.				Material			2025		, , , ,	
2025 3 Jun 16, 2025 \$3,458.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user johnsm7 overridding Payment Estimate Exception 7 on the current Payment Estimate.							2025			Estimate Item Adjustment (0003) due to user hessec2 overridding Payment
2025 Estimate Item Adjustment (0005) due to user johnsm7 overridding Payment Estimate Exception 7 on the current Payment Estimate.						3		SYSTEM	(\$3,458.00)	
- Total \$0.00						3		SYSTEM	\$3,458.00	Estimate Item Adjustment (0005) due to user johnsm7 overridding Payment
					- Total				\$0.00	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
JKR0249	0590	CONSTRUCTION SIGNS	Material - To	otal				\$0.00	
	0590 -	Total						\$0.00	
	0630	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material		2	Jun 2, 2025	SYSTEM	(\$9,500.00)	
					2	Jun 2, 2025	SYSTEM	\$9,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Jun 16, 2025	SYSTEM	(\$9,500.00)	
					3	Jun 16, 2025	SYSTEM	\$9,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user johnsm7 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0630 -	Total						\$0.00	
JKR0249	JKR0249 - Total							\$3,247.09	
Overall - Total								\$3,247.09	

MoDOT

Contract Adjustments for Contract - 250314-C01

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 13 of 13