

### Missouri Department of Transportation Contractor's Pay Estimate Summary

### Pay Estimate Created Date: November 17, 2025

Progress Estimate Number 7	Contract ID Prime Contract	250314 <b>or</b> Concre	-D03 te Strategies, LLC		eriod Start eriod End		nber 2, 2025 nber 15, 2025	Original Contract A Net Change Order Current Contract A	Amount	\$3,948,366.99 \$0.00 \$3,948,366.99	
Approval Date										By User	
November 17, 2025			Generated and Approved (and should be considered Draft) at the Project Office Level by								
November 17, 2025			Reviewed and App	proved (a	and should b	e consid	lered Draft) at	the Resident Engineer	Level by	abbote1	
November 18, 2025			Reviewed and Approved at the Central Office Controllers Office Level by								
Original Completi	Original Completion Date Current			Completion Date Actual Completion				% of Current Contr	act Amount	Complete	
October 1, 20	)26	Octol	October 1, 2026					23	23.23%		
	Cont	ract Informa	tional Dates					Mileston	nes		
Date Description	Original Comp	letion Date	Current Completio	n Date		N	No Milestones	Exist for Contract			
Acceptance Date											
Awarded Date	April 2, 2025		April 2, 2025								
Letting Date	March 14, 2025	5	March 14, 2025								
Notice to Proceed Date	May 5, 2025		May 5, 2025								
Work Began Date											

Contract Total Pay F	For Estimate No.	7							
			This Estimate		Previous	То	Date		
250314-D03									
	Total Posted Iter	ns Pay	\$83,010.28		\$834,317.91	\$9	17,328.19		
	Gross Item Adjus	stments	\$0.00		(\$153,515.21)	) (\$^	53,515.21)		
	Incentive		\$0.00		\$0.00	, \$0	\$0.00		
	Disincentive		\$0.00		\$0.00	\$0	\$0.00		
	Liquidated Dama	age	\$0.00		\$0.00	\$0	00		
	Other Contract A	Adjustments	\$0.00		\$0.00	\$0	00		
					\$680,802.70	\$7	63,812.98		
Contract Total Payal	ble This Estimate:		\$83,010.28						
Items Paid This Estin	nate Period								
Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount		

### 

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		nents Exist on Contract nents This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3480B	0030	SHAPING SLOPES, CLASS	Material			-8	\$1,503.96	(\$12,031.68)
	0030	SHAPING SLOPES, CLASS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	8	\$1,503.96	\$12,031.68
	0060	CONCRETE APPROACH PAVEMENT	Material			-83.60000	\$193.64	(\$16,188.30)
	0060	CONCRETE APPROACH PAVEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	83.60000	\$193.64	\$16,188.30
	0070	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material			-2	\$2,685.64	(\$5,371.28)

Revision 10/17/2025 Page 1 of 19



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 17, 2025

Prog Estimate 7	Numbe		314-D03 crete Strategio		Pay Period End November 15, 2025	Net Change Order	iginal Contract Amount t Change Order Amount rrent Contract Amount			
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount		
J5S3480B	0070	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material		This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		\$2,685.64	\$5,371.28		
	0100	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-746	\$0.43	(\$320.78		
	0100	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		\$0.43	\$320.78		
	0110	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-746	\$0.43	(\$320.78)		
	0110	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 19 on the current Payment Estimate.		\$0.43	\$320.78		
	0200	BRIDGE APPROACH SLAB (MAJOR)	Material			-119	\$324.43	(\$38,607.17)		
	0200	BRIDGE APPROACH SLAB (MAJOR)	Material		This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 7 the current Payment Estimate.		\$324.43	\$38,607.17		
	0220	LATEX MODIFIED CONCRETE WEARING SURFACE	Material			-562	\$151.21	(\$84,980.02)		
	0220	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 13 on the current Payment Estimate.		\$151.21	\$84,980.02		
	0260	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material			-32.31000	\$200.00	(\$6,462.00)		
	0260	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		\$200.00	\$6,462.00		
	0300	VERTICAL DRAIN AT END BENTS	Material			-2	\$10,580.30	(\$21,160.60)		
	0300	VERTICAL DRAIN AT END BENTS	Material		This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 2: on the current Payment Estimate.		\$10,580.30	\$21,160.60		
J5S3549	1140	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material			-2	\$2,685.64	(\$5,371.28)		
	1140	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material		This adjustment offsets the original system generated Material Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 1st on the current Payment Estimate.		\$2,685.64	\$5,371.28		

Revision 10/17/2025 Page 2 of 19



## Missouri Department of Transportation Contractor's Pay Estimate Summary

### Pay Estimate Created Date: November 17, 2025

Prog Estimate		Contract ID Prime Contractor				November 2, 2025 November 15, 2025	Net Change Order	Original Contract Amount Net Change Order Amount Current Contract Amount			
Project Number	Line No.	Item Description Adjustment Type Other Item Adjustment Type  Adjustment Type					Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount		
J5S3549	1370	DECK REPAIR WITH VC TUBE REPLACEMENT	OID Material				-1,020.50000	\$200.00	(\$204,100.00)		
	1370	DECK REPAIR WITH VC TUBE REPLACEMENT	DID Material		generated Mater Adjustment (001	offsets the original system ial Payment Estimate It 1) due to user shankb1 ment Estimate Exception ayment Estimate.	em	\$200.00	\$204,100.00		
Total									\$0.00		

Revision 10/17/2025 Page 3 of 19



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Со	ntract Project Informa	tion	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work	
J5S3480B	FAF 28-1(15)	Bridge rehabilitation	28	PULASKI	over I-44 near St. Robert			
J5S3541	FAS S403(51)	Bridge rehabilitation	E	PHELPS	over I-44 in Rolla			
J5S3547	FAS S403(52)	Bridge rehabilitation	CR 8490	PHELPS	over I-44 approximately	2.9 miles west of Doolittle		
J5S3548	FAS S403(53)	Bridge rehabilitation	J	PHELPS	over I-44 approximately	10 miles southwest of Dooli	ttle	
J5S3549	FAS S403(54)	Bridge rehabilitation	D	PHELPS		6.9 miles southwest of Dool	ittle	
J5S3563	FAS S403(71)	Bridge rehabilitation	LP 44	PHELPS	over I-44 in Rolla			
Totals by	y Job Nu	mbers						
J5S3480B		Item Pay tem Adjustme		Item Pay	This Estimate \$0.00 \$0.00 <b>\$0.00</b>	Previous \$418,908.45 (\$24,398.82) \$394,509.63	To Date \$418,908.45 (\$24,398.82) \$394,509.63	
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	
J5S3541	Posted Item Pay Gross Item Adjustments Gross Item Pay Incentive				This Estimate \$0.00 \$0.00 \$0.00 \$0.00	Previous \$14,976.51 \$0.00 \$14,976.51 \$0.00	To Date \$14,976.51 \$0.00 \$14,976.51 \$0.00	
		ntive ted Damages contract Adjus	tments		\$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00	
J5S3547		Item Pay tem Adjustme		Item Pay	This Estimate \$0.00 \$0.00 <b>\$0.00</b>	Previous \$14,555.78 \$14,980.00 \$29,535.78	To Date \$14,555.78 \$14,980.00 \$29,535.78	
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	
J5S3548		Item Pay tem Adjustme		Item Pay	This Estimate \$0.00 \$0.00 <b>\$0.00</b>	Previous \$13,134.09 \$16,807.50 \$29,941.59	To Date \$13,134.09 \$16,807.50 \$29,941.59	
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	
J5S3549		Item Pay tem Adjustme		Item Pay	This Estimate \$83,010.28 \$0.00 \$83,010.28	Previous \$342,176.48 (\$172,787.39) \$169,389.09	To Date \$425,186.76 (\$172,787.39) \$252,399.37	
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	
J5S3563		Item Pay tem Adjustme		Item Pay	This Estimate \$0.00 \$0.00 <b>\$0.00</b>	Previous \$30,566.60 \$11,883.50 \$42,450.10	To Date \$30,566.60 \$11,883.50 \$42,450.10	
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	

Revision 5/29/2025 Page 4 of 19



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5S3480B, Item 2153000, Project Item Line Number 0030, Material Set 215300096, Material 3304AGBS - Aggregate Base JSP, Acceptance Action Generic 3304AGBS is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3480B, Item 5031010A, Project Item Line Number 0200, Material Set 5031010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3480B, Item 5031010A, Project Item Line Number 0200, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3480B, Item 5031010A, Project Item Line Number 0200, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3480B, Item 5031010A, Project Item Line Number 0200, Material Set 5031010A96, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3480B, Item 5031010A, Project Item Line Number 0200, Material Set 5031010A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3480B, Item 5031010A, Project Item Line Number 0200, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3480B, Item 5041000, Project Item Line Number 0060, Material Set 504100096, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3480B, Item 5041000, Project Item Line Number 0060, Material Set 504100096, Material 1057JMTBE28019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3480B, Item 5041000, Project Item Line Number 0060, Material Set 504100096, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3480B, Item 5041000, Project Item Line Number 0060, Material Set 504100096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3480B, Item 5052000, Project Item Line Number 0220, Material Set 505200096, Material 1054CXLE - Latex Emulsion Admixture @, Acceptance Action Generic 1054CXLE is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3480B, Item 5052000, Project Item Line Number 0220, Material Set 505200096, Material 0505CCLATX - Bridge Deck Concrete, Latex, Acceptance Action Generic 0505CCLATX is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3480B, Item 6161098A, Project Item Line Number 0070, Material Set 6161098A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3549, Item 6161098A, Project Item Line Number 1140, Material Set 6161098A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3480B, Item 6206000C, Project Item Line Number 0100, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3480B, Item 6206000C, Project Item Line Number 0100, Material Set 6206000C96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3480B, Item 6206001C, Project Item Line Number 0110, Material Set 6206001C96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3480B, Item 6206001C, Project Item Line Number 0110, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3480B, Item 7040112, Project Item Line Number 0260, Material Set 704011296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3549, Item 7040112, Project Item Line Number 1370, Material Set 704011296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3480B, Item 7151001, Project Item Line Number 0300, Material Set 715100196, Material 0715DRVT - Vertical Drain at End Bents, Acceptance Action Generic 0715DRVT is insufficient.	QCQA Data	shankb1	Overridden
Estimate Exception Type: Item Overrun: Contract 250314-D03, Contract Project J5S3480B, Project Item Line Number 0210, Contract Line Item Number 0210, Item 5050004, Minor Item.	Pending Change Order	shankb1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 250314-D03, Contract Project J5S3549, Project Item Line Number 1350, Contract Line Item Number 1350, Item 7040104, Minor Item.	Pending Change Order	shankb1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 250314-D03, Contract Project J5S3549, Project Item	Pending Change Order	shankb1	Acknowledged

Revision 5/29/2025 Page 5 of 19



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Line Number 1370, Contract Line Item Number 1370, Item 7040112, Minor Item.			
Estimate Exception Type: Item Overrun: Contract 250314-D03, Contract Project J5S3480B, Project Item Line Number 0040, Contract Line Item Number 0040, Item 4011209, Minor Item.	Pending Change Order	shankb1	Acknowledged

Revision 5/29/2025 Page 6 of 19



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Project	Category	Line	Item	on Report Generated date and can differ from the poster	Bid	Net	Total	Unit	Total	Unit Price	Total Value POST
No.	Category	No.	Code	резацион	Quantity	Change Order	Current Quantity	Offic	Posted Approved Qty	Onit Frice	To Date (See re generated dat
J5S3480E	0001	0010	1081000	SIGNET DBE REPORTING	1.00	0.00	1.00	LS	0.00	\$1,000.00	:
	0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$19,624.63	\$19,6
	0001	0030	2153000	SHAPING SLOPES, CLASS III	8.00	0.00	8.00	100F	8.00	\$1,503.96	\$12,0
	0001	0040	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	30.20	0.00	30.20	TONS	35.30	\$353.42	\$12,4
	0001	0050	4071005	TACK COAT	28.00	0.00	28.00	GAL	0.00	\$3.49	
	0001	0060	5041000	CONCRETE APPROACH PAVEMENT	83.60	0.00	83.60	SQYD	83.60	\$193.64	\$16,1
	0001	0070	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	2.00	0.00	2.00	EA	2.00	\$2,685.64	\$5,3
	0001	0080	6169901	MISC.LUMP SUM TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	1.00	\$19,699.20	\$19,69
	0001	0090	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.37	\$130,516.46	\$47,7
	0001	0100	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	746.00	0.00	746.00	LF	746.00	\$0.43	\$33
	0001	0110	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	746.00	0.00	746.00	LF	746.00	\$0.43	\$3
	0001	0120	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	279.00	0.00	279.00	SQYD	279.00	\$11.43	\$3,1
	0010	0130	6061060	MGS GUARDRAIL	450.00	0.00	450.00	LF	450.00	\$30.08	\$13,53
	0010	0140	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$4,511.88	\$18,04
	0010	0150	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	2.00	\$1,987.37	\$3,97
	0010	0160	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	2.00	\$4,135.89	\$8,2
	0070	0170	2161001	TOTAL SURFACE HYDRO DEMOLITION	562.00	0.00	562.00	SQYD	562.00	\$39.44	\$22,16
	0070	0180	2161502	REMOVAL OF CONCRETE WEARING SURFACE	5,058.00	0.00	5,058.00	SQFT	5,058.00	\$3.51	\$17,75
	0070	0190	2161503	REMOVAL OF EXISTING DECK REPAIR	125.00	0.00	125.00	SQFT	0.00	\$33.26	
	0070	0200	5031010A	BRIDGE APPROACH SLAB (MAJOR)	119.00	0.00	119.00	SQYD	119.00	\$324.43	\$38,60
	0070	0210	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	2.00	0.00	2.00	CUYD	24.60	\$1,000.00	\$24,60
	0070	0220	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	562.00	0.00	562.00	SQYD	562.00	\$151.21	\$84,98
	0070	0230	7031004	DIAMOND GRINDING	562.00	0.00	562.00	SQYD	0.00	\$15.29	\$
	0070	0240	7040104	HALF-SOLE REPAIR	800.00	0.00	800.00	SQFT	222.75	\$88.50	\$19,7
	0070	0250	7040106	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$291.00	
	0070	0260	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	250.00	0.00	250.00	SQFT	32.31	\$200.00	\$6,46
	0070	0270	7040113	CLEANING AND EPOXY COATING	1,809.00	0.00	1,809.00	SQFT	0.00	\$11.84	\$
	0070	0280	7049902	MISC.CORE VOID TUBE WEEP HOLES	72.00	0.00	72.00	EA	72.00	\$36.75	\$2,64
	0070	0290	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$15,497.33	
	0070	0300	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$10,580.30	\$21,1
Project J	5S3480B - To	otal Value	e Posted to I	Date as of Report Generated Date							\$418,9
J5S3541	0001	0310	6123001	TRUCK MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	LS	0.00	\$9,668.31	
	0001	0320	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	2.00	0.00	2.00	EA	0.00	\$1,611.39	:
	0001	0330	6169901	MISC.LUMP SUM TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$15,622.39	\$7,8
	0001	0340	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.10	\$69,566.16	\$7,16
	0070	0350	2169904	MISC.PARTIAL REMOVAL OF EXISTING SIDEWALK	819.00	0.00	819.00	SQFT	0.00	\$114.91	
	0070	0360	7040107	SLAB EDGE REPAIR (BRIDGES)	150.00	0.00	150.00	LF	0.00	\$349.66	
	0070	0370	7040113	CLEANING AND EPOXY COATING	2,331.00	0.00	2,331.00	SQFT	0.00	\$11.84	
	0070	0380	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$15,497.33	\$
	_	al Value	Posted to Da	ite as of Report Generated Date							\$14,9
Project J	0001	0390	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$3,222.77	
Project J J5S3547		0400	2079901	MISC.RESTORE SLOPE	1.00	0.00	1.00	LS	0.00	\$12,725.49	;
	0001				5.00	0.00	5.00	100F	0.00	\$1,503.96	;
	0001	0410	2153000	SHAPING SLOPES, CLASS III					0.00	\$410.58	:
	0001		2153000 4011209	SHAPING SLOPES, CLASS III  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	22.90	0.00	22.90	TONS	0.00		
	0001 0001 0001	0410				0.00	22.90	TONS	0.00	\$3.49	:
	0001 0001 0001 0001	0410 0420	4011209 4071005	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	22.90						
	0001 0001 0001 0001 0001	0410 0420 0430	4011209 4071005	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT	22.90 21.00	0.00	21.00	GAL	0.00	\$3.49	
	0001 0001 0001 0001 0001	0410 0420 0430 0440	4011209 4071005 6096010A	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT FURNISHING TYPE 1 ROCK DITCH LINER	22.90 21.00 24.00	0.00	21.00 24.00	GAL CUYD	0.00	\$3.49 \$124.10	
	0001 0001 0001 0001 0001 0001	0410 0420 0430 0440 0450	4011209 4071005 6096010A 6096041	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT FURNISHING TYPE 1 ROCK DITCH LINER PLACING TYPE 1 ROCK DITCH LINER	22.90 21.00 24.00 24.00	0.00 0.00 0.00	21.00 24.00 24.00	GAL CUYD CUYD	0.00 0.00 0.00	\$3.49 \$124.10 \$119.74	:
	0001 0001 0001 0001 0001	0410 0420 0430 0440 0450 0460	4011209 4071005 6096010A 6096041 6123001	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  TACK COAT  FURNISHING TYPE 1 ROCK DITCH LINER  PLACING TYPE 1 ROCK DITCH LINER  TRUCK MOUNTED ATTENUATOR (TMA)  CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	22.90 21.00 24.00 24.00 1.00	0.00 0.00 0.00 0.00	21.00 24.00 24.00 1.00	GAL CUYD CUYD LS	0.00 0.00 0.00 0.00	\$3.49 \$124.10 \$119.74 \$14,502.47	\$ \$
	0001 0001 0001 0001 0001 0001	0410 0420 0430 0440 0450 0460 0470	4011209 4071005 6096010A 6096041 6123001 6161098A	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  TACK COAT  FURNISHING TYPE 1 ROCK DITCH LINER  PLACING TYPE 1 ROCK DITCH LINER  TRUCK MOUNTED ATTENUATOR (TMA)  CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	22.90 21.00 24.00 24.00 1.00 2.00	0.00 0.00 0.00 0.00 0.00	21.00 24.00 24.00 1.00 2.00	GAL CUYD CUYD LS EA	0.00 0.00 0.00 0.00 0.00	\$3.49 \$124.10 \$119.74 \$14,502.47 \$2,417.08	\$

Revision 5/29/2025 Page 7 of 19



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

0	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change	Total Current	Unit	Total Posted	Unit Price	Total Value POSTED To Date (See report
	5S3547						Order	Quantity		Approved Qty		generated date)
		0001	0510	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	211.00	0.00	211.00	SQYD	0.00	\$15.11	\$0.0
		0001	0520	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	104.00	0.00	104.00	SQYD	0.00	\$5.27	\$0.0
		0001	0530	8061016	SEDIMENT REMOVAL	4.00	0.00	4.00	CUYD	0.00	\$341.90	\$0.0
		0001	0540	8061019	SILT FENCE	440.00	0.00	440.00	LF	0.00	\$4.30	\$0.0
		0010	0550	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	0.00	\$4,511.88	\$0.0
		0010	0560	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	0.00	\$4,189.60	\$0.0
		0070	0570	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	20.00	0.00	20.00	SQFT	0.00	\$322.28	\$0.0
		0070	0580	2161001	TOTAL SURFACE HYDRO DEMOLITION	646.00	0.00	646.00	SQYD	0.00	\$39.44	\$0.0
		0070	0590	2161500	REMOVAL OF SEAL COAT OR POLYMER WEARING SURFACE	5,817.00	0.00	5,817.00	SQFT	0.00	\$3.12	\$0.0
		0070	0600	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	0.00	100.00	SQFT	0.00	\$33.26	\$0.0
		0070	0610	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	5.00	0.00	5.00	CUYD	0.00	\$1,000.00	\$0.0
		0070	0620	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	646.00	0.00	646.00	SQYD	0.00	\$151.21	\$0.0
		0070	0630	7031004	DIAMOND GRINDING	646.00	0.00	646.00	SQYD	0.00	\$15.29	\$0.0
		0070	0640	7034600	CURB BLOCKOUT	438.00	0.00	438.00	LF	0.00	\$125.54	\$0.0
		0070	0650	7040104	HALF-SOLE REPAIR	800.00	0.00	800.00	SQFT	0.00	\$88.50	\$0.0
		0070	0660	7040104	DECK REPAIR WITH VOID TUBE REPLACEMENT	50.00	0.00	50.00	SQFT	0.00	\$200.00	\$0.0
		0070										
		0070	0670	7040113	CLEANING AND EPOXY COATING	1,719.00	0.00	1,719.00	SQFT	0.00	\$11.84	\$0.0
		0070	0680	7049902	MISC.CORED VOID TUBE WEEP HOLES	236.00	0.00	236.00	EA	0.00	\$36.75	\$0.0
		0070	0690	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$15,497.33	\$0.0
					te as of Report Generated Date							\$14,555.7
J5	5S3548	0001	0700	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$5,371.28	\$0.0
		0001	0710	2079901	MISC.RESTORE SLOPE	1.00	0.00	1.00	LS	0.00	\$12,725.49	\$0.0
		0001	0720	2153000	SHAPING SLOPES, CLASS III	6.00	0.00	6.00	100F	0.00	\$1,503.96	\$0.0
		0001	0730	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	77.40	0.00	77.40	TONS	0.00	\$226.66	\$0.0
		0001	0740	4071005	TACK COAT	72.00	0.00	72.00	GAL	0.00	\$3.49	\$0.0
		0001	0750	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	6.00	0.00	6.00	CUYD	0.00	\$496.40	\$0.0
		0001	0760	6096041	PLACING TYPE 1 ROCK DITCH LINER	6.00	0.00	6.00	CUYD	0.00	\$119.74	\$0.0
		0001	0770	6123001	TRUCK MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	LS	0.00	\$12,085.39	\$0.0
		0001	0780	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	2.00	0.00	2.00	EA	0.00	\$2,148.51	\$0.0
		0001	0790	6169901	MISC.LUMP SUM TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.00	\$19,380.94	\$0.0
		0001	0800	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.12	\$105,072.72	\$13,134.0
		0001	0810	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	792.00	0.00	792.00	LF	0.00	\$0.43	\$0.0
		0001	0820	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	792.00	0.00	792.00	LF	0.00	\$0.43	\$0.0
		0001	0830	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	715.00	0.00	715.00	SQYD	0.00	\$5.08	\$0.
		0001	0840	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	29.00	0.00	29.00	SQYD	0.00	\$5.27	\$0.0
		0001	0850	8061016	SEDIMENT REMOVAL	5.00	0.00	5.00	CUYD	0.00	\$341.90	\$0.0
		0001	0860	8061019	SILT FENCE	515.00	0.00	515.00	LF	0.00	\$4.30	\$0.
		0010	0870	6061060	MGS GUARDRAIL	125.00	0.00	125.00	LF	0.00	\$30.08	\$0.
		0010	0880	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	0.00	\$4,511.88	\$0.
		0010	0890	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	0.00	\$4,082.18	\$0.
		0070	0900	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	18.00	0.00	18.00	SQFT	0.00	\$322.28	\$0.
		0070	0910	2161001	TOTAL SURFACE HYDRO DEMOLITION	580.00	0.00	580.00	SQYD	0.00	\$39.44	\$0.
		0070	0920	2161500	REMOVAL OF SEAL COAT OR POLYMER WEARING SURFACE	5,222.00	0.00	5,222.00	SQFT	0.00	\$3.41	\$0.
		0070	0930	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	0.00	100.00	SQFT	0.00	\$33.26	\$0.
		0070	0940	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	5.00	0.00	5.00	CUYD	0.00	\$1,000.00	\$0.
		0070	0950	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	580.00	0.00	580.00	SQYD	0.00	\$151.21	\$0.
		0070	0960	7031004	DIAMOND GRINDING	580.00	0.00	580.00	SQYD	0.00	\$15.29	\$0.
		0070	0970	7034600	CURB BLOCKOUT	395.00	0.00	395.00	LF	0.00	\$128.42	\$0.
		0070	0980	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	40.00	0.00	40.00	SQFT	0.00	\$157.58	\$0.
		0070	0990	7040102	HALF-SOLE REPAIR	100.00	0.00	100.00	SQFT	0.00	\$88.50	\$0.
		0070	1000	7040104	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$291.00	\$0.
		0070	1010	7040100	DECK REPAIR WITH VOID TUBE REPLACEMENT	50.00	0.00	50.00	SQFT	0.00	\$291.00	\$0.
			1010	7040112	DEGRACIA AIN WITH VOID TODE REPLACEIVENT	30.00	0.00	30.00	SQFT	0.00	ΨΖ00.00	φυ.ι

Revision 5/29/2025 Page 8 of 19



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Jaieu Que	intities and	Values	are based	on Report Generated date and can differ from the poster	amount :	at the tim	e me Esmi	ale was	Generaleu.		
Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
J5S3548	0070	1030	7049902	MISC.CORED VOID TUBE WEEP HOLES	258.00	0.00	258.00	EA	0.00	\$36.75	\$0.
	0070	1040	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$15,497.33	\$0.
	0070	1050	7172054	OPEN CELL FOAM JOINT SEAL	76.00	0.00	76.00	LF	0.00	\$51.29	\$0
Project J	5S3548 - Tot	al Value	Posted to Da	ite as of Report Generated Date							\$13,134
J5S3549	0001	1060	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$15,576.72	\$0.
	0001	1070	2079901	MISC.RESTORE SLOPE	1.00	0.00	1.00	LS	0.00	\$12,725.49	\$0
	0001	1080	2153000	SHAPING SLOPES, CLASS III	19.00	0.00	19.00	100F	0.00	\$1,503.96	\$0
	0001	1090	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	140.60	0.00	140.60	TONS	0.00	\$220.36	\$0
	0001	1100	4071005	TACK COAT	130.00	0.00	130.00	GAL	0.00	\$3.49	\$0
	0001	1110	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	8.00	0.00	8.00	CUYD	0.00	\$372.30	\$0
	0001	1120	6096041	PLACING TYPE 1 ROCK DITCH LINER	8.00	0.00	8.00	CUYD	0.00	\$119.74	\$0
	0001	1130	6123001	TRUCK MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	LS	1.00	\$16,919.54	\$16,919.
	0001	1140	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	2.00	0.00	2.00	EA	2.00	\$2,685.64	\$5,371.
	0001	1150	6169901	MISC.LUMP SUM TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$19,323.21	\$9,661
	0001	1160	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$134,756.94	\$134,756
	0001	1170	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	854.00	0.00	854.00	LF	0.00	\$0.43	\$0.
	0001	1180	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	995.00	0.00	995.00	LF	0.00	\$0.43	\$0.
	0001	1190	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,299.00	0.00	1,299.00	SQYD	0.00	\$2.24	\$0.
	0001	1200	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	32.00	0.00	32.00	SQYD	0.00	\$5.27	\$0.
	0001	1210	8061016	SEDIMENT REMOVAL	18.00	0.00	18.00	CUYD	0.00	\$341.90	\$0.
	0001	1220	8061019	SILT FENCE	1,695.00	0.00	1,695.00	LF	0.00	\$4.30	\$0.
	0010	1230	6061060	MGS GUARDRAIL	1,488.00	0.00	1,488.00	LF	0.00	\$30.08	\$0.
	0010	1240	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	0.00	\$4,511.88	\$0.
	0010	1250	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	0.00	\$2,255.94	\$0
	0010	1260	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	3.00	0.00	3.00	EA	0.00	\$4,135.89	\$0
	0070	1270	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	18.00	0.00	18.00	SQFT	14.40	\$322.28	\$4,640
	0070	1280	2161001	TOTAL SURFACE HYDRO DEMOLITION	668.00	0.00	668.00	SQYD	0.00	\$39.44	\$0
	0070	1290	2161500	REMOVAL OF SEAL COAT OR POLYMER WEARING SURFACE	6,015.00	0.00	6,015.00	SQFT	6,015.00	\$3.04	\$18,285
	0070	1300	2161503	REMOVAL OF EXISTING DECK REPAIR	150.00	0.00	150.00	SQFT	0.00	\$33.26	\$0
	0070	1310	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	10.00	0.00	10.00	CUYD	0.00	\$1,000.00	\$0
	0070	1320	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	668.00	0.00	668.00	SQYD	0.00	\$151.21	\$0
	0070	1330	7031004	DIAMOND GRINDING	668.00	0.00	668.00	SQYD	0.00	\$15.29	\$0
	0070	1340	7034600	CURB BLOCKOUT	424.00	0.00	424.00	LF	0.00	\$127.09	\$0
	0070	1350	7040104	HALF-SOLE REPAIR	100.00	0.00	100.00	SQFT	260.70	\$88.50	\$23,071
	0070	1360	7040106	FULL DEPTH REPAIR  DECK REPAIR WITH VOID TUBE REPLACEMENT	100.00	0.00	100.00	SQFT	0.00	\$291.00	\$0.
	0070	1370	7040112		50.00	0.00	50.00	SQFT	1,020.50	\$200.00	\$204,100
	0070	1380	7040113	CLEANING AND EPOXY COATING  MISC.CORED VOID TUBE WEEP HOLES	1,727.00	0.00	1,727.00	SQFT	0.00	\$11.84	\$0.
	0070	1390	7049902 7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	228.00 1.00	0.00	1.00	EA LS	228.00 0.00	\$36.75 \$15,497.33	\$8,379 \$0
	0070	1410	7172054	(EPOXY)  OPEN CELL FOAM JOINT SEAL	80.00	0.00	80.00	LF	0.00	\$51.29	\$0
Project J		al Value	Posted to Da	nte as of Report Generated Date							\$425,186
J5S3563	0001	1420	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	0.00	\$9,980.24	\$0.
	0001	1430	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$63,522.97	\$0.
	0001	1440	2153000	SHAPING SLOPES, CLASS III	3.00	0.00	3.00	100F	0.00	\$1,503.96	\$0
	0001	1450	5041000	CONCRETE APPROACH PAVEMENT	235.00	0.00	235.00	SQYD	0.00	\$193.64	\$0
	0001	1453	6122008	IMPACT ATTENUATOR 40 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	0.00	\$2,148.51	\$0
	0001	1455	6122020	REPLACEMENT SAND BARREL	5.00	0.00	5.00	EA	0.00	\$214.85	\$0
	0001	1457	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	0.00	2.00	EA	0.00	\$1,074.26	\$0
	0001	1460	6123001	TRUCK MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	LS	0.00	\$38,673.24	\$0
	0001	1470	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	4.00	0.00	4.00	EA	0.00	\$5,371.28	\$0
	0001	1480	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.00	\$21,240.77	\$0
	0001	1490	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED /	500.00	0.00	500.00	LF	0.00	\$21.48	\$0.
	0001			RETAINED				LF			

Revision 5/29/2025 Page 9 of 19



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ntract ID	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See report generated date)
	J5S3563	0001	1510	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.11	\$272,916.06	\$30,566.
3		0001	1520	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	21.00	0.00	21.00	EA	0.00	\$32.23	\$0.
		0001	1530	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	1,138.00	0.00	1,138.00	LF	0.00	\$2.68	\$0.
		0001	1540	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	1,111.00	0.00	1,111.00	LF	0.00	\$2.68	\$0.
		0001	1550	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,216.00	0.00	2,216.00	LF	0.00	\$0.43	\$0.
		0001	1560	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,217.00	0.00	1,217.00	LF	0.00	\$0.43	\$0.
		0001	1570	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	18.00	0.00	18.00	LF	0.00	\$19.34	\$0.
		0001	1580	6206125A	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	65.00	0.00	65.00	LF	0.00	\$19.34	\$0.
		0001	1590	6207001	PAVEMENT MARKING REMOVAL	2,249.00	0.00	2,249.00	LF	0.00	\$0.54	\$0.
		0001	1600	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$0.00	\$0.
		0001	1610	8051000A	SEEDING - COOL SEASON GRASSES	1.00	0.00	1.00	ACRE	0.00	\$8,594.05	\$0.
		0001	1620	8061016	SEDIMENT REMOVAL	6.00	0.00	6.00	CUYD	0.00	\$341.90	\$0.
		0001	1630	8061019	SILT FENCE	525.00	0.00	525.00	LF	0.00	\$4.30	\$0
		0010	1640	6061010	GUARDRAIL TYPE A	32.00	0.00	32.00	LF	0.00	\$30.08	\$0
		0010	1650	6061060	MGS GUARDRAIL	25.00	0.00	25.00	LF	0.00	\$38.67	\$0
		0010	1660	6061070	MGS VERTICAL CONCRETE BARRIER TRANSITION	2.00	0.00	2.00	EA	0.00	\$4,511.88	\$0
		0010	1670	6062200A	BRIDGE ANCHOR SECTION, 6.5 FT. POSTS (SAFETY BARRIER CURB) (ROADWAY AND REHABILITATION WORK ONLY)	1.00	0.00	1.00	EA	0.00	\$3,437.62	\$0
		0010	1680	6062303	ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS	1.00	0.00	1.00	EA	0.00	\$1,289.11	\$0
		0010	1690	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	3.00	0.00	3.00	EA	0.00	\$4,135.89	\$0
		0070	1700	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,240.00	0.00	1,240.00	SQYD	0.00	\$39.44	\$0
		0070	1710	2161501	REMOVAL OF ASPHALT WEARING SURFACE	11,158.00	0.00	11,158.00	SQFT	0.00	\$2.12	\$0
		0070	1720	2161503	REMOVAL OF EXISTING DECK REPAIR	165.00	0.00	165.00	SQFT	0.00	\$33.26	\$1
		0070	1730	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	5.00	0.00	5.00	LF	0.00	\$769.02	\$
		0070	1740	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	252.00	0.00	252.00	SQYD	0.00	\$296.16	\$1
		0070	1750	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	1.00	0.00	1.00	CUYD	0.00	\$1,000.00	\$1
		0070	1760	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,240.00	0.00	1,240.00	SQYD	0.00	\$151.21	\$
		0070	1770	7031004	DIAMOND GRINDING	1,240.00	0.00	1,240.00	SQYD	0.00	\$15.29	\$
		0070	1780	7039903	MISC.TYPE B BARRIER (TAPERED)	40.00	0.00	40.00	LF	0.00	\$287.68	\$
		0070	1790	7040101	SUBSTRUCTURE REPAIR (FORMED)	25.00	0.00	25.00	SQFT	0.00	\$204.79	\$1
		0070	1800	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	25.00	0.00	25.00	SQFT	0.00	\$157.58	\$1
		0070	1810	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	100.00	0.00	100.00	SQFT	0.00	\$214.95	\$1
		0070	1820	7040104	HALF-SOLE REPAIR	1,450.00	0.00	1,450.00	SQFT	0.00	\$88.50	\$i
		0070	1830	7040106	FULL DEPTH REPAIR	50.00	0.00	50.00	SQFT	0.00	\$291.00	\$
		0070	1840	7040107	SLAB EDGE REPAIR (BRIDGES)	100.00	0.00	100.00	LF	0.00	\$349.66	\$
		0070	1850	7040107	DECK REPAIR WITH VOID TUBE REPLACEMENT	50.00	0.00	50.00	SQFT	0.00	\$200.00	\$
		0070	1860	7040112	CLEANING AND EPOXY COATING	2.200.00	0.00	2,200.00	SQFT	0.00	\$200.00	\$
		0070	1870	7049113	MISC.CORED VOID TUBE WEEP HOLES	712.00	0.00	712.00	EA	0.00	\$36.75	\$
		0070	1880	7049902	MISC.CURB REPAIR	100.00	0.00	100.00	LF	0.00	\$132.92	
		0070	1890	7049903	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$132.92 \$15,497.33	\$(
		2562 - <del>T</del>	al Valerani	and a data B	(EPOXY) te as of Report Generated Date							\$30,56

Revision 5/29/2025 Page 10 of 19



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5S3549

Line Number	Item Code	Description			Posting Sequence No.					Offset/ Distance		
1160	6181000	MOBILIZATION	11/15/25	11/17/25	1	0.62	LS	Mob Payment	.1			

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 6/5/2025 Page 11 of 19



State	Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
SLOPES, CLASS   III	5,000				Adjustment					
6	J5S3480B	0030	SLOPES, CLASS	Material		6		SYSTEM	(\$12,031.68)	
2025   7   Nov 17,   SYSTEM   \$12,031.68   This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate Estimate Exception 1 on the current			111			6		SYSTEM	\$12,031.68	Estimate Item Adjustment (0001) due to user shankb1 overridding Payment
2025   Estimate Item Adjustment (001) due to user shankth overridding Payment						7		SYSTEM	(\$12,031.68)	
Material - Total   \$0.00						7		SYSTEM	\$12,031.68	Estimate Item Adjustment (0001) due to user shankb1 overridding Payment
Solid   Soli					- Total				\$0.00	
Doct				Material - To	tal				\$0.00	
MIXTURE PG64-22   Adjustment   2025		0030	- Total						\$0.00	
Content   Cont		0040	MIXTURE PG64-22		ACAD	6		shankb1	\$3.62	(513.75-511.25) x 0.041 x 35.3 = \$3.62
Overrun   Overrun   6					ACAD - Tot	al			\$3.62	
Overrun - Total   (\$1,802.44)				Other Item A	djustment - T	otal			\$3.62	
Overrun - Total   (\$1,802.44)						6		SYSTEM	(\$1,802.44)	
CONCRETE APPROACH PAVEMENT   Material   S					Overrun - T	otal			(\$1,802.44)	
O060 CONCRETE APPROACH PAVEMENT    Sociation   System   Side   System   System				Overrun - To	tal				(\$1,802.44)	
APPROACH PAVEMENT  2025  5 Oct 16, 2025  \$16,188.30  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  6 Nov 3, 2025  6 Nov 3, 2025  7 Nov 17, 2025  7 Nov 17, 2025  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  7 Nov 17, 2025  This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment (0002) due to user shankb1 overridding Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		0040	- Total						(\$1,798.82)	
5 Oct 16, SYSTEM 2025 SYSTEM \$16,188.30 This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate.  6 Nov 3, 2025 SYSTEM (\$16,188.30)  6 Nov 3, 2025 SYSTEM \$16,188.30 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  7 Nov 17, 2025 SYSTEM (\$16,188.30)  7 Nov 17, 2025 SYSTEM \$16,188.30 This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		0060	APPROACH	Material		5		SYSTEM	(\$16,188.30)	
2025  6 Nov 3, 2025  8 16,188.30 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  7 Nov 17, 2025  7 Nov 17, 2025  8 16,188.30 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  - Total						5		SYSTEM	\$16,188.30	Estimate Item Adjustment (0001) due to user shankb1 overridding Payment
2025 Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  7 Nov 17, 2025 (\$16,188.30)  7 Nov 17, 2025 \$16,188.30 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  - Total \$0.00						6		SYSTEM	(\$16,188.30)	
2025 7 Nov 17, 2025 \$16,188.30 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  - Total \$0.00						6		SYSTEM	\$16,188.30	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment
2025 Estimate Item Adjustment (0002) dué to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  - Total \$0.00						7		SYSTEM	(\$16,188.30)	
						7		SYSTEM	\$16,188.30	Estimate Item Adjustment (0002) due to user shankb1 overridding Payment
Material - Total \$0.00					- Total				\$0.00	
				Material - To	tal				\$0.00	
0060 - Total \$0.00		0060	- Total						\$0.00	
0070 CHANGEABLE Material 1 Aug 18, SYSTEM (\$5,371.28) MESSAGE SIGN WITHOUT 2025		0070	MESSAGE SIGN	Material		1		SYSTEM	(\$5,371.28)	
COMMUNICATION 1 Aug 18, SYSTEM 55,371.28 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			COMMUNICATION INTERFACE, CONTRACTOR			1	Aug 18, 2025	SYSTEM	\$5,371.28	Estimate Item Adjustment (0001) due to user shankb1 overridding Payment
FURNISHED / RETAINED 2 Sep 2, 2025 SYSTEM (\$5,371.28)						2		SYSTEM	(\$5,371.28)	
2 Sep 2, 2025 SYSTEM \$5,371.28 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						2		SYSTEM	\$5,371.28	Estimate Item Adjustment (0001) due to user shankb1 overridding Payment
3 Sep 16, SYSTEM (\$5,371.28)						3		SYSTEM	(\$5,371.28)	
3 Sep 16, 2025 SYSTEM \$5,371.28 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						3		SYSTEM	\$5,371.28	Estimate Item Adjustment (0001) due to user shankb1 overridding Payment
4 Oct 2, 2025 SYSTEM (\$5,371.28)						4		SYSTEM	(\$5,371.28)	
4 Oct 2, 2025 SYSTEM \$5,371.28 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.						4		SYSTEM	\$5,371.28	Estimate Item Adjustment (0001) due to user shankb1 overridding Payment
5 Oct 16, 2025 SYSTEM (\$5,371.28)						5		SYSTEM	(\$5,371.28)	
5 Oct 16, 2025 \$SYSTEM \$5,371.28 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment						5		SYSTEM	\$5,371.28	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
S3480B	0070	CHANGEABLE MESSAGE SIGN	Material						Estimate Exception 13 on the current Payment Estimate.
		WITHOUT COMMUNICATION			6	Nov 3, 2025	SYSTEM	(\$5,371.28)	
		INTERFACE, CONTRACTOR FURNISHED / RETAINED			6	Nov 3, 2025	SYSTEM	\$5,371.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Nov 17, 2025	SYSTEM	(\$5,371.28)	
					7	Nov 17, 2025	SYSTEM	\$5,371.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0070 -	Total						\$0.00	
	0100	4 IN. WHITE WATERBORNE	Material		6	Nov 3, 2025	SYSTEM	(\$320.78)	
		PAVEMENT MARKING			6	Nov 3, 2025	SYSTEM	\$320.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					7	Nov 17, 2025	SYSTEM	(\$320.78)	
					7	Nov 17, 2025	SYSTEM	\$320.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0100 -	Total						\$0.00	
	0110 4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		6	Nov 3, 2025	SYSTEM	(\$320.78)		
					6	Nov 3, 2025	SYSTEM	\$320.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					7	Nov 17, 2025	SYSTEM	(\$320.78)	
					7	Nov 17, 2025	SYSTEM	\$320.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0110 -	Total						\$0.00	
	0130	MGS GUARDRAIL	Construction Stockpile		6	Nov 3, 2025	SYSTEM	(\$6,579.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$6,579.00)	
			Construction	Stockpile - 1	Γotal			(\$6,579.00)	
			Construction Stockpile STMA		3	Sep 16, 2025	SYSTEM	\$6,579.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$6,579.00	
			Construction	Stockpile S	TMA - Tota	al		\$6,579.00	
	0130 -	Total						\$0.00	
	0140	APP. TRANS SEC	Construction Stockpile		3	Sep 16, 2025	SYSTEM	\$7,580.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		(REG/NO CURB)			6	Nov 3, 2025	SYSTEM	(\$7,580.00) \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total					
			Construction	Stockpile - 1	Total			\$0.00	
	0140 -							\$0.00	
	0150	MGS END ANCHOR	Construction Stockpile		3	Sep 16, 2025	SYSTEM	\$1,300.00	Payment Estimate Item Adjustment generated Stockpile Transaction
					6	Nov 3, 2025	SYSTEM	(\$1,300.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$0.00	



5S3480B	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
	0150	MGS END ANCHOR	Construction	Stockpile - 1	Γotal			\$0.00	
	0150 -	Total						\$0.00	
	0160	TYPE A CRASHWORTHY	Construction Stockpile		3	Sep 16, 2025	SYSTEM	\$3,700.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		END TERMINAL (MASH)			6	Nov 3, 2025	SYSTEM	(\$3,700.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$0.00	
			Construction	Stockpile - 1	Γotal			\$0.00	
	0160 -	Total						\$0.00	
	0200	APPROACH SLAB	Material		5	Oct 16, 2025	SYSTEM	(\$38,607.17)	
		(MAJOR ROAD)			5	Oct 16, 2025	SYSTEM	\$38,607.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Nov 3, 2025	SYSTEM	(\$38,607.17)	
					6	Nov 3, 2025	SYSTEM	\$38,607.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					7	Nov 17, 2025	SYSTEM	(\$38,607.17)	
					7	Nov 17, 2025	SYSTEM	\$38,607.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0200 -	- Total						\$0.00	
	V S	SUPPLEMENTARY WEARING SURFACE	Overrun	Overrun	4	Oct 2, 2025	SYSTEM	(\$22,600.00)	
		MATERIAL		Overrun - T	otal			(\$22,600.00)	
			Overrun - To	tal				(\$22,600.00)	
	0210 -	Total						(\$00.000.00)	
		LATEX MODIFIED CONCRETE WEARING	Material					(\$22,600.00)	
		CONCRETE	Material		4	Oct 2, 2025	SYSTEM	(\$22,600.00)	
			Material		4		SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		CONCRETE WEARING	Material			2025 Oct 2,		(\$84,980.02)	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment
		CONCRETE WEARING	Material		4	2025 Oct 2, 2025 Oct 16,	SYSTEM	(\$84,980.02) \$84,980.02	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment
		CONCRETE WEARING	Material		5	2025 Oct 2, 2025 Oct 16, 2025 Oct 16,	SYSTEM	(\$84,980.02) \$84,980.02 (\$84,980.02)	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment
		CONCRETE WEARING	Material		5	2025 Oct 2, 2025 Oct 16, 2025 Oct 16, 2025 Nov 3,	SYSTEM SYSTEM	(\$84,980.02) \$84,980.02 (\$84,980.02) \$84,980.02	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment
		CONCRETE WEARING	Material		<ul><li>4</li><li>5</li><li>5</li><li>6</li></ul>	2025 Oct 2, 2025 Oct 16, 2025 Oct 16, 2025 Nov 3, 2025 Nov 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$84,980.02) \$84,980.02 (\$84,980.02) \$84,980.02	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment
		CONCRETE WEARING	Material		<ul><li>4</li><li>5</li><li>5</li><li>6</li><li>6</li></ul>	2025 Oct 2, 2025 Oct 16, 2025 Oct 16, 2025 Nov 3, 2025 Nov 3, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$84,980.02) \$84,980.02 (\$84,980.02) \$84,980.02 (\$84,980.02) \$84,980.02	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment
		CONCRETE WEARING	Material	- Total	<ul><li>4</li><li>5</li><li>5</li><li>6</li><li>6</li><li>7</li></ul>	2025 Oct 2, 2025 Oct 16, 2025 Oct 16, 2025 Nov 3, 2025 Nov 3, 2025 Nov 17, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$84,980.02) \$84,980.02 (\$84,980.02) \$84,980.02 (\$84,980.02) \$84,980.02	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 13 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment
		CONCRETE WEARING	Material - To		<ul><li>4</li><li>5</li><li>5</li><li>6</li><li>6</li><li>7</li></ul>	2025 Oct 2, 2025 Oct 16, 2025 Oct 16, 2025 Nov 3, 2025 Nov 3, 2025 Nov 17, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$84,980.02) \$84,980.02 (\$84,980.02) \$84,980.02 (\$84,980.02) \$84,980.02 (\$84,980.02)	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 13 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment
	0220 -	CONCRETE WEARING SURFACE			<ul><li>4</li><li>5</li><li>5</li><li>6</li><li>6</li><li>7</li></ul>	2025 Oct 2, 2025 Oct 16, 2025 Oct 16, 2025 Nov 3, 2025 Nov 3, 2025 Nov 17, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$84,980.02) \$84,980.02 (\$84,980.02) \$84,980.02 (\$84,980.02) \$84,980.02 (\$84,980.02) \$84,980.02	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 13 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment
	<b>0220</b> - 0260	CONCRETE WEARING SURFACE  Total  DECK REPAIR WITH VOID TUBE			<ul><li>4</li><li>5</li><li>5</li><li>6</li><li>6</li><li>7</li></ul>	2025 Oct 2, 2025 Oct 16, 2025 Oct 16, 2025 Nov 3, 2025 Nov 3, 2025 Nov 17, 2025	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$84,980.02) \$84,980.02 (\$84,980.02) \$84,980.02 (\$84,980.02) \$84,980.02 (\$84,980.02) \$84,980.02	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 13 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment
		CONCRETE WEARING SURFACE  Total DECK REPAIR	Material - To		4 5 5 6 6 7 7	2025 Oct 2, 2025 Oct 16, 2025 Oct 16, 2025 Nov 3, 2025 Nov 3, 2025 Nov 17, 2025 Nov 17, 2025 Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$84,980.02) \$84,980.02 (\$84,980.02) \$84,980.02 (\$84,980.02) \$84,980.02 (\$84,980.02) \$84,980.02	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 13 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3480B	0260	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		4	Oct 2, 2025	SYSTEM	\$6,462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Oct 16, 2025	SYSTEM	(\$6,462.00)	
					5	Oct 16, 2025	SYSTEM	\$6,462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					6	Nov 3, 2025	SYSTEM	(\$6,462.00)	
					6	Nov 3, 2025	SYSTEM	\$6,462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user shankb1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					7	Nov 17, 2025	SYSTEM	(\$6,462.00)	
					7	Nov 17, 2025	SYSTEM	\$6,462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot					\$0.00	
	0260	- Total	material - 10					\$0.00	
		VERTICAL DRAIN AT END BENTS	Material		5	Oct 16, 2025	SYSTEM	(\$21,160.60)	
		AT END BENTS			5	Oct 16, 2025	SYSTEM	\$21,160.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					6	Nov 3, 2025	SYSTEM	(\$21,160.60)	
					6	Nov 3, 2025	SYSTEM	\$21,160.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user shankb1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					7	Nov 17, 2025	SYSTEM	(\$21,160.60)	
					7	Nov 17, 2025	SYSTEM	\$21,160.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0300	Total						\$0.00	
J5S3480B	- Total							(\$24,398.82)	
J5S3547	0550	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile		3	Sep 16, 2025	SYSTEM	\$7,580.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$7,580.00	
			Construction	Stockpile - 1	Total			\$7,580.00	
	0550	Total						\$7,580.00	
	0560	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		3	Sep 16, 2025	SYSTEM	\$7,400.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)		- Total				\$7,400.00	
			Construction	Stockpile - 1	Γotal			\$7,400.00	
	0560	Total						\$7,400.00	
J5S3547 - 1	Total							\$14,980.00	
J5S3548	0870	MGS GUARDRAIL	Construction Stockpile		3	Sep 16, 2025	SYSTEM	\$1,827.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$1,827.50	
			Construction	Stockpile - 1	otal			\$1,827.50	
	0870	Total						\$1,827.50	
	0880	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile		3	Sep 16, 2025	SYSTEM	\$7,580.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		,,		- Total				\$7,580.00	
			Construction	Stockpile - 1	Total			\$7,580.00	
	0880	Total						\$7,580.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3548	0890	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile	,,	3	Sep 16, 2025	SYSTEM	\$7,400.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)		- Total				\$7,400.00	
			Construction	Stockpile - 1	Γotal			\$7,400.00	
	0890 -	- Total						\$7,400.00	
J5S3548 - 1	Total							\$16,807.50	
J5S3549	1140	CHANGEABLE MESSAGE SIGN WITHOUT	Material		1	Aug 18, 2025	SYSTEM	(\$5,371.28)	
		COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED			1	Aug 18, 2025	SYSTEM	\$5,371.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Sep 2, 2025	SYSTEM	(\$5,371.28)	
					2	Sep 2, 2025	SYSTEM	\$5,371.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Sep 16, 2025	SYSTEM	(\$5,371.28)	
					3	Sep 16, 2025	SYSTEM	\$5,371.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Oct 2, 2025	SYSTEM	(\$5,371.28)	
					4	Oct 2, 2025	SYSTEM	\$5,371.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Oct 16, 2025	SYSTEM	(\$5,371.28)	
					5	Oct 16, 2025	SYSTEM	\$5,371.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					6	Nov 3, 2025	SYSTEM	(\$5,371.28)	
					6	Nov 3, 2025	SYSTEM	\$5,371.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Nov 17, 2025	SYSTEM	(\$5,371.28)	
					7	Nov 17, 2025	SYSTEM	\$5,371.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	al				\$0.00	
	1140 -	Total						\$0.00	
	1230	MGS GUARDRAIL	Construction Stockpile		3	Sep 16, 2025	SYSTEM	\$21,754.56	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$21,754.56	
			Construction	Stockpile - 1	otal			\$21,754.56	
		Total						\$21,754.56	
	1240	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile		3	Sep 16, 2025	SYSTEM	\$7,580.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		,	O made to	- Total				\$7,580.00	
	4040	Tatal	Construction	Stockpile - 1	otal			\$7,580.00	
		MGS END	Canatinatia		2	Can 40	CVCTER	\$7,580.00	Downsont Februarie Hom Adjustment was sent of Otto India Torrest in
	1250	ANCHOR	Construction Stockpile	- Total	3	Sep 16, 2025	SYSTEM	\$650.00 \$650.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	Stockpile - 1	Total			\$650.00	
	1250	- Total	Construction	- Stockpile - I	otal			\$650.00	
		TYPE A CRASHWORTHY	Construction Stockpile		3	Sep 16, 2025	SYSTEM	\$5,550.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		END TERMINAL (MASH)	i i i	- Total				\$5,550.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3549	1260	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction	Stockpile -	Γotal			\$5,550.00	
	1260 -	- Total						\$5,550.00	
	1350	HALF-SOLE REPAIR	Overrun	Overrun	3	Sep 16, 2025	SYSTEM	(\$1,770.00)	
					4	Oct 2, 2025	SYSTEM	(\$12,451.95)	
				Overrun - T	otal			(\$14,221.95)	
			Overrun - To	tal				(\$14,221.95)	
	1350 -	- Total						(\$14,221.95)	
	1370	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		3	Sep 16, 2025	SYSTEM	(\$84,000.00)	
					3	Sep 16, 2025	SYSTEM	\$84,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user shankb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Oct 2, 2025	SYSTEM	(\$204,100.00)	
					4	Oct 2, 2025	SYSTEM	\$204,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Oct 16, 2025	SYSTEM	(\$204,100.00)	
					5	Oct 16, 2025	SYSTEM	\$204,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					6	Nov 3, 2025	SYSTEM	(\$204,100.00)	
					6	Nov 3, 2025	SYSTEM	\$204,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user shankb1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					7	Nov 17, 2025	SYSTEM	(\$204,100.00)	
					7	Nov 17, 2025	SYSTEM	\$204,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
			Overrun	Overrun	3	Sep 16, 2025	SYSTEM	(\$74,000.00)	
					4	Oct 2, 2025	SYSTEM	(\$120,100.00)	
				Overrun - T	otal			(\$194,100.00)	
			Overrun - To	tal				(\$194,100.00)	
		- Total						(\$194,100.00)	
J5S3549 - 1							21/2==:	(\$172,787.39)	
J5S3563	1640	GUARDRAIL TYPE A	Construction Stockpile	Total	3	Sep 16, 2025	SYSTEM	\$524.80	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	- Total	Fotal			\$524.80	
	40.0	<b>T</b> -4-1	Construction	Stockpile -	rotal			\$524.80	
		- Total	0 1 ::		0	0- 15	OVOT-:	\$524.80	December 1 September 1 September 1 September 2 Septemb
	1650	MGS GUARDRAIL	Construction Stockpile	Total	3	Sep 16, 2025	SYSTEM	\$365.50	Payment Estimate Item Adjustment generated Stockpile Transaction
			O. made ti	- Total				\$365.50	
			Construction	Stockpile - 1	otal			\$365.50	
		- Total					0)/0==	\$365.50	
	1660	CONCRETE BARRIER	Construction Stockpile		3	Sep 16, 2025	SYSTEM	\$3,943.20	Payment Estimate Item Adjustment generated Stockpile Transaction
		TRANSITION		- Total				\$3,943.20	
			Construction	Stockpile -	Total			\$3,943.20	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3563	1660 -	Total						\$3,943.20	
	1670	BRIDGE ANCHOR SECTION, 6 5 FT.	Construction Stockpile		3	Sep 16, 2025	SYSTEM	\$1,315.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		POSTS		- Total				\$1,315.00	
			Construction	Stockpile - 1	otal .			\$1,315.00	
	1670 -	Total						\$1,315.00	
	1680	ASYMMETRICAL TRNS. SEC., 6.5 FT. POSTS	Construction Stockpile		3	Sep 16, 2025	SYSTEM	\$185.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$185.00	
			Construction	Stockpile - 1	「otal			\$185.00	
	1680 -	Total						\$185.00	
	1690	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		3	Sep 16, 2025	SYSTEM	\$5,550.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$5,550.00	
			Construction	Stockpile - 1	otal			\$5,550.00	
	1690 -	Total						\$5,550.00	
J5S3563 -	Total							\$11,883.50	
Overall - T	otal							(\$153,515.21)	

# MoDOT

## Contract Adjustments for Contract - 250314-D03

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 19 of 19