

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 3, 2025

Progress Estimate Number 4	Contract ID Prime Contrac		616-C03 er, Inc.	Pay Period Pay Period		September 16, September 30,		Original Contract Amount Net Change Order Amount Current Contract Amount	\$12,288,356.43 \$13,340.25 \$12,301,696.68
Approval Date									By User
October 3, 2025	October 3, 2025 Generated and Approved (and should be considered Draft) at the Project Office Lev								sandis1
October 3, 2025	3, 2025 Reviewed and Approved (and should be considered Draft) at the Resident Engineer Lev								sandis1
October 3, 2025					Revi	ewed and Approved	at the Ce	ntral Office Controllers Office Level by	ramses1
Original Completi	Current C	Completio	on Date	Α	nt Complete				
November 1, 2	2026	Nove	mber 1, 2	026	27.36%				
	Cor	ntract Informa	ational Da	ates				Milestones	
Date Description	Original Com	pletion Date	Current	Completion	Date		No Miles	tones Exist for Contract	
Acceptance Date									
Awarded Date	June 5, 2025		June 5,	2025					
Letting Date	May 16, 2025		May 16,	2025					
Notice to Proceed Date	July 7, 2025		July 7, 2	2025					
Work Began Date									

Contract Total Pa	ay For Estimate No. 4			
		This Estimate	Previous	To Date
250516-C03				
	Total Posted Items Pay	\$1,514,193.70	\$1,851,185.85	\$3,365,379.55
	Gross Item Adjustments	(\$527.00)	(\$2,505.00)	(\$3,032.00)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$1,848,680.85	\$3,362,347.55
Contract Total Pa	avable This Estimate:	\$1.513.666.70		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4S3412	0010	1081000	SIGNET DBE REPORTING	LS	\$1,000.000	1	\$1,000.00
	0090	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	100F	\$506.000	14	\$7,084.00
	0100	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$24.250	297	\$7,202.25
	0110	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$20.650	1,458	\$30,107.70
	0210	6049902	MISC.DROP INLET CLEANOUT	EA	\$259.000	3	\$777.00
	0220	6049902	MISC.REPLACE STORM LID	EA	\$1,800.000	8	\$14,400.00
	0270	6085008	PAVED APPROACH, 8 IN.	SQYD	\$104.000	346	\$35,984.00
	0290	6091051	CURB AND GUTTER TYPE A	LF	\$38.000	764	\$29,032.00
	0390	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)	EA	\$671.000	24	\$16,104.00
	0420	6161025	CHANNELIZER (TRIM-LINE)	EA	\$17.000	109	\$1,853.00
	0490	6181000	MOBILIZATION	LS	\$904,639.140	0.250	\$226,159.79
	0580	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	LF	\$0.130	47,400	\$6,162.00
	0600	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$139,600.000	0.400	\$55,840.00
	0690	4039905	MISC.12.5 INCHES, ASPHALTIC CONCRETE PAVEMENT	SQYD	\$54.800	19,690.200	\$1,079,022.96
	5001	6161070	TUBULAR MARKER	EA	\$173.250	20	\$3,465.00

 Project J4S3412 - Total
 \$1,514,193.70

 Overall - Total
 \$1,514,193.70

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	ine Item Adjustments This Estimate												
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount					
J4S3412	0100	TYPE 5 AGGREGATE FOR	Material			-450	\$24.25	(\$10,912.50)					

Revision 9/2/2025 Page 1 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 3, 2025

Pro Estimat	gress e Numl 4		250516-C03 Ideker, Inc.	Pay Period Pay Period		Net Char	Contract Amour nge Order Amou Contract Amoun	nt	\$12,288,356.43 \$13,340.25 \$12,301,696.68
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
4S3412		BASE (4 IN. THICK)							
	0100	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original generated Material Payment Estima Adjustment (0001) due to user sand overridding Payment Estimate Except the current Payment Estimate.	ate Item dis1	450	\$24.25	\$10,912.50
	0110	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material				-14,282.02600	\$20.65	(\$294,923.84)
	0110	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original generated Material Payment Estima Adjustment (0002) due to user sand overridding Payment Estimate Except the current Payment Estimate.	ate Item dis1	14,282.02600	\$20.65	\$294,923.84
	0270	PAVED APPROACH, 8 IN.	Material				-499	\$104.00	(\$51,896.00
	0270	PAVED APPROACH, 8 IN.	Material		This adjustment offsets the original generated Material Payment Estima Adjustment (0003) due to user sand overridding Payment Estimate Except the current Payment Estimate.	ate Item dis1	499	\$104.00	\$51,896.00
	0290	CURB AND GUTTER TYPE A	Material				-5,177	\$38.00	(\$196,726.00)
	0290	CURB AND GUTTER TYPE A	Material		This adjustment offsets the original generated Material Payment Estima Adjustment (0004) due to user sand overridding Payment Estimate Exceon the current Payment Estimate.	até Item dis1	5,177	\$38.00	\$196,726.00
	0390	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)	Material				-24	\$671.00	(\$16,104.00)
	0390	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)	Material		This adjustment offsets the original generated Material Payment Estima Adjustment (0005) due to user sand overridding Payment Estimate Exceon the current Payment Estimate.	ate Item dis1	24	\$671.00	\$16,104.00
	0400	CONSTRUCTION SIGNS	Material				-967.75000	\$6.50	(\$6,290.38)
	0400	CONSTRUCTION SIGNS	Material		This adjustment offsets the original generated Material Payment Estima Adjustment (0006) due to user sand overridding Payment Estimate Exceon the current Payment Estimate.	ate Item dis1	967.75000	\$6.50	\$6,290.38
	0420	CHANNELIZER (TRIM-LINE)	Material				-251	\$17.00	(\$4,267.00
	0420	CHANNELIZER (TRIM-LINE)	Material		This adjustment offsets the original generated Material Payment Estima Adjustment (0008) due to user sand overridding Payment Estimate Exceon the current Payment Estimate.	ate Item dis1	251	\$17.00	\$4,267.00
	0420	CHANNELIZER (TRIM-LINE)	Overrun				-31	\$17.00	(\$527.00)
	0430	TYPE 3 MOVEABLE BARRICADE	Material				-84	\$125.00	(\$10,500.00)
	0430	TYPE 3 MOVEABLE BARRICADE	Material		This adjustment offsets the original generated Material Payment Estima Adjustment (0009) due to user sand overridding Payment Estimate Exceon the current Payment Estimate.	ate Item dis1	84	\$125.00	\$10,500.00
	0440	DIRECTION INDICATOR BARRICADE	Material				-24	\$65.00	(\$1,560.00)
	0440	DIRECTION INDICATOR BARRICADE	Material		This adjustment offsets the original generated Material Payment Estima Adjustment (0010) due to user sand overridding Payment Estimate Exceon the current Payment Estimate.	ate Item dis1	24	\$65.00	\$1,560.00
	0450	FLASHING ARROW PANEL	Material				-2	\$3,500.00	(\$7,000.00)

Revision 9/2/2025 Page 2 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 3, 2025

Estimat	gress e Numl 4	Contract ID ber Prime Contractor	250516-C03 Ideker, Inc.	Pay Period Pay Period		September 16, 2025 September 30, 2025	Net Char	Contract Amour nge Order Amou Contract Amoun	nt	\$12,288,356.43 \$13,340.25 \$12,301,696.68
Project umber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type		Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
S3412	0450	FLASHING ARROW PANEL	Material		generate Adjustm overridd	ustment offsets the original ed Material Payment Estima ent (0011) due to user sand ing Payment Estimate Exce urrent Payment Estimate.	ate Item dis1	2	\$3,500.00	\$7,000.00
	0460	SEQUENTIAL FLASHING WARNING LIGHT	Material					-24	\$85.00	(\$2,040.00)
	0460	SEQUENTIAL FLASHING WARNING LIGHT	Material		generate Adjustm overridd	ustment offsets the original ed Material Payment Estima ent (0012) due to user sand ing Payment Estimate Exce urrent Payment Estimate.	ate Item dis1	24	\$85.00	\$2,040.00
	0470	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material					-2	\$4,000.00	(\$8,000.00)
	0470	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	Material		generate Adjustm overridd	ustment offsets the original ed Material Payment Estima ent (0013) due to user sand ing Payment Estimate Exce urrent Payment Estimate.	até Item dis1	2	\$4,000.00	\$8,000.00
	0480	MISC.	Material					-17	\$70.00	(\$1,190.00)
	0480	MISC.	Material		generate Adjustm overridd	ustment offsets the original ed Material Payment Estima ent (0014) due to user sand ing Payment Estimate Exce urrent Payment Estimate.	ate Item lis1	17	\$70.00	\$1,190.00
	0690	MISC.	Material					-19,690.20000	\$54.80	(\$1,079,022.96)
	0690	MISC.	Material		generate Adjustm overridd	ustment offsets the original ed Material Payment Estima ent (0015) due to user sand ing Payment Estimate Exce ent Payment Estimate.	ate Item lis1	19,690.20000	\$54.80	\$1,079,022.96
	5001	TUBULAR MARKER	Material					-20	\$173.25	(\$3,465.00)
	5001	TUBULAR MARKER	Material		generate Adjustm overridd	ustment offsets the original ed Material Payment Estima ent (0016) due to user sand ing Payment Estimate Exce urrent Payment Estimate.	ate Item dis1	20	\$173.25	\$3,465.00
tal										(\$527.00)

Revision 9/2/2025 Page 3 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Co	ntract Project Informa	ition
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4S3412	FAS S303(54)	Reconstruct pavement and ADA improvements	1	CLAY	from NE 72nd Street to NE	44th Street in Gladstone	
Totals b	oy Job N	umbers					
J4S3412		d Item Pay Item Adjustme		tem Pay	This Estimate \$1,514,193.70 (\$527.00) \$1,513,666.70	Previous \$1,851,185.85 (\$2,505.00) \$1,848,680.85	To Date \$3,365,379.55 (\$3,032.00) \$3,362,347.55
	Liquid	tive entive lated Damages Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 5/29/2025 Page 4 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exception Tore Insufficient Macries (Porting 455/12) and 555/12 an	Exceptions (Discrepancies) This Estimate Period			
Names of 100, Automatic Set 380,000,000,000,000,000,000,000,000,000,	Exceptions / Discrepencies	Explanation		Status
Number Offo, Mearria Set 30400506, Mearria Children 1150° - Companied Type 7 & 5 Base. Companies About Process Charles (1994) - Companied Type 7 & 5 Base. Companies About Process Charles (1994) - Companied Type 7 & 5 Base. Companies About Process Charles (1994) - Companied Type 150°	Number 0100, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5	Working with the contractor to resolve this exception.	sandis1	Overridden
Number Of 19. Material Set 300500000, Natural 1007. ACRESTITS - Age Base T ITTS Rectamed Control. Acceptance Action Generic 1007. ACRESTITS - Age Base T ITTS Rectamed Control. Acceptance Action Generic 2007. ACRESTITS - AND STATE OF THE ACTION OF THE ACRESTITS - ACCEPTANCE A	Number 0100, Material Set 304050496, Material 0304SBT15KP - Compacted Type 1 & 5 Base,	Working with the contractor to resolve this exception.	sandis1	Overridden
Namber 0209, Material Set 400905968, Material DidSSP290CLS - Superpase 25.0 nim, Des C. Low Grins, Acceptance Action Centeria Applies in Studionaria. Editionate Cooption Type: Insufficient Materials: Popies 4253412, Bern 8085008, Project Bern Line Editionate Cooption Type: Insufficient Materials: Popies 4253412, Bern 8085008, Project Bern Line Working with the contractor to resolve this exception. Sanda1 Overridden Namber 2027, Materials de 40860086, Material 05510-CPCADL Des 15 materials of 1500-CPCADL Des 15 materials of 1500-CPC	Number 0110, Material Set 304050696, Material 1007RCBT1T5 - Agg Base T1/T5 Reclaimed	Working with the contractor to resolve this exception.	sandis1	Overridden
Number CDT, Material Set (6800008, Mainral 1005A-CCAS-CCAS-CA - Natural Sand for Cone Class A, Acceptance Action Generic 1005A-CCAS-CAS in sizedificant Nationals Project JASS412, Item 60000008, Project Item Line Revision of the Cone Class A, Acceptance Action Generic 1005A-CCAS-CAS-CAS-CAS-CAS-CAS-CAS-CAS-CAS-C	Number 0690, Material Set 403990596, Material 0403SP250CLG - Superpave 25.0 mm, Des C Low	Working with the contractor to resolve this exception.	sandis1	Overridden
Number 0270, Material Set 08800086, Material S0101.CPCALLD - POCTO Pr. Misrority "I Max. LSDO. Acceptance Action Center 100510.CPCALD is insufficient. Eliminate Exception Type: Insufficient Materials. Project 4385412, tlem 0895008, Project titem Line Number 0270. Materials 240000086, Materials 20000407.CPCACACA in Insufficient. Eliminate Exception Type: Insufficient Materials. Project 4385412, tlem 0895008, Project titem Line Number 0270. Materials 20000607. Project Titem Line Number 0270. Materials S0000086, Materials 5000047, Titem 5005008, Project titem Line Number 0270. Materials S0000866, Materials 5000047, Titem 5005008, Project titem Line Number 0270. Materials S0000866, Materials 5000047, Titem 5005008, Project titem Line Number 0270. Materials 50000866, Materials 5000047, Titem 5005008, Project titem Line Number 0270. Materials 50000866, Materials 5000047, Titem 5005008, Project titem Line Number 0270. Materials 5000047, Titem 5005008, Project titem Line Number 0270. Materials 5000047, Titem 5005008, Project titem Line Number 0270. Materials 5000047, Titem 5005008, Project titem Line Number 0270. Materials 5000047, Titem 5005008, Project titem Line Number 0270. Materials 5000047, Titem 5005008, Project titem Line Number 0270. Material 5000047, Titem 5005008, Project titem Line Number 0270. Material 5000047, Titem 5005008, Project titem Line Number 0270. Material 5000047, Titem 5000008, Project titem Line Number 02700, Material 5000047, Number 1000047, Titem 5000000000000000000000000000000000000	Number 0270, Material Set 608500896, Material 1005FACCNSCA - Natural Sand for Conc Class A,	Working with the contractor to resolve this exception.	sandis1	Overridden
Number 0270, Material Set 80980888, Material 80910CPARCOA - Conrote, Perment contractor mix or COCOA, Acceptance Action Generic 10010CPARCOA is sufficient. Elitimate Exception Type: Insufficient Materials: Project JASS412, Item 6085008, Project Item Line Number 0270, Material Set 80850088, Material 1055CMMLDST2 visite Parameter Bridge Dissipating Curre gi, Acceptance Action Generic 1005CMMLDST2 is insufficient. Elitimate Exception Type: Insufficient Materials: Project JASS412, Item 6085008, Project Item Line Number 0270, Material 35 et 80850088, Material 1057AMTSE-42016 - The Bur Ep Ctd 30" No. 5Aft 0 GOMMA098, Acceptance Action Generic 1005CMMLDST3 in sufficient. Elitimate Exception Type: Insufficient Materials: Project JASS412, Item 6085008, Project Item Line Number 0270, Material 1057AMTSE-42016 - The Bur Ep Ctd 30" No. 5Aft 0 GOMMA098, Acceptance Action Generic 1005AMTSE-6706, Material 1057AMTSE-42016 - The Bur Ep Ctd 30" No. 5Aft 0 GOMMA098, Acceptance Action Generic 1005AMTSE-6706, Material 1050100, Project Item Line Number 02708, Material 105100, CPCMLD in Profest Member 1054AMTSE-1054AMTS	Number 0270, Material Set 608500896, Material 100510. CPCMLD - PCCP or Masonry 1" Max LS/DO,	Working with the contractor to resolve this exception.	sandis1	Overridden
Number 0270, Material Set 069800986, Material 055CMMLDST2 - white Pawment-Bridge Dissipating Cure (§). Acceptance Action Generic 1055CMMLDST3 is unufficient. Elaminate Exception Type: Insufficient Materials: Project 4553412, ltem 6085008, Project Item Line Number 0270, Material 55CMMLDST3 is performed Fiber 55CMMLDST3 in COVERNOR (1997). Elaminate Exception Type: Insufficient Materials: Project 4553412, ltem 6085008, Project Item Line Number 0270, Material Set 06000086, Material 1057AMFRPF. Preformed Fiber Expension Joint Matt (2). Acceptance Action Generic 1057AMFRPF is number 0270, Material Set 06000086, Material 1057AMFRPF. Preformed Fiber Expension Joint Matt (2). Acceptance Action Generic 1057AMFRPF is number 0270, Material Set 06000086, Material 1057AMFRPF is number 0270, Material Set 06000086, Material 1057AMFRPF is number 0270. Material Set 06000086, Material 1057AMFRPF is number 0270, Material Set 060000870, material 1057AMFRPF is number 0270, Material Set 060000870, Material Set 0610000870, Institution of 16000000000000000000000000000000000000	Number 0270, Material Set 608500896, Material 0501CCPAQCQA - Concrete, Payment contractor mix	Working with the contractor to resolve this exception.	sandis1	Overridden
Number 0270, Material Set 080500980, Material 1057.MRTB42010 - Tre Barr Ep Ctd 30° No. Shift 0 Gr GMA200, Acceptance Action Generic Refundros/philose in sufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 608000, Project Item Line Number 0270, Material Set 080500980, Material 1057.MRTPR is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6081001, Project Item Line Number 0290, Material Set 080500980, Material 1057.MRTPR is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 608101651, Project Item Line Number 0290, Material Set 0801016918, Material 105610.CPCALD - PCCP or Masonry 1° Max LS/DO. Acceptance Action Generic 10057.CPCALD is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 608101651, Project Item Line Number 0290, Material Set 0801016918, Material 1055CMMLDST1D is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 608101651, Project Item Line Number 0290, Material Set 0801016918, Material 1055CMMLDST1D is Insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6081051, Project Item Line Number 0290, Material Set 0801016918, Material 1055CMMLDST1D is Insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6181055, Project Item Line Number 0390, Material Set 0801016918, Material 1055CMMLDST1D is Insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6181055, Project Item Line Number 0390, Material Set 6181016918, Material 0614DFXTCV - Curved Varie Grate and Frame, Acceptance Action Generic 0618CMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6181005, Project Item Line Number 0400, Material Set 6181016968, Material 0614TMTC - Temporary Traffic Centrol Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6181005, Project	Number 0270, Material Set 608500896, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating	Working with the contractor to resolve this exception.	sandis1	Overridden
Number 0270, Material Set 608500896, Material 1057MFRPF - Preformed Fiber Expansion Joint Matl A. Acceptance Action Generic 0157MFRPF is insufficient. Estimate Exception Type: Insufficient Materials: Project, J453412, Item 6091051, Project Item Line Number 0290, Material Set 609105166, Material 1050510, OPCMLD - PCCP or Masonry 1* Max LS/DO, Acceptance Action Generic 1050510. CPCMLD - Is insufficient. Estimate Exception Type: Insufficient Materials: Project, J453412, Item 6091051, Project Item Line Number 0290, Material Set 609105166, Material 10565ACCNS, CA - Natural Sand for Conc Class A. Acceptance Action Generic 10565ACCNS, CA - Natural Sand for Conc Class A. Acceptance Action Generic 10565ACCNS, CA - Natural Sand for Conc Class A. Acceptance Action Generic 10565ACCNS, CA - Natural Sand for Conc Class A. Description Type: Insufficient Materials: Project, J453412, Item 6091051, Project Item Line Number 2090, Material Set 609105166, Material 1056ACCNS, CA - Standard Set 609105166, Material 1056ACCNS, CA - Standard Set 609105166, Material 1056ACCNS, CA - Concrete, Class B W/RI, Acceptance Action Generic 1056ACCNS, As insufficient. Estimate Exception Type: Insufficient Materials: Project J453412, Item 6991051, Project Item Line Number 2090, Material Set 6910506A As insufficient. Estimate Exception Type: Insufficient Materials: Project J453412, Item 691051, Project Item Line Number 2090, Material Set 61910506A Material 0510FCS. A: Concrete, Class B W/RI, Acceptance Action Generic 0510FCTO's Insufficient Estimate Exception Type: Insufficient Materials: Project J453412, Item 619105, Project Item Line Number 2090, Material Set 619102506, Material 0510FCTO's Insufficient Estimate Exception Type: Insufficient Materials: Project J453412, Item 619105, Project Item Line Number 0420, Material Set 619102506, Material 0510FMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J453412, Item 6191030, Project Item Line Numb	Number 0270, Material Set 608500896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr	Working with the contractor to resolve this exception.	sandis1	Overridden
Number 0290, Material Set 609105196, Material 105510, CPCMLD - PCCP or Masoriny 1" Max LS/DO, Acceptance Action Generic 105051, CPCMLD is insufficient. Estimate Exception Type: Insufficient Materials: Project JAS3412, Item 6091051, Project Item Line Number 0200, Material Set 609105196, Material Society LAS3412, Item 6091051, Project Item Line Number 0200, Material Set 609105196, Material Society LAS3412, Item 6091051, Project Item Line Number 0200, Material Set 609105196, Material Society LAS3412, Item 6091051, Project Item Line Number 0200, Material Set 609105196, Material Society LAS3412, Item 6091051, Project Item Line Number 0200, Material Set 609105196, Material Society LAS3412, Item 6091051, Project Item Line Number 0200, Material Set 609105196, Material Set 60910596, Mate	Number 0270, Material Set 608500896, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl	Working with the contractor to resolve this exception.	sandis1	Overridden
Number 0290, Material Set 609105196, Material 1005FACONS. CA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACONS. CA is insufficient. Estimate Exception Type: Insufficient Materials: Project JAS3412, Item 6091051, Project Item Line Number 0200, Material Set 609105196, Material Set 61910596, Material Set 61910796, Ma	Number 0290, Material Set 609105196, Material 100510. CPCMLD - PCCP or Masonry 1" Max LS/DO,	Working with the contractor to resolve this exception.	sandis1	Overridden
Number 0290, Material Set 609105196, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure (@). Acceptance Action Generic 0155CMMLDST1D is insufficient. Estimate Exception Type: Insufficient Materials: Project JAS3412, Item 619105, Project Item Line Number 0290, Material Set 609105196, Material 05010CS. A Concrete, Class B w/Air, Acceptance Action Generic 05010CS. A. in insufficient. Estimate Exception Type: Insufficient Materials: Project JAS3412, Item 619105, Project Item Line Number 0390, Material Set 61410296, Material 05410FGTCV - Curved Vane Grate and Frame, Acceptance Action Generic 0510FGTCV is insufficient. Estimate Exception Type: Insufficient Materials: Project JAS3412, Item 619105, Project Item Line Number 0400, Material Set 616100596, Material 0516TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project JAS3412, Item 6161025, Project Item Line Number 0420, Material Set 616102596, Material 0516TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0516TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project JAS3412, Item 6161032, Project Item Line Number 0420, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0516TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project JAS3412, Item 6161033, Project Item Line Number 0400, Material Set 616103396, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0516TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project JAS3412, Item 6161033, Project Item Line Number 0450, Material Set 616103396, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0516TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project JAS3412, Item 6161040, Project Item Line Number 0450, Material Set 61610396, Material 0616TMTC - Temporary Traffic Control Devices, Acc	Number 0290, Material Set 609105196, Material 1005FACCNSCA - Natural Sand for Conc Class A,	Working with the contractor to resolve this exception.	sandis1	Overridden
Number 0290, Material Set 609105196, Material 0501CCB. A - Concrete, Class B w/Air, Acceptance Action Generic 0501CCB. A is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161005, Project Item Line Number 0400, Material Set 614112096, Material 0614DFCTV is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161005, Project Item Line Number 0400, Material Set 616100598, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161025, Project Item Line Number 0420, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161030, Project Item Line Number 0420, Material Set 616102996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161030, Project Item Line Number 0430, Material Set 616103096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161033, Project Item Line Number 0430, Material Set 61610396, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161040, Project Item Line Number 0460, Material Set 61610396, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161070, Project Item Line Number 0460, Material Set 61610396, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient	Number 0290, Material Set 609105196, Material 1055CMMLDST1D - Clear Pavement-Bridge	Working with the contractor to resolve this exception.	sandis1	Overridden
Number 0390, Material Set 614112096, Material 06140PGTCV - Curved Vane Grate and Frame, Acceptance Action Generic 0614DFGTCV is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161005, Project Item Line Number 0400, Material Set 616100596, Material 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161005, Project Item Line Number 0420, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161025, Project Item Line Number 0420, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161030, Project Item Line Number 0430, Material Set 616103096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161033, Project Item Line Number 0440, Material Set 616103396, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161040, Project Item Line Number 0450, Material Set 616104096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient Materials: Project J4S3412, Item 6161055, Project Item Line Number 0450, Material Set 616104096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient Materials: Project J4S3412, Item 6161055, Project Item Line Number 0450, Material Set 61605966, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161070, Project Item Line Number 0470, M	Number 0290, Material Set 609105196, Material 0501CCBA - Concrete, Class B w/Air, Acceptance	Working with the contractor to resolve this exception.	sandis1	Overridden
Number 0400, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161025, Project Item Line Number 0420, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161030, Project Item Line Number 0430, Material Set 616103096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161033, Project Item Line Number 0430, Material Set 616103096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161040, Project Item Line Number 0450, Material Set 616103396, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161040, Project Item Line Number 0450, Material Set 616104096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161055, Project Item Line Number 0460, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161070, Project Item Line Number 0470, Material Set 616107096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161099, Project Item Line Number 0470, Material Set 6161070996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMT	Number 0390, Material Set 614112096, Material 0614DFGTCV - Curved Vane Grate and Frame,	Working with the contractor to resolve this exception.	sandis1	Overridden
Number 0420, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Sandis1 Overridden Number 0430, Material Set 616103096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161033, Project Item Line Number 0440, Material Set 616103396, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161040, Project Item Line Number 0450, Material O616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161040, Project Item Line Number 0450, Material O616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161055, Project Item Line Number 0460, Material O616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161055, Project Item Line Number 0460, Material O616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161050, Project Item Line Number 0460, Material O616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161070, Project Item Line Number 0470, Material O616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161070, Project Item Line Number 0470, Material O616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161099, Project Item Line Number 0470, Material O616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161099, Project Item Line Number 0470, Material O616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161099, Project Item Line Number 0470, Material O616TMTC is insufficient. Estimate Exception Type:	Number 0400, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices,	Working with the contractor to resolve this exception.	sandis1	Overridden
Number 0430, Material Set 616103096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161033, Project Item Line Number 0440, Material Set 616103396, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161040, Project Item Line Number 0450, Material Set 616104096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161055, Project Item Line Number 0460, Material Set 616105596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161070, Project Item Line Number 0460, Material Set 616107096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161070, Project Item Line Number 5001, Material Set 616107096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161099, Project Item Line Number 0470, Material Set 6161070996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161099, Project Item Line Number 0470, Material Set 616109996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6169902, Project Item Line Working with the contractor to resolve this exception. Sandis1 Overridden	Number 0420, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices,	Working with the contractor to resolve this exception.	sandis1	Overridden
Number 0440, Material Set 616103396, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161040, Project Item Line Number 0450, Material Set 616104096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161055, Project Item Line Number 0460, Material Set 616105596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161070, Project Item Line Number 5001, Material Set 616107096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161070, Project Item Line Number 5001, Material Set 616107096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Working with the contractor to resolve this exception. Working with the contractor to resolve this exception. Sandis1 Overridden Working with the contractor to resolve this exception. Sandis1 Overridden Working with the contractor to resolve this exception. Sandis1 Overridden Working with the contractor to resolve this exception. Sandis1 Overridden Working with the contractor to resolve this exception. Sandis1 Overridden	Number 0430, Material Set 616103096, Material 0616TMTC - Temporary Traffic Control Devices,	Working with the contractor to resolve this exception.	sandis1	Overridden
Number 0450, Material Set 616104096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161055, Project Item Line Number 0460, Material Set 616105596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161070, Project Item Line Number 5001, Material Set 616107096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161099, Project Item Line Number 0470, Material Set 616109996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161099, Project Item Line Number 0470, Material Set 616109996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 61609902, Project Item Line Working with the contractor to resolve this exception. Sandis1 Overridden Working with the contractor to resolve this exception. Sandis1 Overridden	Number 0440, Material Set 616103396, Material 0616TMTC - Temporary Traffic Control Devices,	Working with the contractor to resolve this exception.	sandis1	Overridden
Number 0460, Material Set 616105596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161070, Project Item Line Number 5001, Material Set 616107096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161099, Project Item Line Number 0470, Material Set 616109996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6169902, Project Item Line Working with the contractor to resolve this exception. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6169902, Project Item Line Working with the contractor to resolve this exception. Sandis1 Overridden Overridden	Number 0450, Material Set 616104096, Material 0616TMTC - Temporary Traffic Control Devices,	Working with the contractor to resolve this exception.	sandis1	Overridden
Number 5001, Material Set 616107096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6161099, Project Item Line Number 0470, Material Set 616109996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Working with the contractor to resolve this exception. Sandis1 Overridden Working with the contractor to resolve this exception. Sandis1 Overridden	Number 0460, Material Set 616105596, Material 0616TMTC - Temporary Traffic Control Devices,	Working with the contractor to resolve this exception.	sandis1	Overridden
Number 0470, Material Set 616109996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. Estimate Exception Type: Insufficient Materials: Project J4S3412, Item 6169902, Project Item Line Working with the contractor to resolve this exception. sandis1 Overridden	Number 5001, Material Set 616107096, Material 0616TMTC - Temporary Traffic Control Devices,	Working with the contractor to resolve this exception.	sandis1	Overridden
	Number 0470, Material Set 616109996, Material 0616TMTC - Temporary Traffic Control Devices,	Working with the contractor to resolve this exception.	sandis1	Overridden
		Working with the contractor to resolve this exception.	sandis1	Overridden

Revision 5/29/2025 Page 5 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Acceptance Action Generic 0616TMTC is insufficient.			
Estimate Exception Type: Item Overrun: Contract 250516-C03, Contract Project J4S3412, Project Item Line Number 0420, Contract Line Item Number 0420, Item 6161025, Minor Item.	This overrun will be addressed on an upcoming change order.	sandis1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 250516-C03, Contract Project J4S3412, Project Item Line Number 0430, Contract Line Item Number 0430, Item 6161030, Minor Item.	This overrun will be addressed on an upcoming change order.	sandis1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 250516-C03, Contract Project J4S3412, Project Item Line Number 0480, Contract Line Item Number 0480, Item 6169902, Minor Item.	This overrun will be addressed on an upcoming change order.	sandis1	Acknowledged

Revision 5/29/2025 Page 6 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See report generated date)
J4S3412	0001	0010	1081000	SIGNET DBE REPORTING	1.00	0.00	1.00	LS	1.00	\$1,000.00	\$1,000.0
	0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.40	\$1,619,332.11	\$647,732.8
	0001	0030	2029901	MISC.SIDEWALK MANICURING	1.00	0.00	1.00	LS	0.00	\$12,052.00	\$0.0
	0001	0040	2031000	CLASS A EXCAVATION	7,975.00	0.00	7,975.00	CUYD	3,360.00	\$45.00	\$151,200.
	0001	0050	2036000	COMPACTING EMBANKMENT	123.00	0.00	123.00	CUYD	0.00	\$55.00	\$0.0
	0001	0060	2063300	CLASS 4 EXCAVATION	54.00	0.00	54.00	CUYD	0.00	\$177.00	\$0.0
	0001	0070	2063500	CULVERT CLEANOUT	2.00	0.00	2.00	EA	0.00	\$9,010.00	\$0.0
	0001	0800	2069901	MISC.DEWATERING	1.00	0.00	1.00	LS	0.00	\$2,500.00	\$0.0
	0001	0090	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	56.00	0.00	56.00	100F	28.00	\$506.00	\$14,168.0
	0001	0100	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	5,848.00	0.00	5,848.00	SQYD	450.00	\$24.25	\$10,912.
	0001	0110	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	39,381.00	0.00	39,381.00	SQYD	17,550.00	\$20.65	\$362,407.
	0001	0120	4030005	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP095C MIX)	6,542.50	0.00	6,542.50	TONS	0.00	\$102.76	\$0.
	0001	0130	4030105	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125C MIX)	8,856.30	0.00	8,856.30	TONS	0.00	\$96.87	\$0.
	0001	0140	4071007	TACK COAT - NON-TRACKING	10,368.00	0.00	10,368.00	GAL	0.00	\$4.73	\$0.
	0001	0150	5021112	CONCRETE PAVEMENT (12 INCH NON-REINFORCED)	1,158.90	0.00	1,158.90	SQYD	0.00	\$89.00	\$0.
	0001	0160	6049902	MISC.ADJUST SANITARY MANHOLE	21.00	0.00	21.00	EA	0.00	\$1,500.00	\$0.
	0001	0170	6049902	MISC.ADJUST SIGNAL PULL BOX	13.00	0.00	13.00	EA	0.00	\$884.23	\$0.
	0001	0180	6049902	MISC.ADJUST STORM LID	127.00	0.00	127.00	EA	0.00	\$1,500.00	\$0.
	0001	0190	6049902	MISC.ADJUST STORM MANHOLE	16.00	0.00	16.00	EA	0.00	\$1,450.00	\$0.
	0001	0200	6049902	MISC.ADJUST WATER VALVE	13.00	0.00	13.00	EA	0.00	\$585.00	\$0.
	0001	0210	6049902	MISC.DROP INLET CLEANOUT	195.00	0.00	195.00	EA	24.00	\$259.00	\$6,216.
	0001	0220	6049902	MISC.REPLACE STORM LID	48.00	0.00	48.00	EA	24.00	\$1,800.00	\$43,200.
	0001	0230	6081010	CONCRETE CURB RAMP	604.70	0.00	604.70	SQYD	0.00	\$218.00	\$0.
	0001	0240	6081012	TRUNCATED DOMES	945.40	0.00	945.40	SQFT	0.00	\$19.20	\$0.
	0001	0250	6083006	6 IN. CONCRETE MEDIAN STRIP	1,158.90	0.00	1,158.90	SQYD	0.00	\$73.50	\$0
	0001	0260	6085007	PAVED APPROACH, 7 IN.	752.10	0.00	752.10	SQYD	0.00	\$101.75	\$0.
	0001	0270	6085008	PAVED APPROACH, 8 IN.	3,938.10	0.00	3,938.10	SQYD	499.00	\$104.00	\$51,896.
	0001	0280	6086004	CONCRETE SIDEWALK, 4 IN.	8,907.40	0.00	8,907.40	SQYD	0.00	\$76.50	\$0.
	0001	0290	6091051	CURB AND GUTTER TYPE A	10,226.00	0.00	10,226.00	LF	5,177.00	\$38.00	\$196,726.
	0001		6097000			0.00		CUYD	0.00		
	0001	0300	6099903	ROCK LINING	10.00	0.00	10.00	LF	0.00	\$331.25 \$63.15	\$0. \$0.
	0001			MISC.MODIFIED CURB AND GUTTER (TYPE A)	17,369.00		17,369.00				
	0001	0320	6116010A	SLOPE PROTECTION	30.00	0.00	30.00	SQYD	0.00	\$382.25	\$0.
	0001	0330	6117000A 6131010	GABIONS FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	67.00 48.00	0.00	67.00 48.00	SQYD	0.00	\$367.00 \$294.00	\$0. \$0.
	0001	0350	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	48.00	0.00	48.00	SQYD	0.00	\$34.00	\$0.
	0001	0360	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	216.00	0.00	216.00	LF	0.00	\$6.50	\$0.
	0001	0370	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	144.00	0.00	144.00	EA	0.00	\$33.00	\$0.
	0001	0380	6139905	MISC.TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	48.00	0.00	48.00	SQYD	0.00	\$33.00	\$0
	0001	0390	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)	48.00	0.00	48.00	EA	24.00	\$671.00	\$16,104.
	0001	0400	6161005	CONSTRUCTION SIGNS	1,721.00	0.00	1,721.00	SQFT	967.75	\$6.50	\$6,290.
		0410	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	0.00	\$45.00	\$0
	0001	0420	6161025	CHANNELIZER (TRIM-LINE)	220.00	0.00	220.00	EA	251.00	\$17.00	\$4,267.
	0001	0430	6161030	TYPE 3 MOVEABLE BARRICADE	69.00	0.00	69.00	EA	84.00	\$125.00	\$10,500.
	0001	0440	6161033	DIRECTION INDICATOR BARRICADE	39.00	0.00	39.00	EA	24.00	\$65.00	\$1,560
	0001	0450	6161040	FLASHING ARROW PANEL	3.00	0.00	3.00	EA	2.00	\$3,500.00	\$7,000
	0001	0460	6161055	SEQUENTIAL FLASHING WARNING LIGHT	39.00	0.00	39.00	EA	24.00	\$85.00	\$2,040
	0001	0470	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED / RETAINED	2.00	0.00	2.00	EA	2.00	\$4,000.00	\$8,000
	0001	0480	6169902	MISC.ADA COMPLIANT MOVEABLE BARRICADE	8.00	0.00	8.00	EA	17.00	\$70.00	\$1,190.
	0001	0490 0500	6181000 6200015	MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	1.00 763.00	0.00	1.00 763.00	LS LF	0.75	\$904,639.14 \$20.00	\$678,479. \$0.
	0001	0510	6200021	WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	102.00	0.00	102.00	EA	0.00	\$198.00	\$0.
	0001	0520	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	2.00	0.00	2.00	EA	0.00	\$475.00	\$0.
	0001	0530	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN	303.00	0.00	303.00	EA	0.00	\$195.00	\$0.

Revision 5/29/2025 Page 7 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

act Proj		Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
6- J4S3	3412				WHITE MIDBLOCK							
		0001	0540	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	162.00	0.00	162.00	LF	0.00	\$13.00	\$0.0
		0001	0550	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	14,835.00	0.00	14,835.00	LF	0.00	\$0.13	\$0.0
		0001	0560	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	42,291.00	0.00	42,291.00	LF	0.00	\$0.13	\$0.0
		0001	0570	6207001	PAVEMENT MARKING REMOVAL	1,510.00	0.00	1,510.00	LF	0.00	\$0.99	\$0.0
		0001	0580	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	50,431.00	0.00	50,431.00	LF	47,400.00	\$0.13	\$6,162.
		0001	0590	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	79,700.00	0.00	79,700.00	SQYD	0.00	\$3.03	\$0.
		0001	0600	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.40	\$139,600.00	\$55,840.
		0001	0610	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	145.00	0.00	145.00	SQFT	0.00	\$225.00	\$0.
		0001	0620	7040113	CLEANING AND EPOXY COATING	216.00	0.00	216.00	SQFT	0.00	\$42.50	\$0.
		0001	0630	8025006	MULCHING	5.10	0.00	5.10	ACRE	0.00	\$1,000.00	\$0
		0001	0640	8051000A	SEEDING - COOL SEASON GRASSES	5.10	0.00	5.10	ACRE	0.00	\$3,100.00	\$0
		0001	0650	8061007A	CURB INLET CHECK	215.00	0.00	215.00	EA	0.00	\$110.01	\$0
		0001	0660	8061016	SEDIMENT REMOVAL	296.00	0.00	296.00	CUYD	0.00	\$68.26	\$0
		0001	0670	8061019	SILT FENCE	6,437.00	0.00	6,437.00	LF	0.00	\$1.66	\$0
		0003	0690	4039905	MISC.12.5 INCHES, ASPHALTIC CONCRETE PAVEMENT	39,380.40	0.00	39,380.40	SQYD	19,690.20	\$54.80	\$1,079,022
		0030	0700	9020213	SIGNAL HEAD, TYPE 3S	2.00	0.00	2.00	EA	0.00	\$1,083.08	\$0
		0030	0710	9020215	SIGNAL HEAD, TYPE 5S	5.00	0.00	5.00	EA	0.00	\$1,861.45	\$0
		0030	0720	9020513	SIGNAL HEAD, TYPE 3B	8.00	0.00	8.00	EA	0.00	\$1,246.76	\$0
		0030	0730	9020514	SIGNAL HEAD, TYPE 4B	6.00	0.00	6.00	EA	0.00	\$1,723.42	\$0
		0030	0740	9020515	SIGNAL HEAD, TYPE 5B	2.00	0.00	2.00	EA	0.00	\$2,200.08	\$(
		0030	0750	9020811	SIGNAL HEAD, TYPE 1S, PEDESTRIAN	22.00	0.00	22.00	EA	0.00	\$755.89	\$1
		0030	0760	9020833	SH-FLAT SHEET - SIGNAL SIGN	72.00	0.00	72.00	SQFT	0.00	\$35.39	\$0
		0030	0770	9020834	SIGNAL SIGN, MOUNTING HARDWARE	8.00	0.00	8.00	EA	0.00	\$319.42	\$(
		0030	0780	9022708	POST, SIGNAL 8 FT.	8.00	0.00	8.00	EA	0.00	\$1,284.97	\$0
		0030	0790	9023140	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	1.00	0.00	1.00	EA	0.00	\$18,694.80	\$1
		0030	0800	9023215	POST, TYPE C, 15 FT. ARM OR 4.6 M ARM	1.00	0.00	1.00	EA	0.00	\$8,479.31	\$1
		0030	0810	9023225	POST, TYPE C, 25 FT. ARM OR 7.6 M ARM	1.00	0.00	1.00	EA	0.00	\$10,421.79	\$1
		0030	0820	9023235	POST, TYPE C, 35 FT. ARM OR 10.7 M ARM	1.00	0.00	1.00	EA	0.00	\$12,437.25	\$1
		0030	0830	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	1.00	0.00	1.00	EA	0.00	\$21,297.75	\$1
		0030	0840	9024920	DETECTOR, PUSHBUTTON	44.00	0.00	44.00	EA	0.00	\$1,240.39	\$1
		0030	0850	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	20.00	0.00	20.00	LF	0.00	\$1,240.39	\$1
		0030							LF	0.00		
		0030	0860	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	91.00	0.00	91.00			\$16.89	\$
		0030	0870	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	611.00	0.00	611.00	LF	0.00	\$28.09	\$1
		0030	0880	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	118.00	0.00	118.00	LF	0.00	\$2.22	\$
		0030	0890	9028308	CABLE, 16 AWG 2 CONDUCTOR	3,101.00	0.00	3,101.00	LF	0.00	\$1.49	\$1
		0030	0900	9028310	CABLE, 16 AWG 5 CONDUCTOR	2,912.00	0.00	2,912.00	LF	0.00	\$1.97	\$1
		0030	0910	9028311	CABLE, 16 AWG 7 CONDUCTOR	2,094.00	0.00	2,094.00	LF	0.00	\$2.55	\$1
			0920	9028610	POWER SUPPLY ASSEMBLY, TYPE 1	1.00	0.00	1.00	EA	0.00	\$4,047.77	\$1
		0030	0930	9028810	PULL BOX, PREFORMED CLASS 1	8.00	0.00	8.00	EA	0.00	\$1,809.14	\$1
		0030	0940	9029100	BASE, CONCRETE	17.50	0.00	17.50	CUYD	0.00	\$2,155.86	\$1
		0030	0950	9039902	MISC.KC DISTRICT VIDEO DETECTION SYSTEM	6.00	0.00	6.00	EA	0.00	\$29,181.53	\$
		0040	0960		2 IN. PSST POST - 12 GA.	445.00	0.00	445.00	LF	0.00	\$29.00	\$1
		0040	0970	9031273A	DRIVEN POST ANCHOR FOR 2 IN. PSST - 7 GA.	32.00	0.00	32.00	EA	0.00	\$190.00	\$(
		0040	0980	9035004A	SH-FLAT SHEET	332.70	0.00	332.70	SQFT	0.00	\$22.00	\$1
		0040	0990	9035011A	ST-STRUCTURAL	22.00	0.00	22.00	SQFT	0.00	\$23.00	\$
		0040	1000	9035069A	SHF-FLAT SHEET FLUORESCENT	9.00	0.00	9.00	SQFT	0.00	\$30.00	\$1
		0001	5001	6161070	TUBULAR MARKER	0.00	77.00	77.00	EA	20.00	\$173.25	\$3,46
		\$2412 To	tal Valuo	Posted to D	Pate as of Report Generated Date							\$3,365,379

Revision 5/29/2025 Page 8 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4S3412

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Posting Sequence No.	Quantity Posted	Units	Location	From Station/Log Mile	Offset/ Distance	To Station/Log Mile	Offset/ Distance	Comments
0010	1081000	SIGNET DBE REPORTING	9/30/25	10/3/25	1	1.00	LS		N/A		N/A		
0090	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	9/30/25	10/2/25	1	14.00	100F	MO-1 Phase 1					Completed 9/10/2025
0100	3040504	TYPE 5 AGGREGATE FOR BASE	9/30/25	10/2/25	1	163.00	SQYD	MO-1 Phase 1					Completed 9/16/2025
				10/2/25	2	134.00	SQYD	MO-1 Phase 1					Completed 9/19/2025
0110	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	9/30/25	10/2/25	1	1,458.00	SQYD	MO-1 Phase 1					Completed 9/19/2025
0210	6049902	MISC. DRAINAGE ITEM	9/30/25	10/2/25	1	3.00	EA	MO-1 Phase 1					Completed 9/13/2025
0220	6049902	MISC. DRAINAGE ITEM	9/30/25	10/2/25	1	8.00	EA	MO-1 Phase 1					Completed 9/13/2025
0270	6085008	PAVED APPROACH, 8 IN.	9/30/25	10/2/25	1	49.00	SQYD	MO-1 Phase 1					Completed 9/15/2025
				10/2/25	2	163.00	SQYD	MO-1 Phase 1					Completed 9/16/2025
				10/2/25	3	134.00	SQYD	MO-1 Phase 1					Completed 9/19/2025
0290	6091051	CURB AND GUTTER TYPE A	9/30/25	10/2/25	1	536.00	LF	MO-1 Phase 1					Completed 9/15/2025
				10/2/25	2	228.00	LF	MO-1 Phase 1					Completed 9/16/2025
0390	6141120	CURVED VANE GRTE AND FRAME(2 FT. X 2 FT)	9/30/25	10/2/25	1	24.00	EA	MO-1 Phase 1					Completed 9/13/2025
0420	6161025	CHANNELIZER (TRIM-LINE)	9/30/25	10/2/25	1	109.00	EA	MO-1 Phase 1					
0490	6181000	MOBILIZATION	9/30/25	10/3/25	1	0.25	LS		N/A		N/A		Third mobilization payment.
0580	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	9/30/25	10/3/25	1	23,700.00	LF	MO-1	1009+75	RT	1065+11	RT	Phase 1 traffic configuration
				10/3/25	2	23,700.00	LF		1009+75	LT	1065+11	LT	Phase 2 traffic configuration
0600	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	9/30/25	10/3/25	1	0.40	LS		1009+75	LT	1065+11	LT	Phase 1 Surveying and Staking
0690	4039905	MISC.	9/30/25	10/2/25	1	174.15	SQYD	MO-1 Phase 1	1009+73.95		1010+80.00		Per Plan Quantities - Phase 1 portion/half
				10/2/25	2	2,034.45	SQYD	MO-1 Phase 1	1010+80.00		1016+20.00		Per Plan Quantities - Phase 1 portion/half
				10/2/25	3	2,223.10	SQYD	MO-1 Phase 1	1016+20.00		1021+60.00		Per Plan Quantities - Phase 1 portion/half
				10/2/25	4	2,029.35	SQYD	MO-1 Phase 1	1021+60.00		1027+00.00		Per Plan Quantities - Phase 1 portion/half
				10/2/25	5	1,579.60	SQYD	MO-1 Phase 1	1027+00.00		1032+40.00		Per Plan Quantities - Phase 1 portion/half
				10/2/25	6	1,700.80	SQYD	MO-1 Phase 1	1032+40.00		1037+80.00		Per Plan Quantities - Phase 1 portion/half
				10/2/25	7	1,575.65	SQYD	MO-1 Phase 1	1037+80.00		1043+20.00		Per Plan Quantities - Phase 1 portion/half
				10/2/25	8	1,629.85	SQYD	MO-1 Phase 1	1043+20.00		1048+60.00		Per Plan Quantities - Phase 1 portion/half
				10/2/25	9	1,633.45	SQYD	MO-1 Phase 1	1048+60.00		1054+00.00		Per Plan Quantities - Phase 1 portion/half
				10/2/25	10	2,138.45	SQYD	MO-1 Phase 1	1054+00.00		1059+40.00		Per Plan Quantities - Phase 1 portion/half
				10/2/25	11	2,859.10	SQYD	MO-1 Phase 1	1059+40.00		1064+80.00		Per Plan Quantities - Phase 1 portion/half
				10/2/25	12	112.25	SQYD	MO-1 Phase 1	1064+80.00		1065+11.00		Per Plan Quantities - Phase 1 portion/half
5001	6161070	TUBULAR MARKER	9/30/25	10/3/25	1	20.00	EA		N/A		N/A		Additional tubular markers required for Phase 2 configuration.

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 6/5/2025 Page 9 of 14



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
112	0100	TYPE 5 AGGREGATE	Material		3	Sep 17, 2025	SYSTEM	(\$3,710.25)	
		FOR BASE			3	Sep 17, 2025	SYSTEM	\$3,710.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sandis1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Oct 3, 2025	SYSTEM	(\$10,912.50)	
					4	Oct 3, 2025	SYSTEM	\$10,912.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user sandis1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0100 -	Total						\$0.00	
	0110	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		3	Sep 17, 2025	SYSTEM	(\$264,816.14)	
					3	Sep 17, 2025	SYSTEM	\$264,816.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sandis1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Oct 3, 2025	SYSTEM	(\$294,923.84)	
					4	Oct 3, 2025	SYSTEM	\$294,923.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sandis1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0110 -							\$0.00	
	0270	PAVED APPROACH, 8 IN.	Material		3	Sep 17, 2025	SYSTEM	(\$15,912.00)	
					3	Sep 17, 2025	SYSTEM	\$15,912.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sandis1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Oct 3, 2025	SYSTEM	(\$51,896.00)	
					4	Oct 3, 2025	SYSTEM	\$51,896.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sandis1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0270 - 0290	CURB AND	Material		3	Sep 17,	SYSTEM	\$0.00 (\$167,694.00)	
		GUTTER TYPE A			3	2025 Sep 17, 2025	SYSTEM	\$167,694.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user sandis1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Oct 3, 2025	SYSTEM	(\$196,726.00)	Estimate Exception 7 on the surface of the Estimate.
					4	Oct 3, 2025	SYSTEM	\$196,726.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user sandis1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0290 -	Total						\$0.00	
	0390	CURVED VANE GRTE AND FRAME(2 FT. X 2			4	Oct 3, 2025	SYSTEM	(\$16,104.00)	
		FRAME(2 F1. X 2 FT)			4	Oct 3, 2025	SYSTEM	\$16,104.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sandis1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0390 -	Total						\$0.00	



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J4S3412	0400	CONSTRUCTION SIGNS	Material		2	Aug 4, 2025	SYSTEM	\$6,290.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Sep 17, 2025	SYSTEM	(\$6,290.38)	
					3	Sep 17, 2025	SYSTEM	\$6,290.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sandis1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					4	Oct 3, 2025	SYSTEM	(\$6,290.38)	
					4	Oct 3, 2025	SYSTEM	\$6,290.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sandis1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0400	- Total						\$0.00	
	0420	CHANNELIZER (TRIM-LINE)	Material		2	Aug 4, 2025	SYSTEM	(\$2,414.00)	
					2	Aug 4, 2025	SYSTEM	\$2,414.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mcclon1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Sep 17, 2025	SYSTEM	(\$2,414.00)	
					3	Sep 17, 2025	SYSTEM	\$2,414.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sandis1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					4	Oct 3, 2025	SYSTEM	(\$4,267.00)	
					4	Oct 3, 2025	SYSTEM	\$4,267.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user sandis1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				- Total				\$0.00	
			Material - T	otal				\$0.00	
			Overrun	Overrun	4	Oct 3, 2025	SYSTEM	(\$527.00)	
				Overrun - T	otal			(\$527.00)	
			Overrun - T	otal				(\$527.00)	
	0420	- Total						(\$527.00)	
	0420	TYPE 3						, ,	
	0430	MOVEABLE	Material		2	Aug 4, 2025	SYSTEM	(\$10,500.00)	
	0430		Material		2		SYSTEM SYSTEM	(\$10,500.00) \$10,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
	0430	MOVEABLE	Material			2025 Aug 4,		, , ,	Estimate Item Adjustment (0004) due to user mcclon1 overridding Payment
	0430	MOVEABLE	Material		2	2025 Aug 4, 2025 Sep 17,	SYSTEM	\$10,500.00	Estimate Item Adjustment (0004) due to user mcclon1 overridding Payment
	0430	MOVEABLE	Material		2	2025 Aug 4, 2025 Sep 17, 2025 Sep 17,	SYSTEM SYSTEM	\$10,500.00 (\$10,500.00)	Estimate Item Adjustment (0004) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user sandis1 overridding Payment
	0430	MOVEABLE	Material		3	2025 Aug 4, 2025 Sep 17, 2025 Sep 17, 2025 Oct 3,	SYSTEM SYSTEM	\$10,500.00 (\$10,500.00) \$10,500.00	Estimate Item Adjustment (0004) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user sandis1 overridding Payment
	0430	MOVEABLE	Material	- Total	3 3 4	2025 Aug 4, 2025 Sep 17, 2025 Sep 17, 2025 Oct 3, 2025 Oct 3,	SYSTEM SYSTEM SYSTEM SYSTEM	\$10,500.00 (\$10,500.00) \$10,500.00	Estimate Item Adjustment (0004) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user sandis1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user sandis1 overridding Payment
	0430	MOVEABLE	Material - To		3 3 4	2025 Aug 4, 2025 Sep 17, 2025 Sep 17, 2025 Oct 3, 2025 Oct 3,	SYSTEM SYSTEM SYSTEM SYSTEM	\$10,500.00 (\$10,500.00) \$10,500.00 (\$10,500.00)	Estimate Item Adjustment (0004) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user sandis1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user sandis1 overridding Payment
	0430	MOVEABLE			3 3 4	2025 Aug 4, 2025 Sep 17, 2025 Sep 17, 2025 Oct 3, 2025 Oct 3,	SYSTEM SYSTEM SYSTEM SYSTEM	\$10,500.00 (\$10,500.00) \$10,500.00 (\$10,500.00) \$10,500.00	Estimate Item Adjustment (0004) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user sandis1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user sandis1 overridding Payment
	0430	MOVEABLE	Material - To	otal	2 3 3 4 4 4	2025 Aug 4, 2025 Sep 17, 2025 Sep 17, 2025 Oct 3, 2025 Oct 3, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM SYSTEM	\$10,500.00 (\$10,500.00) \$10,500.00 (\$10,500.00) \$10,500.00 \$0.00	Estimate Item Adjustment (0004) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user sandis1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user sandis1 overridding Payment
	0430	MOVEABLE	Material - To	Overrun - T	2 3 3 4 4 4	2025 Aug 4, 2025 Sep 17, 2025 Sep 17, 2025 Oct 3, 2025 Oct 3, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM SYSTEM	\$10,500.00 (\$10,500.00) \$10,500.00 (\$10,500.00) \$10,500.00 \$0.00 (\$1,875.00)	Estimate Item Adjustment (0004) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user sandis1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user sandis1 overridding Payment
		MOVEABLE	Material - To	Overrun - T	2 3 3 4 4 4	2025 Aug 4, 2025 Sep 17, 2025 Sep 17, 2025 Oct 3, 2025 Oct 3, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM SYSTEM	\$10,500.00 (\$10,500.00) \$10,500.00 (\$10,500.00) \$10,500.00 \$0.00 (\$1,875.00)	Estimate Item Adjustment (0004) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user sandis1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user sandis1 overridding Payment
		MOVEABLE BARRICADE	Material - To	Overrun - T	2 3 3 4 4 4	2025 Aug 4, 2025 Sep 17, 2025 Sep 17, 2025 Oct 3, 2025 Oct 3, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM SYSTEM	\$10,500.00 (\$10,500.00) \$10,500.00 (\$10,500.00) \$10,500.00 \$0.00 (\$1,875.00) (\$1,875.00) (\$1,875.00)	Estimate Item Adjustment (0004) due to user mcclon1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user sandis1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user sandis1 overridding Payment



ct Line	e Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
12 044	DIRECTION INDICATOR BARRICADE	Material			2025			Estimate Item Adjustment (0005) due to user mcclon1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				3	Sep 17, 2025	SYSTEM	(\$1,560.00)	
				3	Sep 17, 2025	SYSTEM	\$1,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user sandis1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				4	Oct 3, 2025	SYSTEM	(\$1,560.00)	
				4	Oct 3, 2025	SYSTEM	\$1,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user sandis1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
			- Total				\$0.00	
		Material - To	otal				\$0.00	
044	0 - Total						\$0.00	
045	FLASHING ARROW PANEL	Material		2	Aug 4, 2025	SYSTEM	(\$7,000.00)	
				2	Aug 4, 2025	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user mcclon1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				3	Sep 17, 2025	SYSTEM	(\$7,000.00)	
				3	Sep 17, 2025	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user sandis1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				4	Oct 3, 2025	SYSTEM	(\$7,000.00)	
				4	Oct 3, 2025	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user sandis1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
			- Total				\$0.00	
		Material - To	otal				\$0.00	
	0 - Total						\$0.00	
046	SEQUENTIAL FLASHING WARNING LIGHT	Material		2	Aug 4, 2025	SYSTEM	(\$2,040.00)	
	WARNING LIGHT							
				2	Aug 4, 2025	SYSTEM	\$2,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mcclon1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				3		SYSTEM	\$2,040.00 (\$2,040.00)	Estimate Item Adjustment (0007) due to user mcclon1 overridding Payment
					2025 Sep 17,			Estimate Item Adjustment (0007) due to user mcclon1 overridding Payment
				3	2025 Sep 17, 2025 Sep 17,	SYSTEM	(\$2,040.00)	Estimate Item Adjustment (0007) due to user mcclon1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user sandis1 overridding Payment
				3	2025 Sep 17, 2025 Sep 17, 2025	SYSTEM	(\$2,040.00) \$2,040.00	Estimate Item Adjustment (0007) due to user mcclon1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user sandis1 overridding Payment
			- Total	3 3	2025 Sep 17, 2025 Sep 17, 2025 Oct 3, 2025 Oct 3,	SYSTEM SYSTEM	(\$2,040.00) \$2,040.00 (\$2,040.00)	Estimate Item Adjustment (0007) due to user mcclon1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user sandis1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user sandis1 overridding Payment
		Material - To		3 3	2025 Sep 17, 2025 Sep 17, 2025 Oct 3, 2025 Oct 3,	SYSTEM SYSTEM	(\$2,040.00) \$2,040.00 (\$2,040.00) \$2,040.00	Estimate Item Adjustment (0007) due to user mcclon1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user sandis1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user sandis1 overridding Payment
	0 - Total			3 3 4 4	2025 Sep 17, 2025 Sep 17, 2025 Oct 3, 2025 Oct 3, 2025	SYSTEM SYSTEM SYSTEM	(\$2,040.00) \$2,040.00 (\$2,040.00) \$2,040.00 \$0.00 \$0.00	Estimate Item Adjustment (0007) due to user mcclon1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user sandis1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user sandis1 overridding Payment
	CHANGEABLE MESSAGE SIGN	Material - To		3 3 4 4 1	2025 Sep 17, 2025 Sep 17, 2025 Oct 3, 2025 Oct 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,040.00) \$2,040.00 (\$2,040.00) \$2,040.00 \$0.00 \$0.00 (\$8,000.00)	Estimate Item Adjustment (0007) due to user mcclon1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user sandis1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user sandis1 overridding Payment
	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR			3 3 4 4	2025 Sep 17, 2025 Sep 17, 2025 Oct 3, 2025 Oct 3, 2025 Jul 16,	SYSTEM SYSTEM SYSTEM	(\$2,040.00) \$2,040.00 (\$2,040.00) \$2,040.00 \$0.00 \$0.00	Estimate Item Adjustment (0007) due to user mcclon1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user sandis1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user sandis1 overridding Payment
	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE,			3 3 4 4 1	2025 Sep 17, 2025 Sep 17, 2025 Oct 3, 2025 Oct 3, 2025 Jul 16, 2025 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,040.00) \$2,040.00 (\$2,040.00) \$2,040.00 \$0.00 \$0.00 (\$8,000.00)	Estimate Item Adjustment (0007) due to user mcclon1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user sandis1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user sandis1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment
	O CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED /			3 3 4 4 1	2025 Sep 17, 2025 Sep 17, 2025 Oct 3, 2025 Oct 3, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,040.00) \$2,040.00 (\$2,040.00) \$2,040.00 \$0.00 \$0.00 \$0.00 (\$8,000.00)	Estimate Item Adjustment (0007) due to user mcclon1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user sandis1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user sandis1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment
	O CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED /			3 3 4 4 1 1	2025 Sep 17, 2025 Sep 17, 2025 Oct 3, 2025 Oct 3, 2025 Jul 16, 2025 Jul 16, 2025 Aug 4, 2025 Aug 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,040.00) \$2,040.00 (\$2,040.00) \$2,040.00 \$0.00 \$0.00 \$0.00 \$8,000.00) (\$8,000.00)	Estimate Item Adjustment (0007) due to user mcclon1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user sandis1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user sandis1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcclon1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user mcclon1 overridding Payment Estimate Item Adjustment (0008) due to user mcclon1 overridding Payment



MESSAGE SIGN	
COMMUNICATION 4 Oct 3, SYSTEM (\$8,000.00) INTERFACE, CONTRACTOR	0011) due to user sandis1 overridding Payment le current Payment Estimate.
CONTRACTOR 4 Oct 2 SYSTEM \$20,000 CO This additional of the contract of the co	
FURNISHED / 4 Oct 3, SYSTEM \$8,000.00 This adjustment offsets the control of the	original system-generated Material Payment 0013) due to user sandis1 overridding Payment le current Payment Estimate.
- Total \$0.00	
Material - Total \$0.00	
0470 - Total \$0.00	
0480 MISC. TRAFFIC	
2 Aug 4, SYSTEM \$1,190.00 This adjustment offsets the of	original system-generated Material Payment 0010) due to user mcclon1 overridding Payment current Payment Estimate.
3 Sep 17, 2025 SYSTEM (\$1,190.00)	
	original system-generated Material Payment 0012) due to user sandis1 overridding Payment le current Payment Estimate.
4 Oct 3, 2025 SYSTEM (\$1,190.00)	
	original system-generated Material Payment 0014) due to user sandis1 overridding Payment le current Payment Estimate.
- Total \$0.00	
Material - Total \$0.00	
material rotal	
Overrun Overrun 2 Aug 4, 2025 SYSTEM (\$630.00)	
Overrun Overrun 2 Aug 4, SYSTEM (\$630.00)	
Overrun 2 Aug 4, 2025 SYSTEM (\$630.00)	
Overrun 2 Aug 4, 2025 SYSTEM (\$630.00) Overrun - Total (\$630.00)	
Overrun Overrun 2 Aug 4, 2025 SYSTEM (\$630.00) Overrun - Total (\$630.00) Overrun - Total (\$630.00)	
Overrun Overrun 2 Aug 4, SYSTEM (\$630.00)	original system-generated Material Payment 0015) due to user sandis1 overridding Payment current Payment Estimate.
Overrun Overrun 2 Aug 4, 2025 SYSTEM (\$630.00)	0015) due to user sandis1 overridding Payment
Overrun Overrun 2 Aug 4, SYSTEM (\$630.00)	0015) due to user sandis1 overridding Payment
Overrun Overrun 2 Aug 4, 2025 SYSTEM (\$630.00)	0015) due to user sandis1 overridding Payment
Overrun Overrun 2	015) due to user sandis1 overridding Payment e current Payment Estimate.
Overrun Overrun 2	0015) due to user sandis1 overridding Payment
Overrun Overrun 2	0015) due to user sandis1 overridding Payment current Payment Estimate. original system-generated Material Payment 1016) due to user sandis1 overridding Payment
Overrun Overrun 2	0015) due to user sandis1 overridding Payment current Payment Estimate. original system-generated Material Payment 1016) due to user sandis1 overridding Payment
Overrun Overrun 2	0015) due to user sandis1 overridding Payment current Payment Estimate. original system-generated Material Payment 1016) due to user sandis1 overridding Payment
Overrun Overrun 2	0015) due to user sandis1 overridding Payment current Payment Estimate. original system-generated Material Payment 1016) due to user sandis1 overridding Payment

MoDOT

Contract Adjustments for Contract - 250516-C03

There are no contract adjustments to display for this contract.

Revision 5/29/2025 Page 14 of 14