

#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 16, 2020

_	imate Number 4	Contract ID 19 Prime Contractor Ca	0315-D03 apital Paving & Co			y 15, 2020 <b>Net Cha</b>	l Contract Amoun ange Order Amoun Contract Amount	nt \$325,680.81						
Approval Date								By User						
July 20, 2020			Generated and	Approved (and should	d be considered	Draft) at the Projec	t Office Level by	mantlc1						
July 20, 2020		Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by												
July 21, 2020		Reviewed and Approved at the Central Office Controllers Office Level by greggd1												
Original Co	mpletion Date	Current Comp	oletion Date	Actual Comple	tion Date	% of Curren	t Contract Amoun	t Complete						
July	1, 2020	July 1,	2020	June 29, 2	2020		99.25%							
Con	tract Information	nal Dates			Mile	stones								
Date Description	Original Completion Date	Current Completion Date	Date	Description	Original Completion Date	Current Completion Date	Days Remaining Milestone	on Diary Charge Days						
Acceptance Date			Milestone - Ca AC Bridge A23	lendar Time Route 932										
Awarded Date	April 2, 2019	April 2, 2019												
Letting Date	March 15, 2019	March 15, 2019												
Notice to Proceed Date	April 17, 2019	April 17, 2019												
Open to Traffic Date														
Work Began Date	June 10, 2019	June 10, 2019												

Contract Total Pay For Estimate No. 24										
		This Estimate	Previous	To Date						
190315-D03										
To	otal Posted Items Pay	\$0.00	\$3,949,766.41	\$3,949,766.41						
Gr	ross Item Adjustments	\$0.00	\$0.00	\$0.00						
Inc	centive	\$0.00	\$2,634.43	\$2,634.43						
Di	sincentive	\$0.00	\$0.00	\$0.00						
Lic	quidated Damage	\$0.00	(\$5,000.00)	(\$5,000.00)						
Ot	ther Contract Adjustments	\$0.00	\$0.00	\$0.00						
			\$3,947,400.84	\$3,947,400.84						
Contract Total Payable T	his Estimate:	\$0.00								
Itoms Paid This Estimate	Pariod									

#### Items Paid This Estimate Period

No Data Available

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3287	1100	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	MaterialCredit			0.75	\$6,293.00	\$4,719.75
	1100	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material			-0.75	\$6,293.00	(\$4,719.75)
	1280	GRAY EPOXY-MASTIC PRIMER	MaterialCredit			1	\$10,489.00	\$10,489.00
	1280	GRAY EPOXY-MASTIC PRIMER	Material			-1	\$10,489.00	(\$10,489.00)
Total								\$0.00

Revision 4/1/2020 Page 1 of 27



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information																
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work											
J5P3287	FAF 63-3(108)	Bridge rehabilitation	63, AC	BOONE	from Route AC to 3 miles	om Route AC to 3 miles north of Route 54 near Jefferson City											
Totals by Job Numbers																	
Totals by J	Job Number	rs															
Totals by J	Job Number	rs			This Estimate	Previous	To Date										
		rs d Item Pay			This Estimate \$0.00	<b>Previous</b> \$3,949,766.41	<b>To Date</b> \$3,949,766.41										
•	Posted		ents														
•	Posted	d Item Pay		Item Pay	\$0.00	\$3,949,766.41	\$3,949,766.41										
	Posted	d Item Pay Item Adjustme		Item Pay	\$0.00 \$0.00	\$3,949,766.41 \$0.00	\$3,949,766.41 \$0.00										
•	Posted Gross	d Item Pay Item Adjustme		Item Pay	\$0.00 \$0.00 <b>\$0.00</b>	\$3,949,766.41 \$0.00 <b>\$3,949,766.41</b>	\$3,949,766.41 \$0.00 <b>\$3,949,766.41</b>										
	Posted Gross Incent Disinc	d Item Pay Item Adjustme	Gross	Item Pay	\$0.00 \$0.00 <b>\$0.00</b> \$0.00	\$3,949,766.41 \$0.00 <b>\$3,949,766.41</b> \$2,634.43	\$3,949,766.41 \$0.00 <b>\$3,949,766.41</b> \$2,634.43										

Revision 4/1/2020 Page 2 of 27



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5P3287, Item 7110200, Project Item Line Number 1100, Material Set 7110200, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	No Remark was entered by Engineer	mantlc1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3287, Item 7125961, Project Item Line Number 1280, Material Set 7125961, Material 1045PTGREPMA - Gray Epoxy-Mastic Primer, Acceptance Action Generic 1045PTGREPMA is insufficient.	No Remark was entered by Engineer	mantlc1	Acknowledged

Revision 4/1/2020 Page 3 of 27



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

2001   000	Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
2001   0.00	190315-D03	J5P3287	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$113,007.00	\$113,007.00
Control   Cont			0001	0020	2072000	LINEAR GRADING CLASS 2	80.00	4.00	84.00	STA	84.00	\$193.00	\$16,212.00
March   Marc			0001	0030	2153000	SHAPING SLOPES, CLASS III	27.00	0.00	27.00	100F	27.00	\$841.00	\$22,707.00
			0001	0040	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	8,870.00	-5,177.00	3,693.00	SQYD	3,693.00	\$9.30	\$34,344.90
COD			0001	0050	4019905	MISC.OPTIONAL 8" SHOULDER PAVEMENT	8,870.10	-5,177.00	3,693.10	SQYD	3,693.10	\$39.50	\$145,877.45
CODE			0001	0060	4133200	ULTRATHIN BONDED WEARING SURFACE, TYPE C	1,205.00	0.00	1,205.00	SQYD	1,205.00	\$35.30	\$42,536.50
CODITION   CODITION			0001	0070	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARRELS)	6.00	0.00	6.00	EA	6.00	\$4,405.00	\$26,430.00
0011 0100 012508A TRUCK OR THALER MOUNTED ATTENUATOR (TIMA)			0001	0080	6122020	REPLACEMENT SAND BARREL	6.00	-6.00	0.00	EA	0.00	\$393.00	\$0.00
			0001	0090	6122030	IMPACT ATTENUATOR (RELOCATION)	6.00	1.00	7.00	EA	7.00	\$514.00	\$3,598.00
FEMBLE   HOT FOL MERANDENER REPARK MATERIAL   1910   0161000   01610000   15000000000000000000000000000000			0001	0100	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$3,293.00	\$6,586.00
OST   0140   010103   ADVANCED WARRING PALL SYSTEM			0001	0125	6139911		17,618.00	-9,199.00	8,419.00	LB	8,419.00	\$4.00	\$33,676.00
0011 0150 01000			0001	0130	6161005	CONSTRUCTION SIGNS	3,356.00	165.00	3,521.00	SQFT	3,521.00	\$8.40	\$29,576.40
DO31			0001	0140	6161008	ADVANCED WARNING RAIL SYSTEM	47.00	0.00	47.00	EA	47.00	\$105.00	\$4,935.00
COST   0170   0161033   TYPE   III MOVEARE BARRICADE WITH LIGHTS   03.00   0.00   63.00   EA   63.00   \$210.00   \$133,230.00			0001	0150	6161009	FLAG ASSEMBLY	26.00	6.00	32.00	EA	32.00	\$26.20	\$838.40
0001   0110			0001	0160	6161024	CHANNELIZER (TRIM LINE) WITH LIGHT	200.00	-200.00	0.00	EA	0.00	\$21.00	\$0.00
0001   0190   01910			0001	0170	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	63.00	0.00	63.00	EA	63.00	\$210.00	\$13,230.00
0001   0200   6161052   WARNING LIGHT, TYPE B   15.00   0.00   15.00   EA   15.00   \$105.00   \$1.575			0001	0180	6161033	DIRECTIONAL INDICATOR BARRICADE	169.00	0.00	169.00	EA	169.00	\$26.20	\$4,427.80
0001   0210   6151055   SEQUENTIAL FLASHING WARNING LIGHT   198.00   0.00   189.00   EA   199.00   \$88.10   \$14.5503			0001	0190	6161040	FLASHING ARROW PANEL	11.00	0.00	11.00	EA	11.00	\$1,049.00	\$11,539.00
0001   0220   6161070   TUBULAR MARKER   310.00   0.00   310.00   EA   310.00   \$10.500   \$32,550.00			0001	0200	6161052	WARNING LIGHT, TYPE B	15.00	0.00	15.00	EA	15.00	\$105.00	\$1,575.00
0001   0230   6161098A   CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION   1,000   2,000   2,000   2,000   2,000   2,000   3,0			0001	0210	6161055	SEQUENTIAL FLASHING WARNING LIGHT	169.00	0.00	169.00	EA	169.00	\$86.10	\$14,550.90
NTERFACE, CONTRACTOR FURNISHED, CONTRACTOR   CONTRACTOR FURNISHED, CONTRACTOR   C			0001	0220	6161070	TUBULAR MARKER	310.00	0.00	310.00	EA	310.00	\$105.00	\$32,550.00
INTERFACE, CONTRACTOR PURISHED, CONTRACTOR			0001	0230	6161098A	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	2.00	0.00	2.00	EA	2.00	\$6,818.00	\$13,636.00
0001   0260   6169901   MISC.WORK.ZONE INTELLIGENT TRANSPORTATION SYSTEM   1.00   0.00   1.00   LS   1.00   \$87,058.00   \$87,058.00   \$87,058.00   0.001   0.001   0.001   0.001   0.002   0.001   0.002   0.001   0.002   0.001   0.002   0.001   0.002   0.001   0.002   0.001   0.002   0.001   0.002   0			0001	0240	6161099	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	6.00	0.00	6.00	EA	6.00	\$10,489.00	\$62,934.00
0001   0270   8173600D   TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / 3,350.00   75.00   3,425.00   LF   3,425.00   \$27.30   \$93,502.51			0001	0245	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	12.00	0.00	12.00	EA	12.00	\$787.00	\$9,444.00
RETAINED			0001	0260	6169901	MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM	1.00	0.00	1.00	LS	1.00	\$87,058.00	\$87,058.00
0001   0290   6181000   MOBILIZATION   1.00   0.00   1.00   LS   1.00   \$245,229.00   \$245,229.00   \$245,229.00   \$0001   0300   6189902			0001	0270	6173600D		3,350.00	75.00	3,425.00	LF	3,425.00	\$27.30	\$93,502.50
0001   0300   6189902   PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.   210.00   0.00   210.00   LF   210.00   \$26.20   \$5,502.00			0001	0280	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	3,263.00	200.00	3,463.00	LF	3,463.00	\$7.90	\$27,357.70
0001   0310   620015   PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.   210.00   0.00   210.00   LF   210.00   \$26.20   \$5,502.00			0001	0290	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$245,229.00	\$245,229.00
WHITE			0001	0300	6189902		4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
LEFT/RIGHT ARROW   C   C   C   C   C   C   C   C   C			0001	0310	6200015		210.00	0.00	210.00	LF	210.00	\$26.20	\$5,502.00
PAINT, TYPE L BEADS  0001 0340 6205903A 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT			0001	0320	6200021		3.00	0.00	3.00	EA	3.00	\$336.00	\$1,008.00
MARKING PAINT, TYPE L BEADS  0001 0350 6205906A 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT 400.00 0.00 400.00 LF 400.00 \$1.10 \$440.00 \$400.00 0.00 0.00 0.00 0.00 0.			0001	0330	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	14,043.00	0.00	14,043.00	LF	14,043.00	\$0.31	\$4,353.33
MARKING PAINT, TYPE L BEADS			0001	0340	6205903A		2,433.00	0.00	2,433.00	LF	2,433.00	\$0.73	\$1,776.09
PAINT, TYPE P BEADS  0001 0370 620601C 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT 17,975.00 0.00 17,975.00 LF 17,975.00 \$0.15 \$2,696.26			0001	0350	6205906A		400.00	0.00	400.00	LF	400.00	\$1.10	\$440.00
MARKING PAINT, TYPE P BEADS			0001	0360	6206000C		25,042.00	0.00	25,042.00	LF	25,042.00	\$0.15	\$3,756.30
0001         0380         6206124A         24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING         105.00         0.00         105.00         LF         105.00         \$5.20         \$546.00           0001         0390         6207001         PAVEMENT MARKING REMOVAL         60,208.00         0.00         60,208.00         LF         60,208.00         \$0.52         \$31,308.16           0001         0400         6207002         PAVEMENT MARKING REMOVAL (SYMBOLS)         3.00         0.00         3.00         EA         3.00         \$52.40         \$157.20           0001         0410         6224010         MODIFIED COLDMILLING (DEPTH TRANSITIONS)         1,930.00         834.30         2,764.30         SQYD         2,764.30         \$18.70         \$51,692.4°           0001         0420         6262000A         PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP         78.80         10.00         88.80         STA         88.80         \$157.00         \$13,941.60           0001         0430         8051000A         SEEDING - COOL SEASON MIXTURES         1.80         0.00         1.80         ACRE         0.00         \$3,409.00         \$0.00			0001	0370	6206001C		17,975.00	0.00	17,975.00	LF	17,975.00	\$0.15	\$2,696.25
0001         0390         6207001         PAVEMENT MARKING REMOVAL         60,208.00         0.00         60,208.00         LF         60,208.00         \$0.52         \$31,308.16           0001         0400         6207002         PAVEMENT MARKING REMOVAL (SYMBOLS)         3.00         0.00         3.00         EA         3.00         \$52.40         \$157.20           0001         0410         6224010         MODIFIED COLDMILLING (DEPTH TRANSITIONS)         1,930.00         834.30         2,764.30         \$QYD         2,764.30         \$18.70         \$51,692.41           0001         0420         6262000A         PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP         78.80         10.00         88.80         STA         88.80         \$157.00         \$13,941.60           0001         0430         8051000A         SEEDING - COOL SEASON MIXTURES         1.80         0.00         1.80         ACRE         0.00         \$3,409.00         \$0.00			0001	0380	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	105.00	0.00	105.00	LF	105.00	\$5.20	\$546.00
0001         0410         6224010         MODIFIED COLDMILLING (DEPTH TRANSITIONS)         1,930.00         834.30         2,764.30         SQYD         2,764.30         \$18.70         \$51,692.4*           0001         0420         6262000A         PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP         78.80         10.00         88.80         STA         88.80         \$157.00         \$13,941.60           0001         0430         8051000A         SEEDING - COOL SEASON MIXTURES         1.80         0.00         1.80         ACRE         0.00         \$3,409.00         \$0.00			0001	0390	6207001		60,208.00	0.00	60,208.00	LF	60,208.00	\$0.52	\$31,308.16
0001         0420         6262000A         PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP         78.80         10.00         88.80         STA         88.80         \$157.00         \$13,941.60           0001         0430         8051000A         SEEDING - COOL SEASON MIXTURES         1.80         0.00         1.80         ACRE         0.00         \$3,409.00         \$0.00			0001	0400	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	3.00	0.00	3.00	EA	3.00	\$52.40	\$157.20
0001 0430 8051000A SEEDING - COOL SEASON MIXTURES 1.80 0.00 1.80 ACRE 0.00 \$3,409.00 \$0.00			0001	0410	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,930.00	834.30	2,764.30	SQYD	2,764.30	\$18.70	\$51,692.41
			0001	0420	6262000A	PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP	78.80	10.00	88.80	STA	88.80	\$157.00	\$13,941.60
0001 0440 8061005 ROCK DITCH CHECK 800.00 -576.00 224.00 LF 224.00 \$12.10 \$2.710.40			0001	0430	8051000A	SEEDING - COOL SEASON MIXTURES	1.80	0.00	1.80	ACRE	0.00	\$3,409.00	\$0.00
25.7.10.40			0001	0440	8061005	ROCK DITCH CHECK	800.00	-576.00	224.00	LF	224.00	\$12.10	\$2,710.40

Page 4 of 27 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190315-D03	J5P3287	0001	0450	8061006	ALTERNATE DITCH CHECK	125.00	-125.00	0.00	LF	0.00	\$10.50	\$0.00
		0001	0460	8061016	SEDIMENT REMOVAL	113.00	0.00	113.00	CUYD	0.00	\$26.80	\$0.00
		0001	0470	8061019	SILT FENCE	9,495.00	-4,445.00	5,050.00	LF	5,050.00	\$2.40	\$12,120.00
		0001	0480	8061050	TYPE C BERM	1,815.00	-1,815.00	0.00	LF	0.00	\$24.90	\$0.00
		0010	0490	6061060	MGS GUARDRAIL	1,938.00	-175.00	1,763.00	LF	1,763.00	\$25.20	\$44,427.60
		0010	0500	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	7.00	0.00	7.00	EA	7.00	\$3,252.00	\$22,764.00
		0010	0510	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	2.00	\$1,259.00	\$2,518.00
		0010	0520	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	10.00	0.00	10.00	EA	10.00	\$3,094.00	\$30,940.00
		0070	0530	2161501	REMOVAL OF ASPHALT WEARING SURFACE	5,830.00	0.00	5,830.00	SQFT	5,830.00	\$3.50	\$20,405.00
		0070	0540	2161503	REMOVAL OF EXISTING DECK REPAIR	290.00	-290.00	0.00	SQFT	0.00	\$41.50	\$0.00
		0070	0550	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	648.00	0.00	648.00	SQYD	648.00	\$123.00	\$79,704.00
		0070	0560	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	100.00	165.00	265.00	SQFT	265.00	\$136.00	\$36,040.00
		0070	0570	7040104	HALF-SOLE REPAIR	300.00	775.00	1,075.00	SQFT	1,075.00	\$87.20	\$93,740.00
		0070	0580	7040106	FULL DEPTH REPAIR	50.00	-50.00	0.00	SQFT	0.00	\$80.10	\$0.00
		0070	0590	7040107	SLAB EDGE REPAIR (BRIDGES)	110.00	29.00	139.00	LF	139.00	\$148.00	\$20,572.00
		0070	0600	7040109	TOTAL SURFACE HYDRO DEMOLITION	342.00	0.00	342.00	SQYD	342.00	\$38.00	\$12,996.00
		0070	0610	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	50.00	-50.00	0.00	SQFT	0.00	\$143.00	\$0.00
		0070	0620	7040113	CLEAN AND EPOXY SEAL	660.00	0.00	660.00	SQFT	660.00	\$9.40	\$6,204.00
		0070	0630	7040115	HYDRO SURFACE PROFILING	306.00	0.00	306.00	SQYD	306.00	\$19.90	\$6,089.40
		0070	0640	7040117	MONOLITHIC DECK REPAIR	5.00	-4.00	1.00	CUYD	1.00	\$700.00	\$700.00
		0071	0650	2161501	REMOVAL OF ASPHALT WEARING SURFACE	6,535.00	0.00	6,535.00	SQFT	6,535.00	\$3.10	\$20,258.50
		0071	0660	2161503	REMOVAL OF EXISTING DECK REPAIR	65.00	-65.00	0.00	SQFT	0.00	\$41.50	\$0.00
		0071	0670	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	726.00	0.00	726.00	SQYD	726.00	\$120.00	\$87,120.00
		0071	0680	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	400.00	-171.00	229.00	SQFT	229.00	\$125.00	\$28,625.00
		0071	0690	7040104	HALF-SOLE REPAIR	300.00	1,408.00	1,708.00	SQFT	1,708.00	\$87.20	\$148,937.60
		0071	0700	7040106	FULL DEPTH REPAIR	50.00	-50.00	0.00	SQFT	0.00	\$80.10	\$0.00
		0071	0710	7040107	SLAB EDGE REPAIR (BRIDGES)	80.00	58.00	138.00	LF	138.00	\$174.00	\$24,012.00
		0071	0720	7040109	TOTAL SURFACE HYDRO DEMOLITION	384.00	0.00	384.00	SQYD	384.00	\$54.50	\$20,928.00
		0071	0730	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	50.00	-16.00	34.00	SQFT	34.00	\$143.00	\$4,862.00
		0071	0740	7040113	CLEAN AND EPOXY SEAL	770.00	0.00	770.00	SQFT	770.00	\$9.40	\$7,238.00
		0071	0750	7040115	HYDRO SURFACE PROFILING	342.00	0.00	342.00	SQYD	342.00	\$19.90	\$6,805.80
		0071	0760	7040117	MONOLITHIC DECK REPAIR	6.00	17.00	23.00	CUYD	23.00	\$700.00	\$16,100.00
		0072	0770	2161500	REMOVAL OF SEAL COAT OR POLYMER WEARING SURFACE	15,402.00	0.00	15,402.00	SQFT	15,402.00	\$0.98	\$15,093.96
		0072	0780	2161503	REMOVAL OF EXISTING DECK REPAIR	1,100.00	1,102.00	2,202.00	SQFT	2,202.00	\$38.30	\$84,336.60
		0072	0790	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,711.00	0.00	1,711.00	SQYD	1,711.00	\$94.70	\$162,031.70
		0072	0800	7034600	CURB BLOCKOUT	475.00	0.00	475.00	LF	475.00	\$83.10	\$39,472.50
		0072	0810	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	100.00	124.00	224.00	SQFT	224.00	\$133.00	\$29,792.00
		0072	0820	7040106	FULL DEPTH REPAIR	150.00	-150.00	0.00	SQFT	0.00	\$76.10	\$0.00
		0072	0830	7040107	SLAB EDGE REPAIR (BRIDGES)	140.00	20.00	160.00	LF	160.00	\$145.00	\$23,200.00
		0072	0840	7040109	TOTAL SURFACE HYDRO DEMOLITION	1,711.00	-1,711.00	0.00	SQYD	0.00	\$25.50	\$0.00
		0072	0850	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	600.00	-323.00	277.00	SQFT	277.00	\$81.60	\$22,603.20
		0072	0860	7040113	CLEAN AND EPOXY SEAL	2,889.00	0.00	2,889.00	SQFT	2,889.00	\$9.40	\$27,156.60
		0072	0870	7040117	MONOLITHIC DECK REPAIR	33.00	-1.00	32.00	CUYD	32.00	\$700.00	\$22,400.00
		0072	0880	7172054	OPEN CELL FOAM JOINT SEAL	137.00	0.00	137.00	LF	137.00	\$71.00	\$9,727.00
		0073	0890	2161501	REMOVAL OF ASPHALT WEARING SURFACE	5,194.00	0.00	5,194.00	SQFT	5,194.00	\$3.90	\$20,256.60
		0073	0900	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	-100.00	0.00	SQFT	0.00	\$41.50	\$0.00
A												

Page 5 of 27 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190315-D03	J5P3287	0073	0910	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	577.00	0.00	577.00	SQYD	577.00	\$138.00	\$79,626.00
		0073	0920	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	100.00	68.00	168.00	SQFT	168.00	\$133.00	\$22,344.00
		0073	0930	7040104	HALF-SOLE REPAIR	300.00	371.00	671.00	SQFT	671.00	\$87.20	\$58,511.20
		0073	0940	7040106	FULL DEPTH REPAIR	50.00	-50.00	0.00	SQFT	0.00	\$80.10	\$0.00
		0073	0950	7040107	SLAB EDGE REPAIR (BRIDGES)	90.00	50.00	140.00	LF	140.00	\$153.00	\$21,420.00
		0073	0960	7040109	TOTAL SURFACE HYDRO DEMOLITION	311.00	0.00	311.00	SQYD	311.00	\$44.00	\$13,684.00
		0073	0970	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	50.00	-50.00	0.00	SQFT	0.00	\$143.00	\$0.00
		0073	0980	7040113	CLEAN AND EPOXY SEAL	594.00	0.00	594.00	SQFT	594.00	\$9.40	\$5,583.60
		0073	0990	7040115	HYDRO SURFACE PROFILING	266.00	0.00	266.00	SQYD	266.00	\$19.90	\$5,293.40
		0073	1000	7040117	MONOLITHIC DECK REPAIR	3.00	-3.00	0.00	CUYD	0.00	\$700.00	\$0.00
		0074	1010	2161501	REMOVAL OF ASPHALT WEARING SURFACE	5,149.00	0.00	5,149.00	SQFT	5,149.00	\$5.30	\$27,289.70
		0074	1020	2161503	REMOVAL OF EXISTING DECK REPAIR	250.00	-172.00	78.00	SQFT	78.00	\$41.50	\$3,237.00
		0074	1030	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	85.00	0.00	85.00	LF	85.00	\$40.30	\$3,425.50
		0074	1040	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	572.00	0.00	572.00	SQYD	572.00	\$139.00	\$79,508.00
		0074	1050	7039902	MISC.PLUGGING EXISTING CURB OUTLET	24.00	8.00	32.00	EA	32.00	\$171.00	\$5,472.00
		0074	1060	7040101	SUBSTRUCTURE REPAIR (FORMED)	20.00	9.00	29.00	SQFT	29.00	\$156.00	\$4,524.00
		0074	1070	7040109	TOTAL SURFACE HYDRO DEMOLITION	572.00	0.00	572.00	SQYD	572.00	\$33.00	\$18,876.00
		0074	1080	7040113	CLEAN AND EPOXY SEAL	1,470.00	0.00	1,470.00	SQFT	1,103.00	\$9.40	\$10,368.20
		0074	1090	7040117	MONOLITHIC DECK REPAIR	7.00	-2.00	5.00	CUYD	5.00	\$700.00	\$3,500.00
		0074	1100	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.75	\$6,293.00	\$4,719.75
		0074	1110	7129902	(EPOXY) MISC.CORED SLAB DRAINS	18.00	0.00	18.00	EA	18.00	\$380.00	\$6,840.00
		0074	1120	7172054	OPEN CELL FOAM JOINT SEAL	85.00	0.00	85.00	LF	85.00	\$71.40	\$6,069.00
		0075	1130	2161501	REMOVAL OF ASPHALT WEARING SURFACE	10,834.00	0.00	10,834.00	SQFT	10,834.00	\$2.20	\$23,834.80
		0075	1140	2161503	REMOVAL OF EXISTING DECK REPAIR	280.00	-280.00	0.00	SQFT	0.00	\$41.50	\$0.00
		0075	1150	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	84.00	0.00	84.00	LF	84.00	\$215.00	\$18,060.00
		0075	1160	2169902	CONCRETE MISC.REMOVAL OF EXISTING BEARINGS	5.00	0.00	5.00	EA	5.00	\$2,756.00	\$13,780.00
		0075	1170	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	16.00	0.00	16.00	LF	16.00	\$359.00	\$5,744.00
		0075	1180	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,209.00	0.00	1,209.00	SQYD	1,209.00	\$111.00	\$134,199.00
		0075	1190	7031004	DIAMOND GRINDING	1,209.00	-1,209.00	0.00	SQYD	0.00	\$15.00	\$0.00
		0075	1200	7034001	CLASS B-1 CONCRETE	35.00	7.00	42.00	CUYD	35.00	\$857.00	\$29,995.00
		0075	1210	7040106	FULL DEPTH REPAIR	100.00	-100.00	0.00	SQFT	0.00	\$74.10	\$0.00
		0075	1220	7040109	TOTAL SURFACE HYDRO DEMOLITION	1,204.00	0.00	1,204.00	SQYD	1,204.00	\$26.10	\$31,424.40
		0075	1230	7040113	CLEAN AND EPOXY SEAL	30.00	0.00	30.00	SQFT	0.00	\$9.40	\$0.00
		0075	1240	7040117	MONOLITHIC DECK REPAIR	13.00	23.00	36.00	CUYD	36.00	\$700.00	\$25,200.00
		0075	1250	7101000	REINFORCING STEEL (EPOXY COATED)	1,630.00	0.00	1,630.00	LB	1,630.00	\$3.40	\$5,542.00
		0075	1260	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	1.00	0.00	1.00	LS	0.00	\$6,293.00	\$0.00
		0075	1270	7125102	(EPOXY) SURFACE PREPARATION FOR APPLYING EPOXY-MASTIC	1.00	0.00	1.00	LS	1.00	\$10,489.00	\$10,489.00
		0075	1280	7125961	PRIMER GRAY EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	1.00	\$10,489.00	\$10,489.00
		0075	1290	7129902	MISC.Slab Drain Extension	24.00	0.00	24.00	EA	24.00	\$479.00	\$11,496.00
		0075	1300	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	5.00	0.00	5.00	EA	5.00	\$2,240.00	\$11,200.00
		0075	1310	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	42.00	0.00	42.00	LF	42.00	\$631.00	\$26,502.00
		0076	1320	2161501	REMOVAL OF ASPHALT WEARING SURFACE	12,006.00	0.00	12,006.00	SQFT	12,006.00	\$1.70	\$20,410.20
		0076	1330	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	158.00	0.00	158.00	LF	158.00	\$27.10	\$4,281.80
		0076	1340	2169902	MISC.REMOVAL OF EXISTING BEARINGS	10.00	0.00	10.00	EA	10.00	\$2,646.00	\$26,460.00
		0076	1350	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,344.00	0.00	1,344.00	SQYD	1,344.00	\$110.00	\$147,840.00
												. /

Page 6 of 27 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190315-D03	J5P3287	0076	1360	7040115	HYDRO SURFACE PROFILING	1,344.00	0.00	1,344.00	SQYD	1,344.00	\$25.50	\$34,272.00
		0076	1370	7040117	MONOLITHIC DECK REPAIR	5.00	40.00	45.00	CUYD	45.00	\$700.00	\$31,500.00
		0076	1380	7129902	MISC.LUBRICATE AND RESET ROCKER BEARINGS	5.00	0.00	5.00	EA	5.00	\$4,237.00	\$21,185.00
		0076	1390	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	10.00	0.00	10.00	EA	10.00	\$2,185.00	\$21,850.00
		0076	1400	7172054	OPEN CELL FOAM JOINT SEAL	158.00	0.00	158.00	LF	158.00	\$71.40	\$11,281.20
		0001	5001	6161025	CHANNELIZER (TRIM LINE)	0.00	250.00	250.00	EA	221.00	\$19.00	\$4,199.00
		0072	5002	1046002	VALUE ENGINEERING	0.00	5,000.00	5,000.00	EA	5,000.00	\$1.00	\$5,000.00
		0072	5003	7040109	TOTAL SURFACE HYDRO DEMOLITION	0.00	1,711.00	1,711.00	SQYD	1,711.00	\$19.66	\$33,630.49
		0001	5004	6189901	MISC.Misc. Mobilization	0.00	1.00	1.00	LS	1.00	\$4,600.00	\$4,600.00
		0001	5005	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	0.00	256.00	256.00	TONS	256.00	\$208.32	\$53,329.92
		0001	5006	4071005	TACK COAT	0.00	250.00	250.00	GAL	250.00	\$4.20	\$1,050.00
		0071	5007	1094000	FORCE ACCOUNT	0.00	1.00	1.00	EA	1.00	\$41,388.75	\$41,388.75
		0001	5008	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	0.00	117.60	117.60	TONS	117.60	\$65.00	\$7,644.00
		0001	5009	4039902	MISC.Equipment/Labor Cost for SP125 Installation	0.00	1.00	1.00	EA	1.00	\$20,961.78	\$20,961.78
		0001	5010	4071005	TACK COAT	0.00	115.00	115.00	GAL	115.00	\$3.25	\$373.75
		0001	5011	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$2,500.00	\$2,500.00
		0001	5012	4019905	MISC.Optional 10" Shoulder Pavement	0.00	5,177.00	5,177.00	SQYD	5,177.00	\$48.80	\$252,637.60
		0076	5013	2169901	MISC.Lump Sum payment for additional deck milling	0.00	1.00	1.00	LS	1.00	\$3,062.84	\$3,062.84
		0001	5014	4019901	MISC.Sample of Existing Asphalt Wearing Surface	0.00	1.00	1.00	LS	1.00	\$1,183.21	\$1,183.21
		0072	5015	7049902	MISC.CORED VOID TUBE WEEPHOLES	0.00	912.00	912.00	EA	912.00	\$31.08	\$28,344.96
		0010	5025	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	0.00	175.00	175.00	LF	175.00	\$29.20	\$5,110.00
	Project J	5P3287 - To	tal Value	Posted to D	late as of Report Generated Date							\$3,949,766.40
190315-D03 Ove	rall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$3,949,766.40

Page 7 of 27 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details from Line Item agency views.

No Agency View Details Exist

Revision 4/1/2020 Page 8 of 27



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0040	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		4	Jul 17, 2019	SYSTEM	(\$17,884.83)	
				5	Aug 2, 2019	SYSTEM	(\$34,342.11)	
				6	Aug 16, 2019	SYSTEM	(\$34,342.11)	
			- Total				(\$86,569.05)	
	Material - Total						(\$86,569.05)	
	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	MaterialCredit		5	Aug 2, 2019	SYSTEM	\$17,884.83	
				6	Aug 16, 2019	SYSTEM	\$34,342.11	
				7	Sep 4, 2019	SYSTEM	\$34,342.11	
			- Total				\$86,569.05	
	MaterialCredit - Total						\$86,569.05	
	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Other Item Adjustment	OTHR	12	Nov 18, 2019	mantlc1	\$48,146.10	10" shoulders temporarily being paid under line numbers 0040 and 0050 until no cost change order is processed.
				15	Jan 2, 2020	mantlc1	(\$48,146.10)	
			OTHR - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0040 -	· Total						\$0.00	
0050	MISC. OPTIONAL 8" SHOULDER PAVEMENT	Material		4	Jul 17, 2019	SYSTEM	(\$75,962.45)	
				5	Aug 2, 2019	SYSTEM	(\$121,329.78)	
				6	Aug 16, 2019	SYSTEM	(\$121,329.78)	
				7	Sep 4, 2019	SYSTEM	(\$121,329.78)	
				8	Sep 16, 2019	SYSTEM	(\$121,329.78)	
				9	Oct 2, 2019	SYSTEM	(\$121,329.78)	
				10	Oct 17, 2019	SYSTEM	(\$145,873.50)	
				11	Nov 5, 2019	SYSTEM	(\$145,873.50)	
				12	Nov 18, 2019	SYSTEM	(\$145,873.50)	
				13	Dec 3, 2019	SYSTEM	(\$145,873.50)	
			- Total				(\$1,266,105.35)	
	Material - Total					01/2=	(\$1,266,105.35)	
	MISC. OPTIONAL 8" SHOULDER PAVEMENT	MaterialCredit		5	Aug 2, 2019	SYSTEM	\$75,962.45	
				6	Aug 16, 2019	SYSTEM	\$121,329.78	
				7	Sep 4, 2019	SYSTEM	\$121,329.78	
				8	Sep 16, 2019	SYSTEM	\$121,329.78	
				9	Oct 2, 2019	SYSTEM	\$121,329.78	
				10	Oct 17, 2019	SYSTEM	\$121,329.78	
				11	Nov 5, 2019	SYSTEM	\$145,873.50	
				12	Nov 18, 2019	SYSTEM	\$145,873.50	
	4/4/9000			13	Dec 3, 2019	SYSTEM	\$145,873.50	

Revision 4/1/2020 Page 9 of 27



Majorial Cheek	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
MaterialCriedit   Total	0050		MaterialCredit	Туре	14		SYSTEM	\$145,873.50	
Misc OFTIONAL 7' SHOULDER   Chart temperature   12		PAVEIVIENT		- Total		2019		\$1 266 105 35	
MISC CPTONAL 8* SHOULDER, Adjustment   CAPILLER   CAP		MaterialCredit - Total		Total					
PAVEMENT   Adjustment   2019   2019   2000			Other Item	OTHR	12	Nov 18	mantlc1		10" shoulders temporarily being paid under line numbers 0040 and
2019   2019				OTTIK		2019			
2019   15   2020   20					15		manuci	ψ000,000.00	
Color   Internal Color   Col					14		mantlc1	(\$350,368.95)	
Other Itom Adjustment - Total   Superior					15		mantlc1	(\$350,368.95)	
1000   ULTRATHIN BONDED WEARING SURFACE, TYPE C   Total   CASS, 5.50				OTHR - Tota	al			\$0.00	
		Other Item Adjustment - Total						\$0.00	
SURFACE, TYPE C	0050 -	Total						\$0.00	
Material   Total	0060		Material		5	Aug 2, 2019	SYSTEM	(\$42,536.50)	
ULTRATHIN BONDED MEARING   SURFACE, TYPE   S				- Total				(\$42,536.50)	
SURFACE_TYPE_C   Part		Material - Total						(\$42,536.50)	
Material Credit - Total   \$42,586.50			MaterialCredit		6		SYSTEM	\$42,536.50	
Material - Total				- Total				\$42,536.50	
Material - Total		MaterialCredit - Total						\$42,536.50	
CAND BARRELS	0060 -	Total						\$0.00	
Material - Total	0070		Material		4		SYSTEM	(\$4,405.00)	
IMPACT ATTENUATOR 70 MPH (SAND BARRELS)				- Total				(\$4,405.00)	
CONSTRUCTION SIGNS   2019   34,405.00		Material - Total						(\$4,405.00)	
Material Credit - Total   \$4,405.00			MaterialCredit		5		SYSTEM	\$4,405.00	
MISC. CLASS A PARTIAL DEPTH PAVEMENT REPAIR - USING FLEXIBLE. HOT POLYMER MODIFIED REPAIR MATERIAL.   Solution   Solut				- Total				\$4,405.00	
MISC. CLASS A PARTIAL DEPTH PAVEMENT REPAIR - USING FLEXIBLE, HOT POLYMER MODIFIED REPAIR MATERIAL   - Total   (\$33,676.00)		MaterialCredit - Total						\$4,405.00	
PAVEMENT REPAIR USING FLEXIBLE, HOT POLYMER-MODIFIED REPAIR MATERIAL  - Total  Material - Total  MiSC. CLASS A PARTIAL DEPTH PAVEMENT REPAIR - USING FLEXIBLE, HOT POLYMER-MODIFIED REPAIR MATERIAL  - Total  MaterialCredit - Total  MaterialCredit - Total  MISC. CLASS A PARTIAL DEPTH PAVEMENT REPAIR - USING FLEXIBLE, HOT POLYMER-MODIFIED REPAIR MATERIAL  - Total  MISC. CLASS A PARTIAL DEPTH PAVEMENT REPAIR - USING FLEXIBLE, HOT POLYMER-MODIFIED REPAIR MATERIAL  - Total  MISC. CLASS A PARTIAL DEPTH PAVEMENT REPAIR - USING FLEXIBLE, HOT POLYMER-MODIFIED REPAIR MATERIAL  OTHR - Total  -	0070 -	Total						\$0.00	
Material - Total  MISC. CLASS A PARTIAL DEPTH PAVEMENT REPAIR - USING FLEXIBLE, HOT POLYMER-MODIFIED REPAIR MATERIAL  - Total  MaterialCredit - Total  MaterialCredit - Total  MISC. CLASS A PARTIAL DEPTH PAVEMENT REPAIR - USING FLEXIBLE, HOT POLYMER-MODIFIED REPAIR MATERIAL  - Total  MISC. CLASS A PARTIAL DEPTH PAVEMENT REPAIR - USING FLEXIBLE, HOT POLYMER-MODIFIED REPAIR NATERIAL  OTHER - TOTAL  SO.00  OTHER - TOTAL  ONDIFICE SIGNS  OTHER - TOTAL  ONDIFICE SIGNS  OTHER - TOTAL  ONDIFICE SIGNS  OTHER - TOTAL  OTHER - TOTAL  SO.00  OTHER - TOTAL  OTHER - TOTAL  SO.00  OTHER - TOTA	0125	PAVEMENT REPAIR - USING FLEXIBLE, HOT POLYMER-	Material		4		SYSTEM	(\$33,676.00)	
MISC. CLASS A PARTIAL DEPTH PAVEMENT REPAIR - USING FLEXIBLE, HOT POLYMER-MODIFIED REPAIR MATERIAL  -Total  MaterialCredit - Total  MISC. CLASS A PARTIAL DEPTH PAVEMENT REPAIR - USING PAVEMENT REPAIR DISTRICT POLYMER-MODIFIED REPAIR MATERIAL  OTHER - Total  OTHER - Total  OTHER - Total  SO.00  OTHER - Total  SO.00  CONSTRUCTION SIGNS  OTHER - Total  OADJ - Total  OADJ - Total  OADJ - Total  SO.00  OADJ - TOT				- Total				(\$33,676.00)	
PAVEMENT REPAIR - USING FLEXIBLE. HOT POLYMER-MODIFIED REPAIR MATERIAL  - Total  - Total  S33,676.00  MaterialCredit - Total  MISC. CLASS A PARTIAL DEPTH PAVEMENT REPAIR - USING FLEXIBLE, HOT POLYMER-MODIFIED REPAIR MATERIAL  OTHR - Jul 17, 2019  OTHR - Total  OADJ 23 Jul 1, 2020 mantlc1 (\$1,386.00)  CONSTRUCTION SIGNS  OTHR - Total  OADJ - Total  OTHR - Total  S1,386.00  Payment for overrun. This adjustment will be negated once a change order is processed.  OTHR - Total  OTHR - Total  S1,386.00  Payment for overrun. This adjustment will be negated once a change order is processed.		Material - Total						(\$33,676.00)	
MaterialCredit - Total  MISC. CLASS A PARTIAL DEPTH PAVEMENT REPAIR - USING FLEXIBLE, HOT POLYMER-MODIFIED REPAIR MATERIAL  OTHR - Total  OTHR - Total  OTHR - Total  OADJ - Total  CONSTRUCTION SIGNS  CONSTRUCTION SIGNS  OTHR - Total  S33,676.00  A pre-approved product was used for this item following the manufacturers recommendations. Waiting on a sample record.  (\$33,676.00)  Manufacturers recommendations.  A pre-approved product was used for this item following the manufacturers recommendations.  A pre-approved product was used for this item following the manufacturers recommendations.  A pre-approved product was used for this item following the manufacturers recommendations.  A pre-approved product was used for this item following the manufacturers recommendations.  A pre-approved product was used for this item following the manufacturers recommendations.  A pre-approved product was used for this item following the manufacturers recommendations.  A pre-approved product was used for this item		PAVEMENT REPAIR - USING FLEXIBLE, HOT POLYMER-	MaterialCredit		5		SYSTEM	\$33,676.00	
MISC. CLASS A PARTIAL DEPTH PAVEMENT REPAIR - USING FLEXIBLE, HOT POLYMER-MODIFIED REPAIR MATERIAL  OTHR - Total  Sa33,676.00  A pre-approved product was used for this item following the manufacturers recommendations. Waiting on a sample record.  (\$33,676.00)  A pre-approved product was used for this item following the manufacturers recommendations. Waiting on a sample record.  Sa33,676.00  A pre-approved product was used for this item following the manufacturers recommendations. Waiting on a sample record.  Sa33,676.00  A pre-approved product was used for this item following the manufacturers recommendations. Waiting on a sample record.  Sa33,676.00  OTHR - Total  Sa33,676.00  A pre-approved product was used for this item following the manufacturers recommendations. Waiting on a sample record.  Sa33,676.00  A pre-approved product was used for this item following the manufacturers recommendations. Waiting on a sample record.  Sa33,676.00  A pre-approved product was used for this item following the manufacturers recommendations.  Sa33,676.00  A pre-approved product was used for this item following the manufacturers recommendations.  Sa33,676.00  A pre-approved product was used for this item following the manufacturers recommendations.  Sa33,676.00  A pre-approved product was used for this item following the manufacturers recommendations.  Sa3,676.00  A pre-approved product was used for the manufacturers recommendations.  Sa3,676.00  A				- Total				\$33,676.00	
PAVEMENT REPAIR - USING FLEXIBLE, HOT POLYMER-MODIFIED REPAIR MATERIAL  OTHR - Total  OCHOR Item Adjustment  OCH		MaterialCredit - Total						\$33,676.00	
MODIFIED REPAIR MATERIAL  OTHR - Total  OTHR - Total  OCHOR Item Adjustment  OCHOR ITEM ITEM ITEM ITEM ITEM ITEM ITEM ITEM		PAVEMENT REPAIR - USING		OTHR	4		mantlc1	\$33,676.00	
Other Item Adjustment - Total  CONSTRUCTION SIGNS  Other Item Adjustment  OADJ 23 Jul 1, 2020 mantlc1 (\$1,386.00)  CONSTRUCTION SIGNS  CONSTRUCTION SIGNS  OADJ - Total  CONSTRUCTION SIGNS  OADJ - Total  SOMD (\$1,386.00)  OTHR - Total  S1,386.00  Payment for overrun. This adjustment will be negated once a change order is processed.					14		mantlc1	(\$33,676.00)	
O125 - Total  CONSTRUCTION SIGNS Other Item Adjustment OADJ 23 Jul 1, 2020 mantlc1 (\$1,386.00) Negating a previous adjustment for an overrun that has since been processed.  CONSTRUCTION SIGNS OTHR 20 May 19, 2020 mantlc1 \$1,386.00 Payment for overrun. This adjustment will be negated once a change order is processed.				OTHR - Tota	al			\$0.00	
O130 CONSTRUCTION SIGNS Other Item Adjustment  CONSTRUCTION SIGNS Other Item Adjustment  CONSTRUCTION SIGNS OTHR - Total  CONSTRUCTION SIGNS OTHR - Total  CONSTRUCTION SIGNS OTHR - Total  OADJ - 23		Other Item Adjustment - Total						\$0.00	
Adjustment 2020 processed.  OADJ - Total (\$1,386.00)  OTHR 20 May 19, 2020 Payment for overrun. This adjustment will be negated once a change order is processed.  OTHR - Total \$1,386.00 Payment for overrun. This adjustment will be negated once a change order is processed.	0125 -	Total						\$0.00	
CONSTRUCTION SIGNS  OTHR 20 May 19, 2020 mantlc1 \$1,386.00 Payment for overrun. This adjustment will be negated once a change order is processed.  OTHR - Total \$1,386.00	0130	CONSTRUCTION SIGNS		OADJ	23		mantlc1	(\$1,386.00)	
				OADJ - Tota	al			(\$1,386.00)	
		CONSTRUCTION SIGNS		OTHR	20	May 19, 2020	mantlc1	\$1,386.00	
Other Item Adjustment - Total \$0.00				OTHR - Tota	al			\$1,386.00	
		Other Item Adjustment - Total						\$0.00	

Revision 4/1/2020 Page 10 of 27



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0130	CONSTRUCTION SIGNS	Overrun	Overrun	17	Apr 3, 2020	SYSTEM	(\$1,050.00)	
				18	Apr 17, 2020	SYSTEM	(\$336.00)	
				23	Jul 1, 2020	SYSTEM	\$1,386.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',8.40000 - 8.40000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0130 -	· Total						\$0.00	
0150	FLAG ASSEMBLY	Other Item Adjustment	OADJ	23	Jul 1, 2020	mantlc1	(\$157.20)	Negating a previous adjustment for an overrun that has since been processed.
			OADJ - Tota	ıl			(\$157.20)	
	FLAG ASSEMBLY		OTHR	20	May 19, 2020	mantlc1	\$157.20	Payment for overrun. This adjustment will be negated once a change order is processed.
			OTHR - Tota	al			\$157.20	
	Other Item Adjustment - Total						\$0.00	
	FLAG ASSEMBLY	Overrun	Overrun	17	Apr 3, 2020	SYSTEM	(\$157.20)	
				23	Jul 1, 2020	SYSTEM	\$157.20	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',26.20000 - 26.20000, 'is applied (if non-zero).
			Overrun - To	otal			\$0.00	
	Overrun - Total						\$0.00	
0150 -							\$0.00	
0245	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		4	Jul 17, 2019	SYSTEM	(\$3,148.00)	
	NOMBLE OTTAL			5	Aug 2, 2019	SYSTEM	(\$3,148.00)	
			- Total		-0.0		(\$6,296.00)	
	Material - Total		. Otto				(\$6,296.00)	
	TEMPORARY LONG-TERM RUMBLE STRIPS	MaterialCredit		5	Aug 2, 2019	SYSTEM	\$3,148.00	
				6	Aug 16, 2019	SYSTEM	\$3,148.00	
			- Total				\$6,296.00	
	MaterialCredit - Total						\$6,296.00	
0245 -	· Total						\$0.00	
0270	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Material		4	Jul 17, 2019	SYSTEM	(\$18,427.50)	
			- Total				(\$18,427.50)	
	Material - Total						(\$18,427.50)	
	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	MaterialCredit		5	Aug 2, 2019	SYSTEM	\$18,427.50	
			- Total				\$18,427.50	
	MaterialCredit - Total						\$18,427.50	
0270 -							\$0.00	
0290	MOBILIZATION	Other Item Adjustment	OTHR	2	Jun 18, 2019	mantlc1	\$21,177.75	VE 19-14 has been approved on all levels and will appear on a future change order under Line No. 5011.
								Line item 0840 - Total Surface Hydro Demolition, will be removed and replaced with a contingent item, allowing for this payment.
								830.50 SY @ \$25.50 per SY = \$21,177.75
								Will temporarily be paid as mobilization and adjusted on a future estimate.
				3	Jul 1, 2019	mantlc1	(\$21,177.75)	Removing adjustment from Estimate 002. In estimate 002 this amount was paid for total surface hydro demolition. Since, line item 5003 (Total Surface Hydro Demolition) has been created and this payment amount was moved to that line item.
			OTHR - Tota	al			\$0.00	

Revision 4/1/2020 Page 11 of 27



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0290	Other Item Adjustment - Total						\$0.00	
0290 -	- Total						\$0.00	
0330	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		5	Aug 2, 2019	SYSTEM	(\$828.94)	
			- Total				(\$828.94)	
	Material - Total						(\$828.94)	
	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	MaterialCredit		6	Aug 16, 2019	SYSTEM	\$828.94	
			- Total				\$828.94	
	MaterialCredit - Total						\$828.94	
	- Total						\$0.00	
0360	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		2	Jun 18, 2019	SYSTEM	(\$234.75)	
			- Total				(\$234.75)	
	Material - Total						(\$234.75)	
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	MaterialCredit		3	Jul 1, 2019	SYSTEM	\$234.75	
			- Total				\$234.75	
	MaterialCredit - Total						\$234.75	
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT TYPE P READS	Other Item Adjustment	OTHR	14	Dec 18, 2019	mantlc1	(\$234.75)	
	MARKING PAINT, TYPE P BEADS			20	May 19, 2020	mantlc1	\$892.35	Payment for overrun. This adjustment will be negated once a change order is processed.
				21	Jun 2, 2020	mantlc1	(\$892.35)	Negating a previous item adjustment
			OTHR - Total	-1				
			OTHK - TOL	ai			(\$234.75)	
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS		OTHR - TOL	2	Jun 18, 2019	mantlc1	\$234.75 \$234.75	Paint and bead certifications are submitted from the contractor in project file. Need to be reviewed and submitted to AASHTOWare.
	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS		- Total			mantlc1		contractor in project file. Need to be reviewed and
	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Other Item Adjustment - Total		- Total	2			\$234.75 \$234.75 \$0.00	contractor in project file. Need to be reviewed and
	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun		17	2019 Apr 3, 2020	SYSTEM	\$234.75 \$234.75 \$0.00 (\$408.60)	contractor in project file. Need to be reviewed and
	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Other Item Adjustment - Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT	Overrun	- Total	2	2019 Apr 3,		\$234.75 \$234.75 \$0.00	contractor in project file. Need to be reviewed and
	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Other Item Adjustment - Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT	Overrun	- Total	17	2019 Apr 3, 2020 May 4,	SYSTEM	\$234.75 \$234.75 \$0.00 (\$408.60)	contractor in project file. Need to be reviewed and
	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Other Item Adjustment - Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT	Overrun	- Total	17 19 21	Apr 3, 2020 May 4, 2020 Jun 2,	SYSTEM SYSTEM	\$234.75 \$234.75 \$0.00 (\$408.60) (\$483.75)	contractor in project file. Need to be reviewed and submitted to AASHTOWare.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of
	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Other Item Adjustment - Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT	Overrun	- Total Overrun	17 19 21	Apr 3, 2020 May 4, 2020 Jun 2,	SYSTEM SYSTEM	\$234.75 \$234.75 \$0.00 (\$408.60) (\$483.75) \$892.35	contractor in project file. Need to be reviewed and submitted to AASHTOWare.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of
0360 -	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Other Item Adjustment - Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun	- Total Overrun	17 19 21	Apr 3, 2020 May 4, 2020 Jun 2,	SYSTEM SYSTEM	\$234.75 \$234.75 \$0.00 (\$408.60) (\$483.75) \$892.35	contractor in project file. Need to be reviewed and submitted to AASHTOWare.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of
<b>0360</b> - <b>0370</b>	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Other Item Adjustment - Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Overrun - Total		- Total Overrun	17 19 21	Apr 3, 2020 May 4, 2020 Jun 2,	SYSTEM SYSTEM	\$234.75 \$0.00 (\$408.60) (\$483.75) \$892.35 \$0.00	contractor in project file. Need to be reviewed and submitted to AASHTOWare.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of
	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Other Item Adjustment - Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Overrun - Total  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT		- Total Overrun	17 19 21	Apr 3, 2020 May 4, 2020 Jun 2, 2020	SYSTEM SYSTEM SYSTEM	\$234.75 \$0.00 (\$408.60) (\$483.75) \$892.35 \$0.00 \$0.00	contractor in project file. Need to be reviewed and submitted to AASHTOWare.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of
	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Other Item Adjustment - Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Overrun - Total  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT		- Total  Overrun  Overrun - T	17 19 21	Apr 3, 2020 May 4, 2020 Jun 2, 2020	SYSTEM SYSTEM SYSTEM	\$234.75 \$0.00 (\$408.60) (\$483.75) \$892.35 \$0.00 \$0.00 (\$318.90)	contractor in project file. Need to be reviewed and submitted to AASHTOWare.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of
	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Other Item Adjustment - Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Overrun - Total  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material	- Total  Overrun  Overrun - T	17 19 21	Apr 3, 2020 May 4, 2020 Jun 2, 2020	SYSTEM SYSTEM SYSTEM	\$234.75 \$234.75 \$0.00 (\$408.60) (\$483.75) \$892.35 \$0.00 \$0.00 \$0.00 (\$318.90)	contractor in project file. Need to be reviewed and submitted to AASHTOWare.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of
	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Other Item Adjustment - Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Overrun - Total  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Material - Total  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT WATERBORNE PAVEMENT	Material	- Total  Overrun  Overrun - T	17 19 21  otal	Apr 3, 2020 May 4, 2020 Jun 2, 2020 Jun 18, 2019	SYSTEM SYSTEM SYSTEM	\$234.75 \$234.75 \$0.00 (\$408.60) (\$483.75) \$892.35 \$0.00 \$0.00 \$318.90) (\$318.90)	contractor in project file. Need to be reviewed and submitted to AASHTOWare.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of
	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Other Item Adjustment - Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Overrun - Total  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Material - Total  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT WATERBORNE PAVEMENT	Material	- Total  Overrun - T  - Total	17 19 21  otal	Apr 3, 2020 May 4, 2020 Jun 2, 2020 Jun 18, 2019	SYSTEM SYSTEM SYSTEM	\$234.75 \$234.75 \$0.00 (\$408.60) (\$483.75) \$892.35 \$0.00 \$0.00 \$0.00 (\$318.90) (\$318.90)	contractor in project file. Need to be reviewed and submitted to AASHTOWare.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of
	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Other Item Adjustment - Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Overrun - Total  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Material - Total  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Material Credit - Total  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT WATERBORNE PAVEMENT	Material	- Total  Overrun - T  - Total	17 19 21 otal	Apr 3, 2020 May 4, 2020 Jun 2, 2020 Jun 18, 2019	SYSTEM SYSTEM SYSTEM	\$234.75 \$234.75 \$0.00 (\$408.60) (\$483.75) \$892.35 \$0.00 \$0.00 \$0.00 (\$318.90) (\$318.90) \$318.90	contractor in project file. Need to be reviewed and submitted to AASHTOWare.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of
	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Other Item Adjustment - Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Overrun - Total  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Material - Total  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  Material Credit - Total  4 IN. YELLOW STANDARD	Material  MaterialCredit  Other Item	- Total  Overrun - T  - Total  - Total	17 19 21 otal	Apr 3, 2020 May 4, 2020 Jun 2, 2020  Jun 18, 2019  Dec 18,	SYSTEM SYSTEM SYSTEM SYSTEM	\$234.75 \$234.75 \$0.00 (\$408.60) (\$483.75) \$892.35 \$0.00 \$0.00 \$0.00 (\$318.90) (\$318.90) \$318.90 \$318.90	contractor in project file. Need to be reviewed and submitted to AASHTOWare.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of

Revision 4/1/2020 Page 12 of 27



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Lino	Bessiiption	Туре	Adjustment Type		Date	Ву	, anount	Kondile
0370		Other Item	OTHR - Tota	al			(\$318.90)	
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Adjustment		2	Jun 18, 2019	mantlc1	\$318.90	Paint and bead certifications are submitted from the contractor in project file. Need to be reviewed and submitted to AASHTOWare.
			- Total				\$318.90	
	Other Item Adjustment - Total						\$0.00	
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun	Overrun	17	Apr 3, 2020	SYSTEM	(\$195.15)	
	MARKING PAINT, TIPE P DEADS			21	Jun 2, 2020	SYSTEM	\$195.15	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',0.15000 - 0.15000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0370 -	Total						\$0.00	
0380	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		2	Jun 18, 2019	SYSTEM	(\$509.60)	
			- Total				(\$509.60)	
	Material - Total						(\$509.60)	
	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	MaterialCredit		3	Jul 1, 2019	SYSTEM	\$509.60	
			- Total				\$509.60	
	MaterialCredit - Total						\$509.60	
	24 IN. WHITE STANDARD	Other Item	OTHR	14	Dec 17,	mantlc1	(\$509.60)	
	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Adjustment			2019		. ,	
			OTHR - Tota	al			(\$509.60)	
	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS			2	Jun 18, 2019	mantlc1	\$509.60	Paint and bead certifications are submitted from the contractor in project file. Need to be reviewed and submitted to AASHTOWare.
			- Total				\$509.60	
	Other Item Adjustment - Total						\$0.00	
0380 -	Total						\$0.00	
0420	PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP	Other Item Adjustment	OADJ	23	Jul 1, 2020	mantlc1	(\$1,570.00)	Negating a previous adjustment for an overrun that has since been processed.
			OADJ - Tota	al			(\$1,570.00)	
	PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP		OVRN	21	Jun 2, 2020	mantlc1	\$1,570.00	Adjustment being used to temporarily pay for overrun quantity.
			OVRN - Tota	al			\$1,570.00	
	Other Item Adjustment - Total						\$0.00	
	PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP	Overrun	Overrun	21	Jun 2, 2020	SYSTEM	(\$1,570.00)	
				23	Jul 1, 2020	SYSTEM	\$1,570.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',157.00000 - 157.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0420 -	Total						\$0.00	
0440	ROCK DITCH CHECK	Material		8	Sep 16, 2019	SYSTEM	(\$1,089.00)	
			- Total				(\$1,089.00)	
	Material - Total						(\$1,089.00)	
	ROCK DITCH CHECK	MaterialCredit		9	Oct 2, 2019	SYSTEM	\$1,089.00	
			- Total				\$1,089.00	
	MaterialCredit - Total						\$1,089.00	
	ROCK DITCH CHECK	Other Item Adjustment	OTHR	8	Sep 16, 2019	mantlc1	\$1,089.00	Rock ditch check passed visual inspection. Cleared in sample checklist but still had exception and was removed by systemgenerated item adjustment. Will be fixed on Estimate 0009.
				14	Dec 17,	mantlc1	(\$1,089.00)	

Revision 4/1/2020 Page 13 of 27



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0440	ROCK DITCH CHECK	Other Item Adjustment	OTHR		2019			
		Aujustinont	OTHR - Tota	ıl			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0440 -		0 1 1		-		0)/07514	\$0.00	
0490	MGS GUARDRAIL	Construction Stockpile		5	Aug 2, 2019	SYSTEM	\$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0490 -							\$0.00	
0500	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		5	Aug 2, 2019	SYSTEM	\$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0500 -		0 1 1		_		OVOTEN	\$0.00	
0520	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		5	Aug 2, 2019	SYSTEM	\$12,840.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Aug 16, 2019	SYSTEM	(\$2,475.42)	Payment Estimate Item Adjustment generated Stockpile Transaction
				9	Oct 2, 2019	SYSTEM	(\$2,475.42)	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Oct 17, 2019	SYSTEM	(\$2,475.42)	Payment Estimate Item Adjustment generated Stockpile Transaction
				12	Nov 18, 2019	SYSTEM	(\$5,413.74)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0520 -	Total						\$0.00	
0550	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		9	Oct 2, 2019	SYSTEM	(\$47,478.00)	
				10	Oct 17, 2019	SYSTEM	(\$79,704.00)	
				11	Nov 5, 2019	SYSTEM	(\$79,704.00)	
				12	Nov 18, 2019	SYSTEM	(\$79,704.00)	
				13	Dec 3, 2019	SYSTEM	(\$79,704.00)	
				14	Dec 18, 2019	SYSTEM	(\$79,704.00)	
			- Total				(\$445,998.00)	
	Material - Total						(\$445,998.00)	
	LATEX MODIFIED CONCRETE WEARING SURFACE	MaterialCredit		10	Oct 17, 2019	SYSTEM	\$47,478.00	
				11	Nov 5, 2019	SYSTEM	\$79,704.00	
				12	Nov 18, 2019	SYSTEM	\$79,704.00	
				13	Dec 3, 2019	SYSTEM	\$79,704.00	
				14	Dec 18, 2019	SYSTEM	\$79,704.00	
				15	Jan 2, 2020	SYSTEM	\$79,704.00	
			- Total				\$445,998.00	
	MaterialCredit - Total						\$445,998.00	
	LATEX MODIFIED CONCRETE WEARING SURFACE	Other Item Adjustment	OTHR	9	Oct 2, 2019	mantlc1	\$47,478.00	Waiting to get breaks on cylinders to finish sample records.
				10	Oct 17, 2019	mantlc1	\$79,704.00	

Revision 4/1/2020 Page 14 of 27



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0550	LATEX MODIFIED CONCRETE WEARING SURFACE	Other Item Adjustment	OTHR	11	Nov 5, 2019	mantlc1	\$79,704.00	
				12	Nov 18, 2019	mantlc1	\$79,704.00	
				13	Dec 3, 2019	mantlc1	\$79,704.00	
				14	Dec 17, 2019	mantlc1	(\$286,590.00)	
				15	Jan 2, 2020	mantlc1	(\$79,704.00)	
			OTHR - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0550 -	- Total						\$0.00	
0640	MONOLITHIC DECK REPAIR	Material		10	Oct 17, 2019	SYSTEM	(\$700.00)	
				11	Nov 5, 2019	SYSTEM	(\$700.00)	
				12	Nov 18, 2019	SYSTEM	(\$700.00)	
				13	Dec 3, 2019	SYSTEM	(\$700.00)	
				14	Dec 18, 2019	SYSTEM	(\$700.00)	
			- Total				(\$3,500.00)	
	Material - Total						(\$3,500.00)	
	MONOLITHIC DECK REPAIR	MaterialCredit		11	Nov 5, 2019	SYSTEM	\$700.00	
				12	Nov 18, 2019	SYSTEM	\$700.00	
				13	Dec 3, 2019	SYSTEM	\$700.00	
				14	Dec 18, 2019	SYSTEM	\$700.00	
				15	Jan 2, 2020	SYSTEM	\$700.00	
			- Total				\$3,500.00	
	MaterialCredit - Total						\$3,500.00	
	MONOLITHIC DECK REPAIR	Other Item Adjustment	OTHR	10	Oct 17, 2019	mantlc1	\$700.00	
				11	Nov 5, 2019	mantlc1	\$700.00	
				12	Nov 18, 2019	mantlc1	\$700.00	
				13	Dec 3, 2019	mantlc1	\$700.00	
				14	Dec 17, 2019	mantlc1	(\$2,100.00)	
				15	Jan 2, 2020	mantlc1	(\$700.00)	
			OTHR - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0640 -	- Total						\$0.00	
0670	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		5	Aug 2, 2019	SYSTEM	(\$37,624.80)	
				6	Aug 16, 2019	SYSTEM	(\$87,120.00)	
			- Total				(\$124,744.80)	
	Material - Total						(\$124,744.80)	
	LATEX MODIFIED CONCRETE WEARING SURFACE	MaterialCredit		6	Aug 16, 2019	SYSTEM	\$37,624.80	
				7	Sep 4, 2019	SYSTEM	\$87,120.00	

Revision 4/1/2020 Page 15 of 27



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0670		MaterialCredit	- Total				\$124,744.80	
	MaterialCredit - Total						\$124,744.80	
0670 -	Total						\$0.00	
0690	HALF-SOLE REPAIR	Material		4	Jul 17, 2019	SYSTEM	(\$26,160.00)	
				5	Aug 2, 2019	SYSTEM	(\$26,160.00)	
			- Total				(\$52,320.00)	
	Material - Total						(\$52,320.00)	
	HALF-SOLE REPAIR	MaterialCredit		5	Aug 2, 2019	SYSTEM	\$26,160.00	
				6	Aug 16, 2019	SYSTEM	\$26,160.00	
			- Total				\$52,320.00	
	MaterialCredit - Total						\$52,320.00	
0690 -	Total						\$0.00	
0730	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		6	Aug 16, 2019	SYSTEM	(\$4,862.00)	
				7	Sep 4, 2019	SYSTEM	(\$4,862.00)	
				8	Sep 16, 2019	SYSTEM	(\$4,862.00)	
				21	Jun 2, 2020	SYSTEM	(\$4,862.00)	
			- Total				(\$19,448.00)	
	Material - Total						(\$19,448.00)	
	DECK REPAIR WITH VOID TUBE REPLACEMENT	MaterialCredit		7	Sep 4, 2019	SYSTEM	\$4,862.00	
				8	Sep 16, 2019	SYSTEM	\$4,862.00	
				9	Oct 2, 2019	SYSTEM	\$4,862.00	
				22	Jun 17, 2020	SYSTEM	\$4,862.00	
			- Total				\$19,448.00	
	MaterialCredit - Total						\$19,448.00	
	DECK REPAIR WITH VOID TUBE REPLACEMENT	Other Item Adjustment	MDPA	21	Jun 2, 2020	mantlc1	\$4,862.00	Adjustment being used to temporarily pay for materials discrepancy withholding. Will be negating once exceptions are resolved.
			MDPA - Tota	al			\$4,862.00	
	DECK REPAIR WITH VOID TUBE REPLACEMENT		OTHR	22	Jun 17, 2020	mantlc1	(\$4,862.00)	Negating a previous item adjustment because discrepancies have been cleared
			OTHR - Tota	al			(\$4,862.00)	
	Other Item Adjustment - Total						\$0.00	
0730 -	Total						\$0.00	
0760	MONOLITHIC DECK REPAIR	Material		5	Aug 2, 2019	SYSTEM	(\$1,953.00)	
				6	Aug 16, 2019	SYSTEM	(\$4,200.00)	
			- Total				(\$6,153.00)	
	Material - Total						(\$6,153.00)	
	MONOLITHIC DECK REPAIR	MaterialCredit		6	Aug 16, 2019	SYSTEM	\$1,953.00	
				7	Sep 4, 2019	SYSTEM	\$4,200.00	
			- Total				\$6,153.00	
	MaterialCredit - Total						\$6,153.00	
0760 -	Total						\$0.00	
0790	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		3	Jul 1, 2019	SYSTEM	(\$3,706.56)	

Revision 4/1/2020 Page 16 of 27



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0790	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		4	Jul 17, 2019	SYSTEM	(\$162,031.70)	
				5	Aug 2, 2019	SYSTEM	(\$162,031.70)	
				6	Aug 16, 2019	SYSTEM	(\$162,031.70)	
			- Total				(\$489,801.66)	
	Material - Total						(\$489,801.66)	
	LATEX MODIFIED CONCRETE WEARING SURFACE	MaterialCredit		4	Jul 17, 2019	SYSTEM	\$3,706.56	
				5	Aug 2, 2019	SYSTEM	\$162,031.70	
				6	Aug 16, 2019	SYSTEM	\$162,031.70	
				7	Sep 4, 2019	SYSTEM	\$162,031.70	
			- Total				\$489,801.66	
	MaterialCredit - Total						\$489,801.66	
0790 -	Total						\$0.00	
0800	CURB BLOCKOUT	Material		5	Aug 2, 2019	SYSTEM	(\$39,472.50)	
				6	Aug 16, 2019	SYSTEM	(\$39,472.50)	
				7	Sep 4, 2019	SYSTEM	(\$39,472.50)	
				21	Jun 2, 2020	SYSTEM	(\$39,472.50)	
			- Total				(\$157,890.00)	
	Material - Total						(\$157,890.00)	
	CURB BLOCKOUT	MaterialCredit		6	Aug 16, 2019	SYSTEM	\$39,472.50	
				7	Sep 4, 2019	SYSTEM	\$39,472.50	
				8	Sep 16, 2019	SYSTEM	\$39,472.50	
				22	Jun 17, 2020	SYSTEM	\$39,472.50	
			- Total				\$157,890.00	
	MaterialCredit - Total						\$157,890.00	
	CURB BLOCKOUT	Other Item Adjustment	MDPA		Jun 2, 2020	mantlc1	\$39,472.50	Adjustment being used to temporarily pay for materials discrepancy withholding. Will be negating once exceptions are resolved.
			MDPA - Tota	al			\$39,472.50	
	CURB BLOCKOUT		OTHR		Jun 17, 2020	mantlc1	(\$39,472.50)	Negating a previous item adjustment because discrepancies have been cleared
			OTHR - Tota	al			(\$39,472.50)	
	Other Item Adjustment - Total						\$0.00	
0800 -	Total						\$0.00	
0850	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		4	Jul 17, 2019	SYSTEM	(\$22,576.27)	
				5	Aug 2, 2019	SYSTEM	(\$22,576.27)	
				6	Aug 16, 2019	SYSTEM	(\$22,603.20)	
				7	Sep 4, 2019	SYSTEM	(\$22,603.20)	
				8	Sep 16, 2019	SYSTEM	(\$22,603.20)	
				9	Oct 2, 2019	SYSTEM	(\$22,603.20)	
				10	Oct 17, 2019	SYSTEM	(\$22,603.20)	

Revision 4/1/2020 Page 17 of 27



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0850	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		11	Nov 5, 2019	SYSTEM	(\$22,603.20)	
				12	Nov 18, 2019	SYSTEM	(\$22,603.20)	
				21	Jun 2, 2020	SYSTEM	(\$22,603.20)	
			- Total				(\$225,978.14)	
	Material - Total						(\$225,978.14)	
	DECK REPAIR WITH VOID TUBE REPLACEMENT	MaterialCredit		5	Aug 2, 2019	SYSTEM	\$22,576.27	
				6	Aug 16, 2019	SYSTEM	\$22,576.27	
				7	Sep 4, 2019	SYSTEM	\$22,603.20	
				8	Sep 16, 2019	SYSTEM	\$22,603.20	
				9	Oct 2, 2019	SYSTEM	\$22,603.20	
				10	Oct 17, 2019	SYSTEM	\$22,603.20	
				11	Nov 5, 2019	SYSTEM	\$22,603.20	
				12	Nov 18, 2019	SYSTEM	\$22,603.20	
				13	Dec 3, 2019	SYSTEM	\$22,603.20	
				22	Jun 17, 2020	SYSTEM	\$22,603.20	
	MaterialCredit - Total	- Total				\$225,978.14		
							\$225,978.14	
	DECK REPAIR WITH VOID TUBE REPLACEMENT	Other Item Adjustment	MDPA	21	Jun 2, 2020	mantlc1	\$22,603.20	Adjustment being used to temporarily pay for materials discrepancy withholding. Will be negating once exceptions are resolved.
			MDPA - Tota	al			\$22,603.20	
	DECK REPAIR WITH VOID TUBE REPLACEMENT		OTHR		Nov 18, 2019	mantlc1	\$22,603.20	
				14	Dec 17, 2019	mantlc1	(\$22,603.20)	
				22	Jun 17, 2020	mantlc1	(\$22,603.20)	Negating a previous item adjustment because discrepancies have been cleared
			OTHR - Tota	al			(\$22,603.20)	
	Other Item Adjustment - Total						\$0.00	
0850 - 0870	MONOLITHIC DECK REPAIR	Material		4	Jul 17,	SYSTEM	\$0.00 (\$14,000.00)	
				5	2019 Aug 2,	0110==11		
				-	2010	SYSTEM	(\$14,000.00)	
				6	2019 Aug 16,	SYSTEM	(\$14,000.00)	
			- Total		2019		(\$14,098.00)	
	Material - Total		- Total		2019 Aug 16,		(\$14,098.00) (\$42,098.00)	
	Material - Total  MONOLITHIC DECK REPAIR	MaterialCredit	- Total		2019 Aug 16,		(\$14,098.00)	
		MaterialCredit	- Total	6	2019 Aug 16, 2019	SYSTEM	(\$14,098.00) (\$42,098.00) (\$42,098.00)	
		MaterialCredit	- Total	5	Aug 16, 2019  Aug 2, 2019  Aug 16,	SYSTEM	(\$14,098.00) (\$42,098.00) (\$42,098.00) \$14,000.00	
		MaterialCredit	- Total	5	Aug 2, 2019 Aug 2, 2019 Aug 16, 2019 Sep 4,	SYSTEM  SYSTEM  SYSTEM	(\$14,098.00) (\$42,098.00) (\$42,098.00) \$14,000.00	
		MaterialCredit		5	Aug 2, 2019 Aug 2, 2019 Aug 16, 2019 Sep 4,	SYSTEM  SYSTEM  SYSTEM	(\$14,098.00) (\$42,098.00) (\$42,098.00) \$14,000.00 \$14,000.00	
0870 -	MONOLITHIC DECK REPAIR	MaterialCredit		5	Aug 2, 2019 Aug 2, 2019 Aug 16, 2019 Sep 4,	SYSTEM  SYSTEM  SYSTEM	(\$14,098.00) (\$42,098.00) (\$42,098.00) \$14,000.00 \$14,000.00 \$14,098.00	

Revision 4/1/2020 Page 18 of 27



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0880		Material	- Total				(\$9,727.00)	
	Material - Total						(\$9,727.00)	
	OPEN CELL FOAM JOINT SEAL	MaterialCredit		7	Sep 4, 2019	SYSTEM	\$9,727.00	
			- Total				\$9,727.00	
	MaterialCredit - Total						\$9,727.00	
	OPEN CELL FOAM JOINT SEAL	Other Item Adjustment	OTHR	6	Aug 16, 2019	mantlc1	\$9,727.00	Adjustment for Open Cell Foam Joint installed on Route AC Bridge A23932. PAL has been submitted by the contractor but not yet processed in the system.
				14	Dec 17, 2019	mantlc1	(\$9,727.00)	
			OTHR - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0880 -	- Total						\$0.00	
0910	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		12	Nov 18, 2019	SYSTEM	(\$46,920.00)	
				13	Dec 3, 2019	SYSTEM	(\$79,626.00)	
				14	Dec 18, 2019	SYSTEM	(\$79,626.00)	
			- Total				(\$206,172.00)	
	Material - Total						(\$206,172.00)	
	LATEX MODIFIED CONCRETE WEARING SURFACE	MaterialCredit		13	Dec 3, 2019	SYSTEM	\$46,920.00	
				14	Dec 18, 2019	SYSTEM	\$79,626.00	
				15	Jan 2, 2020	SYSTEM	\$79,626.00	
			- Total				\$206,172.00	
	MaterialCredit - Total						\$206,172.00	
	LATEX MODIFIED CONCRETE WEARING SURFACE	Other Item Adjustment	OTHR	12	Nov 18, 2019	mantlc1	\$46,920.00	
				13	Dec 3, 2019	mantlc1	\$79,626.00	
				14	Dec 17, 2019	mantlc1	(\$46,920.00)	
				15	Jan 2, 2020	mantlc1	(\$79,626.00)	
			OTHR - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
	- Total					2) (5	\$0.00	
1040	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		12	Nov 18, 2019	SYSTEM	(\$45,870.00)	
				13	Dec 3, 2019	SYSTEM	(\$79,508.00)	
				14	Dec 18, 2019	SYSTEM	(\$79,508.00)	
			- Total				(\$204,886.00)	
	Material - Total						(\$204,886.00)	
	LATEX MODIFIED CONCRETE WEARING SURFACE	MaterialCredit		13	Dec 3, 2019	SYSTEM	\$45,870.00	
				14	Dec 18, 2019	SYSTEM	\$79,508.00	
				15	Jan 2, 2020	SYSTEM	\$79,508.00	
			- Total				\$204,886.00	
	MaterialCredit - Total						\$204,886.00	
	LATEX MODIFIED CONCRETE WEARING SURFACE	Other Item Adjustment	OTHR		Nov 18, 2019	mantlc1	\$45,870.00	
				13	Dec 3,	mantlc1	\$79,508.00	

Revision 4/1/2020 Page 19 of 27



Macrost   Control   Cont	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
14   Dec 18	1040			OTHR		2019			
Total		WEARING CONTROL	rajasanone		14		mantlc1	(\$45,870.00)	
Cher   Item Adjustment - Total					15		mantlc1	(\$79,508.00)	
MISC, PLUGGING EXISTING CURS   Meletal   11				OTHR - Tota	al			\$0.00	
11		Other Item Adjustment - Total						\$0.00	
12   2019   12   2019   13   2019   14   2019   15	1040 -	Total						\$0.00	
Total	1050		Material		11		SYSTEM	(\$2,565.00)	
Material - Total					12		SYSTEM	, , ,	
MISC. PLUGGING EXISTING CURB   Material Credit   12   Nov 16   13   Des 3, 2019   13   Des 3, 2019   14   Des 66 0.00				- Total					
2019   13   2019   15   2019   2019   15   2019   15   2019   15   2019   15   2019   15   2019									
Total			MaterialCredit			2019			
Material Credit - Total					13		SYSTEM		
MISC. PLUGGING EXISTING CURB   Other item OUTLET   Adjustment   OTHR   11   Nov 5   mantlet   \$2,985.00				- Total					
2019   12   Nov 18   mantlet   2019   14   Dec 18   mantlet   \$4,104.00			011		44				
14				OTHR		2019			
Other   Item Adjustment - Total   Substructure   Repair (FORMED)						2019			
1985 - Total   199							mantlc1	, , ,	
1050 - Total  SUBSTRUCTURE REPAIR (FORMED)  Adjustment - Total  SUBSTRUCTURE REPAIR (FORMED)  - Total  - Total  SUBSTRUCTURE REPAIR (FORMED)  - Total  - Total  SUBSTRUCTURE REPAIR (FORMED)  - Total  -				OTHR - Tota	al .				
19									
Commons   Comm			Meterial		10	Mov 4	SVSTEM		
Material - Total  SUBSTRUCTURE REPAIR (FORMED)  MaterialCredit   20 May 19, 2020   202	1060		Material	Total	19		SYSTEM		
SUBSTRUCTURE REPAIR (FORMED)  MaterialCredit   20 May 19, 2020   54,524.00    MaterialCredit - Total   54,524.00    MaterialCredit - Total   54,524.00    SUBSTRUCTURE REPAIR (FORMED)   OADJ - Total   C1,404.00    SUBSTRUCTURE REPAIR (FORMED)   OADJ - Total   OADJ - Total   C2020   May 19, 2020   May 19, 2		Material Total		- Iotai					
SUBSTRUCTURE REPAIR (FORMED)   Other Item (FORMED)		SUBSTRUCTURE REPAIR	MaterialCredit		20		SYSTEM		
SUBSTRUCTURE REPAIR (FORMED)  SUBSTRUCTURE REPAIR (FORMED)  SUBSTRUCTURE REPAIR (FORMED)  OADJ - Total  OHER Item Adjustment - Total  SUBSTRUCTURE REPAIR (FORMED)  OTHR - Total  OTHR - Total  OUTHR - Total  OVERTURE NEPAIR (FORMED)  OTHR - Total  OTHR - Total  OVERTURE NEPAIR (FORMED)  OTHR - Total  OTHR - Total  OVERTURE NAMP 19, May 4, 2020  OVERTURE - Total  SUBSTRUCTURE REPAIR (FORMED)  OTHR - Total  OVERTURE NAMP 19, May 4, 2020  OTHR - Total  SUBSTRUCTURE REPAIR (FORMED)  OVERTURE NAMP 19, May 4, 2020  OVERTURE NAMP 19, May 19, May 19, 2020  OVERTURE NAMP 19, May 19, May 19, 2020  OVERTURE NAMP 19, May 19, May 19, May 19, May 19, 2020  OVERTURE NAMP 19, May 19,		(I OKWED)		- Total		2020		\$4.524.00	
SUBSTRUCTURE REPAIR (FORMED)  SUBSTRUCTURE REPAIR (FORMED)  OADJ - Total  OTHR 19 May 4, 2020 mantlc1 \$1,404.00 Will be removed once materials discrepancies withholding. Will be removed once materials discrepancies withholding. Will be removed once materials discrepancies withholding. Will be removed once materials discrepancies are cleared.  OTHR - Total  OTHR - Total  OTHR - Total  OTHR - Total  OVerrun 19 May 4, 2020 SySTEM \$1,404.00 This adjustment is offsetting the materials discrepancies withholding. Will be removed once materials discrepancies with holding. Will be removed once materials discrepancies with hold by will be removed once mate		MaterialCredit - Total		- Total					
Community   Comm			Other Item	OADJ	23	Jul 1	mantlc1		Negating a previous adjustment for an overrun that has since been
SUBSTRUCTURE REPAIR (FORMED)  OTHR 19 May 4, 2020 mantlc1 \$4,524.00 This adjustment is offsetting the materials discrepancies withholding. Will be removed once materials discrepancies are cleared.  OWAY 19, mantlc1 (\$4,524.00) This adjustment is negating and adjustment on Estimate 19 that has since been cleared.  OTHR - Total \$1,404.00 Overrun. This adjustment will be negated once a change order is processed.  OTHR - Total \$1,404.00 Overrun. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 16 on the current Payment Estimate.  OVERTIAL SYSTEM (\$1,404.00) Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  OVERTIAL SYSTEM \$1,404.00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',156.00000 - 156.00000, 'is applied (if non-zero).								(+1,101110)	
(FORMED)    2020   Will be removed once materials discrepancies are cleared.   20				OADJ - Tota	ıl			(\$1,404.00)	
2020   Since been cleared.				OTHR	19		mantlc1	\$4,524.00	
OTHR - Total  SUBSTRUCTURE REPAIR (FORMED)  Overrun  Over					20		mantlc1	(\$4,524.00)	
SUBSTRUCTURE REPAIR (FORMED)  Overrun					20		mantlc1	\$1,404.00	
SUBSTRUCTURE REPAIR (FORMED)  Overrun  Overrun  Overrun  Overrun  Overrun  Overrun  19 May 4, 2020 \$YSTEM \$1,404.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 16 on the current Payment Estimate.  19 May 4, 2020 \$YSTEM (\$1,404.00)  20 May 19, 2020 \$YSTEM (\$1,404.00) Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  23 Jul 1, 2020 \$YSTEM \$1,404.00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',156.00000 - 156.00000, 'is applied (if non-zero).  Overrun - Total \$0.00				OTHR - Tota	al			\$1,404.00	
(FORMED)    2020   Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 16 on the current Payment Estimate.    19		Other Item Adjustment - Total						\$0.00	
20 May 19, 2020 (\$1,404.00) Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  23 Jul 1, 2020 \$1,404.00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',156.00000 - 156.00000, 'is applied (if non-zero).			Overrun	Overrun	19		SYSTEM	\$1,404.00	Payment Estimate Item Adjustment (0002) overridding Payment
2020 estimates of '0.00000' is applied (if non-zero).  23 Jul 1, 2020 \$1,404.00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',156.00000 - 156.00000, 'is applied (if non-zero).  Overrun - Total \$0.00					19		SYSTEM	(\$1,404.00)	
2020 quantity on all previous payment estimates. Price Adjustments of ',156.00000 - 156.00000, 'is applied (if non-zero).  Overrun - Total \$0.00					20		SYSTEM	(\$1,404.00)	
					23		SYSTEM	\$1,404.00	quantity on all previous payment estimates. Price Adjustments of
Overrun - Total \$0.00				Overrun - T	otal			\$0.00	
		Overrun - Total						\$0.00	

Revision 4/1/2020 Page 20 of 27



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1060 -	Total						\$0.00	
1090	MONOLITHIC DECK REPAIR	Material		12	Nov 18, 2019	SYSTEM	(\$3,325.00)	
				13	Dec 3, 2019	SYSTEM	(\$3,325.00)	
				14	Dec 18, 2019	SYSTEM	(\$3,500.00)	
			- Total				(\$10,150.00)	
	Material - Total						(\$10,150.00)	
	MONOLITHIC DECK REPAIR	MaterialCredit		13	Dec 3, 2019	SYSTEM	\$3,325.00	
				14	Dec 18, 2019	SYSTEM	\$3,325.00	
				15	Jan 2, 2020	SYSTEM	\$3,500.00	
			- Total				\$10,150.00	
	MaterialCredit - Total						\$10,150.00	
	MONOLITHIC DECK REPAIR	Other Item Adjustment	OTHR	13	Dec 3, 2019	mantlc1	\$3,325.00	
				15	Jan 2, 2020	mantlc1	(\$3,325.00)	
			OTHR - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
1090 -	Total						\$0.00	
1100	PROTECTIVE COATING - CONCRETE BENTS AND PIERS	Material		20	May 19, 2020	SYSTEM	(\$4,719.75)	
	(EPOXY)			21	Jun 2, 2020	SYSTEM	(\$4,719.75)	
				22	Jun 17, 2020	SYSTEM	(\$4,719.75)	
				23	Jul 1, 2020	SYSTEM	(\$4,719.75)	
				24	Jul 16, 2020	SYSTEM	(\$4,719.75)	
			- Total				(\$23,598.75)	
	Material - Total						(\$23,598.75)	
	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	MaterialCredit		21	Jun 2, 2020	SYSTEM	\$4,719.75	
	(LI OXI)			22	Jun 17, 2020	SYSTEM	\$4,719.75	
				23	Jul 1, 2020	SYSTEM	\$4,719.75	
				24	Jul 16, 2020	SYSTEM	\$4,719.75	
			- Total				\$18,879.00	
	MaterialCredit - Total						\$18,879.00	
	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)		OTHR	20	May 19, 2020	mantlc1	\$4,719.75	Waiting on sample record. This adjustment will be negated once discrepancies are cleared.
			OTHR - Tota	al			\$4,719.75	
	Other Item Adjustment - Total						\$4,719.75	
1100 -	Total						\$0.00	
1170	MISC. REMOVE AND REPLACE BARRIER CURB	Material		20	May 19, 2020	SYSTEM	(\$5,744.00)	
				21	Jun 2, 2020	SYSTEM	(\$5,744.00)	
			- Total				(\$11,488.00)	
	Material - Total						(\$11,488.00)	
	MISC. REMOVE AND REPLACE	MaterialCredit		21	Jun 2,	SYSTEM	\$5,744.00	
	BARRIER CURB				2020			

Revision 4/1/2020 Page 21 of 27



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1170	MISC. REMOVE AND REPLACE BARRIER CURB	MaterialCredit		22	Jun 17, 2020	SYSTEM	\$5,744.00	
			- Total				\$11,488.00	
	MaterialCredit - Total						\$11,488.00	
	MISC. REMOVE AND REPLACE BARRIER CURB	Other Item Adjustment	OTHR	20	May 19, 2020	mantlc1	\$5,744.00	Waiting on sample record. This adjustment will be negated once discrepancies are cleared.
				22	Jun 17, 2020	mantlc1	(\$5,744.00)	Negating a previous item adjustment because discrepancies have been cleared
			OTHR - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
1170 -	Total						\$0.00	
1180	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		18	Apr 17, 2020	SYSTEM	(\$73,482.00)	
				19	May 4, 2020	SYSTEM	(\$73,482.00)	
				20	May 19, 2020	SYSTEM	(\$134,199.00)	
			- Total				(\$281,163.00)	
	Material - Total						(\$281,163.00)	
	LATEX MODIFIED CONCRETE WEARING SURFACE	MaterialCredit		19	May 4, 2020	SYSTEM	\$73,482.00	
				20	May 19, 2020	SYSTEM	\$73,482.00	
			- Total	21	Jun 2, 2020	SYSTEM	\$134,199.00 \$281,163.00	
	** * * * * * * * * * * * * * * * * * * *		- Iotai					
	MaterialCredit - Total						\$281,163.00	
	LATEX MODIFIED CONCRETE WEARING SURFACE	Other Item Adjustment	OTHR		Apr 17, 2020	mantlc1	\$73,482.00	This adjustment is offsetting the materials discrepancies withholding. Will be removed once materials discrepancies are cleared.
				20	May 19, 2020 Jun 2,	mantlc1	\$60,717.00	This adjustment is offsetting the materials discrepancy withholding. Will be removed once discrepancies are cleared.  Negating a previous item adjustment
			OTHR - Tota		2020	manuci	\$0.00	regaing a previous item adjustment
	Other Item Adjustment - Total						\$0.00	
1180 -							\$0.00	
1200	CLASS B-1 CONCRETE	Material		18	Apr 17, 2020	SYSTEM	(\$20,139.50)	
				19	May 4, 2020	SYSTEM	(\$29,995.00)	
				20	May 19, 2020	SYSTEM	(\$29,995.00)	
				21	Jun 2, 2020	SYSTEM	(\$29,995.00)	
			- Total				(\$110,124.50)	
	Material - Total						(\$110,124.50)	
	CLASS B-1 CONCRETE	MaterialCredit		19	May 4, 2020	SYSTEM	\$20,139.50	
				20	May 19, 2020	SYSTEM	\$29,995.00	
				21	Jun 2, 2020	SYSTEM	\$29,995.00	
			- Total	22	Jun 17, 2020	SYSTEM	\$29,995.00 \$110,124.50	
	Material Cuestit Tetal		- Total					
	MaterialCredit - Total				. :-		\$110,124.50	
	CLASS B-1 CONCRETE	Other Item Adjustment	OTHR		Apr 17, 2020	mantlc1	\$20,139.50	This adjustment is offsetting the materials discrepancies withholding.  Will be removed once materials discrepancies are cleared.
				19	May 4, 2020	mantlc1	\$9,855.50	This adjustment is offsetting the materials discrepancies withholding. Will be removed once materials discrepancies are cleared.

Revision 4/1/2020 Page 22 of 27



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1200	CLASS B-1 CONCRETE	Other Item Adjustment	OTHR	22	Jun 17, 2020	mantlc1	(\$29,995.00)	Negating a previous item adjustment because discrepancies have been cleared
			OTHR - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
1200 -	- Total						\$0.00	
1240	MONOLITHIC DECK REPAIR	Material		18	Apr 17, 2020	SYSTEM	(\$14,000.00)	
				19	May 4, 2020	SYSTEM	(\$14,000.00)	
				20	May 19, 2020	SYSTEM	(\$25,200.00)	
			- Total				(\$53,200.00)	
	Material - Total						(\$53,200.00)	
	MONOLITHIC DECK REPAIR	MaterialCredit		19	May 4,	SYSTEM	\$14,000.00	
				20	2020 May 19, 2020	SYSTEM	\$14,000.00	
				21	Jun 2, 2020	SYSTEM	\$25,200.00	
			- Total				\$53,200.00	
	MaterialCredit - Total						\$53,200.00	
	MONOLITHIC DECK REPAIR	Other Item Adjustment	OADJ	23	Jul 1, 2020	mantlc1	(\$16,100.00)	Negating a previous adjustment for an overrun that has since been processed.
			OADJ - Tota	ıl			(\$16,100.00)	
	MONOLITHIC DECK REPAIR		OTHR	18	Apr 17, 2020	mantlc1	\$9,100.00	This adjustment is offsetting the materials discrepancies withholding. Will be removed once materials discrepancies are cleared.
				20	May 19, 2020	mantlc1	\$16,100.00	Lacking sample record. This adjustment will be negated once discrepancies are cleared and a change order is processed.
				21	Jun 2, 2020	mantlc1	(\$9,100.00)	Negating a previous item adjustment
			OTHR - Tota	al			\$16,100.00	
	Other Item Adjustment - Total							
	· · · · · · · · · · · · · · · · · · ·						\$0.00	
	MONOLITHIC DECK REPAIR	Overrun	Overrun		Apr 17, 2020	SYSTEM	(\$4,900.00)	
		Overrun	Overrun	18		SYSTEM SYSTEM		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 10 on the current Payment Estimate.
		Overrun	Overrun		2020 Apr 17,		(\$4,900.00)	Payment Estimate Item Adjustment (0002) overridding Payment
		Overrun	Overrun	18	2020 Apr 17, 2020 May 4,	SYSTEM	(\$4,900.00) \$4,900.00	Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 10 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment
		Overrun	Overrun	18	2020 Apr 17, 2020 May 4, 2020 May 4,	SYSTEM SYSTEM	(\$4,900.00) \$4,900.00 (\$4,900.00)	Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 10 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment
		Overrun	Overrun	18 19 19	2020 Apr 17, 2020 May 4, 2020 May 4, 2020	SYSTEM SYSTEM	(\$4,900.00) \$4,900.00 (\$4,900.00) \$4,900.00	Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 10 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 17 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment
		Overrun	Overrun	18 19 19 20	2020 Apr 17, 2020 May 4, 2020 May 4, 2020 May 19, 2020 May 19, 2020	SYSTEM SYSTEM SYSTEM	(\$4,900.00) \$4,900.00 (\$4,900.00) \$4,900.00	Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 10 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 17 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment
		Overrun	Overrun	18 19 19 20 20	2020 Apr 17, 2020 May 4, 2020 May 4, 2020 May 19, 2020 May 19, 2020 May 19, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,900.00) \$4,900.00 (\$4,900.00) \$4,900.00 (\$4,900.00)	Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 10 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 17 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment
		Overrun	Overrun	18 19 19 20 20 20	2020 Apr 17, 2020 May 4, 2020 May 4, 2020 May 19, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,900.00) \$4,900.00 (\$4,900.00) \$4,900.00 (\$4,900.00) (\$11,200.00)	Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 10 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 17 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 21 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment
		Overrun	Overrun	18 19 19 20 20 20 20 20	2020 Apr 17, 2020 May 4, 2020 May 4, 2020 May 19, 2020 May 19, 2020 May 19, 2020 May 19, 2020 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,900.00) \$4,900.00 (\$4,900.00) \$4,900.00) (\$11,200.00) \$11,200.00 \$4,900.00	Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 10 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 17 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 21 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 21 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment
		Overrun	Overrun - T	18 19 19 20 20 20 20 21 23	2020 Apr 17, 2020 May 4, 2020 May 4, 2020 May 19, 2020 May 19, 2020 May 19, 2020 Jun 2, 2020 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,900.00) \$4,900.00 (\$4,900.00) \$4,900.00) (\$11,200.00) \$11,200.00 \$4,900.00	Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 10 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 17 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 21 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 21 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of
		Overrun		18 19 19 20 20 20 20 21 23	2020 Apr 17, 2020 May 4, 2020 May 4, 2020 May 19, 2020 May 19, 2020 May 19, 2020 Jun 2, 2020 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,900.00) \$4,900.00 (\$4,900.00) \$4,900.00 (\$11,200.00) \$11,200.00 \$4,900.00 (\$16,100.00)	Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 10 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 17 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 21 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 21 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of
1240 -	MONOLITHIC DECK REPAIR	Overrun		18 19 19 20 20 20 20 21 23	2020 Apr 17, 2020 May 4, 2020 May 4, 2020 May 19, 2020 May 19, 2020 May 19, 2020 Jun 2, 2020 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,900.00) \$4,900.00 (\$4,900.00) \$4,900.00 (\$4,900.00) (\$11,200.00) \$11,200.00 (\$16,100.00) \$16,100.00	Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 10 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 17 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 21 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 21 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of
1240 - 1250	MONOLITHIC DECK REPAIR  Overrun - Total			18 19 19 20 20 20 20 21 23	2020 Apr 17, 2020 May 4, 2020 May 4, 2020 May 19, 2020 May 19, 2020 May 19, 2020 Jun 2, 2020 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,900.00) \$4,900.00  (\$4,900.00)  \$4,900.00)  (\$4,900.00)  (\$11,200.00)  \$11,200.00  \$16,100.00)  \$0.00	Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 10 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 17 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 21 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 21 on the current Payment Estimate.  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of

Revision 4/1/2020 Page 23 of 27



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1250	REINFORCING STEEL (EPOXY COATED)	Material			2020			
	- Total						(\$11,084.00)	
	Material - Total						(\$11,084.00)	
	REINFORCING STEEL (EPOXY COATED)	MaterialCredit		20	May 19, 2020	SYSTEM	\$5,542.00	
				21	Jun 2, 2020	SYSTEM	\$5,542.00	
	- Total						\$11,084.00	
	MaterialCredit - Total					\$11,084.00		
	REINFORCING STEEL (EPOXY COATED)	Other Item Adjustment	OTHR		May 4, 2020	mantlc1	\$5,542.00	This adjustment is offsetting the materials discrepancies withholding. Will be removed once materials discrepancies are cleared.
				21	Jun 2, 2020	mantlc1	(\$5,542.00)	Negating a previous item adjustment
			OTHR - Total				\$0.00	
	Other Item Adjustment - Total					\$0.00		
1250	· Total						\$0.00	
1280	GRAY EPOXY-MASTIC PRIMER	Material		20	May 19, 2020	SYSTEM	(\$10,489.00)	
				21	Jun 2, 2020	SYSTEM	(\$10,489.00)	
				22	Jun 17, 2020	SYSTEM	(\$10,489.00)	
				23	Jul 1, 2020	SYSTEM	(\$10,489.00)	
				24	Jul 16, 2020	SYSTEM	(\$10,489.00)	
	- Total						(\$52,445.00)	
	Material - Total						(\$52,445.00)	
	GRAY EPOXY-MASTIC PRIMER	MaterialCredit		21	Jun 2, 2020	SYSTEM	\$10,489.00	
				22	Jun 17, 2020	SYSTEM	\$10,489.00	
				23	Jul 1, 2020	SYSTEM	\$10,489.00	
				24	Jul 16, 2020	SYSTEM	\$10,489.00	
		- Total				\$41,956.00		
	MaterialCredit - Total					\$41,956.00		
	GRAY EPOXY-MASTIC PRIMER	Other Item Adjustment	OTHR	20	May 19, 2020	mantlc1	\$10,489.00	Lacking sample record. This adjustment will be negated once discrepancies are cleared.
	OTHR - Total						\$10,489.00	
	Other Item Adjustment - Total						\$10,489.00	
	Total						\$0.00	
1350	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		9	Oct 2, 2019	SYSTEM	(\$75,020.00)	
				10	Oct 17, 2019	SYSTEM	(\$147,840.00)	
				11	Nov 5, 2019	SYSTEM	(\$147,840.00)	
				12	Nov 18, 2019	SYSTEM	(\$147,840.00)	
				13	Dec 3, 2019	SYSTEM	(\$147,840.00)	
				14	Dec 18, 2019	SYSTEM	(\$147,840.00)	
					(\$814,220.00)			
	Material - Total					(\$814,220.00)		
	LATEX MODIFIED CONCRETE WEARING SURFACE	MaterialCredit		10	Oct 17, 2019	SYSTEM	\$75,020.00	

Revision 4/1/2020 Page 24 of 27



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
LIIIC	Doosilphon	Туре	Adjustment Type	Number	Date	By	, anount	ronano
1350	LATEX MODIFIED CONCRETE WEARING SURFACE	MaterialCredit		11	Nov 5, 2019	SYSTEM	\$147,840.00	
				12	Nov 18, 2019	SYSTEM	\$147,840.00	
				13	Dec 3, 2019	SYSTEM	\$147,840.00	
				14	Dec 18, 2019	SYSTEM	\$147,840.00	
				15	Jan 2, 2020	SYSTEM	\$147,840.00	
			- Total				\$814,220.00	
	MaterialCredit - Total						\$814,220.00	
	LATEX MODIFIED CONCRETE WEARING SURFACE	Other Item Adjustment	OTHR	9	Oct 2, 2019	mantlc1	\$75,020.00	Waiting to get breaks on cylinders to finish sample records.
				10	Oct 17, 2019	mantlc1	\$147,840.00	
				11	Nov 5, 2019	mantlc1	\$147,840.00	
				12	Nov 18, 2019	mantlc1	\$147,840.00	
				13	Dec 3, 2019	mantlc1	\$147,840.00	
				14	Dec 18, 2019	mantlc1	(\$356,009.35)	
				15	Jan 2, 2020	mantlc1	(\$106,742.35)	
				16	Mar 2, 2020	mantlc1	(\$18,460.60)	Correction for previous adjustment overpayment
				17	Apr 3, 2020	mantlc1	(\$143,435.03)	This item adjustment is to correct previous overpayments.
				18	Apr 17, 2020	mantlc1	(\$41,732.67)	Correction for previous adjustment overpayment.
			OTHR - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
1350 -	- Total						\$0.00	
1370	MONOLITHIC DECK REPAIR	Material		9	Oct 2, 2019	SYSTEM	(\$3,500.00)	
				10	Oct 17, 2019	SYSTEM	(\$3,500.00)	
				11	Nov 5, 2019	SYSTEM	(\$3,500.00)	
				12	Nov 18, 2019	SYSTEM	(\$3,500.00)	
				13	Dec 3, 2019	SYSTEM	(\$3,500.00)	
				14	Dec 18, 2019	SYSTEM	(\$3,500.00)	
			- Total				(\$21,000.00)	
	Material - Total						(\$21,000.00)	
	MONOLITHIC DECK REPAIR	MaterialCredit		10	Oct 17, 2019	SYSTEM	\$3,500.00	
				11	Nov 5, 2019	SYSTEM	\$3,500.00	
				12	Nov 18, 2019	SYSTEM	\$3,500.00	
				13	Dec 3, 2019	SYSTEM	\$3,500.00	
				14	Dec 18, 2019	SYSTEM	\$3,500.00	
				15	Jan 2, 2020	SYSTEM	\$3,500.00	
			- Total				\$21,000.00	
	MaterialCredit - Total						\$21,000.00	

Revision 4/1/2020 Page 25 of 27



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1370	MONOLITHIC DECK REPAIR	Other Item Adjustment	OTHR	9	Oct 2, 2019	mantlc1	\$3,500.00	Waiting to get breaks on cylinders to finish sample records.
				10	Oct 17, 2019	mantlc1	\$3,500.00	
				11	Nov 5, 2019	mantlc1	\$3,500.00	
				12	Nov 18, 2019	mantlc1	\$3,500.00	
				13	Dec 3, 2019	mantlc1	\$3,500.00	
				14	Dec 17, 2019	mantlc1	(\$14,000.00)	
				15	Jan 2, 2020	mantlc1	(\$3,500.00)	
		OTHR - Total				\$0.00		
	Other Item Adjustment - Total					\$0.00		
1370 -	Total						\$0.00	
5006	TACK COAT	Material		12	Nov 18, 2019	SYSTEM	(\$1,050.00)	
		- Total				(\$1,050.00)		
	Material - Total						(\$1,050.00)	
	TACK COAT	MaterialCredit		13	Dec 3, 2019	SYSTEM	\$1,050.00	
			- Total				\$1,050.00	
	MaterialCredit - Total						\$1,050.00	
	TACK COAT	Other Item Adjustment	OTHR	12	Nov 18, 2019	mantlc1	\$1,050.00	
		,		14	Dec 17, 2019	mantlc1	(\$1,050.00)	
			OTHR - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
5006 -	Total						\$0.00	
5010	TACK COAT	Material		14	Dec 18, 2019	SYSTEM	(\$373.75)	
			- Total				(\$373.75)	
	Material - Total						(\$373.75)	
	TACK COAT	MaterialCredit		15	Jan 2, 2020	SYSTEM	\$373.75	
			- Total				\$373.75	
	MaterialCredit - Total						\$373.75	
5010 -	Total						\$0.00	
5025	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material		18	Apr 17, 2020	SYSTEM	(\$5,110.00)	
				19	May 4, 2020	SYSTEM	(\$5,110.00)	
				20	May 19, 2020	SYSTEM	(\$5,110.00)	
			- Total				(\$15,330.00)	
	Material - Total						(\$15,330.00)	
	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	MaterialCredit		19	May 4, 2020	SYSTEM	\$5,110.00	
				20	May 19, 2020	SYSTEM	\$5,110.00	
				21	Jun 2, 2020	SYSTEM	\$5,110.00	
			- Total				\$15,330.00	
	MaterialCredit - Total						\$15,330.00	
	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING		OTHR	18	Apr 17, 2020	mantlc1	\$5,110.00	This adjustment is offsetting the materials discrepancies withholding. Will be removed once materials discrepancies are cleared.
				21	Jun 2,	mantlc1	(\$5,110,00)	Negating a previous item adjustment

Revision 4/1/2020 Page 26 of 27



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5025	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING		OTHR		2020			
			OTHR - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
5025 -	Total						\$0.00	
Overa	ıll - Total					\$0.00		

Revision 4/1/2020 Page 27 of 27