100.00%



Missouri Department of Transportation Contractor's Pay Estimate Summary

February 4, 2020

Pay Estimate Created Date: May 3, 2020

Progress Estim	ate Number	Contract ID 190517-D03 Prime Contractor KCI Constructio		116, 2020 Original Contract Amount 11, 2020 Net Change Order Amount Current Contract Amount	nt \$167,566.54
Approval Date					By User
May 3, 2020		Generated and Ap	proved (and should be considered	Draft) at the Project Office Level by	malonm
May 4, 2020		Reviewed and Approve	ed (and should be considered Draf	t) at the Resident Engineer Level by	abbote1
May 4, 2020		Re	eviewed and Approved at the Centi	ral Office Controllers Office Level by	greggd1
Original Comp	letion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amou	nt Complete

January 9, 2020

No Milestones Exist for Contract

December 1, 2019

Contract Total Pa	ay For Estimate No. 18			
		This Estimate	Previous	To Date
190517-D03				
	Total Posted Items Pay	\$3,800.00	\$1,680,331.45	\$1,684,131.45
	Gross Item Adjustments	\$0.00	(\$451.63)	(\$451.63)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$1,679,879.82	\$1,683,679.82
Contract Total Pa	avable This Estimate:	\$3.800.00		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5S3174	0210	8051000A	SEEDING - COOL SEASON MIXTURES	ACRE	\$7,600.000	0.5	\$3,800.00
Project J5S3174	I - Total						\$3,800.00
Overall - Total							\$3,800.00

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

No Data Available


Page 1 of 18 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	1
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J5S3174	FAS S401(14)	Bridge replacement	Т	GASCONADE	1.5 miles south of Ro	oute V near Owensville	
Totals by .	Job Numbe	ers					
J5S3174		d Item Pay			This Estimate \$3,800.00	Previous \$1,680,331.45	To Date \$1,684,131.45
	Gross	ltem Adjustm		s Item Pay	\$0.00 \$3,800.00	(\$451.63) \$1,679,879.82	(\$451.63) \$1,683,679.82
	Incen				\$0.00	\$0.00	\$0.00
		centive dated Damage:	s		\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00
		Contract Adju		i	\$0.00	\$0.00	\$0.00

Revision 4/1/2020 Page 2 of 18





Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Revision 4/1/2020 Page 3 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190517-D03	J5S3174	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$27,768.00	\$27,768.00
		0001	0020	2031000	CLASS A EXCAVATION	1,352.00	0.00	1,352.00	CUYD	1,352.00	\$12.00	\$16,224.00
		0001	0030	2036000	COMPACTING EMBANKMENT	755.00	0.00	755.00	CUYD	755.00	\$6.50	\$4,907.50
		0001	0040	2142000	FURNISHING ROCK FILL	271.00	17.00	288.00	CUYD	288.00	\$35.00	\$10,080.00
		0001	0050	2143000	PLACING ROCK FILL	271.00	17.00	288.00	CUYD	288.00	\$15.00	\$4,320.00
		0001	0060	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	518.00	0.00	518.00	SQYD	518.00	\$11.00	\$5,698.00
		0001	0070	4010151	TYPE A3 SHOULDER	121.60	0.00	121.60	SQYD	121.60	\$47.00	\$5,715.20
		0001	0080	4019905	MISC.OPTIONAL PAVEMENT	396.70	0.00	396.70	SQYD	396.70	\$73.35	\$29,097.94
		0001	0090	6113020	FURNISHING TYPE 2 ROCK BLANKET	647.00	65.00	712.00	CUYD	712.00	\$39.00	\$27,768.00
		0001	0100	6113040	PLACING TYPE 2 ROCK BLANKET	647.00	65.00	712.00	CUYD	712.00	\$15.00	\$10,680.00
		0001	0110	6161005	CONSTRUCTION SIGNS	576.00	96.00	672.00	SQFT	672.00	\$6.00	\$4,032.00
		0001	0120	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$35.00	\$140.00
		0001	0130	6161009	FLAG ASSEMBLY	6.00	0.00	6.00	EA	6.00	\$20.00	\$120.00
		0001	0140	6161030	TYPE III MOVEABLE BARRICADE	10.00	0.00	10.00	EA	10.00	\$110.00	\$1,100.00
		0001	0150	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0160	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$124,250.00	\$124,250.00
		0001	0170	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,286.00	1,608.00	2,894.00	LF	2,894.00	\$2.00	\$5,788.00
		0001	0180	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,286.00	1,604.00	2,890.00	LF	2,890.00	\$2.00	\$5,780.00
		0001	0190	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	976.00	-1.00	975.00	SQYD	975.00	\$2.00	\$1,950.00
		0001	0200	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.00
		0001	0210	8051000A	SEEDING - COOL SEASON MIXTURES	0.40	2.20	2.60	ACRE	2.60	\$7,600.00	\$19,760.00
		0001	0220	8061005	ROCK DITCH CHECK	50.00	19.00	69.00	LF	69.00	\$21.00	\$1,449.00
		0001	0230	8061016	SEDIMENT REMOVAL	13.00	-13.00	0.00	CUYD	0.00	\$25.00	\$0.00
		0001	0240	8061019	SILT FENCE	681.00	434.00	1,115.00	LF	1,115.00	\$3.90	\$4,348.50
		0001	0250	8061050	TYPE C BERM	283.00	2.00	285.00	LF	285.00	\$37.00	\$10,545.00
		0001	0260	8064134	TYPE 1D EROSION CONTROL BLANKET	1,966.00	34.00	2,000.00	SQYD	2,000.00	\$2.00	\$4,000.00
		0010	0270	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	200.00	0.00	200.00	LF	200.00	\$27.00	\$5,400.00
		0010	0280	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$2,900.00	\$11,600.00
		0010	0290	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	4.00	\$2,800.00	\$11,200.00
		0070	0300	2061000	CLASS 1 EXCAVATION	80.00	0.00	80.00	CUYD	80.00	\$12.00	\$960.00
		0070	0310	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$166,448.00	\$166,448.00
		0070	0320	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	111.00	0.00	111.00	SQYD	111.00	\$78.30	\$8,691.30
		0070	0330	7011107	DRILLED SHAFTS (4 FT. 6 IN. DIA.)	83.00	13.00	96.00	LF	96.00	\$576.00	\$55,296.00
		0070	0340	7011206	ROCK SOCKETS (4 FT 0 IN. DIA.)	48.00	8.10	56.10	LF	56.10	\$620.25	\$34,796.02
		0070	0350	7011300	VIDEO CAMERA INSPECTION	6.00	0.00	6.00	EA	6.00	\$500.00	\$3,000.00
		0070	0360	7011400	FOUNDATION INSPECTION HOLES	108.00	36.00	144.00	LF	144.00	\$96.00	\$13,824.00
		0070	0370	7011600	SONIC LOGGING TESTING	6.00	0.00	6.00	EA	6.00	\$1,000.00	\$6,000.00
		0070	0380	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	248.00	-1.00	247.00	LF	247.00	\$82.25	\$20,315.75
		0070	0390	7026000	PRE-BORE FOR PILING	236.00	0.00	236.00	LF	236.00	\$75.00	\$17,700.00
		0070	0400	7027000	PILE POINT REINFORCEMENT	8.00	0.00	8.00	EA	8.00	\$97.00	\$776.00
		0070	0410	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	119.00	0.00	119.00	CUYD	119.00	\$725.00	\$86,275.00
		0070	0420	7034215	SAFETY BARRIER CURB	883.00	0.00	883.00	LF	883.00	\$52.85	\$46,666.55
		0070	0430	7034221	SLAB ON CONCRETE NU-GIRDER	1,252.00	0.00	1,252.00	SQYD	1,252.00	\$310.00	\$388,120.00
		0070	0440	7056022	NU 43, PRESTRESSED CONCRETE NU-GIRDER	1,257.00	0.00	1,257.00	LF	1,257.00	\$230.00	\$289,110.00
		0070	0450	7061060	REINFORCING STEEL (BRIDGES)	32,650.00	3,490.00	36,140.00	LB	36,140.00	\$1.07	\$38,669.80

Page 4 of 18 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190517-D03	J5S3174	0070	0460	7123301	STEEL INTERMEDIATE DIAPHRAGM FOR P/S CONCRETE GIRDERS	12.00	0.00	12.00	EA	12.00	\$565.00	\$6,780.00
		0070	0470	7123610	SLAB DRAIN	24.00	0.00	24.00	EA	24.00	\$257.00	\$6,168.00
		0070	0480	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$685.00	\$1,370.00
		0070	0490	7161000	PLAIN NEOPRENE BEARING PAD	6.00	0.00	6.00	EA	6.00	\$200.00	\$1,200.00
		0070	0500	7161002	LAMINATED NEOPRENE BEARING PAD	18.00	0.00	18.00	EA	18.00	\$238.00	\$4,284.00
		0070	5001	6189901	MISC.(ADDED MOBILIZATION FOR ADDED FOUNDATION TEST CORES)	0.00	1.00	1.00	LS	1.00	\$1,500.00	\$1,500.00
		0070	5002	7019903	MISC.(FOUNDATION INSPECTION HOLES AT 150%)	0.00	24.00	24.00	LF	24.00	\$144.00	\$3,456.00
		0070	5003	7019903	MISC.(4 FT. 0 IN. DIA. ROCK SOCKETS AT 150%)	0.00	24.00	24.00	LF	24.00	\$930.38	\$22,329.12
		0070	5004	7019901	MISC.(BRIDGE A8724 BENT 4 REMEDIATION)	0.00	1.00	1.00	LS	1.00	\$90,292.25	\$90,292.25
		0070	5005	7101000	REINFORCING STEEL (EPOXY COATED)	0.00	150.00	150.00	LB	150.00	\$2.55	\$382.50
	Project J	5S3174 - To	otal Value	Posted to D	Date as of Report Generated Date							\$1,684,131.44
190517-D03 Ove	rall - Total	Value Pos	ted to Da	te as of Rep	ort Generated Date							\$1,684,131.44

Page 5 of 18 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5S3174

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0210	8051000A	SEEDING - COOL SEASON MIXTURES	5/1/20	5/3/20	0.50	ACRE	Seeding: Sta. 398+56 to 411+20 Measured = 2.6 AC Previous Pay = 2.1 AC Seeding growth accepted. 2.6 - 2.1 = 0.5 Pay = 0.5 AC					Seeding: Sta. 398+56 to 411+20 Measured = 2.6 AC Previous Pay = 2.1 AC Seeding growth accepted. 2.6 - 2.1 = 0.5 Pay = 0.5 AC

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 6 of 18



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0020	CLASS A EXCAVATION	Other Item Adjustment	FUEL	6	Oct 1, 2019	malonm	(\$21.65)	Line No. 0020 - Class A Excavation: -\$21.65 This first adjustment is far Class A Eye, performed Sept. 16.20, 2010.
				9	Nov 17, 2019	malonm	(\$0.55)	This fuel adjustment is for Class A Exc. performed Sept. 16-30, 2019. Line No. 0020 - Class A Excavation:
								-\$0.55 This fuel adjustment is for Class A Exc. performed Nov. 2-15, 2019.
				11	Dec 16, 2019	malonm	(\$6.29)	Line No. 0020 - Class A Exc.: -\$6.29
								Fuel Adjustment for 262 CY Class A Excavation performed Dec. 02-15, 2019.
				12	Jan 1, 2020	malonm	(\$11.69)	Line No. 0020 - Class A Exc.: -\$11.69
								Fuel Adjustment for 487 CY Class A Excavation performed Dec. 16, 2019 through Jan. 1, 2020.
			FUEL - Tota	il			(\$40.18)	
		Other Item Ad	justment - To	tal			(\$40.18)	
0020 -	· Total						(\$40.18)	
0030	COMPACTING EMBANKMENT	Material		9	Nov 16, 2019	SYSTEM	(\$2,489.50)	
				10	Dec 1, 2019	SYSTEM	(\$2,489.50)	
			- Total				(\$4,979.00)	
		Material - Tota	ı				(\$4,979.00)	
		MaterialCredit		10	Dec 1, 2019	SYSTEM	\$2,489.50	
				11	Dec 15, 2019	SYSTEM	\$2,489.50	
			- Total				\$4,979.00	
		MaterialCredit					\$4,979.00	
		Other Item Adjustment	PPPS	9	Nov 17, 2019	malonm	\$2,489.50	Line No. 0030 - Compacting Embankment: +\$2,489.50
								This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				11	Dec 16, 2019	malonm	(\$2,489.50)	Line No. 0030 - Compacting Embankment: -\$2,489.50
								This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
			PPPS - Tota				\$0.00	
0030 -	· Total	Other Item Ad	justment - To	otal			\$0.00 \$0.00	
0040	FURNISHING ROCK FILL	Material		9	Nov 16, 2019	SYSTEM	(\$7,105.00)	
				10	Dec 1, 2019	SYSTEM	(\$8,540.00)	
			- Total				(\$15,645.00)	
		Material - Tota					(\$15,645.00)	
		MaterialCredit		10	Dec 1, 2019	SYSTEM	\$7,105.00	
				11	Dec 15, 2019	SYSTEM	\$8,540.00	
			- Total				\$15,645.00	
		MaterialCredit	- Total				\$15,645.00	
		Other Item Adjustment	PPPS	9	Nov 17, 2019	malonm	\$7,105.00	Line No. 0040 - Furnishing Rock Fill: +\$7,105.00

Revision 4/1/2020 Page 7 of 18



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0040	FURNISHING ROCK FILL	Other Item Adjustment	PPPS					This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				10	Dec 1, 2019	malonm	(\$7,105.00)	Line No. 0040 - Furnishing Rock Fill:
					2010			-\$7,105.00
								This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				10	Dec 1, 2019	malonm	\$8,540.00	Line No. 0040 - Furnishing Rock Fill:
								+\$8,540.00
								This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				11	Dec 16, 2019	malonm	(\$8,540.00)	Line No. 0040 - Furnishing Rock Fill:
								-\$8,540.00
								This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
			PPPS - Tota				\$0.00	
		Other Item Adj			Dec 15	CVCTEM	\$0.00	
		Overrun	Overrun	11	Dec 15, 2019	SYSTEM	(\$595.00)	
				15	Feb 18, 2020	SYSTEM	\$595.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',35.00000 - 35.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
		Overrun - Tota	ıl				\$0.00	
	- Total						\$0.00	
0050	PLACING ROCK FILL	Overrun	Overrun	11	Dec 15, 2019	SYSTEM	(\$255.00)	
				15	Feb 18, 2020	SYSTEM	\$255.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',15.00000 - 15.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
		Overrun - Tota	ıl				\$0.00	
0050 -	- Total						\$0.00	
0060	FOR BASE (4 IN.	Material		11	Dec 15, 2019	SYSTEM	(\$2,849.00)	
	THICK)			12	Jan 1, 2020	SYSTEM	(\$5,126.00)	
				13	Jan 15, 2020	SYSTEM	(\$5,698.00)	
			- Total				(\$13,673.00)	
		Material - Tota					(\$13,673.00)	
		MaterialCredit		12	Jan 1, 2020	SYSTEM	\$2,849.00	
				13	Jan 15, 2020	SYSTEM	\$5,126.00	
				14	Feb 2, 2020	SYSTEM	\$5,698.00	
			- Total				\$13,673.00	
		MaterialCredit	- Total				\$13,673.00	
		Other Item Adjustment	FUEL	11	Dec 16, 2019	malonm	(\$9.32)	Line No. 0060 - Type 1 Agg. Base: -\$9.32
								Fuel Adjustment for 518 SY of 4" thick Agg. Base placed Dec. 02-15, 2019.
			FUEL - Tota	ı			(\$9.32)	
			PPPS		Dec 16,	malonm	\$2,849.00	Line No. 0060 - Type 1 Agg. Base:
					2019			+\$2,849.00

Revision 4/1/2020 Page 8 of 18



THICK		Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
12 3 in 1,	0060	FOR BASE (4 IN.		PPPS					
12 Jan 1,					12		malonm	(\$2,849.00)	Line No. 0060 - Type 1 Agg. Base:
Acad						2020			-\$2,849.00
1-									
13					12		malonm	\$5,126.00	Line No. 0060 - Type 1 Agg. Base:
13						2020			+\$5,126.00
2020 35,126.00 This user adjustment balances out the previous user adjustment made to balance of the away to address partial payment, incorrect material set-up, or incomplete reporting. 14									
Spice Spic					13		malonm	(\$5,126.00)	Line No. 0060 - Type 1 Agg. Base:
ACAD - Total						2020			-\$5,126.00
14									
Fig. 2					13		malonm	\$5,698.00	Line No. 0060 - Type 1 Agg. Base:
Note						2020			+\$5,698.00
2020 -\$5,698.00 This user adjustment balances out the previous user adjustment made to balan out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting. 2020 2020 -\$5,698.00 This user adjustment balances out the previous user adjustment made to balan out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting. 2020 2020 -\$5,698.00 This user adjustment balances out the previous user adjustment, incorrect material set-up, or incomplete reporting. 2020 2020 -\$5,698.00 This user adjustment balances out the previous user adjustment, incorrect material set-up, or incomplete reporting. 2020 2020 -\$5,698.00 This user adjustment balances out the previous user adjustment, incorrect material set-up, or incomplete reporting. 2030 2020									
Space Spac					14		malonm	(\$5,698.00)	Line No. 0060 - Type 1 Agg. Base:
Other Item Adjustment - Total Section						2020			-\$5,698.00
Other Item Adjustment - Total (\$9.32)									
1				PPPS - Tota	ı			\$0.00	
ACAD			Other Item Ad	justment - To	tal				
Adjustment 2019 .\$26.33 .\$26.33 AC Adjustment for mix placed Dec. 2-15, 2019. 121.6 SY of BP1 18-76. ACAD - Total			Other Item	ACAD	11	Dog 16	malanm		Line No. 0070. Type A2 Shoulder
ACA djustment for mix placed Dec. 2-15, 2019. 121.6 SY of BP1 18-76. ACAD - Total	0070	TIPE AS SHOULDER		ACAD	11		IIIaioiiiii	(\$20.33)	
ACAD - Total FUEL 11 Dec 16, 2019 malonm (\$9.99) Line No. 0070 - Type A3 Shoulder: -\$9.99 Fuel Adjustment for 121.6 SY of A3 Shoulder placed Dec. 02-15, 2019.									
FUEL 11 Dec 16, 2019 Eline No. 0070 - Type A3 Shoulder: -\$9.99 Fuel Adjustment for 121.6 SY of A3 Shoulder placed Dec. 02-15, 2019.				ACAD - Tota	al			(\$26.33)	AC Adjustment for mix placed Dec. 2-13, 2019. 121.0 31 of BF1 16-70.
2019 -\$9.99 Fuel Adjustment for 121.6 SY of A3 Shoulder placed Dec. 02-15, 2019.						Dec 16,	malonm		Line No. 0070 - Type A3 Shoulder:
Other Item Adjustment - Total (\$9.99)						2019			
Other Item Adjustment - Total (\$36.32)									Fuel Adjustment for 121.6 SY of A3 Shoulder placed Dec. 02-15, 2019.
MISC. Other Item Adjustment				FUEL - Tota	ı			(\$9.99)	
MISC. Other Item Adjustment ACAD 11 Dec 16, 2019 In Dec 16, 2019 MISC. Other Item Adjustment ACAD 11 Dec 16, 2019 In Dec			Other Item Ad	justment - To	tal			(\$36.32)	
Adjustment 2019 -\$76.50 AC Adjustment for mix placed Dec. 2-15, 2019. 396.7 SY of BB 19-22. 11 Dec 16, 2019 -\$76.36 AC Adjustment for mix placed Dec. 2-15, 2019. 396.7 SY of BB 18-36. 11 Dec 16, 2019 -\$76.36 AC Adjustment for mix placed Dec. 2-15, 2019. 396.7 SY of BB 18-36. 11 Dec 16, 2019 -\$76.30 Line No. 0080 - 10" Asphalt Pavement: -\$40.09									
AC Adjustment for mix placed Dec. 2-15, 2019. 396.7 SY of BB 19-22. 11 Dec 16, 2019	0800	MISC.		ACAD	11		malonm	(\$76.50)	·
11 Dec 16, 2019 (\$76.36) Line No. 0080 - 10" Asphalt Pavement: -\$76.36 AC Adjustment for mix placed Dec. 2-15, 2019. 396.7 SY of BB 18-36. 11 Dec 16, 2019 (\$40.09) Line No. 0080 - 10" Asphalt Pavement: -\$40.09									
2019 -\$76.36 AC Adjustment for mix placed Dec. 2-15, 2019. 396.7 SY of BB 18-36. 11 Dec 16, 2019 Malonm (\$40.09) Line No. 0080 - 10" Asphalt Pavement: -\$40.09					11	Doc 10	melar	/#70.00\	
AC Adjustment for mix placed Dec. 2-15, 2019. 396.7 SY of BB 18-36. 11 Dec 16, 2019 (\$40.09) Line No. 0080 - 10" Asphalt Pavement: -\$40.09					11		maionm	(\$76.36)	'
11 Dec 16, 2019 malonm (\$40.09) Line No. 0080 - 10" Asphalt Pavement: -\$40.09									
2019 -\$40.09					11	Dec 16	malonm	(\$40 00)	
					* *		maionini	(ψ+υ.υθ)	
ACAD - Total (\$192.95)				ACAD - Tota	al			(\$192,95)	7.0 7.0 gastillarition thin placed 200. 2.10, 2010. 000.7 01 01 01 11 10-70.
				AOAD - IOU					
FUEL 11 Dec 16, malonm (\$86.92) Line No. 0080 - 10" Asph. Pavmt.:							malonm		Line No. 0080 - 10" Asph. Pavmt.:
					11		malonm	(\$40.09)	
FIEL 11 Dog 16 molenn (606 00) Line No. 0000, 40ll April Population						Dec 16	molor		Line No. 0080, 10" Asph. Payert

Revision 4/1/2020 Page 9 of 18



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0800	MISC.	Other Item Adjustment						Fuel Adjustment for 396.7 SY of 10" Asph. Pavmt. placed Dec. 02-15, 2019.
			FUEL - Tota	ı			(\$86.92)	
		Other Item Adj	justment - To	tal			(\$279.87)	
0080 -	Total						(\$279.87)	
0090	FURNISHING TYPE 2 ROCK BLANKET	Overrun	Overrun	11	Dec 15, 2019	SYSTEM	(\$2,535.00)	
				15	Feb 18, 2020	SYSTEM	\$2,535.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',39.00000 - 39.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
		Overrun - Tota	ıl				\$0.00	
0090 -	Total						\$0.00	
0100	PLACING TYPE 2 ROCK BLANKET	Overrun	Overrun	11	Dec 15, 2019	SYSTEM	(\$975.00)	
				15	Feb 18, 2020	SYSTEM	\$975.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',15.00000 - 15.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
		Overrun - Tota	ıl				\$0.00	
0100 -	Total						\$0.00	
0110	CONSTRUCTION SIGNS	Overrun	Overrun	11	Dec 15, 2019	SYSTEM	(\$576.00)	
				15	Feb 18, 2020	SYSTEM	\$576.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',6.00000 - 6.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
		Overrun - Tota	ıl				\$0.00	
0110 -	Total						\$0.00	
0170	4 IN. WHITE WATERBORNE	Overrun	Overrun	11	Dec 15, 2019	SYSTEM	(\$2,058.00)	
	PAVEMENT MARKING			13	Jan 15, 2020	SYSTEM	(\$1,158.00)	
				15	Feb 18, 2020	SYSTEM	\$3,216.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.00000 - 2.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
		Overrun - Tota	ıl				\$0.00	
0170 -	Total						\$0.00	
0180	4 IN. YELLOW WATERBORNE	Overrun	Overrun	11	Dec 15, 2019	SYSTEM	(\$2,052.00)	
	PAVEMENT MARKING			13	Jan 15, 2020	SYSTEM	(\$1,156.00)	
				15	Feb 18, 2020	SYSTEM	\$3,208.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.00000 - 2.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
		Overrun - Tota	ıl				\$0.00	
0180 -	Total						\$0.00	
0190	PERMANENT EROSION CONTROL	Material		5	Sep 16, 2019	SYSTEM	(\$488.00)	
	GEOTEXTILE		- Total				(\$488.00)	
		Material - Tota					(\$488.00)	
		MaterialCredit		6	Sep 30, 2019	SYSTEM	\$488.00	
			- Total				\$488.00	
		MaterialCredit					\$488.00	
		Other Item	PPPS	5	Sep 16,	malonm	\$488.00	Line No. 0190 - Geotextile:
		Adjustment	1113	3	2019	maioriii	φ+00.00	+\$488.00

Revision 4/1/2020 Page 10 of 18



Created Date Crea
EROSION CONTROL GEOTEXTILE Adjustment Control for a way to address partial payment, incorrect material set-up, or incomplete reporting. Control for a way to address partial payment, incorrect material set-up, or incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a way to address partial payment, incomplete reporting. Control for a
2019 -\$488.00 This user adjustment balances out the previous user adjustment made tout the System that does not offer a way to address partial payment, incomplete reporting. PPPS - Total Other Item Adjustment - Total 0210 SEEDING - COOL SEASON MIXTURES Overrun Overrun Overrun Overrun Overrun Overrun - Total 0210 - Total Overrun - Total Overrun - Total Overrun - Total Overrun Overru
-\$488.00 This user adjustment balances out the previous user adjustment made to out the System that does not offer a way to address partial payment, indinaterial set-up, or incomplete reporting. PPPS - Total Other Item Adjustment - Total S0.00 SEEDING - COOL SEASON MIXTURES Overrun S0.00 Unit price based on averaged overrun adjustments for installed quantity previous payment estimates. Price Adjustments of ',7600.00000 - 7600 applied (if non-zero). Overrun - Total Overrun - Total S0.00 Overrun - Total Overrun - Total S0.00 Overrun - Total Overrun - Total S0.00 Overrun - Total S0.00 Overrun - Total S0.00 Overrun - Total Overrun - Total S0.00 Overrun - Total S0.00 Overrun - Total S0.00 Overrun - Total
out the System that does not offer a way to address partial payment, incomplete reporting. PPPS - Total St.0.00 Other Item Adjustment - Total St.0.00 Overrun SEEDING - COOL SEASON MIXTURES Overrun - Total Overrun - Total SYSTEM SYSTEM SYSTEM SYSTEM SEEDING - COOL SEASON MIXTURES Overrun - Total SYSTEM SYSTEM SYSTEM SOU Overrun - Total SUCCO SEASON MIXTURES Overrun - Total SUCCO SYSTEM SYSTEM SUCCO SYSTEM
Other Item Adjustment - Total S0.00 0210 SEEDING - COOL SEASON MIXTURES Overrun Overrun - Total S0.00 Overrun - Total Overrun - Total S0.00 Overrun - Total S0.00 Overrun - Total Overrun - Total S0.00 Overrun - Total Overrun - Total S0.00 Overrun - Total Overrun - Total S0.00 Overrun - Total S0.00 Overrun - Total Overrun - Total S0.00 Overrun - Total Overrun - Total S0.00 Overrun - Total Over
Old SEEDING - COOL SEASON MIXTURES Overrun 13
Overrun 13
SEASON MIXTURES 15 Feb 18, 2020 \$\frac{1}{2020}\$ \$
2020 previous payment estimates. Price Adjustments of ',7600.00000 - 7600 applied (if non-zero). Overrun - Total \$0.00 Overrun 13
Overrun - Total \$0.00
O210 - Total \$0.00 Overrun Overrun 13 Jan 15, 2020 SYSTEM (\$399.00) Overrun 15 Feb 18, SYSTEM
0220 ROCK DITCH CHECK Overrun Overrun 13 Jan 15, 2020 (\$399.00) 15 Feb 18, SYSTEM \$399.00 Unit price based on averaged overrun adjustments for installed quantity
2020 15 Feb 18, SYSTEM \$399.00 Unit price based on averaged overrun adjustments for installed quantity
applied (if non-zero).
Overrun - Total \$0.00
Overrun - Total \$0.00
0220 - Total \$0.00
0240 SILT FENCE Overrun Overrun 1 Jul 16, 2019 (\$132.60)
2 Aug 2, 2019 (\$1,560.00)
13 Jan 15, 2020 \$1,692.60 Unit price based on averaged overrun adjustments for installed quantity previous payment estimates. Price Adjustments of ',3.90000 - 3.90000, applied (if non-zero).
Overrun - Total \$2.27373675E-13
Overrun - Total \$0.00
0240 - Total \$0.00
0250 TYPE C BERM Overrun Overrun 2 Aug 2, 2019 (\$74.00)
Jan 15, 2020 SYSTEM SYSTEM Unit price based on averaged overrun adjustments for installed quantity previous payment estimates. Price Adjustments of ',37.00000 - 37.0000 applied (if non-zero).
Overrun - Total \$0.00
Overrun - Total \$0.00
0250 - Total \$0.00
Overrun Overrun Overrun Overrun Overrun Overrun Overrun 13
O250 - Total S0.00
0250 - Total 0260 TYPE 1D EROSION CONTROL BLANKET 0260 TYPE 1D EROSION COVERUN SYSTEM (\$68.00) 15 Feb 18, 2020 Unit price based on averaged overrun adjustments for installed quantity previous payment estimates. Price Adjustments of ',2.00000 - 2.00000, applied (if non-zero). 0260 TYPE 1D EROSION CONTROL BLANKET 15 Feb 18, 2020 SYSTEM S68.00 15 Feb 18, 2020 SYSTEM S68.00 0260 TYPE 1D EROSION CONTROL BLANKET 15 Feb 18, 2020 SYSTEM S68.00 0260 TYPE 1D EROSION CONTROL BLANKET 15 Feb 18, 2020 SYSTEM S68.00 0260 TYPE 1D EROSION CONTROL BLANKET 15 Feb 18, 2020 SYSTEM S68.00 0260 TYPE 1D EROSION CONTROL BLANKET 15 Feb 18, 2020 SYSTEM S68.00 0260 TYPE 1D EROSION CONTROL BLANKET 15 Feb 18, 2020 SYSTEM S68.00 0260 TYPE 1D EROSION CONTROL BLANKET 15 Feb 18, 2020 SYSTEM S68.00 0260 TYPE 1D EROSION CONTROL BLANKET 16 Feb 18, 2020 SYSTEM S68.00 0260 TYPE 1D EROSION CONTROL BLANKET 16 Feb 18, 2020 SYSTEM S68.00 0260 TYPE 1D EROSION CONTROL BLANKET 16 Feb 18, 2020 SYSTEM S68.00 0260 TYPE 1D EROSION CONTROL BLANKET 16 Feb 18, 2020 SYSTEM S68.00 0260 TYPE 1D EROSION CONTROL BLANKET 17 Feb 18, 2020 SYSTEM S68.00 0260 TYPE 1D EROSION CONTROL BLANKET 18 Feb 18, 2020 SYSTEM S68.00 0260 TYPE 1D EROSION CONTROL BLANKET 18 Feb 18, 2020 SYSTEM S68.00 0260 TYPE 1D EROSION CONTROL BLANKET 0260 TYPE
O250 - Total S0.00 TYPE 1D EROSION CONTROL BLANKET Overrun 13
0250 - Total S0.00
O250 - Total S0.00
CONTROL BLANKET
Oz50 - Total Overrun Overrun 13

Revision 4/1/2020 Page 11 of 18



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0280	MGS BRIDGE APP. TRANS SEC	Construction Stockpile		9	Nov 16, 2019	SYSTEM	\$5,430.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	(REG/NO CURB)			11	Dec 15, 2019	SYSTEM	(\$5,430.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
		Construction	Stockpile - To	otal			\$0.00	
0280 -	- Total						\$0.00	
0290	TYPE A CRSHWTHY END TERMINAL	Construction Stockpile		9	Nov 16, 2019	SYSTEM	\$6,360.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	(MASH)			11	Dec 15, 2019	SYSTEM	(\$6,360.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
		Construction	Stockpile - To	otal			\$0.00	
0290 -	- Total						\$0.00	
0320	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		11	Dec 15, 2019	SYSTEM	(\$4,384.80)	
			- Total				(\$4,384.80)	
		Material - Tota	ı				(\$4,384.80)	
		MaterialCredit		12	Jan 1, 2020	SYSTEM	\$4,384.80	
			- Total			\$4,384.80		
		MaterialCredit	- Total				\$4,384.80	
		Other Item	ACAD	11	Dec 16,	malonm	(\$23.92)	Line No. 0320 - Bridge Approach Slab:
		Adjustment			2019			-\$23.92
					D 40		(004.04)	AC Adjustment for mix placed Dec. 2-15, 2019. 111.0 SY of BB 19-22.
				11	Dec 16, 2019	malonm	(\$24.04)	Line No. 0320 - Bridge Approach Slab:
								-\$24.04
								AC Adjustment for mix placed Dec. 2-15, 2019. 111.0 SY of BB 18-36.
				11	Dec 16,	malonm	(\$11.22)	Line No. 0320 - Bridge Approach Slab:
				20	2019			-\$11.22
								AC Adjustment for mix placed Dec. 2-15, 2019. 111.0 SY of BP1 18-78.
			ACAD - Total				(\$59.18)	
			FUEL		Dec 16,	malonm	(\$26.76)	Line No. 0320 - Bridge Approach Slab:
			. 022		2019		(\$20.10)	
								-\$26.76
								Fuel Adjustment for 111 SY of 12" to 10" Bridge Approach Slab placed Dec. 02-15, 2019.
			FUEL - Tota	ıl			(\$26.76)	
			PPPS	11	Dec 16,	malonm	\$4,384.80	Line No. 0320 - Bridge Approach Slab:
					2019			+\$4,384.80
								This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				12	Jan 1,	malonm	(\$4,384.80)	Line No. 0320 - Bridge Approach Slab:
					2020			-\$4,384.80
								This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
			PPPS - Total				\$0.00	
		Other Item Ad	justment - To	tal			(\$85.94)	
0320 -	- Total						(\$85.94)	
0330	DRILLED SHAFTS (4 FT. 6 IN. DIA.)	Material		4	Sep 2, 2019	SYSTEM	(\$33,984.00)	
	,			5	Sep 16, 2019	SYSTEM	(\$41,875.20)	
				6	Sep 30,	SYSTEM	(\$41,875.20)	

Revision 4/1/2020 Page 12 of 18



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0330	DRILLED SHAFTS (4	Material			2019			
	FT. 6 IN. DIA.)			7	Oct 15, 2019	SYSTEM	(\$41,875.20)	
				8	Nov 4, 2019	SYSTEM	(\$52,531.20)	
			- Total				(\$212,140.80)	
		Material - Tota				(\$212,140.80)		
		MaterialCredit		5	Sep 16, 2019	SYSTEM	\$33,984.00	
				6	Sep 30, 2019	SYSTEM	\$41,875.20	
				7	Oct 15, 2019	SYSTEM	\$41,875.20	
				8	Nov 4, 2019	SYSTEM	\$41,875.20	
				9	Nov 16, 2019	SYSTEM	\$52,531.20	
			- Total				\$212,140.80	
		MaterialCredit	- Total				\$212,140.80	
		Other Item Adjustment	PPPS	4	Sep 2, 2019	malonm	\$33,984.00	Line No. 0330 - Drilled Shafts: +\$33,984.00
								This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				5	Sep 16,	malonm	(\$33,984.00)	Line No. 0330 - Drilled Shafts:
					2019			-\$33,984.00
								This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				5	Sep 16, 2019	malonm	\$41,875.20	Line No. 0330 - Drilled Shafts:
					2013			+\$41,875.20
								This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				8	Nov 3, 2019	malonm	(\$41,875.20)	Line No. 0330 - Drilled Shafts:
					2019			-\$41,875.20
								This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				8	Nov 3, 2019	malonm	\$52,531.20	Line No. 0330 - Drilled Shafts:
					2010			+\$52,531.20
								This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				9	Nov 17, 2019	malonm	(\$52,531.20)	Line No. 0330 - Drilled Shafts:
					2010			-\$52,531.20
								This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
			PPPS - Tota	ıl			\$0.00	
		Other Item Ad	justment - To	tal			\$0.00	
		Overrun	Overrun	8	Nov 4, 2019	SYSTEM	\$4,723.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) overridding Payment Estimate Exception 6 on the current Payment Estimate.
				8	Nov 4, 2019	SYSTEM	(\$4,723.20)	
				9	Nov 16, 2019	SYSTEM	(\$4,723.20)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				13	Jan 15, 2020	SYSTEM	\$4,723.20	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',576.00000 - 576.00000, 'is

Revision 4/1/2020 Page 13 of 18



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0330	DRILLED SHAFTS (4 FT. 6 IN. DIA.)	Overrun	Overrun					applied (if non-zero).
	11.0 IN. DIA.)		otal			\$0.00		
		Overrun - Tota	al				\$0.00	
0330 -	Total						\$0.00	
0340	ROCK SOCKETS (4 FT 0 IN. DIA.)	Material		4	Sep 2, 2019	SYSTEM	(\$21,708.75)	
				5	Sep 16, 2019	SYSTEM	(\$27,228.98)	
				6	Sep 30, 2019	SYSTEM	(\$27,228.98)	
				7	Oct 15, 2019	SYSTEM	(\$27,228.98)	
				8	Nov 4, 2019	SYSTEM	(\$34,796.02)	
			- Total				(\$138,191.71)	
		Material - Tota	ıl				(\$138,191.71)	
		MaterialCredit		5	Sep 16, 2019	SYSTEM	\$21,708.75	
				6	Sep 30, 2019	SYSTEM	\$27,228.98	
				7	Oct 15, 2019	SYSTEM	\$27,228.98	
				8	Nov 4, 2019	SYSTEM	\$27,228.98	
				9	Nov 16, 2019	SYSTEM	\$34,796.02	
			- Total				\$138,191.71	
		MaterialCredit	- Total				\$138,191.71	
		Other Item Adjustment	PPPS	4	Sep 2, 2019	malonm	\$21,708.75	Line No. 0340 - Rock Sockets:
								+\$21,708.75
								This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				5	Sep 16,	malonm	(\$21,708.75)	Line No. 0340 - Rock Sockets:
					2019			-\$21,708.75
								This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				5	Sep 16, 2019	malonm	\$27,228.98	Line No. 0340 - Rock Sockets:
					2019			+\$27,228.98
								This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				8	Nov 3,	malonm	(\$27,228.98)	Line No. 0340 - Rock Sockets:
					2019			-\$27,228.98
								This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				8	Nov 3, 2019	malonm	\$34,796.02	Line No. 0340 - Rock Sockets:
					2018			+\$34,796.02
								This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				9	Nov 17,	malonm	(\$34,796.02)	Line No. 0340 - Rock Sockets:
					2019			-\$34,796.02
								This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
			PPPS - Tota	al			\$0.00	

Revision 4/1/2020 Page 14 of 18



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0340	ROCK SOCKETS (4	Other Item Adj	justment - To	tal			\$0.00	
	FT 0 IN. DIA.)	Overrun	Overrun	8	Nov 4, 2019	SYSTEM	\$5,024.03	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) overridding Payment Estimate Exception 7 on the current Payment Estimate.
				8	Nov 4, 2019	SYSTEM	(\$5,024.03)	
				9	Nov 16, 2019	SYSTEM	(\$5,024.03)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				13	Jan 15, 2020	SYSTEM	\$5,024.03	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',620.25000 - 620.25000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
		Overrun - Tota	nl				\$0.00	
0340 -	Total						\$0.00	
0410	CLASS B CONCRETE	Material		4	Sep 2, 2019	SYSTEM	(\$16,530.00)	
	(SUBSTRUCTURE)			5	Sep 16, 2019	SYSTEM	(\$49,155.00)	
				6	Sep 30, 2019	SYSTEM	(\$60,320.00)	
				7	Oct 15, 2019	SYSTEM	(\$60,320.00)	
				8	Nov 4, 2019	SYSTEM	(\$81,925.00)	
			- Total				(\$268,250.00)	
		Material - Tota	ıl				(\$268,250.00)	
		MaterialCredit		5	Sep 16, 2019	SYSTEM	\$16,530.00	
				6	Sep 30, 2019	SYSTEM	\$49,155.00	
				7	Oct 15, 2019	SYSTEM	\$60,320.00	
				8	Nov 4, 2019	SYSTEM	\$60,320.00	
				9	Nov 16, 2019	SYSTEM	\$81,925.00	
			- Total				\$268,250.00	
		MaterialCredit	- Total				\$268,250.00	
		Other Item Adjustment	PPPS	4	Sep 2, 2019	malonm	\$16,530.00	Line No. 0410 - Class B Concrete:
								+\$16,530.00
								This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				5	Sep 16,	malonm	(\$16,530.00)	Line No. 0410 - Class B Concrete:
					2019			-\$16,530.00
								This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				5	Sep 16,	malonm	\$49,155.00	Line No. 0410 - Class B Concrete:
					2019			+\$49,155.00
								This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				6	Oct 1,	malonm	(\$49,155.00)	Line No. 0410 - Class B Concrete:
					2019			-\$49,155.00
								This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				6	Oct 1, 2019	malonm	\$60,320.00	Line No. 0410 - Class B Concrete:
					2019			+\$60,320.00

Revision 4/1/2020 Page 15 of 18



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0410	CLASS B CONCRETE (SUBSTRUCTURE)	Other Item Adjustment	PPPS					This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				8	Nov 3, 2019	malonm	(\$60,320.00)	Line No. 0410 - Class B Concrete:
					2019			-\$60,320.00
								This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				8	Nov 3,	malonm	\$81,925.00	Line No. 0410 - Class B Concrete:
					2019			+\$81,925.00
								This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				9	Nov 17, 2019	malonm	(\$81,925.00)	Line No. 0410 - Class B Concrete:
					2019			-\$81,925.00
								This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
			PPPS - Tota	ıl			\$0.00	
		Other Item Ad	justment - To	tal			\$0.00	
0410 -	Total						\$0.00	
0420	SAFETY BARRIER CURB	Material		11	Dec 15, 2019	SYSTEM	(\$44,341.15)	
			- Total				(\$44,341.15)	
		Material - Tota	ıl				(\$44,341.15)	
		MaterialCredit		12	Jan 1, 2020	SYSTEM	\$44,341.15	
			- Total				\$44,341.15	
		MaterialCredit	- Total				\$44,341.15	
		Other Item	- Total PPPS	11	Dec 16,	malonm		Line No. 0420 - Safety Barrier Curb:
				11	Dec 16, 2019	malonm	\$44,341.15	Line No. 0420 - Safety Barrier Curb: +\$44,341.15
		Other Item		11		malonm	\$44,341.15	
		Other Item		11	2019 Jan 1,	malonm	\$44,341.15	+\$44,341.15 This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or
		Other Item			2019		\$44,341.15 \$44,341.15	+\$44,341.15 This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
		Other Item	PPPS	12	2019 Jan 1,		\$44,341.15 \$44,341.15	+\$44,341.15 This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting. Line No. 0420 - Safety Barrier Curb:
		Other Item Adjustment	PPPS - Total	12	2019 Jan 1,		\$44,341.15 \$44,341.15 (\$44,341.15)	+\$44,341.15 This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting. Line No. 0420 - Safety Barrier Curb: -\$44,341.15 This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect
		Other Item	PPPS - Total	12	2019 Jan 1,		\$44,341.15 \$44,341.15 (\$44,341.15) \$0.00 \$0.00	+\$44,341.15 This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting. Line No. 0420 - Safety Barrier Curb: -\$44,341.15 This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect
0420 -		Other Item Adjustment	PPPS - Total	12	Jan 1, 2020	malonm	\$44,341.15 \$44,341.15 (\$44,341.15) \$0.00 \$0.00	+\$44,341.15 This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting. Line No. 0420 - Safety Barrier Curb: -\$44,341.15 This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect
0420 - 0430	SLAB ON CONCRETE NU-	Other Item Adjustment	PPPS - Total	12	2019 Jan 1,		\$44,341.15 \$44,341.15 (\$44,341.15) \$0.00 \$0.00	+\$44,341.15 This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting. Line No. 0420 - Safety Barrier Curb: -\$44,341.15 This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect
	SLAB ON	Other Item Adjustment	PPPS - Total	12	Jan 1, 2020	malonm	\$44,341.15 \$44,341.15 (\$44,341.15) \$0.00 \$0.00	+\$44,341.15 This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting. Line No. 0420 - Safety Barrier Curb: -\$44,341.15 This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect
	SLAB ON CONCRETE NU-	Other Item Adjustment	PPPS - Total	12 ltal	Jan 1, 2020 Nov 16, 2019 Dec 1,	malonm	\$44,341.15 \$44,341.15 (\$44,341.15) \$0.00 \$0.00 (\$135,780.00)	+\$44,341.15 This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting. Line No. 0420 - Safety Barrier Curb: -\$44,341.15 This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect
	SLAB ON CONCRETE NU-	Other Item Adjustment	PPPS - Total	12 ttal 9	2019 Jan 1, 2020 Nov 16, 2019 Dec 1, 2019 Dec 15,	malonm SYSTEM SYSTEM	\$44,341.15 \$44,341.15 (\$44,341.15) \$0.00 \$0.00 \$0.00 (\$135,780.00) (\$86,771.79) (\$86,771.79) (\$309,323.58)	+\$44,341.15 This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting. Line No. 0420 - Safety Barrier Curb: -\$44,341.15 This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect
	SLAB ON CONCRETE NU-	Other Item Adjustment	PPPS - Total	12 12 11 11 12 12 12 12 12 12 12 12 12 1	2019 Jan 1, 2020 Nov 16, 2019 Dec 1, 2019 Dec 15,	malonm SYSTEM SYSTEM SYSTEM	\$44,341.15 \$44,341.15 (\$44,341.15) \$0.00 \$0.00 (\$135,780.00) (\$86,771.79)	+\$44,341.15 This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting. Line No. 0420 - Safety Barrier Curb: -\$44,341.15 This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect
	SLAB ON CONCRETE NU-	Other Item Adjustment Other Item Ad Material	PPPS - Total	12 ttal 9	2019 Jan 1, 2020 Nov 16, 2019 Dec 1, 2019 Dec 15,	malonm SYSTEM SYSTEM	\$44,341.15 \$44,341.15 (\$44,341.15) \$0.00 \$0.00 \$0.00 (\$135,780.00) (\$86,771.79) (\$86,771.79) (\$309,323.58)	+\$44,341.15 This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting. Line No. 0420 - Safety Barrier Curb: -\$44,341.15 This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect
	SLAB ON CONCRETE NU-	Other Item Adjustment Other Item Adjustment Material Material - Total	PPPS - Total	12 12 11 11 12 12 12 12 12 12 12 12 12 1	Jan 1, 2020 Nov 16, 2019 Dec 1, 2019 Dec 15, 2019	malonm SYSTEM SYSTEM SYSTEM	\$44,341.15 \$44,341.15 (\$44,341.15) \$0.00 \$0.00 (\$135,780.00) (\$86,771.79) (\$86,771.79) (\$309,323.58) (\$309,323.58)	+\$44,341.15 This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting. Line No. 0420 - Safety Barrier Curb: -\$44,341.15 This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect
	SLAB ON CONCRETE NU-	Other Item Adjustment Other Item Adjustment Material Material - Total	PPPS - Total	12 11 12 10 11 11 10 10 11 10 10 11 10 10 11 10 10	Dec 1, 2019 Dec 1, 2019 Dec 1, 2019 Dec 15, 2019	malonm SYSTEM SYSTEM SYSTEM SYSTEM	\$44,341.15 \$44,341.15 \$44,341.15 (\$44,341.15) \$0.00 \$0.00 (\$135,780.00) (\$86,771.79) (\$86,771.79) (\$309,323.58) (\$309,323.58) \$135,780.00	+\$44,341.15 This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting. Line No. 0420 - Safety Barrier Curb: -\$44,341.15 This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect
	SLAB ON CONCRETE NU-	Other Item Adjustment Other Item Adjustment Material Material - Total	PPPS - Total	12 12 11 10 11 11 11 11 11 11 11 11 11 11 11	Dec 1, 2019 Dec 1, 2019 Dec 15, 2019 Dec 15, 2019 Dec 15, 2019	SYSTEM SYSTEM SYSTEM SYSTEM	\$44,341.15 \$44,341.15 \$44,341.15 (\$44,341.15) \$0.00 \$0.00 (\$135,780.00) (\$86,771.79) (\$86,771.79) (\$309,323.58) (\$309,323.58) \$135,780.00 \$86,771.79	+\$44,341.15 This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting. Line No. 0420 - Safety Barrier Curb: -\$44,341.15 This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect

Revision 4/1/2020 Page 16 of 18



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0430		Other Item Adjustment	PPPS	9	Nov 17, 2019	malonm	\$135,780.00	Line No. 0430 - Slab on Concrete: +\$135,780.00 This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				10	Dec 1, 2019	malonm	(\$135,780.00)	Line No. 0430 - Slab on Concrete: -\$135,780.00 This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				10	Dec 1, 2019	malonm	\$86,771.79	Line No. 0430 - Slab on Concrete: +\$86,771.79 This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				12	Jan 1, 2020	malonm	(\$86,771.79)	Line No. 0430 - Slab on Concrete NU Girder: -\$86,771.79 This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect materials to the second of the system
			DDDO T-4-				£0.00	material set-up, or incomplete reporting.
		Other Item Adj	PPPS - Tota				\$0.00 \$0.00	
0430 -	Total	Other item Au	ustillelit - 10	lai			\$0.00	
0440	NU 43, PRESTRESSED	Material		7	Oct 15, 2019	SYSTEM	(\$144,440.00)	
	CONC NU-GIRDER			8	Nov 4, 2019	SYSTEM	(\$144,440.00)	
			- Total				(\$288,880.00)	
		Material - Tota	!				(\$288,880.00)	
		MaterialCredit	VlaterialCredit		Nov 4, 2019	SYSTEM	\$144,440.00	
			- Total	9	Nov 16, 2019	SYSTEM	\$144,440.00 \$288,880.00	
		MaterialCredit					\$288,880.00	
		Other Item Adjustment	em PPPS	7	Oct 15, 2019	malonm	\$144,440.00	Line No. 0440 - Concrete NU Girder: +\$144,440.00 This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				9	Nov 17, 2019	malonm	(\$144,440.00)	Line No. 0440 - NU Girder: -\$144,440.00 This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
			PPPS - Tota	ıl			\$0.00	
		Other Item Adj					\$0.00	
0440 -	Total						\$0.00	
0450	REINFORCING STEEL (BRIDGES)	Material		4	Sep 2, 2019	SYSTEM	(\$20,785.82)	
				5	Sep 16, 2019	SYSTEM	(\$29,933.25)	
			- Total				(\$50,719.07)	
		Material - Tota				2) (2)	(\$50,719.07)	
		MaterialCredit		5	Sep 16, 2019	SYSTEM	\$20,785.82	
				6	Sep 30, 2019	SYSTEM	\$29,933.25	

Revision 4/1/2020 Page 17 of 18



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0450	REINFORCING	MaterialCredit	- Total				\$50,719.07	
STEEL (BRIDGE	STEEL (BRIDGES)	MaterialCredit	- Total				\$50,719.07	
		Other Item Adjustment	PPPS	4	Sep 2, 2019	malonm	\$20,785.82	Line No. 0450 - Reinforcing Steel: +\$20,785.82
								This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				5	Sep 16, 2019	malonm	(\$20,785.82)	Line No. 0450 - Reinforcing Steel: -\$20,785.82
								This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				5	Sep 16, 2019	malonm	\$29,933.25	Line No. 0450 - Reinforcing Steel: +\$29,933.25
								This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				6	Oct 1, 2019	malonm	(\$29,933.25)	Line No. 0450 - Reinforcing Steel:
					2013			-\$29,933.25
								This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
			PPPS - Tota				\$0.00	
		Other Item Adj	Other Item Adjustment - Total				\$0.00	
		Overrun	Overrun	8	Nov 4, 2019	SYSTEM	(\$3,734.30)	
				13	Jan 15, 2020	SYSTEM	\$3,734.30	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1.07000 - 1.07000, 'is applied (if non-zero).
			Overrun - Total				\$0.00	
		Overrun - Tota	ı				\$0.00	
0450 -	Total						\$0.00	
5005	REINFORCING STEEL (EPOXY COATED)	Material		15	Feb 18, 2020	SYSTEM	(\$382.50)	
	OOATED)		- Total				(\$382.50)	
		Material - Tota	l				(\$382.50)	
		MaterialCredit		16	Mar 1, 2020	SYSTEM	\$382.50	
			- Total				\$382.50	
		MaterialCredit	- Total				\$382.50	
		Other Item Adjustment	PPPS	15	Feb 18, 2020	malonm	\$382.50	Line No. 5005 - Added Epoxy Resteel: +\$382.50
								This user adjustment balances out the adjustment made by the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
				16	Mar 1, 2020	malonm	(\$382.50)	Line No. 5005 - Added Epoxy Resteel: -\$382.50
								This user adjustment balances out the previous user adjustment made to balance out the System that does not offer a way to address partial payment, incorrect material set-up, or incomplete reporting.
			PPPS - Tota	ıl			\$0.00	
		Other Item Adj	ustment - To	tal			\$0.00	
5005 -	Total						\$0.00	
Overa	II - Total						(\$451.63)	

Revision 4/1/2020 Page 18 of 18