

Progress Estima 25	te Number	Contract ID Prime Contrac	190517-F06 tor N.B. West Contracti		nber 2, 2020 Original Contract Amo nber 15, 2020 Net Change Order Amo Current Contract Amo	ount \$90,743.97			
Approval Date	Approval Date								
September 16, 2020	Generated and Approved (and should be considered Draft) at the Project Office Level by								
September 17, 2020			Reviewed and Ap	pproved (and should be considered Dr	aft) at the Resident Engineer Level by	washas			
September 18, 2020				Reviewed and Approved at the Ce	ntral Office Controllers Office Level by	greggd1			
Original Comp	letion Date	Curren	t Completion Date	Actual Completion Date	% of Current Contract Amou	nt Complete			
November	1, 2020	No	vember 1, 2020	August 21, 2020	100.00%				

No Milestones Exist for Contract

Contract Total Pay For Estimate No. 25

Contract Total Payable This Estimate:	\$256,652.33		
		<mark>\$4,698,558.65</mark>	\$4,955,210.98
Other Contract Adjustments	\$0.00	\$69,957.30	\$69,957.30
Liquidated Damage	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Incentive	\$0.00	\$0.00	\$0.00
Gross Item Adjustments	\$136,752.95	(\$175,037.64)	(\$38,284.69)
Total Posted Items Pay	\$119,899.38	\$4,803,638.99	\$4,923,538.37
190517-F06			
	This Estimate	Previous	To Date

Contract Total Payable This Estimate: Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3196	0080	4010150	TYPE A2 SHOULDER	SQYD	\$45.000	716	\$32,220.00
	0170	6091011	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	LF	\$15.000	50	\$750.00
	0310	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	SQYD	\$110.000	89	\$9,790.00
	0340	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	LF	\$6.000	428	\$2,568.00
	0400	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN CONTRACTOR FURNISHED/RETAINED	EA	\$3,000.000	1	\$3,000.00
	0500	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	EA	\$55.000	6	\$330.00
	0820	8061007A	CURB INLET CHECK	EA	\$50.000	64	\$3,200.00
	5010	6139901	MISC.10.5 IN CONCRETE PAVEMENT REPLACEMENT	LS	\$58,252.500	1	\$58,252.50
	5011	4071005	TACK COAT	GAL	\$2.340	1,652	\$3,865.68
	5012	7310060	PRECAST CONCRETE MANHOLE - 60 IN.	FT	\$493.600	12	\$5,923.20
Project J6	63196 - To	tal					\$119,899.38
Overall - T	otal						\$119,899.38

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3196	0080	TYPE A2 SHOULDER	Material			-2,589	\$45.00	(\$116,505.00)
	0080	TYPE A2 SHOULDER	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user clowez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	2,589	\$45.00	\$116,505.00
	0090	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	Material			-10,949	\$97.00	(\$1,062,053.00



Progre		mate Number 5	Contract ID Prime Contra	190517-F06 Ictor N.B. West (Pay Period Start September 2, 2020 C ompany Pay Period End September 15, 2020 C	let Change O	rder Amount	
roject umber	Line No.	Item De	escription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
S3196	0090		IC CONCRETE 76-22 (SP125B MIX)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user clowez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	10,949	\$97.00	\$1,062,053.00
	0120	PIPE CC	DLLAR, TYPE A	MaterialCredit			2	\$2,000.00	\$4,000.00
	0120	PIPE CC	DLLAR, TYPE A	Material			-2	\$2,000.00	(\$4,000.00
	0120	PIPE CC)LLAR, TYPE A	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user clowez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	2	\$2,000.00	\$4,000.00
	0140		MISC.	MaterialCredit			7	\$800.00	\$5,600.00
	0140		MISC.	Material			-7	\$800.00	(\$5,600.00
	0140		MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0013) due to user clowez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	7	\$800.00	\$5,600.00
	0150	CONC	RETE MEDIAN	Material			-6,661	\$52.00	(\$346,372.00
	0150	CONC	RETE MEDIAN	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0014) due to user clowez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	6,661	\$52.00	\$346,372.00
	0160	TRUNC	CATED DOMES	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',30.00000 - 30.00000, 'is applied (if non-zero).	57	\$30.00	\$1,710.00
	0170		CURB (OVER 6 EIGHT) TYPE S	Material			-17,103	\$15.00	(\$256,545.00
	0170		CURB (OVER 6 EIGHT) TYPE S	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0015) due to user clowez1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	17,103	\$15.00	\$256,545.00
	0180	CONCRETE	GUTTER TYPE A	Material			-1,358	\$46.00	(\$62,468.00
	0180	CONCRETE	GUTTER TYPE A	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0019) due to user clowez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	1,358	\$46.00	\$62,468.00
	0190	CONCRETE	GUTTER TYPE B	Material			-326	\$42.00	(\$13,692.00
	0190			Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0020) due to user clowez1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	326	\$42.00	\$13,692.00
	0200	CURB AND GU	JTTER TYPE B	Material			-166	\$30.00	(\$4,980.00
	0200	CURB AND GU	JTTER TYPE B	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0016) due to user clowez1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	166	\$30.00	\$4,980.00
	0210	INTEGRAL	CURB TYPE N	Material			-66	\$25.00	(\$1,650.00
	0210	INTEGRAL	CURB TYPE N	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item	66	\$25.00	\$1,650.00



Progress Estimate Number 25			Contract ID Prime Contrac	190517-F06 ctor N.B. West (Net Change O	rder Amount	\$4,832,794.40 \$90,743.97 \$4,923,538.37		
Project lumber	Line No.	Item Des	scription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
S3196						Adjustment (0017) due to user clowez1 overridding Payment Estimate Exception 26 on the current Payment Estimate.			
			TYPE 2 ROCK DITCH LINER	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',40.00000 - 40.00000, 'is applied (if non-zero).	34.5	\$40.00	\$1,380.00
	0220	DITCH LINER		Other Item Adjustment		Overrun Re-adjustment, this amount was taken away twice for a materials discrepancy and an overrun discrepancy.			\$1,200.00
	0230			Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',80.00000 - 80.00000, 'is applied (if non-zero).	34.5	\$80.00	\$2,760.00
	0240		MISC.	Material			-660	\$26.00	(\$17,160.00
	0240			Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0018) due to user clowez1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	660	\$26.00	\$17,160.00
	0250		MISC.	Material			-26	\$30.00	(\$780.00
	0250		MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0021) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	26	\$30.00	\$780.00
	0260		MISC.	Material			-30	\$30.00	(\$900.00
	0260		MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0022) due to user clowez1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	30	\$30.00	\$900.00
	0310	FURNISHING CONCRETE M FULL DEPT		Material			-883	\$110.00	(\$97,130.00
	0310	FURNISHING A CONCRETE M FULL DEPT		Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0023) due to user clowez1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	883	\$110.00	\$97,130.00
	0320		COMPACTION I) (PAVEMENT REPAIR)	Material			-143	\$0.01	(\$1.43
	0320	0320 SUBGRADE COMPACTIO (6 IN. DEPTH) (PAVEMEN REPAIR		Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0024) due to user clowez1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	143	\$0.01	\$1.43
	FOR BASE (4 IN		YPE 1 OR 5 AGGREGATE Material FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)				-1,174	\$0.01	(\$11.74
	0330 TYPE 1 OR 5 AGGR FOR BASE (4 IN. (PAVEMENT R		E (4 IN. THICK)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0025) due to user clowez1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	1,174	\$0.01	\$11.74
	0410 TEMPORARY TRAF BARRIER, CONTRACT			MaterialCredit			1,000	\$5.00	\$5,000.00



Progre		mate Number 5	Contract ID Prime Contra	Contract ID 190517-F06 Pay Period Start September 2, 2020 Original Contract Amount \$4,832 Prime Contractor N.B. West Contracting Company Pay Period End September 15, 2020 Net Change Order Amount \$90,743 Current Contract Amount \$4,923 September 15, 2020 Net Contract Amount \$4,923							
Project Number	Line No.	Item De	scription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount		
J6S3196	0410	BARRIER, 0	ARY TRAFFIC CONTRACTOR D / RETAINED	Material			-1,000	\$5.00	(\$5,000.00		
	0410	BARRIER, 0	ARY TRAFFIC CONTRACTOR D / RETAINED	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0027) due to user clowez1 overridding Payment Estimate Exception 37 on the current Payment Estimate.	1,000	\$5.00	\$5,000.00		
	0570	OF SUF	BITUMINOUS OR REMOVAL RFACING (3 IN. IICK OR LESS)	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.55000 - 2.55000, 'is applied (if non-zero).	29,609	\$2.55	\$75,502.95		
	0730	MISC.		Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3400.00000 - 3400.00000, 'is applied (if non-zero).	2	\$3,400.00	\$6,800.00		
	0750		MISC.	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',4000.00000 - 4000.00000, 'is applied (if non-zero).	2	\$4,000.00	\$8,000.00		
	0760		MISC.	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3000.00000 - 3000.00000, 'is applied (if non-zero).	6	\$3,000.00	\$18,000.00		
	0850		AL CONCRETE R TRANSITION	MaterialCredit			1	\$3,600.00	\$3,600.00		
	0860		ASHWORTHY MINAL (MASH)	MaterialCredit			1	\$3,200.00	\$3,200.0		
	5011		TACK COAT	Material			-1,652	\$2.34	(\$3,865.6		
	5011	TACK COAT		Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0030) due to user clowez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	1,652	\$2.34	\$3,865.6		
	5012	PRECAST CONCRETE MANHOLE - 60 IN.		Material			-12	\$493.60	(\$5,923.2		
	5012 PRECAST CONCR MANHOLE - 60			Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0031) due to user clowez1 overridding Payment Estimate Exception 38 on the current Payment Estimate.	12	\$493.60	\$5,923.20		
Fotal									\$136,752.9		



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J6S3196	FAS S501(24)	Resurface	Н	ST LOUIS CITY	from Hall Street to North of	I-270 Interchange	
Fotals by J	Job Numbe	rs					
J6S3196		d Item Pay Item Adjustm		item Pay	This Estimate \$119,899.38 \$136,752.95 \$256,652.33	Previous \$4,803,638.99 (\$175,037.64) \$4,628,601.35	To Date \$4,923,538.37 (\$38,284.69) \$4,885,253.68
	Liquid	ive entive lated Damages Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$69,957.30	\$0.00 \$0.00 \$0.00 \$69,957.30



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6099903, Project Item Line Number 0250, Material Set 0501CCBA, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QC Test	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6099903, Project Item Line Number 0250, Material Set 0501CCBA, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QC/QA Test	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6099903, Project Item Line Number 0250, Material Set 0501CCBA, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Awaiting successful PAL submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 4010150, Project Item Line Number 0080, Material Set 401015096, Material 1007RCBT1T5 - Agg Base T1/T5 Reclaimed Concrete, Acceptance Action Generic 1007RCBT1T5 is insufficient.	Awaiting QA test submission. MoDOT materials has been contacted multiple times in attempt to get this test performed.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 4010150, Project Item Line Number 0080, Material Set 401015096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA test submission. MoDOT materials has been contacted multiple times in attempt to get this test performed.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 4010150, Project Item Line Number 0080, Material Set 401015096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA test submission. MoDOT materials has been contacted multiple times in attempt to get this test performed.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 4030116, Project Item Line Number 0090, Material Set 403011696, Material 0403SP125B - Superpave 12.5 mm, Des B, Acceptance Action Generic AspHigh is insufficient.	Awaiting QA/QC Testing submissions	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 4071005, Project Item Line Number 5011, Material Set 407100596, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Awaiting FreeForm test submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 4071005, Project Item Line Number 5011, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Awaiting FreeForm test submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6044011, Project Item Line Number 0120, Material Set 6044011, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QC/QA Test	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6044011, Project Item Line Number 0120, Material Set 6044011, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QC/QA Test	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6044011, Project Item Line Number 0120, Material Set 6044011, Material 0500XX - Concrete Plant Inspection Review, Acceptance Action Generic 0500XX is insufficient.	Awaiting FreeForm Test.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6049902, Project Item Line Number 0140, Material Set 6049902, Material 1033MSDMPP - MSD Miscellaneous Precast Products, Acceptance Action Generic 1033MSDMPP is insufficient.	Awaiting Freeform test submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6081000, Project Item Line Number 0150, Material Set 608100096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA/QC test submission.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6081000, Project Item Line Number 0150, Material Set 608100096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA/QC test submission.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091011, Project Item Line Number 0170, Material Set 609101196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA test submission. MoDOT materials has been contacted multiple times in attempt to get this test performed.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091011, Project Item Line Number 0170, Material Set 609101196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA test submission. MoDOT materials has been contacted multiple times in attempt to get this test performed.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091041, Project Item Line Number 0180, Material Set 609104196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QC/QA Test	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091041, Project Item Line Number 0180, Material Set 609104196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA test submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091041, Project Item Line Number 0180, Material Set 609104196, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Awaiting successful PAL submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091042, Project Item Line Number 0190, Material Set 609104296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QC/QA test submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091042, Project Item Line Number 0190, Material Set 609104296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA test submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091042, Project Item Line Number 0190, Material Set 609104296, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Awaiting successful PAL submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091052, Project Item Line Number 0200, Material Set 609105296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance	Awaiting QA test submission. MoDOT materials has been contacted multiple times in attempt to get this test performed.	clowez1	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Action Generic 1005FACCNSCA is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6091052, Project Item Line Number 0200, Material Set 609105296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA test submission. MoDOT materials has been contacted multiple times in attempt to get this test performed.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6092014, Project Item Line Number 0210, Material Set 609201496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QC/QA Test.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6092014, Project Item Line Number 0210, Material Set 609201496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA test submission. MoDOT materials has been contacted multiple times in attempt to get this test performed.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6099903, Project Item Line Number 0260, Material Set 6099903, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QC/QA test submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6099903, Project Item Line Number 0260, Material Set 6099903, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QC/QA test submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6099903, Project Item Line Number 0260, Material Set 6099903, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Awaiting successful PAL submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6099903, Project Item Line Number 0240, Material Set 6099903, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA/QC test.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6099903, Project Item Line Number 0240, Material Set 6099903, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Awaiting QA/QC test.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6131010, Project Item Line Number 0310, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Awaiting QA test submission. MoDOT materials has been contacted multiple times in attempt to get this test performed.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6131010, Project Item Line Number 0310, Material Set 613101096, Material 100510OPTLD1 - PCCP 1" Max LS/DO, Acceptance Action Generic 100510OPTLD1 is insufficient.	Awaiting QA test submission. MoDOT materials has been contacted multiple times in attempt to get this test performed.	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6131012, Project Item Line Number 0320, Material Set 613101296, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	Awaiting successful QC test submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6131013, Project Item Line Number 0330, Material Set 613101396, Material 1007RCBT1T5 - Agg Base T1/T5 Reclaimed Concrete, Acceptance Action Generic 1007RCBT1T5 is insufficient.	Awaiting successful QC test submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 6173600D, Project Item Line Number 0410, Material Set 6173600D96, Material 0617TCRCTF - Type F Concrete Traffic Barrier, Acceptance Action Generic 0617TCRCTF is insufficient.	Awaiting Freeform test submission	clowez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3196, Item 7310060, Project Item Line Number 5012, Material Set 731006096, Material 1033MHRCPK - Precast Conc Manhole, Acceptance Action Generic 1033MHRCPK is insufficient.	Awaiting certification entry.	clowez1	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Note: Posted Q				eport Generated date and can differ from the posted amo	ount at the	time the Es	timate was	Genera	ted.			
Contract Nm.CONTRACT	Project No.		Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190517-F06	J6S3196	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$448,000.00	\$448,000.00
		0001	0020	2063000	CLASS 3 EXCAVATION	10,653.00	0.00	10,653.00	CUYD	10,653.00	\$0.01	\$106.53
		0001	0030	2063300	CLASS 4 EXCAVATION	588.00	-57.00	531.00	CUYD	531.00	\$40.00	\$21,240.00
		0001	0040	2063500	CULVERT CLEANOUT	82.00	0.00	82.00	EA	82.00	\$300.00	\$24,600.00
		0001	0050	2072000	LINEAR GRADING CLASS 2	136.00	0.00	531.00 82.00 136.00 1 0.000 2 1.350.00 1 0.000 2 1.0,949.00 1 902.00 1 902.00 1 1.353.00 1 1.17.00 1 1.21.00 1 1.358.00 1 1.358.00 1 1.358.00 1 1.66.00 1 1.66.00 1 6.651.00 1 3.26.00 1 3.26.00 1 6.651.00 1 1.358.00 1 6.650.00 1 3.000 1 3.000 1 3.000 1 0.000 1 0.000 1 0.000 8	STA	136.00	\$600.00	\$81,600.00
		0001	0060	2142000	FURNISHING ROCK FILL	42.00	-42.00	0.00	CUYD	0.00	\$40.00	\$0.00
		0001	0070	2143000	PLACING ROCK FILL	42.00	-42.00	0.00	CUYD	0.00	\$40.00	\$0.00
		0001	0080	4010150	TYPE A2 SHOULDER	2,264.00	716.00	2,980.00	SQYD	2,980.00	\$45.00	\$134,100.00
		0001	0090	4030116	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	11,654.80	-705.80	10,949.00	TONS	10,949.00	\$97.00	\$1,062,053.00
		0001	0100	4039905	MISC.OPTIONAL PAVEMENT	938.00	-36.00	902.00	SQYD	902.00	\$62.00	\$55,924.00
		0001	0110	4079912	MISC.POLYMER MODIFIED EMULSION MEMBRANE	21,381.00	-2,442.00	18,939.00	GAL	18,939.00	\$2.50	\$47,347.50
		0001	0120	6044011	PIPE COLLAR, TYPE A	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000.00
		0001	0130	6049902	MISC.ADJUSTING MANHOLES, VALVES AND PULL BOXES		0.00	0.00 17.00	EA	17.00	\$350.00	\$5,950.00
		0001	0140	6049902	MISC.INLET TOP REPLACEMENT	20.00	-13.00	7.00	EA	7.00	\$800.00	\$5,600.00
		0001	0150	6081000		6,465.00	196.00	6,661.00	SQYD	6,661.00	\$52.00	\$346,372.00
		0001	0160	6081012	TRUNCATED DOMES	64.00	57.00	121.00	SQFT	121.00	\$30.00	\$3,630.00
		0001	0170	6091011	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	16,575.00	528.00	17,103.00	LF	17,103.00	\$15.00	\$256,545.00
		0001	0180	6091041	CONCRETE GUTTER TYPE A	1,358.00	1,358.00 0.00	1,358.00	LF	1,358.00	\$46.00	\$62,468.00
		0001	0190	6091042	CONCRETE GUTTER TYPE B	326.00	0.00	326.00	LF	326.00	\$42.00	\$13,692.00
		0001	0200	6091052	CURB AND GUTTER TYPE B	178.00	-12.00	166.00	LF	166.00	\$30.00	\$4,980.00
		0001	0210	6092014	INTEGRAL CURB TYPE N	76.00	-10.00	66.00	LF	66.00	\$25.00	\$1,650.00
		0001	0220	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	35.00	34.50	69.50	CUYD	69.50	\$40.00	\$2,780.00
		0001	0230	6096042	PLACING TYPE 2 ROCK DITCH LINER	35.00	34.50	69.50	CUYD	69.50	\$80.00	\$5,560.00
		0001 0240 6	6099903	MISC.MODIFIED 4 IN. CURB AND GUTTER, TYPE A	660.00	0.00	660.00	LF	660.00	00 \$15.00 00 \$15.00 000 \$46.00 000 \$42.00 000 \$30.00 000 \$25.00 50 \$40.00 50 \$40.00 50 \$40.00 50 \$30.00 00 \$26.00 00 \$30.00 00 \$30.00 00 \$30.00 00 \$120.00 00 \$1,500.00 00 \$1,000.00	\$17,160.00	
		0001	0250	6099903	MISC.TRANSITION TYPE A TO TYPE B GUTTER		0.00	26.00	LF	26.00	\$30.00	\$780.00
		0001	0260	6099903	MISC.TRANSITION TYPE B TO TYPE A GUTTER	30.00	0.00	30.00	LF	30.00	\$30.00	\$900.00
		0001	0270	6116010A	SLOPE PROTECTION	52.00	-52.00	0.00	SQYD	0.00	\$120.00	\$0.00
		0001	0280	6122009	IMPACT ATTENUATOR 45 MPH (SAND BARRELS)	1.00	0.00	1.00	EA	1.00	\$1,500.00	\$1,500.00
		0001	0290	6122020	REPLACEMENT SAND BARREL	1.00	-1.00	0.00	EA	0.00	\$1,000.00	\$0.00
		0001	0300	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	-2.00	0.00	EA	0.00	\$1,000.00	\$0.00
		0001	0310	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	1,434.00	-551.00		SQYD	883.00		\$97,130.00
		0001	0320	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	143.00	0.00	143.00	SQYD	143.00	\$0.01	\$1.43
		0001	0330	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	1,174.00	0.00	1,174.00	SQYD	1,174.00	\$0.01	\$11.74
		0001	0340	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	2,378.00	0.00	2,378.00	LF	2,378.00	\$6.00	\$14,268.00
		0001	0350	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	1,680.00	0.00	1,680.00	EA	1,680.00	\$6.00	\$10,080.00
		0001	0360	6149902	MISC.MSD MANHOLE PRECAST 48 IN.	14.00	0.00	14.00	EA	14.00	\$3,000.00	\$42,000.00
		0001	0370	6149902	MISC.MSD MANHOLE PRECAST 60 IN.	1.00	0.00	1.00	EA	1.00	\$4,500.00	\$4,500.00
		0001	0380	6149902	MISC.MSD STANDARD MANHOLE FRAME AND COVER	15.00	0.00	15.00	EA	15.00	\$400.00	\$6,000.00
		0001	0390	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	1.00	\$56,000.00	\$56,000.00
		0001	0400	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN CONTRACTOR FURNISHED/RETAINED	2.00	1.00	3.00	EA	3.00	\$3,000.00	\$9,000.00
		0001	0410	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,000.00	0.00	1,000.00	LF	1,000.00	\$5.00	\$5,000.00
		0001	0420	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	9,000.00	0.00	9,000.00	LF	9,000.00	\$1.00	\$9,000.00
		0001	0430	6179903	MISC.GRAVITY RETAINING WALL	456.00	-80.00	376.00	LF	376.00	\$250.00	\$94,000.00
		0001	0440	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$311,345.00	\$311,345.00
		0001	0450	6189902		2.00	0.00	2.00	EA	2.00	\$600.00	\$1,200.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	te: Posted Quantities and Values are based on Report Generated date and can differ from the posted am					ount at the	time the E	stimate was	Genera	ted.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190517-F06	J6S3196	0001	0460	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	631.00	0.00	631.00	LF	631.00	\$25.00	\$15,775.00
		0001	0470	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	117.00	0.00	117.00	LF	117.00	\$25.00	\$2,925.00
		0001	0480	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	31.00	0.00	31.00	EA	31.00	\$350.00	\$10,850.00
		0001	0490	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	16.00	0.00	16.00	EA	16.00	\$350.00	\$5,600.00
		0001	0500	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	24.00	0.00	24.00	EA	24.00	\$55.00	\$1,320.00
		0001	0510	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	36,677.00	0.00	36,677.00	LF	36,677.00	\$0.20	\$7,335.40
		0001	0520	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	47,289.00	0.00	47,289.00	LF	47,289.00	\$0.50	\$23,644.50
		0001	0530	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	4,775.00	0.00	4,775.00	LF	4,775.00	\$0.50	\$2,387.50
		0001	0540	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE REDUCTION(LEFT)	6.00	0.00	6.00	EA	6.00	\$2,000.00	\$12,000.00
		0001	0550	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, U- TURN ARROW (LEFT)	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.00
		0001	0560	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING, U- TURN ONLY WORD	2.00	-1.00	1.00	EA	1.00	\$1,500.00	\$1,500.00
		0001	0570	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	20,926.00	29,609.00	50,535.00	SQYD	50,535.00	\$2.55	\$128,864.25
		0001	0580	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	21,450.00	0.00	21,450.00	SQYD	21,450.00	\$4.00	\$85,800.00
		0001	0590	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	285.00	0.00	285.00	STA	285.00	\$40.00	\$11,400.00
		0001	0600	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$61,966.00	\$61,966.00
		0001	0670	7269903	MISC.12 IN. CLASS 3 RCP	1,707.00	-1,707.00	0.00	LF	0.00	\$50.00	\$0.00
		0001	0680	7269903	MISC.15 IN. CLASS 3 RCP	1,915.00	-1,101.00	814.00	LF	814.00	\$53.00	\$43,142.00
		0001	0690	7269903	MISC.18 IN. CLASS 3 RCP	3,928.00	-1,807.00	2,121.00	LF	2,121.00	\$58.00	\$123,018.00
		0001	0700	7269903	MISC.21 IN. CLASS 3 RCP	1,971.00	-1,011.00	960.00	LF	960.00	\$61.00	\$58,560.00
		0001	0710	7269903	MISC.24 IN. CLASS 3 RCP	556.00	-108.00	448.00	LF	448.00	\$66.00	\$29,568.00
		0001	0720	7269903	MISC.30 IN. CLASS 3 RCP	94.00	-45.00	49.00	LF	49.00	\$76.00	\$3,724.00
		0001	0722	7269903	MISC.12 IN. CLASS 4 RCP	328.00	509.00	837.00	LF	837.00	\$50.00	\$41,850.00
		0001	0724	7269903	MISC.15 IN. CLASS 4 RCP		-365.00	0.00	LF	0.00	\$54.00	\$0.00
		0001	0726	7269903			-538.00	0.00	LF	0.00	\$59.00	\$0.00
			0728	7269903	MISC.18 IN. CLASS 4 RCP	538.00	-123.00	0.00	LF	0.00	\$63.00	\$0.00
		0001	0720	7319902	MISC.21 IN. CLASS 4 RCP MISC.MSD 2 GRATE INLET W/ SIDE INTAKE 48 IN. X 48 IN.	51.00	2.00	53.00	EA	53.00	\$3,400.00	\$180,200.00
		0001	0730	7319902	MISC.MSD 2 GRATE INLET W/ SIDE INTAKE 46 IN. X 46 IN.		0.00	4.00	EA	4.00		
		0001				4.00					\$2,500.00	\$10,000.00
		0001	0750	7319902	MISC.MSD DOUBLE STREET INLET 108 IN. X 52 IN.	20.00	2.00	22.00	EA	22.00	\$4,000.00	\$88,000.00
		0001	0760	7319902	MISC.MSD SINGLE STREET INLET 54 IN. X 48 IN.	22.00	6.00	28.00	EA	28.00	\$3,000.00	\$84,000.00
		0001	0770	7319902	MISC.REPLACE INLET TOP TO NEW GRADE	56.00	-2.00	54.00	EA	54.00	\$800.00	\$43,200.00
		0001	0780		15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$800.00	\$800.00
		0001	0790		18 IN, OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	4.00	0.00	4.00	EA	4.00	\$850.00	\$3,400.00
		0001	0800	8051000A	SEEDING - COOL SEASON MIXTURES	5.80	0.00	5.80	ACRE	5.80	\$3,200.00	\$18,560.00
		0001	0810	8061005	ROCK DITCH CHECK	6.00	-6.00	0.00	LF	0.00	\$30.00	\$0.00
		0001	0820	8061007A	CURB INLET CHECK	114.00	-7.00	107.00	EA	107.00	\$50.00	\$5,350.00
		0001	0830	8061016	SEDIMENT REMOVAL	311.00	0.00	311.00	CUYD	311.00	\$0.01	\$3.11
		0001	0840	8061019	SILT FENCE	19,279.00	-19,279.00	0.00	LF	0.00	\$0.01	\$0.00
		0010	0850	6061070	MGS VERTICAL CONCRETE BARRIER TRANSITION	2.00	-1.00	1.00	EA	1.00	\$3,600.00	\$3,600.00
		0010	0860	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	-1.00	1.00	EA	1.00	\$3,200.00	\$3,200.00
		0020	0870	9019902	MISC.RELOCATION OF CITY LIGHTING POLE	4.00	0.00	4.00	EA	4.00	\$2,500.00	\$10,000.00
		0020	0880	9019902	MISC.RELOCATION OF FLASHING BEACON	1.00	0.00	1.00	EA	1.00	\$2,500.00	\$2,500.00
		0030	0890	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	634.00	0.00	634.00	LF	634.00	\$15.00	\$9,510.00
		0030	0900	9028311	CABLE, 16 AWG 7 CONDUCTOR	750.00	0.00	750.00	LF	750.00	\$3.00	\$2,250.00
		0030	0910	9028810	PULL BOX, PREFORMED CLASS 1	3.00	0.00	3.00	EA	3.00	\$1,500.00	\$4,500.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Contract n.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
0517-F06	J6S3196	0040	0920	9031242	36 IN. SURFACE-MOUNT DELINEATOR POST	288.00	0.00	288.00	EA	288.00	\$90.00	\$25,920.0
		0040	0930	9031270A	2 IN. PSST POST - 12 GA.	265.00	0.00	265.00	LF	265.00	\$16.00	\$4,240.0
		0040	0940	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	81.00	0.00	81.00	LF	81.00	\$36.00	\$2,916.0
		0040	0950	9031280	2.5 IN. PSST POST - 12 GA.	97.00	0.00	97.00	LF	97.00	\$17.00	\$1,649.0
		0040	0960	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	18.00	0.00	18.00	LF	18.00	\$48.00	\$864.0
		0040	0970	9035004A	SH-FLAT SHEET	152.00	0.00	152.00	SQFT	152.00	\$26.00	\$3,952.0
		0040	0980	9035069A	SHF-FLAT SHEET FLUORESCENT	32.00	0.00	32.00	SQFT	32.00	\$30.00	\$960.0
		0001	5001	7269903	MISC.12 IN. CLASS 5 RCP	0.00	1,198.00	1,198.00	LF	1,198.00	\$51.31	\$61,469.3
		0001	5002	7269903	MISC.15 IN. CLASS 5 RCP	0.00	1,466.00	1,466.00	LF	1,466.00	\$58.65	\$85,980.9
		0001	5003	7269903	MISC.18 IN. CLASS 5 RCP	0.00	2,477.00	2,477.00	LF	2,477.00	\$60.03	\$148,694.3
		0001	5004	7269903	MISC.21 IN. CLASS 5 RCP	0.00	1,002.00	1,002.00	LF	1,002.00	\$79.40	\$79,558.8
		0001	5005	7269903	MISC.24 IN. CLASS 5 RCP	0.00	108.00	108.00	LF	108.00	\$79.11	\$8,543.8
		0001	5006	7269903	MISC.30 IN. CLASS 5 RCP	0.00	45.00	45.00	LF	45.00	\$91.93	\$4,136.8
		0030	5007	9103700	CCTV CAMERA ASSEMBLY, INSTALLED	0.00	2.00	2.00	EA	2.00	\$2,275.00	\$4,550.0
		0030	5008	9028354	FIBER OPTIC CABLE, 24 - FIBER, 18 SINGLE MODE, 6 MULTIMODE	0.00	371.00	371.00	LF	371.00	\$3.75	\$1,391.2
		0001	5009	6031015	RELOCATING SERVICE CONNECTIONS(CLASS 3)	0.00	1.00	1.00	EA	1.00	\$9,293.66	\$9,293.6
		0001	5010	6139901	MISC.10.5 IN CONCRETE PAVEMENT REPLACEMENT	0.00	1.00	1.00	LS	1.00	\$58,252.50	\$58,252.5
		0001	5011	4071005	TACK COAT	0.00	1,652.00	1,652.00	GAL	1,652.00	\$2.34	\$3,865.6
		0001	5012	7310060	PRECAST CONCRETE MANHOLE - 60 IN.	0.00	12.00	12.00	FT	12.00	\$493.60	\$5,923.2
	Project J	6S3196 - To	otal Value	Posted to D	Date as of Report Generated Date							\$4,923,538.3
517-F06 Ove	rall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$4,923,538



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0080	4010150	TYPE A2 SHOULDER	9/15/20	9/16/20	716.00	SQYD	Quantity update.					
0170	6091011	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	9/15/20	9/16/20	50.00	LF	Quantity update.					
0310	6131010	FURN & PLACE CONC MATL FOR FULL DEPTH	9/15/20	9/16/20	89.00	SQYD	Quantity update.					
0340	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	9/15/20	9/16/20	428.00	LF	Quantity update.					
0400	6169902	MISC. TRAFFIC CONTROL DEVICES	9/15/20	9/16/20	1.00	EA	Quantity update.					
0500	6200042	PREF THERMO PVMT MARK, YIELD TRIAN	9/15/20	9/16/20	6.00	EA	Quantity update.					
0820	8061007A	CURB INLET CHECK	9/15/20	9/16/20	64.00	EA	Quantity update.					
5010	6139901	MISC. PAVEMENT REPAIR	9/15/20	9/16/20	1.00	LS	Quantity Update					
5011	4071005	TACK COAT	9/15/20	9/16/20	1,652.00	GAL	Quantity Update					
5012	7310060	PRECAST CONCRETE MANHOLE - 60 IN.	9/15/20	9/16/20	12.00	FT	Quantity Update					

The information below this line are details from Line Item agency views. No Agency View Details Exist



ine	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
080	TYPE A2 SHOULDER	Material		9	Jan 16, 2020	SYSTEM	(\$32,985.00)										
				10	Feb 3, 2020	SYSTEM	(\$32,985.00)										
				11	Feb 18, 2020	SYSTEM	(\$32,985.00)										
				12	Mar 2, 2020	SYSTEM	(\$32,985.00)										
				12	Mar 2, 2020	SYSTEM	\$32,985.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.									
					13	Mar 16, 2020	SYSTEM	(\$32,985.00)									
				13	Mar 16, 2020	SYSTEM	\$32,985.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.									
				14	Apr 2, 2020	SYSTEM	(\$32,985.00)										
				14	Apr 2, 2020	SYSTEM	\$32,985.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.									
				15	Apr 15, 2020	SYSTEM	(\$57,510.00)										
				15	Apr 15, 2020	SYSTEM	\$57,510.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.									
				16	May 4, 2020	SYSTEM	(\$61,020.00)										
				16	May 4, 2020	SYSTEM	\$61,020.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.									
				17	May 15, 2020	SYSTEM	(\$66,960.00)										
				17	May 15, 2020	SYSTEM	\$66,960.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user cunnid3 overridding Payment Estimate Exception 1 on the current Payment Estimate.									
										18	Jun 2, 2020	SYSTEM	(\$66,960.00)				
					18	Jun 2, 2020	SYSTEM	\$66,960.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user cunnid3 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
				19	Jun 15, 2020	SYSTEM	(\$74,430.00)										
				19	Jun 15, 2020	SYSTEM	\$74,430.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user clowez1 overridding Payment Estimate Exception 1 on the current Paymen Estimate.									
				20	Jul 1, 2020	SYSTEM	(\$84,285.00)										
													20	Jul 1, 2020	SYSTEM	\$84,285.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user clowez1 overridding Payment Estimate Exception 1 on the current Paymen Estimate.
							21	Jul 16, 2020	SYSTEM	(\$84,285.00)							
				21	Jul 16, 2020	SYSTEM	\$84,285.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user clowez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.									
				22	Aug 3, 2020	SYSTEM	(\$84,285.00)										
				22	Aug 3, 2020	SYSTEM	\$84,285.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user clowez1 overridding Payment Estimate Exception 6 on the current Payment									



ine	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
080	TYPE A2 SHOULDER	Material						Estimate.	
				23	Aug 17, 2020	SYSTEM	(\$84,285.00)		
				23	Aug 17, 2020	SYSTEM	\$84,285.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user clowez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
				24	Sep 1, 2020	SYSTEM	(\$84,285.00)		
				24	Sep 1, 2020	SYSTEM	\$84,285.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user clowez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
				25	Sep 16, 2020	SYSTEM	(\$116,505.00)		
				25	Sep 16, 2020	SYSTEM	\$116,505.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user clowez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
			- Total				(\$98,955.00)		
	Material - Total						(\$98,955.00)		
	TYPE A2 SHOULDER	MaterialCredit		10	Feb 3, 2020	SYSTEM	\$32,985.00		
				11	Feb 18, 2020	SYSTEM	\$32,985.00		
				12	Mar 2, 2020	SYSTEM	\$32,985.00		
			- Total				\$98,955.00		
	MaterialCredit - Total						\$98,955.00		
80 -	Total						\$0.00		
90	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	Material	Material		21	Jul 16, 2020	SYSTEM	(\$1,062,053.00)	
					21	Jul 16, 2020	SYSTEM	\$1,062,053.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user clowez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				22	Aug 3, 2020	SYSTEM	(\$1,062,053.00)		
				22	Aug 3, 2020	SYSTEM	\$1,062,053.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user clowez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
				23	Aug 17, 2020	SYSTEM	(\$1,062,053.00)		
				23	Aug 17, 2020	SYSTEM	\$1,062,053.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user clowez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
				24	Sep 1, 2020	SYSTEM	(\$1,062,053.00)		
				24	Sep 1, 2020	SYSTEM	\$1,062,053.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user clowez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
				25	Sep 16, 2020	SYSTEM	(\$1,062,053.00)		
				25	Sep 16, 2020	SYSTEM	\$1,062,053.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user clowez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)	Other Item Adjustment	ACAD	21	Jul 16, 2020	clowez1	(\$43,768.63)	Asphalt Cement Price Adjustment	
			ACAD - Tota	al			(\$43,768.63)		
	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125B MIX)		SMAB	23	Aug 17, 2020	clowez1	\$6,314.89	IRI Smoothness bonus Rt. H Southbound and Northbound.	



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
LING	Description	Туре	Adjustment Type		Date	Ву	, inount	i tomarko
0090		Other Item Adjustment	SMAB - Tota	al			\$6,314.89	
	Other Item Adjustment - Total						(\$37,453.74)	
0090 -	Total						(\$37,453.74)	
0110	MISC. POLYMER MODIFIED EMULSION MEMBRANE	Material		21	Jul 16, 2020	SYSTEM	(\$47,347.50)	
				21	Jul 16, 2020	SYSTEM	\$47,347.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user clowez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				22	Aug 3, 2020	SYSTEM	(\$47,347.50)	
				22	Aug 3, 2020	SYSTEM	\$47,347.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user clowez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	MISC. POLYMER MODIFIED EMULSION MEMBRANE	Other Item Adjustment	UBAW	21	Jul 16, 2020	clowez1	(\$830.95)	UBAWS Adjustment (Membrane)
			UBAW - Tot	al			(\$830.95)	
	Other Item Adjustment - Total						(\$830.95)	
0110 -	Total						(\$830.95)	
0120	PIPE COLLAR, TYPE A	Material		24	Sep 1, 2020	SYSTEM	(\$4,000.00)	
				25	Sep 16, 2020	SYSTEM	(\$4,000.00)	
				25	Sep 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user clowez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				(\$4,000.00)	
	Material - Total						(\$4,000.00)	
	PIPE COLLAR, TYPE A	MaterialCredit		25	Sep 16, 2020	SYSTEM	\$4,000.00	
			- Total				\$4,000.00	
	MaterialCredit - Total						\$4,000.00	
0120 -	Total						\$0.00	
0140	MISC. INLET TOP REPLACEMENT	Material		24	Sep 1, 2020	SYSTEM	(\$5,600.00)	
				25	Sep 16, 2020	SYSTEM	(\$5,600.00)	
				25	Sep 16, 2020	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user clowez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				(\$5,600.00)	
	Material - Total						(\$5,600.00)	
	MISC. INLET TOP REPLACEMENT	MaterialCredit		25	Sep 16, 2020	SYSTEM	\$5,600.00	
			- Total				\$5,600.00	
	MaterialCredit - Total						\$5,600.00	
0140 -	Total						\$0.00	
0150	CONCRETE MEDIAN	Material		22	Aug 3, 2020	SYSTEM	(\$138,580.00)	
				22	Aug 3, 2020	SYSTEM	\$138,580.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user clowez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				23	Aug 17, 2020	SYSTEM	(\$346,372.00)	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0150	CONCRETE MEDIAN	Material						overridding Payment Estimate Exception 9 on the current Payment Estimate.
				24	Sep 1, 2020	SYSTEM	(\$346,372.00)	
				24	Sep 1, 2020	SYSTEM	\$346,372.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user clowez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				25	Sep 16, 2020	SYSTEM	(\$346,372.00)	
				25	Sep 16, 2020	SYSTEM	\$346,372.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user clowez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	CONCRETE MEDIAN	Overrun	Overrun	23	Aug 17, 2020	SYSTEM	(\$10,192.00)	
				23	Aug 17, 2020	SYSTEM	\$10,192.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 52 on the current Payment Estimate.
				24	Sep 1, 2020	SYSTEM	(\$10,192.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				24	Sep 1, 2020	SYSTEM	\$10,192.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 38 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0150 -	Total						\$0.00	
0160	TRUNCATED DOMES	Material		20	Jul 1, 2020	SYSTEM	(\$600.00)	
				20	Jul 1, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user clowez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				21	Jul 16, 2020	SYSTEM	(\$600.00)	
				21	Jul 16, 2020	SYSTEM	\$600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user clowez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total	1			\$0.00	
	Material - Total						\$0.00	
	TRUNCATED DOMES	Overrun	Overrun	23	Aug 17, 2020	SYSTEM	(\$1,710.00)	
				25	Sep 16, 2020	SYSTEM	\$1,710.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',30.00000 - 30.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0160 -	Total						\$0.00	
0170	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	Material		7	Dec 17, 2019	SYSTEM	(\$45,000.00)	
				8	Jan 2, 2020	SYSTEM	(\$50,970.00)	
				9	Jan 16, 2020	SYSTEM	(\$74,070.00)	
				10	Feb 3, 2020	SYSTEM	(\$74,070.00)	
				11	Feb 18, 2020	SYSTEM	(\$74,070.00)	
				12	Mar 2, 2020	SYSTEM	(\$86,040.00)	
				12	Mar 2, 2020	SYSTEM	\$86,040.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user clowez1 overridding Payment Estimate Exception 4 on the current Payment



ne	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
70	CONCRETE CURB (OVER 6 IN.	Material						Estimate.													
	HEIGHT) TYPE S			13	Mar 16, 2020	SYSTEM	(\$117,585.00)														
				13	Mar 16, 2020	SYSTEM	\$117,585.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user clowez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.													
				14	Apr 2, 2020	SYSTEM	(\$143,040.00)														
				14	Apr 2, 2020	SYSTEM	\$143,040.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user clowez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.													
						15	Apr 15, 2020	SYSTEM	(\$156,585.00)												
				15	Apr 15, 2020	SYSTEM	\$156,585.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user clowez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
				16	May 4, 2020	SYSTEM	(\$174,855.00)														
				16	May 4, 2020	SYSTEM	\$174,855.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user clowez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
				17	May 15, 2020	SYSTEM	(\$181,290.00)														
				17	May 15, 2020	SYSTEM	\$181,290.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user cunnid3 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
				18	Jun 2, 2020	SYSTEM	(\$182,310.00)														
				18	Jun 2, 2020	SYSTEM	\$182,310.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user cunnid3 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
				19	Jun 15, 2020	SYSTEM	(\$211,140.00)														
				19	Jun 15, 2020	SYSTEM	\$211,140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user clowez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
									20	Jul 1, 2020	SYSTEM	(\$245,535.00)									
												20	Jul 1, 2020	SYSTEM	\$245,535.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user clowez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
				21	Jul 16, 2020	SYSTEM	(\$245,535.00)														
				21	Jul 16, 2020	SYSTEM	\$245,535.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user clowez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.													
				22	Aug 3, 2020	SYSTEM	(\$255,795.00)														
																	22	Aug 3, 2020	SYSTEM	\$255,795.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user clowez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				23	Aug 17, 2020	SYSTEM	(\$255,795.00)														
				23	Aug 17, 2020	SYSTEM	\$255,795.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user clowez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.													
				24	Sep 1, 2020	SYSTEM	(\$255,795.00)														
				24	Sep 1, 2020	SYSTEM	\$255,795.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user clowez1													



_ine	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0170	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	Material						overridding Payment Estimate Exception 16 on the current Payment Estimate.
				25	Sep 16, 2020	SYSTEM	(\$256,545.00)	
				25	Sep 16, 2020	SYSTEM	\$256,545.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user clowez1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
			- Total				(\$318,180.00)	
	Material - Total						(\$318,180.00)	
	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	MaterialCredit		8	Jan 2, 2020	SYSTEM	\$45,000.00	
				9	Jan 16, 2020	SYSTEM	\$50,970.00	
				10	Feb 3, 2020	SYSTEM	\$74,070.00	
				11	Feb 18, 2020	SYSTEM	\$74,070.00	
				12	Mar 2, 2020	SYSTEM	\$74,070.00	
			- Total				\$318,180.00	
	MaterialCredit - Total						\$318,180.00	
	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	Other Item Adjustment	PPPS	8	Jan 2, 2020	clowez1	\$50,970.00	Return of 15+00 - 38+98
				10	Feb 3, 2020	clowez1	\$23,100.00	Awaiting successful cre2o submission.
				12	Mar 2, 2020	clowez1	(\$74,070.00)	Taking back PPPS due to new adjustment method in AWP.
			PPPS - Tota	ıl			\$0.00	
	Other Item Adjustment - Total						\$0.00	
	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	Overrun	Overrun	22	Aug 3, 2020	SYSTEM	(\$7,170.00)	
				22	Aug 3, 2020	SYSTEM	\$7,170.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 43 on the current Payment Estimate.
				23	Aug 17, 2020	SYSTEM	(\$7,170.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				23	Aug 17, 2020	SYSTEM	\$7,170.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 54 on the current Payment Estimate.
				24	Sep 1, 2020	SYSTEM	(\$7,170.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				24	Sep 1, 2020	SYSTEM	\$7,170.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 40 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
70 -	Total						\$0.00	
80	CONCRETE GUTTER TYPE A	Material		21	Jul 16, 2020	SYSTEM	(\$62,468.00)	
				21	Jul 16, 2020	SYSTEM	\$62,468.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user clowez1 overridding Payment Estimate Exception 14 on the current Paymen Estimate.
				22	Aug 3, 2020	SYSTEM	(\$62,468.00)	
				22	Aug 3, 2020	SYSTEM	\$62,468.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user clowez1 overridding Payment Estimate Exception 15 on the current Paymen Estimate.
				23	Aug 17, 2020	SYSTEM	(\$62,468.00)	
				23	Aug 17, 2020	SYSTEM	\$62,468.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user clowez1 overridding Payment Estimate Exception 13 on the current Paymen Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
0180	CONCRETE GUTTER TYPE A	Material		24	Sep 1, 2020	SYSTEM	(\$62,468.00)			
				24	Sep 1, 2020	SYSTEM	\$62,468.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user clowez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.		
				25	Sep 16, 2020	SYSTEM	(\$62,468.00)			
				25	Sep 16, 2020	SYSTEM	\$62,468.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user clowez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.		
			- Total				\$0.00			
	Material - Total						\$0.00			
180 ·	- Total						\$0.00			
190	CONCRETE GUTTER TYPE B	Material		21	Jul 16, 2020	SYSTEM	(\$13,692.00)			
				21	Jul 16, 2020	SYSTEM	\$13,692.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user clowez1 overridding Payment Estimate Exception 23 on the current Payment Estimate.		
				22	Aug 3, 2020	SYSTEM	(\$13,692.00)			
				22	Aug 3, 2020	SYSTEM	\$13,692.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user clowez1 overridding Payment Estimate Exception 19 on the current Payment Estimate.		
				23	Aug 17, 2020	SYSTEM	(\$13,692.00)			
							23	Aug 17, 2020	SYSTEM	\$13,692.00
				24	Sep 1, 2020	SYSTEM	(\$13,692.00)			
				24	Sep 1, 2020	SYSTEM	\$13,692.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user clowez1 overridding Payment Estimate Exception 21 on the current Payment Estimate.		
				25	Sep 16, 2020	SYSTEM	(\$13,692.00)			
				25	Sep 16, 2020	SYSTEM	\$13,692.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user clowez1 overridding Payment Estimate Exception 21 on the current Payment Estimate.		
			- Total				\$0.00			
	Material - Total						\$0.00			
190 -	- Total						\$0.00			
200	CURB AND GUTTER TYPE B	Material		18	Jun 2, 2020	SYSTEM	(\$4,890.00)			
				18	Jun 2, 2020	SYSTEM	\$4,890.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user cunnid3 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
				19	Jun 15, 2020	SYSTEM	(\$4,890.00)			
				19	Jun 15, 2020	SYSTEM	\$4,890.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user clowez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
				20	Jul 1, 2020	SYSTEM	(\$4,890.00)			
				20	Jul 1, 2020	SYSTEM	\$4,890.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user clowez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.		
				21	Jul 16, 2020	SYSTEM	(\$4,890.00)			



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
0200	CURB AND GUTTER TYPE B	Material			2020			Payment Estimate Item Adjustment (0014) due to user clowez1 overridding Payment Estimate Exception 24 on the current Payment Estimate.								
				22	Aug 3, 2020	SYSTEM	(\$4,890.00)									
				22	Aug 3, 2020	SYSTEM	\$4,890.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user clowez1 overridding Payment Estimate Exception 23 on the current Payment Estimate.								
				23	Aug 17, 2020	SYSTEM	(\$4,890.00)									
				23	Aug 17, 2020	SYSTEM	\$4,890.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user clowez1 overridding Payment Estimate Exception 21 on the current Payment Estimate.								
						24	Sep 1, 2020	SYSTEM	(\$4,980.00)							
				24	Sep 1, 2020	SYSTEM	\$4,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user clowez1 overridding Payment Estimate Exception 24 on the current Payment Estimate.								
				25	Sep 16, 2020	SYSTEM	(\$4,980.00)									
				25	Sep 16, 2020	SYSTEM	\$4,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user clowez1 overridding Payment Estimate Exception 24 on the current Payment Estimate.								
			- Total				\$0.00									
0200 - '	Material - Total						\$0.00									
0200 -	INTEGRAL CURB TYPE N	Material		15	Apr 15, 2020	SYSTEM	\$0.00 (\$1,650.00)									
				16	May 4, 2020	SYSTEM	(\$1,650.00)									
				17	May 15, 2020	SYSTEM	(\$1,650.00)									
					18	Jun 2, 2020	SYSTEM	(\$1,650.00)								
				19	Jun 15, 2020	SYSTEM	(\$1,650.00)									
				20	Jul 1, 2020	SYSTEM	(\$1,650.00)									
					21	Jul 16, 2020	SYSTEM	(\$1,650.00)								
				21	Jul 16, 2020	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user clowez1 overridding Payment Estimate Exception 27 on the current Payment Estimate.								
				22	Aug 3, 2020	SYSTEM	(\$1,650.00)									
				22	Aug 3, 2020	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user clowez1 overridding Payment Estimate Exception 26 on the current Payment Estimate.								
				23	Aug 17, 2020	SYSTEM	(\$1,650.00)									
								2				23	Aug 17, 2020	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user clowez1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				24	Sep 1, 2020	SYSTEM	(\$1,650.00)									
					24	Sep 1, 2020	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user clowez1 overridding Payment Estimate Exception 26 on the current Payment Estimate.							
				25	Sep 16, 2020	SYSTEM	(\$1,650.00)									
				25	Sep 16,	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Overrun								



ine	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
			Туре	Humber		Dy		
210	INTEGRAL CURB TYPE N	Material			2020			Payment Estimate Item Adjustment (0017) due to user clowez1 overridding Payment Estimate Exception 26 on the current Payme Estimate.
			- Total				(\$9,900.00)	
	Material - Total						(\$9,900.00)	
	INTEGRAL CURB TYPE N	MaterialCredit		16	May 4, 2020	SYSTEM	\$1,650.00	
				17	May 15, 2020	SYSTEM	\$1,650.00	
				18	Jun 2, 2020	SYSTEM	\$1,650.00	
				19	Jun 15, 2020	SYSTEM	\$1,650.00	
				20	Jul 1, 2020	SYSTEM	\$1,650.00	
				21	Jul 16, 2020	SYSTEM	\$1,650.00	
			- Total				\$9,900.00	
	MaterialCredit - Total						\$9,900.00	
0 -	Total						\$0.00	
20	FURNISHING TYPE 2 ROCK DITCH LINER	Material		17	May 15, 2020	SYSTEM	(\$2,600.00)	
				17	May 15, 2020	SYSTEM	\$2,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user cunnid3 overridding Payment Estimate Exception 9 on the current Paymer Estimate.
				18	Jun 2, 2020	SYSTEM	(\$2,600.00)	
				18	Jun 2, 2020	SYSTEM	\$2,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user cunnid3 overridding Payment Estimate Exception 16 on the current Paymer Estimate.
				19	Jun 15, 2020	SYSTEM	(\$2,600.00)	
				20	Jul 1, 2020	SYSTEM	(\$2,600.00)	
				21	Jul 16, 2020	SYSTEM	(\$2,600.00)	
				22	Aug 3, 2020	SYSTEM	(\$2,600.00)	
				23	Aug 17, 2020	SYSTEM	(\$2,600.00)	
			- Total				(\$13,000.00)	
	Material - Total						(\$13,000.00)	
	FURNISHING TYPE 2 ROCK DITCH LINER	MaterialCredit		20	Jul 1, 2020	SYSTEM	\$2,600.00	
				21	Jul 16, 2020	SYSTEM	\$2,600.00	
				22	Aug 3, 2020	SYSTEM	\$2,600.00	
				23	Aug 17, 2020	SYSTEM	\$2,600.00	
				24	Sep 1, 2020	SYSTEM	\$2,600.00	
			- Total				\$13,000.00	
	MaterialCredit - Total						\$13,000.00	
	FURNISHING TYPE 2 ROCK DITCH LINER	Other Item Adjustment	OADJ	17	May 18, 2020	brookw1	(\$1,200.00)	material discrepancy over-ridden, adjusting for overrun override.
				25	Sep 16, 2020	clowez1	\$1,200.00	Overrun Re-adjustment, this amount was taken away twice for a materials discrepancy and an overrun discrepancy.
			OADJ - Tota	ıl			\$0.00	
	Other Item Adjustment - Total						\$0.00	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
0220	DITCH LINER	Overrun	Overrun		2020					
				17	May 15, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 16 on the current Payment Estimate.		
				18	Jun 2, 2020	SYSTEM	(\$1,200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		
				18	Jun 2, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 27 on the current Payment Estimate.		
				19	Jun 15, 2020	SYSTEM	(\$1,200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		
				19	Jun 15, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 28 on the current Payment Estimate.		
				20	Jul 1, 2020	SYSTEM	(\$1,200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		
				20	Jul 1, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 21 on the current Payment Estimate.		
				21	Jul 16, 2020	SYSTEM	(\$1,200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		
				21	Jul 16, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 44 on the current Payment Estimate.		
				22	Aug 3, 2020	SYSTEM	(\$1,200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		
				22	Aug 3, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 44 on the current Payment Estimate.		
				23	Aug 17, 2020	SYSTEM	(\$1,200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		
				23	Aug 17, 2020	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 55 on the current Payment Estimate.		
				24	Sep 1, 2020	SYSTEM	(\$1,200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		
						24	Sep 1, 2020	SYSTEM	(\$180.00)	
				25	Sep 16, 2020	SYSTEM	\$1,380.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',40.00000 - 40.00000, 'is applied (if non-zero).		
			Overrun - T	otal			\$0.00			
	Overrun - Total						\$0.00			
0220 - 0230	Total PLACING TYPE 2 ROCK DITCH	Overrun	Overrun	17	May 15,	SYSTEM	\$0.00 (\$2,400.00)			
	LINER			24	2020 Sep 1,	SYSTEM	(\$360.00)			
				25	2020 Sep 16,	SYSTEM	\$2,760.00	Unit price based on averaged overrun adjustments for installed		
			Overrun - T	otal —	2020		\$0.00	quantity on all previous payment estimates. Price Adjustments of ',80.00000 - 80.00000, 'is applied (if non-zero).		
	Overrun - Total			oran						
0230 -							\$0.00			
0230 - 0240	MISC. MODIFIED 4 IN. CURB AND GUTTER, TYPE A	Material		18	Jun 2, 2020	SYSTEM	\$0.00 (\$15,132.00)			
	Soften, HIEA			18	Jun 2, 2020	SYSTEM	\$15,132.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user cunnid3 overridding Payment Estimate Exception 18 on the current Payment Estimate.		
				19	Jun 15, 2020	SYSTEM	(\$15,132.00)			
				19	Jun 15, 2020	SYSTEM	\$15,132.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user clowez1 overridding Payment Estimate Exception 18 on the current Payment Estimate.		



ine	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
240	MISC. MODIFIED 4 IN. CURB AND GUTTER, TYPE A	Material		20	Jul 1, 2020	SYSTEM	(\$15,132.00)						
				20	Jul 1, 2020	SYSTEM	\$15,132.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user clowez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.					
				21	Jul 16, 2020	SYSTEM	(\$15,132.00)						
				21	Jul 16, 2020	SYSTEM	\$15,132.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user clowez1 overridding Payment Estimate Exception 36 on the current Payment Estimate.					
				22	Aug 3, 2020	SYSTEM	(\$15,132.00)						
				22	Aug 3, 2020	SYSTEM	\$15,132.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user clowez1 overridding Payment Estimate Exception 35 on the current Payment Estimate.					
				23	Aug 17, 2020	SYSTEM	(\$15,132.00)						
				23	Aug 17, 2020	SYSTEM	\$15,132.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user clowez1 overridding Payment Estimate Exception 30 on the current Payment Estimate.					
				24	Sep 1, 2020	SYSTEM	(\$17,160.00)						
				24	Sep 1, 2020	SYSTEM	\$17,160.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user clowez1 overridding Payment Estimate Exception 31 on the current Payment Estimate.					
				25	Sep 16, 2020	SYSTEM	(\$17,160.00)						
				25	Sep 16, 2020	SYSTEM	\$17,160.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user clowez1 overridding Payment Estimate Exception 31 on the current Paymen Estimate.					
			- Total				\$0.00						
	Material - Total						\$0.00						
240 250	- Total MISC. TRANSITION TYPE A TO	Material		21	Jul 16,	SYSTEM	\$0.00 (\$780.00)						
.00	TYPE B GUTTER			21	2020 Jul 16,	SYSTEM	\$780.00	This adjustment offsets the original system-generated Overrun					
				21	2020	STOTEM	\$780.00	Payment Estimate Item Adjustment (0016) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.					
				22	Aug 3, 2020	SYSTEM	(\$780.00)						
				22	Aug 3, 2020	SYSTEM	\$780.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.					
				23	Aug 17, 2020	SYSTEM	(\$780.00)						
									23	Aug 17, 2020	SYSTEM	\$780.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				24	Sep 1, 2020	SYSTEM	(\$780.00)						
					2020								
				24	Sep 1, 2020	SYSTEM	\$780.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.					
				24 25	Sep 1,	SYSTEM SYSTEM	\$780.00	Payment Estimate Item Adjustment (0021) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment					
					Sep 1, 2020 Sep 16,			Payment Estimate Item Adjustment (0021) due to user clowez1 overridding Payment Estimate Exception 1 on the current Payment					



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
0250	Material - Total						\$0.00								
0250 -	- Total						\$0.00								
0260	MISC. TRANSITION TYPE B TO TYPE A GUTTER	Material		21	Jul 16, 2020	SYSTEM	(\$900.00)								
				21	Jul 16, 2020	SYSTEM	\$900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user clowez1 overridding Payment Estimate Exception 31 on the current Payment Estimate.							
				22	Aug 3, 2020	SYSTEM	(\$900.00)								
								22	Aug 3, 2020	SYSTEM	\$900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user clowez1 overridding Payment Estimate Exception 30 on the current Payment Estimate.			
				23	Aug 17, 2020	SYSTEM	(\$900.00)								
				23	Aug 17, 2020	SYSTEM	\$900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user clowez1 overridding Payment Estimate Exception 26 on the current Payment Estimate.							
				24	Sep 1, 2020	SYSTEM	(\$900.00)								
							24	Sep 1, 2020	SYSTEM	\$900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user clowez1 overridding Payment Estimate Exception 28 on the current Payment Estimate.				
											25	Sep 16, 2020	SYSTEM	(\$900.00)	
				25	Sep 16, 2020	SYSTEM	\$900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user clowez1 overridding Payment Estimate Exception 28 on the current Payment Estimate.							
			- Total				\$0.00								
	Material - Total						\$0.00								
)260 -	- Total						\$0.00								
0310	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	L		4	Nov 4, 2019	SYSTEM	(\$9,570.00)								
											5	Nov 18, 2019	SYSTEM	(\$1,760.00)	
				6	Dec 2, 2019	SYSTEM	(\$1,760.00)								
				7	Dec 17, 2019	SYSTEM	(\$1,760.00)								
				8	Jan 2, 2020	SYSTEM	(\$1,760.00)								
				9	Jan 16, 2020	SYSTEM	(\$9,790.00)								
				10	Feb 3, 2020	SYSTEM	(\$9,790.00)								
				11	Feb 18, 2020	SYSTEM	(\$9,790.00)								
				12	Mar 2, 2020	SYSTEM	(\$9,790.00)								
							12	Mar 2, 2020	SYSTEM	\$9,790.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user clowez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.				
				13	Mar 16, 2020	SYSTEM	(\$26,070.00)								
				13	Mar 16, 2020	SYSTEM	\$26,070.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user clowez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.							
				14	Apr 2, 2020	SYSTEM	(\$31,460.00)								
								\$31,460.00	This adjustment offsets the original system-generated Overrun						



e	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																		
0	FURNISHING AND PLACING	Material						Estimate.																		
	CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR			15	Apr 15, 2020	SYSTEM	(\$37,730.00)																			
				15	Apr 15, 2020	SYSTEM	\$37,730.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user clowez1 overridding Payment Estimate Exception 12 on the current Paymen Estimate.																		
				16	May 4, 2020	SYSTEM	(\$41,030.00)																			
				16	May 4, 2020	SYSTEM	\$41,030.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user clowez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																		
				17	May 15, 2020	SYSTEM	(\$41,030.00)																			
							17	May 15, 2020	SYSTEM	\$41,030.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user cunnid3 overridding Payment Estimate Exception 11 on the current Paymen Estimate.															
					18	Jun 2, 2020	SYSTEM	(\$41,030.00)																		
				18	Jun 2, 2020	SYSTEM	\$41,030.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user cunnid3 overridding Payment Estimate Exception 22 on the current Paymen Estimate.																		
								19	Jun 15, 2020	SYSTEM	(\$64,460.00)															
							19	Jun 15, 2020	SYSTEM	\$64,460.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user clowez1 overridding Payment Estimate Exception 22 on the current Payme Estimate.															
							20	Jul 1, 2020	SYSTEM	(\$81,730.00)																
					20	Jul 1, 2020	SYSTEM	\$81,730.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user clowez1 overridding Payment Estimate Exception 17 on the current Payme Estimate.																	
						21	Jul 16, 2020	SYSTEM	(\$81,730.00)																	
						21	Jul 16, 2020	SYSTEM	\$81,730.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user clowez1 overridding Payment Estimate Exception 39 on the current Paymen Estimate.																
																						22	Aug 3, 2020	SYSTEM	(\$87,340.00)	
																			22	Aug 3, 2020	SYSTEM	\$87,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user clowez1 overridding Payment Estimate Exception 38 on the current Payme Estimate.			
													23	Aug 17, 2020	SYSTEM	(\$87,340.00)										
							23	Aug 17, 2020	SYSTEM	\$87,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user clowez1 overridding Payment Estimate Exception 32 on the current Payme Estimate.															
				24	Sep 1, 2020	SYSTEM	(\$87,340.00)																			
																	24	Sep 1, 2020	SYSTEM	\$87,340.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user clowez1 overridding Payment Estimate Exception 33 on the current Payme Estimate.					
				25	Sep 16, 2020	SYSTEM	(\$97,130.00)																			
				25	Sep 16, 2020	SYSTEM	\$97,130.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user clowez1 overridding Payment Estimate Exception 33 on the current Payme Estimate.																		
			- Total				(\$45,980.00)																			
	Material - Total						(\$45,980.00)																			
	FURNISHING AND PLACING	MaterialCredit		5	Nov 18,	SYSTEM	\$9,570.00																			



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
0310	CONCRETE MATERIAL FOR FULL	MaterialCredit			2019					
	DEPTH PAVEMENT REPAIR			6	Dec 2, 2019	SYSTEM	\$1,760.00			
				7	Dec 17, 2019	SYSTEM	\$1,760.00			
				8	Jan 2, 2020	SYSTEM	\$1,760.00			
				9	Jan 16, 2020	SYSTEM	\$1,760.00			
				10	Feb 3, 2020	SYSTEM	\$9,790.00			
				11	Feb 18, 2020	SYSTEM	\$9,790.00			
				12	Mar 2, 2020	SYSTEM	\$9,790.00			
			- Total				\$45,980.00			
	MaterialCredit - Total						\$45,980.00			
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Other Item Adjustment	PPPS	8	Jan 2, 2020	clowez1	\$1,760.00	19 and 20 series crossover.		
	DEF HITAVEMENT REPAIR			9	Jan 16, 2020	clowez1	\$8,030.00	15 series crossover.		
				12	Mar 2, 2020	clowez1	(\$9,790.00)	Taking back PPPS due to new adjustment method in AWP.		
			PPPS - Tota	ıl			\$0.00			
	Other Item Adjustment - Total						\$0.00			
0310 -							\$0.00			
0320	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material		9	Jan 16, 2020	SYSTEM	(\$0.73)			
				10	Feb 3, 2020	SYSTEM	(\$0.89)			
				11	Feb 18, 2020	SYSTEM	(\$0.89)			
				12	Mar 2, 2020	SYSTEM	(\$0.89)			
				13	Mar 16, 2020	SYSTEM	(\$1.43)			
				14	Apr 2, 2020	SYSTEM	(\$1.43)			
				14	Apr 2, 2020	SYSTEM	\$1.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user clowez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.		
				15	Apr 15, 2020	SYSTEM	(\$1.43)			
				15	Apr 15, 2020	SYSTEM	\$1.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user clowez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.		
				16	May 4, 2020	SYSTEM	(\$1.43)			
						16	May 4, 2020	SYSTEM	\$1.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user clowez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				17	May 15, 2020	SYSTEM	(\$1.43)			
				18	Jun 2, 2020	SYSTEM	(\$1.43)			
				18	Jun 2, 2020	SYSTEM	\$1.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user cunnid3 overridding Payment Estimate Exception 24 on the current Payment Estimate.		
				19	Jun 15, 2020	SYSTEM	(\$1.43)			
				19	Jun 15, 2020	SYSTEM	\$1.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user clowez1		



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0320	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material						overridding Payment Estimate Exception 24 on the current Payment Estimate.	
				20	Jul 1, 2020	SYSTEM	(\$1.43)		
				20	Jul 1, 2020	SYSTEM	\$1.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user clowez1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	
				21	Jul 16, 2020	SYSTEM	(\$1.43)		
				21	Jul 16, 2020	SYSTEM	\$1.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user clowez1 overridding Payment Estimate Exception 41 on the current Payment Estimate.	
				22	Aug 3, 2020	SYSTEM	(\$1.43)		
				22	Aug 3, 2020	SYSTEM	\$1.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user clowez1 overridding Payment Estimate Exception 40 on the current Payment Estimate.	
				23	Aug 17, 2020	SYSTEM	(\$1.43)		
				23	Aug 17, 2020	SYSTEM	\$1.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user clowez1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	
				24	Sep 1, 2020	SYSTEM	(\$1.43)		
				24	Sep 1, 2020	SYSTEM	\$1.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user clowez1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	
					25	Sep 16, 2020	SYSTEM	(\$1.43)	
				25	Sep 16, 2020	SYSTEM	\$1.43	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user clowez1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	
			- Total				(\$6.26)		
	Material - Total SUBGRADE COMPACTION (6 IN.	MaterialCredit		10	Feb 3,	SYSTEM	(\$6.26) \$0.73		
	DEPTH) (PAVEMENT REPAIR)			11	2020 Feb 18,	SYSTEM	\$0.89		
				12	2020 Mar 2, 2020	SYSTEM	\$0.89		
				13	2020 Mar 16, 2020	SYSTEM	\$0.89		
				14	Apr 2, 2020	SYSTEM	\$1.43		
				18	Jun 2, 2020	SYSTEM	\$1.43		
			- Total				\$6.26		
	MaterialCredit - Total						\$6.26		
0320 -	Total						\$0.00		
0330	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	Material		9	Jan 16, 2020	SYSTEM	(\$0.73)		
				10	Feb 3, 2020	SYSTEM	(\$0.89)		
				11	Feb 18, 2020	SYSTEM	(\$0.89)		
				13	Mar 16, 2020	SYSTEM	(\$2.37)		
				14	Apr 2, 2020	SYSTEM	(\$2.86)		
				14	Apr 2, 2020	SYSTEM	\$2.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user clowez1	



	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																				
)	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT	Material						overridding Payment Estimate Exception 8 on the current Payment Estimate.																				
	REPAIR)			15	Apr 15, 2020	SYSTEM	(\$6.49)																					
				15	Apr 15, 2020	SYSTEM	\$6.49	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user clowez1 overridding Payment Estimate Exception 15 on the current Paymen Estimate.																				
				16	May 4, 2020	SYSTEM	(\$6.49)																					
				16	May 4, 2020	SYSTEM	\$6.49	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user clowez1 overridding Payment Estimate Exception 12 on the current Payme Estimate.																				
				17	May 15, 2020	SYSTEM	(\$6.49)																					
						18	Jun 2, 2020	SYSTEM	(\$11.74)																			
				18	Jun 2, 2020	SYSTEM	\$11.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user cunnid3 overridding Payment Estimate Exception 25 on the current Payme Estimate.																				
				19	Jun 15, 2020	SYSTEM	(\$11.74)																					
				19	Jun 15, 2020	SYSTEM	\$11.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user clowez1 overridding Payment Estimate Exception 25 on the current Payme Estimate.																				
				20	Jul 1, 2020	SYSTEM	(\$11.74)																					
					20	Jul 1, 2020	SYSTEM	\$11.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user clowez1 overridding Payment Estimate Exception 20 on the current Paymer Estimate.																			
							21	Jul 16, 2020	SYSTEM	(\$11.74)																		
				21	Jul 16, 2020	SYSTEM	\$11.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user clowez1 overridding Payment Estimate Exception 42 on the current Paymer Estimate.																				
					22	Aug 3, 2020	SYSTEM	(\$11.74)																				
				22	Aug 3, 2020	SYSTEM	\$11.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user clowez1 overridding Payment Estimate Exception 41 on the current Paymer Estimate.																				
				23	Aug 17, 2020	SYSTEM	(\$11.74)																					
				23	Aug 17, 2020	SYSTEM	\$11.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user clowez1 overridding Payment Estimate Exception 35 on the current Payme Estimate.																				
				24	Sep 1, 2020	SYSTEM	(\$11.74)																					
																								24	Sep 1, 2020	SYSTEM	\$11.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user clowez1 overridding Payment Estimate Exception 36 on the current Payme Estimate.
				25	Sep 16, 2020	SYSTEM	(\$11.74)																					
				25	Sep 16, 2020	SYSTEM	\$11.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user clowez1 overridding Payment Estimate Exception 36 on the current Payme Estimate.																				
			- Total				(\$11.37)																					
	Material - Total TYPE 1 OR 5 AGGREGATE FOR	MaterialCredit		10	Feb 3,	SYSTEM	(\$11.37) \$0.73																					
	BASE (4 IN. THICK) (PAVEMENT REPAIR)				2020																							



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0330	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	MaterialCredit		12	Mar 2, 2020	SYSTEM	\$0.89	
	KEFAIN)			14	Apr 2, 2020	SYSTEM	\$2.37	
				18	Jun 2, 2020	SYSTEM	\$6.49	
			- Total				\$11.37	
	MaterialCredit - Total						\$11.37	
0330 -	Total						\$0.00	
0350	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		4	Nov 4, 2019	SYSTEM	(\$264.00)	
			- Total				(\$264.00)	
	Material - Total						(\$264.00)	
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	MaterialCredit		5	Nov 18, 2019	SYSTEM	\$264.00	
			- Total				\$264.00	
	MaterialCredit - Total						\$264.00	
0350 -							\$0.00	
0380	MISC. MSD STANDARD MANHOLE FRAME AND COVER	Material		4	Nov 4, 2019	SYSTEM	(\$800.00)	
				5	Nov 18, 2019	SYSTEM	(\$800.00)	
				6	Dec 2, 2019	SYSTEM	(\$800.00)	
				7	Dec 17, 2019	SYSTEM	(\$800.00)	
				8	Jan 2, 2020	SYSTEM	(\$800.00)	
			- Total				(\$4,000.00)	
	Material - Total						(\$4,000.00)	
	MISC. MSD STANDARD MANHOLE FRAME AND COVER	MaterialCredit		5	Nov 18, 2019	SYSTEM	\$800.00	
				6	Dec 2, 2019	SYSTEM	\$800.00	
				7	Dec 17, 2019	SYSTEM	\$800.00	
				8	Jan 2, 2020	SYSTEM	\$800.00	
				9	Jan 16, 2020	SYSTEM	\$800.00	
			- Total				\$4,000.00	
	MaterialCredit - Total MISC. MSD STANDARD MANHOLE	Other Item	PPPS	6	Dec 2,	clowez1	\$4,000.00	Return of 2 structures.
	FRAME AND COVER	Adjustment	FFF5	9	2019	clowez1	\$800.00	
					Jan 16, 2020	ciowez'i	(\$800.00)	Taking back the 2 structures that were returned.
	Other Item Adjustment - Total		PPPS - Tota				\$0.00 \$0.00	
0380 -							\$0.00 \$0.00	
0390	MISC. TEMPORARY TRAFFIC CONTROL	Material		21	Jul 16, 2020	SYSTEM	\$0.00 (\$14,000.00)	
	CONTROL			22	Aug 3, 2020	SYSTEM	(\$14,000.00)	
			- Total				(\$28,000.00)	
	Material - Total						(\$28,000.00)	
	MISC. TEMPORARY TRAFFIC CONTROL	MaterialCredit		22	Aug 3, 2020	SYSTEM	\$14,000.00	



								1
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0390	MISC. TEMPORARY TRAFFIC CONTROL	MaterialCredit		23	Aug 17, 2020	SYSTEM	\$14,000.00	
			- Total				\$28,000.00	
	MaterialCredit - Total						\$28,000.00	
0390 -	Total						\$0.00	
0410	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Material		24	Sep 1, 2020	SYSTEM	(\$5,000.00)	
	NETAINED			25	Sep 16, 2020	SYSTEM	(\$5,000.00)	
				25	Sep 16, 2020	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user clowez1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
			- Total				(\$5,000.00)	
	Material - Total						(\$5,000.00)	
	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	MaterialCredit		25	Sep 16, 2020	SYSTEM	\$5,000.00	
			- Total				\$5,000.00	
	MaterialCredit - Total						\$5,000.00	
0410 -	Total						\$0.00	
0460	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		23	Aug 17, 2020	SYSTEM	(\$15,775.00)	
			- Total				(\$15,775.00)	
	Material - Total		Total				(\$15,775.00)	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	MaterialCredit		24	Sep 1, 2020	SYSTEM	\$15,775.00	
	WHITE		Total				ALE 335 00	
	MaterialCredit - Total		- Total				\$15,775.00	
0460 -							\$15,775.00	
0480 -	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	Material		23	Aug 17, 2020	SYSTEM	\$0.00 (\$2,925.00)	
	YELLOW		Total				(\$2,005,00)	
	Motorial Total		- Total				(\$2,925.00)	
	Material - Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	MaterialCredit		24	Sep 1, 2020	SYSTEM	(\$2,925.00) \$2,925.00	
	YELLOW		- Total				\$2,925.00	
	MaterialCredit - Total		- 10(8)					
0470 -							\$2,925.00 \$0.00	
0470 -	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		23	Aug 17, 2020	SYSTEM	\$0.00 (\$10,850.00)	
			- Total				(\$10,850.00)	
	Material - Total						(\$10,850.00)	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING,	MaterialCredit		24	Sep 1, 2020	SYSTEM	\$10,850.00	
	LEFT/RIGHT ARROW		- Total				\$10,850.00	
	MaterialCredit - Total						\$10,850.00	
0480 -							\$0.00	
0490	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	Material		23	Aug 17, 2020	SYSTEM	(\$5,600.00)	
			- Total				(\$5,600.00)	
	Material - Total						(\$5,600.00)	
		MaterialCrodit		24	Son 1	SVSTEM		
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN	watenatoredit		24	Sep 1, 2020	SYSTEM	\$5,600.00	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0490	WHITE MIDBLOCK	MaterialCredit						
			- Total	1			\$5,600.00	
	MaterialCredit - Total						\$5,600.00	
0490 -	Total						\$0.00	
0510	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		23	Aug 17, 2020	SYSTEM	(\$7,335.40)	
			- Total				(\$7,335.40)	
	Material - Total						(\$7,335.40)	
	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	MaterialCredit		24	Sep 1, 2020	SYSTEM	\$7,335.40	
			- Total				\$7,335.40	
	MaterialCredit - Total						\$7,335.40	
0510 -							\$0.00	
0520	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		23	Aug 17, 2020	SYSTEM	(\$23,644.50)	
			- Total				(\$23,644.50)	
	Material - Total						(\$23,644.50)	
	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	MaterialCredit		24	Sep 1, 2020	SYSTEM	\$23,644.50	
			- Total				\$23,644.50	
	MaterialCredit - Total						\$23,644.50	
0520 -	Total						\$0.00	
0530	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		23	Aug 17, 2020	SYSTEM	(\$2,387.50)	
			- Total				(\$2,387.50)	
	Material - Total						(\$2,387.50)	
	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	MaterialCredit		24	Sep 1, 2020	SYSTEM	\$2,387.50	
			- Total				\$2,387.50	
	MaterialCredit - Total						\$2,387.50	
0530 -	Total						\$0.00	
0540	MISC. PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE REDUCTION(LEFT)	Material		23	Aug 17, 2020	SYSTEM	(\$10,000.00)	
			- Total				(\$10,000.00)	
	Material - Total						(\$10,000.00)	
	MISC. PREFORMED THERMOPLASTIC PAVEMENT MARKING, LANE REDUCTION(LEFT)	MaterialCredit		24	Sep 1, 2020	SYSTEM	\$10,000.00	
			- Total				\$10,000.00	
	MaterialCredit - Total						\$10,000.00	
0540 -	Total						\$0.00	
0550	MISC. PREFORMED THERMOPLASTIC PAVEMENT MARKING, U-TURN ARROW (LEFT)	Material		23	Aug 17, 2020	SYSTEM	(\$3,000.00)	
			- Total				(\$3,000.00)	
	Material - Total						(\$3,000.00)	
	MISC. PREFORMED THERMOPLASTIC PAVEMENT MARKING, U-TURN ARROW (LEFT)	MaterialCredit		24	Sep 1, 2020	SYSTEM	\$3,000.00	
	()		- Total				\$3,000.00	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0550	MaterialCredit - Total						\$3,000.00	
0550 -	Total						\$0.00	
0560	MISC. PREFORMED THERMOPLASTIC PAVEMENT MARKING, U-TURN ONLY WORD	Material		23	Aug 17, 2020	SYSTEM	(\$1,500.00)	
			- Total				(\$1,500.00)	
	Material - Total						(\$1,500.00)	
	MISC. PREFORMED THERMOPLASTIC PAVEMENT MARKING, U-TURN ONLY WORD	MaterialCredit		24	Sep 1, 2020	SYSTEM	\$1,500.00	
			- Total				\$1,500.00	
	MaterialCredit - Total						\$1,500.00	
0560 -	Total			_			\$0.00	
0570	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR	Overrun	Overrun		Jul 16, 2020	SYSTEM	(\$75,502.95)	
	LESS)			25	Sep 16, 2020	SYSTEM	\$75,502.95	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.55000 - 2.55000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0570 -	Total						\$0.00	
0670	MISC. 12 IN. CLASS 3 RCP	Material		6	Dec 2, 2019	SYSTEM	(\$7,250.00)	
				7	Dec 17, 2019	SYSTEM	(\$11,450.00)	
				8	Jan 2, 2020	SYSTEM	(\$11,450.00)	
			- Total				(\$30,150.00)	
	Material - Total	N		-	D (7	OVOTEN	(\$30,150.00)	
	MISC. 12 IN. CLASS 3 RCP	MaterialCredit		7	Dec 17, 2019 Jan 2,	SYSTEM	\$7,250.00	
				9	2020 Jan 16,	SYSTEM	\$11,450.00	
					2020			
			- Total				\$30,150.00	
	MaterialCredit - Total						\$30,150.00	
	Total						\$0.00	
0680	MISC. 15 IN. CLASS 3 RCP	Material		6	Dec 2, 2019 Dec 17,	SYSTEM	(\$1,749.00)	
				8	2019 Jan 2,	SYSTEM	(\$16,006.00)	
			- Total		2020		(\$33,761.00)	
	Material - Total						(\$33,761.00)	
	MISC. 15 IN. CLASS 3 RCP	MaterialCredit		7	Dec 17, 2019	SYSTEM	\$1,749.00	
				8	Jan 2, 2020	SYSTEM	\$16,006.00	
				9	Jan 16, 2020	SYSTEM	\$16,006.00	
			- Total				\$33,761.00	
	MaterialCredit - Total						\$33,761.00	
	MISC. 15 IN. CLASS 3 RCP	Other Item Adjustment	PPPS		Dec 2, 2019	clowez1	\$1,749.00	Return of 33 LF.
				8	Jan 2, 2020 Jan 16,	clowez1	\$14,257.00	269 linear ft. for description. Taking back 302 ft. from estimate 6 and 8.
				5	2020		(\$10,000.00)	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0680		Other Item Adjustment	PPPS - Tota	ıl			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0680 -	Total						\$0.00	
0722	MISC. 12 IN. CLASS 4 RCP	Other Item Adjustment	PPPS	9	Jan 16, 2020	clowez1	\$11,450.00	NB West used class 4 12" pipe instead of class 3.
				12	Mar 2, 2020	clowez1	(\$11,450.00)	Taking back PPPS due to new adjustment method in AWP.
			PPPS - Tota	ıl			\$0.00	
	Other Item Adjustment - Total						\$0.00	
	MISC. 12 IN. CLASS 4 RCP	Overrun	Overrun	9	Jan 16, 2020	SYSTEM	(\$11,450.00)	
				13	Mar 16, 2020	SYSTEM	(\$7,450.00)	
				14	Apr 2, 2020	SYSTEM	(\$13,850.00)	
				15	Apr 15, 2020	SYSTEM	(\$3,150.00)	
				16	May 4, 2020	SYSTEM	\$35,900.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',50.00000 - 50.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0722 -	Total						\$0.00	
0730	MISC. MSD 2 GRATE INLET W/ SIDE INTAKE 48 IN. X 48 IN.	Overrun	Overrun	24	Sep 1, 2020	SYSTEM	(\$6,800.00)	
				25	Sep 16, 2020	SYSTEM	\$6,800.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3400.00000 - 3400.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0730 -	Total						\$0.00	
0740	MISC. MSD AREA INLET 58 IN. X 58 IN.	Material		19	Jun 15, 2020	SYSTEM	(\$2,500.00)	
			- Total				(\$2,500.00)	
	Material - Total						(\$2,500.00)	
	MISC. MSD AREA INLET 58 IN. X 58 IN.	MaterialCredit		20	Jul 1, 2020	SYSTEM	\$2,500.00	
			- Total				\$2,500.00	
	MaterialCredit - Total						\$2,500.00	
0740 -	· Total						\$0.00	
0750	MISC. MSD DOUBLE STREET INLET 108 IN. X 52 IN.	Material		17	May 15, 2020	SYSTEM	(\$16,000.00)	
			- Total				(\$16,000.00)	
	Material - Total						(\$16,000.00)	
	MISC. MSD DOUBLE STREET	MaterialCredit		18	Jun 2, 2020	SYSTEM	\$16,000.00	
	INLET 108 IN. X 52 IN.						\$16,000.00	
			- Total					
			- Total				\$16,000.00	
	INLET 108 IN. X 52 IN.	Overrun	- Total Overrun	24	Sep 1, 2020	SYSTEM		
	INLET 108 IN. X 52 IN. MaterialCredit - Total MISC. MSD DOUBLE STREET	Overrun		24 25		SYSTEM SYSTEM	\$16,000.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',4000.00000 - 4000.00000, 'is applied (if non-zero).
	INLET 108 IN. X 52 IN. MaterialCredit - Total MISC. MSD DOUBLE STREET	Overrun		25	2020 Sep 16,		\$16,000.00 (\$8,000.00)	quantity on all previous payment estimates. Price Adjustments of
	INLET 108 IN. X 52 IN. MaterialCredit - Total MISC. MSD DOUBLE STREET	Overrun	Overrun	25	2020 Sep 16,		\$16,000.00 (\$8,000.00) \$8,000.00	quantity on all previous payment estimates. Price Adjustments of
07 <u>50 -</u>	INLET 108 IN. X 52 IN. MaterialCredit - Total MISC. MSD DOUBLE STREET INLET 108 IN. X 52 IN.	Overrun	Overrun	25	2020 Sep 16,		\$16,000.00 (\$8,000.00) \$8,000.00 \$0.00	quantity on all previous payment estimates. Price Adjustments of
0750 - 0760	INLET 108 IN. X 52 IN. MaterialCredit - Total MISC. MSD DOUBLE STREET INLET 108 IN. X 52 IN. Overrun - Total	Overrun Overrun	Overrun	25 otal	2020 Sep 16,		\$16,000.00 (\$8,000.00) \$8,000.00 \$0.00 \$0.00	quantity on all previous payment estimates. Price Adjustments of



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	·	Туре	Adjustment Type	Number	Date	Ву		
0760	MISC. MSD SINGLE STREET INLET 54 IN. X 48 IN.	Overrun	Overrun		2020			quantity on all previous payment estimates. Price Adjustments of ',3000.00000 - 3000.00000, 'is applied (if non-zero).
			Overrun - To	otal			\$0.00	
	Overrun - Total						\$0.00	
0760 -	Total						\$0.00	
0770	MISC. REPLACE INLET TOP TO NEW GRADE	Material		4	Nov 4, 2019	SYSTEM	(\$4,800.00)	
				5	Nov 18, 2019	SYSTEM	(\$4,800.00)	
				6	Dec 2, 2019	SYSTEM	(\$6,400.00)	
				7	Dec 17, 2019	SYSTEM	(\$6,400.00)	
				8	Jan 2, 2020	SYSTEM	(\$6,400.00)	
				9	Jan 16, 2020	SYSTEM	(\$9,600.00)	
				10	Feb 3, 2020	SYSTEM	(\$12,800.00)	
				11	Feb 18, 2020	SYSTEM	(\$18,400.00)	
				12	Mar 2, 2020	SYSTEM	(\$20,000.00)	
				12	Mar 2, 2020	SYSTEM	\$20,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user clowez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				(\$69,600.00)	
	Material - Total		_				(\$69,600.00)	
	MISC. REPLACE INLET TOP TO NEW GRADE	MaterialCredit		5	Nov 18, 2019	SYSTEM	\$4,800.00	
				6	Dec 2, 2019	SYSTEM	\$4,800.00	
				7	Dec 17, 2019	SYSTEM	\$6,400.00	
				8	Jan 2, 2020	SYSTEM	\$6,400.00	
				9	Jan 16, 2020	SYSTEM	\$6,400.00	
				10	Feb 3, 2020	SYSTEM	\$9,600.00	
				11	Feb 18, 2020	SYSTEM	\$12,800.00	
				12	Mar 2, 2020	SYSTEM	\$18,400.00	
			- Total				\$69,600.00	
	MaterialCredit - Total						\$69,600.00	
	MISC. REPLACE INLET TOP TO NEW GRADE	Other Item Adjustment	PPPS	6	Dec 2, 2019	clowez1	\$6,400.00	Return of 8 inlet tops.
				9	Jan 16, 2020	clowez1	\$3,200.00	13 series inlets.
				12	Mar 2, 2020	clowez1	(\$9,600.00)	Taking back PPPS due to new adjustment method in AWP.
			PPPS - Tota	I			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0770 -							\$0.00	
0780	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material		15	Apr 15, 2020	SYSTEM	(\$800.00)	
				15	Apr 15, 2020	SYSTEM	\$800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user clowez1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
			- Total				\$0.00	
			Total				\$0.00	



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0780 0780 -	Material - Total						\$0.00 \$0.00	
0790	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material		12	Mar 2, 2020	SYSTEM	(\$1,700.00)	
				12	Mar 2, 2020	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user clowez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		- Total				\$0.00		
0790 -	Material - Total						\$0.00 \$0.00	
0750-	MGS VERTICAL CONCRETE	Material		24	Sep 1,	SYSTEM	(\$3,600.00)	
0630	BARRIER TRANSITION	Wateria		24	2020	OTOTEM	(\$0,000.00)	
			- Total				(\$3,600.00)	
	Material - Total						(\$3,600.00)	
	MGS VERTICAL CONCRETE BARRIER TRANSITION			25	Sep 16, 2020	SYSTEM	\$3,600.00	
	MaterialCredit - Total		- Total				\$3,600.00	
0850 -							\$3,600.00	
0860		Material		24	Sep 1, 2020	SYSTEM	(\$3,200.00)	
			- Total				(\$3,200.00)	
	Material - Total						(\$3,200.00)	
	TYPE A CRASHWORTHY END TERMINAL (MASH)	MaterialCredit		25	Sep 16, 2020	SYSTEM	\$3,200.00	
			- Total				\$3,200.00	
	MaterialCredit - Total						\$3,200.00	
	Total						\$0.00	
0890	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Material		13	Mar 16, 2020	SYSTEM	(\$9,510.00)	
	Material - Total	- Total				(\$9,510.00)		
				14	Apr 2, 2020	SYSTEM	\$9,510.00	
			- Total				\$9,510.00	
	MaterialCredit - Total						\$9,510.00	
0890 -	Total						\$0.00	
0900	CABLE, 16 AWG 7 CONDUCTOR	Material		13	Mar 16, 2020	SYSTEM	(\$2,250.00)	
		- Total				(\$2,250.00)		
	Material - Total						(\$2,250.00)	
	CABLE, 16 AWG 7 CONDUCTOR	MaterialCredit		14	Apr 2, 2020	SYSTEM	\$2,250.00	
		- Total				\$2,250.00		
0000-	MaterialCredit - Total - Total						\$2,250.00 \$0.00	
	PULL BOX, PREFORMED CLASS 1	Material		13	Mar 16, 2020	SYSTEM	\$0.00 (\$4,500.00)	
		- Total				(\$4,500.00)		
	Material - Total						(\$4,500.00)	
	PULL BOX, PREFORMED CLASS 1	MaterialCredit		14	Apr 2, 2020	SYSTEM	\$4,500.00	
			- Total				\$4,500.00	
	MaterialCredit - Total						\$4,500.00	
0910 -							\$0.00	
5001	MISC. 12 IN. CLASS 5 RCP	Material		13	Mar 16, 2020	SYSTEM	(\$13,084.05)	
a viole	on 4/1/2020							Page 34 of 3



					1			
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
001	MISC. 12 IN. CLASS 5 RCP	Material		13	Mar 16, 2020	SYSTEM	\$13,084.05	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user clowez1 overridding Payment Estimate Exception 12 on the current Paymen Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
001 -	Total						\$0.00	
002	MISC. 15 IN. CLASS 5 RCP	Material		13	Mar 16, 2020	SYSTEM	(\$8,738.85)	
				13	Mar 16, 2020	SYSTEM	\$8,738.85	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user clowez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
002 -	Total						\$0.00	
003	MISC. 18 IN. CLASS 5 RCP	Material		13	Mar 16, 2020	SYSTEM	(\$9,004.50)	
				13	Mar 16, 2020	SYSTEM	\$9,004.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user clowez1 overridding Payment Estimate Exception 10 on the current Paymen Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
003 -	Total						\$0.00	
005	MISC. 24 IN. CLASS 5 RCP	Material		18	Jun 2, 2020	SYSTEM	(\$5,854.14)	
				18	Jun 2, 2020	SYSTEM	\$5,854.14	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user cunnid3 overridding Payment Estimate Exception 26 on the current Paymer Estimate.
				19	Jun 15, 2020	SYSTEM	(\$5,854.14)	
				19	Jun 15, 2020	SYSTEM	\$5,854.14	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user clowez1 overridding Payment Estimate Exception 26 on the current Paymer Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
005 -	Total						\$0.00	
8008	FIBER OPTIC CABLE, 24 - FIBER, Material 18 SINGLE MODE, 6 MULTIMODE	Material		16	May 4, 2020	SYSTEM	(\$1,391.25)	
		- Total				(\$1,391.25)		
	Material - Total						(\$1,391.25)	
	FIBER OPTIC CABLE, 24 - FIBER, 18 SINGLE MODE, 6 MULTIMODE	MaterialCredit		17	May 15, 2020	SYSTEM	\$1,391.25	
			- Total				\$1,391.25	
	MaterialCredit - Total						\$1,391.25	
008 -	Total						\$0.00	
6011	TACK COAT	Material		25	Sep 16, 2020	SYSTEM	(\$3,865.68)	
				25	Sep 16, 2020	SYSTEM	\$3,865.68	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user clowez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5011 -	Total						\$0.00	
5012	PRECAST CONCRETE MANHOLE - 60 IN.	Material		25	Sep 16, 2020	SYSTEM	(\$5,923.20)	
				25	Sep 16, 2020	SYSTEM	\$5,923.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user clowez1 overridding Payment Estimate Exception 38 on the current Paymen Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5012		Material	- Total				\$0.00	
	Material - Total						\$0.00	
5012 -	Total					\$0.00		
Overa	III - Total					(\$38,284.69)		