

# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 4, 2020

Progress Estimate Number	Contract ID	190621-F03	Pay Period Start	April 16, 2020	Original Contract Amount	<b>t</b> \$1,505,662.70
8	Prime Contractor	L.F. Krupp Construction, Inc. dba Krupp	Pay Period End	<b>l</b> May 1, 2020	Net Change Order Amount Current Contract Amount	\$3,028.95 : \$1,508,691.65

Approval Date		By User
May 5, 2020	Generated and Approved (and should be considered Draft) at the Project Office Level by	fernam1
May 5, 2020	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	morgac1
May 6, 2020	Reviewed and Approved at the Central Office Controllers Office Level by	greggd1

Original Completion Date	<b>Current Completion Date</b>	Actual Completion Date	% of Current Contract Amount Complete
June 1, 2020	June 1, 2020		78.36%

No Milestones Exist for Contract

Contract Total Pa	ay For Estimate No. 8				
		This Estimate	Previous	To Date	
190621-F03					
	Total Posted Items Pay	\$981,891.42	\$200,286.46	\$1,182,177.88	
	Gross Item Adjustments	(\$49,805.45)	\$0.00	(\$49,805.45)	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$200,286.46	\$1,132,372.43	
<b>Contract Total Pa</b>	ayable This Estimate:	\$932,085.97			

# Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3276	0070	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	TONS	\$71.150	4,521.9	\$321,733.19
	0800	4030107	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125CLP MIX)	TONS	\$68.200	5,880.9	\$401,077.38
	0090	4071005	TACK COAT	GAL	\$4.000	9,465	\$37,860.00
	0170	6169901	MISC.TRAFFIC CONTROL	LS	\$10,290.000	0.25	\$2,572.50
	0191	6181000	MOBILIZATION	LS	\$52,158.000	0.25	\$13,039.50
	0280	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$2.050	100,297	\$205,608.85
Project J6	S3276 - To	tal					\$981,891.42
Overall - T	otal						\$981,891.42

# Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

	,	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3276	0070	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Overrun			-407.9	\$71.15	(\$29,022.09)
	0070	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	Asphalt Cement Price Adjustment	Mix ID: BP-1 18-29 4521.9 Tons placed during Estimate 0008.			(\$8,139.42)
	0800	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125CLP MIX)	Other Item Adjustment	Asphalt Cement Price Adjustment	Mix ID: SP125 CLP 20-24 5880.9 Tons placed during Estimate 0008.			(\$12,643.94)
	0090	TACK COAT	Material			-9,465	\$4.00	(\$37,860.00)
	0090	TACK COAT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	9,465	\$4.00	\$37,860.00

Revision 4/1/2020 Page 1 of 9



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 4, 2020

Pay Period Start April 16, **Progress Estimate Contract ID** 190621-F03 Original Contract Amount \$1,505,662.70 2020 Number Pay Period End May 1, 2020 Net Change Order Prime L.F. Krupp Construction, Inc. dba 8 \$3,028.95 Amount \$3,028.95 Current Contract Amount \$1,508,691.65 Contractor Krupp

							***************************************	.,,
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3276	0100	CONCRETE PAVEMENT ( 9 IN. NON-REINF)	Material			-123.2	\$83.75	(\$10,318.00)
	0100	CONCRETE PAVEMENT ( 9 IN. NON-REINF)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	123.2	\$83.75	\$10,318.00
	0110	CONCRETE SIDEWALK, 4 IN.	Material			-4	\$75.00	(\$300.00)
	0110	CONCRETE SIDEWALK, 4 IN.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	4	\$75.00	\$300.00
	0120	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material			-101	\$22.00	(\$2,222.00)
	0120	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user fernam1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	101	\$22.00	\$2,222.00
Total								(\$49,805.45)

Revision 4/1/2020 Page 2 of 9



Incentive Disincentive Liquidated Damages Other Contract Adjustments

# Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information										
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work					
J6S3276	J6S3276 I Resurface BL 44 ST from LOUIS				from Neosho Street to E/O	Six Flags Road					
Γotals by J	Job Number	rs									
J6S3276		l Item Pay Item Adjustmo		Item Pay	This Estimate \$981,891.42 (\$49,805.45) \$932,085.97	Previous \$200,286.46 \$0.00 \$200,286.46	<b>To Date</b> \$1,182,177.88 (\$49,805.45) <b>\$1,132,372.43</b>				

\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00

\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020	Page 3 of 9
	Page 3 of 9



# Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

# **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3276, Item 4071005, Project Item Line Number 0090, Material Set 407100596, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3276, Item 4071005, Project Item Line Number 0090, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3276, Item 5021109, Project Item Line Number 0100, Material Set 502110996, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3276, Item 5021109, Project Item Line Number 0100, Material Set 502110996, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3276, Item 6086004, Project Item Line Number 0110, Material Set 608600496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3276, Item 6086004, Project Item Line Number 0110, Material Set 608600496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3276, Item 6086004, Project Item Line Number 0110, Material Set 608600496, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3276, Item 6092011, Project Item Line Number 0120, Material Set 609201196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3276, Item 6092011, Project Item Line Number 0120, Material Set 609201196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3276, Item 6092011, Project Item Line Number 0120, Material Set 609201196, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with Materials to resolve.	fernam1	Overridden
Estimate Exception Type: Item Overrun: Contract 190621-F03, Contract Project J6S3276, Project Item Line Number 0070, Contract Line Item Number 0070, Item 4011209, Minor Item.	Waiting on Change Order.	fernam1	Acknowledged

Revision 4/1/2020 Page 4 of 9



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190621-F03	J6S3276	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	0.00	\$1.00	\$0.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$12,137.00	\$12,137.00
		0001	0030	2063500	CULVERT CLEANOUT	11.00	0.00	11.00	EA	11.00	\$1,230.00	\$13,530.00
		0001	0040	2071000	LINEAR GRADING CLASS 1	5.00	3.20	8.20	STA	8.20	\$1,052.00	\$8,626.40
		0001	0050	2072000	LINEAR GRADING CLASS 2	0.30	0.00	0.30	STA	0.00	\$1,200.00	\$0.00
		0001	0060	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	4.00	0.00	4.00	SQYD	0.00	\$25.00	\$0.00
		0001	0070	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	4,114.00	0.00	4,114.00	TONS	4,521.90	\$71.15	\$292,711.10
		0001	0800	4030107	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125CLP MIX)	8,459.00	0.00	8,459.00	TONS	8,475.10	\$68.20	\$576,903.80
		0001	0090	4071005	TACK COAT	19,922.00	0.00	19,922.00	GAL	12,289.00	\$4.00	\$49,156.00
		0001	0100	5021109	CONCRETE PAVEMENT ( 9 IN. NON-REINF)	137.00	0.00	137.00	SQYD	123.20	\$83.75	\$10,318.00
		0001	0110	6086004	CONCRETE SIDEWALK, 4 IN.	4.00	0.00	4.00	SQYD	4.00	\$75.00	\$300.00
		0001	0120	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	116.00	0.00	116.00	LF	101.00	\$22.00	\$2,222.00
		0001	0130	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	149.00	145.30	294.30	CUYD	294.30	\$27.35	\$8,049.10
		0001	0140	6096041	PLACING TYPE 1 ROCK DITCH LINER	149.00	145.30	294.30	CUYD	294.30	\$26.15	\$7,695.94
		0001	0150	6133018	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	24.20	0.00	24.20	TONS	0.00	\$280.00	\$0.00
		0001	0160	6133019	REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	112.00	0.00	112.00	SQYD	0.00	\$40.00	\$0.00
		0001	0170	6169901	MISC.TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.75	\$10,290.00	\$7,717.50
		0001	0180	6169902	MISC.NTCIP CHANGEABLE MESSAGE SIGN	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00
		0001	0190	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$65,000.00	\$0.00
		0001	0191	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.75	\$52,158.00	\$39,118.50
		0001	0200	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	108.00	0.00	108.00	LF	0.00	\$20.00	\$0.00
		0001	0210	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	20.00	0.00	20.00	EA	0.00	\$400.00	\$0.00
		0001	0220	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$0.00
		0001	0230	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	8.00	0.00	8.00	EA	0.00	\$180.00	\$0.00
		0001	0240	6200051	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT FISH HOOK ARROW	2.00	0.00	2.00	EA	0.00	\$550.00	\$0.00
		0001	0250	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	48,312.00	0.00	48,312.00	LF	0.00	\$0.15	\$0.00
		0001	0260	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	35,737.00	0.00	35,737.00	LF	0.00	\$0.15	\$0.00
		0001	0270	6207001	PAVEMENT MARKING REMOVAL	2,269.00	0.00	2,269.00	LF	0.00	\$0.75	\$0.00
		0001	0280	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	131,669.00	0.00	131,669.00	SQYD	128,378.50	\$2.05	\$263,175.92
		0001	0290	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	344.00	0.00	344.00	STA	0.00	\$11.00	\$0.00
		0001	0300	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	172.00	0.00	172.00	STA	0.00	\$30.00	\$0.00
		0001	0310	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$1.00	\$0.00
		0001	0320	8061016	SEDIMENT REMOVAL	167.00	0.00	167.00	CUYD	167.00	\$1.00	\$167.00
		0001	0330	8069901	MISC.TEMPORARY SEEDING AND MULCHING	1.00	-1.00	0.00	LS	0.00	\$5,500.00	\$0.00
		0001	0340	9028500	CABLE, LOOP DETECTOR, IN DUCT	800.00	0.00	800.00	LF	0.00	\$8.50	\$0.00
		0010	0350	6061060	MGS GUARDRAIL	1,488.00	74.50	1,562.50	LF	1,562.50	\$22.00	\$34,375.00
		0010	0360	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$3,050.00	\$12,200.00
		0010	0370	6061080	MGS END ANCHOR	1.00	-1.00	0.00	EA	0.00	\$1,200.00	\$0.00
		0010	0380	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	15.00	-1.00	14.00	EA	14.00	\$2,900.00	\$40,600.00
		0040	0390	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	3.00	-3.00	0.00	LF	0.00	\$50.00	\$0.00
		0001	5001	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$12,842.00	\$12,842.00
	Project J	6S3276 - To	tal Value	Posted to D	Date as of Report Generated Date							\$1,397,845.28
190621-F03 Ove	rall - Total	Value Post	ed to Dat	e as of Repo	ort Generated Date							\$1,397,845.28

Revision 4/1/2020 Page 5 of 9



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6S3276

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0070	4011209	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	4/16/20	5/4/20	1,092.10	TONS	EB Right Shoulders	1052+38		1151+20		
			4/17/20	5/4/20	1,524.60	TONS	EB/WB Right Shoulders	1151+20	RC	1182+50	LC	
			4/18/20	5/4/20	1,609.10	TONS	EB Right Shoulders	1182+50	LC	1004+69	LC	
			4/21/20	5/4/20	296.10	TONS	EB & WB Entrances	1011+50	RC	1153+15	LC	
0800	4030107	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP1	4/27/20	5/4/20	1,307.70	TONS	EB & WB Lane 2, and Center Lane into Pacific	1037+40	RC	1004+69	CL	
			4/29/20	5/4/20	1,249.70	TONS	WB Lane 1	1004+69	LC	1090+70	LC	
			4/30/20	5/4/20	1,835.90	TONS	WB Lane 1, EB Lane 4	1090+70	LC	1227+27	RC	
			5/1/20	5/4/20	1,487.60	TONS	All Lanes East of Commuter Lot minus EB Lane 4	1204+53	LC	1240+69	CL	
0090	4071005	TACK COAT	4/16/20	5/4/20	1,120.00	GAL	EB Right Shoulders	1052+38		1151+20		
			4/17/20	5/4/20	1,042.00	GAL	EB/WB Right Shoulders	1151+20	RC	1182+50	LC	
			4/18/20	5/4/20	1,509.00	GAL	EB Right Shoulders	1182+50	LC	1004+69	LC	
			4/21/20	5/4/20	341.00	GAL	EB & WB Entrances	1011+50	RC	1153+15	RC	
			4/27/20	5/4/20	1,315.00	GAL	EB & WB Lane 2, and Center Lane into Pacific	1037+40	RC	1004+69	CL	
			4/29/20	5/4/20	1,071.00	GAL	WB Lane 1	1004+69	LC	1090+70	LC	
			4/30/20	5/4/20	1,655.00	GAL	WB Lane 1, EB Lane 4	1090+70	LC	1227+27	RC	
			5/1/20	5/4/20	1,412.00	GAL	All Lanes East of Commuter Lot minus EB Lane 4	1204+53	LC	1240+93	CL	
0170	6169901	MISC.	5/1/20	5/4/20	0.25	LS	EB/WB BL 44	1004+69	CL	1240+93	CL	
0191	6181000	MOBILIZATION	5/1/20	5/4/20	0.25	LS	BL 44	1004+69	CL	1240+93	CL	
0280	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	4/16/20	5/4/20	269.40	SQYD	Entrance at Railroad Crossing	1112+40		1113+37		
				5/4/20	15,676.90	SQYD	EB Right Shoulders	1052+38		1205+43		
			4/17/20	5/4/20	2,504.00	SQYD	EB/WB Entrances	1215+30	RC	1144+50	LC	
				5/4/20	11,180.20	SQYD	EB/WB Right Shoulders	1225+00	RC	1143+62	LC	
			4/18/20	5/4/20	1,523.80	SQYD	EB/WB Entrances	1134+40	LC	1004+69	LC	
				5/4/20	9,407.30	SQYD	EB/WB Right Shoulders	1141+78	LC	1004+69	LC	
			4/27/20	5/4/20	13,835.90	SQYD	EB & WB Lane 2, and Center Lane into Pacific	1037+40	RC	1004+69	CL	
			4/29/20	5/4/20	13,342.30	SQYD	WB Lane 1	1004+69	LC	1090+70	LC	
			4/30/20	5/4/20	18,456.90	SQYD	WB Lane 1, EB Lane 4	1090+70	LC	1230+31	RC	
			5/1/20	5/4/20	14,100.30	SQYD	All Lanes East of Commuter Lot minus EB Lane 4	1204+53	LC	1240+93	CL	

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 6 of 9



# Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

			0.11					
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0070	BIT. PAVEMENT MIXTURE PG64-22	Other Item Adjustment	ACAD	8	May 4, 2020	fernam1	(\$8,139.42)	Mix ID: BP-1 18-29 4521.9 Tons placed during Estimate 0008.
	(BP-1)		ACAD - Total				(\$8,139.42)	
		Other Item Ad	Other Item Adjustment - Total				(\$8,139.42)	
		Overrun	Overrun	8	May 4, 2020	SYSTEM	(\$29,022.09)	
			Overrun - T	otal			(\$29,022.09)	
		Overrun - Total					(\$29,022.09)	
0070 -	· Total						(\$37,161.51)	
0800	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP1	Other Item Adjustment	ACAD	8	May 4, 2020	fernam1	(\$12,643.94)	Mix ID: SP125 CLP 20-24 5880.9 Tons placed during Estimate 0008.
			ACAD - Total				(\$12,643.94)	
		Other Item Adjustment - Total					(\$12,643.94)	
0080 -	· Total					(\$12,643.94)		
0090	TACK COAT	Material		8	May 4, 2020	SYSTEM	(\$37,860.00)	
				8	May 4, 2020	SYSTEM	\$37,860.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
		Material - Tota					\$0.00	
0090 -	· Total						\$0.00	
0100		Material		3	Feb 18, 2020	SYSTEM	(\$10,318.00)	
				4	Mar 2, 2020	SYSTEM	(\$10,318.00)	
				5	Mar 17, 2020	SYSTEM	(\$10,318.00)	
				6	Apr 2, 2020	SYSTEM	(\$10,318.00)	
				6	Apr 2, 2020	SYSTEM	\$10,318.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				7	Apr 16, 2020	SYSTEM	(\$10,318.00)	
				7	Apr 16, 2020	SYSTEM	\$10,318.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user fernam1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				8	May 4, 2020	SYSTEM	(\$10,318.00)	
				8	May 4, 2020	SYSTEM	\$10,318.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				(\$30,954.00)	
		Material - Tota	ıl				(\$30,954.00)	
		MaterialCredit	alCredit	4	Mar 2, 2020	SYSTEM	\$10,318.00	
				5	Mar 17, 2020	SYSTEM	\$10,318.00	
				6	Apr 2, 2020	SYSTEM	\$10,318.00	
			- Total				\$30,954.00	
		MaterialCredit	- Total				\$30,954.00	
		Other Item Adjustment	MDPA	3	Feb 18, 2020	fernam1	\$10,318.00	
				6	Apr 2, 2020	fernam1	(\$10,318.00)	Using Override function to zero out Material Discrepancy Adjustments
			MDPA - Total				\$0.00	
		Other Item Adjustment - Total					\$0.00	
0100 -	· Total						\$0.00	
0110	CONCRETE	Material		4	Mar 2,	SYSTEM	(\$300.00)	

Revision 4/1/2020 Page 7 of 9



# Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0110	SIDEWALK, 4 IN.	Material	Туре		2020			
		waterial		5	Mar 17, 2020	SYSTEM	(\$300.00)	
				6	Apr 2, 2020	SYSTEM	(\$300.00)	
				6	Apr 2, 2020	SYSTEM	\$300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user fernam1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				7	Apr 16, 2020	SYSTEM	(\$300.00)	
				7	Apr 16, 2020	SYSTEM	\$300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				8	May 4, 2020	SYSTEM	(\$300.00)	
				8	May 4, 2020	SYSTEM	\$300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				(\$600.00)	
		Material - Tota	ıl				(\$600.00)	
		MaterialCredit		5	Mar 17, 2020	SYSTEM	\$300.00	
				6	Apr 2, 2020	SYSTEM	\$300.00	
			- Total				\$600.00	
		MaterialCredit	- Total				\$600.00	
		Other Item Adjustment	MDPA	4	Mar 2, 2020	fernam1	\$300.00	
				6	Apr 2, 2020	fernam1	(\$300.00)	Using Override function to zero out Material Discrepancy Adjustments
		MDPA - Total					\$0.00	
0110	Total	Other Item Ad					\$0.00	
<b>0110</b> · 0120	- Total  INTEGRAL CURB (6	Other Item Ad			Feb 18,	SYSTEM		
				tal	Feb 18, 2020 Mar 2, 2020	SYSTEM SYSTEM	\$0.00 \$0.00	
	INTEGRAL CURB (6 IN. HEIGHT AND			atal 3	2020 Mar 2, 2020 Mar 17,		\$0.00 \$0.00 (\$990.00)	
	INTEGRAL CURB (6 IN. HEIGHT AND			3 4	2020 Mar 2, 2020	SYSTEM	\$0.00 \$0.00 (\$990.00) (\$2,222.00)	
	INTEGRAL CURB (6 IN. HEIGHT AND			3 4 5	2020 Mar 2, 2020 Mar 17, 2020 Apr 2,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$990.00) (\$2,222.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	INTEGRAL CURB (6 IN. HEIGHT AND			3 4 5	2020 Mar 2, 2020 Mar 17, 2020 Apr 2, 2020 Apr 2,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$990.00) (\$2,222.00) (\$2,222.00) (\$2,222.00)	Adjustment (0007) due to user fernam1 overridding Payment Estimate Exception 5 on
	INTEGRAL CURB (6 IN. HEIGHT AND			3 4 5 6 6 6	2020 Mar 2, 2020 Mar 17, 2020 Apr 2, 2020 Apr 2, 2020 Apr 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$990.00) (\$2,222.00) (\$2,222.00) (\$2,222.00)	Adjustment (0007) due to user fernam1 overridding Payment Estimate Exception 5 on
	INTEGRAL CURB (6 IN. HEIGHT AND			3 4 5 6 6 7 7	2020 Mar 2, 2020 Mar 17, 2020 Apr 2, 2020 Apr 2, 2020 Apr 16, 2020 Apr 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$990.00) (\$2,222.00) (\$2,222.00) (\$2,222.00) (\$2,222.00)	Adjustment (0007) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 6 on
	INTEGRAL CURB (6 IN. HEIGHT AND			3 4 5 6 6 7 7	2020 Mar 2, 2020 Mar 17, 2020 Apr 2, 2020 Apr 2, 2020 Apr 16, 2020 Apr 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$990.00) (\$2,222.00) (\$2,222.00) \$2,222.00 (\$2,222.00) \$2,222.00	Adjustment (0007) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 6 on
	INTEGRAL CURB (6 IN. HEIGHT AND			3 4 5 6 6 7 7 8 8	2020 Mar 2, 2020 Mar 17, 2020 Apr 2, 2020 Apr 2, 2020 Apr 16, 2020 May 4, 2020 May 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$990.00) (\$2,222.00) (\$2,222.00) \$2,222.00 (\$2,222.00) \$2,222.00 (\$2,222.00)	Adjustment (0007) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user fernam1 overridding Payment Estimate Exception 8 on
	INTEGRAL CURB (6 IN. HEIGHT AND		justment - To	3 4 5 6 6 7 7 8 8	2020 Mar 2, 2020 Mar 17, 2020 Apr 2, 2020 Apr 2, 2020 Apr 16, 2020 May 4, 2020 May 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$990.00) (\$2,222.00) (\$2,222.00) \$2,222.00 (\$2,222.00) \$2,222.00 (\$2,222.00)	Adjustment (0007) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user fernam1 overridding Payment Estimate Exception 8 on
	INTEGRAL CURB (6 IN. HEIGHT AND	Material	justment - To	3 4 5 6 6 7 7 8 8	2020 Mar 2, 2020 Mar 17, 2020 Apr 2, 2020 Apr 2, 2020 Apr 16, 2020 May 4, 2020 May 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$990.00) (\$2,222.00) (\$2,222.00) (\$2,222.00) \$2,222.00 (\$2,222.00) \$2,222.00 (\$2,222.00)	Adjustment (0007) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user fernam1 overridding Payment Estimate Exception 8 on
	INTEGRAL CURB (6 IN. HEIGHT AND	Material  Material - Tota	justment - To	3 4 5 6 7 7 8 8	2020 Mar 2, 2020 Mar 17, 2020 Apr 2, 2020 Apr 2, 2020 Apr 16, 2020 Apr 16, 2020 May 4, 2020 May 4, 2020 May 4, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$990.00) (\$2,222.00) (\$2,222.00) (\$2,222.00) \$2,222.00 (\$2,222.00) \$2,222.00 (\$2,222.00) (\$2,222.00) (\$2,222.00)	Adjustment (0007) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user fernam1 overridding Payment Estimate Exception 8 on
	INTEGRAL CURB (6 IN. HEIGHT AND	Material  Material - Tota	justment - To	3 4 5 6 6 7 7 8 8 8	2020 Mar 2, 2020 Mar 17, 2020 Apr 2, 2020 Apr 16, 2020 Apr 16, 2020 May 4, 2020 May 4, 2020 May 7, 2020 May 7, 2020 May 17, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$990.00) (\$2,222.00) (\$2,222.00) (\$2,222.00) \$2,222.00 (\$2,222.00) \$2,222.00 (\$2,222.00) \$2,222.00 (\$2,222.00)	Adjustment (0007) due to user fernam1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user fernam1 overridding Payment Estimate Exception 8 on

Revision 4/1/2020 Page 8 of 9



# Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0120	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	MaterialCredit	- Total				\$5,434.00	
		Other Item Adjustment	MDPA	3	Feb 18, 2020	fernam1	\$990.00	
				4	Mar 2, 2020	fernam1	\$1,232.00	
				6	Apr 2, 2020	fernam1	(\$2,222.00)	Using Override function to zero out Material Discrepancy Adjustments
			MDPA - Total				\$0.00	
		Other Item Adjustment - Total					\$0.00	
0120 -	1120 - Total						\$0.00	
0130	FURNISHING TYPE 1 ROCK DITCH LINER	Material		3	Feb 18, 2020	SYSTEM	(\$3,850.88)	
				4	Mar 2, 2020	SYSTEM	(\$8,049.10)	
			- Total				(\$11,899.98)	
		Material - Total					(\$11,899.98)	
		MaterialCredit		4	Mar 2, 2020	SYSTEM	\$3,850.88	
				5	Mar 17, 2020	SYSTEM	\$8,049.10	
			- Total				\$11,899.98	
		MaterialCredit - Total					\$11,899.98	
		Other Item Adjustment	MDPA	3	Feb 18, 2020	fernam1	\$3,850.88	
				4	Mar 2, 2020	fernam1	\$4,198.22	
				5	Mar 17, 2020	fernam1	(\$8,049.10)	Material Discrepancy Adjustment Correction from Estimate 004
			MDPA - Total				\$0.00	
		Other Item Adj	justment - To	tal			\$0.00	
0130 -	Total					\$0.00		
0350	MGS GUARDRAIL	Overrun	Overrun	4	Mar 2, 2020	SYSTEM	(\$1,639.00)	
				6	Apr 2, 2020	SYSTEM	\$1,639.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',22.00000 - 22.00000, 'is applied (if non-zero).
			Overrun - T	rrun - Total			\$0.00	
		Overrun - Tota	d				\$0.00	
0350 - Total							\$0.00	
Overall - Total							(\$49,805.45)	

Revision 4/1/2020 Page 9 of 9