

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 16, 2020

Progress Estin	Prime Contract		: :- -		June 2, 2020 June 15, 2020	Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,754,744.10 (\$32,961.50) \$1,721,782.60		
Approval Date							By User		
June 16, 2020		G	enerated and Appro	ved (and should be o	onsidered Draft	at the Project Office Level by	dwighj1		
June 16, 2020		Revie	wed and Approved (and should be consid	dered Draft) at th	e Resident Engineer Level by	lincom		
June 16, 2020			Revie	wed and Approved a	t the Central Off	ice Controllers Office Level by	greggd1		
Original Comp	letion Date	Current Comple	etion Date	Actual Completion	I Completion Date % of Current Contract Amo				
September	1, 2020	September 1	, 2020			39.97%			

No Milestones Exist for Contract

Contract Total Pay	For Estimate No. 6				
		This Estimate	Previous	To Date	
190816-B02					
	Total Posted Items Pay	\$62,920.88	\$625,338.97	\$688,259.85	
	Gross Item Adjustments	(\$651.92)	(\$9,735.40)	(\$10,387.32)	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$615,603.57	\$677,872.53	
Contract Total Pay	able This Estimate:	\$62,268.96			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount				
J2P3182	0030	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	TONS	\$240.000	90	\$21,600.00				
	0040	4071005	TACK COAT	GAL	\$6.000	60	\$360.00				
	0200	6181000	MOBILIZATION	LS	\$134,000.000	0.25	\$33,500.00				
	0260	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$14.000	82.92	\$1,160.88				
	5001	6069902	MISC.REINSTALLATION OF EXISTING BRIDGE APPROACH TRANSITION SECTION	EA	\$2,100.000	3	\$6,300.00				
Project J2P3182 - Total											
Overall - Total											

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		stments Exist on Contract						
Line Item	<u>Adjust</u>	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J2P3182	0030	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	90	(\$3.25)	(\$292.82)
	0030	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	Asphalt Cement Price Adjustment	This Line Item Adjustment is for the AC Price Adjustment for asphalt that was placed on June 15, 2020. There were a total of 90 tons placed on that day, with a virgin asphalt content of 3.8%, with a mix ID of SP125 20-41.			(\$359.10)
	0350	CURB BLOCKOUT	Material			-257	\$100.00	(\$25,700.00)
	0350	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	257	\$100.00	\$25,700.00
	0470	CURB BLOCKOUT	Material			-514	\$100.00	(\$51,400.00)
	0470	CURB BLOCKOUT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item	514	\$100.00	\$51,400.00

Revision 4/1/2020 Page 1 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 16, 2020

Progi	ress Es	stimate Number 6	Contract I		0816-B02 Ilips Hardy, Inc	. Pay Period End June 15, 2020 Net	Change Order A	Il Contract Amount \$1,754,744 ange Order Amount (\$32,961.50 t Contract Amount \$1,721,782			
Project Number	Line No.	Item Descr	iption	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount		
J2P3182						Adjustment (0004) due to user dwig overridding Payment Estimate Exception the current Payment Estim	1 on				
	0540	MONOLITHIC DE	CK REPAIR	Overrun		Averaged Price Adjustment from this iten all previous payment estimates of '0.0000 applied (if non-ze	0' is	\$700.00	(\$16,786.00		
	0540	MONOLITHIC DE	CK REPAIR	Other Item Adjustment	Other	This Line Item Adjustment is to put back amount deducted by the system on this number on estimate 0006. The system m an overrun adjustment automatically \$16,786.00, and nothing was paid out on line number on this estimate. Change O 0002 will correct the quantity to resolve discrepancy, but the system is trying to de the overrun amount again on this estim	line lade of - this rder this duct		\$16,786.00		
Total									(\$651.92		

Revision 4/1/2020 Page 2 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information						
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work						
J2P3182	FAF 61-4(177)	2 Bridge rehabilitations	61	1 MARION over Rte. 24 outer road 1.5 miles north of Rte. 6 near Taylor							
J2P3342	FAF-61-4(180)	Bridge rehabilitation	24	MARION	on ramp over Rte. 24 1.6 miles north of Rte. 6 at Taylor interchange						

2P3182	This Estimate	Previous	To Date
Posted Item Pay	\$62,920.88	\$625,338.97	\$688,259.85
Gross Item Adjustments	(\$651.92)	(\$41,833.61)	(\$42,485.53)
Gross Item Pay	\$62,268.96	\$583,505.36	\$645,774.32
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
2P3342 -	This Estimate	Previous	To Date
Posted Item Pay	\$0.00	\$0.00	\$0.00
Gross Item Adjustments	\$0.00	\$32,098.21	\$32,098.21
Gross Item Pay	\$0.00	\$32,098.21	\$32,098.21
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00

Revision 4/1/2020 Page 3 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J2P3182, Item 7034600, Project Item Line Number 0470, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	There is a material code on this line item setup for Silane concrete sealer, which has not been applied to the curb blockout areas yet. Once the material is delivered to the project for use the cert will be supplied and a report entered, which will eliminate this discrepancy.	dwighj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J2P3182, Item 7034600, Project Item Line Number 0350, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	There is a material code on this line item setup for Silane concrete sealer, which has not been applied to the curb blockout areas yet. Once the material is delivered to the project for use the cert will be supplied and a report entered, which will eliminate this discrepancy.	dwighj1	Overridden
Estimate Exception Type: Item Overrun: Contract 190816-B02, Contract Project J2P3182, Project Item Line Number 0450, Contract Line Item Number 0450, Item 2169904, Minor Item.	No Remark was entered by Engineer	dwighj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 190816-B02, Contract Project J2P3182, Project Item Line Number 0540, Contract Line Item Number 0540, Item 7040117, Minor Item.	No Remark was entered by Engineer	dwighj1	Acknowledged

Revision 4/1/2020 Page 4 of 12



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q Contract	uantities Project	and Value Category	es are b	ltem	eport Generated date and can differ from the posted amo Description	ount at the	time the	Estimate w Total	as Gene Unit	rated. Total	Unit Price	Total Value POSTED
Nm.CONTRACT	No.	,	No.	Code	·	Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See report generated date)
190816-B02	J2P3182	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.30	\$18,100.00	\$5,430.00
		0001	0020	2153000	SHAPING SLOPES, CLASS III	7.00	0.00	7.00	100F	0.00	\$1,100.00	\$0.00
		0001	0030	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	134.30	0.00	134.30	TONS	120.27	\$240.00	\$28,864.80
		0001	0040	4071005	TACK COAT	144.00	0.00	144.00	GAL	89.00	\$6.00	\$534.00
		0001	0050	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARRELS)	2.00	0.00	2.00	EA	2.00	\$3,400.00	\$6,800.00
		0001	0060	6122020	REPLACEMENT SAND BARREL	4.00	0.00	4.00	EA	0.00	\$200.00	\$0.00
		0001	0070	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$0.00
		0001	0080	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	1.00	\$1.00	\$1.00
		0001	0090	6161005	CONSTRUCTION SIGNS	1,523.00	0.00	1,523.00	SQFT	832.00	\$8.00	\$6,656.00
		0001	0100	6161008	ADVANCED WARNING RAIL SYSTEM	20.00	0.00	20.00	EA	16.00	\$35.00	\$560.00
		0001	0110	6161009	FLAG ASSEMBLY	10.00	0.00	10.00	EA	6.00	\$20.00	\$120.00
		0001	0120	6161025	CHANNELIZER (TRIM LINE)	150.00	0.00	150.00	EA	93.00	\$20.00	\$1,860.00
		0001	0130	6161030	TYPE III MOVEABLE BARRICADE	15.00	0.00	15.00	EA	3.00	\$100.00	\$300.00
		0001	0140	6161033	DIRECTIONAL INDICATOR BARRICADE	54.00	0.00	54.00	EA	42.00	\$55.00	\$2,310.00
		0001	0150	6161040	FLASHING ARROW PANEL	3.00	0.00	3.00	EA	3.00	\$850.00	\$2,550.00
		0001	0160	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	3.00	0.00	3.00	EA	3.00	\$2,800.00	\$8,400.00
		0001	0170	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	6.00	0.00	6.00	EA	4.00	\$1,000.00	\$4,000.00
		0001	0180	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	976.00	48.00	1,024.00	LF	976.00	\$26.00	\$25,376.00
		0001	0190	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	976.00	48.00	1,024.00	LF	512.00	\$11.00	\$5,632.00
		0001	0200	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$134,000.00	\$134,000.00
		0001	0210	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,024.00	0.00	1,024.00	LF	0.00	\$1.00	\$0.00
		0001	0220	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	823.00	0.00	823.00	LF	0.00	\$1.00	\$0.00
		0001	0230	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	845.00	0.00	845.00	LF	0.00	\$2.25	\$0.00
		0001	0240	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	165.00	0.00	165.00	LF	0.00	\$8.00	\$0.00
		0001	0250	6207001	PAVEMENT MARKING REMOVAL	245.00	0.00	245.00	LF	0.00	\$5.00	\$0.00
		0001	0260	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,434.00	0.00	1,434.00	SQYD	1,035.83	\$14.00	\$14,501.62
		0001	0270	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	3.00	0.00	3.00	STA	0.00	\$1,000.00	\$0.00
		0001	0280	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$3,000.00	\$3,000.00
		0010	0290	6061060	MGS GUARDRAIL	463.00	-463.00	0.00	LF	0.00	\$42.50	\$0.00
		0010	0300	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	-4.00	0.00	EA	0.00	\$3,940.00	\$0.00
		0010	0310	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	-2.00	0.00	EA	0.00	\$3,850.00	\$0.00
		0070	0320	2161501	REMOVAL OF ASPHALT WEARING SURFACE	11,356.00	0.00	11,356.00	SQFT	5,678.00	\$2.50	\$14,195.00
		0070	0330	2169904	MISC.RUBBLIZE EXISTING DECK REPAIR	500.00	0.00	500.00	SQFT	185.98	\$41.00	\$7,625.18
		0070	0340	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,262.00	0.00	1,262.00	SQYD	0.00	\$94.00	\$0.00
		0070	0350	7034600	CURB BLOCKOUT	514.00	0.00	514.00	LF	257.00	\$100.00	\$25,700.00
		0070	0360	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	25.00	0.00	25.00	SQFT	0.00	\$145.00	\$0.00
		0070	0370	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	150.00	0.00	150.00	SQFT	0.00	\$55.00	\$0.00
		0070	0380	7040106	FULL DEPTH REPAIR	25.00	0.00	25.00	SQFT	0.00	\$130.00	\$0.00
		0070	0390	7040107	SLAB EDGE REPAIR (BRIDGES)	100.00	0.00	100.00	LF	0.00	\$150.00	\$0.00
		0070	0400	7040109	TOTAL SURFACE HYDRO DEMOLITION	1,262.00	0.00	1,262.00	SQYD	631.00	\$48.50	\$30,603.50
		0070	0410	7040113	CLEAN AND EPOXY SEAL	358.00	0.00	358.00	SQFT	0.00	\$10.00	\$0.00
		0070	0420	7040117	MONOLITHIC DECK REPAIR	11.00	0.00	11.00	CUYD	0.00	\$700.00	\$0.00
		0070	0430	7129902	MISC.CORED SLAB DRAINS	22.00	0.00	22.00	EA	0.00	\$605.00	\$0.00
		0071	0440	2161501	REMOVAL OF ASPHALT WEARING SURFACE	11,356.00	0.00	11,356.00	SQFT	11,356.00	\$2.50	\$28,390.00
Revision 4/1/203	20											Page 5 of 12

Page 5 of 12 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted amo	ount at the	time the	Estimate w	as Gene	erated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190816-B02	J2P3182	0071	0450	2169904	MISC.RUBBLIZE EXISTING DECK REPAIR	500.00	0.00	500.00	SQFT	1,465.75	\$41.00	\$60,095.75
		0071	0460	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,262.00	0.00	1,262.00	SQYD	1,262.00	\$94.00	\$118,628.00
		0071	0470	7034600	CURB BLOCKOUT	514.00	0.00	514.00	LF	514.00	\$100.00	\$51,400.00
		0071	0480	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	25.00	0.00	25.00	SQFT	0.00	\$145.00	\$0.00
		0071	0490	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	150.00	0.00	150.00	SQFT	0.00	\$55.00	\$0.00
		0071	0500	7040106	FULL DEPTH REPAIR	25.00	0.00	25.00	SQFT	0.00	\$130.00	\$0.00
		0071	0510	7040107	SLAB EDGE REPAIR (BRIDGES)	100.00	0.00	100.00	LF	0.00	\$150.00	\$0.00
		0071	0520	7040109	TOTAL SURFACE HYDRO DEMOLITION	1,262.00	0.00	1,262.00	SQYD	1,262.00	\$48.50	\$61,207.00
		0071	0530	7040113	CLEAN AND EPOXY SEAL	358.00	0.00	358.00	SQFT	0.00	\$10.00	\$0.00
		0071	0540	7040117	MONOLITHIC DECK REPAIR	11.00	0.00	11.00	CUYD	37.95	\$700.00	\$26,565.00
		0071	0550	7129902	MISC.CORED SLAB DRAINS	22.00	0.00	22.00	EA	11.00	\$605.00	\$6,655.00
		0001	5001	6069902	MISC.REINSTALLATION OF EXISTING BRIDGE APPROACH TRANSITION SECTION	0.00	4.00	4.00	EA	3.00	\$2,100.00	\$6,300.00
	Project J	2P3182 - To	otal Value	Posted to D	ate as of Report Generated Date							\$688,259.85
	J2P3342	0001	0560	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$11,000.00	\$0.00
		0001	0570	2153000	SHAPING SLOPES, CLASS III	25.00	0.00	25.00	100F	0.00	\$1,015.00	\$0.00
		0001	0580	3049910	MISC.TYPE 1 AGGREGATE	13.50	0.00	13.50	TONS	0.00	\$48.50	\$0.00
		0001	0590	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	28.10	0.00	28.10	TONS	0.00	\$350.00	\$0.00
		0001	0600	4071005	TACK COAT	30.00	0.00	30.00	GAL	0.00	\$6.00	\$0.00
		0001	0610	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$84,000.00	\$0.00
		0001	0620	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	528.00	0.00	528.00	LF	0.00	\$1.00	\$0.00
		0001	0630	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	528.00	0.00	528.00	LF	0.00	\$1.00	\$0.00
		0001	0640	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	417.00	0.00	417.00	SQYD	0.00	\$25.00	\$0.00
		0001	0650	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$3,000.00	\$0.00
		0010	0660	6061060	MGS GUARDRAIL	2,063.00	0.00	2,063.00	LF	0.00	\$25.70	\$0.00
		0010	0670	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	0.00	\$2,795.00	\$0.00
		0010	0680	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	0.00	\$1,100.00	\$0.00
		0010	0690	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$2,750.00	\$0.00
		0079	0700	2161000	SCARIFICATION OF BRIDGE DECK	995.00	0.00	995.00	SQYD	0.00	\$21.50	\$0.00
		0079	0710	2163000	PARTIAL REMOVAL OF EXISTING BRIDGE DECK	145.00	0.00	145.00	SQFT	0.00	\$76.50	\$0.00
		0079	0720	2163502	PARTIAL REMOVAL OF SUBSTRUCTURE CONCRETE	1.00	0.00	1.00	LS	0.00	\$9,400.00	\$0.00
		0079	0730	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	76.00	0.00	76.00	LF	0.00	\$170.00	\$0.00
		0079	0740	2169904	MISC.REMOVE AND REPLACE BARRIER CURB	28.00	0.00	28.00	SQFT	0.00	\$1,050.00	\$0.00
		0079	0750	2169904	MISC.RUBBLIZE EXISTING DECK REPAIR	100.00	0.00	100.00	SQFT	0.00	\$41.00	\$0.00
		0079	0760	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	995.00	0.00	995.00	SQYD	0.00	\$75.00	\$0.00
		0079	0770	7031004	DIAMOND GRINDING	995.00	0.00	995.00	SQYD	0.00	\$11.00	\$0.00
		0079	0780	7034214	CLASS B-2 CONCRETE	19.90	0.00	19.90	CUYD	0.00	\$3,000.00	\$0.00
		0079	0790	7034600	CURB BLOCKOUT	758.00	0.00	758.00	LF	0.00	\$85.00	\$0.00
		0079	0800	7040101	SUBSTRUCTURE REPAIR (FORMED)	10.00	0.00	10.00	SQFT	0.00	\$205.00	\$0.00
		0079	0810	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	35.00	0.00	35.00	SQFT	0.00	\$105.00	\$0.00
		0079	0820	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	200.00	0.00	200.00	SQFT	0.00	\$65.00	\$0.00
		0079	0830	7040106	FULL DEPTH REPAIR	25.00	0.00	25.00	SQFT	0.00	\$120.00	\$0.00
	0079 0840 7040107 SLAB EDGE REPAIR (BRIDGES)						0.00	100.00	LF	0.00	\$150.00	\$0.00
		0079	0850	7040109	TOTAL SURFACE HYDRO DEMOLITION	995.00	0.00	995.00	SQYD	0.00	\$43.00	\$0.00
		0079	0860	7040113	CLEAN AND EPOXY SEAL	355.00	0.00	355.00	SQFT	0.00	\$10.00	\$0.00
		0079	0870	7040117	MONOLITHIC DECK REPAIR	9.00	0.00	9.00	CUYD	0.00	\$700.00	\$0.00

Page 6 of 12 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190816-B02	J2P3342	0079	0880	7101000	REINFORCING STEEL (EPOXY COATED)	2,670.00	0.00	2,670.00	LB	0.00	\$3.25	\$0.00
		0079	0890	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00
		0079	0900	7123130	REHABILITATE BEARING	4.00	0.00	4.00	EA	0.00	\$6,100.00	\$0.00
		0079	0910	7129902	MISC.CORED SLAB DRAIN	10.00	0.00	10.00	EA	0.00	\$710.00	\$0.00
		0079	0920	7129902	MISC.PIN AND PIN PLATE REPLACEMENT	2.00	0.00	2.00	EA	0.00	\$24,500.00	\$0.00
		0079	0930	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	76.00	0.00	76.00	LF	0.00	\$425.00	\$0.00
		0079	0940	7172054	OPEN CELL FOAM JOINT SEAL	32.00	0.00	32.00	LF	0.00	\$68.00	\$0.00
	Project J	2P3342 - To	tal Value	Posted to D	Date as of Report Generated Date							\$0.00
190816-B02 Overall - Total Value Posted to Date as of Report Generated Date									\$688,259.85			

Page 7 of 12 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J2P3182

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0030	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP1	6/15/20	6/16/20	17.10	TONS	Southbound Route 61	39.247	0' Lt of Centerline	39.261	16.8' Lt of Cntrline	Passing Lane and Shoulder, north approach, bridge A31521
				6/16/20	17.10	TONS	Southbound Route 61	39.313	0' Lt of Centerline	39.327	16.5' Lt of Cntrline	Passing Lane and Shoulder, south approach, bridge A31521
				6/16/20	26.70	TONS	Northbound Route 61	353.694	0' Rt of Centerline	353.708	30' Rt of Centerline	Driving Lane, Acceleration Lane and Shoulder, south approach, bridge A31522
				6/16/20	29.10	TONS	Northbound Route 61	353.756	0' Rt of Centerline	353.770	30' Rt of Centerline	Driving Lane, Acceleration Lane and Shoulder, north approach, bridge A31522
0040	4071005	TACK COAT	6/15/20	6/16/20	11.00	GAL	Southbound Route 61	39.247	0' Lt of Centerline	39.261	16.8' Lt of Cntrline	Passing Lane and Shoulder, north approach, A31521
				6/16/20	11.00	GAL	Southbound Route 61	39.313	0' Lt of Centerline	39.327	16.5' Lt of Cntrline	Passing Lane and Shoulder, south approach, A31521
				6/16/20	18.00	GAL	Northbound Route 61	353.694	0' Rt of Centerline	353.708	30' Rt of Centerline	Driving Lane, Acceleration Lane and Shoulder, south approach, A31522
				6/16/20	20.00	GAL	Northbound Route 61	353.756	0' Rt of Centerline	353.770	30' Rt of Centerline	Driving Lane, Acceleration Lane and Shoulder, north approach, A31522
0200	6181000	MOBILIZATION	6/10/20	6/10/20	0.25	LS	entire project	0	0	0	0	50% of contract work has been completed, which is the threshold for the fourth mobilization payment
0260	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	6/15/20	6/16/20	82.92	SQYD	Northbound Route 61	3553.694	6' Lt of Centerline	353.770	6' Rt of Centerline	Finished up both the north and south approaches of Bridge A31522, milling complete on that bridge
5001	6069902	MISC. GUARDRAIL ITEM	6/10/20	6/10/20	1.00	EA	NB Route 61, Inside Shoulder, South Approach	353.704	20' Lt of centerline	353.708	20' Lt of centerline	Reinstalled previously removed bridge anchor section an asymmetrical transition (work was actually done on May 4, 2020)
				6/10/20	1.00	EA	NB Route 61, Outside Shoulder, South approach	353.704	29' Rt of centerline	353.708	29' Rt of centerline	Reinstalled previously removed existing bridge anchor section and asymmetrical transition
				6/10/20	1.00	EA	SB Route 61, Inside Shoulder, North Approach	39.257	20' Lt of centerline	39.261	20' Lt of centerline	Reinstalled the previously removed bridge anchor section and asymmetrical transition

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 8 of 12



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0030	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	ACAD	4	May 18, 2020	dwighj1	(\$50.32)	This AC Index Adjustment is for asphalt mix that was placed on April 30, 2020. The material was not paid for until Estimate 0004, which is the May 15, 2020 pay estimate, but it was placed during the previous estimate period. There were a total of 30.27 tons of SP125C mix placed (Mix ID: SP125 20-41), with a virgin AC of 3.8%.
				6	Jun 16, 2020	dwighj1	(\$359.10)	This Line Item Adjustment is for the AC Price Adjustment for asphalt that was placed on June 15, 2020. There were a total of 90 tons placed on that day, with a virgin asphalt content of 3.8%, with a mix ID of SP125 20-41.
		al			(\$409.42)			
	Other Item Adjustment - Total						(\$409.42)	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Price		4	May 18, 2020	SYSTEM	(\$108.54)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				6	Jun 16, 2020	SYSTEM	(\$292.82)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$401.36)	
	Price - Total						(\$401.36)	
0030 -	Total						(\$810.78)	
0050	IMPACT ATTENUATOR 65 MPH (SAND BARRELS)	Material		1	Apr 3, 2020	SYSTEM	(\$6,800.00)	
				1	Apr 3, 2020	SYSTEM	\$6,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0050 -	Total						\$0.00	
0800	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Material		1	Apr 3, 2020	SYSTEM	(\$1.00)	
				1	Apr 3, 2020	SYSTEM	\$1.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0080 -	Total						\$0.00	
0090	CONSTRUCTION SIGNS	Material		1	Apr 3, 2020	SYSTEM	(\$6,656.00)	
				1	Apr 3, 2020	SYSTEM	\$6,656.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0090 -	Total						\$0.00	
0100	ADVANCED WARNING RAIL SYSTEM	Material		1	Apr 3, 2020	SYSTEM	(\$560.00)	
				1	Apr 3, 2020	SYSTEM	\$560.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0100 -	Total						\$0.00	
0110	FLAG ASSEMBLY	Material		1	Apr 3, 2020	SYSTEM	(\$120.00)	
			1		Apr 3, 2020	SYSTEM	\$120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0110 -	- Total						\$0.00	
0120	CHANNELIZER (TRIM LINE)	Material		1	Apr 3, 2020	SYSTEM	(\$1,860.00)	
				1	Apr 3, 2020	SYSTEM	\$1,860.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dwighj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.

Revision 4/1/2020 Page 9 of 12



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0120		Material	- Total				\$0.00	
	Material - Total						\$0.00	
0120 -	Total						\$0.00	
0130	TYPE III MOVEABLE BARRICADE	Material		1	Apr 3, 2020	SYSTEM	(\$300.00)	
				1	Apr 3, 2020	SYSTEM	\$300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dwighj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0130 -	Total						\$0.00	
0140	DIRECTIONAL INDICATOR BARRICADE	Material		1	Apr 3, 2020	SYSTEM	(\$2,310.00)	
				1	Apr 3, 2020	SYSTEM	\$2,310.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user dwighj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0140 -	Total						\$0.00	
0150	FLASHING ARROW PANEL	Material		1	Apr 3, 2020	SYSTEM	(\$2,550.00)	
				1	Apr 3, 2020	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dwighj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0150 -	Total						\$0.00	
0160	CHANGEABLE MESSAGE N SIGN WITHOUT COMMUNICATION			1	Apr 3, 2020	SYSTEM	(\$8,400.00)	
	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED			1	Apr 3, 2020	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dwighj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0160 -	Total						\$0.00	
0170	TEMPORARY LONG- TERM RUMBLE STRIPS	Material		1	Apr 3, 2020	SYSTEM	(\$4,000.00)	
				1	Apr 3, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dwighj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total						\$0.00	
0170 -	Total						\$0.00	
0180	TEMPORARY TRAFFIC BARRIER, CONTRACTOR	Material		1	Apr 3, 2020	SYSTEM	(\$25,376.00)	
	FURNISHED / RETAINED			1	Apr 3, 2020	SYSTEM	\$25,376.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dwighj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0180 -	Total						\$0.00	
0350	CURB BLOCKOUT	COUT Material		2	Apr 15, 2020	SYSTEM	(\$25,700.00)	
				3	May 4, 2020	SYSTEM	(\$25,700.00)	
				3	May 4, 2020	SYSTEM	\$25,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	May 18, 2020	SYSTEM	(\$25,700.00)

Revision 4/1/2020 Page 10 of 12



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0350	CURB BLOCKOUT	Material		4	May 18, 2020	SYSTEM	\$25,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$25,700.00)	
				5	Jun 2, 2020	SYSTEM	\$25,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				6	Jun 16, 2020	SYSTEM	(\$25,700.00)	
				6	Jun 16, 2020	SYSTEM	\$25,700.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				(\$25,700.00)	
	Material - Total						(\$25,700.00)	
	CURB BLOCKOUT	MaterialCredit		3	May 4, 2020	SYSTEM	\$25,700.00	
			- Total				\$25,700.00	
	MaterialCredit - Total						\$25,700.00	
0350 -	Total						\$0.00	
0450	MISC. RUBBLIZE EXISTING DECK REPAIR	Overrun	Overrun	4	May 18, 2020	SYSTEM	(\$39,595.75)	
			Overrun - T	otal			(\$39,595.75)	
	Overrun - Total						(\$39,595.75)	
0450 -	Total						(\$39,595.75)	
0460	CONCRETE WEARING	Material		5	Jun 2, 2020	SYSTEM	(\$118,628.00)	
	SURFACE			5	Jun 2, 2020	SYSTEM	\$118,628.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
							00.00	
			- Total				\$0.00	
	Material - Total		- I otal				\$0.00	
0460 -			- Total					
0460 - 0470		Material	- I otal	2	Apr 15, 2020	SYSTEM	\$0.00	
	Total	Material	- I otal	2		SYSTEM	\$0.00 \$0.00	
	Total	Material	- Total		2020 May 4,		\$0.00 \$0.00 (\$25,700.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
	Total	Material	- Total	3	2020 May 4, 2020 May 4,	SYSTEM	\$0.00 \$0.00 (\$25,700.00) (\$25,700.00)	Estimate Item Adjustment (0014) due to user dwighj1 overridding Payment
	Total	Material	- Total	3	2020 May 4, 2020 May 4, 2020	SYSTEM	\$0.00 \$0.00 (\$25,700.00) (\$25,700.00) \$25,700.00	Estimate Item Adjustment (0014) due to user dwighj1 overridding Payment
	Total	Material	- Total	3 3	2020 May 4, 2020 May 4, 2020 May 18, 2020 May 18,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$25,700.00) (\$25,700.00) \$25,700.00 (\$51,400.00)	Estimate Item Adjustment (0014) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment
	Total	Material	- Total	3 3 4 4	2020 May 4, 2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$25,700.00) (\$25,700.00) \$25,700.00 (\$51,400.00) \$51,400.00	Estimate Item Adjustment (0014) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment
	Total	Material	- Total	3 3 4 4 5	2020 May 4, 2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$25,700.00) (\$25,700.00) \$25,700.00 (\$51,400.00) (\$51,400.00)	Estimate Item Adjustment (0014) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dwighj1 overridding Payment
	Total	Material	- Total	3 3 4 4 5 5	2020 May 4, 2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$25,700.00) (\$25,700.00) (\$25,700.00 (\$51,400.00) (\$51,400.00) (\$51,400.00)	Estimate Item Adjustment (0014) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dwighj1 overridding Payment
	Total	Material	- Total	3 3 4 4 5 5 6 6	2020 May 4, 2020 May 4, 2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$25,700.00) (\$25,700.00) (\$25,700.00) (\$51,400.00) (\$51,400.00) (\$51,400.00) (\$51,400.00)	Estimate Item Adjustment (0014) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment
	Total	Material		3 3 4 4 5 5 6 6	2020 May 4, 2020 May 4, 2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$25,700.00) (\$25,700.00) \$25,700.00 (\$51,400.00) \$51,400.00 (\$51,400.00) \$51,400.00 (\$51,400.00)	Estimate Item Adjustment (0014) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment
	CURB BLOCKOUT			3 3 4 4 5 5 6 6	2020 May 4, 2020 May 4, 2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$25,700.00) (\$25,700.00) \$25,700.00 (\$51,400.00) \$51,400.00 (\$51,400.00) \$51,400.00 (\$51,400.00)	Estimate Item Adjustment (0014) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment
	CURB BLOCKOUT			3 3 4 4 5 5 6 6	2020 May 4, 2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$25,700.00) (\$25,700.00) (\$25,700.00) (\$51,400.00) (\$51,400.00) (\$51,400.00) (\$51,400.00) (\$51,400.00) (\$51,400.00) (\$51,400.00) (\$51,400.00)	Estimate Item Adjustment (0014) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment
	CURB BLOCKOUT		- Total	3 3 4 4 5 5 6 6	2020 May 4, 2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$25,700.00) (\$25,700.00) \$25,700.00 (\$51,400.00) \$51,400.00 (\$51,400.00) \$51,400.00 (\$51,400.00) \$51,400.00 (\$51,400.00) \$51,400.00 \$51,400.00	Estimate Item Adjustment (0014) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment
	CURB BLOCKOUT Material - Total CURB BLOCKOUT		- Total	3 3 4 4 5 5 6 6	2020 May 4, 2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$25,700.00) (\$25,700.00) (\$25,700.00) (\$51,400.00) (\$51,400.00) (\$51,400.00) (\$51,400.00) (\$51,400.00) (\$51,400.00) (\$25,700.00) (\$25,700.00) \$25,700.00	Estimate Item Adjustment (0014) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment
0470	CURB BLOCKOUT Material - Total CURB BLOCKOUT	MaterialCredit	- Total	3 3 4 4 5 5 6 6	2020 May 4, 2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$25,700.00) (\$25,700.00) (\$25,700.00) (\$51,400.00) (\$51,400.00) (\$51,400.00) (\$51,400.00) (\$51,400.00) (\$51,400.00) (\$51,400.00) (\$25,700.00) (\$25,700.00) \$25,700.00 \$25,700.00	Estimate Item Adjustment (0014) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dwighj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dwighj1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment Estimate Item Adjustment (0004) due to user dwighj1 overridding Payment

Revision 4/1/2020 Page 11 of 12



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0540	REPAIR	Material			2020			
				5	Jun 2, 2020	SYSTEM	\$26,565.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dwighj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	MONOLITHIC DECK REPAIR	Other Item Adjustment	OTHR	6	Jun 16, 2020	dwighj1	\$16,786.00	This Line Item Adjustment is to put back the amount deducted by the system on this line number on estimate 0006. The system made an overrun adjustment automatically of -\$16,786.00, and nothing was paid out on this line number on this estimate. Change Order 0002 will correct the quantity to resolve this discrepancy, but the system is trying to deduct the overrun amount again on this estimate.
			OTHR - Tota	al			\$16,786.00	
	Other Item Adjustment - Tot					\$16,786.00		
	MONOLITHIC DECK REPAIR		Overrun	3	May 4, 2020	SYSTEM	(\$2,079.00)	
				3	May 4, 2020	SYSTEM	\$2,079.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dwighj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				4	May 18, 2020	SYSTEM	(\$2,079.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	Jun 2, 2020	SYSTEM	\$16,786.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 6 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$16,786.00)	
				6	Jun 16, 2020	SYSTEM	(\$16,786.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
		Overrun - To	Overrun - Total			(\$18,865.00)		
	Overrun - Total					(\$18,865.00)		
0540 -	Total						(\$2,079.00)	
0660	MGS GUARDRAIL	Construction Stockpile		3	May 4, 2020	SYSTEM	\$22,012.21	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total			\$22,012.21		
	Construction Stockpile - To	tal					\$22,012.21	
0660 -	Total						\$22,012.21	
0670	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		3	May 4, 2020	SYSTEM	\$5,996.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$5,996.00	
	Construction Stockpile - To	tal					\$5,996.00	
0670 -	Total						\$5,996.00	
0680	MGS END ANCHOR	Construction Stockpile		3	May 4, 2020	SYSTEM	\$1,070.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	- Total						\$1,070.00	
	Construction Stockpile - Total						\$1,070.00	
0680 -	0 - Total						\$1,070.00	
0690	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		3	May 4, 2020	SYSTEM	\$3,020.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$3,020.00	
	Construction Stockpile - Total						\$3,020.00	
0690 -	Total						\$3,020.00	
Overa	II - Total						(\$10,387.32)	

Revision 4/1/2020 Page 12 of 12