

Pay Estimate Created Date: October 16, 2020

Progress	Number		190816-C02	Pay Perio Start	Original Contract Amount	\$732,814.10			
4 Prime Contract		Prime Contractor	Radmacher Brothers Co.,Inc.	Excavating Pay Perio	d End ^{October} 15, 2020	Net Change Order Amount Current Contract Amo	\$0.00 500t\$732,814.10		
Approval Date							By User		
October 16, 2020			Generated and	Approved (and should be cor	nsidered Draft) at the F	Project Office Level by	karlic1		
October 16, 2020			Reviewed and Appro	oved (and should be conside	red Draft) at the Resid	ent Engineer Level by	karlic1		
October 19, 2020				Reviewed and Approved at t	he Central Office Cont	rollers Office Level by	greggd1		
Original Comp	Completion Date Current Completion Date Actual Completion Date % of Current Contract An								
December	1, 2020	De	cember 1, 2020			68.60%			

No Milestones Exist for Contract

Contract Total P	ay For Estimat	e No. 4							
			This Estimate	Pre	evious	To Da	te		
190816-C02 Contract Total P ems Paid This E	Gross Ite Incentive Disincen Liquidate Other Co ayable This Es	tive ed Damage ontract Adjus timate:	nts \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0 \$0 \$0 \$0 \$0 \$0	09,585.48 .00 .00 .00 .00 .00 .00 09,585.48	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00		
Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amoun		
J4I3219	0420	7034212	SLAB ON STEEL	SQYD	\$287.300	809	\$232,425.70		
	0430	7004045							
	0430	7034215	SAFETY BARRIER CURB	LF	\$52.500	502	\$26,355.00		
	0430	7034215	SAFETY BARRIER CURB SLAB DRAIN	LF EA	\$52.500 \$347.000	502			
							\$1,388.00		
	0480	7123610	SLAB DRAIN	EA	\$347.000	4	\$1,388.00 \$4,387.10		
Project J4I3219	0480 0540 0560	7123610 7151001	SLAB DRAIN VERTICAL DRAIN AT END BENTS	EA	\$347.000 \$2,193.550	4	\$26,355.00 \$1,388.00 \$4,387.10 \$28,599.20 \$293,155.00		

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project	Line	Item Description	Adjustment	Other Item	Comments	Adjustment	Line Item	Adjustment
Number	No.		Туре	Adjustment Type		Quantity	Adjustment Unit Price	amount
J4I3219	0420	SLAB ON STEEL	Material			-809	\$287.30	(\$232,425.70)
	0420	SLAB ON STEEL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	809	\$287.30	\$232,425.70
	0430	SAFETY BARRIER CURB	Material			-502	\$52.50	(\$26,355.00)
	0430	SAFETY BARRIER CURB	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	502	\$52.50	\$26,355.00
	0540	VERTICAL DRAIN AT END BENTS	Material			-2	\$2,193.55	(\$4,387.10)
	0540	VERTICAL DRAIN AT END BENTS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	2	\$2,193.55	\$4,387.10



Pay Estimate Created Date: October 16, 2020

	Progress Es N 4	stimate lumber	Contract ID Prime Contractor	190816-C0 Radmache Co.,Inc.	2 r Brothers Exc	cavating	Pay Period Start Pay Period Enc	Amount Net Change Amount	Order	\$732,814.10 \$0.00 t \$732,814.10
Project Number	Line No.	Item De	scription	Adjustment Type	Other Item Adjustment Type		Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
Total	, ,									\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Informatio	on							
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work								
J4I3219	FAS S302(001)	Bridge deck replacement	I-35	CLAY	on 128th Street									
Totals by	Job Number	s												
J4I3219		l Item Pay Item Adjustme		Item Pay	This Estimate \$293,155.00 \$0.00 \$293,155.00	Previous \$209,585.48 \$0.00 \$209,585.48	To Date \$502,740.48 \$0.00 \$502,740.48							
					\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00							



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 7034212, Project Item Line Number 0420, Material Set 703421296, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on concrete cylinder breaks.	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 7034212, Project Item Line Number 0420, Material Set 703421296, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Working with materials.	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3219, Item 7034212, Project Item Line Number 0420, Material Set 703421296, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Working with materials.	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 7034212, Project Item Line Number 0420, Material Set 703421296, Material 1036RSDFEC42M22 - Rein Steel EC No. 7/M22 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with materials.	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 7034212, Project Item Line Number 0420, Material Set 703421296, Material 1036RSDFEC42M25 - Rein Steel EC No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with materials.	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 7034212, Project Item Line Number 0420, Material Set 703421296, Material 1036RSDFPL42M16 - Reinforcing Steel No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with materials.	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 7034212, Project Item Line Number 0420, Material Set 703421296, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with materials.	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 7034212, Project Item Line Number 0420, Material Set 703421296, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with materials.	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 7034212, Project Item Line Number 0420, Material Set 703421296, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with materials.	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 7034215, Project Item Line Number 0430, Material Set 703421596, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Working with materials.	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 7034215, Project Item Line Number 0430, Material Set 703421596, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Working with materials.	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 7034215, Project Item Line Number 0430, Material Set 703421596, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Working with materials.	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3219, Item 7034215, Project Item Line Number 0430, Material Set 703421596, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Working with materials.	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3219, Item 7151001, Project Item Line Number 0540, Material Set 7151001, Material 0715DRVT - Vertical Drain at End Bents, Acceptance Action Generic 0715DRVT is insufficient.	Working with materials.	schnod1	Overridden

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	ies are l	based on F	Report Generated date and can differ from the posted am	ount at th	ne time th	e Estimate	was Ger	nerated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190816-C02	J4I3219	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	1.00	\$3,580.95	\$3,580.95
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$829.00	\$829.00
		0001	0030	2069903	MISC.Ditch Cleanout	228.00	0.00	228.00	LF	0.00	\$11.00	\$0.00
		0001	0040	2153000	SHAPING SLOPES, CLASS III	5.00	0.00	5.00	100F	0.00	\$1,098.25	\$0.00
		0001	0050	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	48.00	0.00	48.00	SQYD	0.00	\$20.90	\$0.00
		0001	0060	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	28.80	0.00	28.80	TONS	0.00	\$288.75	\$0.00
		0001	0070	4071005	TACK COAT	3.00	0.00	3.00	GAL	0.00	\$10.50	\$0.00
		0001	0080	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	9.00	0.00	9.00	CUYD	0.00	\$45.55	\$0.00
		0001	0090	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	15.00	0.00	15.00	CUYD	0.00	\$45.55	\$0.00
		0001	0100	6096041	PLACING TYPE 1 ROCK DITCH LINER	9.00	0.00	9.00	CUYD	0.00	\$48.95	\$0.00
		0001	0110	6096042	PLACING TYPE 2 ROCK DITCH LINER	15.00	0.00	15.00	CUYD	0.00	\$48.95	\$0.00
		0001	0120	6113020	FURNISHING TYPE 2 ROCK BLANKET	215.00	0.00	215.00	CUYD	214.95	\$37.10	\$7,974.64
		0001	0130	6113040	PLACING TYPE 2 ROCK BLANKET	215.00	0.00	215.00	CUYD	214.95	\$40.80	\$8,769.96
		0001	0140	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$685.35	\$0.00
		0001	0150	6161005	CONSTRUCTION SIGNS	658.00	0.00	658.00	SQFT	593.00	\$6.30	\$3,735.90
		0001	0160	6161009	FLAG ASSEMBLY	12.00	0.00	12.00	EA	4.00	\$18.90	\$75.60
		0001	0170	6161025	CHANNELIZER (TRIM LINE)	200.00	0.00	200.00	EA	50.00	\$13.65	\$682.50
		0001	0180	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	8.00	0.00	8.00	EA	8.00	\$157.50	\$1,260.00
		0001	0190	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$525.00	\$1,050.00
		0001	0200	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$2,887.50	\$11,550.00
		0001	0210	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	600.00	0.00	600.00	LF	0.00	\$12.95	\$0.00
		0001	0220	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	600.00	0.00	600.00	LF	0.00	\$8.35	\$0.00
		0001	0230	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.25	\$99,709.60	\$24,927.40
		0001	0240	6200001	COLD APPLIED TAPE PAVEMENT MARKING, 4 IN., WHITE	3,920.00	0.00	3,920.00	LF	0.00	\$1.00	\$0.00
		0001	0250	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	4,900.00	0.00	4,900.00	LF	0.00	\$0.55	\$0.00
		0001	0260	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,375.00	0.00	1,375.00	LF	0.00	\$0.55	\$0.00
		0001	0270	6207001	PAVEMENT MARKING REMOVAL	8,820.00	0.00	8,820.00	LF	0.00	\$0.45	\$0.00
		0001	0280	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	298.00	0.00	298.00	SQYD	0.00	\$15.25	\$0.00
		0001	0290	6240104A	SEPARATION GEOTEXTILE	500.00	0.00	500.00	SQYD	322.43	\$2.25	\$725.47
		0001	0300	8061005	ROCK DITCH CHECK	30.00	0.00	30.00	LF	0.00	\$21.00	\$0.00
		0001	0310	9035004A	SH-FLAT SHEET	24.00	0.00	24.00	SQFT	0.00	\$23.10	\$0.00
		0010	0320	6061010	GUARDRAIL TYPE A	12.50	0.00	12.50	LF	0.00	\$20.90	\$0.00
		0010	0330	6061060	MGS GUARDRAIL	112.50	0.00	112.50	LF	0.00	\$20.90	\$0.00
		0010	0340	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	3.00	0.00	3.00	EA	0.00	\$2,887.50	\$0.00
		0010	0350	6062200A	BRIDGE ANCHOR SECTION, 6.5 FT. POSTS (SAFETY BARRIER CURB) (ROADWAY AND REHABILITATION WORK ONLY)	1.00	0.00	1.00	EA	0.00	\$1,995.00	\$0.00
		0010	0360	6062300A	TRANSITION SECTION, 6.5 FT. POSTS	1.00	0.00	1.00	EA	0.00	\$472.50	\$0.00
		0010	0370	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	3.00	0.00	3.00	EA	0.00	\$2,940.00	\$0.00
		0010	0380	6063015	TYPE A CRASHWORTHY END TERMINAL	1.00	0.00	1.00	EA	0.00	\$2,940.00	\$0.00
		0070	0390	2162500	REMOVAL OF EXISTING BRIDGE DECK	6,977.00	0.00	6,977.00	SQFT	6,977.00	\$9.65	\$67,328.05
		0070	0400	2169902	MISC.REMOVAL OF EXISTING BEARINGS	8.00	0.00	8.00	EA	8.00	\$384.70	\$3,077.60
		0070	0410	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	112.00	0.00	112.00	SQYD	0.00	\$153.30	\$0.00
		0070	0420	7034212	SLAB ON STEEL	809.00	0.00	809.00	SQYD	809.00	\$287.30	\$232,425.70
		0070	0430	7034215	SAFETY BARRIER CURB	502.00	0.00	502.00	LF	502.00	\$52.50	\$26,355.00

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190816-C02	J4I3219	0070	0440	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	80.00	0.00	80.00	SQFT	0.00	\$90.85	\$0.00
		0070	0450	7040164	FIBER REINFORCED POLYMER WRAP	94.00	0.00	94.00	SF	0.00	\$151.95	\$0.00
		0070	0460	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$7,068.60	\$0.00
		0070	0470	7121250	STRENGTHENING EXISTING BEAMS	1.00	0.00	1.00	LS	1.00	\$54,075.60	\$54,075.60
		0070	0480	7123610	SLAB DRAIN	4.00	0.00	4.00	EA	4.00	\$347.00	\$1,388.00
		0070	0490	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	600.00	0.00	600.00	SQFT	0.00	\$44.75	\$0.00
		0070	0500	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	600.00	0.00	600.00	SQFT	0.00	\$2.50	\$0.00
		0070	0510	7125365A	INTERMEDIATE FIELD COAT (SYSTEM G)	600.00	0.00	600.00	SQFT	0.00	\$1.50	\$0.00
		0070	0520	7125370A	FINISH FIELD COAT (SYSTEM G)	600.00	0.00	600.00	SQFT	0.00	\$1.50	\$0.00
		0070	0530	7126000	NON-DESTRUCTIVE TESTING	68.00	0.00	68.00	LF	68.00	\$31.50	\$2,142.00
		0070	0540	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$2,193.55	\$4,387.10
		0070	0550	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	8.00	0.00	8.00	EA	8.00	\$2,225.10	\$17,800.80
		0070	0560	7172001	STRIP SEAL EXPANSION JOINT SYSTEM 56.00 0.00 56					56.00	\$510.70	\$28,599.20
	Project J	J4I3219 - To	otal Value	Posted to D	ate as of Report Generated Date							\$502,740.47
190816-C02 Ove	rall - Tota	I Value Pos	sted to Da	ate as of Rep	ort Generated Date							\$502,740.47



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4I3219

Line Number	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0420	7034212	SLAB ON STEEL	10/5/20	10/16/20	809.00	SQYD	128th Street Bridge.	8+73.10		11+26.89		
0430	7034215	SAFETY BARRIER CURB	10/5/20	10/16/20	502.00	LF	North and south sides of the bridge.	8+73.10		11+26.89		
0480	7123610	SLAB DRAIN	10/5/20	10/16/20	4.00	EA	2 drains on the north side, 2 drains on the south side.	8+73.10		11+26.89		
0540	7151001	VERTICAL DRAIN AT END BENTS	10/5/20	10/16/20	2.00	EA	1 vertical drain on the east end, 1 vertical drain on the west end.	8+73.10		11+26.89		
0560	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	10/5/20	10/16/20	56.00	LF	One on the east end of the bridge, one on the west end of the bridge.	8+73.10		11+26.89		

The information below this line are details from Line Item agency views. No Agency View Details Exist



Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0120	FURNISHING TYPE 2 ROCK BLANKET	Material		2	Sep 16, 2020	SYSTEM	(\$7,974.64)	
				2	Sep 16, 2020	SYSTEM	\$7,974.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				3	Oct 2, 2020	SYSTEM	(\$7,974.64)	
				3	Oct 2, 2020	SYSTEM	\$7,974.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0120 -	Total						\$0.00	
0190	FLASHING ARROW PANEL	Material		1	Sep 2, 2020	SYSTEM	(\$1,050.00)	
				1	Sep 2, 2020	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0190 -	Total						\$0.00	
0200	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED,	Material		1	Sep 2, 2020	SYSTEM	(\$11,550.00)	
	CONTRACTOR PURISHED, CONTRACTOR RETAINED			1	Sep 2, 2020	SYSTEM	\$11,550.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0200 -	Total						\$0.00	
0290	SEPARATION GEOTEXTILE	Material		2	Sep 16, 2020	SYSTEM	(\$725.47)	
				2	Sep 16, 2020	SYSTEM	\$725.47	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				3	Oct 2, 2020	SYSTEM	(\$725.47)	
				3	Oct 2, 2020	SYSTEM	\$725.47	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	Total						\$0.00	
0290 -								
	SLAB ON STEEL	Material		4	Oct 16, 2020	SYSTEM	(\$232,425.70)	
0290 - 0420	SLAB ON STEEL	Material		4		SYSTEM SYSTEM	(\$232,425.70) \$232,425.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
	SLAB ON STEEL	Material	- Total		2020 Oct 16,			Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment
	SLAB ON STEEL Material - Total	Material	- Total		2020 Oct 16,		\$232,425.70	Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment
0420		Material	- Total		2020 Oct 16,		\$232,425.70 \$0.00	Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment
0420 0420 -	Material - Total	Material	- Total		2020 Oct 16,		\$232,425.70 \$0.00 \$0.00	Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment
0420	Material - Total Total		- Total	4	2020 Oct 16, 2020 Oct 16,	SYSTEM	\$232,425.70 \$0.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment
0420 0420 -	Material - Total Total		- Total	4	2020 Oct 16, 2020 Oct 16, 2020 Oct 16, 2020 Oct 16,	SYSTEM	\$232,425.70 \$0.00 \$0.00 \$0.00 (\$26,355.00)	Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.



Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0430 -	Total						\$0.00	
0540	VERTICAL DRAIN AT END BENTS	Material		4	Oct 16, 2020	SYSTEM	(\$4,387.10)	
				4	Oct 16, 2020	SYSTEM	\$4,387.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0540 -	Total						\$0.00	
Overall - Total							\$0.00	