

Pay Estimate Created Date: August 3, 2020

Progress	Progress Estimate Number 11 Cont Cont		190816-F01 L.F. Krupp Construct Krupp	S	ay Period Itart ay Period End		Original Contract Amo Net Change Order Amount Current Contract Amo	\$0.00	
Approval Date								By User	
August 3, 2020			Generated and	Approved (and sho	uld be consider	ed Draft) at the	Project Office Level by	gummer1	
August 5, 2020			Reviewed and App	roved (and should b	e considered D	raft) at the Resi	ident Engineer Level by	lewisj1	
August 6, 2020				Reviewed and App	roved at the Ce	entral Office Co	ntrollers Office Level by	greggd1	
Original Comp	letion Date	tion Date Current Completion Date Actual Completion Date % of Current Contract An							
November	6, 2020	No	vember 6, 2020				55.84%		

No Milestones Exist for Contract

Contract Total Pay For Estimate No. 11										
		This Estimate	Previous	To Date						
190816-F01										
	Total Posted Items Pay	\$0.00	\$3,531,580.34	\$3,531,580.34						
	Gross Item Adjustments	\$0.00	\$127,405.68	\$127,405.68						
	Incentive	\$0.00	\$0.00	\$0.00						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
	-		\$3,658,986.02	\$3,658,986.02						
Contract Total Pa	yable This Estimate:	\$0.00								

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
0070	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Material			-17,636.33	\$89.10	(\$1,571,397.00
0070	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user gummer1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	17,636.33	\$89.10	\$1,571,397.00
0080	TACK COAT	Material			-17,413	\$5.10	(\$88,806.30
0080	TACK COAT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user gummer1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	17,413	\$5.10	\$88,806.30
0150	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-1,591.5	\$235.00	(\$374,002.50
0150	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user gummer1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	1,591.5	\$235.00	\$374,002.50
0190	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-2,304	\$3.50	(\$8,064.00)
0190	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user gummer1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	2,304	\$3.50	\$8,064.00
	No. 0070 0070 0080 0080 0150 0150	No.ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)0070ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)0070ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)0080TACK COAT0080TACK COAT0080TACK COAT0150FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR0150FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR0190DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL0190DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL	No.Type0070ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)Material0070ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)Material0080TACK COATMaterial0080TACK COATMaterial0080TACK COATMaterial0150FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIRMaterial0150FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIRMaterial0150ONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIRMaterial0150ONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIRMaterial0190DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULLMaterial0190DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULLMaterial	No.TypeAdjustment Type0070ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)Material0070ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)Material0080TACK COATMaterial0080TACK COATMaterial0080TACK COATMaterial0150FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIRMaterial0150FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIRMaterial0190DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIRMaterial0190DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIRMaterial	No.TypeAdjustment Type0070ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)Material0070ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)Material0070ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)Material0080TACK COATMaterial0080TACK COATMaterial0080TACK COATMaterial0080TACK COATMaterial0080TACK COATMaterial0080TACK COATMaterial0190FURNISHING AND PLACING FULL DEPTH PAVEMENT REPAIRMaterial0190DOWEL BAR (DRILLING, FURNISHING AND REPAIRMaterial0190DOWEL BAR (DRILLING, FURNISHING AND FURNISHING AND REPAIRMaterial0190DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULLMaterial Adjustment offsets the original system- generated Overrun Payment Estimate Exception 4 on the current Payment Estimate Exception 7 on <td>No.TypeAdjustment TypeOutput Adjustment TypeAdjustment Type0070ASPHALTIC CONCRETE (SP125BSM MIX)MaterialImage: Constraint of Sets the original system: generated Overrun Payment Estimate Item Adjustment (0001) due to user gummert overridding Payment Estimate Item Adjustment (0001) due to user gummert overridding Payment Estimate Item Adjustment (0001) due to user gummert sets the original system: generated Overrun Payment Estimate Item Adjustment (0001) due to user gummert overridding Payment Estimate Item Adjustment (0002) due to user gummert overridding Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0002) due to user gummert overridding Payment Estimate Item Adjustment (0002) due to user gummert overridding Payment Estimate Exception 2 on the current Payment Estimate Item Adjustment (0002) due to user gummert overridding Payment Estimate Exception 2 on the current Payment Estimate Item Adjustment (0002) due to user gummert overridding Payment Estimate Exception 2 on the current Payment Estimate Item Adjustment (0002) due to user gummert overridding Payment Estimate Exception 2 on the current Payment Estimate Item Adjustment (0002) due to user gummert overridding Payment Estimate Item Adjustment (0000) due to user gummert overridding Payment Estimate Item Adjustment (0000) due to user gummert overridding Payment Estimate Exception 4 on the current Payment Estimate Item Adjustment (0000) due to user gummert overridding Payment Estimate Estimate Item Adjustment (0000) due to user gummert overridding Payment Estimate Estimate Item Adjustment (0000) due to user gummert overridding Payment Estimate Estimate Item Adjustment (0000) due to user gummert overridding Payment Estimate Estimate Item Adjustment</td> <td>No.TypeAdjustment TypeAdjustment TypeQuantityAdjustment Unit Price0070ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)MaterialC17,636.33\$89.100070ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)MaterialThis adjustment offsets the original system- generated Overrun Payment Estimate Exception 1 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 4 on the current Payment Estimate Exception 7 on erri</td>	No.TypeAdjustment TypeOutput Adjustment TypeAdjustment Type0070ASPHALTIC CONCRETE (SP125BSM MIX)MaterialImage: Constraint of Sets the original system: generated Overrun Payment Estimate Item Adjustment (0001) due to user gummert overridding Payment Estimate Item Adjustment (0001) due to user gummert overridding Payment Estimate Item Adjustment (0001) due to user gummert sets the original system: generated Overrun Payment Estimate Item Adjustment (0001) due to user gummert overridding Payment Estimate Item Adjustment (0002) due to user gummert overridding Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0002) due to user gummert overridding Payment Estimate Item Adjustment (0002) due to user gummert overridding Payment Estimate Exception 2 on the current Payment Estimate Item Adjustment (0002) due to user gummert overridding Payment Estimate Exception 2 on the current Payment Estimate Item Adjustment (0002) due to user gummert overridding Payment Estimate Exception 2 on the current Payment Estimate Item Adjustment (0002) due to user gummert overridding Payment Estimate Exception 2 on the current Payment Estimate Item Adjustment (0002) due to user gummert overridding Payment Estimate Item Adjustment (0000) due to user gummert overridding Payment Estimate Item Adjustment (0000) due to user gummert overridding Payment Estimate Exception 4 on the current Payment Estimate Item Adjustment (0000) due to user gummert overridding Payment Estimate Estimate Item Adjustment (0000) due to user gummert overridding Payment Estimate Estimate Item Adjustment (0000) due to user gummert overridding Payment Estimate Estimate Item Adjustment (0000) due to user gummert overridding Payment Estimate Estimate Item Adjustment	No.TypeAdjustment TypeAdjustment TypeQuantityAdjustment Unit Price0070ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)MaterialC17,636.33\$89.100070ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)MaterialThis adjustment offsets the original system- generated Overrun Payment Estimate Exception 1 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 4 on the current Payment Estimate Exception 7 on erri



Pay Estimate Created Date: August 3, 2020

	Progr 1	ress Estimate Number 1	Contract ID Prime Contractor	190816-F L.F. Krupp Krupp	01 o Construction	Pay Period Start n, Inc. dba Pay Period Enc	July 16, 2020 August 1, 2020	Net Change Amount	Order	t \$6,323,909.21 \$0.00 t \$6,323,909.21
Project Number	Line No.	Item Des	scription	Adjustment Type	Other Item Adjustment Type	Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3195	0320	WATERBORN	E HIGH BUILD IE PAVEMENT PAINT, TYPE L BEADS	Material				-13,335	\$0.21	(\$2,800.35)
	0320	WATERBORN	E HIGH BUILD IE PAVEMENT PAINT, TYPE L BEADS	Material		This adjustment offsets the o generated Overrun Paymen Adjustment (0005) due to overridding Payment Estimate the current Pay	t Estimate Item user gummer1 Exception 8 on	,	\$0.21	\$2,800.35
Total										\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information												
Project Number	Federal Proj. Number	Project Description	Route	Route County Location of Work									
J6l3195	l 70-4(201)	Resurface and guardrail improvements	I-70	ST CHARLES	from W/O Wentzville Pl	kwy to E/O Lake St. Louis I	Blvd						
Totals by .	Job Numbe	rs											
J6I3195		l Item Pay Item Adjustme		tem Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$3,531,580.34 \$127,405.68 \$3,658,986.02	To Date \$3,531,580.34 \$127,405.68 \$3,658,986.02						
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00						



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6I3195, Item 4030132, Project Item Line Number 0070, Material Set 403013296, Material 0403SP125BSM - Superpave 12.5 mm, Des B SM, Acceptance Action Generic AspHigh is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3195, Item 4071005, Project Item Line Number 0080, Material Set 407100596, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3195, Item 4071005, Project Item Line Number 0080, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3195, Item 6131010, Project Item Line Number 0150, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3195, Item 6131010, Project Item Line Number 0150, Material Set 613101096, Material 100510OPTLD1 - PCCP 1" Max LS/DO, Acceptance Action Generic 100510OPTLD1 is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3195, Item 6131010, Project Item Line Number 0150, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3195, Item 6131015, Project Item Line Number 0190, Material Set 6131015, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3195, Item 6205902A, Project Item Line Number 0320, Material Set 6205902A96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3195, Item 6205902A, Project Item Line Number 0320, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3195, Item 6205902A, Project Item Line Number 0320, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	No Remark was entered by Engineer	gummer1	Overridden
Estimate Exception Type: Item Overrun: Contract 190816-F01, Contract Project J6I3195, Project Item Line Number 0290, Contract Line Item Number 0290, Item 6179903, Minor Item.	No Remark was entered by Engineer	gummer1	Acknowledged

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Note: Posted Q	uantities				Report Generated date and can differ from the posted am	ount at the	time the	Estimate wa	is Gener	rated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190816-F01	J6l3195	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$79,240.00	\$0.00
		0001	0020	2063500	CULVERT CLEANOUT	15.00	0.00	15.00	EA	0.00	\$2,230.00	\$0.00
		0001	0030	2153000	SHAPING SLOPES, CLASS III	33.00	0.00	33.00	100F	0.00	\$900.00	\$0.00
		0001	0040	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	8,018.70	0.00	8,018.70	TONS	6,328.25	\$73.90	\$467,657.68
		0001	0050	4019901	MISC.INFRARED SCANNING	1.00	0.00	1.00	LS	0.00	\$25,000.00	\$0.00
		0001	0060	4019901	MISC.INTELLIGENT COMPACTION	1.00	0.00	1.00	LS	0.00	\$33,000.00	\$0.00
		0001	0070	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	28,533.00	0.00	28,533.00	TONS	17,636.33	\$89.10	\$1,571,397.00
		0001	0080	4071005	TACK COAT	27,134.00	0.00	27,134.00	GAL	17,413.00	\$5.10	\$88,806.30
		0001	0090	6064500	AGGREGATE BEDDING FOR 3 - STRAND GUARD CABLE	21.00	0.00	21.00	CUYD	0.00	\$220.00	\$0.00
		0001	0100	6069901	MISC.REMOVE AND REPLACE EXISTING BOLTS	1.00	0.00	1.00	LS	0.00	\$1,200.00	\$0.00
		0001	0110	6071013A	CHAIN-LINK FENCE (72 IN.)	40.00	0.00	40.00	LF	0.00	\$30.00	\$0.00
		0001	0120	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARRELS)	2.00	0.00	2.00	EA	0.00	\$4,250.00	\$0.00
		0001	0130	6122020	REPLACEMENT SAND BARREL	4.00	0.00	4.00	EA	0.00	\$482.00	\$0.00
		0001	0140	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	0.00	4.00	EA	1.00	\$8,000.00	\$8,000.00
		0001	0150	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	2,410.70	0.00	2,410.70	SQYD	1,591.50	\$235.00	\$374,002.50
		0001	0160	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	241.00	0.00	241.00	SQYD	0.00	\$5.00	\$0.00
		0001	0170	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	241.00	0.00	241.00	SQYD	0.00	\$15.00	\$0.00
		0001	0180	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	10,568.00	0.00	10,568.00	LF	6,429.00	\$8.25	\$53,039.25
		0001	0190	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	6,578.00	0.00	6,578.00	EA	2,304.00	\$3.50	\$8,064.00
		0001	0200	6161005	CONSTRUCTION SIGNS	1,915.00	0.00	1,915.00	SQFT	1,072.00	\$7.50	\$8,040.00
		0001	0210	6161008	ADVANCED WARNING RAIL SYSTEM	64.00	0.00	64.00	EA	26.00	\$35.00	\$910.00
		0001	0220	6161009	FLAG ASSEMBLY	16.00	0.00	16.00	EA	4.00	\$20.00	\$80.00
		0001	0230	6161025	CHANNELIZER (TRIM LINE)	334.00	0.00	334.00	EA	334.00	\$19.50	\$6,513.00
		0001	0240	6161033	DIRECTIONAL INDICATOR BARRICADE	56.00	0.00	56.00	EA	42.00	\$55.00	\$2,310.00
		0001	0250	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	4.00	\$850.00	\$3,400.00
		0001	0260	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED AND RETAINED)	4.00	0.00	4.00	EA	4.00	\$3,200.00	\$12,800.00
		0001	0270	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	692.00	0.00	692.00	LF	0.00	\$22.25	\$0.00
		0001	0280	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	692.00	0.00	692.00	LF	0.00	\$11.00	\$0.00
		0001	0290	6179903	MISC.CONCRETE MEDIAN BARRIER REPAIR	50.00	0.00	50.00	LF	57.00	\$420.00	\$23,940.00
		0001	0300	6179903	MISC.MODULAR GLARE FOIL ON TOP OF MEDIAN BARRIER	4,000.00	0.00	4,000.00	LF	0.00	\$23.00	\$0.00
		0001	0310	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$367,725.00	\$0.00
		0001	0311	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.50	\$321,848.00	\$160,924.00
		0001	0320	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	96,750.00	0.00	96,750.00	LF	13,335.00	\$0.21	\$2,800.35
		0001	0330	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	68,098.00	0.00	68,098.00	LF	0.00	\$0.21	\$0.00
		0001	0340	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	12,721.00	0.00	12,721.00	LF	0.00	\$1.00	\$0.00
		0001	0350	6209902	MISC.INLAID PAVEMENT MARKERS INSTALLATION	1,390.00	0.00	1,390.00	EA	0.00	\$20.00	\$0.00
		0001	0360	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	258,421.00	0.00	258,421.00	SQYD	187,302.50	\$3.70	\$693,019.25
		0001	0370	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	99.00	0.00	99.00	SQYD	0.00	\$10.00	\$0.00
		0001	0380	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	514.80	0.00	514.80	STA	0.00	\$46.00	\$0.00
		0001	0390	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$1,500.00	\$0.00
		0001	0400	7034001	CLASS B-1 CONCRETE	9.00	0.00	9.00	CUYD	0.00	\$1,000.00	\$0.00
		0010	0410	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	12,210.00	0.00	12,210.00	LF	0.00	\$24.00	\$0.00
		0010	0420	6061063	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	50.00	0.00	50.00	LF	0.00	\$38.00	\$0.00
		0010	0430	6061065	MGS GUARDRAIL, 6 FT. POSTS, 1 FT 6.75 IN. SPACING	21.00	0.00	21.00	LF	0.00	\$52.00	\$0.00

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190816-F01	J6I3195	0010	0440	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	12.00	0.00	12.00	EA	0.00	\$3,000.00	\$0.00
		0010	0450	6061074	MGS HEIGHT AND BLOCK TRANSITION	3.00	0.00	3.00	EA	0.00	\$700.00	\$0.00
		0010	0460	6061080	MGS END ANCHOR	19.00	0.00	19.00	EA	0.00	\$1,000.00	\$0.00
		0010	0470	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	24.00	0.00	24.00	EA	0.00	\$2,750.00	\$0.00
		0010	0480	6063018	TYPE D CRASHWORTHY END TERMINAL	2.00	0.00	2.00	EA	0.00	\$23,500.00	\$0.00
		0010	0490	6064100	MEDIAN GUARD CABLE 3 - STRAND	390.00	0.00	390.00	LF	0.00	\$12.00	\$0.00
		0010	0500	6064110	ANCHOR ASSEMBLY, GUARD CABLE 3-STRAND	2.00	0.00	2.00	EA	0.00	\$2,400.00	\$0.00
		0040	0510	9035011A	ST-STRUCTURAL	455.00	0.00	455.00	SQFT	0.00	\$27.00	\$0.00
		0040	0520	9035071A	STF-STRUCTURAL FLUORESCENT	51.00	0.00	51.00	SQFT	0.00	\$28.00	\$0.00
		0050	0530	9109903	MISC.MODOT ITS ASSETS RELOCATION	1,300.00	0.00	1,300.00	LF	0.00	\$13.10	\$0.00
		0001	5001	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$45,877.00	\$45,877.00
	Project J	J6I3195 - To	otal Value	Posted to D	ate as of Report Generated Date							\$3,531,580.33
190816-F01 Ove	rall - Tota	I Value Pos	ted to Da	te as of Rep	ort Generated Date							\$3,531,580.33



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details from Line Item agency views. No Agency View Details Exist



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
LINE	Description	Туре	Adjustment Type	Number	Date	By	Amount	rellidirs
0040	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	ACAD	8	Jun 17, 2020	gummer1	(\$14,611.04)	deduct of line 40 sp125 used in lieu of bp1
				9	Jul 1, 2020	gummer1	(\$40.40)	12.74 Tons for period 2 4.3 % cement content
				10	Jul 16, 2020	gummer1	(\$8,542.75)	adjustment for 2244.4 Tons at 3.5%
			ACAD - Tota	al			(\$23,194.19)	
	Other Item Adjustment - Total						(\$23,194.19)	
040 -	Total				_		(\$23,194.19)	
070	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Material		8	Jun 17, 2020	SYSTEM	(\$752,290.01)	
				8	Jun 17, 2020	SYSTEM	\$752,290.01	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user gummer1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				9	Jul 1, 2020	SYSTEM	(\$1,385,447.98)	
				9	Jul 1, 2020	SYSTEM	\$1,385,447.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user gummer1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				10	Jul 16, 2020	SYSTEM	(\$1,571,397.00)	
				10	Jul 16, 2020	SYSTEM	\$1,571,397.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user gummer1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				11	Aug 3, 2020	SYSTEM	(\$1,571,397.00)	
				11	Aug 3, 2020	SYSTEM	\$1,571,397.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user gummer1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total			_			\$0.00	
	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	Other Item Adjustment	ACAD	8	Jun 17, 2020	gummer1	(\$54,965.30)	for sp125 6.2%
				9	Jul 1, 2020	gummer1	(\$32,492.87)	7106.15 Tons AC 6.2%
				10	Jul 16, 2020	gummer1	(\$56,928.34)	Adjustment for 8443.21 Tons at 6.2 %
			ACAD - Tota	al			(\$144,386.51)	
	Other Item Adjustment - Total						(\$144,386.51)	
070 -	Total						(\$144,386.51)	
080	TACK COAT	Material		8	Jun 17, 2020	SYSTEM	(\$39,015.00)	
				8	Jun 17, 2020	SYSTEM	\$39,015.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user gummer1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				9	Jul 1, 2020	SYSTEM	(\$63,240.00)	
				9	Jul 1, 2020	SYSTEM	\$63,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user gummer1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				10	Jul 16, 2020	SYSTEM	(\$88,806.30)	
				10	Jul 16, 2020	SYSTEM	\$88,806.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user gummer1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				11	Aug 3, 2020	SYSTEM	(\$88,806.30)	
				11	Aug 3,	SYSTEM	\$88,806.30	This adjustment offsets the original system-generated Overrun



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
0080	TACK COAT	Material						Estimate.		
			- Total				\$0.00			
	Material - Total						\$0.00			
080 -	Total						\$0.00			
0150	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		4	Apr 17, 2020	SYSTEM	(\$27,894.50)			
				4	Apr 17, 2020	SYSTEM	\$27,894.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user gummer1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
				5	May 4, 2020	SYSTEM	(\$88,877.00)			
				5	May 4, 2020	SYSTEM	\$88,877.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user gummer1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
				6	May 18, 2020	SYSTEM	(\$188,681.50)			
				6	May 18, 2020	SYSTEM	\$188,681.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user gummer1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
				7	Jun 2, 2020	SYSTEM	(\$286,089.00)			
					7	Jun 2, 2020	SYSTEM	\$286,089.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user gummer1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				8	Jun 17, 2020	SYSTEM	(\$374,002.50)			
		8 Jun 17, SYSTEM 2020		\$374,002.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user gummer1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
						9	Jul 1, 2020	SYSTEM	(\$374,002.50)	
				9	Jul 1, 2020	SYSTEM	\$374,002.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user gummer1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
				10	Jul 16, 2020	SYSTEM	(\$374,002.50)			
				10	Jul 16, 2020	SYSTEM	\$374,002.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user gummer1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
				11	Aug 3, 2020	SYSTEM	(\$374,002.50)			
				11	Aug 3, 2020	SYSTEM	\$374,002.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user gummer1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
			- Total				\$0.00			
	Material - Total						\$0.00			
	Total					0.10	\$0.00			
190	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT	Material		4	Apr 17, 2020	SYSTEM	(\$910.00)			
	REPAIR			4	Apr 17, 2020	SYSTEM	\$910.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user gummer1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
				5	May 4, 2020	SYSTEM	(\$2,940.00)			
				5	May 4, 2020	SYSTEM	\$2,940.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user gummer1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
				6	May 18,	SYSTEM	(\$4,970.00)			



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0190	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		6	May 18, 2020	SYSTEM	\$4,970.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user gummer1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				7	Jun 2, 2020	SYSTEM	(\$6,601.00)	
				7	Jun 2, 2020	SYSTEM	\$6,601.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user gummer1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				8	Jun 17, 2020	SYSTEM	(\$8,064.00)	
				8	Jun 17, 2020	SYSTEM	\$8,064.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user gummer1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				9	Jul 1, 2020	SYSTEM	(\$8,064.00)	
				9	Jul 1, 2020	SYSTEM	\$8,064.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user gummer1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				10	Jul 16, 2020	SYSTEM	(\$8,064.00)	
				10	Jul 16, 2020	SYSTEM	\$8,064.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user gummer1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				11	Aug 3, 2020	SYSTEM	(\$8,064.00)	
				11	Aug 3, 2020	SYSTEM	\$8,064.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user gummer1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	Total						\$0.00	
0290	MISC. CONCRETE MEDIAN BARRIER REPAIR	Overrun	Overrun	9	Jul 1, 2020	SYSTEM	(\$2,940.00)	
			Overrun - T	otal			(\$2,940.00)	
	Overrun - Total						(\$2,940.00)	
	Total			-			(\$2,940.00)	
0300	MISC. MODULAR GLARE FOIL ON TOP OF MEDIAN BARRIER			5	May 4, 2020	SYSTEM	\$48,000.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$48,000.00	
	Construction Stockpile - Total						\$48,000.00	
	Total 6 IN. WHITE HIGH BUILD	Material		10	Jul 10	SYSTEM	\$48,000.00	
0320	WATERBORNE PAVEMENT	Material		10	Jul 16, 2020	STOTEM	(\$2,800.35)	
	MARKING PAINT, TYPE L BEADS			10	Jul 16, 2020	SYSTEM	\$2,800.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user gummer1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				11	Aug 3, 2020	SYSTEM	(\$2,800.35)	
				11	Aug 3, 2020	SYSTEM	\$2,800.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user gummer1 overridding Payment Estimate Exception 8 on the current Payment
					2020			Estimate.
			- Total		2020		\$0.00	
	Material - Total		- Total		2020		\$0.00	
0320 -	Total		- Total				\$0.00 \$0.00	Estimate.
0320 - 0410				2	Jan 16, 2020	SYSTEM	\$0.00 \$0.00 \$150,060.90	
	Total MGS GUARDRAIL, 8 FT. POSTS, 6		- Total	2	Jan 16,	SYSTEM	\$0.00 \$0.00	Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0410 -	Total						\$150,060.90	
0420	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	Construction Stockpile		2	Jan 16, 2020	SYSTEM	\$540.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$540.00	
	Construction Stockpile - Total						\$540.00	
0420 -	Total						\$540.00	
0430	MGS GUARDRAIL, 6 FT. POSTS, 1 FT 6.75 IN. SPACING	Construction Stockpile		2	Jan 16, 2020	SYSTEM	\$644.28	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$644.28	
	Construction Stockpile - Total						\$644.28	
0430 -	Total						\$644.28	
0440	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		2	Jan 16, 2020	SYSTEM	\$15,522.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$15,522.00	
	Construction Stockpile - Total						\$15,522.00	
0440 -	Total						\$15,522.00	
0450	MGS HEIGHT AND BLOCK TRANSITION	Construction Stockpile		2	Jan 16, 2020	SYSTEM	\$811.20	Payment Estimate Item Adjustment generated Stockpile Transaction
		1 .	- Total				\$811.20	
	Construction Stockpile - Total						\$811.20	
0450 -	Total						\$811.20	
0460	MGS END ANCHOR	Construction Stockpile		2	Jan 16, 2020	SYSTEM	\$10,108.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$10,108.00	
	Construction Stockpile - Total						\$10,108.00	
0460 -	Total						\$10,108.00	
0470	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		2	Jan 16, 2020	SYSTEM	\$36,240.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$36,240.00	
	Construction Stockpile - Total						\$36,240.00	
0470 -	Total						\$36,240.00	
0480	TYPE D CRASHWORTHY END TERMINAL	Construction Stockpile		5	May 4, 2020	SYSTEM	\$36,000.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$36,000.00	
	Construction Stockpile - Total						\$36,000.00	
0480 -	Total						\$36,000.00	
Overa	ll - Total						\$127,405.68	