

Progress Estima 10	ate Number	Contract ID 190920-D01 Prime Contractor N.B. West Contract		just 2, 2020 Original Contract Amou just 15, 2020 Net Change Order Amou Current Contract Amour	unt \$427,597.54
Approval Date					By User
August 18, 2020		Generated and	Approved (and should be considered	d Draft) at the Project Office Level by	shankb1
August 18, 2020		Reviewed and Appro	oved (and should be considered Dra	ft) at the Resident Engineer Level by	abbote1
August 19, 2020			Reviewed and Approved at the Cen	tral Office Controllers Office Level by	greggd1
Original Comp	letion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amoun	nt Complete
October 1	, 2020	October 1, 2020		89.35%	

No Milestones Exist for Contract

	y For Estimate No. 10			
		This Estimate	Previous	To Date
190920-D01				
	Total Posted Items Pay	\$45,872.60	\$2,114,601.86	\$2,160,474.46
	Gross Item Adjustments	(\$967.01)	(\$18,968.04)	(\$19,935.05)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$2,095,633.82	\$2,140,539.41
Contract Total Pa	yable This Estimate:	\$44,905.59		
ems Paid This Es	timate Period			

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount	
J5I3424	0280	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$7.300	12,398	\$90,505.40	
	0285	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	SQYD	\$3.600	-12,398	(\$44,632.80)	
Project J5	Project J5I3424 - Total							
Overall - Total								

Contract Adjustments This Estimate

	i i i i i i i i i i i i i i i i i i i	tments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5I3424	0040	TACK COAT	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-117	\$5.00	(\$585.00
	0040	TACK COAT	Material			-1,589	\$5.00	(\$7,945.00
	0040	TACK COAT	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 32 on the current Payment Estimate.	117	\$5.00	\$585.00
	0040	TACK COAT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1,589	\$5.00	\$7,945.00
	0040	TACK COAT	Other Item Adjustment	Overrun Re- adjustment	Overrun re-adjustment. System mistakenly returned payment on an overrun material. the overrun will be addressed in upcoming change order.			(\$585.00
	0100	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-3,590	\$12.25	(\$43,977.50
	0100	DOWEL BAR (DRILLING,	Material		This adjustment offsets the original system-	3,590	\$12.25	\$43,977.50



ogre		imate Number 0	Contract ID Prime Contra	190920- I ctor N.B. We		Pay Period StartAugust 2, 2020 Or g Company Pay Period End August 15, 2020 Ne Cu	t Change Or	der Amount	
ject iber	Line No.	Item Des	cription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
424		FURI INSTALLATIO DEPTH PAVEN				generated Overrun Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
	0110		LATION WITH (S) FOR FULL	Material			-336	\$9.25	(\$3,108.0
	0110		LATION WITH S) FOR FULL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	336	\$9.25	\$3,108.0
	0120	FURI INSTALLATIC DEPTH PAVEN		Material			-263	\$11.00	(\$2,893.0
	0120	FURI INSTALLATIC DEPTH PAVEN	R (DRILLING, NISHING AND DN) FOR FULL MENT REPAIR PE L JOINTS)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	263	\$11.00	\$2,893.0
	0160	CONSTRU	CTION SIGNS	Material			-750	\$9.00	(\$6,750.0
	0160	CONSTRU	CTION SIGNS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	750	\$9.00	\$6,750.0
	0170	ADVANCED W	ARNING RAIL SYSTEM	Material			-4	\$55.00	(\$220.0
	0170	ADVANCED W	ARNING RAIL SYSTEM	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	4	\$55.00	\$220.0
	0230			Material			-2	\$6,500.00	(\$13,000.0
	0230			Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	2	\$6,500.00	\$13,000.0
	0250	WATERBORN	E HIGH BUILD E PAVEMENT AINT, TYPE L BEADS	Material			-715,856	\$0.17	(\$121,695.5
	0250	WATERBORN	E HIGH BUILD E PAVEMENT AINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	715,856	\$0.17	\$121,695.5
	0260	6 IN. YELLOW WATERBORN MARKING P		Material			-674,105	\$0.27	(\$182,008.3



Progre		imate Number 0	Contract ID Prime Contra	190920- actorN.B. We		Pay Period StartAugust 2, 2020 Or g Company Pay Period End August 15, 2020 Ne CL	t Change Or	der Amount	
Project lumber	Line No.	Item Des	cription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
513424	0260	6 IN. YELLOW WATERBORN MARKING P		Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	674,105	\$0.27	\$182,008.35
	0270	WATERBORN	E HIGH BUILD E PAVEMENT AINT, TYPE L BEADS	Material			-10,637	\$1.00	(\$10,637.00
	0270	WATERBORN	E HIGH BUILD E PAVEMENT AINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0013) due to user shankb1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	10,637	\$1.00	\$10,637.00
	0287		E DRAINAGE GEOTEXTILE	Material			-499.8	\$3.20	(\$1,599.36
	0287		E DRAINAGE GEOTEXTILE	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0014) due to user shankb1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	499.8	\$3.20	\$1,599.36
	0290	MGS	GUARDRAIL	Material			-550	\$22.60	(\$12,430.00
	0290	MGS	GUARDRAIL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	550	\$22.60	\$12,430.00
	0300	MGS E	ND ANCHOR	Material			-1	\$1,100.00	(\$1,100.00
	0300	MGS E	END ANCHOR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0016) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	1	\$1,100.00	\$1,100.00
	5001	FURNISHING A CONCRETE M FULL DEPT		Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-1.67	\$228.75	(\$382.01
	5001	FURNISHING A CONCRETE M/ FULL DEPT		Material			-3,135.88	\$228.75	(\$717,332.55
	5001	FURNISHING A CONCRETE MA FULL DEPT		Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 33 on the current Payment Estimate.	1.67	\$228.75	\$382.01
	5001	FURNISHING A CONCRETE MA FULL DEPTI		Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	3,135.88	\$228.75	\$717,332.55
	5001	FURNISHING A CONCRETE MA FULL DEPTI		Other Item Adjustment	Overrun Re- adjustment	Overrun re-adjustment. System mistakenly returned payment on an overrun material. the overrun will be addressed in upcoming change order.			(\$382.01
	5002		MISC.	Material			-42.42	\$107.05	(\$4,541.06
	5002		MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0017) due to user shankb1	42.42	\$107.05	\$4,541.06



Progre		imate Number I0	Contract ID Prime Contra	190920- Ictor N.B. We		Pay Period Start August 2, 2020 Or Company Pay Period End August 15, 2020 Ne Cu	t Change Or	der Amount S	
Project Number	Line No.	Item Des	cription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5I3424						overridding Payment Estimate Exception 14 on the current Payment Estimate.			
Total									(\$967.01)



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J5I3424	I-44-2(321)	Pavement repair	I-44	PHELPS	across entire Pulaski/Phe	elps/Crawford and a section i	n Laclede County
Totals by .	Job Numbers	6					
J5I3424		Item Pay tem Adjustme		Item Pay	This Estimate \$45,872.60 (\$967.01) \$44,905.59	Previous \$2,114,601.86 (\$18,968.04) \$2,095,633.82	To Date \$2,160,474.46 (\$19,935.05) \$2,140,539.41
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 4071005, Project Item Line Number 0040, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6061060, Project Item Line Number 0290, Material Set 606106096, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6061080, Project Item Line Number 0300, Material Set 6061080, Material 1040GRBEESCAT2 - Breakaway End Anchor End Sect CI A Typ 2, Acceptance Action Generic 1040GRBEESCAT2 is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6131010, Project Item Line Number 0060, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6131010, Project Item Line Number 0060, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6131010, Project Item Line Number 5001, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6131010, Project Item Line Number 5001, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6131010, Project Item Line Number 5001, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6131015, Project Item Line Number 0100, Material Set 6131015, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6131017, Project Item Line Number 0110, Material Set 6131017, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6131018, Project Item Line Number 0120, Material Set 6131018, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6131018, Project Item Line Number 0120, Material Set 6131018, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6131018, Project Item Line Number 0120, Material Set 6131018, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6139905, Project Item Line Number 5002, Material Set 613990596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6139905, Project Item Line Number 5002, Material Set 613990596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6139905, Project Item Line Number 5002, Material Set 613990596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6161005, Project Item Line Number 0160, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6161008, Project Item Line Number 0170, Material Set 6161008, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6161099, Project Item Line Number 0230, Material Set 6161099, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6205902A, Project Item Line Number 0250, Material Set 6205902A96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6205902A, Project Item Line Number 0250, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6205902A, Project Item Line Number 0250, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6205903A, Project Item Line Number 0260, Material Set 6205903A96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6205903A, Project Item Line Number 0260, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L	No Remark was entered by Engineer	shankb1	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J5/3424, Item 6205903A, Project Item Line Number 0260, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3424, Item 6205906A, Project Item Line Number 0270, Material Set 6205906A96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5/3424, Item 6205906A, Project Item Line Number 0270, Material Set 6205906A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5/3424, Item 6205906A, Project Item Line Number 0270, Material Set 6205906A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5/3424, Item 6240101A, Project Item Line Number 0287, Material Set 6240101A96, Material 1011GXT1 - Geotextile Fabric for SubsrfDrainage(T1), Acceptance Action Generic 1011GXT1 is insufficient.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Item Overrun: Contract 190920-D01, Contract Project J5I3424, Project Item Line Number 0090, Contract Line Item Number 0090, Item 6131014, Minor Item.	No Remark was entered by Engineer	shankb1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 190920-D01, Contract Project J5I3424, Project Item Line Number 0020, Contract Line Item Number 0020, Item 4011209, Minor Item.	No Remark was entered by Engineer	shankb1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 190920-D01, Contract Project J5I3424, Project Item Line Number 0040, Contract Line Item Number 0040, Item 4071005, Minor Item.	No Remark was entered by Engineer	shankb1	Overridden
Estimate Exception Type: Item Overrun: Contract 190920-D01, Contract Project J5I3424, Project Item Line Number 5001, Contract Line Item Number 5001, Item 6131010, Minor Item.	No Remark was entered by Engineer	shankb1	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
920-D01	J5I3424	0001	0005	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$3,750.00	\$3,750.0
		0001	0010	2153000	SHAPING SLOPES, CLASS III	6.00	0.00	6.00	100F	6.00	\$1,295.00	\$7,770.0
		0001	0020	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	427.20	0.00	427.20	TONS	449.00	\$114.00	\$51,186.0
		0001	0025	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	106.50	0.00	106.50	TONS	23.00	\$585.00	\$13,455.0
		0001	0030	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	1,233.60	-1,233.60	0.00	TONS	0.00	\$125.00	\$0.
		0001	0035	4030217	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP190B MIX)	1,409.80	554.40	1,964.20	TONS	1,964.20	\$105.00	\$206,241.
		0001	0040	4071005	TACK COAT	1,472.00	0.00	1,472.00	GAL	1,589.00	\$5.00	\$7,945.
		0001	0045	6057000	AGGREGATE DRAIN	1,660.00	0.00	1,660.00	LF	750.00	\$25.50	\$19,125.
		0001	0050	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$5,000.00	\$0.
		0001	0060	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	1,431.70	-1,431.70	0.00	SQYD	0.00	\$239.25	\$0.
		0001	0070	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	144.00	0.00	144.00	SQYD	0.00	\$10.00	\$0.
		0001	0080	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	144.00	0.00	144.00	SQYD	0.00	\$10.00	\$0.
		0001	0090	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	3,637.00	7,661.00	11,298.00	LF	11,298.50	\$11.00	\$124,283
		0001	0100	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	1,936.00	1,654.00	3,590.00	EA	3,590.00	\$12.25	\$43,977
		0001	0110	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	99.00	264.00	363.00	EA	336.00	\$9.25	\$3,108
		0001	0120	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	105.00	173.00	278.00	EA	263.00	\$11.00	\$2,893
		0001	0130	6134001	DOWEL BAR RETROFIT	24.00	0.00	24.00	EA	0.00	\$180.00	\$0
		0001	0140	6139903	MISC.SAW CUT (LONGITUDINAL)	81,523.00	0.00	81,523.00	LF	79,348.00	\$1.75	\$138,859
		0001	0150	6139903	MISC.SAW CUT (TRANSVERSE)	84,283.00	0.00	84,283.00	LF	82,045.00	\$1.75	\$143,578
		0001 0160 6161005		6161005	CONSTRUCTION SIGNS	967.00	0.00	967.00	SQFT	750.00	\$9.00	\$6,750
		0001	0170	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$55.00	\$220
		0001	0180	6161009	FLAG ASSEMBLY	14.00	0.00	14.00	EA	0.00	\$20.00	\$0
		0001	0190	6161010	RELOCATED SIGNS	180.00	0.00	180.00	SQFT	0.00	\$5.00	\$0
		0001	0200	6161024	CHANNELIZER (TRIM LINE) WITH LIGHT	100.00	100.00 0.00	100.00	EA	0.00	\$20.00	\$0
		0001	0210	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	0.00	\$900.00	\$0
		0001	0220	6161055	SEQUENTIAL FLASHING WARNING LIGHT	30.00	0.00	30.00	EA	0.00	\$90.00	\$0
		0001	0230	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$6,500.00	\$13,000
		0001	0240	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$198,000.00	\$198,000
		0001	0250	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,120,903.00	0.00	1,120,903.00	LF	715,856.00	\$0.17	\$121,695
		0001	0260	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	886,697.00	0.00	886,697.00	LF	674,105.00	\$0.27	\$182,008
		0001	0270	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	37,319.00	0.00	37,319.00	LF	10,637.00	\$1.00	\$10,637
		0001	0280	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	5,486.00	11,265.90	16,751.90	SQYD	16,751.90	\$7.30	\$122,288
		0001	0285	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	12,914.00	-12,914.00	0.00	SQYD	0.00	\$3.60	\$0
		0001	0287	6240101A		799.00	0.00	799.00	SQYD	499.80	\$3.20	\$1,599
		0010	0290	6061060	MGS GUARDRAIL	550.00	0.00	550.00	LF	550.00	\$22.60	\$12,430
		0010	0300	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	1.00	\$1,100.00	\$1,100
		0010	0310	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	1.00	0.00	1.00	EA	1.00	\$2,700.00	\$2,700
		0001	5001	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	0.00	3,134.21	3,134.21	SQYD	3,135.88	\$228.75	\$717,332
		0001	5002	6139905	MISC.Misc Partial Depth Concrete Shoulder Repair	0.00	42.42	42.42	SQYD	42.42	\$107.05	\$4,541
	Destant			Destad to D	Date as of Report Generated Date							\$2,160,47



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project:	oject: J5I3424												
Line Number	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments	
0280	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	8/14/20	8/17/20	12,398.00	SQYD	I-44 Pulaski Climbing lanes	167.0					
0285	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REM	8/14/20	8/17/20	-12,398.00	SQYD	Correcting Quantities.	.1					

The information below this line are details from Line Item agency views. No Agency View Details Exist



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0020	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	ACAD	8	Jul 17, 2020	shankb1	(\$1,885.80)	449.0 tons x .04 x (397.5-502.5) = -\$1885.80
			ACAD - Tota	al			(\$1,885.80)	
	Other Item Adjustment - Total						(\$1,885.80)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Overrun	Overrun	8	Jul 17, 2020	SYSTEM	(\$2,445.39)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			Overrun - T	otal			(\$2,445.39)	
	Overrun - Total						(\$2,445.39)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Price		8	Jul 17, 2020	SYSTEM	(\$819.87)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$819.87)	
	Price - Total						(\$819.87)	
0020 -	Total						(\$5,151.06)	
0025	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	ACAD	8	Jul 17, 2020	shankb1	(\$94.19)	23 tons x 0.039 (397.5-502.5) = -\$94.19
			ACAD - Tota	al			(\$94.19)	
	Other Item Adjustment - Total						(\$94.19)	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Price		8	Jul 17, 2020	SYSTEM	(\$42.00)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$42.00)	
	Price - Total						(\$42.00)	
0025 -	Total						(\$136.19)	
0035	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP190B MIX)	Other Item Adjustment	ACAD	8	Jul 17, 2020	shankb1	(\$8,249.64)	1964.2 tons x 0.04 x (397.5-5025) = -\$8249.64
			ACAD - Tota	al			(\$8,249.64)	
	Other Item Adjustment - Total						(\$8,249.64)	
	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP190B MIX)	Overrun	Overrun	8	Jul 17, 2020	SYSTEM	(\$57,199.67)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				9	Aug 2, 2020	SYSTEM	\$57,199.67	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',103.17401 - 105.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP190B MIX)	Price		8	Jul 17, 2020	SYSTEM	(\$3,586.63)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$3,586.63)	
	Price - Total						(\$3,586.63)	
0035 -	Total						(\$11,836.27)	
0040	TACK COAT	Material		8	Jul 17, 2020	SYSTEM	(\$7,850.00)	
				8	Jul 17, 2020	SYSTEM	\$7,850.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				9	Aug 2, 2020	SYSTEM	(\$7,945.00)	
				9	Aug 2, 2020	SYSTEM	\$7,945.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$7,945.00)	
				10	Aug 18, 2020	SYSTEM	\$7,945.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TACK COAT	Other Item Adjustment	OADJ	9	Aug 2, 2020	shankb1	(\$585.00)	The system mistakenly returned an overrun adjustment for this line item. The overrun will



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0040	TACK COAT	Other Item Adjustment	OADJ	10	Aug 18, 2020	shankb1	(\$585.00)	Overrun re-adjustment. System mistakenly returned payment on an overrun material. the overrun will be addressed in upcoming change order.
			OADJ - Tota	al			(\$1,170.00)	
	TACK COAT		OVRN	8	Jul 17, 2020	shankb1	(\$490.00)	The system mistakenly returned an overrun adjustment for this line item. The overrun will be addressed in a upcoming change order.
			OVRN - Tota	al			(\$490.00)	
	Other Item Adjustment - Total						(\$1,660.00)	
	TACK COAT	Overrun	Overrun		Jul 17, 2020	SYSTEM	(\$490.00)	
				8	Jul 17, 2020	SYSTEM	\$490.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) overridding Payment Estimate Exception 33 on the current Payment Estimate.
				9	Aug 2, 2020	SYSTEM	(\$490.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				9	Aug 2, 2020	SYSTEM	(\$95.00)	
				9	Aug 2, 2020	SYSTEM	\$95.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 32 on the current Payment Estimate.
				9	Aug 2, 2020	SYSTEM	\$490.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 32 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$585.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				10	Aug 17, 2020	SYSTEM	\$585.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 32 on the current Payment Estimate.
		otal			\$0.00			
	Overrun - Total					\$0.00		
0040 -	Total						(\$1,660.00)	
0060	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		1	Apr 3, 2020	SYSTEM	(\$18,443.78)	
				2	Apr 17, 2020	SYSTEM	(\$227,203.76)	
				2	Apr 17, 2020	SYSTEM	\$227,203.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				(\$18,443.78)	
	Material - Total						(\$18,443.78)	
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	MaterialCredit		2	Apr 17, 2020	SYSTEM	\$18,443.78	
			- Total				\$18,443.78	
	MaterialCredit - Total		- Total				\$18,443.78 \$18,443.78	
	MaterialCredit - Total FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Other Item Adjustment	- Total OTHR	2	Apr 17, 2020	shankb1		REVERSING MATERIAL CREDIT
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL					shankb1	\$18,443.78	REVERSING MATERIAL CREDIT
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL		OTHR			shankb1 shankb1	\$18,443.78 (\$18,443.78)	REVERSING MATERIAL CREDIT
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL		OTHR	al	2020 Apr 3,		\$18,443.78 (\$18,443.78) (\$18,443.78)	REVERSING MATERIAL CREDIT
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL		OTHR OTHR - Tota	al	2020 Apr 3,		\$18,443.78 (\$18,443.78) (\$18,443.78) \$18,443.78	REVERSING MATERIAL CREDIT
0060 -	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR Other Item Adjustment - Total		OTHR OTHR - Tota	al	2020 Apr 3,		\$18,443.78 (\$18,443.78) (\$18,443.78) \$18,443.78 \$18,443.78	REVERSING MATERIAL CREDIT
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR Other Item Adjustment - Total Total FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL		OTHR OTHR - Tota	al 1	2020 Apr 3,		\$18,443.78 (\$18,443.78) (\$18,443.78) \$18,443.78 \$18,443.78 \$18,443.78	REVERSING MATERIAL CREDIT
0060 - 0090	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR Other Item Adjustment - Total Total FULL DEPTH PAVEMENT REPAIR SAW	Adjustment	OTHR OTHR - Tota	al 1	2020 Apr 3, 2020 May 19,	shankb1	\$18,443.78 (\$18,443.78) (\$18,443.78) \$18,443.78 \$18,443.78 \$18,443.78 \$0.00	REVERSING MATERIAL CREDIT REVERSING MATERIAL CREDIT This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user shankb1 overridding Payment Estimate Exception 18 on the current Payment Estimate.



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks												
LINC	Description	Туре	Adjustment Type		Date	By	Amount	Relians												
090	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL	Overrun	Overrun					overridding Payment Estimate Exception 18 on the current Payment Estimate.												
	SAW CUTS)			4	May 19, 2020	SYSTEM	\$4,724.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 18 on the current Payment Estimate.												
				5	Jun 2, 2020	SYSTEM	(\$5.50)													
			Overrun - T	otal			(\$5.50)													
	Overrun - Total						(\$5.50)													
090 -	Total						(\$5.50)													
0100	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		1	Apr 3, 2020	SYSTEM	(\$1,470.00)													
				2	Apr 17, 2020	SYSTEM	(\$10,290.00)													
				2	Apr 17, 2020	SYSTEM	\$10,290.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.												
				3	May 4, 2020	SYSTEM	(\$24,377.50)													
				3	May 4, 2020	SYSTEM	\$24,377.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.												
				4	May 19, 2020	SYSTEM	(\$36,750.00)													
				4	May 19, 2020	SYSTEM	\$36,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.												
				5	Jun 2, 2020	SYSTEM	(\$43,977.50)													
				5	Jun 2, 2020	SYSTEM	\$43,977.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.												
				6	Jun 16, 2020	SYSTEM	(\$43,977.50)													
				6	Jun 16, 2020	SYSTEM	\$43,977.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.												
				7	Jul 2, 2020	SYSTEM	(\$43,977.50)													
										7	Jul 2, 2020	SYSTEM	\$43,977.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
																	8	Jul 17, 2020	SYSTEM	(\$43,977.50)
																	8	Jul 17, 2020	SYSTEM	\$43,977.50
								9	Aug 2, 2020	SYSTEM	(\$43,977.50)									
				9	Aug 2, 2020	SYSTEM	\$43,977.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.												
				10	Aug 17, 2020	SYSTEM	(\$43,977.50)													
				10	Aug 18, 2020	SYSTEM	\$43,977.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.												
			- Total				(\$1,470.00)													
	Material - Total						(\$1,470.00)													



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
0100	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	MaterialCredit	,	2	Apr 17, 2020	SYSTEM	\$1,470.00													
			- Total				\$1,470.00													
	MaterialCredit - Total						\$1,470.00													
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Other Item Adjustment	OADJ	4	May 19, 2020	shankb1	(\$2,695.50)	System mistakenly returned pay for quantity overrun. This adjustment will be reversed when pending change order is approved. 220 x 12.25 = \$2695.00 shankb1												
			OADJ - Tota	ป			(\$2,695.50)													
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR		OTHR	2	Apr 17, 2020	shankb1	(\$1,470.00)	REVERSING MATERIAL CREDIT												
				5	Jun 2, 2020	shankb1	\$2,695.50	With CO 0002 Approval, this is reversing the withholdings from Estimate 0004.												
			OTHR - Tota	al			\$1,225.50													
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR			1	Apr 3, 2020	shankb1	\$1,470.00													
			- Total				\$1,470.00													
	Other Item Adjustment - Total						\$0.00													
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Overrun	Overrun	4	May 19, 2020	SYSTEM	(\$2,695.00)													
	PAVEMENT REPAIR			4	May 19, 2020	SYSTEM	\$1,102.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 19 on the current Payment Estimate.												
				4	May 19, 2020	SYSTEM	\$1,592.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 19 on the current Payment Estimate.												
			Overrun - To	otal			\$0.00													
	Overrun - Total						\$0.00													
0100 -	Total						\$0.00													
0110	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material		2	Apr 17, 2020	SYSTEM	(\$915.75)													
				2	Apr 17, 2020	SYSTEM	\$915.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.												
				3	May 4, 2020	SYSTEM	(\$2,053.50)													
				3	May 4, 2020	SYSTEM	\$2,053.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.												
				4	May 19, 2020	SYSTEM	(\$2,830.50)													
				4	May 19, 2020	SYSTEM	\$2,830.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.												
				5	Jun 2, 2020	SYSTEM	(\$3,108.00)													
				5	Jun 2, 2020	SYSTEM	\$3,108.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.												
				6	Jun 16, 2020	SYSTEM	(\$3,108.00)													
				6	Jun 16, 2020	SYSTEM	\$3,108.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.												
				7	Jul 2, 2020	SYSTEM	(\$3,108.00)													
																7	Jul 2, 2020	SYSTEM	\$3,108.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0110	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR	Material		8	Jul 17, 2020	SYSTEM	(\$3,108.00)	
	FULL DEPTH PAVEMENT REPAIR			8	Jul 17, 2020	SYSTEM	\$3,108.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				9	Aug 2, 2020	SYSTEM	(\$3,108.00)	
				9	Aug 2, 2020	SYSTEM	\$3,108.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$3,108.00)	
				10	Aug 18, 2020	SYSTEM	\$3,108.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Other Item Adjustment	OADJ	4	May 19, 2020	shankb1	(\$721.50)	System mistakenly returned pay for quantity overrun. This adjustment will be reversed when pending change order is approved. 78 x 9.25 = \$721.50 shankb1
			OADJ - Tota	al			(\$721.50)	
	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR		OTHR	5	Jun 2, 2020	shankb1	\$721.50	With CO 0002 Approval, this is reversing the withholdings from Estimate 0004.
	OTHR - Total						\$721.50	
	Other Item Adjustment - Total	Overrun					\$0.00	
	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Overrun	Overrun		May 19, 2020	SYSTEM	(\$721.50)	
				4	May 19, 2020	SYSTEM	\$333.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 20 on the current Payment Estimate.
				4	May 19, 2020	SYSTEM	\$388.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 20 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0110 - 0120	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		2	Apr 17, 2020	SYSTEM	\$0.00 (\$990.00)	
	PAVEMENT REPAIR (TYPE L JOINTS)			2	Apr 17, 2020	SYSTEM	\$990.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				3	May 4, 2020	SYSTEM	(\$2,046.00)	
				3	May 4, 2020	SYSTEM	\$2,046.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				4	May 19, 2020	SYSTEM	(\$2,486.00)	
				4	May 19, 2020	SYSTEM	\$2,486.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$2,893.00)	
			5	5	Jun 2, 2020	SYSTEM	\$2,893.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				6	Jun 16, 2020	SYSTEM	(\$2,893.00)	



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	2000.p.ion	Туре	Adjustment Type		Date	Ву	, ano ant	
0120	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material		6	Jun 16, 2020	SYSTEM	\$2,893.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				7	Jul 2, 2020	SYSTEM	(\$2,893.00)	
				7	Jul 2, 2020	SYSTEM	\$2,893.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				8	Jul 17, 2020	SYSTEM	(\$2,893.00)	
				8	Jul 17, 2020	SYSTEM	\$2,893.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				9	Aug 2, 2020	SYSTEM	(\$2,893.00)	
				9	Aug 2, 2020	SYSTEM	\$2,893.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$2,893.00)	
				10	Aug 18, 2020	SYSTEM	\$2,893.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total				_		\$0.00	
	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)		OADJ	4	May 19, 2020	shankb1	(\$440.00)	System mistakenly returned pay for quantity overrun. This adjustment will be reversed when pending change order is approved. $40 \times \$11.00 = \440.00 shankb1
			OADJ - Tota	al			(\$440.00)	
	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)		OTHR		Jun 2, 2020	shankb1	\$440.00	With CO 0002 Approval, this is reversing the withholdings from Estimate 0004.
			OTHR - Tota	al			\$440.00	
	Other Item Adjustment - Total						\$0.00	
	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Overrun	Overrun	4	May 19, 2020	SYSTEM	(\$440.00)	
	TIE BAR (DRILLING, FURNISHING AND	Overrun	Overrun	4		SYSTEM SYSTEM	(\$440.00) \$209.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 21 on the current Payment Estimate.
	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Overrun		4	2020 May 19, 2020		\$209.00 \$231.00	Payment Estimate Item Adjustment (0010) overridding Payment
	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Overrun	Overrun Overrun - T	4	2020 May 19, 2020 May 19,	SYSTEM	\$209.00 \$231.00 \$0.00	Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment
	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Overrun		4	2020 May 19, 2020 May 19,	SYSTEM	\$209.00 \$231.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment
0120 -	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) Overrun - Total			4 4 otal	2020 May 19, 2020 May 19,	SYSTEM SYSTEM	\$209.00 \$231.00 \$0.00	Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment
0120 - 0160	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)			4	2020 May 19, 2020 May 19,	SYSTEM	\$209.00 \$231.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment
	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) Overrun - Total			4 4 otal	2020 May 19, 2020 May 19, 2020	SYSTEM SYSTEM	\$209.00 \$231.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment
	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) Overrun - Total			4 4 otal	2020 May 19, 2020 May 19, 2020 Apr 3, 2020 Apr 17,	SYSTEM SYSTEM SYSTEM	\$209.00 \$231.00 \$0.00 \$0.00 \$0.00 (\$3,024.00)	Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment
	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) Overrun - Total			4 4 otal	2020 May 19, 2020 May 19, 2020 Apr 19, 2020 Apr 3, 2020 Apr 17, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$209.00 \$231.00 \$0.00 \$0.00 (\$3,024.00) (\$6,750.00)	Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 21 on the current Payment Estimate.
	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) Overrun - Total			4 4 00tal	2020 May 19, 2020 May 19, 2020 Apr 3, 2020 Apr 3, 2020 Apr 17, 2020 Apr 17, 2020 May 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$209.00 \$231.00 \$0.00 \$0.00 (\$3,024.00) (\$6,750.00) \$6,750.00	Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 21 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
0160	CONSTRUCTION SIGNS	Material		4	May 19, 2020	SYSTEM	\$6,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user shankb1 overridding Payment Estimate Exception 15 on the current Payment Estimate.		
				5	Jun 2, 2020	SYSTEM	(\$6,750.00)			
				5	Jun 2, 2020	SYSTEM	\$6,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 16 on the current Payment Estimate.		
							6	Jun 16, 2020	SYSTEM	(\$6,750.00)
				6	Jun 16, 2020	SYSTEM	\$6,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 16 on the current Payment Estimate.		
				7	Jul 2, 2020	SYSTEM	(\$6,750.00)			
				7	Jul 2, 2020	SYSTEM	\$6,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 16 on the current Payment Estimate.		
				8	Jul 17, 2020	SYSTEM	(\$6,750.00)			
				8	Jul 17, 2020	SYSTEM	\$6,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment Estimate Exception 17 on the current Payment Estimate.		
				9	Aug 2, 2020	SYSTEM	(\$6,750.00)			
				9	Aug 2, 2020	SYSTEM	\$6,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 17 on the current Payment Estimate.		
				10	Aug 17, 2020	SYSTEM	(\$6,750.00)			
					10	Aug 18, 2020	SYSTEM	\$6,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
			- Total		1		(\$3,024.00)			
	Material - Total						(\$3,024.00)			
	CONSTRUCTION SIGNS	MaterialCredit		2	Apr 17, 2020	SYSTEM	\$3,024.00			
			- Total				\$3,024.00			
	MaterialCredit - Total						\$3,024.00			
	CONSTRUCTION SIGNS	Other Item Adjustment	OTHR	2	Apr 17, 2020	shankb1	(\$3,024.00)	REVERSING MATERIAL CREDIT		
			OTHR - Tota	al			(\$3,024.00)			
	CONSTRUCTION SIGNS			1	Apr 3, 2020	shankb1	\$3,024.00			
			- Total				\$3,024.00			
	Other Item Adjustment - Total						\$0.00			
	Total						\$0.00			
)170	ADVANCED WARNING RAIL SYSTEM	Material		2	Apr 17, 2020	SYSTEM	(\$220.00)			
				2	Apr 17, 2020	SYSTEM	\$220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		
				3	May 4, 2020	SYSTEM	(\$220.00)			
				3	May 4, 2020	SYSTEM	\$220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 14 on the current Payment Estimate.		



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
0170	ADVANCED WARNING RAIL SYSTEM	Material		4	May 19, 2020	SYSTEM	\$220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user shankb1 overridding Payment Estimate Exception 16 on the current Payment Estimate.			
				5	Jun 2, 2020	SYSTEM	(\$220.00)				
				5	Jun 2, 2020	SYSTEM	\$220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 17 on the current Payment Estimate.			
						6	Jun 16, 2020	SYSTEM	(\$220.00)		
				6	Jun 16, 2020	SYSTEM	\$220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 17 on the current Payment Estimate.			
				7	Jul 2, 2020	SYSTEM	(\$220.00)				
							7	Jul 2, 2020	SYSTEM	\$220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				8	Jul 17, 2020	SYSTEM	(\$220.00)				
				8	Jul 17, 2020	SYSTEM	\$220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 18 on the current Payment Estimate.			
				9	Aug 2, 2020	SYSTEM	(\$220.00)				
				9	Aug 2, 2020	SYSTEM	\$220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment Estimate Exception 18 on the current Payment Estimate.			
					10	Aug 17, 2020	SYSTEM	(\$220.00)			
				10	Aug 18, 2020	SYSTEM	\$220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 18 on the current Payment Estimate.			
			- Total				\$0.00				
	Material - Total						\$0.00				
0170 - 0230	Total CHANGEABLE MESSAGE SIGN WITH	Material		2	Apr 17,	SYSTEM	\$0.00 (\$13,000.00)				
	COMMUNICATION INTERFACE, CONTRACTOR FURNISHED,				2020						
	CONTRACTOR RETAINED			2	Apr 17, 2020	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.			
				3	May 4, 2020	SYSTEM	(\$13,000.00)				
				3	May 4, 2020	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 15 on the current Payment Estimate.			
				4	May 19, 2020	SYSTEM	(\$13,000.00)				
				4	May 19, 2020	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user shankb1 overridding Payment Estimate Exception 17 on the current Payment Estimate.			
				5	Jun 2, 2020	SYSTEM	(\$13,000.00)				
				5	Jun 2, 2020	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 18 on the current Payment Estimate.			
				6	Jun 16, 2020	SYSTEM	(\$13,000.00)				
				6	Jun 16,	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Overrun			



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks			
		туре	Туре	Number	Date	Бу					
0230	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED,	Material			2020			Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 18 on the current Payment Estimate.			
	CONTRACTOR RETAINED			7	Jul 2, 2020	SYSTEM	(\$13,000.00)				
				7	Jul 2, 2020	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 18 on the current Payment Estimate.			
				8	Jul 17, 2020	SYSTEM	(\$13,000.00)				
				8	Jul 17, 2020	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user shankb1 overridding Payment Estimate Exception 19 on the current Payment Estimate.			
				9	Aug 2, 2020	SYSTEM	(\$13,000.00)				
				9	Aug 2, 2020	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 19 on the current Payment Estimate.			
				10	Aug 17, 2020	SYSTEM	(\$13,000.00)				
				10	Aug 18, 2020	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 19 on the current Payment Estimate.			
			- Total				\$0.00				
	Material - Total						\$0.00				
0230 -	Total						\$0.00				
0250	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING	Material		6	Jun 16, 2020	SYSTEM	(\$39,245.35)				
	PAINT, TYPE L BEADS			6	Jun 16, 2020	SYSTEM	\$39,245.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 19 on the current Payment Estimate.			
				7	Jul 2, 2020	SYSTEM	(\$121,695.52)				
				7	Jul 2, 2020	SYSTEM	\$121,695.52	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 19 on the current Payment Estimate.			
				8	Jul 17, 2020	SYSTEM	(\$121,695.52)				
				8	Jul 17, 2020	SYSTEM	\$121,695.52	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user shankb1 overridding Payment Estimate Exception 20 on the current Payment Estimate.			
				9	Aug 2, 2020	SYSTEM	(\$121,695.52)				
							9	Aug 2, 2020	SYSTEM	\$121,695.52	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user shankb1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$121,695.52)				
				10	Aug 18, 2020	SYSTEM	\$121,695.52	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment Estimate Exception 20 on the current Payment Estimate.			
			- Total				\$0.00				
	Material - Total						\$0.00				
0250 -	Total						\$0.00				
0260	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING	Material		6	Jun 16, 2020	SYSTEM	(\$119,527.11)				
	PAINT, TYPE L BEADS			6	Jun 16, 2020	SYSTEM	\$119,527.11	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 22 on the current Payment Estimate.			



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0260	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING	Material		7	Jul 2, 2020	SYSTEM	(\$182,008.35)	
	PAINT, TYPE L BEADS			7	Jul 2, 2020	SYSTEM	\$182,008.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				8	Jul 17, 2020	SYSTEM	(\$182,008.35)	
				8	Jul 17, 2020	SYSTEM	\$182,008.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				9	Aug 2, 2020	SYSTEM	(\$182,008.35)	
				9	Aug 2, 2020	SYSTEM	\$182,008.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user shankb1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$182,008.35)	
				10	Aug 18, 2020	SYSTEM	\$182,008.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
260 -	- Total						\$0.00	
0270	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING			6	Jun 16, 2020	SYSTEM	(\$1,657.00)	
	PAINT, TYPE L BEADS			6	Jun 16, 2020	SYSTEM	\$1,657.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				7	Jul 2, 2020	SYSTEM	(\$10,637.00)	
				7	Jul 2, 2020	SYSTEM	\$10,637.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				8	Jul 17, 2020	SYSTEM	(\$10,637.00)	
				8	Jul 17, 2020	SYSTEM	\$10,637.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user shankb1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				9	Aug 2, 2020	SYSTEM	(\$10,637.00)	
				9	Aug 2, 2020	SYSTEM	\$10,637.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$10,637.00)	
				10	Aug 18, 2020	SYSTEM	\$10,637.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user shankb1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
270 -	Total						\$0.00	
287	SUBSURFACE DRAINAGE GEOTEXTILE	Material		5	Jun 2, 2020	SYSTEM	(\$1,599.36)	
				5	Jun 2, 2020	SYSTEM	\$1,599.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				6	Jun 16, 2020	SYSTEM	(\$1,599.36)	
				6	Jun 16,	SYSTEM	\$1,599.36	This adjustment offsets the original system-generated Overrun



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks												
		Type	Туре	Number	Date	Dy														
0287	SUBSURFACE DRAINAGE GEOTEXTILE	Material			2020			Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 28 on the current Payment Estimate.												
				7	Jul 2, 2020	SYSTEM	(\$1,599.36)													
				7	Jul 2, 2020	SYSTEM	\$1,599.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 28 on the current Payment Estimate.												
				8	Jul 17, 2020	SYSTEM	(\$1,599.36)													
				8	Jul 17, 2020	SYSTEM	\$1,599.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 29 on the current Payment Estimate.												
				9	Aug 2, 2020	SYSTEM	(\$1,599.36)													
				9	Aug 2, 2020	SYSTEM	\$1,599.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user shankb1 overridding Payment Estimate Exception 29 on the current Payment Estimate.												
				10	Aug 17, 2020	SYSTEM	(\$1,599.36)													
				10	Aug 18, 2020	SYSTEM	\$1,599.36	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user shankb1 overridding Payment Estimate Exception 29 on the current Payment Estimate.												
			- Total				\$0.00													
	Material - Total						\$0.00													
0287 -	Total						\$0.00													
0290	MGS GUARDRAIL	Material		4	May 19, 2020	SYSTEM	(\$12,430.00)													
				4	May 19, 2020	SYSTEM	\$12,430.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.												
														5	Jun 2, 2020	SYSTEM	(\$12,430.00)			
				5	Jun 2, 2020	SYSTEM	\$12,430.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.												
																6	Jun 16, 2020	SYSTEM	(\$12,430.00)	
															6	Jun 16, 2020	SYSTEM	\$12,430.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				7	Jul 2, 2020	SYSTEM	(\$12,430.00)													
																7	Jul 2, 2020	SYSTEM	\$12,430.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				8	Jul 17, 2020	SYSTEM	(\$12,430.00)													
														8	Jul 17, 2020	SYSTEM	\$12,430.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
				9	Aug 2, 2020	SYSTEM	(\$12,430.00)													
																9	Aug 2, 2020	SYSTEM	\$12,430.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$12,430.00)													
				10	Aug 18, 2020	SYSTEM	\$12,430.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user shankb1												



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
0290	MGS GUARDRAIL	Material	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					overridding Payment Estimate Exception 2 on the current Payment Estimate.										
			- Total				\$0.00											
	Material - Total						\$0.00											
0290 ·	- Total						\$0.00											
0300	MGS END ANCHOR	Material		4	May 19, 2020	SYSTEM	(\$1,100.00)											
				4	May 19, 2020	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
				5	Jun 2, 2020	SYSTEM	(\$1,100.00)											
				5	Jun 2, 2020	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
				6	Jun 16, 2020	SYSTEM	(\$1,100.00)											
				6	Jun 16, 2020	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
				7	Jul 2, 2020	SYSTEM	(\$1,100.00)											
				7	Jul 2, 2020	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
				8	Jul 17, 2020	SYSTEM	(\$1,100.00)											
										8	Jul 17, 2020	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.				
				9	Aug 2, 2020	SYSTEM	(\$1,100.00)											
				9	Aug 2, 2020	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
				10	Aug 17, 2020	SYSTEM	(\$1,100.00)											
				10	Aug 18, 2020	SYSTEM	\$1,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
			- Total				\$0.00											
	Material - Total						\$0.00											
0300 -	- Total						\$0.00											
5001	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL	Material		3	May 4, 2020	SYSTEM	(\$436,882.76)											
	DEPTH PAVEMENT REPAIR													3	May 4, 2020	SYSTEM	\$436,882.76	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				4	May 19, 2020	SYSTEM	(\$639,136.65)											
				4	May 19, 2020	SYSTEM	\$639,136.65	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
				5	Jun 2, 2020	SYSTEM	(\$717,332.55)											
			5	Jun 2, 2020	SYSTEM	\$717,332.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.											
				6	Jun 16,	SYSTEM	(\$717,332.55)											



•	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1	FURNISHING AND PLACING	Material			2020			
	CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR			6	Jun 16, 2020	SYSTEM	\$717,332.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				7	Jul 2, 2020	SYSTEM	(\$717,332.55)	
				7	Jul 2, 2020	SYSTEM	\$717,332.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				8	Jul 17, 2020	SYSTEM	(\$717,332.55)	
				8	Jul 17, 2020	SYSTEM	\$717,332.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user shankbr overridding Payment Estimate Exception 6 on the current Payment Estimate.
				9	Aug 2, 2020	SYSTEM	(\$717,332.55)	
				9	Aug 2, 2020	SYSTEM	\$717,332.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user shankb overridding Payment Estimate Exception 6 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$717,332.55)	
				10	Aug 18, 2020	SYSTEM	\$717,332.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user shankb overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Other Item Adjustment	OADJ	4	May 19, 2020	shankb1	(\$55,824.15)	System mistakenly returned pay for quantity overrun. This adjustment will be reversed when pending change order is approved. 244.04 sq. yd. x \$228.75 = \$55824.15 shankb1
				9	Aug 2, 2020	shankb1	(\$382.01)	The system mistakenly returned an overrun adjustment for this line item. The overrun will be addressed in a upcoming change order.
				10	Aug 18, 2020	shankb1	(\$382.01)	Overrun re-adjustment. System mistakenly returned payment of an overrun material. the overrun will be addressed in upcoming change order.
			OADJ - Tota	al			(\$56,588.17)	
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR		OTHR	5	Jun 2, 2020	shankb1	\$55,824.15	With CO 0002 Approval, this is reversing the withholdings from Estimate 0004.
			OTHR - Tota	al			\$55,824.15	
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR		OVRN	8	Jul 17, 2020	shankb1	(\$382.01)	The system mistakenly returned an overrun adjustment for this line item. The overrun will be addressed in a upcoming change order
		OVRN - Tot	al			(\$382.01)		
	Other Item Adjustment - Total						(\$1,146.03)	
	FURNISHING AND PLACING Overru CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Overrun	Overrun		May 19, 2020	SYSTEM	(\$55,824.15)	
				4	May 19, 2020	SYSTEM	\$33,646.84	This adjustment offsets the original system-generated Overrur Payment Estimate Item Adjustment (0013) overridding Payme Estimate Exception 22 on the current Payment Estimate.
				4	May 19, 2020	SYSTEM	\$22,177.31	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 22 on the current Payment Estimate.
						O) (OTEN	(\$382.01)	
				5	Jun 2, 2020	SYSTEM	(\$302.01)	
				5		SYSTEM	\$382.01	
					2020 Jun 2,		. ,	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Paymen Estimate Exception 21 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payn estimates of '0.00000' is applied (if non-zero).



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5001	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Overrun	Overrun					Estimate Exception 30 on the current Payment Estimate.
				7	Jul 2, 2020	SYSTEM	(\$382.01)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				7	Jul 2, 2020	SYSTEM	\$382.01	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 30 on the current Payment Estimate.
				8	Jul 17, 2020	SYSTEM	(\$382.01)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				8	Jul 17, 2020	SYSTEM	\$382.01	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) overridding Payment Estimate Exception 34 on the current Payment Estimate.
				9	Aug 2, 2020	SYSTEM	(\$382.01)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				9	Aug 2, 2020	SYSTEM	\$382.01	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 33 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$382.01)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				10	Aug 17, 2020	SYSTEM	\$382.01	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 33 on the current Payment Estimate.
		Overrun - T	otal			\$0.00		
	Overrun - Total						\$0.00	
5001 -	Total						(\$1,146.03)	
5002	MISC. Misc Partial Depth Concrete Shoulder Repair	Material		5	Jun 2, 2020	SYSTEM	(\$4,541.06)	
				5	Jun 2, 2020	SYSTEM	\$4,541.06	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user shankb1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				6	Jun 16, 2020	SYSTEM	(\$4,541.06)	
				6	Jun 16, 2020	SYSTEM	\$4,541.06	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				7	Jul 2, 2020	SYSTEM	(\$4,541.06)	
				7	Jul 2, 2020	SYSTEM	\$4,541.06	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				8	Jul 17, 2020	SYSTEM	(\$4,541.06)	
				8	Jul 17, 2020	SYSTEM	\$4,541.06	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user shankb1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				9	Aug 2, 2020	SYSTEM	(\$4,541.06)	
				9	Aug 2, 2020	SYSTEM	\$4,541.06	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user shankb1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$4,541.06)	
				10	Aug 18, 2020	SYSTEM	\$4,541.06	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user shankb1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
5002 -	Total						\$0.00	
Overa	ll - Total						(\$19,935.05)	