

Pay Estimate Created Date: May 15, 2020

ate Number	Contract ID Prime Contractor	190920-H02 Magruder Paving, LLC	Pay Period Start Pay Period End	May 2, 2020 May 15, 2020	Original Contract Amount Net Change Order Amount Current Contract Amount	\$2,441,948.14 \$0.00 \$2,441,948.14			
						By User			
	Generated and Approved (and should be considered Draft) at the Project Office Level by								
	Rev	viewed and Approved (a	nd should be conside	ered Draft) at the	e Resident Engineer Level by	PULLIA			
		Review	ed and Approved at	the Central Offic	ce Controllers Office Level by	greggd1			
letion Date	Current Comp	letion Date Ad	tual Completion Da	ite	% of Current Contract Amour	it Complete			
1, 2020	November	1, 2020			98.66%				
	letion Date	Prime Contractor Rev letion Date Current Comp	Prime Contractor Magruder Paving, LLC Generated and Approve Reviewed and Approved (and Reviewed and Approved (and Reviewed and Approved (and Reviewed and R	Prime Contractor Magruder Paving, LLC Pay Period End Generated and Approved (and should be considered and Approved (and should be considered and Approved (and should be considered and Approved A	Prime Contractor Magruder Paving, LLC Pay Period End May 15, 2020 Generated and Approved (and should be considered Draft) Reviewed and Approved at the Central Office Letion Date	Prime Contractor Magruder Paving, LLC Pay Period End May 15, 2020 Net Change Order Amount Current Contract Amount Generated and Approved (and should be considered Draft) at the Project Office Level by Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by Reviewed and Approved and Approved at the Central Office Controllers Office Level by Reviewed and Approved at the Central Office Controllers Office Level by Reviewed and Approved at the Central Office Controllers Office Level by Reviewed and Approved at the Central Office Controllers Office Level by			

No Milestones Exist for Contract

Contract Total Pay For Estimate No. 5				
	This Estimate	Previous	To Date	
190920-H02				
Total Posted Items Pay	\$161,967.10	\$2,247,180.02	\$2,409,147.12	
Gross Item Adjustments	(\$2,246.13)	(\$86,942.07)	(\$89,188.20)	
Incentive	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Liquidated Damage	\$0.00	\$0.00	\$0.00	
Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
-		\$2,160,237.95	\$2,319,958.92	
Contract Total Payable This Estimate:	\$159,720.97			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9P3413	0100	6181000	MOBILIZATION	LS	\$78,300.000	1	\$78,300.00
Project J9P3	413 - Total						\$78,300.00
J9P3446	0180	3105002	GRAVEL (A) OR CRUSHED STONE (B)	TONS	\$103.290	55	\$5,680.95
	0190	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	TONS	\$76.440	396.8	\$30,331.39
	0200	4071005	TACK COAT	GAL	\$1.940	294	\$570.36
	0270	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	EA	\$9,000.000	1	\$9,000.00
	0275	6181000	MOBILIZATION	LS	\$28,800.000	1	\$28,800.00
	0300	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	LF	\$1.800	1,033	\$1,859.40
	0340	6207001	PAVEMENT MARKING REMOVAL	LF	\$1.000	1,500	\$1,500.00
	0400	9028500	CABLE, LOOP DETECTOR, IN DUCT	LF	\$7.900	750	\$5,925.00
Project J9P3	446 - Total						\$83,667.10
Overall - Tot	al						\$161,967.10

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9P3413	0030	GRAVEL (A) OR CRUSHED STONE (B)	Material			-90	\$85.48	(\$7,693.20
	0030	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user wilesr overridding Payment Estimate Exception 1 on the current Payment Estimate.	90	\$85.48	\$7,693.20
	0040	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-76.2	\$63.80	(\$4,861.56
	0040	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user wilesr overridding Payment Estimate Exception 17	76.2	\$63.80	\$4,861.56



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 15, 2020

Prog	ress Es	timate Number 5	Contract II Prime Con		920-H02 gruder Paving	Pay Period Start , LLC Pay Period End	May 2, 2020 May 15, 2020	Original Contract Net Change Orde Current Contract	er Amount	\$2,441,948.14 \$0.00 \$2,441,948.14
Project Number	Line No.	Item Descr	iption	Adjustment Type	Other Item Adjustment Type	Commer	nts	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9P3413						on the curren	t Payment Estii	mate.		
	0110	4 IN. WHITE WATERBORNE MARKING PAI	PAVEMENT	Material				-155,755	\$0.10	(\$15,575.50)
	0110	4 IN. WHITE WATERBORNE MARKING PAI	PAVEMENT	Material		This adjustment offsets generated Overrun Pay Adjustment (000 overridding Payment Estin the curren	yment Estimate 6) due to user v	e Item wilesr i 6 on	\$0.10	\$15,575.50
	0120	4 IN. YELLOW WATERBORNE MARKING PAI	PAVEMENT	Material				-155,050	\$0.10	(\$15,505.00)
	0120	4 IN. YELLOW WATERBORNE MARKING PAI	PAVEMENT	Material		This adjustment offsets generated Overrun Pay Adjustment (000 overridding Payment Estin the curren	yment Estimate 7) due to user v	e Item wilesr i 9 on	\$0.10	\$15,505.00
J9P3446	0180	GRAVEL (A) OF	CRUSHED STONE (B)	Material				-55	\$103.29	(\$5,680.95)
	0180	GRAVEL (A) OF	CRUSHED STONE (B)	Material		This adjustment offsets generated Overrun Pay Adjustment (000 overridding Payment Estin the curren	yment Estimate 8) due to user v	e Item wilesr i 2 on	\$103.29	\$5,680.95
	0190	BITUMINOUS MIXTUI (SURFACE	RE PG64-22	Price		Reference Item Pri Adjustment T	ce Adjustment ype applied is I		(\$3.02)	(\$1,198.58)
	0190		PAVEMENT RE PG64-22 LEVELING)	Overrun		Reference Item Pri Adjustment T	ce Adjustment ype applied is I		\$73.42	(\$18,942.20)
	0190		PAVEMENT RE PG64-22 LEVELING)	Material				-13,082.7	\$76.44	(\$1,000,041.59)
	0190		PAVEMENT RE PG64-22 LEVELING)	Overrun		This adjustment offsets generated Overrun Pay Adjustment (0002) of Estimate Exception 18 on	yment Estimate overridding Pay the current Pay	e Item vment	\$73.42	\$18,942.20
	0190		PAVEMENT RE PG64-22 LEVELING)	Material		This adjustment offsets generated Overrun Pay Adjustment (000 overridding Payment Estin the curren	yment Estimate 3) due to user v	e Item wilesr i 3 on	\$76.44	\$1,000,041.59
	0190		PAVEMENT RE PG64-22 LEVELING)	Other Item Adjustment		396.8 tons of surfa	ace level 3.2%	virgin		(\$1,047.55)
	0300	TEMPORARY R MARKING	EMOVABLE TAPE 4 IN., WHITE	Material				-2,066	\$1.80	(\$3,718.80)
	0300	0300 TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE WHITE MARKING TAPE 4 IN., WHITE WHITE WHITE WHITE MADE AND ADDRESS AND ADDR				e Item wilesr 14 on	\$1.80	\$3,718.80		
	0310 TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE					-20	\$10.00	(\$200.00)		



Pay Estimate Created Date: May 15, 2020

Progr	ress Es	timate Number 5	Contract II Prime Con		920-H02 Jruder Paving	, LLC Pay Period End May 15, 2020 Net	ginal Contract Change Orde rent Contract	r Amount	\$2,441,948.14 \$0.00 \$2,441,948.14	
Project Number	Line No.	Item Description Adjustment Type Other Item Comments Adjustment Type						Adjustment Line Item Quantity Adjustmen Unit Price		
J9P3446	0310		EMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE WHITE MARKING TAPE, 24 IN., WHITE MATUR					\$10.00	\$200.00	
	0400	CABLE, LOOP D	ETECTOR, IN DUCT	Material			-750	\$7.90	(\$5,925.00	
	0400	CABLE, LOOP D	ETECTOR, IN DUCT	Material		This adjustment offsets the original system generated Overrun Payment Estimate Iten Adjustment (0011) due to user wiles overridding Payment Estimate Exception 16 on the current Payment Estimate	ו ר ל	\$7.90	\$5,925.00	
	0410	CURB E	BLOCKOUT	Material			-875	\$74.00	(\$64,750.00	
	0410	CURB E	BLOCKOUT	Material		This adjustment offsets the original system generated Overrun Payment Estimate Iten Adjustment (0012) due to user wiles overridding Payment Estimate Exception 12 on the current Payment Estimate	1 r 2	\$74.00	\$64,750.00	
Total									(\$2,246.13	



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J9P3413	FAF 19-1(13)	Resurface	19	SHANNON	from Route A to Riverview Drive
J9P3446	FAF 32-2(28)	Resurface	32	TEXAS	from Route 17 to Route 63

Totals by Job Numbers

3413	This Estimate	Previous	To Date
Posted Item Pay	\$78,300.00	\$1,105,774.35	\$1,184,074.35
Gross Item Adjustments	\$0.00	(\$46,276.15)	(\$46,276.15)
Gross Item Pay	\$78,300.00	\$1,059,498.20	\$1,137,798.20
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
	\$0.00	\$0.00	\$0.00
Liquidated Damages Other Contract Adjustments	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	φ0.00	\$0.00	\$0.00
3446	This Estimate	Previous	To Date
	The Lounder		
Posted Item Pav	\$83.667.10	\$1.141.405.67	\$1.225.072.77
Posted Item Pay Gross Item Adjustments	\$83,667.10 (\$2,246.13)	\$1,141,405.67 (\$40,665.92)	\$1,225,072.77 (\$42,912.05)
Gross Item Adjustments Gross Item Pay	(\$2,246.13) \$81,420.97	(\$40,665.92) \$1,100,739.75	(\$42,912.05) \$1,182,160.72
Gross Item Adjustments Gross Item Pay Incentive	(\$2,246.13) \$81,420.97 \$0.00	(\$40,665.92) \$1,100,739.75 \$0.00	(\$42,912.05) \$1,182,160.72 \$0.00
Gross Item Adjustments Gross Item Pay Incentive Disincentive	(\$2,246.13) \$81,420.97 \$0.00 \$0.00	(\$40,665.92) \$1,100,739.75 \$0.00 \$0.00	(\$42,912.05) \$1,182,160.72 \$0.00 \$0.00
Gross Item Adjustments Gross Item Pay Incentive	(\$2,246.13) \$81,420.97 \$0.00	(\$40,665.92) \$1,100,739.75 \$0.00	(\$42,912.05) \$1,182,160.72 \$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 3105002, Project Item Line Number 0030, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 3105002, Project Item Line Number 0180, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 4020520, Project Item Line Number 0190, Material Set 402052096, Material 0402SLPMSL - Plant Mix for Surface Leveling, Acceptance Action Generic AspSL is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6205301B, Project Item Line Number 0300, Material Set 6205301B96, Material 1048PMT - Marking Tape, Acceptance Action Generic 1048PMT is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 6205309, Project Item Line Number 0310, Material Set 620530996, Material 1048PMT - Marking Tape, Acceptance Action Generic 1048PMT is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 6206000C, Project Item Line Number 0110, Material Set 6206000C96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 6206000C, Project Item Line Number 0110, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 6206000C, Project Item Line Number 0110, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 6206001C, Project Item Line Number 0120, Material Set 6206001C96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 6206001C, Project Item Line Number 0120, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3413, Item 6206001C, Project Item Line Number 0120, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 7034600, Project Item Line Number 0410, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 7034600, Project Item Line Number 0410, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 7034600, Project Item Line Number 0410, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 7034600, Project Item Line Number 0410, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Insufficient Materials: Project J9P3446, Item 9028500, Project Item Line Number 0400, Material Set 902850096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Material OK	WILESR	Overridden
Estimate Exception Type: Item Overrun: Contract 190920-H02, Contract Project J9P3413, Project Item Line Number 0040, Contract Line Item Number 0040, Item 4020520, Minor Item.	Change order in progress	WILESR	Overridden
Estimate Exception Type: Item Overrun: Contract 190920-H02, Contract Project J9P3446, Project Item Line Number 0190, Contract Line Item Number 0190, Item 4020520, Minor Item.	Override for this exception was system generated due to greater item withholding on other pay estimate exceptions.	WILESR	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

	uantities				eport Generated date and can differ from the posted amo	ount at the	ime the I	Estimate wa	s Gener	ated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190920-H02	J9P3413	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$2,400.00	\$2,400.00
		0001	0020	2129900	MISC.MODIFIED SHAPING SLOPES, CLASS III	2.00	0.00	2.00	100F	2.00	\$1,600.00	\$3,200.00
		0001	0030	3105002	GRAVEL (A) OR CRUSHED STONE (B)	90.00	0.00	90.00	TONS	90.00	\$85.48	\$7,693.20
		0001	0040	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	15,178.00	0.00	15,178.00	TONS	15,254.20	\$63.80	\$973,217.96
		0001	0050	4071005	TACK COAT	19,356.00	0.00	19,356.00	GAL	16,405.00	\$1.94	\$31,825.70
		0001	0060	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0070	6161005	CONSTRUCTION SIGNS	1,967.00	0.00	1,967.00	SQFT	1,434.00	\$6.50	\$9,321.00
		0001	0080	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	4.00	\$20.00	\$80.00
		0001	0090	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	100.00	\$18.00	\$1,800.00
		0001	0100	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$78,300.00	\$78,300.00
		0001	0110	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	194,694.00	0.00	194,694.00	LF	155,755.00	\$0.10	\$15,575.50
		0001	0120	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	193,812.00	0.00	193,812.00	LF	155,050.00	\$0.10	\$15,505.00
		0001	0130	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	2,409.00	0.00	2,409.00	SQYD	2,409.00	\$6.20	\$14,935.80
		0001	0140	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,477.00	0.00	1,477.00	SQYD	1,477.00	\$6.47	\$9,556.19
		0010	0150	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	488.00	0.00	488.00	LF	488.00	\$28.00	\$13,664.00
		0010	0160	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00
		9P3413 - To	otal Value		ate as of Report Generated Date							\$1,184,074.35
	J9P3446	0001	0170	2129900	MISC.MODIFIED SHAPING SLOPES, CLASS III	4.00	0.00	4.00	100F	4.00	\$1,600.00	\$6,400.00
		0001	0180	3105002	GRAVEL (A) OR CRUSHED STONE (B)	55.00	0.00	55.00	TONS	55.00	\$103.29	\$5,680.95
		0001	0190	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	12,824.70	0.00	12,824.70	TONS	13,082.70	\$76.44	\$1,000,041.59
		0001	0200	4071005	TACK COAT	15,880.00	0.00	15,880.00	GAL	13,566.00	\$1.94	\$26,318.04
		0001	0210	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0220	6161005	CONSTRUCTION SIGNS	1,958.00	0.00	1,958.00	SQFT	1,469.00	\$6.50	\$9,548.50
		0001	0230	6161008	ADVANCED WARNING RAIL SYSTEM	6.00	0.00	6.00	EA	6.00	\$35.00	\$210.00
		0001	0240	6161009	FLAG ASSEMBLY	6.00	0.00	6.00	EA	6.00	\$20.00	\$120.00
		0001	0250	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	100.00	\$18.00	\$1,800.00
		0001	0260	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000.00
		0001	0270	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$9,000.00	\$9,000.00
		0001	0275	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$28,800.00	\$28,800.00
		0001	0280	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	30.00	0.00	30.00	LF	0.00	\$25.00	\$0.00
		0001	0290	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	3.00	0.00	3.00	EA	0.00	\$275.00	\$0.00
		0001	0300	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	2,066.00	0.00	2,066.00	LF	2,066.00	\$1.80	\$3,718.80
		0001	0310	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	20.00	0.00	20.00	LF	20.00	\$10.00	\$200.00
		0001	0320	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	165,671.00	0.00	165,671.00	LF	0.00	\$0.10	\$0.00
		0001	0330	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	146,148.00	0.00	146,148.00	LF	0.00	\$0.10	\$0.00
		0001	0340	6207001	PAVEMENT MARKING REMOVAL	1,500.00	0.00	1,500.00	LF	1,500.00	\$1.00	\$1,500.00
		0001	0350	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,335.00	0.00	1,335.00	SQYD	1,335.00	\$6.63	\$8,851.05
		0001	0360	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,924.00	0.00	1,924.00	SQYD	1,924.00	\$5.41	\$10,408.84
		0010	0370	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	350.00	0.00	350.00	LF	350.00	\$32.00	\$11,200.00
		0010	0380	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$3,200.00	\$12,800.00
		0010	0390	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	4.00	\$3,200.00	\$12,800.00
		0030	0400	9028500	CABLE, LOOP DETECTOR, IN DUCT	750.00	0.00	750.00	LF	750.00	\$7.90	\$5,925.00
		0070	0410	7034600	CURB BLOCKOUT	875.00	0.00	875.00	LF	875.00	\$74.00	\$64,750.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Q	ote: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.											
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
190920-H02	Project J	9P3446 - To	tal Value	Posted to D	ate as of Report Generated Date							\$1,225,072.77
190920-H02 Ove	190920-H02 Overall - Total Value Posted to Date as of Report Generated Date										\$2,409,147.12	



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9P3413

Line Number	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	e Sta	o tion/ og lile	Offset/ Distance	Comments
0100	6181000	MOBILIZATION	5/14/20	5/14/20	1.00	LS	nobilization						
Project:	J9P3446												
Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	Fro Station Mil	n/Log Dis	ffset/ stance	To Station/ Log Mile	Offset/ Distance	Comments
0180	3105002	GRAVEL (A) OR CRUSHED STONE (B)	5/11/20	5/14/20	55.00	TONS	various driveways and county roads	va	rious				
0190	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	5/2/20	5/14/20	396.80	TONS	various driveways and co. roads.	va	rious				
0200	4071005	TACK COAT	5/2/20	5/14/20	294.00	GAL	various entrances and county roads	va	rious				
0270	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	5/14/20	5/14/20	1.00	EA	temporary signals for curb blockout						
0275	6181000	MOBILIZATION	5/11/20	5/14/20	1.00	LS	mobilization	mobiliz	ation				
0300	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN.,	5/14/20	5/14/20	1,033.00	LF	temp centerline for bridge work						
0340	6207001	PAVEMENT MARKING REMOVAL	5/11/20	5/14/20	1,500.00	LF	lane closure and temp signal at bridge over Big Piney	b	ridge				
0400	9028500	CABLE, LOOP DETECTOR, IN DUCT	5/6/20	5/14/20	750.00	LF	63/32 intersection	interse	63/32 ection				

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0030	GRAVEL (A) OR CRUSHED STONE (B)	Material	.)	4	May 3, 2020	SYSTEM	(\$7,693.20)	
				4	May 3, 2020	SYSTEM	\$7,693.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user wilesr overridding Payment Estimate Exception 1 on the current Payment Estimate.
				5	May 15, 2020	SYSTEM	(\$7,693.20)	
				5	May 15, 2020	SYSTEM	\$7,693.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user wilesr overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0030 -	Total						\$0.00	
0040	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material		2	Apr 2, 2020	SYSTEM	(\$162,581.54)	
				2	Apr 2, 2020	SYSTEM	\$162,581.54	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user wilesr overridding Payment Estimate Exception 1 on the current Payment Estimate.
				3	Apr 15, 2020	SYSTEM	(\$973,217.96)	
				3	Apr 15, 2020	SYSTEM	\$973,217.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user wilesr overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total				_		\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	ACAD	2	Apr 2, 2020	WILESR	(\$3,261.82)	AC Adjust for 2548.3 tons of surface level at 3.2% virgin oil. Mix SL20-8 $$
				3	Apr 15, 2020	WILESR	(\$16,263.55)	12,705.9 tons of surface level 3.2% virgin AC
			ACAD - Tot	- Total			(\$19,525.37)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)		FUEL	4	May 3, 2020	WILESR	(\$2,284.30)	Fuel Adjustment for Asphalt laid on 3/31 and 4/1. Manual adjust. due to system not applying the adjust on est 002
				4	May 3, 2020	WILESR	(\$24,466.48)	Fuel Adjustment for asphalt laid 4/2 thru 4/15. system did not apply fuel adjustment on est 003
			FUEL - Tota	I			(\$26,750.78)	
	Other Item Adjustment - Total						(\$46,276.15)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Overrun	Overrun		Apr 15, 2020	SYSTEM	(\$4,861.56)	
				3	Apr 15, 2020	SYSTEM	\$4,861.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 9 on the current Payment Estimate.
				4	May 3, 2020	SYSTEM	(\$4,861.56)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				4	May 3, 2020	SYSTEM	\$4,861.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user wilesr overridding Payment Estimate Exception 15 on the current Payment Estimate.
			5	May 15, 2020	SYSTEM	(\$4,861.56)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
				5	May 15, 2020	SYSTEM	\$4,861.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user wilesr overridding Payment Estimate Exception 17 on the current Payment Estimate.
	Overrun - Total						\$0.00	
	Overrun - Total						\$0.00	
0040 -	Total						(\$46,276.15)	
0050	TACK COAT	Material		2	Apr 2, 2020	SYSTEM	(\$5,794.78)	
			2	Apr 2, 2020	SYSTEM	\$5,794.78	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user wilesr overridding Payment Estimate Exception 2 on the current Payment Estimate.	
				3	Apr 15, 2020	SYSTEM	(\$31,825.70)	
				3	Apr 15, 2020	SYSTEM	\$31,825.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user wilesr overridding Payment Estimate Exception 2 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0050		Material	- Total				\$0.00	
	Material - Total						\$0.00	
050 -	Total						\$0.00	
0110	4 IN. WHITE STANDARD Material WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		4	May 3, 2020	SYSTEM	(\$15,575.50)	
				4	May 3, 2020	SYSTEM	\$15,575.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.
				5	May 15, 2020	SYSTEM	(\$15,575.50)	
				5	May 15, 2020	SYSTEM	\$15,575.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
110 -	Total						\$0.00	
120	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT TYPE P	Material		4	May 3, 2020	SYSTEM	(\$15,505.00)	
	MARKING PAINT, TYPE P BEADS			4	May 3, 2020	SYSTEM	\$15,505.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user wilesr overridding Payment Estimate Exception 8 on the current Payment Estimate.
				5	May 15, 2020	SYSTEM	(\$15,505.00)	
				5	May 15, 2020	SYSTEM	\$15,505.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user wilesr overridding Paymen Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
120 -	Total						\$0.00	
180	GRAVEL (A) OR CRUSHED Ma STONE (B)	Material	erial	5	May 15, 2020	SYSTEM	(\$5,680.95)	
					May 15, 2020	SYSTEM	\$5,680.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user wilesr overridding Paymen Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
180 -	Total						\$0.00	
190	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material		4	May 3, 2020	SYSTEM	(\$969,710.20)	
				4	May 3, 2020	SYSTEM	\$969,710.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user wilesr overridding Paymen Estimate Exception 2 on the current Payment Estimate.
				5	May 15, 2020	SYSTEM	(\$1,000,041.59)	
				5	May 15, 2020	SYSTEM	\$1,000,041.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user wilesr overridding Paymen Estimate Exception 3 on the current Payment Estimate.
		- Total	- Total			\$0.00		
	Material - Total						\$0.00	
		Other Item Adjustment	ACAD	4	May 3, 2020	WILESR	(\$16,237.95)	12685.9 tons of Surface Level 3.2% virgin
				5	May 15, 2020	WILESR	(\$1,047.55)	396.8 tons of surface level 3.2% virgin
			ACAD - Tot	al			(\$17,285.50)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)		FUEL	4	May 3, 2020	WILESR	(\$24,427.97)	Fuel Adjustment for Asphalt laid 4/16 to 5/1
			FUEL - Tota	ıl			(\$24,427.97)	
	Other Item Adjustment - Total						(\$41,713.47)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Overrun	Overrun	5	May 15, 2020	SYSTEM	(\$18,942.20)	Reference Item Price Adjustment Index Adjustment Type applied is FUE
								This adjustment offsets the original system-generated Overrun Payment



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0190	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Overrun	Overrun					18 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		5	May 15, 2020	SYSTEM	(\$1,198.58)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$1,198.58)	
	Price - Total						(\$1,198.58)	
	· Total						(\$42,912.05)	
0300	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		2	Apr 2, 2020	SYSTEM	(\$1,859.40)	
				2	Apr 2, 2020	SYSTEM	\$1,859.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate.
				3	Apr 15, 2020	SYSTEM	(\$1,859.40)	
				3	Apr 15, 2020	SYSTEM	\$1,859.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate.
				4	May 3, 2020	SYSTEM	(\$1,859.40)	
				4	May 3, 2020	SYSTEM	\$1,859.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 3 on the current Payment Estimate.
				5	May 15, 2020	SYSTEM	(\$3,718.80)	
				5	May 15,	SYSTEM	\$3,718.80	This adjustment offsets the original system-generated Overrun Payment
					2020			Estimate Item Adjustment (0009) due to user wilesr overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total		2020		\$0.00	
	Material - Total		- Total		2020		\$0.00	
	- Total		- Total				\$0.00 \$0.00	
0300 - 0310		Material	- Total	2	Apr 2, 2020	SYSTEM	\$0.00 \$0.00 (\$200.00)	Estimate Exception 4 on the current Payment Estimate.
	Total TEMPORARY REMOVABLE	Material	- Total	2 2	Apr 2,	SYSTEM	\$0.00 \$0.00	
	Total TEMPORARY REMOVABLE	Material	- Total		Apr 2, 2020 Apr 2,		\$0.00 \$0.00 (\$200.00)	Estimate Exception 4 on the current Payment Estimate.
	Total TEMPORARY REMOVABLE	Material	- Total	2	Apr 2, 2020 Apr 2, 2020 Apr 15,	SYSTEM	\$0.00 \$0.00 (\$200.00) \$200.00	Estimate Exception 4 on the current Payment Estimate.
	Total TEMPORARY REMOVABLE	Material	- Total	2 3	Apr 2, 2020 Apr 2, 2020 Apr 15, 2020 Apr 15,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$200.00) \$200.00 (\$200.00)	Estimate Exception 4 on the current Payment Estimate.
	Total TEMPORARY REMOVABLE	Material	- Total	2 3 3	Apr 2, 2020 Apr 2, 2020 Apr 15, 2020 Apr 15, 2020 May 3,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$200.00) \$200.00 (\$200.00) \$200.00	Estimate Exception 4 on the current Payment Estimate.
	Total TEMPORARY REMOVABLE	Material	- Total	2 3 3 4	Apr 2, 2020 Apr 2, 2020 Apr 15, 2020 Apr 15, 2020 May 3, 2020 May 3,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$200.00) \$200.00 (\$200.00) \$200.00 (\$200.00)	Estimate Exception 4 on the current Payment Estimate.
	Total TEMPORARY REMOVABLE	Material		2 3 3 4 4	Apr 2, 2020 Apr 2, 2020 Apr 15, 2020 Apr 15, 2020 May 3, 2020 May 3, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$200.00) \$200.00 (\$200.00) \$200.00 (\$200.00) \$200.00	Estimate Exception 4 on the current Payment Estimate.
	Total TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material	- Total	2 3 3 4 4 5	Apr 2, 2020 Apr 2, 2020 Apr 15, 2020 Apr 15, 2020 May 3, 2020 May 3, 2020 May 3, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$200.00) \$200.00 (\$200.00) \$200.00 (\$200.00) \$200.00 (\$200.00)	Estimate Exception 4 on the current Payment Estimate.
0310	Total TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material		2 3 3 4 4 5	Apr 2, 2020 Apr 2, 2020 Apr 15, 2020 Apr 15, 2020 May 3, 2020 May 3, 2020 May 3, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$200.00) \$200.00 (\$200.00) \$200.00 \$200.00 (\$200.00) \$200.00	Estimate Exception 4 on the current Payment Estimate.
0310	Total TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE Material - Total Total			2 3 3 4 4 5 5 5	Apr 2, 2020 Apr 2, 2020 Apr 15, 2020 Apr 15, 2020 May 3, 2020 May 3, 2020 May 15, 2020 May 15, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$200.00) \$200.00 (\$200.00) \$200.00 (\$200.00) \$200.00 \$200.00 \$200.00 \$200.00 \$200.00 \$200.00	Estimate Exception 4 on the current Payment Estimate.
0310	Total TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE			2 3 3 4 4 5 5 5 5	Apr 2, 2020 Apr 2, 2020 Apr 15, 2020 Apr 15, 2020 May 3, 2020 May 15, 2020 May 15, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$200.00) \$200.00 (\$200.00) \$200.00 (\$200.00) \$200.00 \$200.00 \$200.00 \$200.00 \$200.00 \$0.00 \$0.00 \$0.00	Estimate Exception 4 on the current Payment Estimate.
0310	Total TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE Material - Total Total CABLE, LOOP DETECTOR, IN			2 3 3 4 4 5 5 5	Apr 2, 2020 Apr 2, 2020 Apr 15, 2020 Apr 15, 2020 May 3, 2020 May 3, 2020 May 15, 2020 May 15, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$200.00) \$200.00 (\$200.00) \$200.00 (\$200.00) \$200.00 \$200.00 \$200.00 \$200.00 \$200.00 \$200.00	Estimate Exception 4 on the current Payment Estimate.
0310	Total TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE Material - Total Total CABLE, LOOP DETECTOR, IN			2 3 3 4 4 5 5 5 5	Apr 2, 2020 Apr 15, 2020 Apr 15, 2020 Apr 15, 2020 May 3, 2020 May 15, 2020 May 15, 2020 May 15, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$200.00) \$200.00 (\$200.00) \$200.00 (\$200.00) \$200.00 \$200.00 \$200.00 \$200.00 \$200.00 \$0.00 \$0.00 \$0.00	Estimate Exception 4 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0400 -	·Total						\$0.00	
0410	CURB BLOCKOUT Ma	Material		2	Apr 2, 2020	SYSTEM	(\$32,412.00)	
				2	Apr 2, 2020	SYSTEM	\$32,412.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.
				3	Apr 15, 2020	SYSTEM	(\$64,750.00)	
				3	Apr 15, 2020	SYSTEM	\$64,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user wilesr overridding Payment Estimate Exception 5 on the current Payment Estimate.
				4	May 3, 2020	SYSTEM	(\$64,750.00)	
				4	May 3, 2020	SYSTEM	\$64,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user wilesr overridding Payment Estimate Exception 11 on the current Payment Estimate.
				5	May 15, 2020	SYSTEM	(\$64,750.00)	
				5	May 15, 2020	SYSTEM	\$64,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user wilesr overridding Payment Estimate Exception 12 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0410 -	Total						\$0.00	
Overa	III - Total						(\$89,188.20)	