

47.28%

Pay Estimate Created Date: September 16, 2020

Progress Estimate Number 15		Contract ID191018-D03Prime ContractorEmery Sapp & So		er 2, 2020 Original Contract Amoun er 15, 2020 Net Change Order Amoun Current Contract Amoun	nt \$31,922.80			
Approval Date					By User			
September 16, 2020		Generated and Approved (and should be considered Draft) at the Project Office Level by						
September 16, 2020		Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by						
September 17, 2020			Reviewed and Approved at the Cer	tral Office Controllers Office Level by	greggd1			
Original Completion Date		Current Completion Date	Actual Completion Date	% of Current Contract Amount	nt Complete			

December 1, 2021 December 1, 2021

Contract Informational Dates

Con	ntract Informationa	l Dates		Milest	ones		
Date Description	Original Completion Date	Current Completion Date	Date Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days
Acceptance Date			Milestone - Completion Date - Admin Costs for J5P3181	December 1, 2021	December 1, 2021	441	
Awarded Date	November 6, 2019	November 6, 2019	Milestone - Completion Date - RUC for J5P3181	December 1, 2021	December 1, 2021	441	
Letting Date	October 18, 2019	October 18, 2019					
Notice to Proceed Date	February 3, 2020	February 3, 2020					
Open to Traffic Date							
Work Began	February 11,	February 11,					

Contract Total Pay For Estimate No. 15										
		This Estimate	Previous	To Date						
191018-D03										
	Total Posted Items Pay	\$385,319.29	\$4,221,053.82	\$4,606,373.11						
	Gross Item Adjustments	\$23,113.42	\$144,876.11	\$167,989.53						
	Incentive	\$0.00	\$0.00	\$0.00						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
	5		\$4,365,929.93	\$4,774,362.64						
Contract Total Pa	ayable This Estimate:	\$408,432.71								

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3181	0030	2022010	REMOVAL OF IMPROVEMENTS	LS	\$130,500.000	0.15	\$19,575.00
	0040	2035000	UNCLASSIFIED EXCAVATION	CUYD	\$5.900	2,610	\$15,399.00
	0060	2036000	COMPACTING EMBANKMENT	CUYD	\$1.600	1,878.9	\$3,006.24
	0160	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$8.200	100	\$820.00
	0250	5021332	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	SQYD	\$80.000	614.36	\$49,148.80
	0290	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	LF	\$46.000	213.6	\$9,825.60
	0360	6096030A	FURNISHING TYPE 3 ROCK DITCH LINER	CUYD	\$36.000	15.5	\$558.00
	0390	6096043	PLACING TYPE 3 ROCK DITCH LINER	CUYD	\$23.000	15.5	\$356.50
	0440	6099903	MISC.MODIFIED CURB AND GUTTER TYPE B	LF	\$21.000	653.7	\$13,727.70
10	1050	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	FT	\$530.000	7	\$3,710.00
	1240	8061005	ROCK DITCH CHECK	LF	\$10.850	55	\$596.75
	1290	8061016	SEDIMENT REMOVAL	CUYD	\$30.000	46.6	\$1,398.00



Progress E	stimate Nu 15		Contract ID 191018-D03 Prime Contractor Emery Sapp & Sons, Ir	Pay Period Start Sep nc. Pay Period End Sep		r 15, 2020 Net (ount \$31,922.80
Project Number	Line Number	ltem Code		1	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3181			CONCRETE PAVEMENT (8 1/2 IN. N 15 FT. JOINTS)	ON-REINFORCED, S	SQYD	\$56.000	3,197.9	\$179,082.40
	1410	502133	CONCRETE PAVEMENT (8 1/2 IN. N 15 FT. JOINTS)	ON-REINFORCED, S	SQYD	\$56.000	1,464.9	\$82,034.40
	1450	502134	10 TYPE A2 SHOULDER	S	SQYD	\$38.000	13.3	\$505.40
	1590	901300	CONDUIT, 3 IN. RIGID, IN TRENCH	L	LF	\$18.500	49	\$906.50
	2040	707100	00 CONDUIT SYSTEM ON STRUCTURE	E L	LS	\$4,669.000	1	\$4,669.00
Project J5P3	181 - Total							\$385,319.29
Overall - Tot	al							\$385,319.29

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3181	0040	UNCLASSIFIED EXCAVATION	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	510	(\$0.25)	(\$126.99
	0040	UNCLASSIFIED EXCAVATION	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	600	(\$0.25)	(\$149.40
	0040	UNCLASSIFIED EXCAVATION	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	600	(\$0.25)	(\$149.40
	0040	UNCLASSIFIED EXCAVATION	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	300	(\$0.25)	(\$74.70
	0040	UNCLASSIFIED EXCAVATION	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	600	(\$0.25)	(\$149.40
	0160	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	100	(\$0.19)	(\$19.09
	0250	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	614.36	(\$0.55)	(\$336.55
	0250	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material			-614.36	\$80.00	(\$49,148.80
	0250	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user graesj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	614.36	\$80.00	\$49,148.80
	0290	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material			-213.6	\$46.00	(\$9,825.60
	0290	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user graesj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	213.6	\$46.00	\$9,825.60
	0420	MISC.	Material			-476	\$50.00	(\$23,800.00)
	0420	MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user graesj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	476	\$50.00	\$23,800.00
	0430	MISC.	Material			-51	\$115.00	(\$5,865.00
	0430	MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item	51	\$115.00	\$5,865.00



Progre	ess Esti 1	mate Number 5	Contract ID Prime Contra	191018-I actor Emery S		Pay Period Start September 2, 2020 Orig Pay Period End September 15, 2020 Net Cur		er Amount \$	31,922.80
Project Number	Line No.	Item Des	cription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3181						Adjustment (0012) due to user graesj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.			
	0440		MISC.	Material			-1,668.7	\$21.00	(\$35,042.70
	0440		MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0013) due to user graesj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	1,668.7	\$21.00	\$35,042.70
	0730	THE PAVEMEN	PREFORMED RMOPLASTIC NT MARKING, GHT ARROW	Material			-1	\$300.00	(\$300.00
	0730	PREFORME THERMOPLASTI PAVEMENT MARKING LEFT/RIGHT ARROV 24 IN. WHITE STANDAR WATERBORNE PAVEMEN MARKING PAINT, TYPE		Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0014) due to user graesj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	1	\$300.00	\$300.00
	0840	WATERBORNI	E PAVEMENT	Material			-32	\$6.75	(\$216.00
	0840			Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0015) due to user graesj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.	32	\$6.75	\$216.00
	1030	30 IN. PI	PE GROUP A	Material			-72	\$80.00	(\$5,760.00
	1030	30 IN. PI	PE GROUP A	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0016) due to user graesj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	72	\$80.00	\$5,760.00
	1120	SUBSTITU	OR ALLOWED TE GROUP A ND SECTION	Material			-2	\$440.00	(\$880.00
	1120	SUBSTITU	OR ALLOWED TE GROUP A ND SECTION	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0017) due to user graesj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	2	\$440.00	\$880.00
	1350		MISC.	Material			-198	\$75.00	(\$14,850.00
	1350		MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user graesj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.	198	\$75.00	\$14,850.00
	1390	CONCRETE F 1/2 IN. NON-R 1		Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,021.5	(\$0.55)	(\$559.58
	1390	CONCRETE F 1/2 IN. NON-R 1		Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	878.6	(\$0.55)	(\$481.30)
	1390	CONCRETE F 1/2 IN. NON-R 15		Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	248.5	(\$0.55)	(\$136.13)
	1390	CONCRETE F 1/2 IN. NON-R 15		Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	514.5	(\$0.55)	(\$281.84)

Progre		mate Number 5	Contract ID Prime Contra	191018-I actor Emery S		Pay Period Start September 2, 2020 Originc. Pay Period End September 15, 2020 Net Cur	Change Ord	er Amount 🖇	
Project Number	Line No.	Item Des	cription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3181	1390	1/2 IN. NON-F	PAVEMENT (8 REINFORCED, 5 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	534.8	(\$0.55)	(\$292.96)
	1390	1/2 IN. NON-F	PAVEMENT (8 REINFORCED, 5 FT. JOINTS)	Material			-6,002.95	\$56.00	(\$336,165.20)
	1390	1/2 IN. NON-F	PAVEMENT (8 REINFORCED, 5 FT. JOINTS)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0023) due to user graesj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	6,002.95	\$56.00	\$336,165.20
	1410	1/2 IN. NON-F	PAVEMENT (8 REINFORCED, 5 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	523.8	(\$0.55)	(\$286.94)
	1410	1/2 IN. NON-F	PAVEMENT (8 REINFORCED, 5 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	579.5	(\$0.55)	(\$317.45)
	1410	1/2 IN. NON-F	PAVEMENT (8 REINFORCED, 5 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	42.9	(\$0.55)	(\$23.50)
	1410	1/2 IN. NON-F	PAVEMENT (8 REINFORCED, 5 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	318.7	(\$0.55)	(\$174.58
	1410	1/2 IN. NON-F	PAVEMENT (8 REINFORCED, 5 FT. JOINTS)	Material			-3,445.33	\$56.00	(\$192,938.48
	1410	1/2 IN. NON-F	PAVEMENT (8 REINFORCED, 5 FT. JOINTS)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0031) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	3,445.33	\$56.00	\$192,938.48
	1430	TYPE A	2 SHOULDER	Material			-59.57	\$38.00	(\$2,263.66
	1430	TYPE A	2 SHOULDER	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0032) due to user graesj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	59.57	\$38.00	\$2,263.66
	1450	TYPE A	2 SHOULDER	Material			-121.56	\$38.00	(\$4,619.28
	1450	TYPE A	2 SHOULDER	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0033) due to user graesj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	121.56	\$38.00	\$4,619.28
	1450	TYPE A	2 SHOULDER	Other Item Adjustment	Fuel Price	Estimate 15 F.U.F.=0.49 DIFF.= -\$0.83 13.3 SY = -\$5.41			(\$5.41)
	1710	CONCRET	E FOOTINGS, EMBEDDED	Material			-1.26	\$800.00	(\$1,008.00)
	1710	CONCRET	E FOOTINGS, EMBEDDED	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0024) due to user graesj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.	1.26	\$800.00	\$1,008.00
	1730	(PERFORA	Y ASSEMBLY TED SQUARE STEEL TUBE)	Material			-8	\$315.00	(\$2,520.00)
	1730	(PERFORA	Y ASSEMBLY TED SQUARE STEEL TUBE)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0025) due to user graesj1 overridding Payment Estimate Exception 39	8	\$315.00	\$2,520.00



Progre	ess Estii 1	mate Number 5	Contract ID Prime Contra	191018- actor Emery S		nc. Pay Period End September 15, 2020 Net	, Change Orde	er Amount 🖇	\$9,711,377.55 \$31,922.80 \$9,743,300.35				
Project Number	Line No.	Item Description		Item Description		Item Description		Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3181						on the current Payment Estimate.							
	1830	ST-S	TRUCTURAL	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			\$26,678.64				
	2000		CONCRETE STRUCTURE)	Material			-35.2	\$800.00	(\$28,160.00				
	2000		CONCRETE STRUCTURE)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0034) due to user graesj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	35.2	\$800.00	\$28,160.00				
	2040		SYSTEM ON STRUCTURE	Material			-1	\$4,669.00	(\$4,669.00)				
	2040	CONDUIT SYSTEM ON STRUCTURE		Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0035) due to user graesj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	1	\$4,669.00	\$4,669.00				
	2250	ME(STABILIZED E	CHANICALLY EARTH WALL SYSTEMS	Material			-2,528	\$68.00	(\$171,904.00)				
	2250	MECHANICALLY STABILIZED EARTH WALL SYSTEMS		Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0036) due to user graesj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	2,528	\$68.00	\$171,904.00				
	2280	MECHANICALLY STABILIZED EARTH WALL SYSTEMS		Material			-2,710	\$68.00	(\$184,280.00)				
	2280	MECHANICALLY STABILIZED EARTH WALL SYSTEMS		Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0037) due to user graesj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	2,710	\$68.00	\$184,280.00				
otal									\$23,113.42				



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information									
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work					
J5P3181	FAF-15-1(17)	Grading, pavement and 2 bridges	54	MILLER	at the Route 54, BR 54, and Osage Hills Road intersection near Lake Ozark					

Totals by Job Numbers

31	This Estimate	Previous	To Date
Posted Item Pay	\$385,319.29	\$4,221,053.82	\$4,606,373.11
Gross Item Adjustments	\$23,113.42	\$144,876.11	\$167,989.53
Gross Item Pay	\$408,432.71	\$4,365,929.93	\$4,774,362.64
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00

Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 5021332, Project Item Line Number 1410, Material Set 502133296, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	PAL needs to be entered.	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 5021332, Project Item Line Number 1410, Material Set 502133296, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	PAL needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 5021332, Project Item Line Number 1410, Material Set 502133296, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	PAL needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 5021332, Project Item Line Number 1410, Material Set 502133296, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	PAL needs to be entered.	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 5021332, Project Item Line Number 0250, Material Set 502133296, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	PAL needs to be entered.	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 5021332, Project Item Line Number 0250, Material Set 502133296, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	PAL needs to be entered.	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 5021332, Project Item Line Number 0250, Material Set 502133296, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	PAL needs to be entered.	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 5021332, Project Item Line Number 0250, Material Set 502133296, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	PAL needs to be entered.	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 5021332, Project Item Line Number 1390, Material Set 502133296, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	PAL needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 5021332, Project Item Line Number 1390, Material Set 502133296, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	PAL needs to be entered.	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 5021332, Project Item Line Number 1390, Material Set 502133296, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	PAL needs to be entered.	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 5021332, Project Item Line Number 1390, Material Set 502133296, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	PAL needs to be entered.	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 5021340, Project Item Line Number 1450, Material Set 502134096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	PAL needs to be entered.	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 5021340, Project Item Line Number 1430, Material Set 502134096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	PAL needs to be entered.	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 6091010, Project Item Line Number 0290, Material Set 609101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	QC report needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 6091010, Project Item Line Number 0290, Material Set 609101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	QC report needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 6091010, Project Item Line Number 0290, Material Set 609101096, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	QA report needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 6091010, Project Item Line Number 0290, Material Set 609101096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	PAL needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 6099903, Project Item Line Number 0440, Material Set 6099903, Material 1005FACCNS.CA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNS.CA is insufficient.	QC report needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 6099903, Project Item Line Number 0440, Material Set 6099903, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	QC report needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 6099903, Project Item Line Number 0440, Material Set 6099903, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	QC/QA report needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 6099903, Project Item Line Number 0430, Material Set 6099903, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	QC report needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 6099903, Project Item Line Number 0430, Material Set 6099903, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	QC report needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 6099903, Project Item Line Number 0430, Material Set 6099903, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr	PAL needs to be entered	graesj1	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			<u></u>
Exceptions / Discrepencies	Explanation	Entered By	Status
60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 6099903, Project Item Line Number 0420, Material Set 6099903, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	PAL needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 6200021, Project Item Line Number 0730, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Marking tape has not been used yet	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 6206124A, Project Item Line Number 0840, Material Set 6206124A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	HiBld paint has not been used yet.	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 7032003, Project Item Line Number 2000, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	QC report needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 7032003, Project Item Line Number 2000, Material Set 703200396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	QC report needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 7032003, Project Item Line Number 2000, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	QC report needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 7071000, Project Item Line Number 2040, Material Set 707100096, Material 1062JBHL - Junction Boxes for Highway Lighting, Acceptance Action Generic 1062JBHL is insufficient.	Freeform report needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 7201000, Project Item Line Number 2280, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	QC report needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 7201000, Project Item Line Number 2250, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	QC report needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 7261030, Project Item Line Number 1030, Material Set 726103096, Material 1020CPCSAC0030 - CulvPipe AI Ctd Corrug Stl 30" 750mm, Acceptance Action Generic 1020CPCSAC0030 is insufficient.	Performance inspection will be performed at later date	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 7261030, Project Item Line Number 1030, Material Set 726103096, Material 1041CPPPDW30 - Polypropylene Culv Double Wall 30", Acceptance Action Generic 1041CPPPDW30 is insufficient.	Performance inspection will be performed at later date	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 7320618A, Project Item Line Number 1120, Material Set 7320618A96, Material 1032ESRCF - Conc End Section for Round Pipe, Acceptance Action Generic 1032ESRCF is insufficient.	Freeform report needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 8069905, Project Item Line Number 1350, Material Set 8069905, Material 1011GXT3 - Geotextile Fabric for ErosionControl(T3), Acceptance Action Generic 1011GXT3 is insufficient.	Freeform report needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 9031010, Project Item Line Number 1710, Material Set 903101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Report needs to be entered	graesj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3181, Item 9031241, Project Item Line Number 1730, Material Set 903124196, Material 0903HSBA - Breakaway Assembly for Highway Signing, Acceptance Action Generic 0903HSBA is insufficient.	Freeform report needs to be entered	graesj1	Overridden
Estimate Exception Type: Item Overrun: Contract 191018-D03, Contract Project J5P3181, Project Item Line Number 1200, Contract Line Item Number 1200, Item 8052000A, Minor Item.	Change order in progress	graesj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191018-D03, Contract Project J5P3181, Project Item Line Number 0350, Contract Line Item Number 0350, Item 6096020, Minor Item.	Change order in progress	graesj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191018-D03, Contract Project J5P3181, Project Item Line Number 0380, Contract Line Item Number 0380, Item 6096042, Minor Item.	Change order in progress	graesj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191018-D03, Contract Project J5P3181, Project Item Line Number 0400, Contract Line Item Number 0400, Item 6096050, Minor Item.	Change order in progress	graesj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191018-D03, Contract Project JSP3181, Project Item Line Number 0540, Contract Line Item Number 0540, Item 6161005, Minor Item.	Change order in progress	graesj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191018-D03, Contract Project J5P3181, Project Item Line Number 0660, Contract Line Item Number 0660, Item 6173600D, Minor Item.	Change order in progress	graesj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191018-D03, Contract Project J5P3181, Project Item Line Number 0670, Contract Line Item Number 0670, Item 6174000A, Minor Item.	Change order in progress	graesj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191018-D03, Contract Project J5P3181, Project Item Line Number 0890, Contract Line Item Number 0890, Item 6240103A, Minor Item.	Change order in progress	graesj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191018-D03, Contract Project J5P3181, Project Item Line Number 1985, Contract Line Item Number 1985, Item 7026000, Minor Item.	Change order in progress	graesj1	Acknowledged



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted am	ount at the	time the E	stimate was	Genera	ated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191018-D03	J5P3181	0001	0010	2013000	CLEARING AND GRUBBING	20.00	0.00	20.00	ACRE	20.00	\$4,250.00	\$85,000.00
		0001	0020	2019902	MISCMOWING	6.00	0.00	6.00	EA	0.00	\$645.00	\$0.00
		0001	0030	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.50	\$130,500.00	\$65,250.00
		0001	0040	2035000	UNCLASSIFIED EXCAVATION	101,729.00	0.00	101,729.00	CUYD	78,145.68	\$5.90	\$461,059.51
		0001	0050	2035500	EMBANKMENT IN PLACE	100,533.00	0.00	100,533.00	CUYD	76,938.00	\$6.60	\$507,790.80
		0001	0060	2036000	COMPACTING EMBANKMENT	86,177.00	0.00	86,177.00	CUYD	63,976.65	\$1.60	\$102,362.64
		0001	0070	2037075	COMPACTING IN CUT	22.50	0.00	22.50	STA	12.55	\$773.00	\$9,701.15
		0001	0080	2063000	CLASS 3 EXCAVATION	2,253.00	0.00	2,253.00	CUYD	1,026.80	\$10.50	\$10,781.40
		0001	0090	2063100	CLASS 3 EXCAVATION IN ROCK	745.00	0.00	745.00	CUYD	446.00	\$85.00	\$37,910.00
		0001	0100	2081000	INTERCEPTION DITCH	3.00	4.00	7.00	100F	6.10	\$375.00	\$2,287.50
		0001	0110	2099905	MISC.GROUND IMPROVEMENTS	229.60	0.00	229.60	SQYD	0.00	\$100.00	\$0.00
		0001	0120	2142000	FURNISHING ROCK FILL	38.00	0.00	38.00	CUYD	38.00	\$30.00	\$1,140.00
		0001	0130	2143000	PLACING ROCK FILL	38.00	0.00	38.00	CUYD	38.00	\$50.00	\$1,900.00
		0001	0140	2151000A	SHAPING SLOPES, CLASS I	39.20	0.00	39.20	100F	6.21	\$325.00	\$2,018.25
		0001	0150	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	7,101.00	0.00	7,101.00	SQYD	4,610.44	\$6.75	\$31,120.47
		0001	0160	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	34,906.00	0.00	34,906.00	SQYD	15,746.90	\$8.20	\$129,124.58
		0001	0170	3107002	GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C)	41.00	0.00	41.00	TONS	0.00	\$43.00	\$0.00
		0001	0180	4010150	TYPE A2 SHOULDER	115.10	0.00	115.10	SQYD	0.00	\$65.00	\$0.00
		0001	0190	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	244.20	0.00	244.20	TONS	0.00	\$150.00	\$0.00
		0001	0200	4019905	MISC.OPTIONAL PAVEMENT - 7 IN. HMA OR 7 IN. PCCP	6,366.80	0.00	6,366.80	SQYD	4,161.55	\$50.00	\$208,077.50
		0001	0210	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	3,162.30	0.00	3,162.30	TONS	85.16	\$150.00	\$12,774.00
		0001	0220	4030403	10 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125C	839.60	0.00	839.60	SQYD	153.26	\$82.00	\$12,567.32
		0001	0230	4030410	13 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125C	4,505.60	0.00	4,505.60	SQYD	3,899.00	\$75.00	\$292,425.00
		0001	0240	4071005	TACK COAT	2,989.00	0.00	2,989.00	GAL	123.00	\$4.00	\$492.00
		0001	0250	5021332	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	1,668.50	0.00	1,668.50	SQYD	614.36	\$80.00	\$49,148.80
		0001	0260	5041000	CONCRETE APPROACH PAVEMENT	268.10	0.00	268.10	SQYD	0.00	\$165.00	\$0.00
		0001	0270	6083006	6 IN. CONCRETE MEDIAN STRIP	1,296.70	0.00	1,296.70	SQYD	0.00	\$65.00	\$0.00
		0001	0280	6085008	PAVED APPROACH, 8 IN.	734.60	0.00	734.60	SQYD	0.00	\$60.00	\$0.00
		0001	0290	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	686.00	0.00	686.00	LF	213.60	\$46.00	\$9,825.60
		0001	0300	6091042	CONCRETE GUTTER TYPE B	278.00	0.00	278.00	LF	0.00	\$45.00	\$0.00
		0001	0310	6091051	CURB AND GUTTER TYPE A	769.00	0.00	769.00	LF	0.00	\$24.00	\$0.00
		0001	0320	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	125.00	0.00	125.00	LF	0.00	\$26.00	\$0.00
		0001	0330	6094010	DRAIN BASIN	4.00	0.00	4.00	EA	0.00	\$4,300.00	\$0.00
		0001	0340	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	217.00	0.00	217.00	CUYD	0.00	\$26.00	\$0.00
		0001	0350	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	240.00	0.00	240.00	CUYD	264.10	\$30.00	\$7,923.00
		0001	0360	6096030A	FURNISHING TYPE 3 ROCK DITCH LINER	1,541.00	0.00	1,541.00	CUYD	1,089.50	\$36.00	\$39,222.00
		0001	0370	6096041	PLACING TYPE 1 ROCK DITCH LINER	217.00	0.00	217.00	CUYD	0.00	\$26.00	\$0.00
		0001	0380	6096042	PLACING TYPE 2 ROCK DITCH LINER	240.00	0.00	240.00	CUYD	264.10	\$31.00	\$8,187.10
		0001	0390	6096043	PLACING TYPE 3 ROCK DITCH LINER	1,541.00	0.00	1,541.00	CUYD	1,089.50	\$23.00	\$25,058.50
		0001	0400	6096050	BEDDING MATERIAL FOR ROCK DITCH LINER	348.00	0.00	348.00	CUYD	392.00	\$47.00	\$18,424.00
		0001	0410	6097000	ROCK LINING	81.00	0.00	81.00	CUYD	4.20	\$100.00	\$420.00
		0001	0420	6099903	MISC.MODIFIED CONCRETE CURB (6 IN. HEIGHT) TYPE S	476.00	383.00	859.00	LF	476.00	\$50.00	\$23,800.00
		0001	0430	6099903	MISC.MODIFIED CONCRETE GUTTER TYPE A	51.00	0.00	51.00	LF	51.00	\$115.00	\$5,865.00
		0001	0440	6099903	MISC.MODIFIED CURB AND GUTTER TYPE B	2,002.00	0.00	2,002.00	LF	1,668.70	\$21.00	\$35,042.70
		0001	0450	6113010	FURNISHING TYPE 1 ROCK BLANKET	108.00	0.00	108.00	CUYD	0.00	\$36.00	\$0.00
		0001	0460	6113030	PLACING TYPE 1 ROCK BLANKET	108.00	0.00	108.00	CUYD	0.00	\$49.00	\$0.00



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted amo	ount at the t	time the E	stimate was	Genera	ited.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191018-D03	J5P3181	0001	0470	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$12,000.00	\$0.00
		0001	0480	6141022	GRATE AND BEARING PLATE (3 FT. X 3 FT. OR 914 MM X 914 MM)	3.00	0.00	3.00	EA	1.00	\$1,110.00	\$1,110.00
		0001	0490	6141024	GRATE AND BEARING PLATE (5 FT. X 3 FT. OR 1524 MM X 914 MM)	1.00	0.00	1.00	EA	0.00	\$1,400.00	\$0.00
		0001	0500	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)	5.00	0.00	5.00	EA	2.00	\$455.00	\$910.00
		0001	0510	6141121	CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM)	3.00	0.00	3.00	EA	0.00	\$760.00	\$0.00
		0001	0520	6143013	MANHOLE FRAME AND COVER, TYPE 3	4.00	0.00	4.00	EA	0.00	\$465.00	\$0.00
		0001	0530	6143020	CURB INLET	4.00	0.00	4.00	EA	2.00	\$3,300.00	\$6,600.00
		0001	0540	6161005	CONSTRUCTION SIGNS	3,061.00	192.00	3,253.00	SQFT	3,478.80	\$8.00	\$27,830.40
		0001	0550	6161008	ADVANCED WARNING RAIL SYSTEM	33.00	0.00	33.00	EA	33.00	\$35.00	\$1,155.00
		0001	0560	6161009	FLAG ASSEMBLY	31.00	0.00	31.00	EA	21.00	\$20.00	\$420.00
		0001	0570	6161024	CHANNELIZER (TRIM LINE) WITH LIGHT	40.00	0.00	40.00	EA	30.00	\$50.00	\$1,500.00
		0001	0575	6161025	CHANNELIZER (TRIM LINE)	120.00	100.00	220.00	EA	220.00	\$20.00	\$4,400.00
		0001	0580	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	30.00	0.00	30.00	EA	9.00	\$175.00	\$1,575.00
		0001	0585	6161033	DIRECTIONAL INDICATOR BARRICADE	30.00	0.00	30.00	EA	30.00	\$65.00	\$1,950.00
		0001	0600	6161040	FLASHING ARROW PANEL	6.00	0.00	6.00	EA	3.00	\$2,050.00	\$6,150.00
		0001	0610	6161052	WARNING LIGHT, TYPE B	27.00	0.00	27.00	EA	0.00	\$55.00	\$0.00
		0001	0620	6161055	SEQUENTIAL FLASHING WARNING LIGHT	30.00	0.00	30.00	EA	30.00	\$75.00	\$2,250.00
		0001	0630	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	8.00	0.00	8.00	EA	5.00	\$4,020.00	\$20,100.00
		0001	0640	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	40.00	0.00	40.00	EA	8.00	\$1,200.00	\$9,600.00
		0001	0650	6169901	MISC.MESSAGE BOARD INTERFACE	1.00	0.00	1.00	LS	1.00	\$10,990.00	\$10,990.00
		0001	0660	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	895.00	0.00	895.00	LF	1,444.00	\$25.50	\$36,822.00
		0001	0670	6174000A	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	1.00	0.00	1.00	EA	3.00	\$750.00	\$2,250.00
		0001	0680	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	970.00	0.00	970.00	LF	0.00	\$9.00	\$0.00
		0001	0690	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$935,200.00	\$0.00
		0001	0691	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.75	\$893,789.00	\$670,341.75
		0001	0700	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0001	0710	6191000	PAVEMENT EDGE TREATMENT	11,609.00	0.00	11,609.00	LF	654.00	\$1.25	\$817.50
		0001	0720	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	24.00	0.00	24.00	LF	0.00	\$30.00	\$0.00
		0001	0730	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	13.00	0.00	13.00	EA	1.00	\$300.00	\$300.00
		0001	0740	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	1.00	0.00	1.00	EA	0.00	\$300.00	\$0.00
		0001	0750	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	131.00	0.00	131.00	EA	0.00	\$37.50	\$0.00
		0001	0760	6200051	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT FISH HOOK ARROW	3.00	0.00	3.00	EA	0.00	\$1,500.00	\$0.00
		0001	0770	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	108.00	0.00	108.00	LF	0.00	\$6.75	\$0.00
		0001	0780	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	12,915.00	0.00	12,915.00	LF	0.00	\$0.44	\$0.00
		0001	0790	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	10,282.00	0.00	10,282.00	LF	0.00	\$0.44	\$0.00
		0001	0800	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	3,304.00	0.00	3,304.00	LF	0.00	\$0.95	\$0.00
		0001	0810	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6,331.00	0.00	6,331.00	LF	0.00	\$0.79	\$0.00
		0001	0820	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	8,882.00	0.00	8,882.00	LF	2,180.00	\$0.79	\$1,722.20
		0001	0830	6206108A	8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	258.00	0.00	258.00	LF	0.00	\$2.25	\$0.00
		0001	0840	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	34.00	0.00	34.00	LF	32.00	\$6.75	\$216.00
		0001	0850	6207001	PAVEMENT MARKING REMOVAL	19,398.00	0.00	19,398.00	LF	4,391.00	\$0.72	\$3,161.52
		0001	0860	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	16.00	0.00	16.00	EA	1.00	\$100.00	\$100.00



Note: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted amo	ount at the	time the E	Estimate was	Genera	ated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191018-D03	J5P3181	0001	0870	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	25,477.00	0.00	25,477.00	LF	12,352.00	\$0.79	\$9,758.08
		0001	0880	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,654.00	0.00	2,654.00	SQYD	332.56	\$12.00	\$3,990.72
		0001	0890	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	2,788.00	0.00	2,788.00	SQYD	3,266.00	\$5.00	\$16,330.00
		0001	0900	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	98.50	0.00	98.50	STA	0.00	\$60.00	\$0.00
		0001	0910	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.50	\$79,000.00	\$39,500.00
		0001	0920	7250315A	15 IN. PIPE GROUP B	134.00	0.00	134.00	LF	0.00	\$41.00	\$0.00
		0001	0930	7250318A	18 IN. PIPE GROUP B	268.00	0.00	268.00	LF	268.00	\$55.00	\$14,740.00
		0001	0940	7250324A	24 IN. PIPE GROUP B	40.00	0.00	40.00	LF	0.00	\$95.00	\$0.00
		0001	0950	7250415	15 IN. PIPE GROUP C	210.00	0.00	210.00	LF	0.00	\$27.00	\$0.00
		0001	0960	7250418	18 IN. PIPE GROUP C	501.00	0.00	501.00	LF	357.00	\$35.00	\$12,495.00
		0001	0970	7250424	24 IN. PIPE GROUP C	159.00	0.00	159.00	LF	58.00	\$40.00	\$2,320.00
		0001	0980	7252005	CORRUGATED METALLIC-COATED STEEL PIPE-ARCH TYPE B-5	53.00	0.00	53.00	LF	0.00	\$84.00	\$0.00
		0001	0990	7259903	MISC.UTILITY ENCASEMENT	700.00	0.00	700.00	LF	268.00	\$98.00	\$26,264.00
		0001	1000	7261015	15 IN. PIPE GROUP A	56.00	0.00	56.00	LF	0.00	\$41.00	\$0.00
		0001	1010	7261018	18 IN. PIPE GROUP A	305.00	0.00	305.00	LF	100.00	\$51.00	\$5,100.00
		0001	1020	7261024	24 IN. PIPE GROUP A	305.00	0.00	305.00	LF	97.00	\$60.50	\$5,868.50
		0001	1030	7261030	30 IN. PIPE GROUP A	72.00	0.00	72.00	LF	72.00	\$80.00	\$5,760.00
		0001	1040	7261036	36 IN. PIPE GROUP A	366.00	0.00	366.00	LF	366.00	\$98.00	\$35,868.00
		0001	1050	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	17.00	-2.00	15.00	FT	15.00	\$530.00	\$7,950.00
		0001	1060	7311033	PRECAST CONCRETE DROP INLET 3 FT X 3 FT	11.00	0.00	11.00	FT	4.00	\$560.00	\$2,240.00
		0001	1070	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	9.00	2.00	11.00	FT	2.00	\$570.00	\$1,140.00
		0001	1080	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	3.00	0.00	3.00	FT	0.00	\$780.00	\$0.00
		0001	1090	7320015A	15 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	1.00	0.00	1.00	EA	0.00	\$360.00	\$0.00
		0001	1100	7320018A	18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	5.00	0.00	5.00	EA	5.00	\$380.00	\$1,900.00
		0001	1110	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	0.00	\$400.00	\$0.00
		0001	1120	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	4.00	0.00	4.00	EA	2.00	\$440.00	\$880.00
		0001	1130	7320624A	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	5.00	0.00	5.00	EA	2.00	\$520.00	\$1,040.00
		0001	1140	7320630A	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$730.00	\$1,460.00
		0001	1150	7320636A	36 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	4.00	0.00	4.00	EA	4.00	\$1,000.00	\$4,000.00
		0001	1160	7320815A	15 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	8.00	0.00	8.00	EA	0.00	\$360.00	\$0.00
		0001	1170	7320824A	24 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	1.00	0.00	1.00	EA	0.00	\$520.00	\$0.00
		0001	1180	7321005	B5 FLARED END SECTION	2.00	0.00	2.00	EA	0.00	\$670.00	\$0.00
		0001	1190	8051000A	SEEDING - COOL SEASON MIXTURES	14.20	0.00	14.20	ACRE	3.51	\$2,050.00	\$7,195.50
		0001	1200	8052000A	SEEDING - WARM SEASON MIXTURES	4.60	0.00	4.60	ACRE	6.50	\$2,250.00	\$14,625.00
		0001	1210	8061001	SEDIMENT BASIN EXCAVATION	7,200.00	0.00	7,200.00	CUYD	857.00	\$0.01	\$8.57
		0001	1220	8061002	SEDIMENT BASIN ROCK	7,200.00	0.00	7,200.00	CUYD	57.70	\$0.01	\$0.58
		0001	1230	8061004	SEDIMENT TRAP ROCK	10.00	0.00	10.00	CUYD	0.00	\$70.00	\$0.00
		0001	1240	8061005	ROCK DITCH CHECK	1,679.00	0.00	1,679.00	LF	1,611.00	\$10.85	\$17,479.35
		0001	1250	8061006	ALTERNATE DITCH CHECK	464.00	0.00	464.00	LF	0.00	\$9.25	\$0.00
		0001	1260	8061007A	CURB INLET CHECK	9.00	0.00	9.00	EA	0.00	\$155.00	\$0.00
		0001	1270	8061010A	TYPE B BERM	1,630.00	0.00	1,630.00	LF	800.00	\$2.00	\$1,600.00
		0001	1280	8061011	SLOPE DRAINS	710.00	0.00	710.00	LF	375.00	\$7.50	\$2,812.50
		0001	1290	8061016	SEDIMENT REMOVAL	245.00	0.00	245.00	CUYD	157.20	\$30.00	\$4,716.00
		0001	1300	8061017	TEMPORARY SEEDING AND MULCHING	5.50	0.00	5.50	ACRE	2.86	\$1,750.00	\$5,005.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Note: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted amo	unt at the t	ime the E	stimate was	Genera	ated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191018-D03	J5P3181	0001	1310	8061019	SILT FENCE	6,365.00	0.00	6,365.00	LF	3,770.00	\$2.20	\$8,294.00
		0001	1320	8061020	TEMPORARY PIPE	430.00	0.00	430.00	LF	335.00	\$66.00	\$22,110.00
		0001	1330	8064128	TYPE 1 TURF REINFORCEMENT MAT	9,764.00	0.00	9,764.00	SQYD	540.00	\$3.10	\$1,674.00
		0001	1340	8064140	TYPE 3B EROSION CONTROL BLANKET	1,838.00	0.00	1,838.00	SQYD	0.00	\$1.95	\$0.00
		0001	1350	8069905	MISC.TIED CONCRETE BLOCK SYSTEM	359.30	0.00	359.30	SQYD	198.00	\$75.00	\$14,850.00
		0003	1370	5021333	CONCRETE PAVEMENT (9 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	649.10	0.00	649.10	SQYD	0.00	\$77.00	\$0.00
		0005	1390	5021332	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	19,894.50	0.00	19,894.50	SQYD	6,002.95	\$56.00	\$336,165.20
		0007	1410	5021332	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	3,856.10	0.00	3,856.10	SQYD	3,445.33	\$56.00	\$192,938.48
		0009	1430	5021340	TYPE A2 SHOULDER	2,725.70	0.00	2,725.70	SQYD	59.57	\$38.00	\$2,263.66
		0011	1450	5021340	TYPE A2 SHOULDER	154.70	0.00	154.70	SQYD	121.56	\$38.00	\$4,619.28
		0012	1460	6061040	GUARDRAIL TYPE D	50.00	0.00	50.00	LF	25.00	\$25.50	\$637.50
		0012	1470	6061060	MGS GUARDRAIL	11,613.00	0.00	11,613.00	LF	3,274.50	\$19.00	\$62,215.50
		0012	1480	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	6.00	0.00	6.00	EA	0.00	\$2,700.00	\$0.00
		0012	1490	6061074	MGS HEIGHT AND BLOCK TRANSITION	1.00	0.00	1.00	EA	0.00	\$800.00	\$0.00
		0012	1500	6061080	MGS END ANCHOR	14.00	0.00	14.00	EA	5.00	\$800.00	\$4,000.00
		0012	1510	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	19.00	0.00	19.00	EA	5.00	\$2,700.00	\$13,500.00
		0020	1520	9011030	LIGHTING POLE, 30 FT. OR 9.0 M, TYPE AT	20.00	0.00	20.00	EA	0.00	\$1,664.00	\$0.00
		0020	1530	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	5.00	0.00	5.00	EA	0.00	\$2,700.00	\$0.00
		0020	1540	9011115	BRACKET ARM, 15 FT. OR 4.6 M	25.00	0.00	25.00	EA	0.00	\$546.00	\$0.00
		0020	1550	9011311	LUMINAIRE, LED-A	20.00	0.00	20.00	EA	0.00	\$471.00	\$0.00
		0020	1560	9011312	LUMINAIRE, LED-B	5.00	0.00	5.00	EA	0.00	\$546.00	\$0.00
		0020	1570	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	3.00	0.00	3.00	EA	0.00	\$6,721.00	\$0.00
		0020	1580	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	82.00	0.00	82.00	LF	0.00	\$18.00	\$0.00
		0020	1590	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	617.00	0.00	617.00	LF	259.00	\$18.50	\$4,791.50
		0020	1600	9014003	CONDUIT, 3 IN. RIGID, PUSHED	401.00	0.00	401.00	LF	0.00	\$18.50	\$0.00
		0020	1610	9014004	CONDUIT, 4 IN. RIGID, PUSHED	47.00	0.00	47.00	LF	0.00	\$19.00	\$0.00
		0020	1620	9015010	TRENCHING TYPE I	4,068.00	0.00	4,068.00	LF	0.00	\$3.95	\$0.00
		0020	1630	9015020	TRENCHING TYPE II	882.00	0.00	882.00	LF	0.00	\$3.95	\$0.00
		0020	1640	9016110	PULL BOX, PREFORMED CLASS 1	30.00	0.00	30.00	EA	0.00	\$643.00	\$0.00
		0020	1650	9017002	CABLE, 2 AWG 1 CONDUCTOR	320.00	0.00	320.00	LF	0.00	\$2.50	\$0.00
		0020	1660	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	2,550.00	0.00	2,550.00	LF	0.00	\$0.50	\$0.00
		0020	1670	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	8,180.00	0.00	8,180.00	LF	0.00	\$2.75	\$0.00
		0020	1680	9018230	POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT)	20.00	0.00	20.00	EA	0.00	\$788.00	\$0.00
		0020	1690	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	5.00	0.00	5.00	EA	0.00	\$1,100.00	\$0.00
		0020	1700	9018612	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING ONLY	3.00	0.00	3.00	EA	0.00	\$1.00	\$0.00
		0040	1710	9031010	CONCRETE FOOTINGS, EMBEDDED	28.50	0.00	28.50	CUYD	1.26	\$800.00	\$1,008.00
		0040	1720	9031210	STRUCTURAL STEEL POSTS	11,434.00	866.00	12,300.00	LB	0.00	\$3.50	\$0.00
		0040	1730	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	22.00	0.00	22.00	EA	8.00	\$315.00	\$2,520.00
		0040	1740	9031242	36 IN. SURFACE-MOUNT DELINEATOR POST	32.00	0.00	32.00	EA	0.00	\$125.00	\$0.00
		0040	1750	9031252	7 FT. CHANNEL POST DELINEATOR, DOUBLE STACKED WHITE	11.00	0.00	11.00	EA	0.00	\$45.00	\$0.00
		0040	1760	9031256	7 FT. CHANNEL POST DELINEATOR, WHITE	6.00	0.00	6.00	EA	0.00	\$40.00	\$0.00
		0040	1770	9031257A	7 FT. CHANNEL POST DELINEATOR, YELLOW	4.00	0.00	4.00	EA	0.00	\$40.00	\$0.00
		0040	1780	9031258	7 FT. CHANNEL POST DELINEATOR, WHITE/RED	10.00	0.00	10.00	EA	0.00	\$45.00	\$0.00
		0040	1790	9031259A	7 FT. CHANNEL POST DELINEATOR, YELLOW/RED	6.00	0.00	6.00	EA	0.00	\$45.00	\$0.00
		0040	1800	9031280	2.5 IN. PSST POST - 12 GA.	1,984.00	0.00	1,984.00	LF	224.00	\$10.00	\$2,240.00



Note: Posted Q	uantities	and Value	es are b	ased on R	eport Generated date and can differ from the posted am	ount at the f	time the E	Estimate was	Genera	ated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191018-D03	J5P3181	0040	1810	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	372.00	0.00	372.00	LF	42.00	\$50.00	\$2,100.00
		0040	1820	9035004A	SH-FLAT SHEET	862.00	0.00	862.00	SQFT	21.00	\$15.75	\$330.75
		0040	1830	9035011A	ST-STRUCTURAL	2,136.00	0.00	2,136.00	SQFT	0.00	\$20.00	\$0.00
		0040	1840	9035069A	SHF-FLAT SHEET FLUORESCENT	530.00	0.00	530.00	SQFT	47.25	\$19.25	\$909.56
		0056	1850	3109910	MISC.COMPACTED GRANULAR BACKFILL	238.00	0.00	238.00	TONS	238.00	\$8.00	\$1,904.00
		0056	1860	4019905	MISC.ASPHALT PAVEMENT REPAIR	7.00	0.00	7.00	SQYD	7.00	\$240.00	\$1,680.00
		0056	1870	6039901	WATER	1.00	0.00	1.00	LS	1.00	\$6,100.00	\$6,100.00
		0056	1880	6039901	WATER	1.00	0.00	1.00	LS	1.00	\$4,900.00	\$4,900.00
		0056	1890	6039902	WATER	3.00	0.00	3.00	EA	3.00	\$465.00	\$1,395.00
		0056	1900	6039902	WATER	3.00	0.00	3.00	EA	3.00	\$465.00	\$1,395.00
		0056	1910	6039902	WATER	2.00	0.00	2.00	EA	2.00	\$310.00	\$620.00
		0056	1920	6039903	WATER	90.00	0.00	90.00	LF	90.00	\$110.00	\$9,900.00
		0056	1930	6039903	WATER	643.00	0.00	643.00	LF	643.00	\$75.00	\$48,225.00
		0056	1940	6039903	WATER	80.00	0.00	80.00	LF	80.00	\$160.00	\$12,800.00
		0056	1950	6039903	WATER	100.00	0.00	100.00	LF	100.00	\$44.00	\$4,400.00
		0070	1960	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	0.00	\$1.00	\$0.00
		0070	1970	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	179.00	0.00	179.00	SQYD	0.00	\$240.00	\$0.00
		0070	1980	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	360.00	0.00	360.00	LF	355.00	\$59.00	\$20,945.00
		0070	1985	7026000	PRE-BORE FOR PILING	60.00	0.00	60.00	LF	93.00	\$190.00	\$17,670.00
		0070	1990	7027000	PILE POINT REINFORCEMENT	12.00	0.00	12.00	EA	12.00	\$110.00	\$1,320.00
		0070	2000	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	35.20	0.00	35.20	CUYD	35.20	\$800.00	\$28,160.00
		0070	2010	7034213	SLAB ON CONCRETE I-GIRDER	475.00	0.00	475.00	SQYD	0.00	\$410.00	\$0.00
		0070	2020	7034219A	TYPE D BARRIER	285.00	0.00	285.00	LF	0.00	\$120.00	\$0.00
		0070	2030	7056003	TYPE 6 (54 IN.), PRESTRESSED CONCRETE I-GIRDER	505.00	0.00	505.00	LF	505.00	\$200.00	\$101,000.00
		0070	2040	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	1.00	\$4,669.00	\$4,669.00
		0070	2050	7123301	STEEL INTERMEDIATE DIAPHRAGM FOR P/S CONCRETE GIRDERS	4.00	0.00	4.00	EA	0.00	\$460.00	\$0.00
		0070	2060	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$2,150.00	\$0.00
		0070	2070	7161000	PLAIN NEOPRENE BEARING PAD	5.00	0.00	5.00	EA	0.00	\$180.00	\$0.00
		0070	2080	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	5.00	0.00	5.00	EA	0.00	\$350.00	\$0.00
		0070	2090	7201300	PIPE PILE SPACERS	12.00	0.00	12.00	EA	0.00	\$1,400.00	\$0.00
		0071	2100	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	179.00	0.00	179.00	SQYD	0.00	\$240.00	\$0.00
		0071	2110	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	360.00	0.00	360.00	LF	0.00	\$59.00	\$0.00
		0071	2120	7027000	PILE POINT REINFORCEMENT	12.00	0.00	12.00	EA	0.00	\$110.00	\$0.00
		0071	2130	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	35.20	0.00	35.20	CUYD	0.00	\$800.00	\$0.00
		0071	2140	7034213	SLAB ON CONCRETE I-GIRDER	475.00	0.00	475.00	SQYD	0.00	\$410.00	\$0.00
		0071	2150	7034219A	TYPE D BARRIER	285.00	0.00	285.00	LF	0.00	\$120.00	\$0.00
		0071	2151	7026000	PRE-BORE FOR PILING	60.00	0.00	60.00	LF	0.00	\$190.00	\$0.00
		0071	2160	7056003	TYPE 6 (54 IN.), PRESTRESSED CONCRETE I-GIRDER	505.00	0.00	505.00	LF	0.00	\$200.00	\$0.00
		0071	2170	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	0.00	\$4,669.00	\$0.00
		0071	2180	7123301	STEEL INTERMEDIATE DIAPHRAGM FOR P/S CONCRETE GIRDERS	4.00	0.00	4.00	EA	0.00	\$460.00	\$0.00
		0071	2190	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$2,150.00	\$0.00
		0071	2200	7161000	PLAIN NEOPRENE BEARING PAD	5.00	0.00	5.00	EA	0.00	\$180.00	\$0.00
		0071	2210	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	5.00	0.00	5.00	EA	0.00	\$350.00	\$0.00
		0071	2220	7201300	PIPE PILE SPACERS	12.00	0.00	12.00	EA	0.00	\$1,400.00	\$0.00
		0072	2230	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$3,451.78	\$0.00
		0072	2240	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$3,451.78	\$0.00

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191018-D03	J5P3181	0072	2250	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	5,057.00	0.00	5,057.00	SQFT	2,528.00	\$68.00	\$171,904.00
		0073	2260	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$3,701.60	\$0.00
		0073	2270	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$3,701.60	\$0.00
		0073	2280	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	5,423.00	0.00	5,423.00	SQFT	2,710.00	\$68.00	\$184,280.00
		0001	5001	6189901	MISC.Adjust Mobilization for Contract Bond (Payment for Bid Bond)	0.00	1.00	1.00	LS	1.00	\$41,411.00	\$41,411.00
		0001	5002	8069903	MISC.Erosion Control - 9 IN. STRAW WATTLES	0.00	1,300.00	1,300.00	LF	876.00	\$2.63	\$2,303.88
		0001	5003	8069903	MISC.Erosion Control - 12 IN. STRAW WATTLES	0.00	280.00	280.00	LF	280.00	\$4.31	\$1,206.80
	Project J	5P3181 - To	otal Value	Posted to D	Date as of Report Generated Date							\$4,606,373.10
191018-D03 Ove	rall - Total	Value Post	ted to Dat	te as of Rep	ort Generated Date							\$4,606,373.10



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5P3181

_ine imber	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0030	2022010	REMOVAL OF IMPROVEMENTS	9/10/20	9/16/20	0.15	LS	Various Locations throughout Project					
0040	2035000	UNCLASSIFIED EXCAVATION	9/2/20	9/8/20	510.00	CUYD	RB 1 NE Leg					
			9/10/20	9/16/20	600.00	CUYD	RB 3					
			9/11/20	9/15/20	600.00	CUYD	RB #3					
			9/14/20	9/15/20	300.00	CUYD	RB #3					
			9/15/20	9/16/20	600.00	CUYD	RB #3 at old OHR					
0060	2036000	COMPACTING EMBANKMENT	9/10/20	9/16/20	533.30	CUYD	RB 3 near Ramp 3					
			9/11/20	9/15/20	533.30	CUYD	RB #3					
			9/14/20	9/15/20	279.00	CUYD	RB #3					
			9/15/20	9/16/20	533.30	CUYD	RB #3 at old OHR					
0160	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	9/3/20	9/8/20	100.00	SQYD	RB 1 NE Leg					
0250	5021332	CONCRETE PAVEMENT (8 1/2 IN. NON-REINF,	9/2/20	9/8/20	614.36	SQYD	RB 1 Truck Apron	0+00		3+39.29		
0290	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER)	9/2/20	9/8/20	213.60	LF	RB 1 Center	0+00		3+39.29		
0360	6096030A	FURNISHING TYPE 3 ROCK DITCH LINER	9/15/20	9/16/20	15.50	CUYD	Ramp 1 rock drain in interception levee					
0390	6096043	PLACING TYPE 3 ROCK DITCH LINER	9/15/20	9/16/20	15.50	CUYD	Ramp 1 rock drain in interception levee					
0440	6099903	MISC. PAVED DRAINAGE	9/3/20	9/8/20	329.00	LF	Willmore Ln.	1+11	Lt.	4+40	Lt.	
			9/10/20	9/16/20	33.60	LF	Willmore Ln.	0+77.2	Lt.	1+10.8	Lt.	
				9/16/20	120.00	LF	Willmore Ln.	3+80	rt.	5+00	Rt.	
				9/16/20	140.20	LF	Willmore Ln.	1+04.8	Rt.	2+45	Rt.	
			9/11/20	9/15/20	30.90	LF	Willmore Ln.	0+73.9	Rt.	1+04.8	Rt.	
1050	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	9/9/20	9/15/20	3.00	FT	Willmore Ln.	2+70	Rt.			
				9/15/20	4.00	FT	Willmore Ln.	3+64	Rt.			
1240	8061005	ROCK DITCH CHECK	9/2/20	9/14/20	12.00	LF	P-20 Rt & Lt of inlet Sta. 2+08	2+08				
				9/14/20	20.00	LF	Existing Willmore Lane Sta. 6+50 replaced after utility contractor contaminated dirt with the rock.	6.50				
				9/14/20	23.00	LF	P-15 inlet Sta. 3+50	3+50				
1290	8061016	SEDIMENT REMOVAL	9/2/20	9/14/20	1.50	CUYD	Existing Willmore Lane Cross-pipe Sta. 0+20 RT 5x6x1.38 /27 =1.53	0+20				
				9/14/20	2.80	CUYD	Connector Rd. 4+20 P-15 inlet 20x3x1.25=2.78					
				9/14/20	13.00	CUYD	Connector Rd. 4+20 P-15 outlet 14x20x1.25=12.96	4+20				
				9/14/20	18.50	CUYD	Existing Willmore Lane behind wattle Sta. 0+20 RT 250x4x0.5 /27 =18.51	0+20		6+00		
			9/8/20	9/14/20			Existing Willmore Lane Cross-pipe Sta. 0+20 RT 5x6x1.38 /27 =1.53	0+20				
				9/14/20			Existing Willmore Lane behind wattle Sta. 0+20 to 5+00 RT 250x2x0.5 /27 =9.26	0+20		5+00		
1390	5021332	CONCRETE PAVEMENT (8 1/2 IN. NON-REINF,	9/4/20		450.60		RB 1 NW Leg	1+70		3+43		
				9/8/20	570.90	SQYD	RB 1 SE Leg	0+00	Rt.	2+17	Rt.	
				9/15/20	878.60	SQYD	RB #1					Inside circle
				9/15/20	248.50		RB #1 SE Leg Median	0+53		1+99		
			9/14/20		175.80		RB #1 SE Leg Median					
				9/15/20	338.70		RB #1 SE Leg Left Lane					
				9/16/20	534.80		RB #1 NW Leg Lt. & Median					
1410	5021332	CONCRETE PAVEMENT (8 1/2 IN. NON-REINF,		9/8/20	523.80		Willmore Ln.	1+08		5+00		
			9/10/20	9/16/20	38.50	SQYD	Willmore Ln. at SE Leg of RB 1		Lt.		Lt.	
				9/16/20	541.00	SQYD	Willmore Ln.	1+01	Rt.	5+00	Rt.	
				9/15/20	42.90		Willmore Ln. Right @ RB #1 NW Leg					
				9/15/20	318.70		Willmore Ln inside triangle at RB #1					
1450		TYPE A2 SHOULDER		9/8/20	13.30		Willmore Ln.		Lt.	5+00	Lt.	
1590		CONDUIT, 3 IN. RIGID, IN TRENCH	9/11/20	9/14/20	49.00	LE	RB #1 Pull Box 62 to 67	0				

The information below this line are details from Line Item agency views. No Agency View Details Exist



				-				_
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0040	UNCLASSIFIED EXCAVATION	Other Item Adjustment	FUEL	6	May 5, 2020	graesj1	(\$1,289.34)	Estimate 4, 7,540 C.Y. F.U.F. 0.3 Diff\$0.57 = -\$12,89.34
				6	May 5, 2020	graesj1	(\$1,906.08)	Estimate 5, 7220.0 C.Y. F.U.F. 0.3 Diff\$0.88 = -\$1906.08
				6	May 5, 2020	graesj1	(\$79.20)	Estimate 6, 300 C.Y. F.U.F. 0.3 Diff\$0.88 = -\$79.20
			FUEL - Tota	ıl			(\$3,274.62)	
	Other Item Adjustment - Total						(\$3,274.62)	
	UNCLASSIFIED EXCAVATION	Price		7	May 18, 2020	SYSTEM	(\$785.53)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				9	Jun 16, 2020	SYSTEM	(\$1,336.22)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				10	Jul 1, 2020	SYSTEM	(\$9,138.86)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				11	Jul 16, 2020	SYSTEM	(\$4,686.88)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				12	Aug 4, 2020	SYSTEM	(\$898.88)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				14	Sep 2, 2020	SYSTEM	(\$1,277.10)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				15	Sep 16, 2020	SYSTEM	(\$649.89)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$18,773.36)	
	Price - Total						(\$18,773.36)	
0040 -	Total						(\$22,047.98)	
0050	EMBANKMENT IN PLACE	Other Item Adjustment	FUEL	6	May 5, 2020	graesj1	(\$8,494.64)	Estimate 5, 27,580 C.Y. FUF 0.35 Diff\$0.88 = -\$8,494.64
				6	May 5, 2020	graesj1	(\$1,197.50)	Estimate 6, 3888 C.Y. F.U.F. 0.35 Diff\$0.88 = -\$1197.50
			FUEL - Tota	il			(\$9,692.14)	
	Other Item Adjustment - Total						(\$9,692.14)	
	EMBANKMENT IN PLACE	Price		7	May 18, 2020	SYSTEM	(\$7,014.00)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				8	Jun 2, 2020	SYSTEM	(\$7,737.35)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				9	Jun 16, 2020	SYSTEM	(\$1,636.36)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				9	Jun 16, 2020	SYSTEM	(\$2,496.50)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$18,884.21)	
	Price - Total						(\$18,884.21)	
0050 -	Total						(\$28,576.35)	
0060	COMPACTING EMBANKMENT	Material		4	Apr 2, 2020	SYSTEM	(\$11,219.52)	
				4	Apr 2, 2020	SYSTEM	\$11,219.52	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0060 -	Total						\$0.00	
0100	INTERCEPTION DITCH	Overrun	Overrun	9	Jun 16, 2020	SYSTEM	(\$1,162.50)	
				10	Jul 1, 2020	SYSTEM	\$1,162.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',375.00000 - 375.00000, 'is applied (if non-zero).
			Overrun - To	otal			\$0.00	
	Overrun - Total						\$0.00	
0100 -							\$0.00	
- 000 -		Other Item	FUEL	6	May 4,	graesj1	(\$304.01)	2303.12 S.Y. F.U.F. 0.15 Diff\$0.88 =
0150	TYPE 5 AGGREGATE FOR BASE (4 IN THICK)		TOLL	0		gracojr	(+++++)	
0150	BASE (4 IN. THICK)		FUEL - Tota		2020	gracojr	(\$304.01)	-\$304.01



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0150	Other Item Adjustment - Total						(\$304.01)	
	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Price		8	Jun 2, 2020	SYSTEM	(\$323.13)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				9	Jun 16, 2020	SYSTEM	(\$74.74)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				14	Sep 2, 2020	SYSTEM	(\$10.07)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$407.94)	
	Price - Total						(\$407.94)	
0150 -	Total						(\$711.95)	
0160	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Other Item Adjustment	FUEL	6	May 4, 2020	graesj1	(\$520.84)	2573.3 S.Y. F.U.F. 0.23 Diff \$0.88 = -\$520.84
				8	Jun 2, 2020	graesj1	(\$1,253.91)	4505.6 SY FUF 0.23 Diff1.21 =
			FUEL - Tota	ıl			(\$1,774.75)	
	Other Item Adjustment - Total						(\$1,774.75)	
	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		11	Jul 16, 2020	SYSTEM	(\$623.45)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				14	Sep 2, 2020	SYSTEM	(\$28.19)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				14	Sep 2, 2020	SYSTEM	(\$1,035.78)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				15	Sep 16, 2020	SYSTEM	(\$19.09)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$1,706.51)	
	Price - Total						(\$1,706.51)	
0160 -	Total						(\$3,481.26)	
0200	MISC. OPTIONAL PAVEMENT - 7 IN. HMA OR 7 IN. PCCP	Other Item Adjustment	ACAD	8	Jun 2, 2020	graesj1	(\$2,464.28)	SP 190 20-63A 3062.55 S.Y. AC 3.8% Index Diff.= -55
				8	Jun 2, 2020	graesj1	(\$843.08)	SP 125 20-55A 1020.9 S.Y. AC 3.9% Index Diff.= -55
				14	Sep 2, 2020	graesj1	(\$93.81)	Estimate 14 Index Diff. = -80 SP125 20/55 78.1 SY 7" thick 3.9% AC = -\$93.81
			ACAD - Tot	al			(\$3,401.17)	
	MISC. OPTIONAL PAVEMENT - 7 IN. HMA OR 7 IN. PCCP		FUEL	8	Jun 2, 2020	graesj1	(\$6,315.56)	4083.45 SY / 1572.13 Ton FUF 3.32 Diff1.21 =
				14	Sep 2, 2020	graesj1	(\$85.86)	Estimate 14 Index Diff= -0.86 F.U.F.= 3.23 78.1SY/30.07 Ton = -\$85.86
			FUEL - Tota	ıl			(\$6,401.42)	
	MISC. OPTIONAL PAVEMENT - 7 IN. HMA OR 7 IN. PCCP		SUBI	10	Jul 1, 2020	graesj1	(\$12,031.58)	Density results of 89.3% for the SP125 placed on May 29,2020 for EB & WB temporary bypasses. (2.75"/7")*(4,083.45 SY) = 1,604.21 SY @\$50.00 per SY = \$80,210.50 @ 15% = \$12,031.58
			SUBI - Tota				(\$12,031.58)	
	Other Item Adjustment - Total						(\$21,834.17)	
0200 -	Total						(\$21,834.17)	
0210	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)		ACAD	14	Sep 2, 2020	graesj1	(\$265.70)	Estimate 14 Index Diff.=-80 SP125 20/55 85.16 Tons 3.9% AC = -\$265.70
			ACAD - Tota	al			(\$265.70)	
	Other Item Adjustment - Total						(\$265.70)	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Price		14	Sep 2, 2020	SYSTEM	(\$243.15)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
	,		- Total				(\$243.15)	
	Price - Total						(\$243.15)	
0210 -	Total						(\$508.85)	
0220	10 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125C		ACAD	14	Sep 2, 2020	graesj1	(\$257.43)	Estimate 14 Index Diff. = -80 SP190 20/63 153.26 SY 8.25" thick 3.8% AC = -\$211.41 153.26 SY 1.75" thick 3.9% AC = -\$46.02
	5F 1250		ACAD T-				(\$257.48)	100.20 01 1.70 unor 0.370 AC = -\$40.02
			ACAD - Tot	ar			(\$257.43)	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0220	Other Item Adjustment - Total						(\$257.43)	
	10 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125C	Price		14	Sep 2, 2020	SYSTEM	(\$240.67)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$240.67)	
	Price - Total						(\$240.67)	
0220 -	Total						(\$498.10)	
0230	13 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125C	Other Item Adjustment	ACAD	8	Jun 2, 2020	graesj1	(\$4,272.35)	SP 190 20-63A 2859 S.Y. AC 3.8% Index Diff.= -55
	3F 1230			8	Jun 2, 2020	graesj1	(\$1,554.12)	SP 190 20-63 1040 S.Y. AC 3.8% Index Diff.= -55
			ACAD - Tota	al			(\$5,826.47)	
	13 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125C		SUBI	10	Jul 1, 2020	graesj1	(\$19,495.31)	Density test results of 90.3% for the SP190 PG70-22 placed on May 21, 2020 median widening on US 54. (3/13'')(4505.6 SY) = 1039.75 SY @\$75 per SY = \$77,981.25 @ 25% = \$19,495.31
			SUBI - Tota	I			(\$19,495.31)	
	Other Item Adjustment - Total						(\$25,321.78)	
	13 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125C	Price		8	Jun 2, 2020	SYSTEM	(\$11,199.10)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$11,199.10)	
	Price - Total						(\$11,199.10)	
)230 -	Total						(\$36,520.88)	
)250	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material		15	Sep 16, 2020	SYSTEM	(\$49,148.80)	
	3011473)			15	Sep 16, 2020	SYSTEM	\$49,148.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user graesj1 overridding Paymen Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Price		15	Sep 16, 2020	SYSTEM	(\$336.55)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$336.55)	
	Price - Total						(\$336.55)	
)250 -	Total						(\$336.55)	
0290	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material		15	Sep 16, 2020	SYSTEM	(\$9,825.60)	
				15	Sep 16, 2020	SYSTEM	\$9,825.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user graesj1 overridding Paymen Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
)290 -	Total						\$0.00	
0350	FURNISHING TYPE 2 ROCK DITCH LINER	Material		9	Jun 16, 2020	SYSTEM	(\$843.00)	
				9	Jun 16, 2020	SYSTEM	\$843.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user graesj1 overridding Paymen Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	FURNISHING TYPE 2 ROCK DITCH LINER	Overrun	Overrun	11	Jul 16, 2020	SYSTEM	(\$723.00)	
			Overrun - T	otal			(\$723.00)	
	Overrun - Total						(\$723.00)	
0350 -	PLACING TYPE 2 ROCK DITCH	Overrun	Overrun	11	Jul 16,	SYSTEM	(\$723.00) (\$747.10)	
0380					2020			
0380	LINER		Overrun - T		2020		(\$747.10)	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0380 -	Total						(\$747.10)	
0400	BEDDING MATERIAL FOR ROCK DITCH LINER	Overrun	Overrun	13	Aug 17, 2020	SYSTEM	(\$2,068.00)	
			Overrun - T	otal			(\$2,068.00)	
	Overrun - Total						(\$2,068.00)	
0400 ·	Total						(\$2,068.00)	
0410	ROCK LINING	Material		11	Jul 16, 2020	SYSTEM	(\$420.00)	
				11	Jul 16, 2020	SYSTEM	\$420.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user graesj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total		1		\$0.00	
	Material - Total						\$0.00	
0410 ·	Total						\$0.00	
0420	MISC. MODIFIED CONCRETE CURB (6 IN. HEIGHT) TYPE S	Material		7	May 18, 2020	SYSTEM	(\$23,800.00)	
				7	May 18, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user graesj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				8	Jun 2, 2020	SYSTEM	(\$23,800.00)	
				8	Jun 2, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user graesj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$23,800.00)	
				9	Jun 16, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user graesj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				10	Jul 1, 2020	SYSTEM	(\$23,800.00)	
				10	Jul 1, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user morgat overridding Payment Estimate Exception 6 on the current Payment Estimate.
				11	Jul 16, 2020	SYSTEM	(\$23,800.00)	
				11	Jul 16, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user graesj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				12	Aug 4, 2020	SYSTEM	(\$23,800.00)	
				12	Aug 4, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user graesj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				13	Aug 17, 2020	SYSTEM	(\$23,800.00)	
				13	Aug 17, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user graesj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				14	Sep 2, 2020	SYSTEM	(\$23,800.00)	
				14	Sep 2, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) due to user graesj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				15	Sep 16, 2020	SYSTEM	(\$23,800.00)	
				15	Sep 16, 2020	SYSTEM	\$23,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user graesj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
04 <u>20</u> ·	Total						\$0.00	
0430	MISC. MODIFIED CONCRETE GUTTER TYPE A	Material		13	Aug 17, 2020	SYSTEM	(\$5,865.00)	
				13	Aug 17,	SYSTEM	\$5,865.00	This adjustment offsets the original system-generated Overrun Payment



	D		011	- .	<u> </u>			
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0430	MISC. MODIFIED CONCRETE GUTTER TYPE A	Material			2020			Estimate Item Adjustment (0032) due to user graesj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				14	Sep 2, 2020	SYSTEM	(\$5,865.00)	
				14	Sep 2, 2020	SYSTEM	\$5,865.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) due to user graesj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				15	Sep 16, 2020	SYSTEM	(\$5,865.00)	
				15	Sep 16, 2020	SYSTEM	\$5,865.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user graesj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
430 -	Total						\$0.00	
440	MISC. MODIFIED CURB AND GUTTER TYPE B	Material		12	Aug 4, 2020	SYSTEM	(\$8,358.00)	
				12	Aug 4, 2020	SYSTEM	\$8,358.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user graesj1 overridding Paymen Estimate Exception 12 on the current Payment Estimate.
				13	Aug 17, 2020	SYSTEM	(\$18,606.00)	
				13	Aug 17, 2020	SYSTEM	\$18,606.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user graesj1 overridding Paymen Estimate Exception 11 on the current Payment Estimate.
				14	Sep 2, 2020	SYSTEM	(\$21,315.00)	
				14	Sep 2, 2020	SYSTEM	\$21,315.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0045) due to user graesj1 overridding Paymen Estimate Exception 14 on the current Payment Estimate.
				15	Sep 16, 2020	SYSTEM	(\$35,042.70)	
				15	Sep 16, 2020	SYSTEM	\$35,042.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user graesj1 overridding Paymen
								Estimate Exception 19 on the current Payment Estimate.
			- Total				\$0.00	Estimate Exception 19 on the current Payment Estimate.
	Material - Total		- Total				\$0.00 \$0.00	Estimate Exception 19 on the current Payment Estimate.
440 -	Material - Total Total		- Total					Estimate Exception 19 on the current Payment Estimate.
	Total	Overrun	- Total Overrun	14	Sep 2, 2020	SYSTEM	\$0.00	Estimate Exception 19 on the current Payment Estimate.
	Total	Overrun				SYSTEM	\$0.00 \$0.00	Estimate Exception 19 on the current Payment Estimate.
	Total	Overrun	Overrun			SYSTEM	\$0.00 \$0.00 (\$1,806.40)	Estimate Exception 19 on the current Payment Estimate.
0540	Total CONSTRUCTION SIGNS	Overrun	Overrun			SYSTEM	\$0.00 \$0.00 (\$1,806.40) (\$1,806.40)	Estimate Exception 19 on the current Payment Estimate.
)540)540 -	Total CONSTRUCTION SIGNS Overrun - Total		Overrun	otal		SYSTEM	\$0.00 \$0.00 (\$1,806.40) (\$1,806.40) (\$1,806.40)	Estimate Exception 19 on the current Payment Estimate.
)540)540 -	Total CONSTRUCTION SIGNS Overrun - Total Total		Overrun Overrun - T	otal	2020 May 18,		\$0.00 \$0.00 (\$1,806.40) (\$1,806.40) (\$1,806.40) (\$1,806.40)	Estimate Exception 19 on the current Payment Estimate.
)540 540 -	Total CONSTRUCTION SIGNS Overrun - Total Total		Overrun Overrun - T	otal 7 10	2020 May 18, 2020 Jul 1,	SYSTEM	\$0.00 \$0.00 (\$1,806.40) (\$1,806.40) (\$1,806.40) (\$1,806.40) (\$2,000.00)	Unit price based on averaged overrun adjustments for installed quantity o all previous payment estimates. Price Adjustments of ',20.0000 -
)540 540 -	Total CONSTRUCTION SIGNS Overrun - Total Total		Overrun Overrun - T Overrun	otal 7 10	2020 May 18, 2020 Jul 1,	SYSTEM	\$0.00 \$0.00 (\$1,806.40) (\$1,806.40) (\$1,806.40) (\$1,806.40) (\$2,000.00) \$2,000.00	Unit price based on averaged overrun adjustments for installed quantity o all previous payment estimates. Price Adjustments of ',20.0000 -
1540 1540 - 1575	Total CONSTRUCTION SIGNS Overrun - Total Total CHANNELIZER (TRIM LINE)		Overrun Overrun - T Overrun	otal 7 10	2020 May 18, 2020 Jul 1,	SYSTEM	\$0.00 \$0.00 (\$1,806.40) (\$1,806.40) (\$1,806.40) (\$1,806.40) (\$2,000.00) \$2,000.00	Unit price based on averaged overrun adjustments for installed quantity of all previous payment estimates. Price Adjustments of ',20.0000 -
9540 - 9575 - 9575 -	Total CONSTRUCTION SIGNS Overrun - Total Total CHANNELIZER (TRIM LINE)	Overrun	Overrun Overrun - T Overrun	otal 7 10	2020 May 18, 2020 Jul 1,	SYSTEM	\$0.00 \$0.00 (\$1,806.40) (\$1,806.40) (\$1,806.40) (\$1,806.40) (\$2,000.00) \$2,000.00 \$0.00	Unit price based on averaged overrun adjustments for installed quantity o all previous payment estimates. Price Adjustments of ',20.0000 -
0540 0540 - 0575	Total CONSTRUCTION SIGNS Overrun - Total Total CHANNELIZER (TRIM LINE) Overrun - Total Total	Overrun	Overrun Overrun - T Overrun	7 10 otal	2020 May 18, 2020 Jul 1, 2020 Jun 16,	SYSTEM	\$0.00 \$0.00 (\$1,806.40) (\$1,806.40) (\$1,806.40) (\$1,806.40) (\$2,000.00) \$2,000.00 \$0.00 \$0.00	Unit price based on averaged overrun adjustments for installed quantity or all previous payment estimates. Price Adjustments of ',20.00000 - 20.00000, 'is applied (if non-zero).
540 - 5575 -	Total CONSTRUCTION SIGNS Overrun - Total Total CHANNELIZER (TRIM LINE) Overrun - Total Total Total	Overrun	Overrun Overrun - T Overrun	otal 7 10 otal 9	2020 May 18, 2020 Jul 1, 2020 Jul 1, 2020 Jul 16, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$1,806.40) (\$1,806.40) (\$1,806.40) (\$2,000.00) \$2,000.00 \$0.00 \$0.00 \$0.00 (\$22,618.50)	Unit price based on averaged overrun adjustments for installed quantity of all previous payment estimates. Price Adjustments of ',20.00000 - 20.00000, 'is applied (if non-zero).
0540 - 0575 - 0575 -	Total CONSTRUCTION SIGNS Overrun - Total Total CHANNELIZER (TRIM LINE) Overrun - Total Total Total	Overrun	Overrun - T Overrun - T Overrun - T	otal 7 10 otal 9	2020 May 18, 2020 Jul 1, 2020 Jul 1, 2020 Jul 16, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$1,806.40) (\$1,806.40) (\$1,806.40) (\$2,000.00) \$2,000.00 \$0.00 \$0.00 (\$22,618.50) \$22,618.50	Unit price based on averaged overrun adjustments for installed quantity of all previous payment estimates. Price Adjustments of ',20.00000 - 20.00000, 'is applied (if non-zero).
0540 - 0575 - 0575 -	Total CONSTRUCTION SIGNS Overrun - Total Total CHANNELIZER (TRIM LINE) Overrun - Total Total Total TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Overrun	Overrun - T Overrun - T Overrun - T	otal 7 10 otal 9 9	2020 May 18, 2020 Jul 1, 2020 Jul 1, 2020 Jul 16, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$1,806.40) (\$1,806.40) (\$1,806.40) (\$2,000.00) \$2,000.00 \$0.00 \$0.00 (\$22,618.50) \$22,618.50 \$0.00	Unit price based on averaged overrun adjustments for installed quantity of all previous payment estimates. Price Adjustments of ',20.00000 - 20.00000, 'is applied (if non-zero).
0540 - 0575 - 0575 -	Total CONSTRUCTION SIGNS Overrun - Total Total CHANNELIZER (TRIM LINE) Overrun - Total Total Total Total TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Overrun	Overrun - T Overrun - T Overrun - T	otal 7 10 otal 9 9	2020 May 18, 2020 Jul 1, 2020 Jul 16, 2020 Jun 16, Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$1,806.40) (\$1,806.40) (\$1,806.40) (\$2,000.00) \$2,000.00 \$0.00 \$0.00 (\$22,618.50) \$22,618.50 \$22,618.50 \$22,618.50	Unit price based on averaged overrun adjustments for installed quantity of all previous payment estimates. Price Adjustments of ',20.00000 - 20.00000, 'is applied (if non-zero).



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
0660	Overrun - Total						(\$13,999.50)					
0660 -	Total						(\$13,999.50)					
0670	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	Material		9	Jun 16, 2020	SYSTEM	(\$750.00)					
				9	Jun 16, 2020	SYSTEM	\$750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user graesj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.				
			- Total				\$0.00					
	Material - Total						\$0.00					
	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	Overrun	Overrun	14	Sep 2, 2020	SYSTEM	(\$1,500.00)					
			Overrun - T	otal			(\$1,500.00)					
	Overrun - Total						(\$1,500.00)					
0670 -	Total						(\$1,500.00)					
0730	PREFORMED THERMOPLASTIC PAVEMENT MARKING,	Material		9	Jun 16, 2020	SYSTEM	(\$300.00)					
	LEFT/RIGHT ARROW			9	Jun 16, 2020	SYSTEM	\$300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user graesj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.				
				10	Jul 1, 2020	SYSTEM	(\$300.00)					
				10	Jul 1, 2020	SYSTEM	\$300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user morgat overridding Payment Estimate Exception 7 on the current Payment Estimate.				
				11	Jul 16, 2020	SYSTEM	(\$300.00)					
							11	Jul 16, 2020	SYSTEM	\$300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user graesj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
								12	Aug 4, 2020	SYSTEM	(\$300.00)	
							12	Aug 4, 2020	SYSTEM	\$300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user graesj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
				13	Aug 17, 2020	SYSTEM	(\$300.00)					
				13	Aug 17, 2020	SYSTEM	\$300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user graesj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.				
				14	Sep 2, 2020	SYSTEM	(\$300.00)					
				14	Sep 2, 2020	SYSTEM	\$300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0046) due to user graesj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.				
				15	Sep 16, 2020	SYSTEM	(\$300.00)					
				15	Sep 16, 2020	SYSTEM	\$300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user graesj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.				
			- Total				\$0.00					
	Material - Total						\$0.00					
0730 -	Total						\$0.00					
0840	24 IN. WHITE STANDARD WATERBORNE PAVEMENT	Material		9	Jun 16, 2020	SYSTEM	(\$216.00)					
	MARKING PAINT, TYPE P BEADS			9	Jun 16, 2020	SYSTEM	\$216.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user graesj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.				
				10	Jul 1, 2020	SYSTEM	(\$216.00)					
				10	Jul 1, 2020	SYSTEM	\$216.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user morgat overridding Payment Estimate Exception 8 on the current Payment Estimate.				
				11	Jul 16, 2020	SYSTEM	(\$216.00)					
				11	Jul 16,	SYSTEM	\$216.00	This adjustment offsets the original system-generated Overrun Payment				



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0840	24 IN. WHITE STANDARD	Material	Туре		2020	_,		Estimate Item Adjustment (0015) due to user graesj1 overridding Payment
	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS			12	Aug 4,	SYSTEM	(\$216.00)	Estimate Exception 9 on the current Payment Estimate.
				12	2020 Aug 4,	SYSTEM	\$216.00	This adjustment offsets the original system-generated Overrun Payment
				12	2020	STOTEM	φ210.00	Estimate Item Adjustment (0006) due to user graesj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				13	Aug 17, 2020	SYSTEM	(\$216.00)	
				13	Aug 17, 2020	SYSTEM	\$216.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user graesj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				14	Sep 2, 2020	SYSTEM	(\$216.00)	
				14	Sep 2, 2020	SYSTEM	\$216.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0047) due to user graesj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				15	Sep 16, 2020	SYSTEM	(\$216.00)	
				15	Sep 16, 2020	SYSTEM	\$216.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user graesj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0840 -	Total						\$0.00	
0890	PERMANENT EROSION CONTROL GEOTEXTILE	Material		9	Jun 16, 2020	SYSTEM	(\$370.00)	
				9	Jun 16, 2020	SYSTEM	\$370.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user graesj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	PERMANENT EROSION CONTROL GEOTEXTILE	Overrun	Overrun	13	Aug 17, 2020	SYSTEM	(\$2,390.00)	
			Overrun - T	otal			(\$2,390.00)	
	Overrun - Total						(\$2,390.00)	
0890 -							(\$2,390.00)	
0930	18 IN. PIPE GROUP B	Material		5	Apr 16, 2020	SYSTEM	(\$9,020.00)	
				5	Apr 16, 2020	SYSTEM	\$9,020.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0930 -	Total						\$0.00	
0990	MISC. UTILITY ENCASEMENT	Construction Stockpile		5	Apr 16, 2020	SYSTEM	\$25,200.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				12	Aug 4, 2020	SYSTEM	(\$9,648.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$15,552.00	
	Construction Stockpile - Total						\$15,552.00	
	Total						\$15,552.00	
1020	24 IN. PIPE GROUP A	Material		9	Jun 16, 2020	SYSTEM	(\$5,868.50)	
				9	Jun 16, 2020	SYSTEM	\$5,868.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user graesj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				10	Jul 1, 2020	SYSTEM	(\$5,868.50)	
				10	Jul 1, 2020	SYSTEM	\$5,868.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user morgat overridding Payment Estimate Exception 9 on the current Payment Estimate.
								,



	D 14		0.1	- .	0 1 1	0 1 1		
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1020	24 IN. PIPE GROUP A	Material			2020			
				11	Jul 16, 2020	SYSTEM	\$5,868.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user graesj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				12	Aug 4, 2020	SYSTEM	(\$5,868.50)	
				12	Aug 4, 2020	SYSTEM	\$5,868.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user graesj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				13	Aug 17, 2020	SYSTEM	(\$5,868.50)	
				13	Aug 17, 2020	SYSTEM	\$5,868.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user graesj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
			- Total	1	1		\$0.00	
	Material - Total						\$0.00	
1020 -	Total						\$0.00	
1030	30 IN. PIPE GROUP A	Material		14	Sep 2, 2020	SYSTEM	(\$5,760.00)	
				14	Sep 2, 2020	SYSTEM	\$5,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0048) due to user graesj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				15	Sep 16, 2020	SYSTEM	(\$5,760.00)	
				15	Sep 16, 2020	SYSTEM	\$5,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user graesj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
1030 -	Total						\$0.00	
1040	36 IN. PIPE GROUP A	Material		5	Apr 16, 2020	SYSTEM	(\$11,760.00)	
				5	Apr 16, 2020	SYSTEM	\$11,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user graesj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1040 -	Total						\$0.00	
1120	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material		14	Sep 2, 2020	SYSTEM	(\$880.00)	
	LIND SECTION			14	Sep 2, 2020	SYSTEM	\$880.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0049) due to user graesj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				15	Sep 16, 2020	SYSTEM	(\$880.00)	
				15	Sep 16, 2020	SYSTEM	\$880.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user graesj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1120 -	Total						\$0.00	
1190	SEEDING - COOL SEASON MIXTURES	Material		9	Jun 16, 2020	SYSTEM	(\$4,940.50)	
				9	Jun 16, 2020	SYSTEM	\$4,940.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user graesj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	Total						\$0.00	
1190 -								
1190 - 1200	SEEDING - WARM SEASON MIXTURES	Overrun	Overrun	12	Aug 4, 2020	SYSTEM	(\$4,275.00)	
		Overrun	Overrun Overrun - T		Aug 4, 2020	SYSTEM	(\$4,275.00)	



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks	
		Туре	Adjustment Type	Number	Date	Ву			
1200 -	Total						(\$4,275.00)		
1280	SLOPE DRAINS	Material		13	Aug 17, 2020	SYSTEM	(\$2,812.50)		
				13	Aug 17, 2020	SYSTEM	\$2,812.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user graesj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
1280 -	Total						\$0.00		
1300	TEMPORARY SEEDING AND MULCHING	Material		9	Jun 16, 2020	SYSTEM	(\$5,005.00)		
				9	Jun 16, 2020	SYSTEM	\$5,005.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user graesj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	
			- Total	1	1		\$0.00		
	Material - Total						\$0.00		
1300 -	Total						\$0.00		
1330	TYPE 1 TURF REINFORCEMENT MAT	Material		9	Jun 16,	SYSTEM	(\$1,674.00)		
	REINFORCEMENT MAT			9	2020 Jun 16, 2020	SYSTEM	\$1,674.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user graesj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	
				10	Jul 1, 2020	SYSTEM	(\$1,674.00)	Estimate Exception is on the current rayment Estimate.	
				10	Jul 1, 2020	SYSTEM	\$1,674.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user morgat overridding Payment Estimate Exception 10 on the current Payment Estimate.	
	- Total						\$0.00		
	Material - Total		_				\$0.00		
1330 -	I - Total						\$0.00		
1350	MISC. TIED CONCRETE BLOCK SYSTEM	Material		14	Sep 2, 2020	SYSTEM	(\$14,850.00)		
	3131EW				14	Sep 2, 2020	SYSTEM	\$14,850.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0050) due to user graesj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
				15	Sep 16, 2020	SYSTEM	(\$14,850.00)		
				15	Sep 16, 2020	SYSTEM	\$14,850.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user graesj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
1350 -	Total						\$0.00		
1390	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT.	Material		7	May 18, 2020	SYSTEM	(\$144,107.60)		
	JOINTS)			7	May 18, 2020	SYSTEM	\$144,107.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user graesj1 overridding Payment	
								Estimate Exception 1 on the current Payment Estimate.	
				8	Jun 2, 2020	SYSTEM	(\$144,107.60)	Estimate Exception 1 on the current Payment Estimate.	
				8		SYSTEM SYSTEM	(\$144,107.60) \$144,107.60	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					2020 Jun 2,	SYSTEM	. , ,	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user graesj1 overridding Payment	
				8	2020 Jun 2, 2020 Jun 16,	SYSTEM	\$144,107.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user graesj1 overridding Payment	
				8 9	2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jul 1,	SYSTEM SYSTEM SYSTEM	\$144,107.60 (\$144,107.60)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user graesj1 overridding Payment	
				8 9 9	2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM	\$144,107.60 (\$144,107.60) \$144,107.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user graesj1 overridding Payment	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1390	CONCRETE PAVEMENT (8 1/2	Material			2020			
	IN. NON-REINFORCED, 15 FT. JOINTS)			11	Jul 16, 2020	SYSTEM	\$144,107.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				12	Aug 4, 2020	SYSTEM	(\$157,082.80)	
				12	Aug 4, 2020	SYSTEM	\$157,082.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user graesj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				13	Aug 17, 2020	SYSTEM	(\$157,082.80)	
				13	Aug 17, 2020	SYSTEM	\$157,082.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user graesj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				14	Sep 2, 2020	SYSTEM	(\$157,082.80)	
				14	Sep 2, 2020	SYSTEM	\$157,082.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0051) due to user graesj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				15	Sep 16, 2020	SYSTEM	(\$336,165.20)	
				15	Sep 16, 2020	SYSTEM	\$336,165.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user graesj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT.	Price		7	May 18, 2020	SYSTEM	(\$2,055.07)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
	JOINTS)			12	Aug 4, 2020	SYSTEM	(\$129.98)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				15	Sep 16, 2020	SYSTEM	(\$1,751.81)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		- Total				(\$3,936.86)		
	Price - Total					(\$3,936.86)		
390 -	Total				_		(\$3,936.86)	
410	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT. JOINTS)	Material		12	Aug 4, 2020	SYSTEM	(\$58,908.08)	
				12	Aug 4, 2020	SYSTEM	\$58,908.08	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				13	Aug 17, 2020	SYSTEM	(\$110,904.08)	
				13	Aug 17, 2020	SYSTEM	\$110,904.08	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				14	Sep 2, 2020	SYSTEM	(\$110,904.08)	
				14	Sep 2,	SYSTEM	\$110,904.08	This adjustment offsets the original system-generated Overrun Payment
					2020			Estimate Item Adjustment (0052) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				15	2020 Sep 16, 2020	SYSTEM	(\$192,938.48)	Estimate Item Adjustment (0052) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					Sep 16,	SYSTEM	(\$192,938.48) \$192,938.48	
			- Total	15	Sep 16, 2020 Sep 16,		. , ,	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user graesj1 overridding Paymen
	Material - Total		- Total	15	Sep 16, 2020 Sep 16,		\$192,938.48	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user graesj1 overridding Paymen
	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT.	Price	- Total	15	Sep 16, 2020 Sep 16,		\$192,938.48	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user graesj1 overridding Paymen Estimate Exception 1 on the current Payment Estimate.
	CONCRETE PAVEMENT (8 1/2	Price	- Total	15	Sep 16, 2020 Sep 16, 2020	SYSTEM	\$192,938.48 \$0.00 \$0.00	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user graesj1 overridding Payment
	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT.	Price	- Total	15 15 12	Sep 16, 2020 Sep 16, 2020 Aug 4, 2020 Aug 17,	SYSTEM	\$192,938.48 \$0.00 \$0.00 (\$590.13)	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user graesj1 overridding Paymen Estimate Exception 1 on the current Payment Estimate. Reference Item Price Adjustment Index Adjustment Type applied is FUEL
	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT.	Price	- Total	15 15 12 13	Sep 16, 2020 Sep 16, 2020 Aug 4, 2020 Aug 17, 2020 Sep 16,	SYSTEM SYSTEM SYSTEM	\$192,938.48 \$0.00 \$0.00 (\$590.13) (\$527.02)	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user graesj1 overridding Paymer Estimate Exception 1 on the current Payment Estimate. Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL



1410 - `		Туре	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
	Total						(\$1,919.62)											
1430	TYPE A2 SHOULDER	Material		7	May 18, 2020	SYSTEM	(\$2,001.46)											
				7	May 18, 2020	SYSTEM	\$2,001.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user graesj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.										
				8	Jun 2, 2020	SYSTEM	(\$2,001.46)											
				8	Jun 2, 2020	SYSTEM	\$2,001.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user graesj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.										
				9	Jun 16, 2020	SYSTEM	(\$2,001.46)											
				9	Jun 16, 2020	SYSTEM	\$2,001.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user graesj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.										
				10	Jul 1, 2020	SYSTEM	(\$2,001.46)											
															10	Jul 1, 2020	SYSTEM	\$2,001.46
				11	Jul 16, 2020	SYSTEM	(\$2,001.46)											
											11	Jul 16, 2020	SYSTEM	\$2,001.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user graesj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.			
								12	Aug 4, 2020	SYSTEM	(\$2,263.66)							
							12	Aug 4, 2020	SYSTEM	\$2,263.66	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user graesj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.							
								13	Aug 17, 2020	SYSTEM	(\$2,263.66)							
						13	Aug 17, 2020	SYSTEM	\$2,263.66	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user graesj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.								
						14	Sep 2, 2020	SYSTEM	(\$2,263.66)									
					14	Sep 2, 2020	SYSTEM	\$2,263.66	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0053) due to user graesj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.									
								15	Sep 16, 2020	SYSTEM	(\$2,263.66)							
				15	Sep 16, 2020	SYSTEM	\$2,263.66	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user graesj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.										
			- Total				\$0.00											
	Material - Total						\$0.00											
	TYPE A2 SHOULDER	Other Item Adjustment	FUEL	7	May 18, 2020	graesj1	(\$31.23)	52.67 S.Y. F.U.F. 0.49 Diff\$1.21 = -\$31.23										
				12	Aug 4, 2020	graesj1	(\$2.87)	Estimate 12 6.9 SY F.U.F. 0.49 Diff\$0.85 = - \$2.87										
			FUEL - Tota	I			(\$34.10)											
	Other Item Adjustment - Total						(\$34.10)											
1 430 - 1 1450	Total TYPE A2 SHOULDER	Material		12	Aug 4,	SYSTEM	(\$34.10) (\$2,357.52)											
				12	2020 Aug 4, 2020	SYSTEM	\$2,357.52	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user graesj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.										
				13	Aug 17, 2020	SYSTEM	(\$4,113.88)	באווומנש באסטקוטור ש טור שוש טעורפות ר מצוופות באעווומנש.										
				13	Aug 17, 2020	SYSTEM	\$4,113.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user graesj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.										
				14	Sep 2,	SYSTEM	(\$4,113.88)	. ,										



			01	- .	0.1.1	0.1.1		
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1450	TYPE A2 SHOULDER	Material			2020			
				14	Sep 2, 2020	SYSTEM	\$4,113.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0054) due to user graesj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				15	Sep 16, 2020	SYSTEM	(\$4,619.28)	
				15	Sep 16, 2020	SYSTEM	\$4,619.28	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user graesj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total	1			\$0.00	
	Material - Total						\$0.00	
	TYPE A2 SHOULDER	Other Item Adjustment	FUEL	12	Aug 4, 2020	graesj1	(\$25.84)	Estimate 12 62.04 SY F.U.F. 0.49 Diff\$0.85 = -\$25.84
				13	Aug 17, 2020	graesj1	(\$19.48)	Estimate 13
				15	Sep 16, 2020	graesj1	(\$5.41)	Estimate 15 F.U.F.=0.49 DIFF.= -\$0.83 13.3 SY = -\$5.41
			FUEL - Tota	1			(\$50.73)	
	Other Item Adjustment - Total						(\$50.73)	
1450 -	Total						(\$50.73)	
1460	GUARDRAIL TYPE D	Construction Stockpile		4	Apr 2, 2020	SYSTEM	\$345.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				13	Aug 17, 2020	SYSTEM	(\$172.75)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$172.75	
	Construction Stockpile - Total						\$172.75	
1460 -	Total						\$172.75	
1470	MGS GUARDRAIL	Construction Stockpile		4	Apr 2, 2020	SYSTEM	\$119,256.51	Payment Estimate Item Adjustment generated Stockpile Transaction
				9	Jun 16, 2020	SYSTEM	(\$26,314.89)	Payment Estimate Item Adjustment generated Stockpile Transaction
				13	Aug 17, 2020	SYSTEM	(\$5,134.61)	Payment Estimate Item Adjustment generated Stockpile Transaction
				14	Sep 2, 2020	SYSTEM	(\$2,177.08)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$85,629.93	
	Construction Stockpile - Total						\$85,629.93	
1470 -	Total						\$85,629.93	
1480	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		4	Apr 2, 2020	SYSTEM	\$8,886.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$8,886.00	
	Construction Stockpile - Total						\$8,886.00	
1480 -	Total						\$8,886.00	
1490	MGS HEIGHT AND BLOCK TRANSITION	Construction Stockpile		4	Apr 2, 2020	SYSTEM	\$265.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$265.00	
	Construction Stockpile - Total						\$265.00	
1490 -	Total						\$265.00	
1500	MGS END ANCHOR	Construction Stockpile		4	Apr 2, 2020	SYSTEM	\$6,958.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				9	Jun 16, 2020	SYSTEM	(\$1,491.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				13	Aug 17, 2020	SYSTEM	(\$497.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				14	Sep 2, 2020	SYSTEM	(\$497.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
	- Total					\$4,473.00		
	Construction Stockpile - Total						\$4,473.00	
1500 -	Total						\$4,473.00	



Image: state in the	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
Image: state in the state in thest in the state in thest in the state in the state in	1510							¢28 822 00	Downent Estimate Item Adjustment generated Stackaile Transaction
Image: market in Stack plan - Total Image: market in Stack plan - Total <thimage: -="" in="" market="" plan="" stack="" th="" total<=""> Image: ma</thimage:>	1310					2020			
Construction Stockpile - Total 941,236.00 942,236.00 150 - Total CONCRETE FOOTNOS, EMBEDOED Material EMBEDOED 13 Aug 17, 2020 SYSTEM \$1,088.00 Init adjustment offeds the original system-generated Overrul Extende Ban Adjustment (2020) as to user grangel Toreitit Extende Exception 30 on the current Payment Estimate Extende Exception 30 on the current Payment Estimate Extende Exception 30 on the current Payment Estimate Exception 30 on the current Payment Estimate Exception 30 on the current Payment Estimate Extende Exception 30 on the current Payment Estimate Estimate Estimate Exception 30 on the current Payment Estimate Estimate Estimate Estimate Estimate Exception 30 on the current Payment Estimate Estimate Exception 30 on the current Payment Estimate Estimate Exception					9		SYSTEM	(\$7,585.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
1510 - Total CONCRETE FOOTNOCS EMBEDICIDED Material EMBEDICIDED Material EMBEDICIDED<				- Total				\$21,238.00	
1710 CONCRETE FOOTNOG EMBEDDED Material EMBEDDED Material EMBEDDED Material Embed Exception 30 on the currer		· ·						\$21,238.00	
EMBEDDED EMBEDDED Image: State in the section of the s								\$21,238.00	
Image: stand bit in Adjustment (00/2) duis to using grangel versific Extinute Exception 30 on the curren Payment Extinute. Image: stand bit in Adjustment (00/2) duis to using grangel versific Extinute. Image: stand bit in Adjustment (00/2) duis to using grangel versific Extinute. Image: stand bit in Adjustment (00/2) duis to using grangel versific Extinute. Image: stand bit in Adjustment (00/2) duis to using grangel versific Extinute. Image: stand bit in Adjustment (00/2) duis to using grangel versific Extinute. Image: stand bit in Adjustment (00/2) duis to using grangel versific Extinute. Image: stand bit in Adjustment (00/2) duis to using grangel versific Extinute. Image: stand bit in Adjustment (00/2) duis to using grangel versific Extinute. Image: stand bit in Adjustment (00/2) duis to using grangel versific Extinute. Image: stand bit in Adjustment (00/2) duis to using grangel versific Extinute. Image: stand bit in Adjustment (00/2) duis to using grangel versific Extinute. Image: stand bit in Adjustment (00/2) duis to using grangel versific Extinute. Image: stand bit in Adjustment (00/2) duis to using grangel versific Extinute. Image: stand bit in Adjustment (00/2) duis to using grangel versific Extinute. Image: stand bit in Adjustment (00/2) duis to using grangel versific Extinute. Image: stand bit in Adjustment (00/2) duis to using grangel versific Extinute. Image: stand bit in Adj	1710		Material			2020		(\$1,008.00)	
4 2020					13		SYSTEM	\$1,008.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0042) due to user graesj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
Image: state in the substrate is consistent of the state is consistent of the					14		SYSTEM	(\$1,008.00)	
Image: state in the second state in the se					14		SYSTEM	\$1,008.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0055) due to user graesj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
Image: state in the ima					15		SYSTEM	(\$1,008.00)	
Material - Total 40.00 1710 - Total 50.00 1710 - Total 50.00 1720 STRUCTURAL STELL POSTS Stockpile - Total Construction Stockpile - Total 10 J.J.1 J.92.75 Payment Estimate Item Adjustment generated Stockpile Tran Stockpile - Total 1720 - Total - Total 521,932.75 Stockpile - Total 521,932.75 1720 - Total - Construction Stockpile - Total 521,932.76 Stockpile - Total 521,932.76 1720 - Total - Total - Stockpile - Total 522,880.00 Payment Estimate Item Adjustment generated Stockpile Tran Stockpile - Total 52,288.00 1720 - Total - Total - Total 52,288.00 Payment Estimate Item Adjustment generated Stockpile Tran Stockpile - Total 1730 - REFORATED SQUARE STOCKPILE - Total - Total 52,288.00 Payment Estimate Item Adjustment offsets the original system-generated Overru Estimate Item Adjustment Odes) due to user grassel overrido Estimate Exception 32 on the current Payment Estimate. 174 - Sep 2, Sep 16, Sep 26, Sep 16, Sep 26, Sep 16, Sep 28, Sep 00, Sep 16, Sep 1					15		SYSTEM	\$1,008.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user graesj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
1720 Total StrucTURAL STEEL POSTS Stockpile Construction Stockpile 10 Jul 1, 2020 SYSTEM \$21,832.75 Payment Estimate Item Adjustment generated Stockpile Trans 2521,932.75 1720 Total - Total 521,932.75 521,932.75 1720 Total 521,932.75 521,932.75 1720 Total 521,932.75 521,932.75 1720 Total 521,932.75 522,85.00 Payment Estimate Item Adjustment generated Stockpile Trans 252,858.00 1720 Total - Total 522,85.00 Payment Estimate Item Adjustment generated Stockpile Trans 52,285.00 120 FORFORATED SOLARE STEEL TUBE Stockpile Total 52,285.00 Payment Estimate Item Adjustment (064) due to user gransel') override Estimate Exception 31 on the current Payment Estimate. 13 Aug 17, 2020 SYSTEM (\$2,520.00) This adjustment offsets the original system-generated Overru Estimate Exception 31 on the current Payment Estimate. 14 Sep 2, 2020 SYSTEM (\$2,520.00) This adjustment offsets the original system-generated Overru Estimate Exception 32 on the current Payment Estimate. 170 - Total - Total 52,000 This adjustment offsets the original system-generated Overru Estimate Exception 32 on the current Payment Estimate. 171 Sup 3 SySTEM S2,252.000 This				- Total				\$0.00	
1720 STRUCTURAL STEEL POSTS Construction Stockpile Construction For an analysis Construction For an analysis Construction For an analysis SYSTEM \$21,932.75 Payment Estimate Item Adjustment generated Stockpile Tran S1,932.75 1720 Total - Total 521,932.75 S21,932.75 S21,932.75 1720 Total Stockpile Construction Stockpile - Total S21,932.75 Payment Estimate Item Adjustment generated Stockpile Tran Stockpile 1720 FORATED SQUARE STEEL (PERFORATED SQUARE STEEL) TUBE) Construction Stockpile - Total S2,268.00 Payment Estimate Item Adjustment generated Stockpile Tran Stockpile 1730 SPSTEM SVSTEM \$2,268.00 Payment Estimate Item Adjustment offsets the original system-generated Overrue Estimate Item Adjustment (054) due to user grassify override Estimate Exception 31 on the current Payment Estimate. 1730 SPSTEM \$2,520.00 This adjustment offsets the original system-generated Overrue Estimate Exception 32 on the current Payment Estimate. 174 Sep 2, 2020 SYSTEM \$2,520.00 This adjustment offsets the original system-generated Overrue Estimate Exception 32 on the current Payment Estimate. 175 Sep 16, 2020 SYSTEM \$2,520.00 This adjustment offs		Material - Total						\$0.00	
Stockpile Stockpile Construction Stockpile Stockpile <thstockpile< th=""> <thstockpile< th=""> <</thstockpile<></thstockpile<>	1710 -	Total						\$0.00	
Construction Stockpile - Total S21,332.75 1720 - Total S21,932.75 1730 BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE) Construction TUBE) Construction Stockpile 14 Sep 2. 2020 SYSTEM \$2,268.00 Payment Estimate Item Adjustment generated Stockpile Tran S2,268.00 Construction Stockpile - Total - Total 52,268.00 Payment Estimate Item Adjustment offsets the original system-generated Overru Estimate Exception 31 on the current Payment Estimate Item Adjustment offsets the original system-generated Overru Estimate Item Adjustment (0f3) due to user grass) override Estimate Item Adjustment (0f3) due to user grass) override Estimate Exception 31 on the current Payment Estimate 113 Aug 17, 2020 SYSTEM \$2,280.00 124 Sep 2, 2020 SYSTEM \$2,520.00 13 Aug 17, 2020 SYSTEM \$2,520.00 14 Sep 2, 2020 SYSTEM \$2,520.00 15 Sep 16, 2020 SYSTEM \$2,520.00 15 Sep 16, 2020 SYSTEM \$2,280.00 1730 - Total - Total \$2,280.00 This adjustment offsets the original system-generated Overru Estimate Exception 32 on the current Payment Estimate 174 Sep 2, 2020 SYSTEM \$2,280.00 This adjustment o	1720	STRUCTURAL STEEL POSTS			10		SYSTEM	\$21,932.75	Payment Estimate Item Adjustment generated Stockpile Transaction
1720 Total \$21,932.75 1730 BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE) Construction Stockpile 14 Sep 2, 2020 SYSTEM \$2,288.00 Payment Estimate Item Adjustment generated Stockpile Tran 7 Construction Stockpile - Total -Total \$2,288.00 Payment Estimate Item Adjustment generated Stockpile Tran 7 Construction Stockpile - Total 13 Aug 17, 2020 SYSTEM \$2,280.00 13 Aug 17, 2020 SYSTEM \$2,520.00 This adjustment offsets the original system-generated Overrule Estimate Etem Adjustment (0643) due to user graes] to verride Estimate Etem Adjustment (0643) due to user graes] to verride Estimate Etem Adjustment (0656) due to user graes] to verride Estimate Etem Adjustment (0656) due to user graes] to verride Estimate Etem Adjustment (0656) due to user graes] to verride Estimate Etem Adjustment (0656) due to user graes] to verride Estimate Etem Adjustment (0656) due to user graes] to verride Estimate Etem Adjustment (0656) due to user graes] to verride Estimate Etem Adjustment (0656) due to user graes] to verride Estimate Etem Adjustment (0657) due to user graes] to verride Estimate Etem Adjustment (0657) due to user graes] to verride Estimate Etem Adjustment (0657) due to user graes] to verride Estimate Etem Adjustment (0657) due to user graes] to verride Estimate Etem Adjustment (0657) due to user graes] to verride Estimate Etem Adjustment (0657) due to user graes] to verride Estimate Etem Adjustment (0570) due to user graes] to verride Estimate Etem Adjustment (0570) due to user graes] to verride Estimate Etem Adjustment (0570) du						\$21,932.75			
1730 BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE) Construction Stockpile - Total 14 Sep 2, 2020 SYSTEM \$2,268.00 Payment Estimate Item Adjustment generated Stockpile Trans Construction Stockpile - Total - Total \$2,268.00 SYSTEM \$2,268.00 BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE) Material Material Aug 17, 2020 SYSTEM \$2,260.00 13 Aug 17, 2020 SYSTEM \$2,520.00 This adjustment offsets the original system-generated Overru Estimate Exception 31 on the current Payment Estimate 14 Sep 2, 2020 SYSTEM \$2,520.00 This adjustment offsets the original system-generated Overru Estimate Exception 31 on the current Payment Estimate. 14 Sep 2, 2020 SYSTEM \$2,520.00 This adjustment offsets the original system-generated Overru Estimate Exception 32 on the current Payment Estimate. 15 Sep 16, 2020 SYSTEM \$2,520.00 This adjustment (0056) due to user graes] override Estimate Exception 39 on the current Payment Estimate. 1750 7 FT. CHANNEL POST Construction Stockpile - Total \$2,020.01 SYSTEM \$2,200.01 1750 7 FT. CHANNEL POST Construction Stockpile - Total S2,268.00 Payment Estimate Item Adjustment generated Stockpile Tra		Construction Stockpile - Total						\$21,932.75	
Image: PERFORATED SQUARE STEEL TUBE) Stockpile Stockpile <thstockpile< th=""> Stockpile <thstockpile< th=""> Stockpile Stockpile</thstockpile<></thstockpile<>	1720 -	Total						\$21,932.75	
Construction Stockpile - Total S2,268.00 BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE) Material TUBE) Material Aug 17, 2020 SYSTEM (\$2,520.00) This adjustment offsets the original system-generated Overru Estimate Item Adjustment (0043) due to user graesj1 overrido Estimate Exception 31 on the current Payment Estimate. 14 Sep 2, 2020 SYSTEM (\$2,520.00) This adjustment offsets the original system-generated Overru Estimate Item Adjustment (0054) due to user graesj1 overrido Estimate Item Adjustment (0055) due to user graesj1 overrido Estimate Item Adjustment (0055) due to user graesj1 overrido Estimate Item Adjustment (0055) due to user graesj1 overrido Estimate Exception 32 on the current Payment Estimate. 15 Sep 16, 2020 SYSTEM (\$2,520.00) 16 Sep 16, 2020 SYSTEM \$2,520.00 170 Total Total \$2,520.00 This adjustment offsets the original system-generated Overru Estimate Item Adjustment (0055) due to user graesj1 overrido Estimate Exception 39 on the current Payment Estimate. 1700 - Total - Total \$0.00 This adjustment offsets the original system-generated Stockpile Tran 1700 - Total - Total \$2,202.0 SYSTEM \$2,30.45 1700 - Total - Total \$2,30.45 Payment Estimate Item Adjustment generated Stockpile Tran	1730	(PERFORATED SQUARE STEEL			14		SYSTEM	\$2,268.00	Payment Estimate Item Adjustment generated Stockpile Transaction
BREAKAWAY ASSEMBLY (PERFORATED SQUARE STELL TUBE) Material TUBE) Material 13 Aug 17, 2020 SYSTEM \$2,520.00 This adjustment offsets the original system-generated Overrul Estimate Exception 31 on the current Payment Estimate. 14 Sep 2, 2020 SYSTEM \$2,520.00 This adjustment offsets the original system-generated Overrul Estimate Exception 31 on the current Payment Estimate. 14 Sep 2, 2020 SYSTEM \$2,520.00 This adjustment offsets the original system-generated Overrul Estimate Exception 32 on the current Payment Estimate. 14 Sep 2, 2020 SYSTEM \$2,520.00 This adjustment offsets the original system-generated Overrul Estimate Exception 32 on the current Payment Estimate. 15 Sep 16, 2020 SYSTEM \$2,520.00 This adjustment offsets the original system-generated Overrul Estimate Exception 32 on the current Payment Estimate. 1700 Total - Total \$2020 SYSTEM \$2,520.00 This adjustment offsets the original system-generated Overrul Estimate Exception 39 on the current Payment Estimate. 1720 - Total - Total \$2020 SYSTEM \$2,02.00 This adjustment offsets the original system-generated Stockpile Trans 1720 - Total 14 Sep 2, 2020 SYSTEM <				- Total				\$2,268.00	
Image: Performance of the performance		Construction Stockpile - Total						\$2,268.00	
Image: state of the state		(PERFORATED SQUARE STEEL	Material		13		SYSTEM	(\$2,520.00)	
 Image: Stand Stan		TUBE)			13		SYSTEM	\$2,520.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) due to user graesj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
Image: state in the image: state in					14		SYSTEM	(\$2,520.00)	
Image: stand					14		SYSTEM	\$2,520.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0056) due to user graesj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
Image: Standard S					15		SYSTEM	(\$2,520.00)	
Material - Total \$0.00 1730 - Total \$2,268.00 1750 - Total \$2,268.00 1750 - Total \$14 Sep 2, 2020 SYSTEM \$230.45 Payment Estimate Item Adjustment generated Stockpile Transport 1750 - Total - Total - Total \$230.45 Payment Estimate Item Adjustment generated Stockpile Transport 1750 - Total - Total \$230.45 \$230.45 \$230.45 1750 - Total - Total \$230.45 \$230.45 1760 7 FT. CHANNEL POST Construction 14 Sep 2, SYSTEM \$101.70 1760 7 FT. CHANNEL POST Construction 14 Sep 2, SYSTEM \$101.70					15		SYSTEM	\$2,520.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user graesj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
1730 - Total 1730 - Total \$2,268.00 1750 - Total Construction Stockpile Stackpile Stackpile 14 Sep 2, 2020 SYSTEM \$230.45 Payment Estimate Item Adjustment generated Stockpile Transformed Stockpile Transformed Stockpile Transformed Stockpile - Total Construction Stockpile - Total \$230.45				- Total				\$0.00	
1750 7 FT. CHANNEL POST DELINEATOR, DOUBLE STACKED WHITE Construction Stockpile 14 Sep 2, 2020 SYSTEM \$230.45 Payment Estimate Item Adjustment generated Stockpile Transition of the tem Adjustment generated Stockpile Transition of tem Adjustment generated Stockpile Transitem Adjustment generat		Material - Total						\$0.00	
DELINEATOR, DOUBLE STACKED WHITE Stockpile - Total 2020 Stockpile Stockpile - Total - Total \$230.45 \$230.45	1730 -	Total						\$2,268.00	
\$230.45 1750 - Total \$230.45 1760 7 FT. CHANNEL POST Construction 14 Sep 2, SYSTEM \$101.70 Payment Estimate Item Adjustment generated Stockpile Tran	1750	DELINEATOR, DOUBLE			14		SYSTEM	\$230.45	Payment Estimate Item Adjustment generated Stockpile Transaction
\$230.45 1750 - Total \$230.45 1760 7 FT. CHANNEL POST Construction 14 Sep 2, SYSTEM \$101.70 Payment Estimate Item Adjustment generated Stockpile Tran				- Total				\$230.45	
1760 7 FT. CHANNEL POST Construction 14 Sep 2, SYSTEM \$101.70 Payment Estimate Item Adjustment generated Stockpile Tran		Construction Stockpile - Total						\$230.45	
	1750 -	Total						\$230.45	
	1760				14		SYSTEM	\$101.70	Payment Estimate Item Adjustment generated Stockpile Transaction
- Total \$101.70				- Total				\$101.70	



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
1760	Construction Stockpile - Total						\$101.70	
1760 -	Total						\$101.70	
1770	7 FT. CHANNEL POST DELINEATOR, YELLOW	Construction Stockpile		14	Sep 2, 2020	SYSTEM	\$67.80	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$67.80	
4770	Construction Stockpile - Total						\$67.80	
1770 - 1780	7 FT. CHANNEL POST	Construction		14	Son 2	SVSTEM	\$67.80	Deument Estimate Item Adjustment generated Steeleile Transastion
1760	DELINEATOR, WHITE/RED		- Total	14	Sep 2, 2020	SYSTEM	\$209.50 \$209.50	Payment Estimate Item Adjustment generated Stockpile Transaction
	Construction Stockpile - Total		- Total				\$209.50	
1780 -							\$209.50	
1790	7 FT. CHANNEL POST DELINEATOR, YELLOW/RED	Construction Stockpile		14	Sep 2, 2020	SYSTEM	\$125.70	Payment Estimate Item Adjustment generated Stockpile Transaction
		·	- Total				\$125.70	
	Construction Stockpile - Total						\$125.70	
1790 -	Total						\$125.70	
1800	2.5 IN. PSST POST - 12 GA.	Construction Stockpile		14	Sep 2, 2020	SYSTEM	\$8,976.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$8,976.00	
	Construction Stockpile - Total						\$8,976.00	
	2.5 IN. PSST POST - 12 GA.	Material		13	Aug 17, 2020	SYSTEM	(\$2,240.00)	
				13	Aug 17, 2020	SYSTEM	\$2,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) due to user graesj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
				14	Sep 2, 2020	SYSTEM	(\$2,240.00)	
				14	Sep 2, 2020	SYSTEM	\$2,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0057) due to user graesj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1800 -	Total						\$8,976.00	
1810	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.			14	Sep 2, 2020	SYSTEM	\$7,250.10	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$7,250.10	
	Construction Stockpile - Total						\$7,250.10	
	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	Material		13	Aug 17, 2020	SYSTEM	(\$2,100.00)	
				13	Aug 17, 2020	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0045) due to user graesj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				14	Sep 2, 2020	SYSTEM	(\$2,100.00)	
				14	Sep 2, 2020	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0058) due to user graesj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1810 -	Total						\$7,250.10	
1820	SH-FLAT SHEET	Construction Stockpile		14	Sep 2, 2020	SYSTEM	\$6,643.90	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$6,643.90	
	Construction Stockpile - Total						\$6,643.90	
	SH-FLAT SHEET	Material		13	Aug 17, 2020	SYSTEM	(\$330.75)	
				13	Aug 17, 2020	SYSTEM	\$330.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0046) due to user graesj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
820		Material	- Total				\$0.00	
	Material - Total						\$0.00	
820 -	Total						\$6,643.90	
830	ST-STRUCTURAL	Construction Stockpile		15	Sep 16, 2020	SYSTEM	\$26,678.64	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$26,678.64	
	Construction Stockpile - Total						\$26,678.64	
830 -	Total						\$26,678.64	
840	SHF-FLAT SHEET FLUORESCENT	Construction Stockpile		14	Sep 2, 2020	SYSTEM	\$5,261.97	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$5,261.97	
	Construction Stockpile - Total						\$5,261.97	
	SHF-FLAT SHEET FLUORESCENT	Material		13	Aug 17, 2020	SYSTEM	(\$909.56)	
				13	Aug 17, 2020	SYSTEM	\$909.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0047) due to user graesj1 overridding Payme Estimate Exception 35 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
840 -	Total						\$5,261.97	
980	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Construction Stockpile		7	May 18, 2020	SYSTEM	\$12,330.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			11	Jul 16, 2020	SYSTEM	(\$6,294.81)	Payment Estimate Item Adjustment generated Stockpile Transaction	
			12	Aug 4, 2020	SYSTEM	(\$5,692.69)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				13	Aug 17, 2020	SYSTEM	(\$171.25)	Payment Estimate Item Adjustment generated Stockpile Transaction
		- Total				\$171.25		
	Construction Stockpile - Total						\$171.25	
980 - 985	Total PRE-BORE FOR PILING	Overrun	Overrun	12	Aug 4,	SYSTEM	\$171.25 (\$6,270.00)	
					2020			
			Overrun - T	otal			(\$6,270.00)	
	Overrun - Total						(\$6,270.00)	
985 -	Total						(\$6,270.00)	
990	PILE POINT REINFORCEMENT	Construction Stockpile		7	May 18, 2020	SYSTEM	\$1,200.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				11	Jul 16, 2020	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
				12	Aug 4, 2020	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
	Total						\$0.00	
2000	CLASS B CONCRETE (SUBSTRUCTURE)	Material		13	Aug 17, 2020	SYSTEM	(\$28,160.00)	
				13	Aug 17, 2020	SYSTEM	\$28,160.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0048) due to user graesj1 overridding Payme Estimate Exception 21 on the current Payment Estimate.
				14	Sep 2, 2020	SYSTEM	(\$28,160.00)	
				14	Sep 2, 2020	SYSTEM	\$28,160.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0059) due to user graesj1 overridding Payme Estimate Exception 19 on the current Payment Estimate.
				15	Sep 16, 2020	SYSTEM	(\$28,160.00)	
				15	Sep 16,	SYSTEM	\$28,160.00	This adjustment offsets the original system-generated Overrun Payment
				15	2020	OTOTEM	\$20,100.00	Estimate Item Adjustment (0034) due to user graesj1 overridding Payme Estimate Exception 28 on the current Payment Estimate.



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks	
		Туре	Adjustment Type	Number	Date	Ву			
2000	Material - Total						\$0.00		
2000 -	Total						\$0.00		
2040	CONDUIT SYSTEM ON STRUCTURE	Material		15	Sep 16, 2020	SYSTEM	(\$4,669.00)		
				15	Sep 16, 2020	SYSTEM	\$4,669.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user graesj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
2040 -							\$0.00		
2110	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Construction Stockpile	Total	7	May 18, 2020	SYSTEM	\$12,330.00 \$12,330.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
	Construction Stockpile - Total	- Total				\$12,330.00			
2110 -	· ·						\$12,330.00		
2120	PILE POINT REINFORCEMENT	Construction Stockpile		7	May 18, 2020	SYSTEM	\$1,200.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			- Total				\$1,200.00		
	Construction Stockpile - Total						\$1,200.00		
2120 -	Total						\$1,200.00		
2250	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Construction Stockpile		10	Jul 1, 2020	SYSTEM	\$89,306.62	Payment Estimate Item Adjustment generated Stockpile Transaction	
				12	Aug 4, 2020	SYSTEM	(\$23,841.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				13	Aug 17, 2020	SYSTEM	(\$20,803.48)	Payment Estimate Item Adjustment generated Stockpile Transaction	
	- Total						\$44,662.14		
	Construction Stockpile - Total		10			\$44,662.14			
	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material	Material		12	Aug 4, 2020 Aug 4,	SYSTEM	(\$91,800.00) \$91,800.00	This adjustment offsets the original system-generated Overrun Payment
				12	2020	STOTEM	φ91,000.00	Estimate Item Adjustment (0021) due to user graesj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	
				13	Aug 17, 2020	SYSTEM	(\$171,904.00)		
				13	Aug 17, 2020	SYSTEM	\$171,904.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0049) due to user graesj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	
				14	Sep 2, 2020	SYSTEM	(\$171,904.00)		
				14	Sep 2, 2020	SYSTEM	\$171,904.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0060) due to user graesj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	
				15	Sep 16, 2020	SYSTEM	(\$171,904.00)		
				15	Sep 16, 2020	SYSTEM	\$171,904.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user graesj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
2250 -							\$44,662.14		
2280	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Construction Stockpile		10	Jul 1, 2020	SYSTEM	\$95,745.73	Payment Estimate Item Adjustment generated Stockpile Transaction	
				12	Aug 4, 2020 Aug 17,	SYSTEM	(\$23,834.91)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction	
				15	Aug 17, 2020	STOTEM	(φ24,011.47)		
	- Total						\$47,899.35		
	Construction Stockpile - Total						\$47,899.35		
	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		12	Aug 4, 2020	SYSTEM	(\$91,800.00)		



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2280	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		12	Aug 4, 2020	SYSTEM	\$91,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user graesj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				13	Aug 17, 2020	SYSTEM	(\$184,280.00)	
				13	Aug 17, 2020	SYSTEM	\$184,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0050) due to user graesj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				14	Sep 2, 2020	SYSTEM	(\$184,280.00)	
				14	Sep 2, 2020	SYSTEM	\$184,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0061) due to user graesj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				15	Sep 16, 2020	SYSTEM	(\$184,280.00)	
				15	Sep 16, 2020	SYSTEM	\$184,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user graesj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
2280 -	2280 - Total						\$47,899.35	
Overall - Total							\$167,989.53	