#### Pay Estimate Created Date: June 3, 2020

Progress Estima 10	ate Number	Contract ID Prime Contractor	191018-D04 Joe's Bridge & Grad		Pay Period Start Pay Period End		Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,409,119.51 \$51,465.12 \$1,460,584.63		
Approval Date								By User		
June 3, 2020	Generated and Approved (and should be considered Draft) at the Project Office Level by									
June 3, 2020		F	Reviewed and Appro	oved (and sh	ould be consider	ed Draft) at the	Resident Engineer Level by	abbote1		
June 4, 2020			F	Reviewed ar	d Approved at th	e Central Offic	e Controllers Office Level by	greggd1		
Original Compl	Completion Date Current Completion Date Actual Completion Date % of Current Contract Amount									
July 1, 20	July 1, 2020 July 1, 2020 81.67%									

#### No Milestones Exist for Contract

Contract Total Pa	y For Estimate No. 10				
		This Estimate	Previous	To Date	
191018-D04					
	Total Posted Items Pay	\$142,604.00	\$1,050,235.71	\$1,192,839.71	
	Gross Item Adjustments	\$0.00	\$90,314.90	\$90,314.90	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			<b>\$1,140,550.61</b>	\$1,283,154.61	
Contract Total Pa	yable This Estimate:	\$142,604.00			

#### Items Paid This Estimate Period

Project Number	Line Number	ltem Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3241	0590	7034213	SLAB ON CONCRETE I-GIRDER	SQYD	\$385.000	134	\$51,590.00
	0610	7056002	TYPE 4 (45 IN.), PRESTRESSED CONCRETE I- GIRDER	LF	\$198.000	443	\$87,714.00
	0670	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	EA	\$275.000	12	\$3,300.00
Project J5P324	1 - Total						\$142,604.00
<b>Overall - Total</b>	\$142,604.00						

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
I5P3241	0040	EMBANKMENT IN PLACE	MaterialCredit			1,000	\$21.00	\$21,000.00
	0040	EMBANKMENT IN PLACE	Material			-1,000	\$21.00	(\$21,000.00)
	0050	COMPACTING EMBANKMENT	MaterialCredit			136	\$5.00	\$680.00
	0050	COMPACTING EMBANKMENT	Material			-136	\$5.00	(\$680.00)
	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	MaterialCredit			542	\$8.99	\$4,872.58
	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-542	\$8.99	(\$4,872.58)
	0070	GRAVEL (A) OR CRUSHED STONE (B)	MaterialCredit			71	\$12.00	\$852.00
	0070	GRAVEL (A) OR CRUSHED STONE (B)	Material			-71	\$12.00	(\$852.00)
	0080	TYPE A2 SHOULDER	MaterialCredit			176.3	\$38.24	\$6,741.71
	0080	TYPE A2 SHOULDER	Material			-176.3	\$38.24	(\$6,741.71)
	0400	SEEDING - COOL SEASON MIXTURES	MaterialCredit			0.25	\$10,800.00	\$2,700.00
	0400	SEEDING - COOL SEASON MIXTURES	Material			-0.25	\$10,800.00	(\$2,700.00)
	0450	TYPE C BERM	MaterialCredit			110	\$10.00	\$1,100.00



#### Pay Estimate Created Date: June 3, 2020

Progr		imate Number Contra 0 Prime		-D04 ridge & Grading, Inc.			r Amount \$	1,409,119.51 51,465.12 1,460,584.63
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3241	0450	TYPE C BE	RM Material			-110	\$10.00	(\$1,100.00
	0460	MGS GUARDF	AIL MaterialCredit			12.5	\$30.00	\$375.00
	0460	MGS GUARDF	AIL Material			-12.5	\$30.00	(\$375.0
	0470	MGS BRIDGE APPRO/ TRANSITION SECT (REGULAR/NO CU	ION			2	\$3,200.00	\$6,400.00
	0470	MGS BRIDGE APPRO/ TRANSITION SECT (REGULAR/NO CU	ION			-2	\$3,200.00	(\$6,400.0
	0480	TYPE A CRASHWOR END TERMINAL (MA				2	\$3,000.00	\$6,000.0
	0480	TYPE A CRASHWOR END TERMINAL (MA				-2	\$3,000.00	(\$6,000.0
	0530	BRIDGE APPROACH S (MINOR RC				64	\$150.00	\$9,600.0
	0530	BRIDGE APPROACH S (MINOR RC				-64	\$150.00	(\$9,600.0
	0580	CLASS B CONCR (SUBSTRUCTU				48.2	\$1,200.00	\$57,840.0
	0580	CLASS B CONCR (SUBSTRUCTU				-48.2	\$1,200.00	(\$57,840.0
	0590	SLAB ON CONCRET GIRI				386	\$385.00	\$148,610.0
	0590	SLAB ON CONCRET GIRI				-520	\$385.00	(\$200,200.0
	0590	SLAB ON CONCRET GIRI			Material Credit Recovery	T		(\$148,610.0
	0590	SLAB ON CONCRET GIRI			Material Credit			\$200,200.0
	0600	SAFETY BARRIER CU	JRB MaterialCredit			243.5	\$98.00	\$23,863.0
	0600	SAFETY BARRIER CU	JRB Material			-243.5	\$98.00	(\$23,863.0
	0650	SLAB DR	AIN MaterialCredit			6	\$350.00	\$2,100.0
	0650	SLAB DR	AIN Material			-6	\$350.00	(\$2,100.0
	0660	VERTICAL DRAIN AT E	ND MaterialCredit			2	\$2,000.00	\$4,000.0
	0660	VERTICAL DRAIN AT E	END Material			-2	\$2,000.00	(\$4,000.0
otal								\$0.0



# Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Informatio	n					
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work					
J5P3241	FAF 49-1(18)	Bridge replacement	49	CRAWFORD	west of Cherryville ove	rest of Cherryville over Dry Fork Creek						
Totals by .	Job Numb	ers										
J5P3241		ed Item Pay s Item Adjustn		s Item Pay	This Estimate \$142,604.00 \$0.00 <b>\$142,604.00</b>	Previous \$1,050,235.71 \$90,314.90 <b>\$1,140,550.61</b>	<b>To Date</b> \$1,192,839.71 \$90,314.90 <b>\$1,283,154.61</b>					
	Liqui	itive centive dated Damage r Contract Adji		5	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00						



# Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 2035500, Project Item Line Number 0040, Material Set 203550096, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 2036000, Project Item Line Number 0050, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 3040504, Project Item Line Number 0060, Material Set 304050496, Material 1007T1ABLD.:T5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLD.:T5 is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 3105003, Project Item Line Number 0070, Material Set 310500396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 4010150, Project Item Line Number 0080, Material Set 401015096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 5031011A, Project Item Line Number 0530, Material Set 5031011A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 5031011A, Project Item Line Number 0530, Material Set 5031011A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 5031011A, Project Item Line Number 0530, Material Set 5031011A96, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 5031011A, Project Item Line Number 0530, Material Set 5031011A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 5031011A, Project Item Line Number 0530, Material Set 5031011A96, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 5031011A, Project Item Line Number 0530, Material Set 5031011A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 5031011A, Project Item Line Number 0530, Material Set 5031011A96, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 5031011A, Project Item Line Number 0530, Material Set 5031011A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 5031011A, Project Item Line Number 0530, Material Set 5031011A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4* (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 6061060, Project Item Line Number 0460, Material Set 606106096, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 6061069, Project Item Line Number 0470, Material Set 6061069, Material 1040GRAB - Bridge Anchor Section, Acceptance Action Generic 1040GRAB is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 6063014, Project Item Line Number 0480, Material Set 6063014, Material 1040GRCWA - Crashworthy End Terminal Type A, Acceptance Action Generic 1040GRCWA is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 7032003, Project Item Line Number 0580, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 7032003, Project Item Line Number 0580, Material Set 703200396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 7032003, Project Item Line Number 0580, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 7034213, Project Item Line Number 0590, Material Set 703421396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 7034213, Project Item Line Number 0590, Material Set 703421396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 7034213, Project Item Line Number 0590, Material Set 703421396, Material 0705DPRCPS30 - Prestress Conc Deck Panel 3" (75 mm), Acceptance Action Generic 0705DPRCPS30 is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 7034213, Project Item Line Number 0590, Material Set 703421396, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance	Waiting on QA	linkd1	Acknowledged



# Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Action Generic 0501CCB2.A is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 7034213, Project Item Line Number 0590, Material Set 703421396, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 7034213, Project Item Line Number 0590, Material Set 703421396, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 7034213, Project Item Line Number 0590, Material Set 703421396, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 7034215, Project Item Line Number 0600, Material Set 703421596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 7034215, Project Item Line Number 0600, Material Set 703421596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 7034215, Project Item Line Number 0600, Material Set 703421596, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 7034215, Project Item Line Number 0600, Material Set 703421596, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 7034215, Project Item Line Number 0600, Material Set 703421596, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 7123610, Project Item Line Number 0650, Material Set 7123610, Material 0712STDRSB - Slab Drain, Acceptance Action Generic 0712STDRSB is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 7151001, Project Item Line Number 0660, Material Set 7151001, Material 0715DRVT - Vertical Drain at End Bents, Acceptance Action Generic 0715DRVT is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 8051000A, Project Item Line Number 0400, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 8051000A, Project Item Line Number 0400, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5P3241, Item 8061050, Project Item Line Number 0450, Material Set 806105096, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Waiting on QA	linkd1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191018-D04, Contract Project J5P3241, Project Item Line Number 0340, Contract Line Item Number 0340, Item 6208076, Minor Item.	Waiting on QA	linkd1	Acknowledged



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

Vote: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted am	ount at th	e time the	e Estimate v	vas Gen	erated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191018-D04	J5P3241	0001	0010	2019901	MISC.CLEARING AND GRUBBING	1.00	0.00	1.00	LS	1.00	\$3,500.00	\$3,500.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.50	\$18,000.00	\$9,000.00
		0001	0030	2031000	CLASS A EXCAVATION	136.00	0.00	136.00	CUYD	136.00	\$15.00	\$2,040.00
		0001	0040	2035500	EMBANKMENT IN PLACE	1,034.00	0.00	1,034.00	CUYD	1,000.00	\$21.00	\$21,000.00
		0001	0050	2036000	COMPACTING EMBANKMENT	136.00	0.00	136.00	CUYD	136.00	\$5.00	\$680.00
		0001	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	542.00	0.00	542.00	SQYD	542.00	\$8.99	\$4,872.58
		0001	0070	3105003	GRAVEL (A) OR CRUSHED STONE (B)	71.00	0.00	71.00	SQYD	71.00	\$12.00	\$852.00
		0001	0080	4010150	TYPE A2 SHOULDER	341.60	0.00	341.60	SQYD	176.30	\$38.24	\$6,741.71
		0001	0090	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	160.40	0.00	160.40	TONS	0.00	\$82.64	\$0.00
		0001	0100	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	62.20	0.00	62.20	TONS	0.00	\$82.64	\$0.00
		0001	0110	4019905	MISC.OPTIONAL PAVEMENT	542.00	0.00	542.00	SQYD	433.00	\$49.10	\$21,260.30
		0001	0120	4071006	TACK COAT - POLYMER MODIFIED	120.00	0.00	120.00	GAL	0.00	\$21.50	\$0.00
		0001	0130	6079903	MISC.BARBED WIRE FENCE	271.00	0.00	271.00	LF	0.00	\$16.00	\$0.00
		0001	0140	6085008	PAVED APPROACH, 8 IN.	151.30	0.00	151.30	SQYD	0.00	\$40.41	\$0.00
		0001	0150	6113020	FURNISHING TYPE 2 ROCK BLANKET	2,598.00	0.00	2,598.00	CUYD	2,000.00	\$20.00	\$40,000.00
		0001	0160	6113040	PLACING TYPE 2 ROCK BLANKET	2,598.00	0.00	2,598.00	CUYD	2,000.00	\$28.00	\$56,000.00
		0001	0170	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARRELS)	2.00	0.00	2.00	EA	2.00	\$1,800.00	\$3,600.00
		0001	0180	6122020	REPLACEMENT SAND BARREL	2.00	0.00	2.00	EA	0.00	\$150.00	\$0.00
		0001	0190	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0200	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	EA	0.00	\$5,000.00	\$0.00
		0001	0210	6161005	CONSTRUCTION SIGNS	435.00	0.00	435.00	SQFT	435.00	\$7.50	\$3,262.50
		0001	0220	6161008	ADVANCED WARNING RAIL SYSTEM	6.00	0.00	6.00	EA	6.00	\$50.00	\$300.00
		0001	0230	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	4.00	\$25.00	\$100.00
		0001	0240	6161025	CHANNELIZER (TRIM LINE)	26.00	0.00	26.00	EA	26.00	\$23.00	\$598.00
		0001	0250	6161030	TYPE III MOVEABLE BARRICADE	1.00	0.00	1.00	EA	1.00	\$175.00	\$175.00
		0001	0260	6161040	FLASHING ARROW PANEL	1.00	0.00	1.00	EA	0.00	\$800.00	\$0.00
		0001	0270	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	2.00	0.00	2.00	EA	2.00	\$15,000.00	\$30,000.00
		0001	0280	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR	340.00	0.00	340.00	LF	340.00	\$30.00	\$10,200.00
			0290	64750404	FURNISHED / RETAINED RELOCATING TEMPORARY TRAFFIC BARRIER	250.00	0.00	250.00	LF	250.00	\$17.00	¢4.050.00
		0001									\$17.00	\$4,250.00
		0001	0300	6181000	MOBILIZATION	1.00	-1.00	0.00	LS		,	\$0.00
		0001	0301	6181000		0.00		1.00	LS		\$144,636.00	\$144,636.00
		0001	0310	6191000		678.00	0.00	678.00	LF	0.00	\$3.00	\$0.00
		0001	0320	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	2,184.00	0.00	2,184.00	LF	0.00	\$0.50	\$0.00
		0001	0330	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,366.00	0.00	1,366.00	LF	0.00	\$0.50	\$0.00
		0001	0340	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	3,290.00	0.00	3,290.00	LF	3,502.00	\$0.75	\$2,626.50
		0001	0350	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,483.00	0.00	1,483.00	SQYD	0.00	\$7.35	\$0.00
		0001	0360	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,299.00	0.00	1,299.00	SQYD	700.00	\$3.00	\$2,100.00
		0001	0370	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	9.10	0.00	9.10	STA	0.00	\$265.00	\$0.00
		0001	0380	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	8.30	0.00	8.30	STA	0.00	\$265.00	\$0.00
		0001	0390	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$8,000.00	\$8,000.00
		0001	0400	8051000A	SEEDING - COOL SEASON MIXTURES	0.50	0.00	0.50	ACRE	0.25	\$10,800.00	\$2,700.00
		0001 0410 8061004 SEDIMENT TRAP ROCK			4.00	0.00	4.00	CUYD	0.00	\$105.00	\$0.00	
		0001	0420	8061005	ROCK DITCH CHECK	180.00	0.00	180.00	LF	0.00	\$12.50	\$0.00
		0001	0430	8061016	SEDIMENT REMOVAL	37.00	0.00	37.00	CUYD	0.00	\$10.00	\$0.00
		0001	0440	8061019	SILT FENCE	1,993.00	0.00	1,993.00	LF	465.00	\$2.40	\$1,116.00
		0001	0 1-0	0001010		.,555.00	0.00	.,000.00	-	-00.00	ψ2.40	φ1,110.00



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
91018-D04	J5P3241	0001	0450	8061050	TYPE C BERM	170.00	0.00	170.00	LF	110.00	\$10.00	\$1,100.00
		0010	0460	6061060	MGS GUARDRAIL	25.00	0.00	25.00	LF	12.50	\$30.00	\$375.00
		0010	0470	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	2.00	\$3,200.00	\$6,400.00
		0010	0480	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	2.00	\$3,000.00	\$6,000.00
		0040	0490	9039902	MISC.MISC. SIGN RELOCATION	4.00	0.00	4.00	EA	0.00	\$250.00	\$0.00
		0070	0500	2061000	CLASS 1 EXCAVATION	80.00	0.00	80.00	CUYD	80.00	\$25.00	\$2,000.00
		0070	0510	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	1.00	\$30,000.00	\$30,000.00
		0070	0520	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$60,000.00	\$60,000.00
		0070	0530	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	128.00	0.00	128.00	SQYD	64.00	\$150.00	\$9,600.00
		0070	0540	7021214	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	565.00	165.00	730.00	LF	730.00	\$96.00	\$70,080.00
		0070	0550	7025002	PILE WAVE ANALYSIS	2.00	0.00	2.00	EA	2.00	\$1,000.00	\$2,000.00
		0070	0560	7026000	PRE-BORE FOR PILING	360.00	132.00	492.00	LF	492.00	\$150.00	\$73,800.00
		0070	0570	7027000	PILE POINT REINFORCEMENT	20.00	0.00	20.00	EA	20.00	\$160.00	\$3,200.00
		0070	0580	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	48.20	0.00	48.20	CUYD	48.20	\$1,200.00	\$57,840.00
		0070	0590	7034213	SLAB ON CONCRETE I-GIRDER	765.00	0.00	765.00	SQYD	520.00	\$385.00	\$200,200.00
		0070	0600	7034215	SAFETY BARRIER CURB	487.00	0.00	487.00	LF	243.50	\$98.00	\$23,863.00
		0070	0610	7056002	TYPE 4 (45 IN.), PRESTRESSED CONCRETE I-GIRDER	887.00	0.00	887.00	LF	887.00	\$198.00	\$175,626.00
		0070	0620	7061060	REINFORCING STEEL (BRIDGES)	2,990.00	0.00	2,990.00	LB	2,990.00	\$2.00	\$5,980.00
		0070	0630	7061070	MECHANICAL BAR SPLICE	841.00	0.00	841.00	EA	841.00	\$36.00	\$30,276.00
		0070	0640	7123301	STEEL INTERMEDIATE DIAPHRAGM FOR P/S CONCRETE GIRDERS	9.00	0.00	9.00	EA	0.00	\$650.00	\$0.00
		0070	0650	7123610	SLAB DRAIN	11.00	0.00	11.00	EA	6.00	\$350.00	\$2,100.00
		0070	0660	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000.00
		0070	0670	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	24.00	0.00	24.00	EA	24.00	\$275.00	\$6,600.00
		0001	5001	6161098A	HANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION ITERFACE, CONTRACTOR FURNISHED, CONTRACTOR ETAINED							\$12,300.00
		0001	5002	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	0.00	40.00	40.00	EA	40.00	\$88.13	\$3,525.12
		0001	5003	1099901	MISC.Adjustment Mobilization for Contract Bond: Bond Payment.	0.00	1.00	1.00	LS	1.00	\$25,364.00	\$25,364.00
	Project J	5P3241 - To	otal Value	Posted to D	bate as of Report Generated Date							\$1,192,839.71
1018-D04 Ove	18-D04 Overall - Total Value Posted to Date as of Report Generated Date										\$1,192,839.71	



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project:	roject: J5P3241											
Line Number	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0590	7034213	SLAB ON CONCRETE I-GIRDER	5/29/20	6/3/20	134.00	SQYD	35% for forming deck.	105+75		108+00		
0610	7056002	TYPE 4 (45 IN.), PRESTRESSED CONC I-GIRD	5/19/20	6/3/20	443.00	LF	Stage 2, All 6 girders. All Spans Girder's 3-4 of each span.	105+75		108+00		
0670	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	5/18/20	6/3/20	12.00	EA	Bent Caps 1-4					

The information below this line are details from Line Item agency views. No Agency View Details Exist



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0040	EMBANKMENT IN PLACE	Material	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	4	Mar 2, 2020	SYSTEM	(\$8,400.00)	
				5	Mar 17, 2020	SYSTEM	(\$8,400.00)	
				6	Apr 3, 2020	SYSTEM	(\$16,800.00)	
				7	Apr 16, 2020	SYSTEM	(\$21,000.00)	
				8	May 5, 2020	SYSTEM	(\$21,000.00)	
				9	May 19, 2020	SYSTEM	(\$21,000.00)	
				10	Jun 3, 2020	SYSTEM	(\$21,000.00)	
			- Total				(\$117,600.00)	
	Material - Total						(\$117,600.00)	
	EMBANKMENT IN PLACE	MaterialCredit		5	Mar 17, 2020	SYSTEM	\$8,400.00	
				6	Apr 3, 2020	SYSTEM	\$8,400.00	
				7	Apr 16, 2020	SYSTEM	\$16,800.00	
				8	May 5, 2020	SYSTEM	\$21,000.00	
				9	May 19, 2020	SYSTEM	\$21,000.00	
				10	Jun 3, 2020	SYSTEM	\$21,000.00	
			- Total				\$96,600.00	
	MaterialCredit - Total						\$96,600.00	
	EMBANKMENT IN PLACE	Other Item Adjustment		4	Mar 2, 2020	linkd1	\$8,400.00	Material Correction
				6	Apr 3, 2020	linkd1	(\$8,400.00)	Material Cr Takeaway
				6	Apr 3, 2020	linkd1	\$16,800.00	Material Credit
				7	Apr 16, 2020	linkd1	(\$16,800.00)	Material Credit Recovery
				7	Apr 16, 2020	linkd1	\$21,000.00	Material Credit
			- Total				\$21,000.00	
	Other Item Adjustment - Total						\$21,000.00	
0040 -	- Total						\$0.00	
0050	COMPACTING EMBANKMENT	Material		7	Apr 16, 2020	SYSTEM	(\$680.00)	
				8	May 5, 2020	SYSTEM	(\$680.00)	
				9	May 19, 2020	SYSTEM	(\$680.00)	
				10	Jun 3, 2020	SYSTEM	(\$680.00)	
			- Total				(\$2,720.00)	
	Material - Total						(\$2,720.00)	
	COMPACTING EMBANKMENT	MaterialCredit		8	May 5, 2020	SYSTEM	\$680.00	
				9	May 19, 2020	SYSTEM	\$680.00	
				10	Jun 3, 2020	SYSTEM	\$680.00	
			- Total				\$2,040.00	
	MaterialCredit - Total						\$2,040.00	
	COMPACTING EMBANKMENT	Other Item		7	Apr 16,	linkd1	\$680.00	Material Credit



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0050		Adjustment			2020			
	Other Kom Adjustment Tetal		- Total				\$680.00	
0050 -	Other Item Adjustment - Total						\$680.00 \$0.00	
0060	TYPE 5 AGGREGATE FOR BASE (4 IN.	Material		7	Apr 16,	SYSTEM	(\$4,872.58)	
	THICK)				2020		(+ ., =)	
				8	May 5, 2020	SYSTEM	(\$4,872.58)	
				9	May 19, 2020	SYSTEM	(\$4,872.58)	
				10	Jun 3, 2020	SYSTEM	(\$4,872.58)	
			- Total				(\$19,490.32)	
	Material - Total						(\$19,490.32)	
	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	MaterialCredit		8	May 5, 2020	SYSTEM	\$4,872.58	
				9	May 19, 2020	SYSTEM	\$4,872.58	
				10	Jun 3, 2020	SYSTEM	\$4,872.58	
			- Total				\$14,617.74	
	MaterialCredit - Total						\$14,617.74	
	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Other Item Adjustment		7	Apr 16, 2020	linkd1	\$4,872.58	Material Credit
			- Total				\$4,872.58	
	Other Item Adjustment - Total						\$4,872.58	
0060 -	Total						\$0.00	
0070	GRAVEL (A) OR CRUSHED STONE (B)	Material		2	Feb 3, 2020	SYSTEM	(\$852.00)	
				3	Feb 18, 2020	SYSTEM	(\$852.00)	
				4	Mar 2, 2020	SYSTEM	(\$852.00)	
				5	Mar 17, 2020	SYSTEM	(\$852.00)	
				6	Apr 3, 2020	SYSTEM	(\$852.00)	
				7	Apr 16, 2020	SYSTEM	(\$852.00)	
				8	May 5, 2020	SYSTEM	(\$852.00)	
				9	May 19, 2020	SYSTEM	(\$852.00)	
				10	Jun 3, 2020	SYSTEM	(\$852.00)	
			- Total				(\$7,668.00)	
	Material - Total						(\$7,668.00)	
	GRAVEL (A) OR CRUSHED STONE (B)	MaterialCredit		3	Feb 18, 2020	SYSTEM	\$852.00	
				4	Mar 2, 2020	SYSTEM	\$852.00	
				5	Mar 17, 2020	SYSTEM	\$852.00	
				6	Apr 3, 2020	SYSTEM	\$852.00	
				7	Apr 16, 2020	SYSTEM	\$852.00	
				8	May 5, 2020	SYSTEM	\$852.00	



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0070	GRAVEL (A) OR CRUSHED STONE (B)	MaterialCredit	Туре	10	Jun 3,	SYSTEM	\$852.00	
	(.)				2020			
			- Total				\$6,816.00	
	MaterialCredit - Total						\$6,816.00	
	GRAVEL (A) OR CRUSHED STONE (B)	Other Item Adjustment		2	Feb 3, 2020	linkd1	\$852.00	Adjustment for material deficiency.
			- Total				\$852.00	
	Other Item Adjustment - Total						\$852.00	
0070 -							\$0.00	
0800	TYPE A2 SHOULDER	Material		8	May 5, 2020	SYSTEM	(\$6,741.71)	
				9	May 19, 2020	SYSTEM	(\$6,741.71)	
				10	Jun 3, 2020	SYSTEM	(\$6,741.71)	
			- Total				(\$20,225.13)	
	Material - Total						(\$20,225.13)	
	TYPE A2 SHOULDER	MaterialCredit		9	May 19, 2020	SYSTEM	\$6,741.71	
				10	Jun 3, 2020	SYSTEM	\$6,741.71	
			- Total				\$13,483.42	
	MaterialCredit - Total						\$13,483.42	
	TYPE A2 SHOULDER	Other Item Adjustment		8	May 5, 2020	linkd1	\$6,741.74	Material Credit
			- Total				\$6,741.74	
	Other Item Adjustment - Total						\$6,741.74	
0080 -	Total						\$0.03	
0150	FURNISHING TYPE 2 ROCK BLANKET	Material		4	Mar 2, 2020	SYSTEM	(\$16,000.00)	
				5	Mar 17, 2020	SYSTEM	(\$16,000.00)	
			- Total				(\$32,000.00)	
	Material - Total						(\$32,000.00)	
	FURNISHING TYPE 2 ROCK BLANKET	MaterialCredit		5	Mar 17, 2020	SYSTEM	\$16,000.00	
				6	Apr 3, 2020	SYSTEM	\$16,000.00	
			- Total				\$32,000.00	
	MaterialCredit - Total						\$32,000.00	
	FURNISHING TYPE 2 ROCK BLANKET	Other Item Adjustment		4	Mar 2, 2020	linkd1	\$16,000.00	Material Credit
				6	Apr 3, 2020	linkd1	(\$16,000.00)	Material Credit Recovery
			- Total				\$0.00	
	Other Item Adjustment - Total						\$0.00	
0150 -	Total						\$0.00	
0210	CONSTRUCTION SIGNS	Material		4	Mar 2, 2020	SYSTEM	(\$3,262.50)	
			- Total				(\$3,262.50)	
	Material - Total						(\$3,262.50)	
	CONSTRUCTION SIGNS	MaterialCredit		5	Mar 17, 2020	SYSTEM	\$3,262.50	
			- Total				\$3,262.50	
	MaterialCredit - Total						\$3,262.50	
	CONSTRUCTION SIGNS	Other Item Adjustment		4	Mar 2, 2020	linkd1	\$3,262.50	Material Credit
				5	Mar 17, 2020	linkd1	(\$3,262.50)	Remove Material Credit



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0210		Other Item Adjustment	- Total				\$0.00	
	Other Item Adjustment - Total						\$0.00	
0210 -	Total						\$0.00	
0220	ADVANCED WARNING RAIL SYSTEM	Material		2	Feb 3, 2020	SYSTEM	(\$300.00)	
				3	Feb 18, 2020	SYSTEM	(\$300.00)	
				4	Mar 2, 2020	SYSTEM	(\$300.00)	
			- Total				(\$900.00)	
	Material - Total						(\$900.00)	
	ADVANCED WARNING RAIL SYSTEM	MaterialCredit		3	Feb 18, 2020	SYSTEM	\$300.00	
				4	Mar 2, 2020	SYSTEM	\$300.00	
				5	Mar 17, 2020	SYSTEM	\$300.00	
			- Total				\$900.00	
	MaterialCredit - Total			_	_		\$900.00	
	ADVANCED WARNING RAIL SYSTEM	Other Item Adjustment		2	Feb 3, 2020	linkd1	\$300.00	Adjustment for material deficiency.
				5	Mar 17, 2020	linkd1	(\$300.00)	Remove Material Credit
			- Total				\$0.00	
	Other Item Adjustment - Total						\$0.00	
0220 -	Total						\$0.00	
0230	FLAG ASSEMBLY	Material		2	Feb 3, 2020	SYSTEM	(\$100.00)	
				3	Feb 18, 2020	SYSTEM	(\$100.00)	
				4	Mar 2, 2020	SYSTEM	(\$100.00)	
			- Total				(\$300.00)	
	Material - Total						(\$300.00)	
	FLAG ASSEMBLY	MaterialCredit		3	Feb 18, 2020	SYSTEM	\$100.00	
				4	Mar 2, 2020	SYSTEM	\$100.00	
				5	Mar 17, 2020	SYSTEM	\$100.00	
			- Total				\$300.00	
	MaterialCredit - Total						\$300.00	
	FLAG ASSEMBLY	Other Item Adjustment		2	Feb 3, 2020	linkd1	\$100.00	Adjustment for material deficiency.
				5	Mar 17, 2020	linkd1	(\$100.00)	Remove Material Credit
			- Total				\$0.00	
	Other Item Adjustment - Total						\$0.00	
0230 -							\$0.00	
0240	CHANNELIZER (TRIM LINE)	Material		2	Feb 3, 2020	SYSTEM	(\$598.00)	
				3	Feb 18, 2020	SYSTEM	(\$598.00)	
				4	Mar 2, 2020	SYSTEM	(\$598.00)	
			- Total				(\$1,794.00)	
	Material - Total						(\$1,794.00)	
	CHANNELIZER (TRIM LINE)	MaterialCredit		3	Feb 18, 2020	SYSTEM	\$598.00	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0240	CHANNELIZER (TRIM LINE)	MaterialCredit		4	Mar 2, 2020	SYSTEM	\$598.00	
				5	Mar 17, 2020	SYSTEM	\$598.00	
			- Total				\$1,794.00	
	MaterialCredit - Total						\$1,794.00	
	CHANNELIZER (TRIM LINE)	Other Item Adjustment		2	Feb 3, 2020	linkd1	\$598.00	Adjustment for material deficiency.
				5	Mar 17, 2020	linkd1	(\$598.00)	Remove Material Credit
			- Total				\$0.00	
	Other Item Adjustment - Total						\$0.00	
0240 -	Total						\$0.00	
0270	WORK ZONE TRAFFIC SIGNAL SYSTEM	Material		2	Feb 3, 2020	SYSTEM	(\$30,000.00)	
				3	Feb 18, 2020	SYSTEM	(\$30,000.00)	
				4	Mar 2, 2020	SYSTEM	(\$30,000.00)	
			- Total				(\$90,000.00)	
	Material - Total						(\$90,000.00)	
	WORK ZONE TRAFFIC SIGNAL SYSTEM	MaterialCredit		3	Feb 18, 2020	SYSTEM	\$30,000.00	
				4	Mar 2, 2020	SYSTEM	\$30,000.00	
				5	Mar 17, 2020	SYSTEM	\$30,000.00	
			- Total				\$90,000.00	
	MaterialCredit - Total						\$90,000.00	
	WORK ZONE TRAFFIC SIGNAL SYSTEM	Other Item Adjustment		2	Feb 3, 2020	linkd1	\$30,000.00	Adjustment for material deficiency.
				5	Mar 17, 2020	linkd1	(\$30,000.00)	Remove Material Credit
			- Total				\$0.00	
	Other Item Adjustment - Total						\$0.00	
0270 -	Total						\$0.00	
0280	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	Material		2	Feb 3, 2020	SYSTEM	(\$10,200.00)	
				3	Feb 18, 2020	SYSTEM	(\$10,200.00)	
				4	Mar 2, 2020	SYSTEM	(\$10,200.00)	
			- Total				(\$30,600.00)	
	Material - Total						(\$30,600.00)	
	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	MaterialCredit		3	Feb 18, 2020	SYSTEM	\$10,200.00	
	IN TAINED			4	Mar 2, 2020	SYSTEM	\$10,200.00	
				5	Mar 17, 2020	SYSTEM	\$10,200.00	
			- Total				\$30,600.00	
	MaterialCredit - Total						\$30,600.00	
	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED			2	Feb 3, 2020	linkd1	\$10,200.00	Adjustment for material deficiency.
				5	Mar 17, 2020	linkd1	(\$10,200.00)	Remove Material Credit
			- Total				\$0.00	
	Other Item Adjustment - Total						\$0.00	
0280 -	Total						\$0.00	
0340	4 IN TEMPORARY PAVEMENT MARKING	Overrun	Overrun	8	May 5,	SYSTEM	(\$159.00)	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0340	PAINT	Overrun			2020			
			Overrun - T	otal			(\$159.00)	
	Overrun - Total						(\$159.00)	
0340 -	Total						(\$159.00)	
0400	SEEDING - COOL SEASON MIXTURES	Material		8	May 5, 2020	SYSTEM	(\$2,700.00)	
				9	May 19, 2020	SYSTEM	(\$2,700.00)	
				10	Jun 3, 2020	SYSTEM	(\$2,700.00)	
			- Total				(\$8,100.00)	
	Material - Total						(\$8,100.00)	
	SEEDING - COOL SEASON MIXTURES	MaterialCredit		9	May 19, 2020	SYSTEM	\$2,700.00	
				10	Jun 3, 2020	SYSTEM	\$2,700.00	
			- Total				\$5,400.00	
	MaterialCredit - Total						\$5,400.00	
	SEEDING - COOL SEASON MIXTURES	Other Item Adjustment		8	May 5, 2020	linkd1	\$2,700.00	Material Credit
			- Total				\$2,700.00	
	Other Item Adjustment - Total						\$2,700.00	
0400 -	Total						\$0.00	
0440	SILT FENCE	Material		2	Feb 3, 2020	SYSTEM	(\$1,116.00)	
			- Total				(\$1,116.00)	
	Material - Total						(\$1,116.00)	
	SILT FENCE	MaterialCredit		3	Feb 18, 2020	SYSTEM	\$1,116.00	
			- Total				\$1,116.00	
	MaterialCredit - Total						\$1,116.00	
	SILT FENCE	Other Item Adjustment		2	Feb 3, 2020	linkd1	\$1,116.00	Adjustment for material deficiency.
			- Total	3	Feb 18, 2020	linkd1	(\$1,116.00) \$0.00	Material Credit Takeaway
	Other Item Adjustment - Total		- 10141				\$0.00	
0440 -							\$0.00	
0440 -	TYPE C BERM	Material		4	Mar 2, 2020	SYSTEM	(\$1,100.00)	
				5	Mar 17, 2020	SYSTEM	(\$1,100.00)	
				6	Apr 3, 2020	SYSTEM	(\$1,100.00)	
				7	Apr 16, 2020	SYSTEM	(\$1,100.00)	
				8	May 5, 2020	SYSTEM	(\$1,100.00)	
				9	May 19, 2020 Jun 3,	SYSTEM	(\$1,100.00)	
						SIGILIVI	(ψ1,100.00)	
				10	2020			
			- Total		2020		(\$7,700.00)	
	Material - Total		- Total		2020		(\$7,700.00) (\$7,700.00)	
	Material - Total TYPE C BERM	MaterialCredit	- Total	5	2020 Mar 17, 2020	SYSTEM		
		MaterialCredit	- Total		Mar 17,	SYSTEM SYSTEM SYSTEM	(\$7,700.00)	



Line     Description     Adjustment Type     Other Adjustment Type     Rate Adjustment Type     Name Adjustment Type     Rate Adjustment Type     Rate Adjustment Type <thr< th=""><th></th></thr<>	
4     2020     0	
$ \begin{array}{ c c c c c } \hline  c c c c c c c c c c c c c c c c c c $	
$ \left  \begin{array}{c c c c c } \hline   \   \   \   \   \   \   \   \   \  $	
MaterialCredit - Total   Material Credit   TYPE C BERM   Other Item Adjustment   Other Item Adjustment   4   Mar 2, 2020   linkd1   \$\$1,100.00   Material Credit     Other Item Adjustment - Total   - Total   - Total   \$\$1,100.00   Material Credit     Other Item Adjustment - Total   Other Item Adjustment - Total   - Total   \$\$1,100.00   Material Credit     Other Item Adjustment - Total     Other Item Adjustment - Total     One Total     On	
$ \frac{1}{10000000000000000000000000000000000$	
$\begin{tabular}{ c c c c } \hline \begin{tabular}{ c c c c } \hline \begin{tabular}{ c c c c } \hline \begin{tabular}{ c c c c c } \hline \begin{tabular}{ c c c c c c c } \hline \begin{tabular}{ c c c c c c c c c c c c c c c c c c c$	
Other Item Adjustment - Total   \$\$1,100.00     0450 - Total   Construction   Solution   Solution <thsolution< th="">   Solution   &lt;</thsolution<>	
0450 - Total   State	
0460   MGS GUARDRAIL   Construction Stockpile   1   Jan 16, 2020   SYSTEM   \$260.50   Payment Estimate Item Adjustme Transaction     0460   May 5, 2020   SYSTEM   (\$260.50)   Payment Estimate Item Adjustme Transaction     0460   -Total   -Total   50.00   SYSTEM   (\$260.50)   Payment Estimate Item Adjustme Transaction     0460   -Total   -Total   50.00   SYSTEM   (\$30.00)     0470   MGS GUARDRAIL   Material   8   May 5, 2020   SYSTEM   (\$375.00)     0480   Material - Total   -Total   8   May 19, 2020   SYSTEM   (\$375.00)     049   May 19, 2020   SYSTEM   (\$375.00)   System   (\$1,125.00)     049   May 19, 2020   SYSTEM   (\$1,125.00)   System   System	
$ \begin{array}{ c c c c c c } \hline \begin{tabular}{ c c c c } \hline \begin{tabular}{ c c c c c } \hline \begin{tabular}{ c c c c c c c } \hline \begin{tabular}{ c c c c c c c c c c c c c c c c c c c$	
Image:	ent generated Stockpile
Construction Stockpile - Total   Material   Material   Material   8   May 5, 2020   SYSTEM   \$(\$375.00)     9   May 19, 2020   SYSTEM   \$(\$375.00)   9   May 19, 2020   \$(\$375.00)     10   Jun 3, 2020   SYSTEM   \$(\$375.00)   \$(\$375.00)     Interview of the second sec	
MGS GUARDRAIL     Material     8     May 5, 2020     SYSTEM     (\$375.00)       9     May 19, 2020     SYSTEM     (\$375.00)       10     Jun 3, 2020     SYSTEM     (\$375.00)       - Total       MaterialCredit       MGS GUARDRAIL     MaterialCredit     9     May 19, SYSTEM     (\$375.00)       Material - Total	
Image: second	
Image: Constraint of the second sec	
Image: Constraint of the second sec	
Material - Total (\$1,125.00)   MGS GUARDRAIL MaterialCredit 9 May 19, SYSTEM \$375.00	
MGS GUARDRAIL MaterialCredit 9 May 19, SYSTEM \$375.00	
10 Jun 3, 2020 \$\$375.00	
- Total \$750.00	
MaterialCredit - Total \$750.00	
MGS GUARDRAIL Other Item Adjustment 8 May 5, 2020 linkd1 \$375.00 Material Credit	
8 May 5, linkd1 \$130.00 Stockpile Material System Correct	tion:
- Total \$505.00	
Other Item Adjustment - Total \$505.00	
0460 - Total \$130.00	
0470     MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)     Construction Stockpile     1     Jan 16, 2020     System     \$5,944.00     Payment Estimate Item Adjustment Transaction	nt generated Stockpile
8 May 5, 2020 SYSTEM (\$5,944.00) Payment Estimate Item Adjustme Transaction	nt generated Stockpile
- Total \$0.00	
Construction Stockpile - Total \$0.00	
MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) Material 8 May 5, 2020 SYSTEM (\$6,400.00)	
9 May 19, SYSTEM (\$6,400.00) 2020	
10 Jun 3, 2020 SYSTEM (\$6,400.00)	
- Total (\$19,200.00)	
Material - Total (\$19,200.00)	
MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) MaterialCredit 9 May 19, 2020 SYSTEM \$6,400.00	
10 Jun 3, 2020 SYSTEM \$6,400.00	
- Total \$12,800.00	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0470	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Other Item Adjustment		8	May 5, 2020	linkd1	\$6,400.00	Material Credit
				8	May 5, 2020	linkd1	\$2,972.00	Stockpile Material System Correction
			- Total				\$9,372.00	
	Other Item Adjustment - Total						\$9,372.00	
0470 -	Total						\$2,972.00	
0480	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		1	Jan 16, 2020	SYSTEM	\$6,040.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	May 5, 2020	SYSTEM	(\$6,040.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material		8	May 5, 2020	SYSTEM	(\$6,000.00)	
				9	May 19, 2020	SYSTEM	(\$6,000.00)	
				10	Jun 3, 2020	SYSTEM	(\$6,000.00)	
			- Total				(\$18,000.00)	
	Material - Total						(\$18,000.00)	
	TYPE A CRASHWORTHY END TERMINAL (MASH)	MaterialCredit		9	May 19, 2020	SYSTEM	\$6,000.00	
			- Total	10	Jun 3, 2020	SYSTEM	\$6,000.00 \$12,000.00	
	Material Credit Tatal		- Total					
		Oth on them		0	May 5	lin hald	\$12,000.00	Matarial Ora dit
	TYPE A CRASHWORTHY END TERMINAL (MASH)	Other Item Adjustment		8	May 5, 2020	linkd1	\$6,000.00	Material Credit
			- Total	0	May 5, 2020	linka i	\$9,020.00	Stockpile Material System Correction
	Other Item Adjustment - Total		Total				\$9,020.00	
0480 -	· ·						\$3,020.00	
0530	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		8	May 5, 2020	SYSTEM	(\$9,600.00)	
				9	May 19, 2020	SYSTEM	(\$9,600.00)	
				10	Jun 3, 2020	SYSTEM	(\$9,600.00)	
			- Total				(\$28,800.00)	
	Material - Total						(\$28,800.00)	
	BRIDGE APPROACH SLAB (MINOR ROAD)	MaterialCredit		9	May 19, 2020	SYSTEM	\$9,600.00	
				10	Jun 3, 2020	SYSTEM	\$9,600.00	
			- Total				\$19,200.00	
	MaterialCredit - Total						\$19,200.00	
	BRIDGE APPROACH SLAB (MINOR ROAD)	Other Item Adjustment		8	May 5, 2020	linkd1	\$9,600.00	Material Credit
			- Total				\$9,600.00	
	Other Item Adjustment - Total						\$9,600.00	
0530 -	Total						\$0.00	
0540	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	Construction Stockpile		2	Feb 3, 2020	SYSTEM	\$30,142.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				3	Feb 18, 2020	SYSTEM	(\$30,142.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0540	GALVANIZED STRUCTURAL STEEL PILES	Material	Туре	3	Feb 18,	SYSTEM	(\$22,212,00)	
0340	GALVANIZED STRUCTURAL STEEL FILES (14 IN)	Watenai		5	2020	STOTEIN	(\$33,312.00)	
				4	Mar 2, 2020	SYSTEM	(\$42,528.00)	
			- Total				(\$75,840.00)	
	Material - Total						(\$75,840.00)	
	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	MaterialCredit		4	Mar 2, 2020	SYSTEM	\$33,312.00	
				5	Mar 17, 2020	SYSTEM	\$42,528.00	
			- Total				\$75,840.00	
	MaterialCredit - Total						\$75,840.00	
	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	Other Item Adjustment		3	Feb 18, 2020	linkd1	\$33,312.00	Material Credit
				3	Feb 18, 2020	linkd1	\$11,820.40	System is taking away too much to reclaim money from initial stockpile material payment. This is to fix the amount taken away. Reatin rate is 55%
				4	Mar 2, 2020	linkd1	(\$33,312.00)	Material Credit fix
				4	Mar 2, 2020	linkd1	\$42,528.00	Material Credit
				5	Mar 17, 2020	linkd1	(\$42,528.00)	Remove Material Credit
			- Total				\$11,820.40	
	Other Item Adjustment - Total						\$11,820.40	
0540 -							\$11,820.40	
0560	PRE-BORE FOR PILING	Overrun	Overrun	8	May 5, 2020	SYSTEM	(\$19,800.00)	
				9	May 19, 2020	SYSTEM	\$19,800.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',150.00000 - 150.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0560 -	Total						\$0.00	
0570	PILE POINT REINFORCEMENT	Material		3	Feb 18, 2020	SYSTEM	(\$1,440.00)	
				4	Mar 2, 2020	SYSTEM	(\$1,920.00)	
			- Total				(\$3,360.00)	
	Material - Total						(\$3,360.00)	
	PILE POINT REINFORCEMENT	MaterialCredit		4	Mar 2, 2020	SYSTEM	\$1,440.00	
				5	Mar 17, 2020	SYSTEM	\$1,920.00	
			- Total				\$3,360.00	
	MaterialCredit - Total						\$3,360.00	
	PILE POINT REINFORCEMENT	Other Item Adjustment		3	Feb 18, 2020	linkd1	\$1,440.00	Material Credit
		,		4	Mar 2, 2020	linkd1	(\$1,440.00)	Material Credit fix
				4	Mar 2, 2020	linkd1	\$1,920.00	Material Credit
				5	Mar 17, 2020	linkd1	(\$1,920.00)	Remove Material Credit
			- Total				\$0.00	
	Other Item Adjustment - Total						\$0.00	
0570 -	Total						\$0.00	
0580	CLASS B CONCRETE (SUBSTRUCTURE)	Material		4	Mar 2, 2020	SYSTEM	(\$31,200.00)	
				5	Mar 17,	SYSTEM	(\$31,200.00)	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0580	CLASS B CONCRETE (SUBSTRUCTURE)	Material			2020			
				6	Apr 3, 2020	SYSTEM	(\$31,200.00)	
				7	Apr 16, 2020	SYSTEM	(\$31,200.00)	
				8	May 5, 2020	SYSTEM	(\$31,200.00)	
				9	May 19, 2020	SYSTEM	(\$57,840.00)	
				10	Jun 3, 2020	SYSTEM	(\$57,840.00)	
			- Total				(\$271,680.00)	
	Material - Total						(\$271,680.00)	
	CLASS B CONCRETE (SUBSTRUCTURE)	MaterialCredit		5	Mar 17, 2020	SYSTEM	\$31,200.00	
				6	Apr 3, 2020	SYSTEM	\$31,200.00	
				7	Apr 16, 2020	SYSTEM	\$31,200.00	
				8	May 5, 2020	SYSTEM	\$31,200.00	
				9	May 19, 2020	SYSTEM	\$31,200.00	
				10	Jun 3, 2020	SYSTEM	\$57,840.00	
			- Total				\$213,840.00	
	MaterialCredit - Total						\$213,840.00	
	CLASS B CONCRETE (SUBSTRUCTURE) Other	Other Item Adjustment		4	Mar 2, 2020	linkd1	\$31,200.00	Material Credit
				9	May 19, 2020	linkd1	\$57,840.00	Material Credit
				9	May 19, 2020	linkd1	(\$31,200.00)	Material Credit Recovery
			- Total				\$57,840.00	
	Other Item Adjustment - Total						\$57,840.00	
0580 -	Total						\$0.00	
0590	SLAB ON CONCRETE I-GIRDER	Construction Stockpile		4	Mar 2, 2020	SYSTEM	\$29,334.81	Payment Estimate Item Adjustment generated Stockpile Transaction
				5	Mar 17, 2020	SYSTEM	(\$29,334.81)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total				_		\$0.00	
	SLAB ON CONCRETE I-GIRDER	Material		5	Mar 17, 2020	SYSTEM	(\$81,235.00)	
				6	Apr 3, 2020	SYSTEM	(\$148,610.00)	
				7	Apr 16, 2020	SYSTEM	(\$148,610.00)	
				8	May 5, 2020	SYSTEM	(\$148,610.00)	
				9	May 19, 2020	SYSTEM	(\$148,610.00)	
				10	Jun 3, 2020	SYSTEM	(\$200,200.00)	
			- Total				(\$875,875.00)	
	Material - Total						(\$875,875.00)	
	SLAB ON CONCRETE I-GIRDER	MaterialCredit		6	Apr 3, 2020	SYSTEM	\$81,235.00	
				7	Apr 16, 2020	SYSTEM	\$148,610.00	
				8	May 5, 2020	SYSTEM	\$148,610.00	
	$n \frac{1}{12020}$							Page 18 of 22



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0590	SLAB ON CONCRETE I-GIRDER	MaterialCredit		9	May 19, 2020	SYSTEM	\$148,610.00	
				10	Jun 3, 2020	SYSTEM	\$148,610.00	
			- Total				\$675,675.00	
	MaterialCredit - Total						\$675,675.00	
	SLAB ON CONCRETE I-GIRDER	Other Item Adjustment		5	Mar 17, 2020	linkd1	\$13,087.81	Stockpile Materials Correction - system recovered too much.
				5	Mar 17, 2020	linkd1	\$81,235.00	Material Credit
				6	Apr 3, 2020	linkd1	(\$81,235.00)	Material Credit Recovery
				6	Apr 3, 2020	linkd1	\$148,610.00	Material Credit
				10	Jun 3, 2020	linkd1	(\$148,610.00)	Material Credit Recovery
				10	Jun 3, 2020	linkd1	\$200,200.00	Material Credit
			- Total				\$213,287.81	
0500	Other Item Adjustment - Total						\$213,287.81	
0590 - 0600		Material		6	Apr 3, 2020	SYSTEM	\$13,087.81 (\$23,863.00)	
				7	Apr 16, 2020	SYSTEM	(\$23,863.00)	
				8	May 5, 2020	SYSTEM	(\$23,863.00)	
				9	May 19, 2020	SYSTEM	(\$23,863.00)	
				10	Jun 3, 2020	SYSTEM	(\$23,863.00)	
			- Total				(\$119,315.00)	
	Material - Total						(\$119,315.00)	
	SAFETY BARRIER CURB	MaterialCredit		7	Apr 16, 2020	SYSTEM	\$23,863.00	
				8	May 5, 2020	SYSTEM	\$23,863.00	
				9	May 19, 2020	SYSTEM	\$23,863.00	
				10	Jun 3, 2020	SYSTEM	\$23,863.00	
			- Total				\$95,452.00	
	MaterialCredit - Total						\$95,452.00	
	SAFETY BARRIER CURB	Other Item Adjustment		6	Apr 3, 2020	linkd1	\$23,863.00	Material Credit
	Other Kom Adjustment Total		- Total				\$23,863.00	
0600 -	Other Item Adjustment - Total						\$23,863.00 \$0.00	
0610	TYPE 4 (45 IN.), PRESTRESSED CONCRETE I-GIRDER	Construction Stockpile		2	Feb 3, 2020	SYSTEM	\$51,015.88	Payment Estimate Item Adjustment generated Stockpile Transaction
				4	Mar 2, 2020	SYSTEM	(\$51,015.88)	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Apr 3, 2020	SYSTEM	\$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
	TYPE 4 (45 IN.), PRESTRESSED CONCRETE I-GIRDER	Other Item Adjustment		6	Apr 3, 2020	linkd1	\$59,443.66	Fixing System error with stockpiled materials. System recovered payment without installing any quantity.
			- Total				\$59,443.66	
	Other Item Adjustment - Total						\$59,443.66	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0610 -	Total						\$59,443.66	
0620	REINFORCING STEEL (BRIDGES)	Material		4	Mar 2, 2020	SYSTEM	(\$3,000.00)	
				5	Mar 17, 2020	SYSTEM	(\$3,000.00)	
				6	Apr 3, 2020	SYSTEM	(\$3,000.00)	
			- Total				(\$9,000.00)	
	Material - Total			_			(\$9,000.00)	
	REINFORCING STEEL (BRIDGES)	MaterialCredit		5	Mar 17, 2020	SYSTEM	\$3,000.00	
				6	Apr 3, 2020	SYSTEM	\$3,000.00	
				7	Apr 16, 2020	SYSTEM	\$3,000.00	
			- Total				\$9,000.00	
	MaterialCredit - Total						\$9,000.00	
	REINFORCING STEEL (BRIDGES)	Other Item Adjustment		4	Mar 2, 2020	linkd1	\$3,000.00	Material Credit
				7	Apr 16, 2020	linkd1	(\$3,000.00)	Material Credit Recovery
			- Total				\$0.00	
	Other Item Adjustment - Total						\$0.00	
0620 -							\$0.00	
0630	MECHANICAL BAR SPLICE	Construction Stockpile		4	Mar 2, 2020	SYSTEM	\$13,992.69	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	May 5, 2020	SYSTEM	(\$13,992.69)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0630 -	Total						\$0.00	
0650	SLAB DRAIN	Material		9	May 19, 2020	SYSTEM	(\$2,100.00)	
				10	Jun 3, 2020	SYSTEM	(\$2,100.00)	
			- Total				(\$4,200.00)	
	Material - Total						(\$4,200.00)	
	SLAB DRAIN	MaterialCredit		10	Jun 3, 2020	SYSTEM	\$2,100.00	
			- Total				\$2,100.00	
	MaterialCredit - Total						\$2,100.00	
	SLAB DRAIN	Other Item Adjustment		9	May 19, 2020	linkd1	\$2,100.00	Material Credit
			- Total				\$2,100.00	
0050	Other Item Adjustment - Total						\$2,100.00	
0650 - 0660	Total VERTICAL DRAIN AT END BENTS	Material		9	May 19, 2020	SYSTEM	\$0.00 (\$4,000.00)	
				10	Jun 3, 2020	SYSTEM	(\$4,000.00)	
			- Total		2020		(\$8,000.00)	
	Material - Total		- Total				(\$8,000.00)	
	VERTICAL DRAIN AT END BENTS	MaterialCredit		10	Jun 3,	SYSTEM	(\$8,000.00) \$4,000.00	
			- Total		2020		\$4,000.00	
	MaterialCredit - Total						\$4,000.00	
	VERTICAL DRAIN AT END BENTS	Other Item Adjustment		9	May 19, 2020	linkd1	\$4,000.00	Material Credit
		-	- Total				\$4,000.00	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0660	Other Item Adjustment - Total						\$4,000.00	
0660 -	Total						\$0.00	
0670	LAMINATED NEOPRENE BEARING PAD (TAPERED)	Material		4	Mar 2, 2020	SYSTEM	(\$3,300.00)	
				5	Mar 17, 2020	SYSTEM	(\$3,300.00)	
			- Total				(\$6,600.00)	
	Material - Total						(\$6,600.00)	
	LAMINATED NEOPRENE BEARING PAD (TAPERED)	MaterialCredit		5	Mar 17, 2020	SYSTEM	\$3,300.00	
				6	Apr 3, 2020	SYSTEM	\$3,300.00	
			- Total				\$6,600.00	
	MaterialCredit - Total						\$6,600.00	
	LAMINATED NEOPRENE BEARING PAD (TAPERED)	Other Item Adjustment		4	Mar 2, 2020	linkd1	\$3,300.00	Material Credit
				6	Apr 3, 2020	linkd1	(\$3,300.00)	Material Credit Recovery
			- Total				\$0.00	
	Other Item Adjustment - Total						\$0.00	
0670 -							\$0.00	
5001	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE,	Material		2	Feb 3, 2020	SYSTEM	(\$8,200.00)	
	CONTRACTOR FURNISHED, CONTRACTOR RETAINED			3	Feb 18, 2020	SYSTEM	(\$8,200.00)	
				4	Mar 2, 2020	SYSTEM	(\$8,200.00)	
			- Total				(\$24,600.00)	
	Material - Total						(\$24,600.00)	
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE,	MaterialCredit		3	Feb 18, 2020	SYSTEM	\$8,200.00	
	CONTRACTOR FURNISHED, CONTRACTOR RETAINED			4	Mar 2, 2020	SYSTEM	\$8,200.00	
				5	Mar 17, 2020	SYSTEM	\$8,200.00	
			- Total				\$24,600.00	
	MaterialCredit - Total						\$24,600.00	
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE,	Other Item Adjustment		2	Feb 3, 2020	linkd1	\$8,200.00	Adjustment for material deficiency.
	CONTRACTOR FURNISHED, CONTRACTOR RETAINED			5	Mar 17, 2020	linkd1	(\$8,200.00)	Remove Material Credit
			- Total				\$0.00	
	Other Item Adjustment - Total						\$0.00	
5001 -	Total						\$0.00	
5002	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		2	Feb 3, 2020	SYSTEM	(\$3,525.12)	
				3	Feb 18, 2020	SYSTEM	(\$3,525.12)	
				4	Mar 2, 2020	SYSTEM	(\$3,525.12)	
				5	Mar 17, 2020	SYSTEM	(\$3,525.12)	
			- Total				(\$14,100.48)	
	Material - Total						(\$14,100.48)	
	TEMPORARY LONG-TERM RUMBLE STRIPS	MaterialCredit		3	Feb 18, 2020	SYSTEM	\$3,525.12	
				4	Mar 2, 2020	SYSTEM	\$3,525.12	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5002	TEMPORARY LONG-TERM RUMBLE STRIPS	MaterialCredit		6	Apr 3, 2020	SYSTEM	\$3,525.12	
				- Total			\$14,100.48	
	MaterialCredit - Total						\$14,100.48	
	TEMPORARY LONG-TERM RUMBLE STRIPS	Other Item Adjustment		2	Feb 3, 2020	linkd1	\$3,525.12	Adjustment for material deficiency.
				6	Apr 3, 2020	linkd1	(\$3,525.12)	Material Credit Recovery
		- Total			\$0.00			
	Other Item Adjustment - Total						\$0.00	
5002 - Total							\$0.00	
Overall - Total							\$90,314.90	