

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 1, 2021

Progress Estimate Number		91018-D06		OOriginal Contract Amount \$2	, . ,
7	Prime Contractor Ble	evins Asphalt Construction Compan	y Pay Period End April 1, 202	1 Net Change Order Amount(\$	84,419.23)
'				Current Contract Amount \$2	2,527,580.77

Approval Date		By User
April 1, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	abbote1
April 1, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	abbote1
April 5, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete				
October 1, 2020	October 1, 2020		99.55%				

	Milestones						
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract				
Acceptance Date							
Awarded Date	November 6, 2019	November 6, 2019					
Letting Date	October 18, 2019	October 18, 2019					
Notice to Proceed Date	December 9, 2019	December 9, 2019					
Open to Traffic Date							
Work Began Date							

Contract Total Pay For Estimate No. 7									
		This Estimate	Previous	To Date					
191018-D06									
	Total Posted Items Pay	\$128,234.46	\$2,388,028.17	\$2,516,262.63					
	Gross Item Adjustments	(\$1,813.00)	\$0.00	(\$1,813.00)					
	Incentive	\$0.00	\$0.00	\$0.00					
	Disincentive	\$0.00	\$0.00	\$0.00					
	Liquidated Damage	\$0.00	\$0.00	\$0.00					
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00					
	•		\$2,388,028.17	\$2,514,449.63					
Contract Total Pay	/able This Estimate:	\$126.421.46							

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount	
J5S3278	0110	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.110	248,002	\$27,280.22	
	0120	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.110	219,962	\$24,195.82	
Project J5S	3278 - Tota	ıl					\$51,476.04	
J5S3383	0180	4091048	EMULSIFIED ASPHALT, SEAL COAT	GAL	\$2.220	8,870.1	\$19,691.62	
	0190	4094012	SEAL COAT AGGREGATE, GRADE B2	SQYD	\$0.580	52,134.14	\$30,237.80	
	0250	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.110	214,389.6	\$23,582.86	
	0260	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.100	32,461.4	\$3,246.14	
Project J5S3383 - Total								
Overall - Total								

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

	Line Item Adjustments This Estimate											
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount				
J5S3278	0040	SEAL COAT AGGREGATE, GRADE B2	Material			-348,387	\$0.61	(\$212,516.07)				
	0040	SEAL COAT AGGREGATE, GRADE B2	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	348,387	\$0.61	\$212,516.07				

Revision 4/1/2020 Page 1 of 12



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 1, 2021

Progress Estimate Number
7
Contract ID 191018-D06 Pay Period Start July 16, 2020 Original Contract Amount \$2,612,000.00
Prime Contractor Blevins Asphalt Construction Company Pay Period End April 1, 2021 Net Change Order Amount \$4,419.23)
Current Contract Amount \$2,527,580.77

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3278				71	Adjustment (0022) due to user abbote1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
	0110	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	Substandard Item	The stripe on Rte. 19 was installed incorrectly between approximate Log 153.994 and 155.054. It was agreed between the contractor and R.E. that a one mile deduct would be assessed for this section of roadway and no pay for the stripe would be issued.  Calculation: -5280 LF x 2 x \$0.11/LF = \$1161.60 round to -\$1162.00			(\$1,162.00)
	0110	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-248,002	\$0.11	(\$27,280.22)
	0110	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	E PAVEMENT  AINT, TYPE P  BEADS  BEADS  generated Material Payment Estimate Item  Adjustment (0023) due to user abbote1  overridding Payment Estimate Exception 6 on  the current Payment Estimate.		248,002	\$0.11	\$27,280.22	
	0120	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	Substandard Item	The stripe on Rte. 19 was installed incorrectly between approximate Log 153.994 and 155.054. It was agreed between the contractor and R.E. that a one mile deduct would be assessed for this section of roadway and no pay for the stripe would be issued. Plan Quantity between Log Mi 153.994 and Log Mi 155.054 is 5916 LF. Calculation:  -5916 LF x \$0.11/LF = -\$650.76 round to \$651.00			(\$651.00)
	0120	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-219,962	\$0.11	(\$24,195.82)
	0120	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user abbote1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	219,962	\$0.11	\$24,195.82
	0130	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material			-2,262.5	\$25.60	(\$57,920.00)
	0130	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user abbote1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	2,262.5	\$25.60	\$57,920.00
J5S3383	0180	EMULSIFIED ASPHALT, SEAL COAT	Material			-290,585	\$2.22	(\$645,098.70)
	0180	EMULSIFIED ASPHALT, SEAL COAT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0025) due to user abbote1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	290,585	\$2.22	\$645,098.70
	0190	SEAL COAT AGGREGATE, GRADE B2	Material			-1,118,514	\$0.58	(\$648,738.12)
	0190	SEAL COAT AGGREGATE, GRADE B2	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user abbote1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	1,118,514	\$0.58	\$648,738.12
	0250	4 IN. WHITE STANDARD	Material			-833,601	\$0.11	(\$91,696.11)

Revision 4/1/2020 Page 2 of 12



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 1, 2021

Progress Estimate Number
7
Contract ID 191018-D06 Pay Period Start July 16, 2020 Original Contract Amount \$2,612,000.00
Prime Contractor Blevins Asphalt Construction Company Pay Period End April 1, 2021 Net Change Order Amount \$84,419.23)
Current Contract Amount \$2,527,580.77

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
5S3383		WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS						
	0250	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user abbote1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	833,601	\$0.11	\$91,696.11
	0260	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-720,754	\$0.10	(\$72,075.40)
	0260	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user abbote1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	720,754	\$0.10	\$72,075.40
	5102	MGS GUARDRAIL	Material			-2	\$3,123.75	(\$6,247.50)
	5102	MGS GUARDRAIL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0028) due to user abbote1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	2	\$3,123.75	\$6,247.50
otal								(\$1,813.00

Revision 4/1/2020 Page 3 of 12



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information						
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work					
J5S3278	FAF 19-2(27)	Seal coat	19	CRAWFORD	from Route 68 to Ro	om Route 68 to Route 49						
J5S3383	FAS- S402(018)	Seal coat	Various	DENT	at various routes in Phelps and Dent counties							
Γotals by .	Job Number	's										
J5S3278		l Item Pay Item Adjustme	ents Gross It	tem Pay	This Estimate \$51,476.04 (\$1,813.00) \$49,663.04	Previous \$627,430.55 \$0.00 \$627,430.55	To Date \$678,906.59 (\$1,813.00) \$677,093.59					
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					
J5S3383		Posted Item Pay Gross Item Adjustments Gross Item Pay			This Estimate \$76,758.42 \$0.00 \$76,758.42	Previous \$1,760,597.62 \$0.00 \$1,760,597.62	To Date \$1,837,356.04 \$0.00 \$1,837,356.04					
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					

Revision 4/1/2020 Page 4 of 12



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) Trils Estimate Period  Exceptions / Discrepencies	Explanation	Entered	Status
Exceptions / Discrependes	схріанацоп	By	Status
Estimate Exception Type: Insufficient Materials: Project J5S3383, Item 4091048, Project Item Line Number 0180, Material Set 409104896, Material 1015EARS1 - Emulsified Asphalt RS-1, Acceptance Action Generic AspEmulsion is insufficient.	Pending entry of sampling/testing data.	abbote1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3278, Item 4094012, Project Item Line Number 0040, Material Set 409401296, Material 1003GB2 - Aggregate for Seal Coat Grade B2, Acceptance Action Generic 1003GB2 is insufficient.	Pending entry of sampling/testing data.	abbote1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3383, Item 4094012, Project Item Line Number 0190, Material Set 409401296, Material 1003GB2 - Aggregate for Seal Coat Grade B2, Acceptance Action Generic 1003GB2 is insufficient.	Pending entry of sampling/testing data.	abbote1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3383, Item 6061060, Project Item Line Number 5102, Material Set 606106096, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	Pending entry of sampling/testing data.	abbote1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3278, Item 6061061, Project Item Line Number 0130, Material Set 606106196, Material 1040GRSRCAT2 - Steel Beam for Class A Type 2 Guard Rail, Acceptance Action Generic 1040GRSRCAT2 is insufficient.	Pending entry of sampling/testing data.	abbote1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3278, Item 6206000C, Project Item Line Number 0110, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Pending entry of sampling/testing data.	abbote1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3278, Item 6206000C, Project Item Line Number 0110, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Pending entry of sampling/testing data.	abbote1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3383, Item 6206000C, Project Item Line Number 0250, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Pending entry of sampling/testing data.	abbote1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3383, Item 6206000C, Project Item Line Number 0250, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Pending entry of sampling/testing data.	abbote1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3383, Item 6206000C, Project Item Line Number 0250, Material Set 6206000C96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Pending entry of sampling/testing data.	abbote1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3278, Item 6206001C, Project Item Line Number 0120, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Pending entry of sampling/testing data.	abbote1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3278, Item 6206001C, Project Item Line Number 0120, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Pending entry of sampling/testing data.	abbote1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3383, Item 6206001C, Project Item Line Number 0260, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Pending entry of sampling/testing data.	abbote1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3383, Item 6206001C, Project Item Line Number 0260, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Pending entry of sampling/testing data.	abbote1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3383, Item 6206001C, Project Item Line Number 0260, Material Set 6206001C96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Pending entry of sampling/testing data.	abbote1	Overridden

Revision 4/1/2020 Page 5 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191018-D06	J5S3278	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$12,765.00	\$12,765.00
		0001	0020	2153000	SHAPING SLOPES, CLASS III	30.00	0.00	30.00	100F	30.00	\$1,335.30	\$40,059.00
		0001	0030	4091048	EMULSIFIED ASPHALT, SEAL COAT	97,548.00	4,935.00	102,483.00	GAL	97,548.00	\$2.19	\$213,630.12
		0001	0040	4094012	SEAL COAT AGGREGATE, GRADE B2	348,387.00	0.00	348,387.00	SQYD	348,387.00	\$0.61	\$212,516.07
		0001	0050	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$1,635.00	\$3,270.00
		0001	0060	6161005	CONSTRUCTION SIGNS	1,453.00	0.00	1,453.00	SQFT	1,453.00	\$6.13	\$8,906.89
		0001	0070	6161009	FLAG ASSEMBLY	16.00	0.00	16.00	EA	16.00	\$20.45	\$327.20
		0001	0800	6161025	CHANNELIZER (TRIM LINE)	50.00	-50.00	0.00	EA	0.00	\$10.25	\$0.00
		0001	0090	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$44,516.27	\$44,516.27
		0001	0100	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	1.00	0.00	1.00	EA	0.00	\$510.50	\$0.00
		0001	0110	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	248,002.00	0.00	248,002.00	LF	248,002.00	\$0.11	\$27,280.22
		0001	0120	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	219,962.00	0.00	219,962.00	LF	219,962.00	\$0.11	\$24,195.82
		0010	0130	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	2,400.00	-137.50	2,262.50	LF	2,262.50	\$25.60	\$57,920.00
		0010	0140	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$2,810.00	\$11,240.00
		0010	0150	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	8.00	0.00	8.00	EA	8.00	\$2,785.00	\$22,280.00
	Project J	5S3278 - To	tal Value	Posted to D	ate as of Report Generated Date							\$678,906.59
	J5S3383	0001	0160	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$11,790.00	\$11,790.00
		0001	0170	2153000	SHAPING SLOPES, CLASS III	31.00	0.00	31.00	100F	31.00	\$1,072.00	\$33,232.00
		0001	0180	4091048	EMULSIFIED ASPHALT, SEAL COAT	313,184.00	-22,599.00	290,585.00	GAL	290,585.00	\$2.22	\$645,098.70
		0001	0190	4094012	SEAL COAT AGGREGATE, GRADE B2	1,118,514.00	0.00	1,118,514.00	SQYD	1,118,514.00	\$0.58	\$648,738.12
		0001	0200	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$4,400.00	\$8,800.00
		0001	0210	6161005	CONSTRUCTION SIGNS	8,975.00	0.00	8,975.00	SQFT	8,975.00	\$6.15	\$55,196.25
		0001	0220	6161009	FLAG ASSEMBLY	134.00	0.00	134.00	EA	134.00	\$20.45	\$2,740.30
		0001	0230	6161025	CHANNELIZER (TRIM LINE)	100.00	-50.00	50.00	EA	50.00	\$10.25	\$512.50
		0001	0240	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$88,600.00	\$88,600.00
		0001	0250	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	833,601.00	0.00	833,601.00	LF	833,601.00	\$0.11	\$91,696.11
		0001	0260	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	720,754.00	0.00	720,754.00	LF	720,754.00	\$0.10	\$72,075.40
		0010	0265	6061010	GUARDRAIL TYPE A	25.00	0.00	25.00	LF	25.00	\$19.95	\$498.75
		0010	0270	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	700.00	0.00	700.00	LF	700.00	\$24.90	\$17,430.00
		0010	0280	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	31.00	-14.00	17.00	EA	17.00	\$2,890.00	\$49,130.00
		0010	0290	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	32.00	-4.00	28.00	EA	28.00	\$2,785.00	\$77,980.00
		0010	0300	00 6066610 END ANCHOR		1.00	0.00	1.00	EA	1.00	\$1,300.00	\$1,300.00
		0070	0310	7039902	MISC.END POST MODIFICATION BR. NO. T05831	3.00	0.00	3.00	EA	3.00	\$7,150.00	\$21,450.00
		0010	5101	6061074	MGS HEIGHT AND BLOCK TRANSITION	0.00	8.00	8.00	EA	8.00	\$605.05	\$4,840.40
		0010	5102	6061060	MGS GUARDRAIL	0.00	2.00	2.00	LF	2.00	\$3,123.75	\$6,247.50
	Project J	5S3383 - To	tal Value	Posted to D	late as of Report Generated Date							\$1,837,356.03
191018-D06 Ove	rall - Total	Value Pos	ed to Da	te as of Rep	ort Generated Date							\$2,516,262.62

Revision 4/1/2020 Page 6 of 12



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

### Project: J5S3278

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Si	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0110	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	3/17/21	3/17/21	248,002.00	LF	14	41.439		165.04		Striping Complete
0120	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	3/17/21	3/17/21	219,962.00	LF	14	41.439		165.040		Striping Complete

### Project: J5S3383

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0180	4091048	EMULSIFIED ASPHALT, SEAL COAT	3/17/21	3/17/21	8,870.10	GAL	Rte. 19 NBL	179.524		184.726		Log Miles locations are for reference only.
0190	4094012	SEAL COAT AGGREGATE, GRADE B2	3/17/21	3/17/21	52,134.14	SQYD	Rte. 19 NBL	179.524		184.76		Log Mile locations are for reference only
0250	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	3/17/21	3/17/21	214,389.60	LF	Various	0.001				Striping Complete
0260	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	3/17/21	3/17/21	32,461.40	LF	Various	.001				Striping Complete

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 7 of 12



Marcal   Total   Marc										
ACCIDENTE   CRACE 52	Project	Line	Description		Adjustment				Amount	Remarks
2000   SVSTEM   S212.518.07   This adjustment offices the original system generated Overson Payment Estimate Extendition from Adjustment (2001) size to use of stude overson Payment Estimate Extendition from Adjustment (2001) size to use of stude oversional prevent Estimate Extendition from Adjustment (2001) size to use of stude oversional prevent Estimate from Adjustment (2001) size to use of stude oversional prevent Estimate from Adjustment (2001) size to use of stude oversional prevent Estimate from Adjustment (2001) size to use of stude oversional prevent Estimate from Adjustment (2001) size to use of stude oversional prevent Estimate from Adjustment (2002) size to use of stude oversional prevent Estimate from Adjustment (2002) size to use of stude oversional prevent Estimate from Adjustment (2002) size to use of stude oversional prevent Estimate Escapsion 2 on the current Payment Estimate 2 on the Current Payment Estimate 2 on the deduct would be associated for the section of machinery and on pay for nature to 41 february 2 on the current Payment Estimate	J5S3278	0040	AGGREGATE,	Material		4		SYSTEM	\$212,516.07	Estimate Item Adjustment (0001) due to user dzuric overridding Payment
2020						4		SYSTEM	(\$212,516.07)	
2020   6   Jul 14, SYSTEM   S212,516.07   The adjustment officets the original system-generated Overturn Payment Estimate Examine Exception 2 on the current Payment Estimate Standard Standard Standard Standard Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 1						5		SYSTEM	\$212,516.07	Estimate Item Adjustment (0001) due to user dzuric overridding Payment
2000   STATEM   STA						5		SYSTEM	(\$212,516.07)	
2020   7						6		SYSTEM	\$212,516.07	Estimate Item Adjustment (0001) due to user dzuric overridding Payment
2021   Estimate Item Adjustment (0022) due to user abbole 1 overridding Payment						6		SYSTEM	(\$212,516.07)	
1-Total   1-To						7		SYSTEM	\$212,516.07	Estimate Item Adjustment (0022) due to user abbote1 overridding Payment
Material - Total   Substitute						7		SYSTEM	(\$212,516.07)	
Other Item Adjustment - Total   Other Item Adjustment - Total   SySTEM   SySTEM   SySTEM   Sz7,280.22   This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate Exception 6 on the current Payment Estimate Exception 6 on the current Payment Estimate.					- Total				\$0.00	
Other Item Adjustment - Total   Other Item Adjustment - Total   SySTEM   SySTEM   SySTEM   Sz7,280.22   This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate Exception 6 on the current Payment Estimate Exception 6 on the current Payment Estimate.				Material - To	otal				\$0.00	
		0040	Total							
WATERBORNE PAVEMBY MARKING Waterial - Total  Total  Subi -				Meterial		7	Apr 1	CVCTEM		This adjustment affects the existinal outlant generated Material Decement
Agr 1		0110	WATERBORNE PAVEMENT				2021			Estimate Item Adjustment (0023) due to user abbote1 overridding Payment
Material - Total  Other Item Adjustment  Item Adjustment  Other Item Adjustment  Item Adjustment  Other Item Adjustment  Item Adjustment  Other Item Adjustment  Item Adjustment  Item Adjustment  Other Item Adjustment  Item Adjustment  Item Adjustment  Other Item Adjustment  Item Adjustment  Other Item Adjustment  Item Adjustment  Item Adjustment  Other Item Adjustment  Item Adjustm						7		SYSTEM	(\$27,280.22)	
Other Item Adjustment  SUBI 7 Apr 1, 2021  Other Item Adjustment - Total  Other Item Adjustment - Total  Other Item Adjustment - Total  Other Item Adjustment  Other Item Adjustment - Total  Other Item Adjustment  Other Item Adjustment  Other Item Adjustment  Other Item Adjustment - Total  Other Item Adjustment  Other Item Adjustment - Total  Other Item Adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dzuric overidding Payment Estimate Item Adjustment (0001) due to user dzuric overidding Payment Estimate Item Adjustment Item Item Item Item Item Item Item Ite					- Total				\$0.00	
Adjustment				Material - To	otal				\$0.00	
Other Item Adjustment - Total  Other Item Adjustment  Other Item Adjustment - Total  Other Item Adjustment - Total - Septical - S					SUBI	7		abbote1	(\$1,162.00)	153.994 and 155.054. It was agreed between the contractor and R.E. that a one mile deduct would be assessed for this section of roadway and no pay for the stripe would be issued. Calculation: -5280 LF x 2 x \$0.11/LF = -\$1161.60
Other Item Adjustment   Other Item Adjustment   Total   Other Item Adjustment   Total   Other Item Adjustment   Total   Other Item Adjustment   Total   Other Item Adjustment   Other Item Adjustmen					SUBI - Total				(\$1,162.00)	
Apr 1, 2021   SYSTEM   \$24,195.82   This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user abbote1 overridding Payment Estimate Item Adjustment (0021) due to user abbote1 overridding Payment Estimate Exception 11 on the current Payment Estimate.				Other Item	Adjustment -	Total			(\$1,162.00)	
Apr 1, 2021   SYSTEM   \$24,195.82   This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user abbote1 overridding Payment Estimate Item Adjustment (0021) due to user abbote1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		0110 -	Total						(\$1.162.00)	
Total  Agr 1, 2021  SysTEM (\$24,195.82)  - Total  So.00  Material - Total  Other Item Adjustment  Adjustment  SUBI 7 Apr 1, 2021  Apr 1, 2021  Apr 1, 2021  The stripe on Rte. 19 was installed incorrectly between approximate Log 153.994 and 155.054. It was agreed between the contractor and R.E. that a one mile deduct would be assessed for this section of roadway and no pay for the stripe would be issued. Plan Quantity between Log Mi 153.994 and Log Mi 155.054 is 5916 LF. Calculation: -5916 LF x \$0.11/LF = -\$650.76 round to -\$651.00  Other Item Adjustment - Total  (\$651.00)  Other Item Adjustment - Total  (\$6551.00)  MGS GUARDRALL, 8 FT. POSTS, 6 FT 3 IN  May 4, 2020  May 18, 2020  May 18, 2020  May 18, 2020  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 1 on the current Payment Estimate.  System (\$24,000.00)  The stripe on Rte. 19 was installed incorrectly between approximate Log 153.994 and 155.054. It was agreed between the contractor and R.E. that a one mile deduct would be assessed for this section of roadway and no pay for the stripe would be issued. Plan Quantity between Log Mi 153.994 and 155.054. It was agreed between the contractor and R.E. that a one mile deduct would be assessed for this section of roadway and no pay for the stripe would be issued. Plan Quantity between Log Mi 153.994 and 155.054. It was agreed between the contractor and R.E. that a one mile deduct would be assessed for the stripe on Rie. 19 was installed incorrectly between approximate Log 153.994 and 155.054. It was agreed between the contractor of roadway and no pay for the tifs.  May 4, 2020  May 18, 5YSTEM \$57,920.00  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 1 on the current Payment Estimate Estimate Exception 2 on the current Payment Estimate.			4 IN. YELLOW WATERBORNE	Material		7		SYSTEM		Estimate Item Adjustment (0021) due to user abbote1 overridding Payment
Other Item Adjustment  SUBI 7 Apr 1, 2021 (\$651.00)  The stripe on Rte. 19 was installed incorrectly between approximate Log 153.994 and 155.054. It was agreed between the contractor and R.E. that a one mile deduct would be assessed for this section of roadway and no pay for the stripe would be issued. Plan Quantity between Log Mi 153.994 and 155.054 is 5916 LF. Calculation: -5916 LF x \$0.11/LF = -\$650.76 round to -\$651.00  SUBI - Total (\$651.00)  Other Item Adjustment - Total (\$651.00)  O120 - Total  O130 MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN  I May 4, SYSTEM \$24,000.00  2 May 18, SYSTEM (\$24,000.00)  2 May 18, SYSTEM \$57,920.00  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 1 on the current Payment Estimate.			MARKING			7		SYSTEM	(\$24,195.82)	
Other Item Adjustment  Other Item Adjustment  SUBI 7 Apr 1, 2021  SUBI - Total (\$651.00)  Other Item Adjustment - Total					- Total				\$0.00	
Other Item Adjustment  SUBI 7 Apr 1, 2021  SUBI - Total (\$651.00)  Other Item Adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dzuric overridding Payment Estimate Exception 1 on the current Payment Estimate.  I May 4, SYSTEM (\$24,000.00)  Other Item Adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dzuric overridding Payment Estimate Item Adjustment (0001) due to user dzuric overridding Payment Estimate Item Adjustment (0001) due to user dzuric overridding Payment Estimate Item Adjustment (0001) due to user dzuric overridding Payment Estimate Item Adjustment (0001) due to user dzuric overridding Payment Estimate Item Adjustment (0001) due to user dzuric overridding Payment Estimate Item Adjustment (0001) due to user dzuric overridding Payment Estimate Exception 2 on the current Payment Estimate.				Material - I						
Other Item Adjustment - Total  Other Item Adjustment - Total  (\$651.00)  Item Adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dzuric overridding Payment Estimate Exception 1 on the current Payment Estimate.  I May 4, 2020 SYSTEM (\$24,000.00)  Item Adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dzuric overridding Payment Estimate Exception 2 on the current Payment Estimate.				Other Item		7		abbote1		153.994 and 155.054. It was agreed between the contractor and R.E. that a one mile deduct would be assessed for this section of roadway and no pay for the stripe would be issued. Plan Quantity between Log Mi 153.994 and Log Mi 155.054 is 5916 LF. Calculation: -5916 LF x \$0.11/LF = -\$650.76 round to -
0120 - Total  O130 MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN  I May 4, 2020 SYSTEM \$24,000.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 1 on the current Payment Estimate.  I May 4, 2020 SYSTEM (\$24,000.00)  I May 4, 2020 SYSTEM STANDAIL					SUBI - Total				(\$651.00)	
0130 MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN  1 May 4, 2020 SYSTEM \$24,000.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 1 on the current Payment Estimate.  1 May 4, 2020 SYSTEM (\$24,000.00)  2 May 18, 2020 SYSTEM \$57,920.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 1 on the current Payment Estimate Exception 2 on the current Payment Estimate.				Other Item	Adjustment -	Total			(\$651.00)	
0130 MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN  1 May 4, 2020 SYSTEM \$24,000.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 1 on the current Payment Estimate.  1 May 4, 2020 SYSTEM (\$24,000.00)  2 May 18, 2020 SYSTEM \$57,920.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 1 on the current Payment Estimate Exception 2 on the current Payment Estimate.		0120 -	· Total						(\$651.00)	
1 May 4, 2020 (\$24,000.00) 2 May 18, 2020 \$57,920.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dzuric overridding Payment Estimate Exception 2 on the current Payment Estimate.		0130	MGS GUARDRAIL, 8 FT. POSTS, 6	Material		1		SYSTEM		Estimate Item Adjustment (0001) due to user dzuric overridding Payment
2020 Estimate Item Adjustment (0001) due to user dzuric overridding Payment Estimate Exception 2 on the current Payment Estimate.			1 1 3 IN			1		SYSTEM	(\$24,000.00)	
2 May 18, SYSTEM (\$57,920.00)						2		SYSTEM	\$57,920.00	Estimate Item Adjustment (0001) due to user dzuric overridding Payment
						2	May 18,	SYSTEM	(\$57,920.00)	



J5S3278 0130 MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN Material Processing Fraction of State o	
GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN  SYSTEM \$57,920.00 This adjustment offsets the original system-gen Estimate Item Adjustment (0001) due to user d.	
FT. POSTS, 6 T 3 IN SYSTEM \$57,920.00 This adjustment offsets the original system-gen Estimate Item Adjustment (0001) due to user disconnected by the system of the sys	
	dzuric overridding Payment
3 Jun 2, 2020 SYSTEM (\$57,920.00)	
4 Jun 16, 2020 \$57,920.00 This adjustment offsets the original system-gen Estimate Item Adjustment (0002) due to user de Estimate Exception 5 on the current Payment E	dzuric overridding Payment
4 Jun 16, 2020 (\$57,920.00)	
5 Jul 1, 2020 \$57,920.00 This adjustment offsets the original system-gen Estimate Item Adjustment (0002) due to user de Estimate Exception 7 on the current Payment E	dzuric overridding Payment
5 Jul 1, 2020 (\$57,920.00)	
6 Jul 16, 2020 \$SYSTEM \$57,920.00 This adjustment offsets the original system-gen Estimate Item Adjustment (0002) due to user de Estimate Exception 7 on the current Payment E	dzuric overridding Payment
6 Jul 16, 2020 (\$57,920.00)	
7 Apr 1, 2021 \$SYSTEM \$57,920.00 This adjustment offsets the original system-gen Estimate Item Adjustment (0024) due to user a Estimate Exception 5 on the current Payment E	abbote1 overridding Payment
7 Apr 1, 2021 (\$57,920.00)	
T	
-Total \$0.00	
Material - Total \$0.00	
Material - Total \$0.00	
Material - Total \$0.00 0130 - Total \$0.00	dzuric overridding Payment
Material - Total   \$0.00	dzuric overridding Payment
Material - Total   \$0.00	dzuric overridding Payment Estimate.  nerated Overrun Payment dzuric overridding Payment
Material - Total   \$0.00	dzuric overridding Payment Estimate.  nerated Overrun Payment dzuric overridding Payment
Material - Total   \$0.00	zuric overridding Payment Estimate.  nerated Overrun Payment dzuric overridding Payment Estimate.  nerated Overrun Payment dzuric overridding Payment
Material - Total   \$0.00	zuric overridding Payment Estimate.  nerated Overrun Payment dzuric overridding Payment Estimate.  nerated Overrun Payment dzuric overridding Payment
Material - Total   \$0.00	tzuric overridding Payment Estimate.  nerated Overrun Payment tzuric overridding Payment Estimate.  nerated Overrun Payment tzuric overridding Payment Estimate.  nerated Material Payment tabbote1 overridding Payment
Material - Total   \$0.00	tzuric overridding Payment Estimate.  nerated Overrun Payment tzuric overridding Payment Estimate.  nerated Overrun Payment tzuric overridding Payment Estimate.  nerated Material Payment tabbote1 overridding Payment
Material - Total   \$0.00	tzuric overridding Payment Estimate.  nerated Overrun Payment tzuric overridding Payment Estimate.  nerated Overrun Payment tzuric overridding Payment Estimate.  nerated Material Payment tabbote1 overridding Payment
Material - Total   So.00	tzuric overridding Payment Estimate.  nerated Overrun Payment tzuric overridding Payment Estimate.  nerated Overrun Payment tzuric overridding Payment Estimate.  nerated Material Payment tabbote1 overridding Payment
Material - Total   \$0.00	tzuric overridding Payment Estimate.  nerated Overrun Payment tzuric overridding Payment Estimate.  nerated Overrun Payment tzuric overridding Payment Estimate.  nerated Material Payment tabbote1 overridding Payment
Material - Total   S0.00	tzuric overridding Payment Estimate.  Inerated Overrun Payment Izuric overridding Payment Estimate.  Inerated Overrun Payment Izuric overridding Payment Estimate.  Inerated Material Payment Izuric overridding Payment Estimate.  Inerated Material Payment Izuric overridding Payment Izuric overridding Payment Izuric overridding Payment Izuric overridding Payment
Material - Total   \$0.00	tzuric overridding Payment Estimate.  Inerated Overrun Payment Izuric overridding Payment Estimate.  Inerated Overrun Payment Izuric overridding Payment Estimate.  Inerated Material Payment Izuric overridding Payment Estimate.  Inerated Material Payment Izuric overridding Payment Izuric overridding Payment Izuric overridding Payment Izuric overridding Payment
Material - Total   So.00	dzuric overridding Payment Estimate.  Inerated Overrun Payment dzuric overridding Payment Estimate.  Inerated Overrun Payment dzuric overridding Payment Estimate.  Inerated Material Payment abbote1 overridding Payment Estimate.  Inerated Overrun Payment dzuric overridding Payment Estimate.  Inerated Overrun Payment dzuric overridding Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J5S3383	0190	SEAL COAT AGGREGATE, GRADE B2	Material		6	Jul 16, 2020	SYSTEM	\$618,500.32	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dzuric overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					6	Jul 16, 2020	SYSTEM	(\$618,500.32)		
					7	Apr 1, 2021	SYSTEM	\$648,738.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user abbote1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					7	Apr 1, 2021	SYSTEM	(\$648,738.12)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0190 -	· Total						\$0.00		
	0250	4 IN. WHITE WATERBORNE PAVEMENT	Material		6	Jul 16, 2020	SYSTEM	\$68,113.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dzuric overridding Payment Estimate Exception 9 on the current Payment Estimate.	
		MARKING			6	Jul 16, 2020	SYSTEM	(\$68,113.25)		
					7	Apr 1, 2021	SYSTEM	\$91,696.11	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user abbote1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					7	Apr 1, 2021	SYSTEM	(\$91,696.11)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0250 -	Total						\$0.00		
	0260	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		6	Jul 16, 2020	SYSTEM	\$68,829.26	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dzuric overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					6	Jul 16, 2020	SYSTEM	(\$68,829.26)		
					7	Apr 1, 2021	SYSTEM	\$72,075.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user abbote1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
					7	Apr 1, 2021	SYSTEM	(\$72,075.40)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0260 -	· Total						\$0.00		
	0265	GUARDRAIL TYPE A	Material		2	May 18, 2020	SYSTEM	\$498.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user dzuric overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					2	May 18, 2020	SYSTEM	(\$498.75)		
						3	Jun 2, 2020	SYSTEM	\$498.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user dzuric overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Jun 2, 2020	SYSTEM	(\$498.75)		
					4	Jun 16, 2020	SYSTEM	\$498.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dzuric overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					4	Jun 16, 2020	SYSTEM	(\$498.75)		
					5	Jul 1, 2020	SYSTEM	\$498.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dzuric overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					5	Jul 1, 2020	SYSTEM	(\$498.75)		
					6	Jul 16, 2020	SYSTEM	\$498.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dzuric overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					6	Jul 16,	SYSTEM	(\$498.75)		



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
383	0265	GUARDRAIL	Material			2020														
		TYPE A		- Total				\$0.00												
			Material - To	otal				\$0.00												
	0265 -	Total						\$0.00												
	0270	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	Material		3	Jun 2, 2020	SYSTEM	\$17,430.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dzuric overridding Payment Estimate Exception 3 on the current Payment Estimate.											
		113114			3	Jun 2, 2020	SYSTEM	(\$17,430.00)												
					4	Jun 16, 2020	SYSTEM	\$17,430.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dzuric overridding Payment Estimate Exception 6 on the current Payment Estimate.											
					4	Jun 16, 2020	SYSTEM	(\$17,430.00)												
					5	Jul 1, 2020	SYSTEM	\$17,430.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dzuric overridding Payment Estimate Exception 6 on the current Payment Estimate.											
					5	Jul 1, 2020	SYSTEM	(\$17,430.00)												
					6	Jul 16, 2020	SYSTEM	\$17,430.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user dzuric overridding Payment Estimate Exception 6 on the current Payment Estimate.											
					6	Jul 16, 2020	SYSTEM	(\$17,430.00)												
				- Total				\$0.00												
			Material - To	otal				\$0.00												
	0270 -	Total						\$0.00												
	0300	END ANCHOR	Material		2	May 18, 2020	SYSTEM	\$1,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dzuric overridding Payment Estimate Exception 3 on the current Payment Estimate.											
									2	May 18, 2020	SYSTEM	(\$1,300.00)								
													3	Jun 2, 2020	SYSTEM	\$1,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dzuric overridding Payment Estimate Exception 4 on the current Payment Estimate.			
												3	Jun 2, 2020	SYSTEM	(\$1,300.00)					
					4	Jun 16, 2020	SYSTEM	\$1,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dzuric overridding Payment Estimate Exception 7 on the current Payment Estimate.											
					4	Jun 16, 2020	SYSTEM	(\$1,300.00)												
																5	Jul 1, 2020	SYSTEM	\$1,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dzuric overridding Payment Estimate Exception 8 on the current Payment Estimate.
											5	Jul 1, 2020	SYSTEM	(\$1,300.00)						
											6	Jul 16, 2020	SYSTEM	\$1,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dzuric overridding Payment Estimate Exception 8 on the current Payment Estimate.					
					6	Jul 16, 2020	SYSTEM	(\$1,300.00)												
				- Total				\$0.00												
			Material - To	otal				\$0.00												
	0300 -							\$0.00												
	5102	MGS GUARDRAIL	Material		5	Jul 1, 2020	SYSTEM	\$6,247.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user dzuric overridding Payment Estimate Exception 5 on the current Payment Estimate.											
					5	Jul 1, 2020	SYSTEM	(\$6,247.50)												
					6	Jul 16, 2020	SYSTEM	\$6,247.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dzuric overridding Payment Estimate Exception 5 on the current Payment Estimate.											





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3383	5102	MGS GUARDRAIL	Material		6	Jul 16, 2020	SYSTEM	(\$6,247.50)	
					7	Apr 1, 2021	SYSTEM	\$6,247.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user abbote1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Apr 1, 2021	SYSTEM	(\$6,247.50)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
5102 - Total									
J5S3383 - Total									
Overall - Total									