

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 17, 2020

| Progress Estim 8 | ate Number | Contract ID Prime Contractor | 191018-D08 Gene Haile Excav | | | | Original Contract Amou Net Change Order Amo Current Contract Amou | unt \$0.00 | | | |
|--------------------------|------------|---|--|--------------|----------------------|------------------|---|-------------|--|--|--|
| Approval Date | | | | | | | | By User | | | |
| August 17, 2020 | | Generated and Approved (and should be considered Draft) at the Project Office Level l | | | | | | | | | |
| August 18, 2020 | | Re | eviewed and Appro | oved (and sh | ould be considered D | Oraft) at the Re | sident Engineer Level by | browns1 | | | |
| August 19, 2020 | | Reviewed and Approved at the Central Office Controllers Office Level by | | | | | | | | | |
| Original Completion Date | | Current Com | ppletion Date Actual Completion Date % of Current Contract A | | | | Current Contract Amou | nt Complete | | | |
| December | 1, 2020 | Decembe | er 1, 2020 | | | | 60.26% | | | | |

No Milestones Exist for Contract

| Contract Total Pay For Estimate No. 8 | | | | | | | | | | | |
|---------------------------------------|----------------------------|---------------|--------------|--------------|--|--|--|--|--|--|--|
| | | This Estimate | Previous | To Date | | | | | | | |
| 191018-D08 | | | | | | | | | | | |
| | Total Posted Items Pay | \$45,244.00 | \$466,556.00 | \$511,800.00 | | | | | | | |
| | Gross Item Adjustments | (\$1,996.20) | (\$926.75) | (\$2,922.95) | | | | | | | |
| | Incentive | \$0.00 | \$0.00 | \$0.00 | | | | | | | |
| | Disincentive | \$0.00 | \$0.00 | \$0.00 | | | | | | | |
| | Liquidated Damage | \$0.00 | \$0.00 | \$0.00 | | | | | | | |
| | Other Contract Adjustments | \$0.00 | \$0.00 | \$0.00 | | | | | | | |
| | | | \$465,629.25 | \$508,877.05 | | | | | | | |
| Contract Total Paya | able This Estimate: | \$43,247.80 | | | | | | | | | |

Items Paid This Estimate Period

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount |
|-------------------|----------------|--------------|--|------|------------|--------------------------|-----------------------------|
| J5S3288 | 0030 | 2024043 | REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) | SQFT | \$162.000 | 3 | \$486.00 |
| | 0130 | 6113040 | PLACING TYPE 2 ROCK BLANKET | CUYD | \$18.000 | 180 | \$3,240.00 |
| | 0240 | 6240103A | PERMANENT EROSION CONTROL GEOTEXTILE | SQYD | \$3.000 | 271 | \$813.00 |
| | 0550 | 7032003 | CLASS B CONCRETE (SUBSTRUCTURE) | CUYD | \$850.000 | 26.8 | \$22,780.00 |
| | 0590 | 7061060 | REINFORCING STEEL (BRIDGES) | LB | \$1.500 | 9,750 | \$14,625.00 |
| | 0620 | 7161000 | PLAIN NEOPRENE BEARING PAD | EA | \$150.000 | 6 | \$900.00 |
| | 0630 | 7161002 | LAMINATED NEOPRENE BEARING PAD | EA | \$200.000 | 12 | \$2,400.00 |
| Project J5S328 | 88 - Total | | | | | | \$45,244.00 |
| Overall - Total | | | | | | | \$45,244.00 |

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
|-------------------|-------------|--------------------------------|--------------------|----------------------------------|--|------------------------|---------------------------------------|-------------------|
| J5S3288 | 0340 | MGS GUARDRAIL | Overrun | | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | -37.8 | \$29.00 | (\$1,096.20) |
| | 0410 | SLAB ON STEEL | Material | | | -628 | \$230.00 | (\$144,440.00) |
| | 0410 | SLAB ON STEEL | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user coram overridding Payment Estimate Exception 1 on the current Payment Estimate. | 628 | \$230.00 | \$144,440.00 |
| | 0420 | SAFETY BARRIER CURB | Material | | | -394 | \$48.00 | (\$18,912.00) |
| | 0420 | SAFETY BARRIER CURB | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user coram overridding Payment Estimate Exception 2 on the current Payment Estimate. | 394 | \$48.00 | \$18,912.00 |
| | 0590 | REINFORCING STEEL (BRIDGES) | Material | | | -9,750 | \$1.50 | (\$14,625.00) |

Revision 4/1/2020 Page 1 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 17, 2020

| Progre | | imate Number 8 | Contract ID Prime Contr | 191018 actor Gene l | | | | der Amount | \$849,329.75 \$0.00 \$849,329.75 |
|-------------------|-------------|-------------------|--------------------------|------------------------|----------------------------------|--|------------------------|---------------------------------------|--|
| Project Number | Line No. | Item Des | cription | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| J5S3288 | 0590 | REINFOR | RCING STEEL (BRIDGES) | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user coram overridding Payment Estimate Exception 3 on the current Payment Estimate. | 9,750 | \$1.50 | \$14,625.00 |
| | 0620 | | NEOPRENE EARING PAD | Material | | | -6 | \$150.00 | (\$900.00) |
| Total | | | | | | | | | (\$1,996.20) |

Revision 4/1/2020 Page 2 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | | | | | (| Contract Project Information | 1 | | | | | | | |
|-------------------|----------------------------|---|-------|----------|--|--|---|--|--|--|--|--|--|--|
| Project Number | Federal Proj. Number | Project Description | Route | County | | Location of Work | | | | | | | | |
| J5S3288 | FAS S401(61) | Bridge replacement and bridge rehabilitation | CC | MONITEAU | 0.3 miles and 3.0 miles | miles and 3.0 miles north of Route C | | | | | | | | |
| Totals by J | Job Numbe | rs | | | | | | | | | | | | |
| J5S3288 | | d Item Pay Item Adjustm | | Item Pay | This Estimate \$45,244.00 (\$1,996.20) \$43,247.80 | Previous \$466,556.00 (\$926.75) \$465,629.25 | To Date \$511,800.00 (\$2,922.95) \$508,877.05 | | | | | | | |
| | | | | | \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 | | | | | | | | | |

Revision 4/1/2020 Page 3 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions / Discrepencies | Explanation | Entered By | Status |
|--|---|---------------|--------------|
| Estimate Exception Type: Insufficient Materials: Project J5S3288, Item 7034212, Project Item Line Number 0410, Material Set 703421296, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient. | Waiting for QA to report concrete Sealer. | coram | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3288, Item 7034215, Project Item Line Number 0420, Material Set 703421596, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient. | Waiting for QA to report sealer. | coram | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3288, Item 7061060, Project Item Line Number 0590, Material Set 706106096, Material 1036RSDFPL42M16 - Reinforcing Steel No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient. | Waiting for QA to report test results. | coram | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3288, Item 7061060, Project Item Line Number 0590, Material Set 706106096, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient. | Waiting for QA to report test results. | coram | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3288, Item 7061060, Project Item Line Number 0590, Material Set 706106096, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient. | Waiting for QA to report test results. | coram | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3288, Item 7061060, Project Item Line Number 0590, Material Set 706106096, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient. | Waiting for QA to report test results. | coram | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3288, Item 7061060, Project Item Line Number 0590, Material Set 706106096, Material 1036RSDFPL42M29 - Reinforcing Steel No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient. | Waiting for QA to report test results. | coram | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3288, Item 7161000, Project Item Line Number 0620, Material Set 716100096, Material 1038BBPD - Bridge Bearing Pad, Acceptance Action Generic 1038BBPD is insufficient. | Waiting for contractor to submit certifications | coram | Acknowledged |
| Estimate Exception Type: Item Overrun: Contract 191018-D08, Contract Project J5S3288, Project Item Line Number 0340, Contract Line Item Number 0340, Item 6061060, Minor Item. | Change Order not complete at this time. | coram | Acknowledged |

Revision 4/1/2020 Page 4 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTEI To Date (See repor- generated date) |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 91018-D08 | J5S3288 | 0001 | 0010 | 2013000 | CLEARING AND GRUBBING | 1.00 | 0.00 | 1.00 | ACRE | 0.50 | \$4,000.00 | \$2,000.0 |
| | | 0001 | 0020 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$5,000.00 | \$5,000.0 |
| | | 0001 | 0030 | 2024043 | REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) | 27.00 | 0.00 | 27.00 | SQFT | 27.00 | \$162.00 | \$4,374.0 |
| | | 0001 | 0040 | 2031000 | CLASS A EXCAVATION | 198.00 | 0.00 | 198.00 | CUYD | 77.00 | \$10.00 | \$770.0 |
| | | 0001 | 0050 | 2035500 | EMBANKMENT IN PLACE | 824.00 | 0.00 | 824.00 | CUYD | 342.00 | \$24.00 | \$8,208.0 |
| | | 0001 | 0060 | 2036000 | COMPACTING EMBANKMENT | 158.00 | 0.00 | 158.00 | CUYD | 62.00 | \$9.50 | \$589.0 |
| | | 0001 | 0070 | 3040143 | TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) | 62.00 | 0.00 | 62.00 | SQYD | 28.00 | \$9.00 | \$252.0 |
| | | 0001 | 0800 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 33.00 | 0.00 | 33.00 | SQYD | 15.00 | \$15.00 | \$225.0 |
| | | 0001 | 0090 | 4011209 | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) | 129.00 | 0.00 | 129.00 | TONS | 47.45 | \$150.00 | \$7,117.5 |
| | | 0001 | 0100 | 4019905 | MISC.OPTIONAL PAVEMENT (7" BP VS. 7"PCCP) | 62.00 | 0.00 | 62.00 | SQYD | 33.77 | \$65.00 | \$2,195.0 |
| | | 0001 | 0110 | 4071005 | TACK COAT | 45.00 | 0.00 | 45.00 | GAL | 30.00 | \$22.00 | \$660.0 |
| | | 0001 | 0120 | 6113020 | FURNISHING TYPE 2 ROCK BLANKET | 728.00 | 0.00 | 728.00 | CUYD | 167.00 | \$28.00 | \$4,676.0 |
| | | 0001 | 0130 | 6113040 | PLACING TYPE 2 ROCK BLANKET | 728.00 | 0.00 | 728.00 | CUYD | 347.00 | \$18.00 | \$6,246.0 |
| | | 0001 | 0140 | 6161005 | CONSTRUCTION SIGNS | 230.00 | 0.00 | 230.00 | SQFT | 215.00 | \$10.00 | \$2,150.0 |
| | | 0001 | 0150 | 6161008 | ADVANCED WARNING RAIL SYSTEM | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$53.00 | \$106.0 |
| | | 0001 | 0160 | 6161009 | FLAG ASSEMBLY | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$22.00 | \$44.0 |
| | | 0001 | 0170 | 6161010 | RELOCATED SIGNS | 109.00 | 0.00 | 109.00 | SQFT | 109.00 | \$7.00 | \$763.0 |
| | | 0001 | 0180 | 6161031 | TYPE III MOVEABLE BARRICADE WITH LIGHTS | 14.00 | 0.00 | 14.00 | EA | 12.00 | \$190.00 | \$2,280.0 |
| | | 0001 | 0190 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$4,000.00 | \$8,000.0 |
| | | 0001 | 0200 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 0.75 | \$52,500.00 | \$39,375.0 |
| | | 0001 | 0210 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 1,188.00 | 0.00 | 1,188.00 | LF | 539.00 | \$1.25 | \$673. |
| | | 0001 | 0220 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 559.00 | 0.00 | 559.00 | LF | 336.00 | \$1.25 | \$420.0 |
| | | 0001 | 0230 | 6221001 | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) | 454.00 | 0.00 | 454.00 | SQYD | 347.00 | \$26.00 | \$9,022. |
| | | 0001 | 0240 | 6240103A | PERMANENT EROSION CONTROL GEOTEXTILE | 1,093.00 | 0.00 | 1,093.00 | SQYD | 522.00 | \$3.00 | \$1,566. |
| | | 0001 | 0250 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 0.50 | \$7,500.00 | \$3,750. |
| | | 0001 | 0260 | 8051000A | SEEDING - COOL SEASON MIXTURES | 0.60 | 0.00 | 0.60 | ACRE | 0.38 | \$7,500.00 | \$2,820. |
| | | 0001 | 0270 | 8061005 | ROCK DITCH CHECK | 42.00 | 0.00 | 42.00 | LF | 42.00 | \$15.00 | \$630. |
| | | 0001 | 0280 | 8061016 | SEDIMENT REMOVAL | 15.00 | 0.00 | 15.00 | CUYD | 0.00 | \$5.00 | \$0. |
| | | 0001 | 0290 | 8061017 | TEMPORARY SEEDING AND MULCHING | 0.20 | 0.00 | 0.20 | ACRE | 0.00 | \$12,500.00 | \$0. |
| | | 0001 | 0300 | 8061019 | SILT FENCE | 1,186.00 | 0.00 | 1,186.00 | LF | 645.00 | \$2.50 | \$1,612. |
| | | 0001 | 0310 | 8061050 | TYPE C BERM | 510.00 | 0.00 | 510.00 | LF | 349.00 | \$15.00 | \$5,235. |
| | | 0001 | 0320 | 8064137 | TYPE 2C EROSION CONTROL BLANKET | 1,305.00 | 0.00 | 1,305.00 | SQYD | 0.00 | \$2.00 | \$0. |
| | | 0001 | 0330 | 8064138 | TYPE 2D EROSION CONTROL BLANKET | 1,917.00 | 0.00 | 1,917.00 | SQYD | 0.00 | \$2.00 | \$0. |
| | | 0010 | 0340 | 6061060 | MGS GUARDRAIL | 131.00 | 0.00 | 131.00 | LF | 168.80 | \$29.00 | \$4,895. |
| | | 0010 | 0350 | 6061069 | MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) | 8.00 | 0.00 | 8.00 | EA | 4.00 | \$3,050.00 | \$12,200. |
| | | 0010 | 0360 | 6061078 | MGS EMBEDDED ANCHOR SECTION (WITH RUBRAIL) | 125.00 | 0.00 | 125.00 | LF | 0.00 | \$36.00 | \$0. |
| | | 0010 | 0370 | 6061080 | MGS END ANCHOR | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$1,734.00 | \$1,734. |
| | | 0010 | 0380 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | 6.00 | 0.00 | 6.00 | EA | 3.00 | \$3,000.00 | \$9,000. |
| | | 0070 | 0390 | 2162500 | REMOVAL OF EXISTING BRIDGE DECK | 5,666.00 | 0.00 | 5,666.00 | SQFT | 5,666.00 | \$6.00 | \$33,996. |
| | | 0070 | 0400 | 5031011A | BRIDGE APPROACH SLAB (MINOR ROAD) | 122.00 | 0.00 | 122.00 | SQYD | 116.00 | \$125.00 | \$14,500. |
| | | 0070 | 0410 | 7034212 | SLAB ON STEEL | 628.00 | 0.00 | 628.00 | SQYD | 628.00 | \$230.00 | \$144,440. |
| | | 0070 | 0420 | 7034215 | SAFETY BARRIER CURB | 394.00 | 0.00 | 394.00 | LF | 394.00 | \$48.00 | \$18,912. |
| | | 0070 | 0430 | 7121159 | SHEAR CONNECTORS | 328.00 | 0.00 | 328.00 | EA | 328.00 | \$16.00 | \$5,248. |
| | | 0070 | 0440 | 7123610 | SLAB DRAIN | 12.00 | 0.00 | 12.00 | EA | 12.00 | \$375.00 | \$4,500.0 |

Revision 4/1/2020 Page 5 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|----------------------|----------------|-------------|-------------|---------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 018-D08 | J5S3288 | 0070 | 0450 | 7126000 | NON-DESTRUCTIVE TESTING | 196.00 | 0.00 | 196.00 | LF | 196.00 | \$10.00 | \$1,960.00 |
| | | 0071 | 0460 | 2061000 | CLASS 1 EXCAVATION | 70.00 | 0.00 | 70.00 | CUYD | 0.00 | \$15.00 | \$0.00 |
| | | 0071 | 0470 | 2160500 | REMOVAL OF BRIDGES | 1.00 | 0.00 | 1.00 | LS | 0.90 | \$22,500.00 | \$20,250.00 |
| | | 0071 | 0480 | 5031011A | BRIDGE APPROACH SLAB (MINOR ROAD) | 120.00 | 0.00 | 120.00 | SQYD | 0.00 | \$125.00 | \$0.00 |
| | | 0071 | 0490 | 7011203 | ROCK SOCKETS (2 FT 6IN. DIA.) | 28.00 | 0.00 | 28.00 | LF | 28.00 | \$1,000.00 | \$28,000.00 |
| | | 0071 | 0500 | 7011300 | VIDEO CAMERA INSPECTION | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$100.00 | \$400.00 |
| | | 0071 | 0510 | 7011400 | FOUNDATION INSPECTION HOLES | 68.00 | 0.00 | 68.00 | LF | 68.00 | \$110.00 | \$7,480.00 |
| | | 0071 | 0520 | 7011600 | SONIC LOGGING TESTING | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$1,300.00 | \$5,200.00 |
| | | 0071 | 0530 | 7021212 | GALVANIZED STRUCTURAL STEEL PILES (12 IN) | 112.00 | 0.00 | 112.00 | LF | 107.00 | \$150.00 | \$16,050.00 |
| | | 0071 | 0540 | 7027000 | PILE POINT REINFORCEMENT | 8.00 | 0.00 | 8.00 | EA | 8.00 | \$125.00 | \$1,000.00 |
| | | 0071 | 0550 | 7032003 | CLASS B CONCRETE (SUBSTRUCTURE) | 51.10 | 0.00 | 51.10 | CUYD | 51.00 | \$850.00 | \$43,350.00 |
| | | 0071 | 0560 | 7034213 | SLAB ON CONCRETE I-GIRDER | 374.00 | 0.00 | 374.00 | SQYD | 0.00 | \$320.00 | \$0.00 |
| | | 0071 | 0570 | 7034215 | SAFETY BARRIER CURB | 265.00 | 0.00 | 265.00 | LF | 0.00 | \$60.00 | \$0.00 |
| | | 0071 | 0580 | 7056000 | TYPE 2 (32 IN.), PRESTRESSED CONCRETE I-GIRDER | 345.00 | 0.00 | 345.00 | LF | 0.00 | \$175.00 | \$0.00 |
| | | 0071 | 0590 | 7061060 | REINFORCING STEEL (BRIDGES) | 9,750.00 | 0.00 | 9,750.00 | LB | 9,750.00 | \$1.50 | \$14,625.00 |
| | | 0071 | 0600 | 7123610 | SLAB DRAIN | 16.00 | 0.00 | 16.00 | EA | 0.00 | \$275.00 | \$0.00 |
| | | 0071 | 0610 | 7151001 | VERTICAL DRAIN AT END BENTS | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$1,000.00 | \$0.00 |
| | | 0071 | 0620 | 7161000 | PLAIN NEOPRENE BEARING PAD | 6.00 | 0.00 | 6.00 | EA | 6.00 | \$150.00 | \$900.00 |
| | | 0071 | 0630 | 7161002 | LAMINATED NEOPRENE BEARING PAD | 12.00 | 0.00 | 12.00 | EA | 12.00 | \$200.00 | \$2,400.00 |
| | Project J | 5S3288 - To | otal Value | Posted to D | late as of Report Generated Date | | | | | | | \$511,800.00 |
| 18-D08 Ove | erall - Total | Value Post | ted to Da | te as of Repo | ort Generated Date | | | | | | | \$511,800.00 |

Revision 4/1/2020 Page 6 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5S3288

| | | 8 12 | DIAID | DIAID | 0 17 | 11.7 | 1 2 | 055.11 | - | 0" " | |
|----------------|--------------|--|-------------|-------------------------|--------------------|-------|---|-------------|-------------------------------|---------------------|--|
| Line Number | Item Code | Description | DWR Date | DWR Approval Date | Quantity Posted | Units | Location From Station Log Mile | n/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
| 0030 | 2024043 | REMOVAL OF MISCELLANEOUS ACM NON-FRIABLE | 8/4/20 | 8/11/20 | 3.00 | SQFT | 355+70 | 0 | 356+87 | | Final paperwork received. Final payment on removal of ACM from Bridge A8800. |
| 0120 | 6113020 | FURNISHING TYPE 2 ROCK BLANKET | 8/13/20 | 8/17/20 | -180.00 | CUYD | (| 0 | | | Rock tickets not received from Contractor. Payment withheld. |
| | | | | 8/17/20 | 67.00 | CUYD | 355+63 | 33 | 355+90 | | Type 2 Rock Blanket |
| | | | | 8/17/20 | 113.00 | CUYD | 356+67 | 57 | 356+95 | | Type 2 Rock Blanket |
| 0130 | 6113040 | PLACING TYPE 2 ROCK BLANKET | 8/13/20 | 8/17/20 | 67.00 | CUYD | 355+63 | 33 | 355+90 | | Type 2 Rock Blanket |
| | | | | 8/17/20 | 113.00 | CUYD | 356+67 | 67 | 356+95 | | Type 2 Rock Blanket |
| 0240 | 6240103A | PERMANENT EROSION CONTROL GEOTEXTILE | 8/13/20 | 8/17/20 | 100.00 | SQYD | 355+63 | 3 | 355+90 | | |
| | | | | 8/17/20 | 171.00 | SQYD | 356+67 | 67 | 356+95 | | |
| 0550 | 7032003 | CLASS B CONCRETE (SUBSTRUCTURE) | 8/10/20 | 8/11/20 | 13.40 | CUYD | 356+07 | 07 | | | Bent 2 Cap |
| | | | | 8/11/20 | 13.40 | CUYD | 356+52 | 52 | | | Bent 3 Cap |
| 0590 | 7061060 | REINFORCING STEEL (BRIDGES) | 8/10/20 | 8/11/20 | 4,830.00 | LB | 356+07 |)7 | | | Bent 2 Reinforcing Steel |
| | | | | 8/11/20 | 4,920.00 | LB | 356+52 | 52 | | | Bent 3 Reinforcing Steel |
| 0620 | 7161000 | PLAIN NEOPRENE BEARING PAD | 8/13/20 | 8/17/20 | 6.00 | EA | 355+70 | 0 | 356+88 | | Bent 1 & 4 |
| 0630 | 7161002 | LAMINATED NEOPRENE BEARING PAD | 8/13/20 | 8/17/20 | 12.00 | EA | 356+07 |)7 | 356+52 | | Bent 2 & 3 |

The information below this line are details from Line Item agency views.

No Agency View Details Exist

Revision 4/1/2020 Page 7 of 13



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|------------|---|
| 0040 | CLASS A EXCAVATION | Price | | 5 | Jul 1, 2020 | SYSTEM | (\$11.10) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | 6 | Jul 16, 2020 | SYSTEM | (\$4.59) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | - Total | | | | (\$15.69) | |
| | Price - Total | | | | | | (\$15.69) | |
| 0040 - | Total | | | | | | (\$15.69) | |
| 0050 | EMBANKMENT IN PLACE | Price | | 5 | Jul 1, 2020 | SYSTEM | (\$97.12) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | 6 | Jul 16, 2020 | SYSTEM | (\$27.37) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | - Total | | | | (\$124.49) | |
| | Price - Total | | | | | | (\$124.49) | |
| 0050 - | Total | | | | | | (\$124.49) | |
| 0070 | TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) | Material | | 6 | Jul 16, 2020 | SYSTEM | (\$252.00) | |
| | | | | 6 | Jul 16, 2020 | SYSTEM | \$252.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user coram overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) | Price | | 6 | Jul 16, 2020 | SYSTEM | (\$3.57) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | - Total | | | | (\$3.57) | |
| | Price - Total | | | | | | (\$3.57) | |
| 0070 - | ·Total | | | | | | (\$3.57) | |
| 0800 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Material | | 5 | Jul 1, 2020 | SYSTEM | (\$225.00) | |
| | | | | 6 | Jul 16, 2020 | SYSTEM | (\$225.00) | |
| | | | - Total | | | | (\$450.00) | |
| | Material - Total | | | | | | (\$450.00) | |
| | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | MaterialCredit | | 6 | Jul 16, 2020 | SYSTEM | \$225.00 | |
| | | | | 7 | Aug 3, 2020 | SYSTEM | \$225.00 | |
| | | | - Total | | | | \$450.00 | |
| | MaterialCredit - Total | | | | | | \$450.00 | |
| 0080 - | Total | | | | | | \$0.00 | |
| 0090 | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) | | ACAD | | Jul 16, 2020 | coram | (\$139.74) | |
| | | | ACAD - Tota | al | | | (\$139.74) | |
| | Other Item Adjustment - Total | | | | | | (\$139.74) | |
| | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) | Price | | 6 | Jul 16, 2020 | SYSTEM | (\$133.90) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | - Total | | | | (\$133.90) | |
| | Price - Total | | | | | | (\$133.90) | |
| 0090 - | Total | | | | | | (\$273.64) | |
| 0100 | MISC. OPTIONAL PAVEMENT (7" BP VS. 7"PCCP) | | ACAD | | Jul 16, 2020 | coram | (\$38.29) | |
| | | | ACAD - Tota | al | | | (\$38.29) | |
| | MISC. OPTIONAL PAVEMENT (7" BP VS. 7"PCCP) | | FUEL | 6 | Jul 16, 2020 | coram | (\$35.64) | |
| | | | FUEL - Tota | ı | | | (\$35.64) | |
| | Other Item Adjustment - Total | | | | | | (\$73.93) | |
| 0100 - | Total | | | | | | (\$73.93) | |
| 0110 | TACK COAT | Material | | 6 | Jul 16, 2020 | SYSTEM | (\$660.00) | |

Revision 4/1/2020 Page 8 of 13



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|----------------------|---|
| 0110 | TACK COAT | Material | | 6 | Jul 16, 2020 | SYSTEM | \$660.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user coram overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0110 - | | | | | | | \$0.00 | |
| | | | | | | | | |
| 0120 | FURNISHING TYPE 2 ROCK BLANKET | Material | | 3 | Jun 3, 2020 | SYSTEM | (\$3,584.00) | |
| | | | | 4 | Jun 16, 2020 | SYSTEM | (\$3,584.00) | |
| | | | | 4 | Jun 16, 2020 | SYSTEM | \$3,584.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user coram overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | - Total | | | | (\$3,584.00) | |
| | Material - Total | | | | | | (\$3,584.00) | |
| | FURNISHING TYPE 2 ROCK | MaterialCredit | | 4 | Jun 16, | SYSTEM | \$3,584.00 | |
| | BLANKET | MaterialOreuit | | 7 | 2020 | STOTEM | | |
| | | | - Total | | | | \$3,584.00 | |
| | MaterialCredit - Total | | | | | | \$3,584.00 | |
| 0120 - | Total | | | | | | \$0.00 | |
| 0170 | RELOCATED SIGNS | Material | | 6 | Jul 16, 2020 | SYSTEM | (\$763.00) | |
| | | | - Total | | | | (\$763.00) | |
| | Material - Total | | | | | | (\$763.00) | |
| | | | | _ | | 0) (0 === 1.4 | | |
| | RELOCATED SIGNS | MaterialCredit | | 7 | Aug 3, 2020 | SYSTEM | \$763.00 | |
| | | | - Total | | | | \$763.00 | |
| | MaterialCredit - Total | | | | | | \$763.00 | |
| 0170 - | · Total | | | | | | \$0.00 | |
| 0210 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT | | | 6 | Jul 16, 2020 | SYSTEM | (\$673.75) | |
| | MARKING PAINT, TYPE P BEADS | | | 7 | Aug 3, 2020 | SYSTEM | (\$673.75) | |
| | | | | 7 | Aug 3, 2020 | SYSTEM | \$673.75 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user coram overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | - Total | | | | (\$673.75) | |
| | Material - Total | | | | | | (\$673.75) | |
| | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | MaterialCredit | | 7 | Aug 3, 2020 | SYSTEM | \$673.75 | |
| | | | - Total | | | | \$673.75 | |
| | MaterialCredit - Total | | | | | | \$673.75 | |
| 0240 | ·Total | | | | | | | |
| 0210 - | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT | Material | | 6 | Jul 16, | SYSTEM | \$0.00 (\$420.00) | |
| | MARKING PAINT, TYPE P BEADS | | | 7 | 2020 Aug 3, | SYSTEM | (\$420.00) | |
| | | | | 7 | 2020 Aug 3, | SYSTEM | \$420.00 | This adjustment offsets the original system-generated Overrun Payment |
| | | | | | 2020 | | | Estimate Item Adjustment (0008) due to user coram overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | - Total | | | | (\$420.00) | |
| | Material - Total | | | | | | (\$420.00) | |
| | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | MaterialCredit | | 7 | Aug 3, 2020 | SYSTEM | \$420.00 | |
| | | | - Total | | | | \$420.00 | |
| | MaterialCredit - Total | | | | | | \$420.00 | |
| 0220 | · Total | | | | | | \$0.00 | |
| 0220 - | - Total | | | | | | \$0.00 | |

Revision 4/1/2020 Page 9 of 13



| Total | Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks |
|--|--------|------------------------|----------------|--------------------|--------|---------|---------|--------------|--|
| CONTROL GEOTEXTILE | | | Туре | Adjustment Type | Number | Date | Ву | | |
| Material - Total | 0240 | | Material | | 3 | | SYSTEM | (\$576.00) | |
| Material - Total | | | | | 4 | | SYSTEM | (\$576.00) | |
| PERMANENT ROSION Material Credit | | | | - Total | | | | (\$1,152.00) | |
| 200 201 202 | | Material - Total | | | | | | (\$1,152.00) | |
| Autoritical Total | | | MaterialCredit | | 4 | | SYSTEM | \$576.00 | |
| Material - Total | | | | | 5 | | SYSTEM | \$576.00 | |
| Material Credit - Total | | | | - Total | | | | \$1,152.00 | |
| SEEDING - COOK SEADON Material | | MaterialCredit - Total | | | | | | \$1,152.00 | |
| | 0240 - | | | | | | | | |
| Total | 0260 | | Material | | 7 | | SYSTEM | | |
| Material - Total So.00 | | | | | 7 | Aug 3, | SYSTEM | \$2,820.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user coram overridding Payment Estimate Exception 25 on the current Payment Estimate. |
| September Sept | | - Total | | | | | | \$0.00 | |
| ROCK DITCH CHECK Material | | Material - Total | | | | | | \$0.00 | |
| 2020 | 0260 - | Total | | | | | | \$0.00 | |
| 2020 4 2016 2020 1 2020 | 0270 | ROCK DITCH CHECK | Material | | 3 | | SYSTEM | (\$630.00) | |
| 2020 Estimate Item Adjustment (0006) due to user coram overridding Pay Estimate Exception 8 on the current Payment Estimate. | | | | | 4 | | SYSTEM | (\$630.00) | |
| Material - Total | | | | | 4 | | SYSTEM | \$630.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user coram overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| ROCK DITCH CHECK | | | | - Total | | | | (\$630.00) | |
| 2020 Se30.00 Se30.00 | | Material - Total | | | | | | (\$630.00) | |
| Material Credit - Total \$630.00 | | ROCK DITCH CHECK | MaterialCredit | | 4 | | SYSTEM | \$630.00 | |
| | | | | - Total | | | | \$630.00 | |
| | | MaterialCredit - Total | | | | | | \$630.00 | |
| 2020 4 | 0270 - | Total | | | | | | \$0.00 | |
| 2020 4 | 0310 | TYPE C BERM | Material | | 3 | | SYSTEM | (\$2,670.00) | |
| 2020 Estimate Item Adjustment (0003) due to user coram overridding Paye | | | | | 4 | | SYSTEM | (\$2,670.00) | |
| Material - Total | | | | | 4 | | SYSTEM | \$2,670.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user coram overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| TYPE C BERM MaterialCredit 4 | | | | - Total | | | | (\$2,670.00) | |
| 2020 S2,670.00 | | Material - Total | | | | | | (\$2,670.00) | |
| MaterialCredit - Total \$2,670.00 MGS GUARDRAIL Material 6 | | TYPE C BERM | MaterialCredit | | 4 | | SYSTEM | \$2,670.00 | |
| MGS GUARDRAIL Material 6 | | | | - Total | | | | \$2,670.00 | |
| MGS GUARDRAIL Material 6 Jul 16, 2020 SYSTEM (\$4,895.20) 6 Jul 16, SYSTEM \$4,895.20 This adjustment offsets the original system-generated Overrun Paym Estimate Item Adjustment (0013) due to user coram overridding Payle Estimate Exception 16 on the current Payment Estimate. 7 Aug 3, 2020 SYSTEM \$4,895.20 7 Aug 3, 2020 This adjustment offsets the original system-generated Overrun Paym Estimate Item Adjustment (0002) due to user coram overridding Payle Estimate Exception 1 on the current Payment Estimate. - Total \$0.00 | | MaterialCredit - Total | | | | | | \$2,670.00 | |
| 2020 6 Jul 16, 2020 84,895.20 This adjustment offsets the original system-generated Overrun Paym Estimate Item Adjustment (0013) due to user coram overridding Payle Estimate Exception 16 on the current Payment Estimate. 7 Aug 3, 2020 7 Aug 3, 2020 84,895.20 This adjustment offsets the original system-generated Overrun Paym Estimate Item Adjustment (0002) due to user coram overridding Payle Estimate Exception 1 on the current Payment Estimate. - Total \$0.00 | 0310 - | Total | | | | | | \$0.00 | |
| 2020 Estimate Item Adjustment (0013) due to user coram overridding Payl Estimate Exception 16 on the current Payment Estimate. 7 Aug 3, 2020 7 Aug 3, 2020 SYSTEM \$4,895.20 This adjustment offsets the original system-generated Overrun Paym Estimate Item Adjustment (0002) due to user coram overridding Payl Estimate Exception 1 on the current Payment Estimate. | 0340 | MGS GUARDRAIL | Material | | 6 | | SYSTEM | (\$4,895.20) | |
| 7 Aug 3, 2020 This adjustment offsets the original system-generated Overrun Paym Estimate Item Adjustment (0002) due to user coram overridding Payl Estimate Exception 1 on the current Payment Estimate. | | | | | 6 | | SYSTEM | \$4,895.20 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user coram overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| Estimate Item Adjustment (0002) due to user coram overridding Payl Estimate Exception 1 on the current Payment Estimate. - Total \$0.00 | | | | | 7 | | SYSTEM | (\$4,895.20) | |
| | | | | | 7 | | SYSTEM | \$4,895.20 | This adjustment offsets the original system-generated Overrun Payment |
| | | | | | | 2020 | | | |
| Material - Total \$0.00 | | | | - Total | | 2020 | | \$0.00 | |

Revision 4/1/2020 Page 10 of 13



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|--------------------------------------|--------------------------|-----------------------------|----------------|-----------------|---------------|----------------|---|
| 0340 | MGS GUARDRAIL | Overrun | Overrun | 6 | Jul 16, 2020 | SYSTEM | (\$1,096.20) | |
| | | | | 6 | Jul 16, 2020 | SYSTEM | \$1,096.20 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 31 on the current Payment Estimate. |
| | | | | 7 | Aug 3, 2020 | SYSTEM | (\$1,096.20) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | 7 | Aug 3, 2020 | SYSTEM | \$1,096.20 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 27 on the current Payment Estimate. |
| | | | | 8 | Aug 17, 2020 | SYSTEM | (\$1,096.20) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | Overrun - Total | | | | (\$1,096.20) | | |
| | Overrun - Total | | | | | | (\$1,096.20) | |
| 0340 - | Total | | | | | | (\$1,096.20) | |
| 0370 | MGS END ANCHOR | Material | | 6 | Jul 16, 2020 | SYSTEM | (\$1,734.00) | |
| | | | | 7 | Aug 3, 2020 | SYSTEM | (\$1,734.00) | |
| | | | | 7 | Aug 3, 2020 | SYSTEM | \$1,734.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user coram overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | - Total | | | | (\$1,734.00) | | |
| | Material - Total | | | | | | (\$1,734.00) | |
| | MGS END ANCHOR | MaterialCredit | | 7 | Aug 3, 2020 | SYSTEM | \$1,734.00 | |
| | - Total | | | | | | \$1,734.00 | |
| | MaterialCredit - Total | | | | | | \$1,734.00 | |
| 0370 - | Total | | | | | | \$0.00 | |
| 0400 | BRIDGE APPROACH SLAB (MINOR ROAD) | Material | | 6 | Jul 16, 2020 | SYSTEM | (\$14,500.00) | |
| | | | - Total | | | | (\$14,500.00) | |
| | Material - Total | | | | | | (\$14,500.00) | |
| | BRIDGE APPROACH SLAB (MINOR ROAD) | MaterialCredit | | 7 | Aug 3, 2020 | SYSTEM | \$14,500.00 | |
| | | | - Total | | | | \$14,500.00 | |
| | MaterialCredit - Total | | | | | \$14,500.00 | | |
| | BRIDGE APPROACH SLAB (MINOR ROAD) | Other Item Adjustment | ACAD | 6 | Jul 16, 2020 | coram | (\$225.47) | |
| | | | ACAD - Tota | | | | (\$225.47) | |
| | BRIDGE APPROACH SLAB (MINOR ROAD) | | FUEL | 6 | Jul 16, 2020 | coram | (\$209.96) | |
| | FUEL - Total | | | | | | (\$209.96) | |
| | Other Item Adjustment - Total | | | | | | (\$435.43) | |
| 0400 - | Total | | | | | | (\$435.43) | |
| 0410 | SLAB ON STEEL | Material | | 3 | Jun 3, 2020 | SYSTEM | (\$34,500.00) | |
| | | | | 3 | Jun 3, 2020 | SYSTEM | \$34,500.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user coram overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 4 | Jun 16, 2020 | SYSTEM | (\$135,240.00) | |
| | | | | 4 | Jun 16, 2020 | SYSTEM | \$135,240.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user coram overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 5 | Jul 1, 2020 | SYSTEM | (\$135,240.00) | |
| | | | | 5 | Jul 1, 2020 | SYSTEM | \$135,240.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user coram overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 6 | Jul 16, 2020 | SYSTEM | (\$135,240.00) | |

Revision 4/1/2020 Page 11 of 13



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|--|
| 0410 | SLAB ON STEEL | Material | | 6 | Jul 16, 2020 | SYSTEM | \$135,240.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user coram overridding Payment Estimate Exception 23 on the current Payment Estimate. |
| | | | | 7 | Aug 3, 2020 | SYSTEM | (\$144,440.00) | |
| | | | | 7 | Aug 3, 2020 | SYSTEM | \$144,440.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user coram overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | 8 | Aug 17, 2020 | SYSTEM | (\$144,440.00) | |
| | | | | 8 | Aug 17, 2020 | SYSTEM | \$144,440.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user coram overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0410 - | Total | | | | | | \$0.00 | |
| 0420 | SAFETY BARRIER CURB | Material | | 5 | Jul 1, 2020 | SYSTEM | (\$17,040.00) | |
| | | | | 5 | Jul 1, 2020 | SYSTEM | \$17,040.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user coram overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | 6 | Jul 16, 2020 | SYSTEM | (\$17,040.00) | |
| | | | | 6 | Jul 16, 2020 | SYSTEM | \$17,040.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user coram overridding Payment Estimate Exception 27 on the current Payment Estimate. |
| | | | | 7 | Aug 3, 2020 | SYSTEM | (\$18,912.00) | |
| | | | | 7 | Aug 3, 2020 | SYSTEM | \$18,912.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user coram overridding Payment Estimate Exception 21 on the current Payment Estimate. |
| | | | | 8 | Aug 17, 2020 | SYSTEM | (\$18,912.00) | |
| | | | | 8 | Aug 17, 2020 | SYSTEM | \$18,912.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user coram overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | - Total | | | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0420 - | Total | | | | | | \$0.00 | |
| 0490 | ROCK SOCKETS (2 FT 6IN. DIA.) | Material | | 7 | Aug 3, 2020 | SYSTEM | (\$28,000.00) | |
| | | | | 7 | Aug 3, 2020 | SYSTEM | \$28,000.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user coram overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0490 - | Total | | | | | | \$0.00 | |
| 0530 | GALVANIZED STRUCTURAL STEEL PILES (12 IN) | | | 7 | Aug 3, 2020 | SYSTEM | (\$16,050.00) | |
| | | | | 7 | Aug 3, 2020 | SYSTEM | \$16,050.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user coram overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | - Total | | | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0530 - | Total | | | | | | \$0.00 | |
| 0540 | PILE POINT REINFORCEMENT | Material | | 7 | Aug 3, 2020 | SYSTEM | (\$1,000.00) | |
| | | | | 7 | Aug 3, 2020 | SYSTEM | \$1,000.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user coram overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | - Total | | | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0540 | Total | | | | | | \$0.00 | |

Revision 4/1/2020 Page 12 of 13



| Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks |
|--------|------------------------------------|------------|--------------------|------|-----------------|------------|---------------|--|
| LIIIC | Description | Туре | Adjustment Type | | Date | Ву | Amount | r.Cinear.C |
| 0550 | CLASS B CONCRETE (SUBSTRUCTURE) | Material | | 7 | Aug 3, 2020 | SYSTEM | (\$20,570.00) | |
| | | | | 7 | Aug 3, 2020 | SYSTEM | \$20,570.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user coram overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0550 - | Total | | | | | | \$0.00 | |
| 0590 | REINFORCING STEEL (BRIDGES) | Material | | 8 | Aug 17, 2020 | SYSTEM | (\$14,625.00) | |
| | | | | 8 | Aug 17, 2020 | SYSTEM | \$14,625.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user coram overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | - Total | | | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0590 - | Total | | | | | | \$0.00 | |
| 0620 | PLAIN NEOPRENE BEARING PAD | Material | | 8 | Aug 17, 2020 | SYSTEM | (\$900.00) | |
| | | - Total | | | | (\$900.00) | | |
| | Material - Total | | | | | | (\$900.00) | |
| 0620 - | Total | | | | | | (\$900.00) | |
| Overa | ıll - Total | | | | | | (\$2,922.95) | |

Revision 4/1/2020 Page 13 of 13