

Pay Estimate Created Date: September 16, 2020

Progress Estima 13	te Number	Contract ID Prime Contrac	ontract ID 191018-F06 Pay Period StartSeptember 2, 2020 Original Contract Amount \$1,751,00 rime Contractor N.B. West Contracting Company Pay Period End September 15, 2020 Net Change Order Amount \$85,775.9 Current Contract Amount \$1,836,77							
Approval Date						By User				
September 16, 2020		Generated and Approved (and should be considered Draft) at the Project Office Level by ha								
September 17, 2020			Reviewed and Ap	proved (and should be considered Dr	aft) at the Resident Engineer Level by	washas				
September 18, 2020				Reviewed and Approved at the Cer	ntral Office Controllers Office Level by	greggd1				
Original Comp	letion Date	Curren	t Completion Date	Actual Completion Date	% of Current Contract Amou	nt Complete				
November	1, 2020	No	vember 1, 2020		86.30%					

No Milestones Exist for Contract

Contract Total Pay For Estimate No. 13

Total Posted Items Pay \$57,618.21 \$1,527,457.98 \$1,585,076.19 191018-F06 foross Item Adjustments (\$21,097.48) \$69,758.50 \$48,661.02 Incentive \$0.00 \$0.00 \$0.00 \$0.00 Disincentive \$0.00 \$0.00 \$0.00 \$0.00 Liquidated Damage \$0.00 \$0.00 \$0.00 \$0.00 Other Contract Adjustments \$0.00 \$0.00 \$0.00 \$0.00	Contract Total Payable This Estimate:	\$36,520.73		
191018-F06 Total Posted Items Pay \$57,618.21 \$1,527,457.98 \$1,585,076.19 Gross Item Adjustments (\$21,097.48) \$69,758.50 \$48,661.02 Incentive \$0.00 \$0.00 \$0.00 Disincentive \$0.00 \$0.00 \$0.00 Liquidated Damage \$0.00 \$0.00 \$0.00			<mark>\$1,597,216.48</mark>	\$1,633,737.21
191018-F06 Total Posted Items Pay \$57,618.21 \$1,527,457.98 \$1,585,076.19 Gross Item Adjustments (\$21,097.48) \$69,758.50 \$48,661.02 Incentive \$0.00 \$0.00 \$0.00 Disincentive \$0.00 \$0.00 \$0.00	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
I91018-F06 Total Posted Items Pay \$57,618.21 \$1,527,457.98 \$1,585,076.19 Gross Item Adjustments (\$21,097.48) \$69,758.50 \$48,661.02 Incentive \$0.00 \$0.00 \$0.00	Liquidated Damage	\$0.00	\$0.00	\$0.00
191018-F06 Total Posted Items Pay	Disincentive	\$0.00	\$0.00	\$0.00
191018-F06 Total Posted Items Pay <mark>\$57,618.21 \$1,527,457.98 \$1,585,076.19</mark>	Incentive	\$0.00	\$0.00	\$0.00
191018-F06	Gross Item Adjustments	(\$21,097.48)	\$69,758.50	\$48,661.02
	Total Posted Items Pay	<mark>\$57,618.21</mark>	\$1,527,457.98	\$1,585,076.19
This Estimate Previous To Date	91018-F06			
		This Estimate	Previous	To Date

Contract Total Payable This Estimate:

Items Paid This Estimate Period

				1			
Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3229	0090	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	LF	\$16.800	580	\$9,744.00
	0130	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	EA	\$190.000	249	\$47,310.00
	0140	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.090	6,269	\$564.21
Project J6S3	3229 - Total	ĺ					\$57,618.21
Overall - To	tal						\$57,618.21

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project	Line	Item Description	Adjustment	Other Item	Comments	Adjustment	Line Item	Adjustment
Number	No.	item Description	Туре	Adjustment Type	Comments	Quantity	Adjustment Unit Price	amount
J6S3229	0010	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-1)	Material			-11,859.5	\$87.45	(\$1,037,113.28)
	0010	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-1)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user harank1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	11,859.5	\$87.45	\$1,037,113.28
	0060	MISC.	Material			-12	\$312.75	(\$3,753.00)
	0060	MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user harank1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	12	\$312.75	\$3,753.00
	0070	MISC.	Material			-30	\$347.36	(\$10,420.80)
	0070	MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user harank1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	30	\$347.36	\$10,420.80



Pay Estimate Created Date: September 16, 2020

	1	mate Number 3	Contract ID 191018-F06 Pay Period Start September 2, 2020 Original Contract Amount \$1,751,00 Prime Contractor N.B. West Contracting Company Pay Period End September 15, 2020 Net Change Order Amount \$85,775.9 Current Contract Amount \$1,836,77									
Project Number	Line No.	Item De	scription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount			
6S3229	0090		PREFORMED ERMOPLASTIC MARKING, 24 IN. WHITE	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$3,577.30			
	0090		PREFORMED ERMOPLASTIC MARKING, 24 IN. WHITE	Material			-711	\$16.80	(\$11,944.80			
	0090		PREFORMED ERMOPLASTIC MARKING, 24 IN. WHITE	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user harank1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	711	\$16.80	\$11,944.80			
	0100	PAVEME	PREFORMED ERMOPLASTIC ENT MARKING, RIGHT ARROW	Material			-64	\$273.21	(\$17,485.44			
	0100	PAVEME	PREFORMED ERMOPLASTIC ENT MARKING, RIGHT ARROW	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user harank1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	64	\$273.21	\$17,485.44			
	0130	PAVEMENT M	PREFORMED ERMOPLASTIC ARKING, 30 IN TE MIDBLOCK	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$17,520.18			
	0130	PAVEMENT M	PREFORMED ERMOPLASTIC ARKING, 30 IN TE MIDBLOCK	Material			-309	\$190.00	(\$58,710.00			
	0130	PAVEMENT M	PREFORMED ERMOPLASTIC ARKING, 30 IN TE MIDBLOCK	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user harank1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	309	\$190.00	\$58,710.00			
	0140	WATERBORN	TE STANDARD NE PAVEMENT PAINT, TYPE P BEADS	Material			-53,420	\$0.09	(\$4,807.80			
	0140	WATERBORN	TE STANDARD NE PAVEMENT PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user harank1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	53,420	\$0.09	\$4,807.80			
	0150	WATERBORN	W STANDARD NE PAVEMENT PAINT, TYPE P BEADS	Material			-44,022	\$0.09	(\$3,961.98			
	0150	WATERBORN	W STANDARD NE PAVEMENT PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user harank1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	44,022	\$0.09	\$3,961.98			



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					C	Contract Project Information	n				
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work				
J6S3229	FAS S501(65)	Coldmill and resurface	180	ST LOUIS CITY	on Dr. Martin Luther King Drive from St. Louis City limits to Route D						
Totals by J	Job Numbe	rs									
J6S3229		d Item Pay Item Adjustm		ttem Pay	This Estimate \$57,618.21 (\$21,097.48) \$36,520.73	Previous \$1,527,457.98 \$69,758.50 \$1,597,216.48	To Date \$1,585,076.19 \$48,661.02 \$1,633,737.21				
	Liquid	ive entive lated Damages Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3229, Item 6200015, Project Item Line Number 0090, Material Set 1048PMPFWH, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Waiting on final field measured totals	harank1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3229, Item 6209902, Project Item Line Number 0070, Material Set 1048PMPFWHXX, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Waiting on final field measured totals	harank1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3229, Item 6209902, Project Item Line Number 0060, Material Set 1048PMPFWHXX, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Waiting on final field measured totals	harank1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3229, Item 4011207, Project Item Line Number 0010, Material Set 401120796, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient.	Waiting on Materials to complete their reporting	harank1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3229, Item 6200021, Project Item Line Number 0100, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Waiting on final field measured totals	harank1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3229, Item 6200036, Project Item Line Number 0130, Material Set 620003696, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Waiting on final field measured totals	harank1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3229, Item 6206000C, Project Item Line Number 0140, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Waiting on final field measured totals	harank1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3229, Item 6206000C, Project Item Line Number 0140, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Waiting on final field measured totals	harank1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3229, Item 6206001C, Project Item Line Number 0150, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Waiting on final field measured totals	harank1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3229, Item 6206001C, Project Item Line Number 0150, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Waiting on final field measured totals	harank1	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
18-F06	J6S3229	0001	0010	4011207	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-1)	11,584.00	275.50	11,859.50	TONS	11,859.50	\$87.45	\$1,037,113.28
		0001	0020	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1,500.00	\$0.00
		0001	0030	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$1,200.00	\$2,400.00
		0001	0040	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,500.00	\$7,000.00
		0001	0050	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.75	\$7,146.00	\$5,359.50
		0001	0060	6209902	MISC.SHARED BIKE LANE	109.00	0.00	109.00	EA	12.00	\$312.75	\$3,753.00
		0001	0070	6209902	MISC.BIKE LANE	67.00	0.00	67.00	EA	30.00	\$347.36	\$10,420.80
		0001	0080	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.90	\$105,730.94	\$95,157.85
		0001	0090	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	2,220.00	0.00	2,220.00	LF	711.00	\$16.80	\$11,944.80
		0001	0100	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	177.00	0.00	177.00	EA	64.00	\$273.21	\$17,485.44
		0001	0110	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	4.00	0.00	4.00	EA	0.00	\$240.53	\$0.00
		0001	0120	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	2.00	0.00	2.00	EA	0.00	\$497.53	\$0.00
		0001	0130	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	1,010.00	0.00	1,010.00	EA	309.00	\$190.00	\$58,710.00
		0001	0140	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	57,428.00	0.00	57,428.00	LF	53,420.00	\$0.09	\$4,807.80
		0001	0150	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	53,312.00	0.00	53,312.00	LF	44,022.00	\$0.09	\$3,961.98
		0001	0160	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	123,084.00	0.00	123,084.00	SQYD	122,814.00	\$2.16	\$265,278.24
		0001	5001	4071005	TACK COAT	0.00	12,986.00	12,986.00	GAL	12,986.00	\$4.75	\$61,683.50
	Project J	6S3229 - To	otal Value	Posted to D	ate as of Report Generated Date							\$1,585,076.18
18-F06 Ove	rall - Total	Value Post	ed to Dat	te as of Repo	ort Generated Date							\$1,585,076.18



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0090	6200015	PREF THERMO PVMT MARK, 24 IN WHIT	9/2/20	9/14/20	70.00	LF	Prairie- 31 & Spring- 39	0	0	0	0	
			9/9/20	9/14/20	87.00	LF	Striped Stopbars- 64' at Sarah Striped Stopbars- 23' Whittier	0	0	0	0	
			9/10/20	9/14/20	139.00	LF	Striped Stopbars- 42' at Whittier Striped Stopbars- 55' at Annie Malone Striped Stopbars- 42' at Billups	0	0	0	0	
			9/11/20	9/16/20	112.00	LF	Striped Stopbars- 13' at Billups Striped Stopbars- 63' at Newstead Striped Stopbars- 36' at Cora	0	0	0	0	
			9/14/20	9/15/20	114.00	LF	Striped Stopbars- 34' at Grand Striped Stopbars- 19' at Cora Striped Stopbars- 61' at Marcus	0	0	0	0	
			9/15/20	9/16/20	58.00	LF	Striped Stopbars- 11' at Prairie Striped Stopbars- 20' at Grand Striped Stopbars- 5' at Spring Striped Stopbars- 22' at Taylor	0	0	0	0	
0130	6200036	PREF THERMO PVMT MARK, 30" WHT MIDBL	9/2/20	9/14/20	35.00	EA	Prairie- 11 & Spring 24	0	0	0	0	
			9/9/20	9/14/20	44.00	EA	Striped Midblocks- 36 at Sarah Striped Midblocks- 8 at Whittier	0	0	0	0	
			9/10/20	9/14/20	41.00	EA	Striped Midblocks- 14 at Whittier Striped Midblocks- 11 at Annie Malone Striped Midblocks- 16 at Billups	0	0	0	0	
			9/11/20	9/16/20	50.00	EA	Striped Midblocks- 6 at Billups Striped Midblocks- 25 at Newstead Striped Midblocks- 19 at Cora	0	0	0	0	
			9/14/20	9/15/20	51.00	EA	Striped Midblocks- 22 at Grand Striped Midblocks- 3 at Cora Striped Midblocks- 26 at Marcus	0	0	0	0	
			9/15/20	9/16/20	28.00	EA	Striped Midblocks- 12 at Grand Striped Midblocks- 1 at Spring Striped Midblocks- 15 at Taylor	0	0	0	0	
0140	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	9/9/20	9/14/20	6,269.00	LF	Striped Bike Lane at various locations EB	0	0	0	0	

The information below this line are details from Line Item agency views. No Agency View Details Exist



						1		
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0010	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-1)	Material		11	Aug 16, 2020	SYSTEM	(\$1,037,113.28)	
				11	Aug 16, 2020	SYSTEM	\$1,037,113.28	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user harank1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				12	Sep 1, 2020	SYSTEM	(\$1,037,113.28)	
				12	Sep 1, 2020	SYSTEM	\$1,037,113.28	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user harank1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				13	Sep 16, 2020	SYSTEM	(\$1,037,113.28)	
				13	Sep 16, 2020	SYSTEM	\$1,037,113.28	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user harank1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total		1		\$0.00	
	Material - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-1)	Other Item Adjustment	ACAD	10	Aug 3, 2020	harank1	(\$17,335.03)	The (17,335.03) is for the second estimate period of July. Base Index- 470 Current Index- 397.5 Index Difference= -72.5 Asphalt Cement Price Adjustment documentation is stored on eProjects
				11	Aug 16, 2020	harank1	(\$20,966.37)	BP-1 8/2-8/15 Current Index- 395 Base Index- 470 Diff Index= (19770.86) Estimate# 11 Also corrected amount for Estimate# 10 (wrong letting date was used)- original (17335.03) actual (18530.54)= diff of (1195.51) more
			ACAD - Tot	al			(\$38,301.40)	
	Other Item Adjustment - Total						(\$38,301.40)	
	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-1)	Overrun	Overrun	11	Aug 16, 2020	SYSTEM	(\$24,092.48)	
				11	Aug 16, 2020	SYSTEM	\$24,092.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 2 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0010 -	- Total						(\$38,301.40)	
0050	MISC. TEMPORARY TRAFFIC CONTROL	Material		10	Aug 1, 2020	SYSTEM	(\$1,786.50)	
				10	Aug 1, 2020	SYSTEM	\$1,786.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user harank1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0050 -	- Total		_				\$0.00	
0060	MISC. SHARED BIKE LANE	Construction Stockpile		2	Apr 1, 2020	SYSTEM	\$12,054.85	Payment Estimate Item Adjustment generated Stockpile Transaction
				12	Sep 1, 2020	SYSTEM	(\$1,327.14)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$10,727.71	
							\$10,727.71	
	Construction Stockpile - Total							
	Construction Stockpile - Total MISC. SHARED BIKE LANE	Material		12	Sep 1, 2020	SYSTEM	(\$3,753.00)	
		Material		12 12		SYSTEM	(\$3,753.00) \$3,753.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user harank1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		Material			2020 Sep 1,		(,	Estimate Item Adjustment (0002) due to user harank1 overridding
		Material		12	2020 Sep 1, 2020 Sep 16,	SYSTEM	\$3,753.00	Estimate Item Adjustment (0002) due to user harank1 overridding
		Material	- Total	12 13	2020 Sep 1, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM	\$3,753.00 (\$3,753.00)	Estimate Item Adjustment (0002) due to user harank1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user harank1 overridding
		Material	- Total	12 13	2020 Sep 1, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM	\$3,753.00 (\$3,753.00) \$3,753.00	Estimate Item Adjustment (0002) due to user harank1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user harank1 overridding
0060 -	MISC. SHARED BIKE LANE	Material	- Total	12 13	2020 Sep 1, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM	\$3,753.00 (\$3,753.00) \$3,753.00 \$0.00	Estimate Item Adjustment (0002) due to user harank1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user harank1 overridding



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
			Туре			-	(*** *** ***	
0070	MISC. BIKE LANE	Construction Stockpile		12	Sep 1, 2020	SYSTEM	(\$3,925.06)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$4,840.90	
	Construction Stockpile - Total						\$4,840.90	
	MISC. BIKE LANE	Material		12	Sep 1, 2020	SYSTEM	(\$10,420.80)	
				12	Sep 1, 2020	SYSTEM	\$10,420.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user harank1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				13	Sep 16, 2020	SYSTEM	(\$10,420.80)	
				13	Sep 16, 2020	SYSTEM	\$10,420.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user harank1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0070 -							\$4,840.90	
0090	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Construction Stockpile		2	Apr 1, 2020	SYSTEM	\$13,692.39	Payment Estimate Item Adjustment generated Stockpile Transaction
				12	Sep 1, 2020	SYSTEM	(\$807.97)	Payment Estimate Item Adjustment generated Stockpile Transaction
				13	Sep 16, 2020	SYSTEM	(\$3,577.30)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$9,307.12	
	Construction Stockpile - Total						\$9,307.12	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	Material		12	Sep 1, 2020	SYSTEM	(\$2,200.80)	
	WHITE			12	Sep 1, 2020	SYSTEM	\$2,200.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user harank1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				13	Sep 16, 2020	SYSTEM	(\$11,944.80)	
				13	Sep 16, 2020	SYSTEM	\$11,944.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user harank1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0090	- Total						\$9,307.12	
0100	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Construction Stockpile		2	Apr 1, 2020	SYSTEM	\$18,876.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				12	Sep 1, 2020	SYSTEM	(\$6,825.40)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$12,051.10	
	Construction Stockpile - Total						\$12,051.10	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING,	Material		12	Sep 1, 2020	SYSTEM	\$12,051.10 (\$17,485.44)	
	PREFORMED THERMOPLASTIC	Material		12 12		SYSTEM SYSTEM		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user harank1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	PREFORMED THERMOPLASTIC PAVEMENT MARKING,	Material			2020 Sep 1,		(\$17,485.44)	Estimate Item Adjustment (0009) due to user harank1 overridding
	PREFORMED THERMOPLASTIC PAVEMENT MARKING,	Material		12	2020 Sep 1, 2020 Sep 16,	SYSTEM	(\$17,485.44) \$17,485.44	Estimate Item Adjustment (0009) due to user harank1 overridding
	PREFORMED THERMOPLASTIC PAVEMENT MARKING,	Material	- Total	12 13	2020 Sep 1, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM	(\$17,485.44) \$17,485.44 (\$17,485.44)	Estimate Item Adjustment (0009) due to user harank1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user harank1 overridding
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material	- Total	12 13	2020 Sep 1, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM	(\$17,485.44) \$17,485.44 (\$17,485.44) \$17,485.44 \$17,485.44	Estimate Item Adjustment (0009) due to user harank1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user harank1 overridding
0100	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material	- Total	12 13	2020 Sep 1, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM	(\$17,485.44) \$17,485.44 (\$17,485.44) \$17,485.44 \$0.00 \$0.00	Estimate Item Adjustment (0009) due to user harank1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user harank1 overridding
0100 -	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW Material - Total Total		- Total	12 13 13	2020 Sep 1, 2020 Sep 16, 2020 Sep 16, 2020	SYSTEM SYSTEM SYSTEM	(\$17,485.44) \$17,485.44 (\$17,485.44) \$17,485.44 \$0.00 \$0.00 \$12,051.10	Estimate Item Adjustment (0009) dué to user harank1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user harank1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
0100 - 0110	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW Material - Total Total		- Total	12 13	2020 Sep 1, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM	(\$17,485.44) \$17,485.44 (\$17,485.44) \$17,485.44 \$0.00 \$0.00	Estimate Item Adjustment (0009) due to user harank1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user harank1 overridding
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW Material - Total Total PREFORMED THERMOPLASTIC PAVEMENT MARKING,	Construction	- Total	12 13 13	2020 Sep 1, 2020 Sep 16, 2020 Sep 16, 2020 Apr 1,	SYSTEM SYSTEM SYSTEM	(\$17,485.44) \$17,485.44 (\$17,485.44) \$17,485.44 \$0.00 \$0.00 \$12,051.10	Estimate Item Adjustment (0009) due to user harank1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user harank1 overridding Payment Estimate Exception 5 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0110 -	Total						\$349.86	
0120	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	Construction Stockpile		2	Apr 1, 2020	SYSTEM	\$361.84	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$361.84	
	Construction Stockpile - Total						\$361.84	
0120 -	Total						\$361.84	
0130	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	Construction Stockpile		2	Apr 1, 2020	SYSTEM	\$71,065.80	Payment Estimate Item Adjustment generated Stockpile Transaction
	WHITE WIDDLOCK			12	Sep 1, 2020	SYSTEM	(\$4,221.73)	Payment Estimate Item Adjustment generated Stockpile Transaction
				13	Sep 16, 2020	SYSTEM	(\$17,520.18)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$49,323.89	
	Construction Stockpile - Total						\$49,323.89	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	Material		12	Sep 1, 2020	SYSTEM	(\$11,400.00)	
	WITTE WIDDLOOK			12	Sep 1, 2020	SYSTEM	\$11,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user harank1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				13	Sep 16, 2020	SYSTEM	(\$58,710.00)	
				13	Sep 16, 2020	SYSTEM	\$58,710.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user harank1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
)130 -	Total						\$49,323.89	
0140	4 IN. WHITE STANDARD WATERBORNE PAVEMENT	Material		12	Sep 1, 2020	SYSTEM	(\$4,243.59)	
	MARKING PAINT, TYPE P BEADS			12	Sep 1, 2020	SYSTEM	\$4,243.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user harank1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				13	Sep 16, 2020	SYSTEM	(\$4,807.80)	
				13	Sep 16, 2020	SYSTEM	\$4,807.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user harank1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
)140 -	Total						\$0.00	
0150	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	Material		12	Sep 1, 2020	SYSTEM	(\$3,961.98)	
	MARKING PAINT, TYPE P BEADS			12	Sep 1, 2020	SYSTEM	\$3,961.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user harank1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				13	Sep 16, 2020	SYSTEM	(\$3,961.98)	
				13	Sep 16, 2020	SYSTEM	\$3,961.98	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user harank1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total	13		SYSTEM	\$3,961.98 \$0.00	Estimate Item Adjustment (0010) due to user harank1 overridding
	Material - Total		- Total	13		SYSTEM		Estimate Item Adjustment (0010) due to user harank1 overridding
015 <u>0 -</u>	Material - Total Total		- Total	13		SYSTEM	\$0.00	Estimate Item Adjustment (0010) due to user harank1 overridding
		Material	- Total	13		SYSTEM SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0010) due to user harank1 overridding
	· Total	Material	- Total		2020 Aug 1,		\$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0010) due to user harank1 overridding
	· Total	Material	- Total	10	2020 Aug 1, 2020 Aug 1,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$29,730.25)	Estimate Item Adjustment (0010) due to user harank1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
<mark>0150</mark> - 5001	· Total	Material		10	2020 Aug 1, 2020 Aug 1,	SYSTEM	\$0.00 \$0.00 (\$29,730.25) \$29,730.25	Estimate Item Adjustment (0010) due to user harank1 overridding Payment Estimate Exception 9 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5001	TACK COAT	Overrun	Overrun	11	Aug 16, 2020	SYSTEM	\$3,220.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user harank1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		Overrun - Total					\$0.00	
	Overrun - Total						\$0.00	
5001 -	5001 - Total						\$0.00	
Overall - Total							\$48,661.02	