

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2020

| Progress Estima | ite Number | Contract ID Prime Contract | 191018-F06 orN.B. West Contractin | | | mber 16, 2020 Original Contract Amo mber 30, 2020 Net Change Order Am Current Contract Amo | ount \$85,775.98 | |
|-----------------|-----------------------------------|----------------------------|--|----------------------|--|---|------------------|--|
| Approval Date | | | | | | | By User | |
| October 1, 2020 | | | evel by harank1 | | | | | |
| October 1, 2020 | | | Reviewed and App | proved (and should b | uld be considered Draft) at the Resident Engineer Level by was | | | |
| October 2, 2020 | | | ntral Office Controllers Office Level by | greggd1 | | | | |
| Original Comp | Original Completion Date | | Completion Date | Actual Comp | letion Date | % of Current Contract Amou | ınt Complete | |
| November | November 1, 2020 November 1, 2020 | | | | | 91 99% | | |

No Milestones Exist for Contract

| Contract Total Pa | ay For Estimate No. 14 | | | | |
|-------------------|----------------------------|---------------|----------------|----------------|--|
| | | This Estimate | Previous | To Date | |
| 191018-F06 | | | | | |
| | Total Posted Items Pay | \$104,659.94 | \$1,585,076.19 | \$1,689,736.13 | |
| | Gross Item Adjustments | (\$38,890.33) | \$48,661.02 | \$9,770.69 | |
| | Incentive | \$0.00 | \$0.00 | \$0.00 | |
| | Disincentive | \$0.00 | \$0.00 | \$0.00 | |
| | Liquidated Damage | \$0.00 | \$0.00 | \$0.00 | |
| | Other Contract Adjustments | \$0.00 | \$0.00 | \$0.00 | |
| | · | | \$1,633,737.21 | \$1,699,506.82 | |
| Contract Total Pa | ayable This Estimate: | \$65,769.61 | | | |

Items Paid This Estimate Period

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount |
|-------------------|----------------|--------------|--|------|------------|--------------------------|-----------------------------|
| J6S3229 | 0090 | 6200015 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | LF | \$16.800 | 1,006 | \$16,900.80 |
| | 0100 | 6200021 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | EA | \$273.210 | 34 | \$9,289.14 |
| | 0130 | 6200036 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK | EA | \$190.000 | 413 | \$78,470.00 |
| Project J6S3 | 229 - Total | | | | | | \$104,659.94 |
| Overall - Tot | al | | | | | | \$104,659.94 |

Contract Adjustments This Estimate

| | | tments Exist on Contract nents This Estimate | | | | | | |
|-------------------|-------------|--|---------------------------|----------------------------------|--|------------------------|---------------------------------------|----------------------|
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| J6S3229 | 0010 | BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-1) | Material | | | -11,859.5 | \$87.45 | (\$1,037,113.28) |
| | 0010 | BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-1) | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user harank1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | 11,859.5 | \$87.45 | \$1,037,113.28 |
| | 0060 | MISC. | Material | | | -12 | \$312.75 | (\$3,753.00) |
| | 0060 | MISC. | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user harank1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | 12 | \$312.75 | \$3,753.00 |
| | 0070 | MISC. | Material | | | -30 | \$347.36 | (\$10,420.80) |
| | 0070 | MISC. | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user harank1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | 30 | \$347.36 | \$10,420.80 |
| | 0090 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 | Construction Stockpile | | Payment Estimate Item Adjustment generated Stockpile Transaction | | | (\$6,204.75) |

Page 1 of 10 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2020

Progress Estimate Number
14 Contract ID 191018-F06 Pay Period Start September 16, 2020 Original Contract Amount \$1,751,000.00
Prime Contractor N.B. West Contracting Company Pay Period End September 30, 2020 Net Change Order Amount \$85,775.98
Current Contract Amount \$1,836,775.98

| | reject Line Item Description Adjustment Other Item | | iaci Ailloulli | \$1,836,775.98 | | | | |
|-------------------|--|--|---------------------------|----------------------------------|--|------------------------|---------------------------------------|----------------------|
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| J6S3229 | | IN. WHITE | | | | | | |
| | 0090 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | Material | | | -1,717 | \$16.80 | (\$28,845.60) |
| | 0090 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user harank1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | 1,717 | \$16.80 | \$28,845.60 |
| | 0100 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | Construction Stockpile | | Payment Estimate Item Adjustment generated Stockpile Transaction | | | (\$3,626.00) |
| | 0100 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | Material | | | -98 | \$273.21 | (\$26,774.58) |
| | 0100 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user harank1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | 98 | \$273.21 | \$26,774.58 |
| | 0130 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK | Construction Stockpile | | Payment Estimate Item Adjustment generated Stockpile Transaction | | | (\$29,059.58) |
| | 0130 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK | Material | | | -722 | \$190.00 | (\$137,180.00) |
| | 0130 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user harank1 overridding Payment Estimate Exception 6 on the current Payment Estimate. | 722 | \$190.00 | \$137,180.00 |
| | 0140 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | | -53,420 | \$0.09 | (\$4,807.80) |
| | 0140 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user harank1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | 53,420 | \$0.09 | \$4,807.80 |
| | 0150 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | | -44,022 | \$0.09 | (\$3,961.98) |
| | 0150 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user harank1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | 44,022 | \$0.09 | \$3,961.98 |
| Total | | | | | | | | (\$38,890.33) |

Revision 4/1/2020 Page 2 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | | | | | (| Contract Project Information | |
|-------------------|----------------------------|---|-------|---------------------|---|---|---|
| Project Number | Federal Proj. Number | Project Description | Route | County | | | Location of Work |
| J6S3229 | FAS S501(65) | Coldmill and resurface | 180 | ST LOUIS CITY | on Dr. Martin Luther King D | rive from St. Louis City limits | to Route D |
| Totals by J | Job Numbe | rs | | | | | |
| J6S3229 | | d Item Pay Item Adjustm | | s Item Pay | This Estimate \$104,659.94 (\$38,890.33) \$65,769.61 | Previous \$1,585,076.19 \$48,661.02 \$1,633,737.21 | To Date \$1,689,736.13 \$9,770.69 \$1,699,506.82 |
| | Liquid | ive entive lated Damages Contract Adju | | | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 |

Revision 4/1/2020 Page 3 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions / Discrepencies | Explanation | Entered By | Status |
|--|--|---------------|------------|
| Estimate Exception Type: Insufficient Materials: Project J6S3229, Item 6200015, Project Item Line Number 0090, Material Set 1048PMPFWH, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient. | Waiting on final field measured totals | harank1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3229, Item 6209902, Project Item Line Number 0070, Material Set 1048PMPFWHXX, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient. | Waiting on final field measured totals | harank1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3229, Item 6209902, Project Item Line Number 0060, Material Set 1048PMPFWHXX, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient. | Waiting on final field measured totals | harank1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3229, Item 4011207, Project Item Line Number 0010, Material Set 401120796, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient. | Waiting on Materials to complete their reporting | harank1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3229, Item 6200021, Project Item Line Number 0100, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient. | Waiting on final field measured totals | harank1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3229, Item 6200036, Project Item Line Number 0130, Material Set 620003696, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient. | Waiting on final field measured totals | harank1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3229, Item 6206000C, Project Item Line Number 0140, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient. | Waiting on final field measured totals | harank1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3229, Item 6206000C, Project Item Line Number 0140, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. | Waiting on final field measured totals | harank1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3229, Item 6206001C, Project Item Line Number 0150, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient. | Waiting on final field measured totals | harank1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3229, Item 6206001C, Project Item Line Number 0150, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. | Waiting on final field measured totals | harank1 | Overridden |

Revision 4/1/2020 Page 4 of 10



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Im.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|-------------|-------------|--------------|---|-----------------|------------------------|------------------------------|------|------------------------------------|--------------|--|
| 91018-F06 | J6S3229 | 0001 | 0010 | 4011207 | BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-1) | 11,584.00 | 275.50 | 11,859.50 | TONS | 11,859.50 | \$87.45 | \$1,037,113.28 |
| | | 0001 | 0020 | 6123000A | TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$1,500.00 | \$0.00 |
| | | 0001 | 0030 | 6161040 | FLASHING ARROW PANEL | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,200.00 | \$2,400.00 |
| | | 0001 | 0040 | 6161099 | CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$3,500.00 | \$7,000.00 |
| | | 0001 | 0050 | 6169901 | MISC.TEMPORARY TRAFFIC CONTROL | 1.00 | 0.00 | 1.00 | LS | 0.75 | \$7,146.00 | \$5,359.50 |
| | | 0001 | 0060 | 6209902 | MISC.SHARED BIKE LANE | 109.00 | 0.00 | 109.00 | EA | 12.00 | \$312.75 | \$3,753.00 |
| | | 0001 | 0070 | 6209902 | MISC.BIKE LANE | 67.00 | 0.00 | 67.00 | EA | 30.00 | \$347.36 | \$10,420.80 |
| | | 0001 | 0080 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 0.90 | \$105,730.94 | \$95,157.85 |
| | | 0001 | 0090 | 6200015 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | 2,220.00 | 0.00 | 2,220.00 | LF | 1,717.00 | \$16.80 | \$28,845.60 |
| | | 0001 | 0100 | 6200021 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | 177.00 | 0.00 | 177.00 | EA | 98.00 | \$273.21 | \$26,774.58 |
| | | 0001 | 0110 | 6200024 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$240.53 | \$0.00 |
| | | 0001 | 0120 | 6200027 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$497.53 | \$0.00 |
| | | 0001 | 0130 | 6200036 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK | 1,010.00 | 0.00 | 1,010.00 | EA | 722.00 | \$190.00 | \$137,180.00 |
| | | 0001 | 0140 | 6206000C | $4\ \mbox{IN}.$ WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 57,428.00 | 0.00 | 57,428.00 | LF | 53,420.00 | \$0.09 | \$4,807.80 |
| | | 0001 | 0150 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 53,312.00 | 0.00 | 53,312.00 | LF | 44,022.00 | \$0.09 | \$3,961.98 |
| | | 0001 | 0160 | 6221001 | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) | 123,084.00 | 0.00 | 123,084.00 | SQYD | 122,814.00 | \$2.16 | \$265,278.24 |
| | | 0001 | 5001 | 4071005 | TACK COAT | 0.00 | 12,986.00 | 12,986.00 | GAL | 12,986.00 | \$4.75 | \$61,683.50 |
| | Project J | 6S3229 - To | otal Value | Posted to D | ate as of Report Generated Date | | | | | | | \$1,689,736.12 |
| 1018-F06 Ove | rall - Total | Value Post | ted to Dat | e as of Repo | rt Generated Date | | | | | | | \$1,689,736.12 |

Page 5 of 10 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

| Line Number | Item Code | Description | DWR Date | DWR Approval Date | Quantity Posted | Units | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------|--------------------------------------|-------------|-------------------------|--------------------|-------|---|---------------------------------|---------------------|-------------------------------|---------------------|----------|
| 0090 | 6200015 | PREF THERMO PVMT MARK, 24 IN WHIT | 9/16/20 | 10/1/20 | 25.00 | LF | Striped Stopbars- 10' at Taylor Striped Stopbars- 15' at Kingshighway | | | | | |
| | | | 9/28/20 | 10/1/20 | 689.00 | LF | Totals from 9/17-9/28 Striped Stopbars- 689 at Kingshighway- Hodiamont various locations | 0 | 0 | 0 | 0 | |
| | | | 9/29/20 | 10/1/20 | 137.00 | LF | Striped Stopbars- 137' at Clara, Pendleton, Whittier, Prairie, Bishop PL Scott, Hamilton, Arlington, & Euclid | 0 | 0 | 0 | 0 | |
| | | | 9/30/20 | 10/1/20 | 155.00 | LF | Striped Stopbars- 155' at Newstead, Bayard, Walton, Cora, & Marcus | 0 | 0 | 0 | 0 | |
| 0100 | 6200021 | PREF THERMO PVMT MARK, LT/RT ARROW | 9/28/20 | 10/1/20 | 12.00 | EA | Striped Arrows- 12 at Vandeventer & Cass | 0 | 0 | 0 | 0 | |
| | | | 9/29/20 | 10/1/20 | 22.00 | EA | Striped Arrows- 22 from Kingshighway- Arlington | 0 | 0 | 0 | 0 | |
| 0130 | 6200036 | PREF THERMO PVMT MARK, 30" WHT MIDBL | 9/16/20 | 10/1/20 | 25.00 | EA | Striped Midblocks- 7 at Taylor Striped Midblocks- 9 at Marcus Striped Midblocks- 9 at Kingshighway | 0 | 0 | 0 | 0 | |
| | | | 9/28/20 | 10/1/20 | 289.00 | EA | Totals from 9/17-9/28 Striped Midblocks- 289 at Kingshighway- Hodiamont various locations | 0 | 0 | 0 | 0 | |
| | | | 9/29/20 | 10/1/20 | 51.00 | EA | Striped Midblocks- 51 at Clara, Pendleton, Whittier, Newstead, Spring, Bishop PL Scott, Euclid | 0 | 0 | 0 | 0 | |
| | | | 9/30/20 | 10/1/20 | 48.00 | EA | Striped Midblocks- 48 at Newstead, Euclid, Bayard, Walton, & Cora | 0 | 0 | 0 | 0 | |

<u>The information below this line are details from Line Item agency views.</u>

No Agency View Details Exist

Revision 4/1/2020 Page 6 of 10



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|--|---------------------------|-----------------------------|----------------|-----------------|---------------|------------------|---|
| 0010 | BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-1) | Material | , | 11 | Aug 16, 2020 | SYSTEM | (\$1,037,113.28) | |
| | , | | | 11 | Aug 16, 2020 | SYSTEM | \$1,037,113.28 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user harank1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 12 | Sep 1, 2020 | SYSTEM | (\$1,037,113.28) | |
| | | | | 12 | Sep 1, 2020 | SYSTEM | \$1,037,113.28 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user harank1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | 13 | Sep 16, 2020 | SYSTEM | (\$1,037,113.28) | |
| | | | | 13 | Sep 16, 2020 | SYSTEM | \$1,037,113.28 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user harank1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | 14 | Oct 1, 2020 | SYSTEM | (\$1,037,113.28) | |
| | | | | 14 | Oct 1, 2020 | SYSTEM | \$1,037,113.28 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user harank1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-1) | Other Item Adjustment | ACAD | 10 | Aug 3, 2020 | harank1 | (\$17,335.03) | The (17,335.03) is for the second estimate period of July. Base Index- 470 Current Index- 397.5 Index Difference= -72.5 Asphalt Cement Price Adjustment documentation is stored on eProjects |
| | | | | 11 | Aug 16, 2020 | harank1 | (\$20,966.37) | BP-1 8/2-8/15 Current Index- 395 Base Index- 470 Diff Index= (19770.86) Estimate# 11 Also corrected amount for Estimate# 10 (wrong letting date was used)-original (17335.03) actual (18530.54)= diff of (1195.51) more |
| | | | ACAD - Tota | al | | | (\$38,301.40) | |
| | Other Item Adjustment - Total | | | | | | (\$38,301.40) | |
| | BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-1) | Overrun | Overrun | 11 | Aug 16, 2020 | SYSTEM | (\$24,092.48) | |
| | | | | 11 | Aug 16, 2020 | SYSTEM | \$24,092.48 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | Overrun - T | otal | | | \$0.00 | |
| | Overrun - Total | | | | | | \$0.00 | |
| 0010 - | Total | | | | | | (\$38,301.40) | |
| 0050 | MISC. TEMPORARY TRAFFIC CONTROL | Material | | 10 | Aug 1, 2020 | SYSTEM | (\$1,786.50) | |
| | | | | 10 | Aug 1, 2020 | SYSTEM | \$1,786.50 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user harank1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0050 - | Total | | | | | | \$0.00 | |
| 0060 | MISC. SHARED BIKE LANE | Construction Stockpile | | 2 | Apr 1, 2020 | SYSTEM | \$12,054.85 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | 12 | Sep 1, 2020 | SYSTEM | (\$1,327.14) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | - Total | | | | \$10,727.71 | |
| | Construction Stockpile - Total | | | | | | \$10,727.71 | |
| | MISC. SHARED BIKE LANE | Material | | 12 | Sep 1, 2020 | SYSTEM | (\$3,753.00) | |
| | | | | 12 | Sep 1, 2020 | SYSTEM | \$3,753.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user harank1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 13 | Sep 16, 2020 | SYSTEM | (\$3,753.00) | |
| | | | | 13 | Sep 16, 2020 | SYSTEM | \$3,753.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user harank1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 14 | Oct 1, 2020 | SYSTEM | (\$3,753.00) | |

Revision 4/1/2020 Page 7 of 10



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|--|---------------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| 0060 | MISC. SHARED BIKE LANE | Material | | 14 | Oct 1, 2020 | SYSTEM | \$3,753.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user harank1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0060 - | · Total | | | | | | \$10,727.71 | |
| 0070 | MISC. BIKE LANE | Construction | | 2 | Apr 1, | SYSTEM | \$8,765.96 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| 00.0 | 60. 2.1.12 | Stockpile | | 12 | 2020 Sep 1, | SYSTEM | (\$3,925.06) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | - Total | | 2020 | 01012 | \$4,840.90 | Symmetric Community Commun |
| | Construction Stockpile - Total | | | | | | \$4,840.90 | |
| | MISC. BIKE LANE | Material | | 12 | Sep 1, 2020 | SYSTEM | (\$10,420.80) | |
| | | | | 12 | Sep 1, 2020 | SYSTEM | \$10,420.80 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user harank1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 13 | Sep 16, 2020 | SYSTEM | (\$10,420.80) | |
| | | | | 13 | Sep 16, 2020 | SYSTEM | \$10,420.80 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user harank1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 14 | Oct 1, 2020 | SYSTEM | (\$10,420.80) | |
| | | | | 14 | Oct 1, 2020 | SYSTEM | \$10,420.80 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user harank1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0070 - | Total | | | | | | \$4,840.90 | |
| 0090 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. | Construction Stockpile | | 2 | Apr 1, 2020 | SYSTEM | \$13,692.39 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | WHITE | | | 12 | Sep 1, 2020 | SYSTEM | (\$807.97) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | 13 | Sep 16, 2020 | SYSTEM | (\$3,577.30) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | 14 | Oct 1, 2020 | SYSTEM | (\$6,204.75) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | - Total | | | | \$3,102.37 | |
| | Construction Stockpile - Total | | | | | | \$3,102.37 | |
| | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | Material | | 12 | Sep 1, 2020 | SYSTEM | (\$2,200.80) | |
| | WHILE | | | 12 | Sep 1, 2020 | SYSTEM | \$2,200.80 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user harank1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 13 | Sep 16, 2020 | SYSTEM | (\$11,944.80) | |
| | | | | 13 | Sep 16, 2020 | SYSTEM | \$11,944.80 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user harank1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 14 | Oct 1, 2020 | SYSTEM | (\$28,845.60) | |
| | | | | 14 | Oct 1, 2020 | SYSTEM | \$28,845.60 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user harank1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0090 - | · Total | | | | | | \$3,102.37 | |
| 0100 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, | Construction Stockpile | | 2 | Apr 1, 2020 | SYSTEM | \$18,876.50 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | LEFT/RIGHT ARROW | | | 12 | Sep 1, 2020 | SYSTEM | (\$6,825.40) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | 14 | Oct 1, | SYSTEM | (\$3,626.00) | Payment Estimate Item Adjustment generated Stockpile Transaction |

Revision 4/1/2020 Page 8 of 10



| Line | Description | Adjustment Type | Other Adjustment | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|---|---------------------------|---------------------|----------------|------------------------|---------------|--------------------------------|--|
| | | | Туре | | | , | | |
| 0100 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | Construction Stockpile | | | 2020 | | | |
| | | | - Total | | | | \$8,425.10 | |
| | Construction Stockpile - Total | | | | | | \$8,425.10 | |
| | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | Material | | 12 | Sep 1, 2020 | SYSTEM | (\$17,485.44) | |
| | ELI IMOITI AMOW | | | 12 | Sep 1, 2020 | SYSTEM | \$17,485.44 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user harank1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | 13 | Sep 16, 2020 | SYSTEM | (\$17,485.44) | |
| | | | | 13 | Sep 16, 2020 | SYSTEM | \$17,485.44 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user harank1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | 14 | Oct 1, 2020 | SYSTEM | (\$26,774.58) | |
| | | | | 14 | Oct 1, 2020 | SYSTEM | \$26,774.58 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user harank1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0100 | - Total | | | | | | \$8,425.10 | |
| 0110 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW | Construction Stockpile | | 2 | Apr 1, 2020 | SYSTEM | \$349.86 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | - Total | | | | \$349.86 | |
| | Construction Stockpile - Total | | | | | | \$349.86 | |
| 0110 - | - Total | | | | | | \$349.86 | |
| 0120 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT | Construction Stockpile | | 2 | Apr 1, 2020 | SYSTEM | \$361.84 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | - Total | | | | \$361.84 | |
| | Construction Stockpile - Total | | | | | | \$361.84 | |
| 0120 - | - Total | | | | | | \$361.84 | |
| 0130 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK | Construction Stockpile | | 2 | Apr 1, 2020 | SYSTEM | \$71,065.80 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | 12 | Sep 1, 2020 | SYSTEM | (\$4,221.73) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | 13 | Sep 16, 2020 | SYSTEM | (\$17,520.18) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | 14 | Oct 1, 2020 | SYSTEM | (\$29,059.58) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | - Total | | | | \$20,264.31 | |
| | Construction Stockpile - Total | | | | | | \$20,264.31 | |
| | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN | Material | | 12 | Sep 1, 2020 | SYSTEM | (\$11,400.00) | |
| | WHITE MIDBLOCK | | | 12 | Sep 1, 2020 | SYSTEM | \$11,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user harank1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | 13 | Sep 16, 2020 | SYSTEM | (\$58,710.00) | |
| | | | | 40 | Sep 16, | SYSTEM | \$58,710.00 | This adjustment offsets the original system-generated Overrun Payment |
| | | | | 13 | 2020 | | | Estimate Item Adjustment (0008) due to user harank1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | 14 | 2020 Oct 1, 2020 | SYSTEM | (\$137,180.00) | |
| | | | | | Oct 1, | SYSTEM | (\$137,180.00) \$137,180.00 | |
| | | | - Total | 14 | Oct 1, 2020 | | , , , | Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user harank1 overridding |
| | Material - Total | | - Total | 14 | Oct 1, 2020 | | \$137,180.00 | Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user harank1 overridding |

Revision 4/1/2020 Page 9 of 10



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------------|--|--------------------|-----------------------------|----------------|-----------------|---------------|------------------|---|
| 0140 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | 12 | Sep 1, 2020 | SYSTEM | (\$4,243.59) | |
| | | | | 12 | Sep 1, 2020 | SYSTEM | \$4,243.59 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user harank1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | 13 | Sep 16, 2020 | SYSTEM | (\$4,807.80) | |
| | | | | 13 | Sep 16, 2020 | SYSTEM | \$4,807.80 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user harank1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | 14 | Oct 1, 2020 | SYSTEM | (\$4,807.80) | |
| | | | | 14 | Oct 1, 2020 | SYSTEM | \$4,807.80 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user harank1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0140 - Total | | | | | | | \$0.00 | |
| 0150 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | 12 | Sep 1, 2020 | SYSTEM | (\$3,961.98) | |
| | | | | 12 | Sep 1, 2020 | SYSTEM | \$3,961.98 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user harank1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | 13 | Sep 16, 2020 | SYSTEM | (\$3,961.98) | |
| | | | | 13 | Sep 16, 2020 | SYSTEM | \$3,961.98 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user harank1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | 14 | Oct 1, 2020 | SYSTEM | (\$3,961.98) | |
| | | | | 14 | Oct 1, 2020 | SYSTEM | \$3,961.98 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user harank1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0150 | - Total | | | | | | \$0.00 | |
| 5001 | TACK COAT | TACK COAT Material | | 10 | Aug 1, 2020 | SYSTEM | (\$29,730.25) | |
| | | | | 10 | Aug 1, 2020 | SYSTEM | \$29,730.25 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user harank1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | TACK COAT | Overrun | Overrun | 11 | Aug 16, 2020 | SYSTEM | (\$3,220.50) | |
| | | | | 11 | Aug 16, 2020 | SYSTEM | \$3,220.50 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user harank1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | | | | |
| | | | Overrun - T | otal | | | \$0.00 | |
| | Overrun - Total | | Overrun - T | otal | | | \$0.00 \$0.00 | |
| 5001 | Overrun - Total - Total | | Overrun - T | otal | | | | |

Revision 4/1/2020 Page 10 of 10