

Pay Estimate Created Date: June 15, 2020

Progress Estir 8	Progress Estimate Number 8		· · · · · · · · · · · · · · · · · · ·		June 2, 2020 June 15, 2020	Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,471,364.66 \$23,821.33 \$1,495,185.99		
Approval Date	Approval Date								
June 15, 2020		t) at the Project Office Level by	lashlh1						
June 15, 2020		Review	ved and Approved	(and should be cons	idered Draft) at t	he Resident Engineer Level by	dowdyd		
June 17, 2020			Revie	ewed and Approved	at the Central O	ffice Controllers Office Level by	greggd1		
Original Comp	ompletion Date Current Completion Date Actual Completion Date % of Current Contract Am								
November	November 1, 2020 November 1, 2020 96.65%								

No Milestones Exist for Contract

Contract Total Pa	y For Estimate No. 8			
		This Estimate	Previous	To Date
191018-H03				
	Total Posted Items Pay	\$152,614.16	\$1,292,434.54	\$1,445,048.70
	Gross Item Adjustments	(\$45,489.13)	(\$4,022.68)	(\$49,511.81)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$1,288,411.86	\$1,395,536.89
Contract Total Pa	vable This Estimate:	\$107.125.03		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Installed Qty								
J9S3397	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$2,909.700	1	\$2,909.70						
	0030	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	TONS	\$29.610	0.45	\$13.32						
	0050	4011211	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	TONS	\$60.260	273.32	\$16,470.26						
	0070	4071005	TACK COAT	GAL	\$2.160	294	\$635.04						
	0210	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.100	2,640	\$264.00						
	0220	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.100	2,640	\$264.00						
	0230	6207001	PAVEMENT MARKING REMOVAL	LF	\$1.000	4,481	\$4,481.00						
	0320	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	LF	\$485.000	23	\$11,155.00						
Project J9	S3397 - To	tal					\$36,192.32						
J9S3400	0420	3049910	MISC.Permanent Aggregate Edge Treatment	TONS	\$29.020	1,215.57	\$35,275.84						
	0440	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	TONS	\$54.180	93.55	\$5,068.54						
	0450	4071005	TACK COAT	GAL	\$2.210	566	\$1,250.86						
	0470	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	EA	\$500.000	2	\$1,000.00						
	0510	6181000	MOBILIZATION	LS	\$52,000.000	1	\$52,000.00						
	0520	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.100	113,500	\$11,350.00						
	0530	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.100	104,766	\$10,476.60						
Project J9	<mark>S3400 - To</mark>	tal					\$116,421.84						
	otal						\$152,614.16						

Line Item Adjustments This Estimate

Pay Estimate Created Date: June 15, 2020

Prog	ress Es	stimate Number 8	Contract Prime Co		1018-H03 bex Paving Co.	Pay Period End June 15, 2020	Net Chang	ontract Ame e Order Am ontract Ame	ount \$23	1,471,364.66 23,821.33 1,495,185.99	
Project Number	Line No.	Item Descri	iption	Adjustment Type	Other Item Adjustment Type	Comments	1	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
J9S3397	0050	BITUMINOUS I MIXTURE PG6		Overrun				-197.15	\$60.26	(\$11,880.26)	
	0070	Т	ГАСК СОАТ	Overrun				-294	\$2.16	(\$635.04)	
	0360	CURBI	BLOCKOUT	Other Item Adjustment	Material Discrepancy Payment Adjustment	The barrier curb was sealed with th specification of sealer. Payment withheld at 10% of current paid	is being			(\$3,920.00)	
	0360	CURB	BLOCKOUT	Material				-560	\$140.00	(\$78,400.00)	
	0360	CURBI	BLOCKOUT	Material		This adjustment offsets the original generated Overrun Payment Estim Adjustment (0023) due to user overridding Payment Estimate Except the current Payment E	ate Item r lashlh1 tion 4 on	560	\$140.00	\$78,400.00	
	0410	STRIP SEAL E JOIN	EXPANSION NT SYSTEM	Material				-46	\$660.00	(\$30,360.00)	
	0410 STRIP SEAL EXPANSION JOINT SYSTEM Material This adjustment offsets the original syste Adjustment (0024) due to user lash overridding Payment Estimate Exception 6 the current Payment Estima					ate Item r lashlh1 tion 6 on	46	\$660.00	\$30,360.00		
J9S3400	0420		MISC.	Material				-1,832.79	\$29.02	(\$53,187.57)	
(0420		MISC.	Material		This adjustment offsets the original generated Overrun Payment Estim Adjustment (0025) due to user overridding Payment Estimate Except the current Payment E	ate Item r lashlh1 tion 1 on	1,832.79	\$29.02	\$53,187.57	
	0440	BITUMINOUS I MIXTUF (SURFACE	RE PG64-22	Other Item Adjustment	Asphalt Cement Price Adjustment	This adjustment is made for surface placed between 5-20-20 and 5-29- attached AC adjustmer	-20. See			(\$18,369.11)	
	0440		PAVEMENT RE PG64-22 LEVELING)	Overrun				-93.55	\$54.18	(\$5,068.54)	
	0450	Т	TACK COAT	Overrun				-566	\$2.21	(\$1,250.86)	
	0520	4 IN. WHITE S WATERBORNE I MARKING PAI	PAVEMENT	Other Item Adjustment	Other	This adjustment is being made at -2 retroreflectivity results are re				(\$2,270.00)	
	0520	4 IN. WHITE S WATERBORNE I MARKING PAI	PAVEMENT	Material				-113,500	\$0.10	(\$11,350.00)	
	0520	4 IN. WHITE S WATERBORNE I MARKING PAI	PAVEMENT	Material		This adjustment offsets the original generated Overrun Payment Estim Adjustment (0026) due to user overridding Payment Estimate Except the current Payment E	ate Item r lashlh1 tion 2 on	113,500	\$0.10	\$11,350.00	
	0530	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS		Other Item Adjustment	Other	This adjustment is being made at -2 retroreflectivity results are re				(\$2,095.32)	
	0530	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS		Material				-104,766	\$0.10	(\$10,476.60)	
	0530 4 IN. YELLOW STANDARD Material WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS				This adjustment offsets the original generated Overrun Payment Estim Adjustment (0027) due to user overridding Payment Estimate Except	ate Item r lashlh1	104,766	\$0.10	\$10,476.60		



Pay Estimate Created Date: June 15, 2020

Prog	ress Es	stimate Number 8	Contract II Prime Con		91018-H03 opex Paving Co.	Pay Period Start Pay Period End				nount \$2	471,364.66 3,821.33 495,185.99
Project Number	Line No.	Item Descrip	otion	Adjustmen Type	t Other Item Adjustment Type	Comments			Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3400						the	current Payment	Estimate.			
Total											(\$45,489.13)



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J9S3397	FAS S702(76)	Resurface and Bridge Rehabilitation	Z	STE GENEVIEVE	from Route N to Route 61
J9S3400	FAS S702(74)	Resurface	A	CAPE GIRARDEAU	from Route U to Route 25 near Dutchtown

Totals by Job Numbers

07	This Estimate	Previous	To Date
Posted Item Pay	\$36,192.32	\$758,224.69	\$794,417.01
Gross Item Adjustments	(\$16,435.30)	(\$4,022.68)	(\$20,457.98)
Gross Item Pay	\$19,757.02	\$754,202.01	\$773,959.03
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
0	This Estimate	Previous	To Date
Posted Item Pay	This Estimate \$116,421.84	Previous \$534,209.85	To Date \$650,631.69
Posted Item Pay	\$116,421.84	\$534,209.85	\$650,631.69
Posted Item Pay Gross Item Adjustments Gross Item Pay	\$116,421.84 (\$29,053.83) \$87,368.01	\$534,209.85 \$0.00 \$534,209.85	\$650,631.69 (\$29,053.83) \$621,577.86
Posted Item Pay Gross Item Adjustments	\$116,421.84 (\$29,053.83)	\$534,209.85 \$0.00	\$650,631.69 (\$29,053.83) \$621,577.86 \$0.00
Posted Item Pay Gross Item Adjustments Gross Item Pay Incentive	\$116,421.84 (\$29,053.83) \$87,368.01 \$0.00	\$534,209.85 \$0.00 \$534,209.85 \$0.00	\$650,631.69 (\$29,053.83) \$621,577.86



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9S3400, Item 3049910, Project Item Line Number 0420, Material Set 304991096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Awaiting QC results	lashlh1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3400, Item 6206000C, Project Item Line Number 0520, Material Set 6206000C96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Waiting on performance results	lashlh1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3400, Item 6206001C, Project Item Line Number 0530, Material Set 6206001C96, Material 0620PMLI - Pavement Marking Performance Line, Acceptance Action Generic 0620PMLI is insufficient.	Waiting on performance results	lashlh1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3397, Item 7034600, Project Item Line Number 0360, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	PAL ID has not been submitted	lashlh1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3397, Item 7034600, Project Item Line Number 0360, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	PAL ID has not been submitted	lashlh1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3397, Item 7172001, Project Item Line Number 0410, Material Set 717200196, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	Waiting on results from Jeff City and Bridge Division	lashlh1	Overridden
Estimate Exception Type: Item Overrun: Contract 191018-H03, Contract Project J9S3397, Project Item Line Number 0050, Contract Line Item Number 0050, Item 4011211, Minor Item.	Change order in progress	lashlh1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191018-H03, Contract Project J9S3397, Project Item Line Number 0070, Contract Line Item Number 0070, Item 4071005, Minor Item.	Change order in progress	lashlh1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191018-H03, Contract Project J9S3397, Project Item Line Number 0180, Contract Line Item Number 0180, Item 6205301B, Minor Item.	Change order in progress	lashlh1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191018-H03, Contract Project J9S3397, Project Item Line Number 0370, Contract Line Item Number 0370, Item 7040104, Minor Item.	Change order in progress	lashlh1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191018-H03, Contract Project J9S3400, Project Item Line Number 0440, Contract Line Item Number 0440, Item 4020520, Minor Item.	Change order in progress	lashlh1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 191018-H03, Contract Project J9S3400, Project Item Line Number 0450, Contract Line Item Number 0450, Item 4071005, Minor Item.	Change order in progress	lashlh1	Acknowledged

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted amo	unt at the f	time the l	Estimate wa	s Gener	ated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191018-H03	J9S3397	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$2,909.70	\$2,909.70
		0001	0020	2159903	MISC.MODIFIED SHAPING SLOPES, CLASS III	437.50	0.00	437.50	LF	437.50	\$18.00	\$7,875.00
		0001	0030	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	735.80	258.92	994.72	TONS	994.72	\$29.61	\$29,453.66
		0001	0040	3105002	GRAVEL (A) OR CRUSHED STONE (B)	23.00	0.00	23.00	TONS	0.00	\$11.33	\$0.00
		0001	0050	4011211	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	3,352.00	0.00	3,352.00	TONS	3,549.15	\$60.26	\$213,871.78
		0001	0060	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	848.30	0.00	848.30	TONS	805.10	\$58.20	\$46,856.82
		0001	0070	4071005	TACK COAT	3,949.00	23.00	3,972.00	GAL	4,266.00	\$2.16	\$9,214.56
		0001	0080	4134000	BITUMINOUS FOG SEAL	2,398.00	0.00	2,398.00	GAL	1,919.00	\$2.99	\$5,737.81
		0001	0090	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0100	6161005	CONSTRUCTION SIGNS	993.00	0.00	993.00	SQFT	882.00	\$6.00	\$5,292.00
		0001	0110	6161008	ADVANCED WARNING RAIL SYSTEM	6.00	0.00	6.00	EA	6.00	\$45.00	\$270.00
		0001	0120	6161009	FLAG ASSEMBLY	6.00	0.00	6.00	EA	6.00	\$20.00	\$120.00
		0001	0130	6161010	RELOCATED SIGNS	16.00	0.00	16.00	SQFT	16.00	\$6.50	\$104.00
		0001	0140	6161025	CHANNELIZER (TRIM LINE)	75.00	0.00	75.00	EA	35.00	\$15.00	\$525.00
		0001	0150	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.00
		0001	0160	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$12,000.00	\$12,000.00
		0001	0170	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$140,000.00	\$140,000.00
		0001	0180	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	883.00	0.00	883.00	LF	1,747.04	\$1.50	\$2,620.56
		0001	0190	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	2,000.00	0.00	2,000.00	LF	0.00	\$1.50	\$0.00
		0001	0200	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	20.00	0.00	20.00	LF	20.00	\$5.00	\$100.00
		0001	0210	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	44,590.00	0.00	44,590.00	LF	44,590.00	\$0.10	\$4,459.00
		0001	0220	6206001C		45,482.00	0.00	45,482.00	LF	45,482.00	\$0.10	\$4,548.20
		0001	0230	6207001	PAVEMENT MARKING REMOVAL	4,481.00	0.00	4,481.00	LF	4,481.00	\$1.00	\$4,481.00
		0001	0240	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	570.00	0.00	570.00	SQYD	570.00	\$8.76	\$4,993.20
		0001	0250	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,399.00	-166.00	1,233.00	SQYD	1,233.00	\$7.47	\$9,210.51
		0001	0260	8061019	SILT FENCE	1,150.00	0.00	1,150.00	LF	1,150.00	\$3.90	\$4,485.00
		0010	0270	6061060	MGS GUARDRAIL	25.00	0.00	25.00	LF	25.00	\$40.00	\$1,000.00
		0010	0280	6061070	MGS VERTICAL CONCRETE BARRIER TRANSITION	4.00	0.00	4.00	EA	4.00	\$3,000.00	\$12,000.00
		0010	0290	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	1.00	\$1,200.00	\$1,200.00
		0010	0300	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	3.00	0.00	3.00	EA	3.00	\$2,900.00	\$8,700.00
		0070	0310	2161501	REMOVAL OF ASPHALT WEARING SURFACE	5,668.00	0.00	5,668.00	SQFT	5,668.00	\$0.88	\$4,987.84
		0070	0320	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	46.00	0.00	46.00	LF	46.00	\$485.00	\$22,310.00
		0070	0330	4091048	EMULSIFIED ASPHALT, SEAL COAT	247.00	0.00	247.00	GAL	230.00	\$4.00	\$920.00
		0070	0340	4094011	SEAL COAT AGGREGATE, GRADE B1	617.00	0.00	617.00	SQYD	617.00	\$4.00	\$2,468.00
		0070	0350	7034214	CLASS B-2 CONCRETE	4.30	0.00	4.30	CUYD	4.30	\$4,600.00	\$19,780.00
		0070	0360	7034600	CURB BLOCKOUT	560.00	0.00	560.00	LF	560.00	\$140.00	\$78,400.00
		0070	0370	7040104	HALF-SOLE REPAIR	1,400.00	0.00	1,400.00	SQFT	1,428.96	\$43.50	\$62,159.59
		0070	0380	7040106	FULL DEPTH REPAIR	400.00	0.00	400.00	SQFT	1.00	\$85.00	\$85.00
		0070	0390	7040113	CLEAN AND EPOXY SEAL	1,388.00	0.00	1,388.00	SQFT	1,388.00	\$14.00	\$19,432.00
		0070	0400	7101000	REINFORCING STEEL (EPOXY COATED)	310.00	0.00	310.00	LB	310.00	\$5.00	\$1,550.00
		0070	0410	7172001	STRIP SEAL EXPANSION JOINT SYSTEM		0.00	46.00	LF	46.00	\$660.00	\$30,360.00
		0001	5001	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS		2.00	2.00	EA	2.00	\$1,890.00	\$3,780.00
		0001	5002	1099901	MISC.Furnishing Protective Steel Plates for Bridge Deck Repairs	0.00	1.00	1.00	LS	1.00	\$8,811.55	\$8,811.55
		0001	5003	1099902	MISC.Hourly Rate for Installation and Removal of Protective Steel Plates for Bridge Deck Repairs	0.00	10.00	10.00	EA	2.83	\$475.35	\$1,345.24

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191018-H03	Project J	983397 - То	otal Value	Posted to D	ate as of Report Generated Date							\$794,417.01
	J9S3400	0001	0420	3049910	MISC.Permanent Aggregate Edge Treatment	1,934.60	0.00	1,934.60	TONS	1,832.79	\$29.02	\$53,187.57
		0001	0430	3105002	GRAVEL (A) OR CRUSHED STONE (B)	53.00	0.00	53.00	TONS	0.00	\$13.58	\$0.00
		0001	0440	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	8,695.50	0.00	8,695.50	TONS	8,789.05	\$54.18	\$476,190.73
		0001	0450	4071005	TACK COAT	10,156.00	0.00	10,156.00	GAL	10,722.00	\$2.21	\$23,695.62
		0001	0460	4134000	BITUMINOUS FOG SEAL	6,306.00	0.00	6,306.00	GAL	0.00	\$2.93	\$0.00
		0001	0470	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0480	6161005	CONSTRUCTION SIGNS	1,427.00	0.00	1,427.00	SQFT	1,276.00	\$6.00	\$7,656.00
		0001	0490	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	0.00	\$20.00	\$0.00
		0001	0500	6161025	CHANNELIZER (TRIM LINE)	57.00	0.00	57.00	EA	0.00	\$15.00	\$0.00
		0001	0510	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$52,000.00	\$52,000.00
		0001	0520	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	113,500.00	0.00	113,500.00	LF	113,500.00	\$0.10	\$11,350.00
		0001	0530	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	104,766.00	0.00	104,766.00	LF	104,766.00	\$0.10	\$10,476.60
		0001	0540	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	475.00	0.00	475.00	SQYD	366.00	\$11.79	\$4,315.14
		0001	0550	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,529.00	0.00	1,529.00	SQYD	1,476.00	\$7.29	\$10,760.04
	Project J	9S3400 - To	otal Value	Posted to D	ate as of Report Generated Date							\$650,631.69
91018-H03 Ove	erall - Total	Value Pos	ted to Da	te as of Repo	ort Generated Date							\$1,445,048.71



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9S3397

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	6/9/20	6/9/20	1.00	LS	Rte Z	1.53		1.59		removal of old railing on bridge X0421
0030	3049910	MISC. AGGREGATE FOR BASE	6/10/20	6/10/20	0.45	TONS	Rte Z					When payment was originally entered on 3-28-20, user made a typo and paid for 994.27 tons instead of the 994.72 tons. This left 0.45 tons unaccounted for.
0050	4011211	BIT. PAVEMENT MIXTURE PG64-22 (BP-2)	6/5/20	6/10/20	273.32	TONS	EB and WB lane	1.44		1.69		BP1 18-74 @ 1.5" thick
0070	4071005	TACK COAT	6/5/20	6/10/20	294.00	GAL	EB/WB lane	1.44		1.69		20 ft wide
0210	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	6/8/20	6/9/20	2,640.00	LF	Rte Z	1.44		1.69		
0220	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	6/8/20	6/9/20	2,640.00	LF	Rte Z	1.44		1.69		
0230	6207001	PAVEMENT MARKING REMOVAL	6/10/20	6/10/20	4,481.00	LF	Rte Z	1.434		1.684		
0320	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	6/9/20	6/9/20	23.00	LF	Rte Z	1.53		1.59		Payment for LI 0320 in EB lane along BR X0421

Project: J9S3400

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0420	3049910	MISC. AGGREGATE FOR BASE	6/2/20	6/3/20	577.69	TONS		2.277 WB	CL	4.602 EB	CL	
			6/3/20	6/4/20	214.58	TONS		4.602 EB	CL	6.88 EB	CL	
			6/5/20	6/10/20	423.30	TONS		6.88 EB	CL	10.734 EB	CL	
0440	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	6/2/20	6/3/20	93.55	TONS		9.344 WB	CL	10.74 WB	CL	
0450	4071005	TACK COAT	6/2/20	6/3/20	566.00	GAL		9.244 WB	CL	10.74 WB	CL	
0470	6123000A	TRUCK OR TRAILER MOUNTED ATTEN (TMA)	6/10/20	6/10/20	2.00	EA	Rte A					
0510	6181000	MOBILIZATION	6/3/20	6/4/20	1.00	LS		0.002		11.063		
0520	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	6/8/20	6/9/20	100,167.00	LF		0.002	CL	11.063	CL	
			6/10/20	6/11/20	13,333.00	LF		0.002		11.063		
0530	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	6/8/20	6/9/20	81,982.00	LF		0.002	CL	11.063	CL	
			6/10/20	6/11/20	22,784.00	LF		0.002		11.063		

The information below this line are details from Line Item agency views. No Agency View Details Exist



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0030	MISC. PERMANENT AGGREGATE EDGE	Overrun	Overrun	3	Apr 3, 2020	SYSTEM	(\$7,653.30)	
	TREATMENT			6	May 18, 2020	SYSTEM	\$7,653.30	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',29.61000 - 29.61000, 'is applied (if non-zero).
		Overrun - T	otal			\$0.00		
	Overrun - Total						\$0.00	
0030 -	Total						\$0.00	
0050	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	Other Item Adjustment	ACAD	3	Apr 3, 2020	schmij8	(\$1,360.03)	this adjustment is made for BP-2 placed during this estimate period. See attache AC adjustment sheet.
			ACAD - Tota	al			(\$1,360.03)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22,		SMAB	5	May 5, 2020	pinkle1	\$2,168.87	Smoothness adjustment for Rte Z WB lane was calculated using Table 3 (610.10 in accordance with spec 610.5.2. See attached adjustment excel sheet for detail
	(BP-2)			5	May 5, 2020	pinkle1	\$1,987.09	Smoothness adjustment for Rte Z EB lane was calculated using Table 3 (610.1d in accordance with spec 610.5.2. See attached adjustment excel sheet for detail
			SMAB - Total			\$4,155.96		
	Other Item Adjustment - To	otal					\$2,795.93	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	Overrun	Overrun	8	Jun 15, 2020	SYSTEM	(\$11,880.26)	
			Overrun - Total			(\$11,880.26)		
	Overrun - Total						(\$11,880.26)	
0050 -	Total						(\$9,084.33)	
060	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	ACAD	3	Apr 3, 2020	schmij8	(\$342.96)	This adjustment is made for surface leveling placed during this estimate period 3/16/20 - 4/1/20. See attached AC adjustment sheet.
	ACAD - Total						(\$342.96)	
	Other Item Adjustment - To	otal					(\$342.96)	
060 -	Total						(\$342.96)	
070	TACK COAT	Overrun	Overrun	3	Apr 3, 2020	SYSTEM	(\$49.68)	
				6	May 18, 2020	SYSTEM	\$49.68	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.16000 - 2.16000, 'is applie (if non-zero).
			2020		Jun 15, 2020	SYSTEM	(\$635.04)	
			Overrun - T	otal			(\$635.04)	
	Overrun - Total						(\$635.04)	
070 -	Total						(\$635.04)	
0180	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		4	Apr 16, 2020	SYSTEM	(\$1,290.00)	
	,				Apr 16, 2020	SYSTEM	\$1,290.00	This adjustment offsets the original system-generated Overrun Payment Estimat Item Adjustment (0001) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
	TEMPORARY REMOVABLE MARKING	Overrun	Overrun	6	May 18, 2020	SYSTEM	(\$1,296.06)	
	TAPE 4 IN., WHITE			6	May 18, 2020	SYSTEM	\$1,296.06	This adjustment offsets the original system-generated Overrun Payment Estimat Item Adjustment (0003) due to user pinkle1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				7	Jun 2, 2020	SYSTEM	(\$1,296.06)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
	Overrun - Total						(\$1,296.06)	
	Overrun - Total						(\$1,296.06)	
0180 -	Total						(\$1,296.06)	
	TEMPORARY	Material		4	Apr 16, 2020	SYSTEM	(\$100.00)	
0200	REMOVABLE MARKING TAPE, 24 IN., WHITE							



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0200		Material	- Total				\$0.00	
	Material - Total						\$0.00	
0200 -	Total						\$0.00	
0210	4 IN. WHITE STANDARD WATERBORNE	Material		4	Apr 16, 2020	SYSTEM	(\$4,195.00)	
	PAVEMENT MARKING PAINT, TYPE P BEADS			4	Apr 16, 2020	SYSTEM	\$4,195.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user pinkle1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0210 -	Total				_		\$0.00	
0220	4 IN. YELLOW STANDARD WATERBORNE	Material		4	Apr 16, 2020	SYSTEM	(\$4,284.20)	
	PAVEMENT MARKING PAINT, TYPE P BEADS			4	Apr 16, 2020	SYSTEM	\$4,284.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0220 -	Total						\$0.00	
0250	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	Overrun	Overrun	3	Apr 3, 2020	SYSTEM	(\$2,338.86)	
				6	May 18, 2020	SYSTEM	\$2,338.86	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',7.47000 - 7.47000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0250 -	Total						\$0.00	
0260	SILT FENCE	Material		2	Mar 14, 2020	SYSTEM	(\$4,485.00)	
			- Total				(\$4,485.00)	
	Material - Total						(\$4,485.00)	
	SILT FENCE	MaterialCredit		3	Apr 3, 2020	SYSTEM	\$4,485.00	
			- Total				\$4,485.00	
	MaterialCredit - Total						\$4,485.00	
0260 -	Total						\$0.00	
0270	MGS GUARDRAIL	Construction Stockpile		1	Jan 16, 2020	SYSTEM	\$260.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Jun 2, 2020	SYSTEM	(\$260.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
	- Total						\$0.00	
	Construction Stockpile - T	otal					\$0.00	
0270 -	Total						\$0.00	
0280	MGS VERTICAL CONCRETE BARRIER	Construction Stockpile		1	Jan 16, 2020	SYSTEM	\$5,168.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	TRANSITION			7	Jun 2, 2020	SYSTEM	(\$5,168.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
	- Total						\$0.00	
	Construction Stockpile - Total						\$0.00	
0280 -	Total						\$0.00	
0290	MGS END ANCHOR	Construction Stockpile		1	Jan 16, 2020	SYSTEM	\$532.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Jun 2, 2020	SYSTEM	(\$532.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - T	otal					\$0.00	
0290 -	Total						\$0.00	
		Construction		1	Jan 16,	SYSTEM	\$4,530.00	Payment Estimate Item Adjustment generated Stockpile Transaction
0300	TYPE A CRASHWORTHY END TERMINAL (MASH)	Stockpile			2020			, , , , , , , , , , , , , , , , , , , ,



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0300	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	7	Jun 2, 2020	SYSTEM	(\$4,530.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - To	otal					\$0.00	
0300 -	Total						\$0.00	
0350	CLASS B-2 CONCRETE	Material		5	May 5, 2020	SYSTEM	(\$9,890.00)	
				5	May 5, 2020	SYSTEM	\$9,890.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				6	May 18, 2020	SYSTEM	(\$19,780.00)	
				6	May 18, 2020	SYSTEM	\$19,780.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user pinkle1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	CLASS B-2 CONCRETE	Other Item Adjustment	MDPA	5	May 5, 2020	pinkle1	(\$4,945.00)	QC results have not been received at time of estimate. Prior payment is being withheld at 50%.
				6	May 18, 2020	pinkle1	\$4,945.00	The adjustment of (\$4945.00) made on EST 0005 is being rescinded. A new adjustment will be made on EST 0006 based on current installed qty.
				6	May 18, 2020	pinkle1	(\$9,890.00)	QC results have not been received at time of estimate 0006. Prior payment is being withheld at 50%.
				7	Jun 2, 2020	lashlh1	\$9,890.00	The adjustment of (\$9890.00) made on EST 006 is being rescinded. QC results have been received.
			MDPA - Tota	al			\$0.00	
	Other Item Adjustment - To	otal					\$0.00	
0350 -	Total						\$0.00	
0360	CURB BLOCKOUT	Material	laterial	5	May 5, 2020	SYSTEM	(\$39,200.00)	
				5	May 5, 2020	SYSTEM	\$39,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				6	May 18, 2020	SYSTEM	(\$39,200.00)	
				6	May 18, 2020	SYSTEM	\$39,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user pinkle1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				7	Jun 2, 2020	SYSTEM	(\$78,400.00)	
				7	Jun 2, 2020	SYSTEM	\$78,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user lashlh1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				8	Jun 15, 2020	SYSTEM	(\$78,400.00)	
				8	Jun 15, 2020	SYSTEM	\$78,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user lashlh1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total	Material - Total					\$0.00	
	CURB BLOCKOUT	JT Other Item Adjustment	MDPA	5	May 5, 2020	pinkle1	(\$19,600.00)	QC results have not been received at time of estimate. Prior payment is being withheld at 50%.
				6	May 18, 2020	pinkle1	\$19,600.00	The adjustment of (\$19600.00) made on EST 0005 is being rescinded. A new adjustment will be made on EST 0006 based on current installed qty and test requirements.
				6	May 18, 2020	pinkle1	(\$3,920.00)	The barrier curb has not been sealed nor has the sealer been PAL reported. An adjustment of 10% of the current installed quantity is being made until an approved PAL sealer is applied.
				6	May 18, 2020	pinkle1	(\$3,920.00)	Awaiting 28 day cylinder breaks. An adjustment of 10% of the current installed quantity is being made until 28 day breaks are received.
				7	Jun 2, 2020	lashlh1	\$3,920.00	The adjustment of (\$3920.00) made on EST 006 is being rescinded because cylinder breaks have been received.
				8	Jun 15, 2020	lashlh1	(\$3,920.00)	The barrier curb was sealed with the wrong specification of sealer. Payment is being withheld at 10% of current paid amount.



	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0360		Other Item Adjustment	MDPA - Tot	al			(\$7,840.00)		
	Other Item Adjustment - To	otal					(\$7,840.00)		
0360 -	Total						(\$7,840.00)		
0370	HALF-SOLE REPAIR	Material		4	Apr 16, 2020	SYSTEM	(\$26,576.59)		
				4	Apr 16, 2020	SYSTEM	\$26,576.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user pinkle1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
				5	May 5, 2020	SYSTEM	(\$26,576.59)		
				5	May 5, 2020	SYSTEM	\$26,576.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user pinkle1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
	HALF-SOLE REPAIR	Other Item Adjustment	MDPA	4	Apr 16, 2020	pinkle1	(\$5,315.32)	There were \$26576.59 of half-sole repairs performed during this estimate period. We are paying the repairs at 80% until design strength, inspection reporting, and certifications are received. Therefore, \$5315.32 or 20% of \$26575.59 is being withheld from this line item on this estimate.	
				5	May 5, 2020	pinkle1	(\$13,288.30)	QC results have not been received at time of estimate. Prior payment is being withheld at 50%.	
				6	May 18, 2020	pinkle1	\$13,822.30	The adjustment of (\$13822.30) made on EST 0005 is being rescinded. A new adjustment will be made on EST 0006 based on current installed qty.	
					6	May 18, 2020	pinkle1	\$5,315.32	The adjustment of (\$5315.32) made on EST 0004 is being rescinded because test results have been received for the material installed on that estimate. A new adjustment will be made on EST 0006 based on tests needed for subsequent installed qtys.
				6	May 18, 2020	pinkle1	(\$17,617.50)	QC results have not been received for the \$35235.00 of half-sole repair performed in the EB lane during EST period 0006. Payment for this work is being withheld at 50%.	
				7	Jun 2, 2020	lashlh1	\$17,083.50	QC results have been received for half-sole repair performed during EST 006, therefore, payment is being made at 100%	
			MDPA - Tot	al			\$0.00		
	Other Item Adjustment - To	otal		_	_		\$0.00		
	HALF-SOLE REPAIR	Overrun	n Overrun	6	May 18,	SYSTEM	(\$911.59)		
	HALF-SULE REFAIR	Overrun			2020				
	HALF-SOLE REPAIR	Overrun		6	2020 May 18, 2020	SYSTEM	\$911.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
	HALF-SULE REPAIR	Overrun		6 7	May 18,	SYSTEM SYSTEM	\$911.59 (\$911.59)	Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate	
	HALF-SULE KEPAIK	Overrun		7 7	May 18, 2020 Jun 2,		(\$911.59) (\$348.00)	Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of	
		Overrun	Overrun - T	7 7	May 18, 2020 Jun 2, 2020 Jun 2,	SYSTEM	(\$911.59) (\$348.00) (\$1,259.59)	Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of	
	Overrun - Total	Overrun	Overrun - T	7 7	May 18, 2020 Jun 2, 2020 Jun 2,	SYSTEM	(\$911.59) (\$348.00)	Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of	
0370 -		Overrun	Overrun - T	7 7	May 18, 2020 Jun 2, 2020 Jun 2,	SYSTEM	(\$911.59) (\$348.00) (\$1,259.59)	Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of	
0370 - 0410	Overrun - Total	Material	Overrun - T	7 7	May 18, 2020 Jun 2, 2020 Jun 2,	SYSTEM	(\$911.59) (\$348.00) (\$1,259.59) (\$1,259.59)	Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of	
	Overrun - Total Total STRIP SEAL EXPANSION		Overrun - T	7 7 otal	May 18, 2020 Jun 2, 2020 Jun 2, 2020 May 18,	SYSTEM SYSTEM	(\$911.59) (\$348.00) (\$1,259.59) (\$1,259.59) (\$1,259.59)	Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of	
	Overrun - Total Total STRIP SEAL EXPANSION		Overrun - T	7 7 otal	May 18, 2020 Jun 2, 2020 Jun 2, 2020 May 18, 2020 May 18,	SYSTEM SYSTEM SYSTEM	(\$911.59) (\$348.00) (\$1,259.59) (\$1,259.59) (\$1,259.59) (\$30,360.00)	Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
	Overrun - Total Total STRIP SEAL EXPANSION		Overrun - T	7 7 otal 6 6	May 18, 2020 Jun 2, 2020 Jun 2, 2020 May 18, 2020 May 18, 2020 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$911.59) (\$348.00) (\$1,259.59) (\$1,259.59) (\$1,259.59) (\$30,360.00) \$30,360.00	Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
	Overrun - Total Total STRIP SEAL EXPANSION		Overrun - T	7 7 7 00tal 6 6 6 7	May 18, 2020 Jun 2, 2020 Jun 2, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$911.59) (\$348.00) (\$1,259.59) (\$1,259.59) (\$30,360.00) \$30,360.00 (\$30,360.00)	Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user pinkle1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 5 on the current Payment Estimate.	
	Overrun - Total Total STRIP SEAL EXPANSION		Overrun - T	7 7 otal	May 18, 2020 Jun 2, 2020 Jun 2, 2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Jun 2, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$911.59) (\$348.00) (\$1,259.59) (\$1,259.59) (\$30,360.00) (\$30,360.00) (\$30,360.00)	Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user pinkle1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 5 on the current Payment Estimate.	
	Overrun - Total Total STRIP SEAL EXPANSION		Overrun - T	7 7 otal	May 18, 2020 Jun 2, 2020 Jun 2, 2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Jun 2, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$911.59) (\$348.00) (\$1,259.59) (\$1,259.59) (\$30,360.00) (\$30,360.00) (\$30,360.00) (\$30,360.00) (\$30,360.00)	Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
	Overrun - Total Total STRIP SEAL EXPANSION			7 7 otal	May 18, 2020 Jun 2, 2020 Jun 2, 2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Jun 2, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$911.59) (\$348.00) (\$1,259.59) (\$1,259.59) (\$30,360.00) \$30,360.00 (\$30,360.00) \$30,360.00	Item Adjustment (0004) due to user pinkle1 overridding Payment Estimate Exception 7 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
LINE	Description	Туре	Adjustment Type	Number	Date	By	Amount	IVEIHAIKS
0420	MISC. Permanent Aggregate Edge Treatment	Material		7	Jun 2, 2020	SYSTEM	(\$17,911.72)	
				7	Jun 2, 2020	SYSTEM	\$17,911.72	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user lashIh1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				8	Jun 15, 2020	SYSTEM	(\$53,187.57)	
				8	Jun 15, 2020	SYSTEM	\$53,187.57	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user lashIh1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
)420 -	Total						\$0.00	
0440	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	ACAD	8	Jun 15, 2020	lashlh1	(\$18,369.11)	This adjustment is made for surface leveling placed between 5-20-20 and 5-29-20 See attached AC adjustment sheet.
			ACAD - Tota	al			(\$18,369.11)	
	Other Item Adjustment - To	otal					(\$18,369.11)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Overrun	Overrun	8	Jun 15, 2020	SYSTEM	(\$5,068.54)	
			Overrun - T	otal			(\$5,068.54)	
	Overrun - Total						(\$5,068.54)	
440 -	Total						(\$23,437.65)	
450	TACK COAT	Overrun	Overrun		Jun 15, 2020	SYSTEM	(\$1,250.86)	
	Overrun - Total						(\$1,250.86)	
	Overrun - Total						(\$1,250.86)	
	Total						(\$1,250.86)	
)520	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	Material		8	Jun 15, 2020 Jun 15,	SYSTEM	(\$11,350.00) \$11,350.00	This adjustment offsets the original system-generated Overrun Payment Estimate
	PAINT, TYPE P BEADS			0	2020	STOTEM	φ11,330.00	Item Adjustment (0026) due to user lashlh1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	OTHR	8	Jun 15, 2020	lashlh1	(\$2,270.00)	This adjustment is being made at -20% until retroreflectivity results are received.
	OTHR - Total						(\$2,270.00)	
	Other Item Adjustment - To	otal					(\$2,270.00)	
520 -	Total						(\$2,270.00)	
0530	4 IN. YELLOW STANDARD WATERBORNE	Material		8	Jun 15, 2020	SYSTEM	(\$10,476.60)	
	PAVEMENT MARKING PAINT, TYPE P BEADS			8	Jun 15, 2020	SYSTEM	\$10,476.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user lashIh1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total					\$0.00		
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	OTHR		Jun 15, 2020	lashlh1	(\$2,095.32)	This adjustment is being made at -20% until retroreflectivity results are received.
	OTHR - Total						(\$2,095.32)	
	Other Item Adjustment - Total						(\$2,095.32)	
)530 -							(\$2,095.32)	
5001	TEMPORARY LONG- TERM RUMBLE STRIPS	Material		4	Apr 16, 2020	SYSTEM	(\$3,780.00)	
				4	Apr 16, 2020	SYSTEM	\$3,780.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user pinkle1 overridding Payment Estimate



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5001		Material	- Total				\$0.00	
	Material - Total						\$0.00	
	TEMPORARY LONG- TERM RUMBLE STRIPS	Other Item Adjustment	MDPA	4	Apr 16, 2020	pinkle1	(\$3,780.00)	The certifications for the temporary rumble strips have not been received. Therefore payment is being withheld until certifications are received.
				7	Jun 2, 2020	pinkle1	\$3,780.00	The certifications for the temporary rumble strips have been received. Therefore the negative adjustment made on estimate 0004 is being rescinded.
			MDPA - Tota	al			\$0.00	
	Other Item Adjustment - To	otal					\$0.00	
5001 -	- Total						\$0.00	
Overa	all - Total						(\$49,511.81)	