70.89%



Missouri Department of Transportation Contractor's Pay Estimate Summary

November 1, 2020

Pay Estimate Created Date: September 16, 2020

Progress Estima	te Number	Contract ID 191018-H Prime Contractor H.R. Quad	04 Pay Period Start S dri Contractors, LLC Pay Period End S		Original Contract Amou Net Change Order Amou Current Contract Amou	unt \$50,861.07	
Approval Date						By User	
September 16, 2020		ne Project Office Level by	schmij8				
September 16, 2020	16, Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by						
September 17, 2020			Reviewed and Approved at the	ne Central Office (Controllers Office Level by	greggd1	
Original Comp	letion Date	Current Completion	Date Actual Completion Date	e % c	f Current Contract Amou	nt Complete	

No Milestones Exist for Contract

November 1, 2020

Contract Total Pag	y For Estimate No. 11				
		This Estimate	Previous	To Date	
191018-H04					
	Total Posted Items Pay	\$886,522.86	\$2,402,859.97	\$3,289,382.83	
	Gross Item Adjustments	(\$24,827.39)	(\$44,702.16)	(\$69,529.55)	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$2,358,157.81	\$3,219,853.28	
Contract Total Pay	yable This Estimate:	\$861,695.47			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9S3518	0800	4029905	MISC.OPTIONAL SHOULDERS	SQYD	\$17.600	8,345.3	\$146,877.28
	5001	8061006	ALTERNATE DITCH CHECK	LF	\$14.000	80	\$1,120.00
Project J9S3518	\$147,997.28						
J9S3527	0960	4029905	MISC.OPTIONAL SHOULDERS	SQYD	\$17.200	13,286.9	\$228,534.68
Project J9S3527	- Total						\$228,534.68
J9S3554	1420	2063300	CLASS 4 EXCAVATION	CUYD	\$100.000	11	\$1,100.00
	1430	2129909	MISC.SHOULDER GRADING	STA	\$352.000	320.6	\$112,851.20
	1470	4029905	MISC.OPTIONAL SHOULDER	SQYD	\$18.000	6,428.9	\$115,720.20
	1650	7034041	CLASS B-1 CONCRETE (CULVERTS)	CUYD	\$2,000.000	19.3	\$38,600.00
	1660	7061030	REINFORCING STEEL (CULVERTS)	LB	\$2.000	3,670	\$7,340.00
	1700	8061005	ROCK DITCH CHECK	LF	\$11.250	726	\$8,167.50
	1720	8061019	SILT FENCE	LF	\$2.300	295	\$678.50
Project J9S3554	- Total						\$284,457.40
J9S3555	\$225,533.50						
Project J9S3555	\$225,533.50						
Overall - Total	\$886,522.86						

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjusti	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3518	0080	MISC.	Other Item Adjustment		See AC Adjustment for Estimate 0011.			(\$7,527.46)
	0260	CLASS B-1 CONCRETE (CULVERTS)	MaterialCredit			21.3	\$2,000.00	\$42,600.00
	0260	CLASS B-1 CONCRETE (CULVERTS)	Other Item Adjustment	Material Discrepancy	Materials exceptions have been satisfied. Taking back previous pay adjustments.			(\$39,400.00)

Revision 4/1/2020 Page 1 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 16, 2020

Progress Estimate Number
11 Contract ID 191018-H04 Pay Period Start September 2, 2020 Original Contract Amount \$4,589,414.37
Prime Contractor H.R. Quadri Contractors, LLC Pay Period End September 15, 2020 Net Change Order Amount \$50,861.07
Current Contract Amount \$4,640,275.44

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3518				Payment Adjustment				
	0270	REINFORCING STEEL (CULVERTS)	Material			-3,690	\$2.00	(\$7,380.00
	0270	REINFORCING STEEL (CULVERTS)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user schmij8 overridding Payment Estimate Exception 15 on the current Payment Estimate.	3,690	\$2.00	\$7,380.00
	0400	CURB BLOCKOUT	MaterialCredit			535	\$74.00	\$39,590.00
	0400	CURB BLOCKOUT	Material			-535	\$74.00	(\$39,590.00)
	5001	ALTERNATE DITCH CHECK	Material			-80	\$14.00	(\$1,120.00)
J9S3519	0510	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	MaterialCredit			2	\$1,500.00	\$3,000.00
	0510	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Material			-2	\$1,500.00	(\$3,000.00)
	0790	MISC.	MaterialCredit			1	\$125.00	\$125.00
	0790	MISC.	Material			-1	\$125.00	(\$125.00)
	0860	CURB BLOCKOUT	MaterialCredit			284	\$108.00	\$30,672.00
	0860	CURB BLOCKOUT	Material			-284	\$108.00	(\$30,672.00)
J9S3527	0960	MISC.	Other Item Adjustment		See AC Adjustment for Estimate 0011.			(\$11,984.78)
	0980	CONCRETE APPROACH PAVEMENT	MaterialCredit			16	\$100.00	\$1,600.00
	1190	CLASS B-1 CONCRETE (CULVERTS)	MaterialCredit			8.1	\$2,000.00	\$16,200.00
	1190	CLASS B-1 CONCRETE (CULVERTS)	Other Item Adjustment		Materials exceptions have been satisfied. Taking back previous pay adjustments.			(\$12,400.00)
	1200	REINFORCING STEEL (CULVERTS)	Material			-1,280	\$2.00	(\$2,560.00)
	1200	REINFORCING STEEL (CULVERTS)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0020) due to user schmij8 overridding Payment Estimate Exception 16 on the current Payment Estimate.	1,280	\$2.00	\$2,560.00
	1400	CURB BLOCKOUT	MaterialCredit			836	\$83.00	\$69,388.00
	1400	CURB BLOCKOUT	Material			-836	\$83.00	(\$69,388.00)
J9S3554	1470	MISC.	Other Item Adjustment		See AC Adjustment for Estimate 0011.			(\$5,798.87)
	1650	CLASS B-1 CONCRETE (CULVERTS)	MaterialCredit			19.9	\$2,000.00	\$39,800.00
	1650	CLASS B-1 CONCRETE (CULVERTS)	Other Item Adjustment	Material Discrepancy Payment Adjustment	Materials exceptions have been satisfied. Taking back previous pay adjustments.			(\$36,000.00)
	1660	REINFORCING STEEL (CULVERTS)	Material			-6,880	\$2.00	(\$13,760.00)
	1660	REINFORCING STEEL	Material		This adjustment offsets the original system-	6,880	\$2.00	\$13,760.00

Revision 4/1/2020 Page 2 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 16, 2020

Progress Estimate Number
11 Contract ID 191018-H04 Pay Period Start September 2, 2020 Original Contract Amount \$4,589,414.37
Prime Contractor H.R. Quadri Contractors, LLC Pay Period End September 15, 2020 Net Change Order Amount \$50,861.07
Current Contract Amount \$4,640,275.44

Page	Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
1700 ROCK DITCH CHECK Material This adjustment offsets the original system-generated (0022) due to user schmijk overridding Payment Estimate Item Adjustment (0022) due to user schmijk overridding Payment Estimate Exception 17 on the current Payment Estimate Exception 17 on the current Payment Estimate Exception 17 on the current Payment Estimate. 234 \$125.00 \$29,25 \$1,500.00 \$34,80	J9S3554		(CULVERTS)		1,100	Adjustment (0021) due to user schmij8 overridding Payment Estimate Exception 13		Onit i fisc	
Page		1700	ROCK DITCH CHECK	Material			-726	\$11.25	(\$8,167.50
1790 CURB BLOCKOUT Material		1700	ROCK DITCH CHECK	Material		generated Overrun Payment Estimate Item Adjustment (0022) due to user schmij8 overridding Payment Estimate Exception 17	726	\$11.25	\$8,167.50
J9S3555 1860 MISC. Other Item Adjustment Asphalt Cement Price Adjustment Cement Pric		1790	CURB BLOCKOUT	MaterialCredit			234	\$125.00	\$29,250.00
Adjustment Adjustment Cement Price Adjustment		1790	CURB BLOCKOUT	Material			-234	\$125.00	(\$29,250.00)
CULVERTS CHASS B-1 CONCRETE (CULVERTS) Other Item Adjustment Material Discrepancy Payment Adjustment Taking back previous pay adjustments. CULVERTS CULVERTS Material Discrepancy Payment Adjustment Taking back previous pay adjustments. CULVERTS CULVERTS Material CULVERTS	J9S3555	1860	MISC.		Cement Price	See AC Adjustment for Estimate 0011.			(\$10,996.28)
CULVERTS Adjustment Discrepancy Payment Taking back previous pay adjustments.		2020		MaterialCredit			17.4	\$2,000.00	\$34,800.00
CULVERTS This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user schmij8 overridding Payment Estimate Exception 14 on the current Payment Estimate. 2 \$1,500.00 \$3,		2020			Discrepancy Payment				(\$34,600.00)
GCULVERTS) generated Overrun Payment Estimate Item Adjustment (0023) due to user schmij8 overridding Payment Estimate Exception 14 on the current Payment Estimate. 2 \$1,500.00 \$3,000 \$3,000 2230 TRUCK OR TRAILER (TMA) 2230 TRUCK OR TRAILER Material Material Material Material		2030		Material			-3,500	\$2.00	(\$7,000.00)
MOUNTED ATTENUATOR (TMA) 2230 TRUCK OR TRAILER Material -2 \$1,500.00 (\$3,00		2030		Material		generated Overrun Payment Estimate Item Adjustment (0023) due to user schmij8 overridding Payment Estimate Exception 14	3,500	\$2.00	\$7,000.00
	J9S3594	2230	MOUNTED ATTENUATOR	MaterialCredit			2	\$1,500.00	\$3,000.00
(TMA)		2230	MOUNTED ATTENUATOR	Material			-2	\$1,500.00	(\$3,000.00)

Revision 4/1/2020 Page 3 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Informatio	on
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9S3518	FAS S702(88)	Add shoulders and rumble stripes	Н	ST FRANCOIS	from Old Fredericktown	n Road to Route AA	
J9S3519	FAS S702(87)	Add shoulders and rumble stripes	В	PERRY	from 0.25 miles south of	of National Guard Drive to	I-55
J9S3527	FAS S702(89)	Add shoulders and rumble stripes	K	ST FRANCOIS	from Point View Drive	to Route D	
J9S3554	FAS S702(92)	Add shoulders and rumble stripes	NN	ST FRANCOIS	from Route N to MO 22	21	
J9S3555	FAS S702(93)	Add shoulders and rumble stripes	AA	ST FRANCOIS	from Route H to Pende	elton Road	
J9S3594	FAS- S703(066	Add shoulders and rumble stripes	В	PERRY	From I-55 to the Perry	County Line	
otals by J	Job Numbe	ers					
J9S3518		d Item Pay Item Adjustme		Item Pay	This Estimate \$147,997.28 (\$5,447.46) \$142,549.82	Previous \$307,668.25 (\$7,159.00) \$300,509.25	To Date \$455,665.53 (\$12,606.46) \$443,059.07
	Liqui	tive centive dated Damages Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00
J9S3519		d Item Pay s Item Adjustme		Item Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$805,782.22 (\$17,923.93) \$787,858.29	To Date \$805,782.22 (\$17,923.93) \$787,858.29
	Liqui	tive centive dated Damages Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00
J9S3527		d Item Pay s Item Adjustme		Item Pay	This Estimate \$228,534.68 (\$6,584.78) \$221,949.90	Previous \$494,668.20 (\$3,134.80) \$491,533.40	To Date \$723,202.88 (\$9,719.58) \$713,483.30
	Liqui	tive centive dated Damages Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00
J9S3554	Posted Item Pay Gross Item Adjustments Gross Item Pay				This Estimate \$284,457.40 (\$1,998.87) \$282,458.53	Previous \$108,360.00 (\$8,187.50) \$100,172.50	To Date \$392,817.40 (\$10,186.37) \$382,631.03
	Incentive Disincentive Liquidated Damages Other Contract Adjustments				\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00
J9S3555	Gros	d Item Pay s Item Adjustme		Item Pay	This Estimate \$225,533.50 (\$10,796.28) \$214,737.22	Previous \$335,786.95 (\$200.00) \$335,586.95	To Date \$561,320.45 (\$10,996.28) \$550,324.17
	Liqui	tive centive dated Damages Contract Adjus			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 4 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

tals by Job Numbers			
983594	This Estimate	Previous	To Date
Posted Item Pay	\$0.00	\$350,594.35	\$350,594.35
Gross Item Adjustments	\$0.00	(\$8,096.93)	(\$8,096.93)
Gross Item Pay	\$0.00	\$342,497.42	\$342,497.42
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00

Revision 4/1/2020 Page 5 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) I his Estimate Period Exceptions / Discrepencies	Explanation	Entered	Status
		Ву	
Estimate Exception Type: Insufficient Materials: Project J9S3519, Item 6123000A, Project Item Line Jumber 0510, Material Set 6123000A, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	We have not received a certification for the TMA.	schmij8	Acknowledged
estimate Exception Type: Insufficient Materials: Project J9S3594, Item 6123000A, Project Item Line lumber 2230, Material Set 6123000A, Material 0616TMTC - Temporary Traffic Control Devices, acceptance Action Generic 0616TMTC is insufficient.	We have not received a certification for the TMA.	schmij8	Acknowledged
stimate Exception Type: Insufficient Materials: Project J9S3518, Item 7034600, Project Item Line lumber 0400, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, cceptance Action Generic 1053CSSIL is insufficient.	PAL ID has not been reported for this item yet.	schmij8	Acknowledged
stimate Exception Type: Insufficient Materials: Project J9S3518, Item 7034600, Project Item Line umber 0400, Material Set 703460096, Material 1036RSDFEC42M16 - Rein Steel EC No. 5/M16 Gr 0/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	PAL ID has not been reported for this item yet.	schmij8	Acknowledged
stimate Exception Type: Insufficient Materials: Project J9S3519, Item 7034600, Project Item Line umber 0860, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, cceptance Action Generic 1005FACCNSCA is insufficient.	Split sample record has not been created.	schmij8	Acknowledged
stimate Exception Type: Insufficient Materials: Project J9S3519, Item 7034600, Project Item Line umber 0860, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, cceptance Action Generic 100510CPCMLD is insufficient.	Split sample record has not been created.	schmij8	Acknowledged
stimate Exception Type: Insufficient Materials: Project J9S3519, Item 7034600, Project Item Line umber 0860, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance ction Generic 0501CCB1.A is insufficient.	We have not received QC CRE2O reports for air, slump, strength, and site inspection for the concrete used for curb blockouts.	schmij8	Acknowledged
stimate Exception Type: Insufficient Materials: Project J9S3519, Item 7034600, Project Item Line umber 0860, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, cceptance Action Generic 1053CSSIL is insufficient.	PAL ID has not been reported for this item yet.	schmij8	Acknowledged
stimate Exception Type: Insufficient Materials: Project J9S3527, Item 7034600, Project Item Line umber 1400, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, cceptance Action Generic 1053CSSIL is insufficient.	PAL ID has not been reported for this item yet.	schmij8	Acknowledged
stimate Exception Type: Insufficient Materials: Project J9S3554, Item 7034600, Project Item Line tumber 1790, Material Set 703460096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance ction Generic 0501CCB1.A is insufficient.	We have not received QC CRE2O reports for air, slump, strength, and site inspection for the concrete used for curb blockouts.	schmij8	Acknowledged
stimate Exception Type: Insufficient Materials: Project J9S3554, Item 7034600, Project Item Line umber 1790, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, cceptance Action Generic 1053CSSIL is insufficient.	PAL ID has not been reported for this item yet.	schmij8	Acknowledged
stimate Exception Type: Insufficient Materials: Project J9S3554, Item 7034600, Project Item Line lumber 1790, Material Set 703460096, Material 1036RSDFEC42M16 - Rein Steel EC No. 5/M16 Gr 0/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	PAL ID has not been reported for this item yet.	schmij8	Acknowledged
stimate Exception Type: Insufficient Materials: Project J9S3554, Item 7061030, Project Item Line lumber 1660, Material Set 706103096, Material 1036RSDFPL42M16 - Reinforcing Steel No. 5/M16 Gr 0/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	PAL ID has not been reported for this item yet.	schmij8	Overridden
stimate Exception Type: Insufficient Materials: Project J9S3555, Item 7061030, Project Item Line umber 2030, Material Set 706103096, Material 1036RSDFPL42M16 - Reinforcing Steel No. 5/M16 Gr 0/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	PAL ID has not been reported for this item yet.	schmij8	Overridden
stimate Exception Type: Insufficient Materials: Project J9S3518, Item 7061030, Project Item Line lumber 0270, Material Set 706103096, Material 1036RSDFPL42M16 - Reinforcing Steel No. 5/M16 Gr 0/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	PAL ID has not been reported for this item yet.	schmij8	Overridden
stimate Exception Type: Insufficient Materials: Project J9S3527, Item 7061030, Project Item Line lumber 1200, Material Set 706103096, Material 1036RSDFPL42M16 - Reinforcing Steel No. 5/M16 Gr 0/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	PAL ID has not been reported for this item yet.	schmij8	Overridden
stimate Exception Type: Insufficient Materials: Project J9S3554, Item 8061005, Project Item Line umber 1700, Material Set 8061005, Material 0806TEC - Temporary Erosion Control, Acceptance Action teneric 0806TEC is insufficient.	Visual inspection for rock ditch check has not been entered yet.	schmij8	Overridden
stimate Exception Type: Insufficient Materials: Project J9S3518, Item 8061006, Project Item Line umber 5001, Material Set 806100696, Material 0806TEC - Temporary Erosion Control, Acceptance ction Generic 0806TEC is insufficient.	We have not received a certification for the alternate ditch checks.	schmij8	Acknowledged
stimate Exception Type: Insufficient Materials: Project J9S3519, Item 8069902, Project Item Line lumber 0790, Material Set 8069902, Material 0806EK - Erosion Control Materials, Acceptance Action is insufficient.	We have not received a cert for the flocculant sock.	schmij8	Acknowledged

Revision 4/1/2020 Page 6 of 25



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

				eport Generated date and can differ from the posted am							
ct Project RACT No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
4 J9S3518	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.66	\$23,000.00	\$15,180.00
	0001	0020	2063300	CLASS 4 EXCAVATION	2.00	0.00	2.00	CUYD	2.00	\$200.00	\$400.00
	0001	0030	2063500	CULVERT CLEANOUT	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.00
	0001	0040	2129909	MISC.SHOULDER GRADING	370.50	0.00	370.50	STA	296.40	\$351.00	\$104,036.40
	0001	0050	2159903	MISC.MODIFIED SHAPING SLOPES, CLASS III	550.00	0.00	550.00	LF	0.00	\$8.00	\$0.00
	0001	0060	3105002	GRAVEL (A) OR CRUSHED STONE (B)	57.00	0.00	57.00	TONS	0.00	\$30.00	\$0.00
	0001	0070	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	95.10	0.00	95.10	TONS	0.00	\$160.00	\$0.00
	0001	0080	4029905	MISC.OPTIONAL SHOULDERS	8,345.30	0.00	8,345.30	SQYD	8,345.30	\$17.60	\$146,877.28
	0001	0090	6119910	MISC.TYPE 2 ROCK DITCH LINER FURNISHING AND PLACING	36.40	0.00	36.40	TONS	0.00	\$50.00	\$0.00
	0001	0100	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	0.00	2.00	EA	0.00	\$1,200.00	\$0.00
	0001	0110	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1,500.00	\$0.00
	0001	0120	6129902	MISC.CRASH CUSHION	2.00	0.00	2.00	EA	0.00	\$3,000.00	\$0.00
	0001	0130	6161005	CONSTRUCTION SIGNS	1,240.00	0.00	1,240.00	SQFT	580.00	\$5.00	\$2,900.00
	0001	0140	6161008	ADVANCED WARNING RAIL SYSTEM	6.00	0.00	6.00	EA	0.00	\$45.00	\$0.00
		0150	6161009	FLAG ASSEMBLY	8.00	0.00	8.00	EA	0.00	\$20.00	\$0.00
	0001										
	0001	0160	6161025 6161098A	CHANNELIZER (TRIM LINE) CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	200.00	0.00	200.00	EA	1.00	\$20.00 \$2,500.00	\$0.00 \$2,500.00
	0001	0180	6181000	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$71,000.00	\$53,250.00
		0190	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
	0001	0200	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	41,517.00	0.00	41,517.00	LF	0.00	\$0.10	\$0.00
	0001	0210	6206001C	PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	34,631.00	0.00	34,631.00	LF	0.00	\$0.11	\$0.00
	0001	0220	6207001	PAVEMENT MARKING REMOVAL	41,517.00	0.00	41,517.00	LF	0.00	\$0.20	\$0.00
	0001	0230	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	68.00	0.00	68.00	SQYD	0.00	\$2.00	\$0.00
	0001	0240	6269909	MISC.SHOULDER RUMBLE STRIP	259.10	0.00	259.10	STA	0.00	\$41.50	\$0.00
	0001	0250	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$1.00	\$0.00
	0001	0260	7034041	CLASS B-1 CONCRETE (CULVERTS)	21.30	0.00	21.30	CUYD	21.30	\$2,000.00	\$42,600.00
	0001	0270	7061030	REINFORCING STEEL (CULVERTS)	3,690.00	0.00	3,690.00	LB	3,690.00	\$2.00	\$7,380.00
	0001	0280	7250415	15 IN. PIPE GROUP C	417.00	0.00	417.00	LF	417.00	\$50.00	\$20,850.00
	0001	0290	7250418	18 IN. PIPE GROUP C	8.00	0.00	8.00	LF	8.00	\$100.00	\$800.00
	0001	0300	8051000A	SEEDING - COOL SEASON MIXTURES	10.00	0.00	10.00	ACRE	0.00	\$2,150.00	\$0.00
	0001	0310	8061005	ROCK DITCH CHECK	660.00	240.00	900.00	LF	900.00	\$11.25	\$10,125.00
	0001	0320	8061016	SEDIMENT REMOVAL	68.00	0.00	68.00	CUYD	0.00	\$20.00	\$0.00
	0001	0330	8061019	SILT FENCE	2,073.00	0.00	2,073.00	LF	85.00	\$2.30	\$195.50
	0010	0340	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	4.00	0.00	4.00	EA	0.00	\$3,300.00	\$0.00
	0010	0350	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	0.00	\$2,900.00	\$0.00
	0040	0360	9031260	WOOD POST, 4 IN. BY 4 IN.	30.00	0.00	30.00	LF	18.00	\$5.00	\$90.00
	0040	0370	9031270A	2 IN. PSST POST - 12 GA.	264.00	0.00	264.00	LF	0.00	\$12.00	\$0.00
	0040	0380	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	66.00	0.00	66.00	LF	0.00	\$30.00	\$0.00
	0040	0390	9035004A	SH-FLAT SHEET	66.00	0.00	66.00	SQFT	0.00	\$26.00	\$0.00
	0070	0400	7034600	CURB BLOCKOUT	535.00	0.00	535.00	LF	535.00	\$74.00	\$39,590.00
	0001	5001	8061006	ALTERNATE DITCH CHECK	0.00	400.00	400.00	LF	80.00	\$14.00	\$1,120.00
	0001	5002	5041000	CONCRETE APPROACH PAVEMENT	0.00	23.00	23.00	SQYD	23.00	\$207.45	\$4,771.35
Project .	9S3518 - T	otal Value	Posted to D	ate as of Report Generated Date							\$455,665.53
J9S3519	0001	0410	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.74	\$15,000.00	\$11,100.00
	0001	0420	2129909	MISC.SHOULDER GRADING	665.10	0.00	665.10	STA	665.10	\$350.00	\$232,785.00

Page 7 of 25 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

lote: Posted Q Contract	uantities Project	and Value Category	es are b	ltem	eport Generated date and can differ from the posted am- Description	ount at the	time the	Estimate wa	as Gene Unit	rated. Total	Unit Price	Total Value POSTED
Nm.CONTRACT	No.		No.	Code		Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See report generated date)
191018-H04	J9S3519	0001	0430	2159903	MISC.MODIFIED SHAPING SLOPES, CLASS III	550.00	0.00	550.00	LF	550.00	\$8.00	\$4,400.00
		0001	0440	3049907	MISC.TYPE 1 AGGREGATE	282.00	0.00	282.00	CUYD	282.00	\$50.00	\$14,100.00
		0001	0450	3105002	GRAVEL (A) OR CRUSHED STONE (B)	126.00	0.00	126.00	TONS	60.80	\$40.00	\$2,432.00
		0001	0460	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	173.60	0.00	173.60	TONS	88.43	\$165.00	\$14,590.95
		0001	0470	4029905	MISC.OPTIONAL SHOULDERS	14,832.10	0.00	14,832.10	SQYD	14,832.10	\$18.00	\$266,977.80
		0001	0480	4071005	TACK COAT	20.00	0.00	20.00	GAL	20.00	\$6.25	\$125.00
		0001	0490	6119910	MISC.TYPE 2 ROCK DITCH LINER FURNISHING AND PLACING	5.60	0.00	5.60	TONS	5.60	\$100.00	\$560.00
		0001	0500	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	0.00	2.00	EA	0.00	\$1,200.00	\$0.00
		0001	0510	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.00
		0001	0520	6129902	MISC.CRASH CUSHION	2.00	0.00	2.00	EA	0.00	\$3,000.00	\$0.00
		0001	0530	6161005	CONSTRUCTION SIGNS	1,427.00	0.00	1,427.00	SQFT	398.76	\$5.00	\$1,993.80
		0001	0540	6161008	ADVANCED WARNING RAIL SYSTEM	6.00	0.00	6.00	EA	0.00	\$45.00	\$0.00
		0001	0550	6161009	FLAG ASSEMBLY	8.00	0.00	8.00	EA	1.00	\$20.00	\$20.00
		0001	0560	6161025	CHANNELIZER (TRIM LINE)	200.00	0.00	200.00	EA	0.00	\$20.00	\$0.00
		0001	0570	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	0.00	\$2,500.00	\$0.00
		0001	0580	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$69,500.00	\$69,500.00
		0001	0590	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0001	0600	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	67,436.00	0.00	67,436.00	LF	0.00	\$0.10	\$0.00
		0001	0610	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	65,678.00	0.00	65,678.00	LF	0.00	\$0.11	\$0.0
		0001	0620	6207001	PAVEMENT MARKING REMOVAL	67,436.00	0.00	67,436.00	LF	67,436.00	\$0.20	\$13,487.20
		0001	0630	6269909	MISC.SHOULDER RUMBLE STRIP	349.20	0.00	349.20	STA	349.20	\$31.00	\$10,825.2
		0001	0640	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$1.00	\$1.0
		0001	0650	7250318A	18 IN. PIPE GROUP B	244.00	0.00	244.00	LF	232.00	\$50.00	\$11,600.0
		0001	0660	7250324A	24 IN. PIPE GROUP B	4.00	0.00	4.00	LF	4.00	\$100.00	\$400.0
		0001	0670	7250336A	36 IN. PIPE GROUP B	2.00	0.00	2.00	LF	2.00	\$200.00	\$400.0
		0001	0680	7250415	15 IN. PIPE GROUP C	35.00	0.00	35.00	LF	35.00	\$50.00	\$1,750.0
		0001	0690	7320018A	18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END	19.00	0.00	19.00	EA	18.00	\$300.00	\$5,400.00
		0001	0700	7320024A	SECTION 24 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	1.00	1.00	2.00	EA	2.00	\$400.00	\$800.0
		0001	0710	7320036A	36 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$500.00	\$500.0
		0001	0720	7350001	PIPE LINER FOR EXISTING CULVERT	48.00	34.00	82.00	LF	82.00	\$200.00	\$16,400.0
		0001	0730	8051000A	SEEDING - COOL SEASON MIXTURES	14.00	0.00	14.00	ACRE	9.60	\$2,150.00	\$20,640.0
		0001	0740	8061003	SEDIMENT TRAP EXCAVATION	1,526.00	0.00	1,526.00	CUYD	0.00	\$4.00	\$0.0
		0001	0750	8061004	SEDIMENT TRAP ROCK	2,030.00	0.00	2,030.00	CUYD	0.00	\$20.00	\$0.0
		0001	0760	8061005	ROCK DITCH CHECK	1,073.00	908.00	1,981.00	LF	1,981.00	\$11.25	\$22,286.2
		0001	0770	8061016	SEDIMENT REMOVAL	110.00	33.00	143.00	CUYD	143.00	\$10.00	\$1,430.0
		0001	0780	8061019	SILT FENCE	3,372.00	0.00	3,372.00	LF	1,861.00	\$2.30	\$4,280.3
		0001	0790	8069902	MISC.FLOCCULANT SOCK	15.00	0.00	15.00	EA	1.00	\$125.00	\$125.0
		0010	0800	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED	4.00	0.00	4.00	EA	4.00	\$3,400.00	\$13,600.0
		0010	0810	6063014	CURB) TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	4.00	\$2,900.00	\$11,600.0
		0010	0820	9031260	WOOD POST, 4 IN. BY 4 IN.	30.00	198.00	228.00	LF	228.00	\$5.00	\$1,140.0
		0040	0830		2 IN. PSST POST - 12 GA.	48.00	0.00	48.00	LF	36.00	\$12.00	\$432.0
			0840	9031270A 9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	12.00	0.00	12.00	LF	9.00	\$12.00	\$432.0
		0040	0850	9031271 9035004A	SH-FLAT SHEET	12.00	0.00	12.00	SQFT	9.00	\$26.00	\$270.0
		0040										
		0070	0860	7034600	CURB BLOCKOUT	284.00	0.00	284.00	LF	284.00	\$108.00	\$30,672.00

Revision 4/1/2020 Page 8 of 25



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

	Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted amo Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
	191018-H04	J9S3519	0070	0870	7123000	STEEL BAR DAM	1.00	-1.00	0.00	EA		\$5,000.00	\$0.00
Control 1500 151000 151000 15100 1			0001	5101	6214600A	FLOWABLE BACKFILL	0.00	3.00	3.00	CUYD	3.00	\$510.00	\$1,530.00
Montability Marie			0001	5102	4020520		0.00	24.00	24.00	TONS	24.00	\$510.88	\$12,261.12
MASSACT 1001 0000 2022010 SAMOVACO REPREVEMENTS 1.00 0.00 1.00 1.00 1.00 0.00			0001	5103	6181000		0.00	1.00	1.00	LS	1.00	\$2,133.60	\$2,133.60
Control Cont		Project J	9S3519 - To	otal Value	Posted to D	ate as of Report Generated Date							\$805,782.22
Main		J9S3527	0001	0880	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.79	\$30,900.00	\$24,411.00
0011 0011 2105004 MISC SHOULDER GRACIMG 584-30 0.00 584-30 0.01 584-30 487-40 489-50 584-30 592-80 0.00 0.00 0.00 0.00 0.00 584-00 584-00 584-00 592-80 0.00			0001	0890	2031000	CLASS A EXCAVATION	3.00	0.00	3.00	CUYD	0.00	\$20.00	\$0.00
Month 1920 2198933 MISCAMODIFED SHAPPING SLOPES, CLASS III 2,225.00			0001	0900	2063500	CULVERT CLEANOUT	1.00	0.00	1.00	EA	1.00	\$1,500.00	\$1,500.00
10011 1001 1002 1002000 10020000 10020000 10020000 1002000 10020000 1002000 1002000 1002000 1002000 1002000 1002000 1002000 1002000 1002000 1002000 1002000 1002000 1002000 1002000 1002000 1002000 10020000000000			0001	0910	2129909	MISC.SHOULDER GRADING	584.30	0.00	584.30	STA	467.40	\$356.00	\$166,394.40
Management Man			0001	0920	2159903	MISC.MODIFIED SHAPING SLOPES, CLASS III	2,225.00	0.00	2,225.00	LF	266.00	\$8.00	\$2,128.00
MODI 0800 4011870 MIDLANINGUIS PAVEMENT MIXTURE PG64-22, (RP-1) 247 80 0.00 247 80 TONB 51 51 \$1800 36,271 80 0.00 10,000 0.00			0001	0930	3049907	MISC.TYPE 1 AGGREGATE	265.00	0.00	265.00	CUYD	265.00	\$50.00	\$13,250.00
1,431 90 0.001 0.000 0.000 0.001 0			0001	0940	3105002	GRAVEL (A) OR CRUSHED STONE (B)	54.00	0.00	54.00	TONS	0.00	\$40.00	\$0.00
0001 0070 4071005 TACK COAT 2000 0.00			0001	0950	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	247.90	0.00	247.90	TONS	51.51	\$180.00	\$9,271.80
0001 090			0001	0960	4029905	MISC.OPTIONAL SHOULDERS	13,431.90	0.00	13,431.90	SQYD	13,286.90	\$17.20	\$228,534.68
MISCLYPE 1 ROCK DITCH LINER PURNISHING AND PLACING 30.00			0001	0970	4071005	TACK COAT	20.00	0.00	20.00	GAL	0.00	\$6.25	\$0.00
MINISTRYPE 2 ROCK DITCH LINER PURNISHING AND PLACING 574.10			0001	0980	5041000	CONCRETE APPROACH PAVEMENT	30.60	0.00	30.60	SQYD	16.00	\$100.00	\$1,600.00
1001 1010 6122030 MIPACT ATTENUATOR (RELOCATION) 2.00 0.00 2.00 EA 0.00 \$1,200.00 \$0,00 \$0.00			0001	0990	6119910	MISC.TYPE 1 ROCK DITCH LINER FURNISHING AND PLACING	30.00	0.00	30.00	TONS	0.00	\$50.00	\$0.00
1021 1022 6123000A TRICK OR TRAILER MOUNTED ATTENUATOR (TMA) 2.00 0.00 2.00 EA 0.00 \$1,500.00 \$6,000.00			0001	1000	6119910	MISC.TYPE 2 ROCK DITCH LINER FURNISHING AND PLACING	574.10	0.00	574.10	TONS	205.00	\$50.00	\$10,250.00
1000 1030 6129902 MISC CRASH CUSHION 2.00 0.00 2.00 EA 2.00 \$3,000.00 \$6,000.00			0001	1010	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	0.00	2.00	EA	0.00	\$1,200.00	\$0.00
0001 1040 6131014 FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER 5000 0.00 50.00 LF 50.00 \$5.00 \$52.00 \$22.00 \$20.00 \$0.00 1050 6151005 \$0.00 \$0.00 \$1050 \$0.00 \$1.00 \$0.00 \$1.00 \$0.00 \$			0001	1020	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1,500.00	\$0.00
AND INTERNAL SAW CUTS			0001	1030	6129902	MISC.CRASH CUSHION	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00
0001 1060 6161005 CONSTRUCTION SIGNS 1,615.00 0.00 1,615.00 SOFT 490.00 \$5.00 \$2,465.00			0001	1040	6131014		50.00	0.00	50.00	LF	50.00	\$5.00	\$250.00
0001 1070 6161009 FLAG ASSEMBLY 8.00 0.00 8.00 EA 2.00 \$20.00 \$40.00 \$40.00 \$30.00 \$40.00 \$30.00			0001	1050	6161005		1,615.00	0.00	1,615.00	SQFT	490.00	\$5.00	\$2,450.00
0001 1080 6161025 CHANNELIZER (TRIM LINE) 200 0 0.00 200 0 EA 0.00 \$20.00 \$0.00			0001	1060	6161008	ADVANCED WARNING RAIL SYSTEM	6.00	0.00	6.00	EA	1.00	\$45.00	\$45.00
1090			0001	1070	6161009	FLAG ASSEMBLY	8.00	0.00	8.00	EA	2.00	\$20.00	\$40.00
NTERFACE, CONTRACTOR FURNISHED, CONTRACTOR			0001	1080	6161025	CHANNELIZER (TRIM LINE)	200.00	0.00	200.00	EA	0.00	\$20.00	\$0.00
0001 1110 6181020 ADDITIONAL MOBILIZATION FOR SEEDING 4.00 0.00 4.00 EA 0.00 \$600.00 \$0.00			0001	1090	6161098A	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.00
0001 1120 6200018 PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. 62.00 0.00 62.00 LF 0.00 \$18.00 \$0.00 \$0.00 \$18.00 \$0.00 \$18.00 \$0.00 \$18.00 \$0.00 \$18.00 \$0.00 \$18.00 \$0.00 \$18.00 \$0.00 \$18.00 \$0.00 \$18.00 \$0.00 \$18.00 \$0.00 \$18.00 \$0.00 \$0.10 \$0.00 \$0.00 \$0.10 \$0.00 \$0.00 \$0.00 \$0.10 \$0.00 \$0.00 \$0.00 \$0.10 \$0.00 \$0.			0001	1100	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$80,000.00	\$60,000.00
VELLOW			0001	1110	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
PAINT, TYPE P BEADS 0001 1140 6206001C 4 IIN, YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 0001 1150 6207001 PAVEMENT MARKING REMOVAL 71,676.00 0.00 71,676.00 LF 0.00 \$0.20 \$0.0			0001	1120	6200018		62.00	0.00	62.00	LF	0.00	\$18.00	\$0.00
MARKING PAINT, TYPE P BEADS 0001 1150 6207001 PAVEMENT MARKING REMOVAL 71,676.00 0.00 71,676.00 LF 0.00 \$0.20 \$0.00 0001 1160 6240103A PERMANENT EROSION CONTROL GEOTEXTILE 194.00 0.00 194.00 SQYD 182.00 \$2.00 \$364.00 0001 1170 6269909 MISC. SHOULDER RUMBLE STRIP 577.30 0.00 577.30 STA 0.00 \$17.50 \$0.00 0001 1180 6274000 CONTRACTOR FURNISHED SURVEYING AND STAKING 1.00 0.00 1.00 LS 1.00 \$1.00 \$1.00 0001 1190 7034041 CLASS B-1 CONCRETE (CULVERTS) 8.10 0.00 8.10 CUYD 8.10 \$2,000.00 \$16,200.00 0001 1200 7061030 REINFORCING STEEL (CULVERTS) 1,280.00 0.00 1,280.00 LB 1,280.00 \$2.00 \$2,560.00 0001 1210 7250318A 18 IN. PIPE GROUP B 183.00 6.00 189.00 LF 189.00 \$50.00 \$9,450.00 0001 1220 7250324A 24 IN. PIPE GROUP B 163.00 0.00 163.00 LF 163.00 \$70.00 \$11,410.00 0001 1240 7250315 15 IN. PIPE GROUP B 8.00 0.00 743.00 LF 743.00 \$40.00 \$29,720.00 0001 1250 7250418 18 IN. PIPE GROUP C 106.00 0.00 160.00 LF 106.00 \$50.00 \$5,300.00 0001 1260 7320018A 18 IN. PIPE GROUP C 106.00 0.00 13.00 EA 13.00 \$50.00 \$3,900.00			0001	1130	6206000C		71,676.00	0.00	71,676.00	LF	0.00	\$0.10	\$0.00
1160 6240103A PERMANENT EROSION CONTROL GEOTEXTILE 194.00 0.00 194.00 SQYD 182.00 \$2.00 \$364.00			0001	1140	6206001C		65,549.00	0.00	65,549.00	LF	0.00	\$0.11	\$0.00
0001 1170 6269909 MISC.SHOULDER RUMBLE STRIP 577.30 0.00 577.30 STA 0.00 \$17.50 \$0.00 0001 1180 6274000 CONTRACTOR FURNISHED SURVEYING AND STAKING 1.00 0.00 1.00 LS 1.00 \$1.00 \$1.00 0001 1190 7034041 CLASS B-1 CONCRETE (CULVERTS) 8.10 0.00 8.10 CUYD 8.10 \$2,000.00 \$16,200.00 0001 1200 7061030 REINFORCING STEEL (CULVERTS) 1,280.00 0.00 1,280.00 LB 1,280.00 \$2.00 \$2,560.00 0001 1210 7250318A 18 IN. PIPE GROUP B 183.00 6.00 189.00 LF 189.00 \$50.00 \$9,450.00 0001 1220 7250324A 24 IN. PIPE GROUP B 163.00 0.00 163.00 LF 163.00 \$70.00 \$11,410.00 0001 1230 7250330A 30 IN. PIPE GROUP B 8.00 0.00 8.00 LF 8.00 \$100.00 \$8			0001	1150	6207001	PAVEMENT MARKING REMOVAL	71,676.00	0.00	71,676.00	LF	0.00	\$0.20	\$0.00
180 180			0001	1160	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	194.00	0.00	194.00	SQYD	182.00	\$2.00	\$364.00
0001 1190 7034041 CLASS B-1 CONCRETE (CULVERTS) 8.10 0.00 8.10 CUYD 8.10 \$2,000.00 \$16,200.00 0001 1200 7061030 REINFORCING STEEL (CULVERTS) 1,280.00 0.00 1,280.00 LB 1,280.00 \$2.00 \$2,560.00 0001 1210 7250318A 18 IN. PIPE GROUP B 183.00 6.00 189.00 LF 163.00 \$50.00 \$9,450.00 0001 1220 7250324A 24 IN. PIPE GROUP B 163.00 0.00 163.00 LF 163.00 \$70.00 \$11,410.00 0001 1230 7250330A 30 IN. PIPE GROUP B 8.00 0.00 8.00 LF 8.00 \$100.00 \$800.00 0001 1240 7250415 15 IN. PIPE GROUP C 743.00 0.00 743.00 LF 743.00 \$40.00 \$29,720.00 0001 1250 7250418 18 IN. PIPE GROUP C 106.00 0.00 106.00 LF 106.00 \$50.00 \$5,300.00			0001	1170	6269909	MISC.SHOULDER RUMBLE STRIP	577.30	0.00	577.30	STA	0.00	\$17.50	\$0.00
0001 1200 7061030 REINFORCING STEEL (CULVERTS) 1,280.00 0.00 1,280.00 LB 1,280.00 \$2.00 \$2,560.00 0001 1210 7250318A 18 IN. PIPE GROUP B 183.00 6.00 189.00 LF 189.00 \$50.00 \$9,450.00 0001 1220 7250324A 24 IN. PIPE GROUP B 163.00 0.00 163.00 LF 163.00 \$70.00 \$11,410.00 0001 1230 7250330A 30 IN. PIPE GROUP B 8.00 0.00 8.00 LF 8.00 \$100.00 \$800.00 0001 1240 7250415 15 IN. PIPE GROUP C 743.00 0.00 743.00 LF 743.00 \$40.00 \$29,720.00 0001 1250 7250418 18 IN. PIPE GROUP C 106.00 0.00 106.00 LF 106.00 \$50.00 \$5,300.00 0001 1260 7320018A 18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END 13.00 0.00 13.00 EA 13.00 \$300.00			0001	1180	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$1.00	\$1.00
0001 1210 7250318A 18 IN. PIPE GROUP B 183.00 6.00 189.00 LF 189.00 \$50.00 \$9,450.00 0001 1220 7250324A 24 IN. PIPE GROUP B 163.00 0.00 163.00 LF 163.00 \$70.00 \$11,410.00 0001 1230 7250330A 30 IN. PIPE GROUP B 8.00 0.00 8.00 LF 8.00 \$100.00 \$800.00 0001 1240 7250415 15 IN. PIPE GROUP C 743.00 0.00 743.00 LF 743.00 \$40.00 \$29,720.00 0001 1250 7250418 18 IN. PIPE GROUP C 106.00 0.00 106.00 LF 106.00 \$50.00 \$5,300.00 0001 1260 7320018A 18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END 13.00 0.00 13.00 EA 13.00 \$300.00 \$3,900.00			0001	1190	7034041	CLASS B-1 CONCRETE (CULVERTS)	8.10	0.00	8.10	CUYD	8.10	\$2,000.00	\$16,200.00
0001 1220 7250324A 24 IN. PIPE GROUP B 163.00 0.00 163.00 LF 163.00 \$70.00 \$11,410.00 0001 1230 7250330A 30 IN. PIPE GROUP B 8.00 0.00 8.00 LF 8.00 \$100.00 \$800.00 0001 1240 7250415 15 IN. PIPE GROUP C 743.00 0.00 743.00 LF 743.00 \$40.00 \$29,720.00 0001 1250 7250418 18 IN. PIPE GROUP C 106.00 0.00 106.00 LF 106.00 \$50.00 \$5,300.00 0001 1260 7320018A 18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END 13.00 0.00 13.00 EA 13.00 \$300.00 \$3,900.00			0001	1200	7061030	REINFORCING STEEL (CULVERTS)	1,280.00	0.00	1,280.00	LB	1,280.00	\$2.00	\$2,560.00
0001 1230 7250330A 30 IN. PIPE GROUP B 8.00 0.00 8.00 LF 8.00 \$100.00 \$800.00 0001 1240 7250415 15 IN. PIPE GROUP C 743.00 0.00 743.00 LF 743.00 \$40.00 \$29,720.00 0001 1250 7250418 18 IN. PIPE GROUP C 106.00 0.00 106.00 LF 106.00 \$50.00 \$53,000.00 0001 1260 7320018A 18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END 13.00 0.00 13.00 EA 13.00 \$300.00 \$3,900.00			0001	1210	7250318A	18 IN. PIPE GROUP B	183.00	6.00	189.00	LF	189.00	\$50.00	\$9,450.00
0001 1240 7250415 15 IN. PIPE GROUP C 743.00 0.00 743.00 LF 743.00 \$40.00 \$29,720.00 0001 1250 7250418 18 IN. PIPE GROUP C 106.00 0.00 106.00 LF 106.00 \$50.00 \$5,300.00 0001 1260 7320018A 18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END 13.00 0.00 13.00 EA 13.00 \$300.00 \$3,900.00			0001	1220	7250324A	24 IN. PIPE GROUP B	163.00	0.00	163.00	LF	163.00	\$70.00	\$11,410.00
0001 1250 7250418 18 IN. PIPE GROUP C 106.00 0.00 106.00 LF 106.00 \$50.00 \$5,300.00 0001 1260 7320018A 18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END 13.00 0.00 13.00 EA 13.00 \$300.00 \$3,900.00			0001	1230	7250330A	30 IN. PIPE GROUP B	8.00	0.00	8.00	LF	8.00	\$100.00	\$800.00
0001 1260 7320018A 18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END 13.00 0.00 13.00 EA 13.00 \$300.00 \$3,900.00			0001	1240	7250415	15 IN. PIPE GROUP C	743.00	0.00	743.00	LF	743.00	\$40.00	\$29,720.00
			0001	1250	7250418	18 IN. PIPE GROUP C	106.00	0.00	106.00	LF	106.00	\$50.00	\$5,300.00
DEUTIUN			0001	1260	7320018A	18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	13.00	0.00	13.00	EA	13.00	\$300.00	\$3,900.00

Page 9 of 25 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
1018-H04	J9S3527	0001	1270	7320024A	24 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	8.00	0.00	8.00	EA	8.00	\$400.00	\$3,200.0
		0001	1280	7320030A	30 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.0
		0001	1290	8051000A	SEEDING - COOL SEASON MIXTURES	14.00	0.00	14.00	ACRE	0.00	\$2,150.00	\$0.0
		0001	1300	8061005	ROCK DITCH CHECK	1,012.00	124.00	1,136.00	LF	1,136.00	\$11.25	\$12,780.0
		0001	1310	8061016	SEDIMENT REMOVAL	104.00	0.00	104.00	CUYD	5.00	\$10.00	\$50.0
		0001	1320	8061019	SILT FENCE	3,181.00	0.00	3,181.00	LF	450.00	\$2.30	\$1,035.
		0010	1330	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	1,125.00	0.00	1,125.00	LF	525.00	\$24.00	\$12,600.
		0010	1340	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	8.00	0.00	8.00	EA	2.00	\$3,200.00	\$6,400
		0010	1350	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	8.00	0.00	8.00	EA	2.00	\$2,900.00	\$5,800
		0040	1360	9031260	WOOD POST, 4 IN. BY 4 IN.	30.00	0.00	30.00	LF	24.00	\$5.00	\$120
		0040	1370	9031270A	2 IN. PSST POST - 12 GA.	192.00	0.00	192.00	LF	0.00	\$12.00	\$0
		0040	1380	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	48.00	0.00	48.00	LF	0.00	\$30.00	\$0
		0040	1390	9035004A	SH-FLAT SHEET	48.00	0.00	48.00	SQFT	0.00	\$26.00	\$0
		0070	1400	7034600	CURB BLOCKOUT	836.00	0.00	836.00	LF	836.00	\$83.00	\$69,388
	Project J	9S3527 - To	tal Value	Posted to D	ate as of Report Generated Date							\$723,202
	J9S3554	0001	1410	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.13	\$55,000.00	\$7,370
		0001	1420	2063300	CLASS 4 EXCAVATION	28.00	0.00	28.00	CUYD	16.00	\$100.00	\$1,600
		0001	1430	2129909	MISC.SHOULDER GRADING	445.20	0.00	445.20	STA	320.60	\$352.00	\$112,851
		0001	1440	2159903	MISC.MODIFIED SHAPING SLOPES, CLASS III	550.00	0.00	550.00	LF	0.00	\$8.00	\$(
		0001	1450	3105002	GRAVEL (A) OR CRUSHED STONE (B)	64.00	0.00	64.00	TONS	0.00	\$40.00	\$(
		0001	1460	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	9.40	0.00	9.40	TONS	0.00	\$170.00	\$
		0001	1470	4029905	MISC.OPTIONAL SHOULDER	10,015.60	0.00	10,015.60	SQYD	6,428.90	\$18.00	\$115,72
		0001	1480	4071005	TACK COAT	10.00	0.00	10.00	GAL	0.00	\$10.25	\$
		0001	1490	6119910	MISC.TYPE 2 ROCK DITCH LINER FURNISHING AND PLACING	4.20	0.00	4.20	TONS	0.00	\$50.00	\$
		0001	1500	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	0.00	2.00	EA	0.00	\$1,200.00	\$
		0001	1510	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1,500.00	\$
		0001	1520	6129902	MISC.CRASH CUSHION	2.00	0.00	2.00	EA	0.00	\$3,000.00	\$
		0001	1530	6161005	CONSTRUCTION SIGNS	899.00	0.00	899.00	SQFT	332.00	\$5.00	\$1,66
		0001	1540	6161008	ADVANCED WARNING RAIL SYSTEM	6.00	0.00	6.00	EA	6.00	\$45.00	\$27
		0001 1550 6161009 FLAG ASSEMBLY	8.00	0.00	8.00	EA	2.00	\$20.00	\$4			
		0001	1560	6161025	CHANNELIZER (TRIM LINE)	200.00	0.00	200.00	EA	50.00	\$20.00	\$1,000
		0001	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000	
		0001	1580	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$101,000.00	\$0
		0001 1590 6181020 ADDITIONAL MOBILIZATION FOR SEEDING	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$(
		0001	1600	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	0.00	45,830.00	LF	0.00	\$0.10	\$6	
		0001	1610	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT. TYPE P BEADS	39,192.00	0.00	39,192.00	LF	0.00	\$0.11	\$
		0001	1620	6207001	PAVEMENT MARKING REMOVAL	45,830.00	0.00	45,830.00	LF	0.00	\$0.20	\$
		0001	1630	6269909	MISC.SHOULDER RUMBLE STRIP	434.20	0.00	434.20	STA	0.00	\$19.50	\$
		0001	1640	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$1.00	\$0
		0001	1650	7034041	CLASS B-1 CONCRETE (CULVERTS)	84.20	0.00	84.20	CUYD	39.20	\$2,000.00	\$78,400
		0001	1660	7061030	REINFORCING STEEL (CULVERTS)	15,520.00	0.00	15,520.00	LB	6,880.00	\$2.00	\$13,76
		0001	1670	7250424	24 IN. PIPE GROUP C	35.00	0.00	35.00	LF	35.00	\$70.00	\$2,450
		0001	1680	7350001	PIPE LINER FOR EXISTING CULVERT	73.00	0.00	73.00	LF	73.00	\$200.00	\$14,600
		0001	1690	8051000A	SEEDING - COOL SEASON MIXTURES	10.00	0.00	10.00	ACRE	0.00	\$2,150.00	S

Revision 4/1/2020 Page 10 of 25



Total Paid / All Items / All Estimates (Including this Estimate)

Contract n.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTI To Date (See repo generated date)
1018-H04	J9S3554	0001	1700	8061005	ROCK DITCH CHECK	726.00	0.00	726.00	LF	726.00	\$11.25	\$8,167.
		0001	1710	8061016	SEDIMENT REMOVAL	75.00	0.00	75.00	CUYD	0.00	\$10.00	\$0.
		0001	1720	8061019	SILT FENCE	2,280.00	0.00	2,280.00	LF	295.00	\$2.30	\$678.
		0010	1730	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	4.00	0.00	4.00	EA	0.00	\$3,100.00	\$0.
		0010	1740	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	0.00	\$2,900.00	\$0
		0040	1750	9031260	WOOD POST, 4 IN. BY 4 IN.	30.00	0.00	30.00	LF	0.00	\$5.00	\$0
		0040	1760	9031270A	2 IN. PSST POST - 12 GA.	408.00	0.00	408.00	LF	0.00	\$12.00	\$0
		0040	1770	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	102.00	0.00	102.00	LF	0.00	\$30.00	\$0
		0040	1780	9035004A	SH-FLAT SHEET	102.00	0.00	102.00	SQFT	0.00	\$26.00	\$(
		0070	1790	7034600	CURB BLOCKOUT	234.00	0.00	234.00	LF	234.00	\$125.00	\$29,250
	Project J9	S3554 - To	otal Value	Posted to D	ate as of Report Generated Date							\$392,817
	J9S3555	0001	1800	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.67	\$32,400.00	\$21,708
		0001	1810	2063300	CLASS 4 EXCAVATION	4.00	0.00	4.00	CUYD	4.00	\$200.00	\$800
		0001	1820	2129909	MISC.SHOULDER GRADING	540.20	0.00	540.20	STA	432.20	\$351.00	\$151,702
		0001	1830	2159903	MISC.MODIFIED SHAPING SLOPES, CLASS III	625.00	0.00	625.00	LF	0.00	\$8.00	\$0
		0001	1840	3105002	GRAVEL (A) OR CRUSHED STONE (B)	75.00	0.00	75.00	TONS	0.00	\$40.00	\$(
		0001	1850	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	62.60	0.00	62.60	TONS	0.00	\$215.00	\$
		0001	1860	4029905	MISC.OPTIONAL SHOULDER	12,191.00	0.00	12,191.00	SQYD	12,191.00	\$18.50	\$225,53
		0001	1870	4071005	TACK COAT	20.00	0.00	20.00	GAL	0.00	\$6.25	\$
		0001	1880	6119910	MISC.TYPE 2 ROCK DITCH LINER FURNISHING AND PLACING	106.60	0.00	106.60	TONS	0.00	\$50.00	\$
		0001	1890	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1,500.00	\$
		0001	1900	6161005	CONSTRUCTION SIGNS	1,048.00	0.00	1,048.00	SQFT	38.00	\$5.00	\$19
		0001	1910	6161009	FLAG ASSEMBLY	6.00	0.00	6.00	EA	0.00	\$20.00	\$
		0001	1920	6161025	CHANNELIZER (TRIM LINE)	50.00	0.00	50.00	EA	0.00	\$20.00	\$
		0001	1930	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	2.00	0.00	2.00	EA	1.00	\$2,500.00	\$2,50
		0001	1940	6181000	RETAINED MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$72,000.00	\$54,00
		0001	1950	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	5
		0001	1960	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	55,239.00	0.00	55,239.00	LF	0.00	\$0.10	s
		0001	1970	6206001C	PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT. TYPE P BEADS	49,289.00	0.00	49,289.00	LF	0.00	\$0.11	\$
		0001	1980	6207001	PAVEMENT MARKING REMOVAL	55,239.00	0.00	55,239.00	LF	0.00	\$0.20	\$
		0001	1990	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	160.00	0.00	160.00	SQYD	0.00	\$2.00	\$
		0001	2000	6269909	MISC.SHOULDER RUMBLE STRIP	523.40	0.00	523.40	STA	0.00	\$17.50	\$
		0001	2010	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$1.00	\$
		0001	2020	7034041	CLASS B-1 CONCRETE (CULVERTS)	17.40	0.00	17.40	CUYD	17.40	\$2,000.00	\$34,80
		0001	2030	7061030	REINFORCING STEEL (CULVERTS)	3,500.00	0.00	3,500.00	LB	3,500.00	\$2.00	\$7,00
		0001	2040	7250415	15 IN. PIPE GROUP C	145.00	0.00	145.00	LF	145.00	\$50.00	\$7,25
		0001	2050	7350001	PIPE LINER FOR EXISTING CULVERT	211.00	0.00	211.00	LF	211.00	\$200.00	\$42,20
		0001	2060	8051000A	SEEDING - COOL SEASON MIXTURES	12.00	0.00	12.00	ACRE	0.00	\$2,150.00	9.2,20
		0001	2070	8061005	ROCK DITCH CHECK	873.00	292.00	1,165.00	LF	1,165.00	\$11.25	\$13,10
		0001	2080	8061016	SEDIMENT REMOVAL	90.00	0.00	90.00	CUYD	0.00	\$10.00	\$13,10
			2090	8061019	SILT FENCE	2,743.00	0.00	2,743.00	LF	35.00	\$2.30	\$8
		0001										
		0010	2100	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	213.00	0.00	213.00	LF	0.00	\$24.00	\$
		0010	2110	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	3.00	0.00	3.00	EA	0.00	\$3,100.00	\$
		0010	2120	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	3.00	0.00	3.00	EA	0.00	\$2,900.00	\$
		0040	2130	9031260	WOOD POST, 4 IN. BY 4 IN.	30.00	60.00	90.00	LF	90.00	\$5.00	\$45

Revision 4/1/2020 Page 11 of 25



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Q	uantities	and Value	es are b	ased on R	eport Generated date and can differ from the po	osted amount at the	time the	Estimate w	as Gene	erated.		
Contract	Project	Category	Line	Itom	Description	Rid	Not	Total	Unit	Total	Unit Price	Total Value POSTED

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191018-H04	J9S3555	0040	2140	9031270A	2 IN. PSST POST - 12 GA.	60.00	0.00	60.00	LF	0.00	\$12.00	\$0.00
		0040	2150	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	15.00	0.00	15.00	LF	0.00	\$30.00	\$0.00
		0040	2160	9035004A	SH-FLAT SHEET	15.00	0.00	15.00	SQFT	0.00	\$26.00	\$0.00
	Project J	9S3555 - To	otal Value	Posted to D	late as of Report Generated Date							\$561,320.45
	J9S3594	0001	2170	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$10,000.00	\$10,000.00
		0001	2180	2129909	MISC.SHOULDER GRADING	290.00	0.00	290.00	STA	290.00	\$350.00	\$101,500.00
		0001	2190	3049907	MISC.TYPE 1 AGGREGATE	12.00	0.00	12.00	CUYD	12.00	\$50.00	\$600.00
		0001	2200	3105002	GRAVEL (A) OR CRUSHED STONE (B)	103.00	0.00	103.00	TONS	49.70	\$40.00	\$1,988.00
		0001	2210	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	57.00	0.00	57.00	TONS	20.90	\$225.00	\$4,702.50
		0001	2220	4029905	MISC.OPTIONAL SHOULDERS	6,443.90	0.00	6,443.90	SQYD	6,443.90	\$18.00	\$115,990.20
		0001	2230	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.00
		0001	2240	6161005	CONSTRUCTION SIGNS	769.00	0.00	769.00	SQFT	508.76	\$5.00	\$2,543.80
		0001	2250	6161009	FLAG ASSEMBLY	6.00	0.00	6.00	EA	6.00	\$20.00	\$120.00
		0001	2260	6161025	CHANNELIZER (TRIM LINE)	50.00	0.00	50.00	EA	50.00	\$20.00	\$1,000.00
		0001	2270	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.00
		0001	2280	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$54,500.00	\$54,500.00
		0001	2290	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0001	2300	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	28,998.00	0.00	28,998.00	LF	0.00	\$0.10	\$0.00
		0001	2310	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	26,197.00	0.00	26,197.00	LF	0.00	\$0.11	\$0.00
		0001	2320	6207001	PAVEMENT MARKING REMOVAL	28,998.00	0.00	28,998.00	LF	28,998.00	\$0.20	\$5,799.60
		0001	2330	6269909	MISC.SHOULDER RUMBLE STRIP	181.40	0.00	181.40	STA	181.40	\$45.00	\$8,163.00
		0001	2340	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$1.00	\$1.00
		0001	2350	7250318A	18 IN. PIPE GROUP B	118.00	0.00	118.00	LF	118.00	\$50.00	\$5,900.00
		0001	2360	7250415	15 IN. PIPE GROUP C	120.00	0.00	120.00	LF	120.00	\$50.00	\$6,000.00
		0001	2370	7320018A	18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	8.00	0.00	8.00	EA	8.00	\$400.00	\$3,200.00
		0001	2380	8051000A	SEEDING - COOL SEASON MIXTURES	6.00	0.00	6.00	ACRE	4.80	\$2,150.00	\$10,320.00
		0001	2390	8061003	SEDIMENT TRAP EXCAVATION	1,243.00	0.00	1,243.00	CUYD	0.00	\$4.00	\$0.00
		0001	2400	8061004	SEDIMENT TRAP ROCK	1,653.00	0.00	1,653.00	CUYD	0.00	\$20.00	\$0.00
		0001	2410	8061005	ROCK DITCH CHECK	461.00	216.00	677.00	LF	677.00	\$11.25	\$7,616.25
		0001	2420	8061016	SEDIMENT REMOVAL	47.00	0.00	47.00	CUYD	47.00	\$10.00	\$470.00
		0001	2430	8061019	SILT FENCE	1,450.00	0.00	1,450.00	LF	700.00	\$2.30	\$1,610.00
		0001	2440	8069902	MISC.FLOCCULANT SOCK	11.00	0.00	11.00	EA	0.00	\$125.00	\$0.00
		0040	2450	9031260	WOOD POST, 4 IN. BY 4 IN.	30.00	84.00	114.00	LF	114.00	\$5.00	\$570.00
	Project J	9S359 <u>4 - To</u>	otal Value	Posted to D	ate as of Report Generated Date							\$350,594.35
191018-H04 Ove	rall - Total	Value Pos	ted to Dat	te as of Repo	ort Generated Date							\$3,289,382.83

Revision 4/1/2020 Page 12 of 25



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9S3518

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0800	4029905	MISC. BITUMINOUS PAVEMENT (SURF. LEVEL)	9/11/20	9/16/20	4,166.60	SQYD		1.197		5.170		
			9/14/20	9/16/20	4,178.70	SQYD	Finished paving	1.197		5.170		
5001	8061006	ALTERNATE DITCH CHECK	9/15/20	9/16/20	80.00	LF	Rte H	1.197		5.170		

Project: J9S3527

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0960	4029905	MISC. BITUMINOUS PAVEMENT (SURF. LEVEL)	9/8/20	9/14/20	7,278.50	SQYD	Rte K EB					
			9/9/20	9/14/20	6,008.40	SQYD	Rte K WB shoulder					

Project: J9S3554

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
1420	2063300	CLASS 4 EXCAVATION	9/15/20	9/16/20	11.00	CUYD		1.412		2.040		2 CY @ 1.412, 9 CY @ 2.040
1430	2129909	MISC. SUBGRADING & SHOULDERING	9/15/20	9/16/20	320.60	STA		0.000		3.918		400.7 STA Paid at 80% until finish graded.
1470	4029905	MISC. BITUMINOUS PAVEMENT (SURF. LEVEL)	9/15/20	9/16/20	6,428.90	SQYD	0.000-3.979 RT, 0.058-1.616 LT	0.000		3.979		
1650	7034041	CLASS B-1 CONCRETE (CULVERTS)	9/15/20	9/16/20	8.70	CUYD		3.236	RT			
				9/16/20	10.60	CUYD		1.412		2.040		3.5 CY @ 1.412 RT, 7.1 CY @ 2.040 LT
1660	7061030	REINFORCING STEEL (CULVERTS)	9/15/20	9/16/20	1,630.00	LB		3.236	RT			
				9/16/20	2,040.00	LB		1.412		2.040		620 lbs @ 1.412, 1420 lbs @ 2.040
1700	8061005	ROCK DITCH CHECK	9/15/20	9/16/20	726.00	LF		0.000		4.340		
1720	8061019	SILT FENCE	9/15/20	9/16/20	295.00	LF		0		4.340		

Project: J9S3555

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
1860	4029905	MISC. BITUMINOUS PAVEMENT (SURF. LEVEL)	9/10/20	9/16/20	10,088.00	SQYD	Rte AA - LM 0.005 to LM 5.236 WB and LM 5.236 to LM 1.796					
			9/11/20	9/16/20	2,103.00	SQYD	EB - Rte AA	1.796		0.005		

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 13 of 25



13 on the current Payment Estimate. 8 Aug 3, SYSTEM (\$7,380.00) 8 Aug 37, SYSTEM \$7,380.00 Ithis adjustment offsets the original system-generated Overrun Payment Estimate Exception 18 on the current Payment Estimate. 9 Aug 17, SYSTEM (\$7,380.00) 9 Aug 17, SYSTEM \$7,380.00 Ithis adjustment offsets the original system-generated Overrun Payment Estimate Exception 18 on the current Payment Estimate. 10 Sep 2, SYSTEM (\$7,380.00) 10 Sep 2, SYSTEM (\$7,380.00) 10 Sep 2, SYSTEM \$7,380.00 Ithis adjustment offsets the original system-generated Overrun Payment Estimate Exception 23 on the current Payment Estimate. 10 Sep 2, SYSTEM (\$7,380.00) 11 Sep 16, SYSTEM (\$7,380.00) 11 Sep 16, SYSTEM (\$7,380.00) 11 Sep 16, SYSTEM \$7,380.00 Ithis adjustment offsets the original system-generated Overrun Payment Estimate Exception 29 on the current Payment Estimate. 11 Sep 16, SYSTEM (\$7,380.00) 12 Sep 16, SYSTEM SY,380.00 Ithis adjustment offsets the original system-generated Overrun Payment Estimate Exception 29 on the current Payment Estimate. 11 Sep 16, SYSTEM SY,380.00 Ithis adjustment offsets the original system-generated Overrun Payment Estimate Exception 25 on the current Payment Estimate. 11 Sep 16, SYSTEM SY,380.00 Ithis adjustment offsets the original system-generated Overrun Payment Estimate Exception 25 on the current Payment Estimate.	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
Column C	0800						schmij8	, , ,	See AC Adjustment for Estimate 0011.
CLASS R.1 Malerial County				ACAD - Tota	al				
CLASS ET CLAVERTS STORE	0000		- Total						
CONCRETE S			Meterial		7	Jul 46	CVCTEM		
Page 2, 2007 SYSTEM \$42,600.00	0260	CONCRETE	мателаг			2020			
1-70stal						2020		, ,	
Material - Total					10	2020 Sep 2,		(\$42,600.00)	
Material - Total						2020			
CLASS B.1 Material Credit Applications Aug 17 SYSTEM \$42,000 to		Motorial Total		- Iotal					
Part			Material Credit		0	Aug 2	CVCTEM		
10 Sep 2 SYSTEM \$42,600.00		CONCRETE	MaterialCredit			2020			
Aug 17 SySTEM S42,600.00							OTOTEW	ψ+2,000.00	
CLASS BL Other Item Material Credit - Total					10		SYSTEM	\$42,600.00	
Material Crodit - Total CLAS B-1 Other Item CULVERTS Adjustment COUNCRETE Adjustment Total Sap 16, schmij8 \$20,400.00 Paying for precast box culvert extensions at LM 4.666 (7.4 CY) and 4.860 (2.8 CY). MDPA - Total					11		SYSTEM	\$42,600.00	
CLASS B-1 Other Item CONCRETE (GULVERTS) Page 14, 2020 MDPA - Total Sound MDPA - Total CONCRETE (GULVERTS) Page 14, 2020 MDPA - Total Sound MDPA - Total Sound MDPA - Total Sound This adjustment offsets the original system-generated Overrun Payment Estimate Exception 18 on the current Payment Estimate (Moral payment Estimate Exception 19 on the current Payment Estimate (Moral payment Estimate Exception 19 on the current Payment Estimate Estimate Exception 19 on the current Payment Estimate Estimate Exception 29 on the current Payment Estimate Exception 25 on the c				- Total				\$150,000.00	
CONCRETE (CULVERTS) Adjustment 2020 MoDOT materials yet. This is payment for the 3.6CV extension @ 1.251 and the 5.9 CV extension @ 3.223. 9		MaterialCredit - Total						\$150,000.00	
1		CONCRETE		MDPA	7		schmij8	\$19,000.00	MoDOT materials yet. This is payment for the 3.6CY extension @ 1.251 and the 5.9
2020 S0.00 S0.00					9		schmij8	\$20,400.00	Paying for precast box culvert extensions at LM 4.666 (7.4 CY) and 4.860 (2.8 CY).
Other Rem Adjustment - Total So.00					11		schmij8	(\$39,400.00)	Materials exceptions have been satisfied. Taking back previous pay adjustments.
Social				MDPA - Tot	al			\$0.00	
REINFORCING STEEL (CULVERTS)			- Total					\$0.00	
CULVERTS									
B Aug 3, 2020 SYSTEM (\$7,380.00)	0270		Material			2020		,	
8 Aug 3, 2020 SYSTEM \$7,380.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 18 on the current Payment Estimate. 9 Aug 17, 2020 SYSTEM \$7,380.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 23 on the current Payment Estimate Exception 23 on the current Payment Estimate Exception 23 on the current Payment Estimate Exception 25 on the current Payment Estimate Exception 27 on the current Payment Estimate Exception 28 on the current Payment Estimate Exception 29 on the current Payment Estimate. 11 Sep 16, 2020 SYSTEM \$7,380.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 29 on the current Payment Estimate. 11 Sep 16, 2020 SYSTEM \$7,380.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 29 on the current Payment Estimate. 11 Sep 16, 2020 SYSTEM \$7,380.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 2000 due to user schmij8 overridding Payment Estimate Exception 15 on the current Payment Estimate.					/		SYSTEM	\$3,560.00	Item Adjustment (0037) due to user schmij8 overridding Payment Estimate Exception
Lem Adjustment (0003) due to user schmij8 overridding Payment Éstimate Exception 18 on the current Payment Estimate.					8		SYSTEM	(\$7,380.00)	
9 Aug 17, 2020 \$7,380.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user schmij8 overridding Payment Estimate Exception 23 on the current Payment Estimate. 10 Sep 2, 2020 \$YSTEM (\$7,380.00) 10 Sep 2, 2020 \$7,380.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user schmij8 overridding Payment Estimate Exception 29 on the current Payment Estimate. 11 Sep 16, 2020 \$YSTEM (\$7,380.00) 11 Sep 16, 2020 \$7,380.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 11 Sep 16, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schmij8 overridding Payment Estimate Exception 15 on the current Payment Estimate.					8		SYSTEM	\$7,380.00	Item Adjustment (0003) due to user schmij8 overridding Payment Estimate Exception
10 Sep 2, 2020 SYSTEM (\$7,380.00) Sep 2, 2020 SYSTEM (\$7,380.00) Sep 3, 380.00 Sep 4, 2020 SYSTEM (\$7,380.00) SYSTEM (\$7,38					9		SYSTEM	(\$7,380.00)	
2020 10 Sep 2, 2020 11 Sep 16, 2020 11 Sep 16, 2020 11 Sep 16, 2020 11 Sep 16, 2020 12 Sep 16, 2020 13 Sep 16, 2020 14 Sep 16, 2020 15 on the current Payment Estimate Item Adjustment offsets the original system-generated Overrun Payment Estimate. 16 Sep 16, 2020 17 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schmijß overridding Payment Estimate Exception 15 on the current Payment Estimate. 18 Sound Material - Total					9		SYSTEM	\$7,380.00	Item Adjustment (0011) due to user schmij8 overridding Payment Estimate Exception
11 Sep 16, 2020 SYSTEM (\$7,380.00) 11 Sep 16, 2020 SYSTEM \$7,380.00 SYSTEM \$7,380.00 SYSTEM \$10,00 SYSTEM \$0.00 SYSTEM SYSTEM \$0.00 SYSTEM \$					10		SYSTEM	(\$7,380.00)	
2020 11 Sep 16, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schmij8 overridding Payment Estimate Exception 15 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00					10		SYSTEM	\$7,380.00	Item Adjustment (0017) due to user schmij8 overridding Payment Estimate Exception
2020 Item Adjustment (0002) due to user schmij8 overridding Payment Estimate Exception 15 on the current Payment Estimate. - Total					11		SYSTEM	(\$7,380.00)	
Material - Total \$0.00					11	Sep 16, 2020	SYSTEM	\$7,380.00	Item Adjustment (0002) due to user schmij8 overridding Payment Estimate Exception
				- Total				\$0.00	
0270 - Total \$0.00		Material - Total						\$0.00	
	0270 -	Total						\$0.00	

Revision 4/1/2020 Page 14 of 25



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0310	ROCK DITCH CHECK	Overrun	Overrun	9	Aug 17, 2020	SYSTEM	(\$1,462.50)	
				10	Sep 2, 2020	SYSTEM	\$1,462.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',11.25000 - 11.25000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0310 -	Total						\$0.00	
0400	CURB BLOCKOUT	Material		9	Aug 17, 2020	SYSTEM	(\$39,590.00)	
				10	Sep 2, 2020	SYSTEM	(\$39,590.00)	
				11	Sep 16, 2020	SYSTEM	(\$39,590.00)	
			- Total				(\$118,770.00)	
	Material - Total						(\$118,770.00)	
	CURB BLOCKOUT	MaterialCredit		10	Sep 2, 2020	SYSTEM	\$39,590.00	
				11	Sep 16, 2020	SYSTEM	\$39,590.00	
			- Total				\$79,180.00	
	MaterialCredit - Total						\$79,180.00	
	CURB BLOCKOUT	Other Item Adjustment	MDPA	10	Sep 2, 2020	schmij8	\$35,631.00	Paying 90%. Holding the rest until curbs are sealed.
			MDPA - Tota	al			\$35,631.00	
	Other Item Adjustment	- Total					\$35,631.00	
0400 -	Total						(\$3,959.00)	
0470	MISC. OPTIONAL SHOULDERS	Other Item Adjustment	ACAD	5	Jun 16, 2020	schmij8	(\$11,731.73)	See AC adjustment sheet attached with this estimate.
			ACAD - Tota	al			(\$11,731.73)	
	Other Item Adjustment	- Total					(\$11,731.73)	
0470 -	Total						(\$11,731.73)	
0510	TRUCK OR TRAILER MOUNTED	Material		10	Sep 2, 2020	SYSTEM	(\$3,000.00)	
	ATTENUATOR (TMA)			11	Sep 16, 2020	SYSTEM	(\$3,000.00)	
			- Total				(\$6,000.00)	
	Material - Total						(\$6,000.00)	
	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	MaterialCredit		11	Sep 16, 2020	SYSTEM	\$3,000.00	
			- Total				\$3,000.00	
	MaterialCredit - Total						\$3,000.00	
0510 -	Total						(\$3,000.00)	
0650	18 IN. PIPE GROUP B	Material		2	May 4, 2020	SYSTEM	(\$5,600.00)	
			- Total				(\$5,600.00)	
	Material - Total						(\$5,600.00)	
	18 IN. PIPE GROUP B	MaterialCredit		3	May 15, 2020	SYSTEM	\$5,600.00	
			- Total				\$5,600.00	
	MaterialCredit - Total						\$5,600.00	
	18 IN. PIPE GROUP B	Other Item Adjustment	MDPA	2	May 4, 2020	schmij8	\$3,000.00	Item adjustment for \$3000 to pay for all installed pipes except pipe installed at LM 7.364. We are withholding pay for this pipe until culvert performance test is complete.
				3	May 15, 2020	schmij8	(\$3,000.00)	Adjustment for \$3000 was made on estimate 0002 to pay contractor for portion of pipe not affected by material exception. Material exception has been satisfied and system has adjusted full price of item onto this estimate.
			MDPA - Tota	al			\$0.00	
	Other Item Adjustment	- Total					\$0.00	

Revision 4/1/2020 Page 15 of 25



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0650 -	· Total						\$0.00	
0660	24 IN. PIPE GROUP B	Material		2	May 4, 2020	SYSTEM	(\$400.00)	
				2	May 4, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user schmij8 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0660 -	- Total						\$0.00	
0670	36 IN. PIPE GROUP B	Material		2	May 4, 2020	SYSTEM	(\$400.00)	
				2	May 4, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user schmij8 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0670 -	· Total						\$0.00	
0680	15 IN. PIPE GROUP C	Material		2	May 4, 2020	SYSTEM	(\$1,750.00)	
				2	May 4, 2020	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user schmij8 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0680 -	· Total						\$0.00	
0700	24 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END	Overrun	Overrun	2	May 4, 2020	SYSTEM	(\$400.00)	
	SECTION			7	Jul 16, 2020	SYSTEM	\$400.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',400.00000 - 400.00000, 'is applied (if non-zero).
			Overrun - To	otal			\$0.00	
	Overrun - Total						\$0.00	
0700 -	· Total						\$0.00	
0730	SEEDING - COOL SEASON MIXTURES	Material		8	Aug 3, 2020	SYSTEM	(\$20,640.00)	
				8	Aug 3, 2020	SYSTEM	\$20,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user schmij8 overridding Payment Estimate Exception 23 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0730 -	Total						\$0.00	
0760	ROCK DITCH CHECK	Overrun	Overrun	4	Jun 2, 2020	SYSTEM	(\$2,385.00)	
				5	Jun 16, 2020	SYSTEM	(\$7,830.00)	
				7	Jul 16, 2020	SYSTEM	\$10,215.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',11.25000 - 11.25000, 'is applied (if non-zero).
			Overrun - To	otal			\$0.00	
	Overrun - Total						\$0.00	
0760 -	· Total						\$0.00	
0770	SEDIMENT REMOVAL	Overrun	Overrun	9	Aug 17, 2020	SYSTEM	(\$330.00)	
				10	Sep 2, 2020	SYSTEM	\$330.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',10.00000 - 10.00000, 'is applied (if non-zero).
			Overrun - To	otal			\$0.00	
	Overrun - Total						\$0.00	
0770 -	Total						\$0.00	
0780	SILT FENCE	Material		3	May 15, 2020	SYSTEM	(\$1,541.00)	

Revision 4/1/2020 Page 16 of 25



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0780		Material	- Total				(\$1,541.00)	
	Material - Total						(\$1,541.00)	
	SILT FENCE	MaterialCredit		4	Jun 2, 2020	SYSTEM	\$1,541.00	
			- Total				\$1,541.00	
	MaterialCredit - Total						\$1,541.00	
0780 -	Total						\$0.00	
0790	MISC. FLOCCULANT SOCK	Material		5	Jun 16, 2020	SYSTEM	(\$125.00)	
				6	Jul 1, 2020	SYSTEM	(\$125.00)	
				7	Jul 16, 2020	SYSTEM	(\$125.00)	
				8	Aug 3, 2020	SYSTEM	(\$125.00)	
				9	Aug 17, 2020	SYSTEM	(\$125.00)	
				10	Sep 2, 2020	SYSTEM	(\$125.00)	
				11	Sep 16, 2020	SYSTEM	(\$125.00)	
			- Total				(\$875.00)	
	Material - Total						(\$875.00)	
	MISC. FLOCCULANT SOCK	MaterialCredit		6	Jul 1, 2020	SYSTEM	\$125.00	
				7	Jul 16, 2020	SYSTEM	\$125.00	
				8	Aug 3, 2020	SYSTEM	\$125.00	
				9	Aug 17, 2020	SYSTEM	\$125.00	
				10	Sep 2, 2020	SYSTEM	\$125.00	
				11	Sep 16, 2020	SYSTEM	\$125.00	
			- Total				\$750.00	
	MaterialCredit - Total						\$750.00	
0790 -	Total						(\$125.00)	
0820	WOOD POST, 4 IN. BY 4 IN.	Overrun	Overrun	3	May 15, 2020	SYSTEM	(\$600.00)	
				4	Jun 2, 2020	SYSTEM	(\$390.00)	
				7	Jul 16, 2020	SYSTEM	\$990.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0820 -	Total						\$0.00	
0860	CURB BLOCKOUT	Material		10	Sep 2, 2020	SYSTEM	(\$30,672.00)	
				11	Sep 16, 2020	SYSTEM	(\$30,672.00)	
			- Total				(\$61,344.00)	
	Material - Total						(\$61,344.00)	
	CURB BLOCKOUT	MaterialCredit		11	Sep 16, 2020	SYSTEM	\$30,672.00	
			- Total				\$30,672.00	
	MaterialCredit - Total						\$30,672.00	
	CURB BLOCKOUT	Other Item Adjustment	MDPA	10	Sep 2, 2020	schmij8	\$27,604.80	Paying 90%. Holding the rest until curbs are sealed.

Revision 4/1/2020 Page 17 of 25



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0860		Other Item Adjustment	MDPA - Tota	al			\$27,604.80	
	Other Item Adjustment	- Total					\$27,604.80	
0860 -	Total						(\$3,067.20)	
0950	BITUMINOUS PAVEMENT MIXTURE	Material		6	Jul 1, 2020	SYSTEM	(\$3,987.00)	
	PG64-22, (BP-1)			7	Jul 16, 2020	SYSTEM	(\$3,987.00)	
				8	Aug 3, 2020	SYSTEM	(\$9,271.80)	
				9	Aug 17, 2020	SYSTEM	(\$9,271.80)	
			- Total				(\$26,517.60)	
	Material - Total						(\$26,517.60)	
	BITUMINOUS PAVEMENT MIXTURE	MaterialCredit		7	Jul 16, 2020	SYSTEM	\$3,987.00	
	PG64-22, (BP-1)			8	Aug 3, 2020	SYSTEM	\$3,987.00	
				9	Aug 17, 2020	SYSTEM	\$9,271.80	
				10	Sep 2, 2020	SYSTEM	\$9,271.80	
			- Total				\$26,517.60	
	MaterialCredit - Total						\$26,517.60	
0950 -	Total						\$0.00	
0960	MISC. OPTIONAL SHOULDERS	Other Item Adjustment	ACAD	11	Sep 16, 2020	schmij8	(\$11,984.78)	See AC Adjustment for Estimate 0011.
			ACAD - Tota	al			(\$11,984.78)	
	Other Item Adjustment	- Total					(\$11,984.78)	
0960 -	Total						(\$11,984.78)	
0980	CONCRETE APPROACH	Material		7	Jul 16, 2020	SYSTEM	(\$1,600.00)	
	PAVEMENT			8	Aug 3, 2020	SYSTEM	(\$1,600.00)	
				9	Aug 17, 2020	SYSTEM	(\$1,600.00)	
				10	Sep 2, 2020	SYSTEM	(\$1,600.00)	
			- Total				(\$6,400.00)	
	Material - Total						(\$6,400.00)	
	APPROACH	MaterialCredit		8	Aug 3, 2020	SYSTEM	\$1,600.00	
	PAVEMENT			9	Aug 17, 2020	SYSTEM	\$1,600.00	
				10	Sep 2, 2020	SYSTEM	\$1,600.00	
				11	Sep 16, 2020	SYSTEM	\$1,600.00	
			- Total				\$6,400.00	
	MaterialCredit - Total						\$6,400.00	
0980 -	Total						\$0.00	
1160	PERMANENT EROSION CONTROL GEOTEXTILE	Material		8	Aug 3, 2020	SYSTEM	(\$364.00)	
	GEOTEXTILE			9	Aug 17, 2020	SYSTEM	(\$364.00)	
			- Total				(\$728.00)	
	Material - Total						(\$728.00)	
	EROSION CONTROL	MaterialCredit		9	Aug 17, 2020	SYSTEM	\$364.00	
	GEOTEXTILE			10	Sep 2,	SYSTEM	\$364.00	

Revision 4/1/2020 Page 18 of 25



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1160	PERMANENT EROSION CONTROL GEOTEXTILE	MaterialCredit			2020			
			- Total				\$728.00	
	MaterialCredit - Total						\$728.00	
1160 -	Total						\$0.00	
1190	CLASS B-1 CONCRETE (CULVERTS)	Material		6	Jul 1, 2020	SYSTEM	(\$16,200.00)	
				8	Jul 16, 2020 Aug 3,	SYSTEM	(\$16,200.00)	
				9	2020 Aug 17,	SYSTEM	(\$16,200.00)	
				10	2020 Sep 2, 2020	SYSTEM	(\$16,200.00)	
			- Total		2020		(\$81,000.00)	
	Material - Total		Total				(\$81,000.00)	
		MaterialCredit		7	Jul 16, 2020	SYSTEM	\$16,200.00	
	(CULVERTS)			8	Aug 3, 2020	SYSTEM	\$16,200.00	
				9	Aug 17, 2020	SYSTEM	\$16,200.00	
				10	Sep 2, 2020	SYSTEM	\$16,200.00	
				11	Sep 16, 2020	SYSTEM	\$16,200.00	
			- Total				\$81,000.00	
	MaterialCredit - Total						\$81,000.00	
	CLASS B-1 CONCRETE (CULVERTS)	Other Item Adjustment	MDPA		Jul 1, 2020	schmij8	\$12,400.00	Paying for the culvert extension @ 5.799. Culvert extension was precast. Holding pay for 1.9 CY of headwall extension until tests for concrete rock and sand are received.
			MDPA - Tota	11	Sep 16, 2020	schmij8	(\$12,400.00) \$0.00	Materials exceptions have been satisfied. Taking back previous pay adjustments.
	Other Item Adjustment	Total	WIDPA - TOO	aı			\$0.00	
1190 -		- I Otal					\$0.00	
1200	REINFORCING STEEL (CULVERTS)	Material		6	Jul 1, 2020	SYSTEM	(\$2,560.00)	
				6	Jul 1, 2020	SYSTEM	\$2,560.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user schmij8 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$2,560.00)	
				7	Jul 16, 2020	SYSTEM	\$2,560.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0045) due to user schmij8 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$2,560.00)	
				8	Aug 3, 2020	SYSTEM	\$2,560.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user schmij8 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				9	Aug 17, 2020	SYSTEM	(\$2,560.00)	
				9	Aug 17, 2020	SYSTEM	\$2,560.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user schmij8 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				10	Sep 2, 2020	SYSTEM	(\$2,560.00)	
				10	Sep 2, 2020	SYSTEM	\$2,560.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user schmij8 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$2,560.00)	

Revision 4/1/2020 Page 19 of 25



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
1200	REINFORCING STEEL (CULVERTS)	Material		11	Sep 16, 2020	SYSTEM	\$2,560.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user schmij8 overridding Payment Estimate Exception 16 on the current Payment Estimate.						
			- Total				\$0.00							
	Material - Total						\$0.00							
1200 -							\$0.00							
		Meterial		6	hal 4	CVCTEM								
1210	18 IN. PIPE GROUP B	Material		6	Jul 1, 2020	SYSTEM	(\$4,650.00)	This adjustment effects the existing queters appeared Oversia Downson's Fatimate						
				6	Jul 1, 2020	SYSTEM	\$4,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user schmij8 overridding Payment Estimate Exception 5 on the current Payment Estimate.						
				7	Jul 16, 2020	SYSTEM	(\$5,150.00)							
				7	Jul 16, 2020	SYSTEM	\$5,150.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0046) due to user schmij8 overridding Payment Estimate Exception 15 on the current Payment Estimate.						
			- Total				\$0.00							
	Material - Total						\$0.00							
1210 -							\$0.00							
1220	24 IN. PIPE GROUP B	Material		6	Jul 1, 2020	SYSTEM	(\$3,080.00)							
				7	Jul 16, 2020	SYSTEM	(\$3,080.00)							
			- Total				(\$6,160.00)							
	Material - Total						(\$6,160.00)							
		MatarialCradit		7	Jul 46	CVCTEM								
	24 IN. PIPE GROUP B	B MaterialCredit		8	Jul 16, 2020 Aug 3,	SYSTEM	\$3,080.00 \$3,080.00							
			- Total	0	2020	STSTEW	\$6,160.00							
	MaterialCredit - Total						\$6,160.00							
	24 IN. PIPE GROUP B	Other Item Adjustment	MDPA	6	Jul 1, 2020	schmij8	\$210.00	AWP is looking for a QC culvert performance test. I have informed the contractors that we are requesting pipes at LM 3.618 and 4.372 be tested. I am holding pay for the installed pipe at 3.618 until the test is performed and paying for the 3' pipe extension RT@ 3.167.						
				8	Aug 3, 2020	schmij8	(\$210.00)	QC Culvert Performance tests have been done. I am taking back the \$210 adjustment that paid for a 3' extension.						
			MDPA - Tota	al			\$0.00							
	Other Item Adjustment	- Total					\$0.00							
1220 -							\$0.00							
1230	30 IN. PIPE GROUP B	Material		6	Jul 1, 2020	SYSTEM	(\$800.00)							
										6	Jul 1, 2020	SYSTEM	\$800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schmij8 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$800.00)							
				7	Jul 16, 2020	SYSTEM	\$800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0049) due to user schmij8 overridding Payment Estimate Exception 17 on the current Payment Estimate.						
			- Total				\$0.00							
	Material - Total						\$0.00							
1230	Total						\$0.00							
1240	15 IN. PIPE GROUP C	Material		6	Jul 1, 2020	SYSTEM	(\$4,280.00)							
				6	Jul 1, 2020	SYSTEM	\$4,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user schmij8 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
				7	Jul 16, 2020	SYSTEM	(\$22,480.00)	·						
				7	Jul 16, 2020	SYSTEM	\$22,480.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0050) due to user schmij8 overridding Payment Estimate Exception 18 on the current Payment Estimate.						

Revision 4/1/2020 Page 20 of 25



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1240		Material	- Total				\$0.00	
	Material - Total						\$0.00	
1240 -	Total						\$0.00	
1250	18 IN. PIPE GROUP C	Material		7	Jul 16,	SYSTEM	(\$1,800.00)	
				7	Jul 16, 2020	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0051) due to user schmij8 overridding Payment Estimate Exception
					2020			19 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1250 -	Total						\$0.00	
1300	ROCK DITCH CHECK	Material		8	Aug 3, 2020	SYSTEM	(\$4,916.25)	
				8	Aug 3, 2020	SYSTEM	\$4,916.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user schmij8 overridding Payment Estimate Exception 24 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	ROCK DITCH CHECK	Overrun	Overrun	9	Aug 17, 2020	SYSTEM	(\$1,395.00)	
				10	Sep 2, 2020	SYSTEM	\$1,395.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',11.25000 - 11.25000, 'is applied (if non-zero).
			Overrun - To	otal			\$0.00	
	Overrun - Total						\$0.00	
1300 -	Total						\$0.00	
1330	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material		9	Aug 17, 2020	SYSTEM	(\$12,600.00)	
			- Total				(\$12,600.00)	
	Material - Total						(\$12,600.00)	
	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	MaterialCredit		10	Sep 2, 2020	SYSTEM	\$12,600.00	
			- Total				\$12,600.00	
	MaterialCredit - Total						\$12,600.00	
1330 -	Total						\$0.00	
1340	MGS BRIDGE APPROACH	Construction Stockpile		1	Apr 1, 2020	SYSTEM	\$12,272.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	TRANSITION SECTION (EXTENDED CURB)			9	Aug 17, 2020	SYSTEM	(\$3,068.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$9,204.00	
	Construction Stockpile	- Total					\$9,204.00	
1340 -	Total						\$9,204.00	
1400	CURB BLOCKOUT	Material		8	Aug 3, 2020	SYSTEM	(\$34,694.00)	
				9	Aug 17, 2020	SYSTEM	(\$69,388.00)	
				10	Sep 2, 2020	SYSTEM	(\$69,388.00)	
				11	Sep 16, 2020	SYSTEM	(\$69,388.00)	
			- Total				(\$242,858.00)	
	Material - Total						(\$242,858.00)	
	CURB BLOCKOUT	MaterialCredit		9	Aug 17, 2020	SYSTEM	\$34,694.00	
				10	Sep 2, 2020	SYSTEM	\$69,388.00	
				11	Sep 16, 2020	SYSTEM	\$69,388.00	

Revision 4/1/2020 Page 21 of 25



Majorial Cuelly Total Total Majorial Cuelly Total Tota	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
CURS BLOCKOUT Maint Main	1400		MaterialCredit	- Total				\$173,470.00	
Modera M		MaterialCredit - Total							
MISC OFTICANA Cheer libra ACAD 11 Sep 16, Sec 17 Sec 27 Sec		CURB BLOCKOUT					schmij8		Paying 90%. Holding the rest until curbs are sealed.
Marcial Mode Mode				MDPA - Tota	al				
MINSCORTIONAL Once tem ACAD 10 Sep 10 2000 2	4400		- Total						
SHOULDER Adjustment Total CACA - Total CES - TREE CES - TR			Oth on Itom	ACAD	44	Con 16	o o b maii O		See A.C. Adjustment for Fatimete 0044
Character Converge Converge	1470						Scriinijo		See AC Aujusunent for Estimate 0011.
CALAS B.1 CALA		Other Item Adjustment	- Total	AOAD TOL					
10	1470 -								
Material - Total	1650	CONCRETE	Material		10		SYSTEM		
CAUSS B.T. COUNCETTE (CULVERTS)				- Total				(\$39,800.00)	
CONCRETE (CULVENTS) - Total S39,800.00		Material - Total						(\$39,800.00)	
Material Cridit - Total CLASS Bal Other Item		CONCRETE	MaterialCredit		11		SYSTEM	\$39,800.00	
CLASS p. Adjustment COUNCRETE COUNCRETE COUNCRETE Adjustment Adjustment Sep 16, schmij8 \$36,000.00 Pulying for precade box curient sections at LM 0.25 RT, 1.286 RT&1. The 2 CV for notice are being held until correct CRE20 reports are submitted. 11				- Total				\$39,800.00	
CONCRETE Adjustment (CULVERTS) Adjustment (CULVERTS)		MaterialCredit - Total						\$39,800.00	
MOPA - Total So.00		CONCRETE		MDPA	10		schmij8	\$36,000.00	headwall and pipe collar concrete are being held until correct CRE2O reports are
Naterial - Total Suppose					11		schmij8	(\$36,000.00)	Materials exceptions have been satisfied. Taking back previous pay adjustments.
1860 Total 1860 REINFORCING STEEL (CULVERTS) Material 10 Sep 2, 2020 2				MDPA - Tota	al			\$0.00	
10			- Total					\$0.00	
CULVERTS	1650	· Total							
Part	1000 -							\$0.00	
2020 11 Sep 16, 2020 2		REINFORCING STEEL	Material			2020		(\$6,420.00)	
Curb Substitute Substitut		REINFORCING STEEL	Material		10	2020 Sep 2, 2020	SYSTEM	(\$6,420.00) \$6,420.00	Item Adjustment (0027) due to user schmij8 overridding Payment Estimate Exception
Material - Total So.00		REINFORCING STEEL	Material		10	2020 Sep 2, 2020 Sep 16,	SYSTEM	(\$6,420.00) \$6,420.00	Item Adjustment (0027) due to user schmij8 overridding Payment Estimate Exception
1700 ROCK DITCH CHECK Material 11 Sep 16, 2020 20		REINFORCING STEEL	Material		10	2020 Sep 2, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM	(\$6,420.00) \$6,420.00 (\$13,760.00)	Item Adjustment (0027) due to user schmijß overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user schmijß overridding Payment Estimate Exception
ROCK DITCH CHECK		REINFORCING STEEL	Material	- Total	10	2020 Sep 2, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM	(\$6,420.00) \$6,420.00 (\$13,760.00) \$13,760.00	Item Adjustment (0027) due to user schmijß overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user schmijß overridding Payment Estimate Exception 13 on the current Payment Estimate.
2020		REINFORCING STEEL (CULVERTS)	Material	- Total	10	2020 Sep 2, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM	(\$6,420.00) \$6,420.00 (\$13,760.00) \$13,760.00	Item Adjustment (0027) due to user schmijß overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user schmijß overridding Payment Estimate Exception 13 on the current Payment Estimate.
2020 Item Adjustment (0022) due to user schmijß overridding Payment Estimate Exception 17 on the current Payment Estimate. Total	1660	REINFORCING STEEL (CULVERTS)	Material	- Total	10	2020 Sep 2, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM	(\$6,420.00) \$6,420.00 (\$13,760.00) \$13,760.00 \$0.00	Item Adjustment (0027) due to user schmijß overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user schmijß overridding Payment Estimate Exception 13 on the current Payment Estimate.
Material - Total	1660 -	REINFORCING STEEL (CULVERTS) Material - Total Total		- Total	11 11	2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM	(\$6,420.00) \$6,420.00 (\$13,760.00) \$13,760.00 \$0.00 \$0.00	Item Adjustment (0027) due to user schmijß overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user schmijß overridding Payment Estimate Exception 13 on the current Payment Estimate.
1700 - Total \$0.00	1660 -	REINFORCING STEEL (CULVERTS) Material - Total Total		- Total	10 11 11 11	2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM SYSTEM	(\$6,420.00) \$6,420.00 (\$13,760.00) \$13,760.00 \$0.00 \$0.00 (\$8,167.50)	Item Adjustment (0027) due to user schmij8 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user schmij8 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user schmij8 overridding Payment Estimate Exception
1790 CURB BLOCKOUT Material 10 Sep 2, 2020 SYSTEM (\$29,250.00)	1660 -	Material - Total ROCK DITCH CHECK			10 11 11 11	2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM SYSTEM	(\$6,420.00) \$6,420.00 (\$13,760.00) \$13,760.00 \$0.00 \$0.00 \$0.00 (\$8,167.50) \$8,167.50	Item Adjustment (0027) due to user schmij8 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user schmij8 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user schmij8 overridding Payment Estimate Exception
2020 11 Sep 16, 2020 (\$29,250.00)	1660 - 1700	Material - Total ROCK DITCH CHECK			10 11 11 11	2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM SYSTEM	(\$6,420.00) \$6,420.00 (\$13,760.00) \$13,760.00 \$0.00 \$0.00 \$8,167.50) \$8,167.50 \$0.00 \$0.00	Item Adjustment (0027) due to user schmij8 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user schmij8 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user schmij8 overridding Payment Estimate Exception
2020	1660 - 1660 - 1700 - 17	Material - Total ROCK DITCH CHECK Material - Total Total Total	Material		10 11 11 11 11	2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Sep 16, 2020 Sep 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$6,420.00) \$6,420.00 (\$13,760.00) \$13,760.00 \$0.00 \$0.00 (\$8,167.50) \$8,167.50 \$0.00 \$0.00 \$0.00	Item Adjustment (0027) due to user schmij8 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user schmij8 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user schmij8 overridding Payment Estimate Exception
Material - Total (\$58,500.00) CURB BLOCKOUT MaterialCredit 11 Sep 16, 2020 SYSTEM \$29,250.00	1660 - 1660 - 1700 - 17	Material - Total ROCK DITCH CHECK Material - Total Total Total	Material		10 11 11 11 11 11	2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Sep 16, 2020 Sep 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$6,420.00) \$6,420.00 (\$13,760.00) \$13,760.00 \$0.00 \$0.00 (\$8,167.50) \$8,167.50 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	Item Adjustment (0027) due to user schmij8 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user schmij8 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user schmij8 overridding Payment Estimate Exception
CURB BLOCKOUT MaterialCredit 11 Sep 16, 2020 \$YSTEM \$29,250.00	1660 - 1660 - 1700 - 17	Material - Total ROCK DITCH CHECK Material - Total Total Total	Material	- Total	10 11 11 11 11 11	2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Sep 16, 2020 Sep 16, 2020 Sep 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$6,420.00) \$6,420.00 (\$13,760.00) \$13,760.00 \$0.00 \$0.00 (\$8,167.50) \$8,167.50 \$0.00 \$0.00 (\$29,250.00)	Item Adjustment (0027) due to user schmij8 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user schmij8 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user schmij8 overridding Payment Estimate Exception
	1660 - 1660 - 1700 - 17	Material - Total Total ROCK DITCH CHECK Material - Total CURB BLOCKOUT	Material	- Total	10 11 11 11 11 11	2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Sep 16, 2020 Sep 16, 2020 Sep 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$6,420.00) \$6,420.00 (\$13,760.00) \$13,760.00 \$0.00 \$0.00 \$0.00 (\$8,167.50) \$8,167.50 \$0.00 \$0.00 \$0.00	Item Adjustment (0027) due to user schmij8 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user schmij8 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user schmij8 overridding Payment Estimate Exception
	1660 - 1660 - 1700 - 17	Material - Total Total ROCK DITCH CHECK Material - Total CURB BLOCKOUT	Material Material	- Total	10 11 11 11 11 10	2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Sep 16, 2020 Sep 16, 2020 Sep 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$6,420.00) \$6,420.00 (\$13,760.00) \$13,760.00 \$0.00 \$0.00 (\$8,167.50) \$8,167.50 \$0.00 \$0.00 (\$29,250.00) (\$58,500.00) (\$58,500.00)	Item Adjustment (0027) due to user schmij8 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user schmij8 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user schmij8 overridding Payment Estimate Exception

Revision 4/1/2020 Page 22 of 25



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
1790	MaterialCredit - Total						\$29,250.00		
	CURB BLOCKOUT	Other Item Adjustment	MDPA	10	Sep 2, 2020	schmij8	\$24,862.50	Paying 85%. Holding the rest until curbs are sealed and cracks are fixed	
			MDPA - Tota	al			\$24,862.50		
	Other Item Adjustment	- Total					\$24,862.50		
1790 -	- Total						(\$4,387.50)		
1860	MISC. OPTIONAL SHOULDER		ACAD		Sep 16, 2020	schmij8	(\$10,996.28)	See AC Adjustment for Estimate 0011.	
			ACAD - Tota	al			(\$10,996.28)		
	Other Item Adjustment	- Total					(\$10,996.28)		
	- Total			_		0) (0 = =)	(\$10,996.28)		
2020	CLASS B-1 CONCRETE (CULVERTS)	Material		7	Jul 16, 2020	SYSTEM	(\$200.00)		
				8	Aug 3, 2020	SYSTEM	(\$16,400.00)		
				9	Aug 17, 2020	SYSTEM	(\$34,800.00)		
				10	Sep 2, 2020	SYSTEM	(\$34,800.00)		
			- Total				(\$86,200.00)		
	Material - Total						(\$86,200.00)		
	CLASS B-1 CONCRETE	MaterialCredit		8	Aug 3, 2020	SYSTEM	\$200.00		
	(CULVERTS)			9	Aug 17, 2020	SYSTEM	\$16,400.00		
				10	Sep 2, 2020	SYSTEM	\$34,800.00		
				11	Sep 16, 2020	SYSTEM	\$34,800.00		
			- Total				\$86,200.00		
	MaterialCredit - Total						\$86,200.00		
	CLASS B-1 CONCRETE	Other Item Adjustment	MDPA	9	Aug 17, 2020	schmij8	\$34,600.00	Paying for the precast box culverts.	
	(CULVERTS)			11	Sep 16, 2020	schmij8	(\$34,600.00)	Materials exceptions have been satisfied. Taking back previous pay adjustments.	
			MDPA - Tota	al			\$0.00		
	Other Item Adjustment	- Total					\$0.00		
2020 -	- Total						\$0.00		
2030	REINFORCING STEEL (CULVERTS)	Material		8	Aug 3, 2020	SYSTEM	(\$3,200.00)		
				8	Aug 3, 2020	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user schmij8 overridding Payment Estimate Exception 19 on the current Payment Estimate.	
				9	Aug 17, 2020	SYSTEM	(\$7,000.00)		
					9	Aug 17, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user schmij8 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				10	Sep 2, 2020	SYSTEM	(\$7,000.00)		
				10	Sep 2, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user schmij8 overridding Payment Estimate Exception 30 on the current Payment Estimate.	
				11	Sep 16, 2020	SYSTEM	(\$7,000.00)		
				11	Sep 16, 2020	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user schmij8 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		

Revision 4/1/2020 Page 23 of 25



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
2050	PIPE LINER FOR	Material	Туре	8	Aug 3,	SYSTEM	(\$42,200.00)	
	EXISTING CULVERT			8	2020 Aug 3,	SYSTEM	\$42,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate
					2020	OTOTEM	Ψ42,200.00	Item Adjustment (0021) due to user schmij8 overridding Payment Estimate Exception 21 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
2050 -	Total						\$0.00	
2220	MISC. OPTIONAL SHOULDERS	Other Item Adjustment	ACAD	5	Jun 16, 2020	schmij8	(\$2,355.43)	See AC adjustment sheet attached with this estimate.
				6	Jul 1, 2020	schmij8	(\$2,741.50)	See attached AC adjustment sheet.
			ACAD - Tota	al			(\$5,096.93)	
	Other Item Adjustment	- Total					(\$5,096.93)	
2220 -	Total						(\$5,096.93)	
2230	TRUCK OR TRAILER MOUNTED	Material		10	Sep 2, 2020	SYSTEM	(\$3,000.00)	
	ATTENUATOR (TMA)			11	Sep 16, 2020	SYSTEM	(\$3,000.00)	
			- Total				(\$6,000.00)	
	Material - Total						(\$6,000.00)	
	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	MaterialCredit		11	Sep 16, 2020	SYSTEM	\$3,000.00	
			- Total				\$3,000.00	
	MaterialCredit - Total						\$3,000.00	
2230 -							(\$3,000.00)	
2350	18 IN. PIPE GROUP B	Material		2	May 4,	SYSTEM	(\$5,900.00)	
2330	10 IIV. FIFE GROOF B	Iviaterial		2	2020 May 4,	SYSTEM	\$5,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate
					2020		, ,,, , , , ,	Item Adjustment (0020) due to user schmij8 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
2350 -	Total						\$0.00	
2360	15 IN. PIPE GROUP C	Material		2	May 4, 2020	SYSTEM	(\$6,000.00)	
				2	May 4, 2020	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user schmij8 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
2360 -	Total						\$0.00	
2380	SEEDING - COOL SEASON MIXTURES	Material		8	Aug 3, 2020	SYSTEM	(\$10,320.00)	
				8	Aug 3, 2020	SYSTEM	\$10,320.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user schmij8 overridding Payment Estimate Exception 22 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
2380 -	· Total						\$0.00	
2410	ROCK DITCH CHECK	Overrun	Overrun	5	Jun 16, 2020	SYSTEM	(\$2,430.00)	
				7	Jul 16, 2020	SYSTEM	\$2,430.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',11.25000 - 11.25000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
2410 -	· Total						\$0.00	
2450	WOOD POST, 4 IN. BY 4 IN.	Overrun	Overrun	4	Jun 2, 2020	SYSTEM	(\$390.00)	

Revision 4/1/2020 Page 24 of 25



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2450	WOOD POST, 4 IN. BY 4 IN.	Overrun	Overrun	6	Jul 1, 2020	SYSTEM	(\$30.00)	
				7	Jul 16, 2020	SYSTEM	\$420.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is applied (if non-zero).
		Overrun - Total					\$0.00	
	Overrun - Total						\$0.00	
2450 -	- Total						\$0.00	
5001	ALTERNATE DITCH CHECK	Material		11	Sep 16, 2020	SYSTEM	(\$1,120.00)	
			- Total				(\$1,120.00)	
	Material - Total						(\$1,120.00)	
5001 -	· Total						(\$1,120.00)	
Overa	ıll - Total						(\$69,529.55)	

Revision 4/1/2020 Page 25 of 25