

# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 30, 2020

Progress Estim	Progress Estimate Number 5		191115-B01 W. L. Miller Company	Pay Period Start Pay Period End		Original Contract Amount Net Change Order Amount Current Contract Amount	\$4,970,996.71 \$0.00 \$4,970,996.71
Approval Date							By User
July 1, 2020			Generated and Approv	ed (and should be co	onsidered Draft)	at the Project Office Level by	vierss
July 1, 2020		Rev	riewed and Approved (a	and should be consid	ered Draft) at the	e Resident Engineer Level by	vierss
July 2, 2020			Review	ved and Approved at	the Central Office	ce Controllers Office Level by	greggd1
Original Comp	letion Date	% of Current Contract Amoun	nt Complete				
November	1, 2020	November	1, 2020			10.36%	

No Milestones Exist for Contract

Contract Total Pay For Estimate No. 5				
	This Estimate	Previous	To Date	
191115-B01				
Total Posted Items Pay	\$515,131.18	\$0.00	\$515,131.18	
Gross Item Adjustments	(\$73,857.92)	\$157,622.32	\$83,764.40	
Incentive	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Liquidated Damage	\$0.00	\$0.00	\$0.00	
Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
		<b>\$157,622.32</b>	\$598,895.58	
Contract Total Payable This Estimate:	\$441,273.26			

# Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J2S3288	0400	4091048	EMULSIFIED ASPHALT, SEAL COAT	GAL	\$2.400	25,544	\$61,305.60
	0410	4094012	SEAL COAT AGGREGATE, GRADE B2	SQYD	\$0.600	104,001	\$62,400.60
	0420	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	EA	\$500.000	2	\$1,000.00
	0430	6161005	CONSTRUCTION SIGNS	SQFT	\$6.000	670.76	\$4,024.56
	0440	6161009	FLAG ASSEMBLY	EA	\$20.000	8	\$160.00
	0460	6181000	MOBILIZATION	LS	\$4,500.000	1	\$4,500.00
	0470	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.110	74,418	\$8,185.98
	0480	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.110	53,514	\$5,886.54
Project J2	S3288 - Tot	tal					\$147,463.28
J2S3298	0490	4091048	EMULSIFIED ASPHALT, SEAL COAT	GAL	\$2.400	8,438	\$20,251.20
	0500	4094012	SEAL COAT AGGREGATE, GRADE B2	SQYD	\$0.600	30,136	\$18,081.60
	0510	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	EA	\$500.000	2	\$1,000.00
	0520	6161005	CONSTRUCTION SIGNS	SQFT	\$6.000	433.76	\$2,602.56
	0530	6161009	FLAG ASSEMBLY	EA	\$20.000	4	\$80.00
	0550	6181000	MOBILIZATION	LS	\$11,800.000	1	\$11,800.00
	0560	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.110	18,096	\$1,990.56
	0570	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.110	9,358	\$1,029.38
Project J2	S3298 - Tot	tal					\$56,835.30
J2S3299	0580	4091048	EMULSIFIED ASPHALT, SEAL COAT	GAL	\$2.400	66,890	\$160,536.00
	0590	4094012	SEAL COAT AGGREGATE, GRADE B2	SQYD	\$0.600	231,506	\$138,903.60
	0610	6161005	CONSTRUCTION SIGNS	SQFT	\$6.000	384.5	\$2,307.00
	0620	6161009	FLAG ASSEMBLY	EA	\$20.000	8	\$160.00
	0640	6181000	MOBILIZATION	LS	\$35,704.000	0.25	\$8,926.00
Project J2	S3299 - Tot	tal					\$310,832.60
Overall - T	otal						\$515,131.18

Revision 4/1/2020 Page 1 of 12



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 30, 2020

Progress Estimate Number
5

Contract ID 191115-B01 Pay Period Start June 16, 2020 Original Contract Amount S4,970,996.71
Pay Period End June 30, 2020 Current Contract Amount Current Contract Amount S4,970,996.71

### Contract Adjustments This Estimate

		ments This Estimate			_			
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J2S3288	0400	EMULSIFIED ASPHALT, SEAL COAT	Material			-25,544	\$2.40	(\$61,305.60)
	0400	EMULSIFIED ASPHALT, SEAL COAT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.	25,544	\$2.40	\$61,305.60
	0400	EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	Asphalt Cement Price Adjustment				(\$5,123.04)
	0410	SEAL COAT AGGREGATE, GRADE B2	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$15,254.37)
	0410	SEAL COAT AGGREGATE, GRADE B2	Material			-104,001	\$0.60	(\$62,400.60)
	0410	SEAL COAT AGGREGATE, GRADE B2	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 22 on the current Payment Estimate.	104,001	\$0.60	\$62,400.60
	0470	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-74,418	\$0.11	(\$8,185.98)
	0470	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 27 on the current Payment Estimate.	74,418	\$0.11	\$8,185.98
	0480	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-53,514	\$0.11	(\$5,886.54)
	0480	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 29 on the current Payment Estimate.	53,514	\$0.11	\$5,886.54
J2S3298	0490	EMULSIFIED ASPHALT, SEAL COAT	Material			-8,438	\$2.40	(\$20,251.20)
	0490	EMULSIFIED ASPHALT, SEAL COAT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 15 on the current Payment Estimate.	8,438	\$2.40	\$20,251.20
	0490	EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment					(\$1,692.30)
	0500	SEAL COAT AGGREGATE, GRADE B2	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$4,423.42)
	0500	SEAL COAT AGGREGATE, GRADE B2	Material			-30,136	\$0.60	(\$18,081.60)
	0500	SEAL COAT AGGREGATE, GRADE B2	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0013) due to user buckj	30,136	\$0.60	\$18,081.60

Revision 4/1/2020 Page 2 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 30, 2020

Progress Estimate Number	Contract ID	191115-B01			9	\$4,970,996.71
5	Prime Contractor	W. L. Miller Company	Pay Period End	June 30, 2020	Net Change Order Amount	\$0.00
3					<b>Current Contract Amount</b>	\$4,970,996.71

					Guilei	i Contract A	-	+,910,990.11
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J2S3298					overridding Payment Estimate Exception 23 on the current Payment Estimate.			
	0560	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-18,096	\$0.11	(\$1,990.56)
	0560	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 25 on the current Payment Estimate.	18,096	\$0.11	\$1,990.56
	0570	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-9,358	\$0.11	(\$1,029.38)
	0570	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 31 on the current Payment Estimate.	9,358	\$0.11	\$1,029.38
J2S3299	0580	EMULSIFIED ASPHALT, SEAL COAT	Material			-66,890	\$2.40	(\$160,536.00)
	0580	EMULSIFIED ASPHALT, SEAL COAT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 8 on the current Payment Estimate.	66,890	\$2.40	\$160,536.00
	0580	EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	Asphalt Cement Price Adjustment				(\$13,415.29)
	0590	SEAL COAT AGGREGATE, GRADE B2	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$33,949.50)
	0590	SEAL COAT AGGREGATE, GRADE B2	Material			-231,506	\$0.60	(\$138,903.60)
	0590	SEAL COAT AGGREGATE, GRADE B2	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 24 on the current Payment Estimate.	231,506	\$0.60	\$138,903.60
Total								(\$73,857.92)

Revision 4/1/2020 Page 3 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information	1						
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work						
J2P3246	FAF 6-2(52)	Resurface	6	ADAIR	from 0.2 mile east of Rou	ute 63 to Route 15 south jur	nction in Knox County near Edina						
J2P3292	FAF-6-2(54)	Seal coat	6	ADAIR	from east of Route 149 a	at the Chariton River to Bus.	. 63 in Kirksville						
J2S3288	FAS- S201(082)	Seal coat	3	ADAIR	from east Route 11 in Ac	n east Route 11 in Adair County to Route 156 in Macon County near Cardy							
J2S3298	FAS- S201(084)	Seal coat	Н	ADAIR	from La Harpe Street to	Route 11 in Kirksville							
2S3299	FAS S201(64)	Seal coat	11	ADAIR	from Rte. 15 near Baring	to Rte. 129 in Linn County	(two disconnected sections)						
283343	FAS- S201(085)	Seal coat	Р	ADAIR	from Bus. 63 to Route 63	3 in Kirksville							
otals by	Job Numbers												
2P3246	Posted I	em Adjustmen	ts <mark>Gross Ite</mark>	em Pay	This Estimate \$0.00 \$0.00 <b>\$0.00</b>	Previous \$0.00 \$40,909.50 \$40,909.50	To Date \$0.00 \$40,909.50 \$40,909.50						
			nents		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00						
J2P3292	Posted I	em Adjustmen	ts Gross Ite	em Pay	This Estimate \$0.00 \$0.00 <b>\$0.00</b>	Previous \$0.00 \$18,615.69 \$18,615.69	To Date \$0.00 \$18,615.69 \$18,615.69						
			ments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00						
J2S3288	Posted I	em Adjustmen	ts Gross Ite	em Pay	This Estimate \$147,463.28 (\$20,377.41) \$127,085.87	Previous \$0.00 \$15,254.37 \$15,254.37	To Date \$147,463.28 (\$5,123.04) \$142,340.24						
			nents		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00						
J2S3298	Posted I	em Adjustmen	ts Gross Ite	em Pay	This Estimate \$56,835.30 (\$6,115.72) \$50,719.58	<b>Previous</b> \$0.00 \$4,423.42 <b>\$4,423.42</b>	To Date \$56,835.30 (\$1,692.30) \$55,143.00						
			nents		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00						
J2S3299		tem Pay em Adjustmen	ts <mark>Gross It</mark> e	em Pay	This Estimate \$310,832.60 (\$47,364.79) \$263,467.81	Previous \$0.00 \$75,968.37 \$75,968.37	To Date \$310,832.60 \$28,603.58 \$339,436.18						
Incentive Disincentive Liquidated Damages Other Contract Adjustments					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00						
J2S3343	Posted I	em Adjustmen	ts Gross Ite	em Pay	This Estimate \$0.00 \$0.00 <b>\$0.00</b>	Previous \$0.00 \$2,450.97 \$2,450.97	To Date \$0.00 \$2,450.97 \$2,450.97						
			mant-		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00						

Revision 4/1/2020 Page 4 of 12



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

**Exceptions (Discrepancies) This Estimate Period** 

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J2S3288, Item 4091048, Project Item Line Number 0400, Material Set 409104896, Material 1015EACRS1 - Emulsified Asphalt CRS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3288, Item 4091048, Project Item Line Number 0400, Material Set 409104896, Material 1015EACRS2 - Emulsified Asphalt CRS-2, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3288, Item 4091048, Project Item Line Number 0400, Material Set 409104896, Material 1015EACRS2P - Emulsified Asphalt CRS-2P, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3288, Item 4091048, Project Item Line Number 0400, Material Set 409104896, Material 1015EAEA150 - Emulsified Asphalt EA-150, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3288, Item 4091048, Project Item Line Number 0400, Material Set 409104896, Material 1015EAEA300 - Emulsified Asphalt EA-300, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3288, Item 4091048, Project Item Line Number 0400, Material Set 409104896, Material 1015EAEA90P - Emulsified Asphalt EA-90P, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3288, Item 4091048, Project Item Line Number 0400, Material Set 409104896, Material 1015EARS1 - Emulsified Asphalt RS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3299, Item 4091048, Project Item Line Number 0580, Material Set 409104896, Material 1015EACRS1 - Emulsified Asphalt CRS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3299, Item 4091048, Project Item Line Number 0580, Material Set 409104896, Material 1015EACRS2 - Emulsified Asphalt CRS-2, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3299, Item 4091048, Project Item Line Number 0580, Material Set 409104896, Material 1015EACRS2P - Emulsified Asphalt CRS-2P, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3299, Item 4091048, Project Item Line Number 0580, Material Set 409104896, Material 1015EAEA150 - Emulsified Asphalt EA-150, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3299, Item 4091048, Project Item Line Number 0580, Material Set 409104896, Material 1015EAEA300 - Emulsified Asphalt EA-300, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3299, Item 4091048, Project Item Line Number 0580, Material Set 409104896, Material 1015EAEA90P - Emulsified Asphalt EA-90P, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3299, Item 4091048, Project Item Line Number 0580, Material Set 409104896, Material 1015EARS1 - Emulsified Asphalt RS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3298, Item 4091048, Project Item Line Number 0490, Material Set 409104896, Material 1015EACRS1 - Emulsified Asphalt CRS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3298, Item 4091048, Project Item Line Number 0490, Material Set 409104896, Material 1015EACRS2 - Emulsified Asphalt CRS-2, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3298, Item 4091048, Project Item Line Number 0490, Material Set 409104896, Material 1015EACRS2P - Emulsified Asphalt CRS-2P, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3298, Item 4091048, Project Item Line Number 0490, Material Set 409104896, Material 1015EAEA150 - Emulsified Asphalt EA-150, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3298, Item 4091048, Project Item Line Number 0490, Material Set 409104896, Material 1015EAEA300 - Emulsified Asphalt EA-300, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3298, Item 4091048, Project Item Line Number 0490, Material Set 409104896, Material 1015EAEA90P - Emulsified Asphalt EA-90P, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3298, Item 4091048, Project Item Line Number 0490, Material Set 409104896, Material 1015EARS1 - Emulsified Asphalt RS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3288, Item 4094012, Project Item Line Number 0410, Material Set 409401296, Material 1003GB2 - Aggregate for Seal Coat Grade B2, Acceptance Action Generic 1003GB2 is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3298, Item 4094012, Project Item Line Number 0500, Material Set 409401296, Material 1003GB2 - Aggregate for Seal Coat Grade B2, Acceptance Action Generic 1003GB2 is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3299, Item 4094012, Project Item Line Number 0590, Material Set 409401296, Material 1003GB2 - Aggregate for Seal Coat Grade B2, Acceptance Action	No Remark was entered by Engineer	buckj	Overridden

Revision 4/1/2020 Page 5 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

**Exceptions (Discrepancies) This Estimate Period** 

Exceptions / Discrepencies	Explanation	Entered By	Status
Generic 1003GB2 is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J2S3298, Item 6206000C, Project Item Line Number 0560, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3298, Item 6206000C, Project Item Line Number 0560, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3288, Item 6206000C, Project Item Line Number 0470, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3288, Item 6206000C, Project Item Line Number 0470, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3288, Item 6206001C, Project Item Line Number 0480, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3288, Item 6206001C, Project Item Line Number 0480, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3298, Item 6206001C, Project Item Line Number 0570, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	No Remark was entered by Engineer	buckj	Overridden
Estimate Exception Type: Insufficient Materials: Project J2S3298, Item 6206001C, Project Item Line Number 0570, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	buckj	Overridden

Revision 4/1/2020 Page 6 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ct Project RACT No.	Category	Line No.	Item Code	Poort Generated date and can differ from the posted amo	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
1 J2P3246	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$6,000.00	\$0.00
	0001	0020	2072000	LINEAR GRADING CLASS 2	1,997.30	0.00	1,997.30	STA	0.00	\$110.50	\$0.00
	0001	0030	2153000	SHAPING SLOPES, CLASS III	24.00	0.00	24.00	100F	0.00	\$1,200.00	\$0.00
	0001	0040	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	10,909.20	0.00	10,909.20	TONS	0.00	\$23.96	\$0.00
	0001	0050	3105002	GRAVEL (A) OR CRUSHED STONE (B)	322.00	0.00	322.00	TONS	0.00	\$28.50	\$0.00
	0001	0060	4011208	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-2)	36,249.60	0.00	36,249.60	TONS	0.00	\$55.50	\$0.00
	0001	0070	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	11,054.10	0.00	11,054.10	TONS	0.00	\$55.50	\$0.00
	0001	0080	4071005	TACK COAT	26,753.85	0.00	26,753.85	GAL	0.00	\$2.25	\$0.00
	0001	0090	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	0.00	4.00	EA	0.00	\$500.00	\$0.00
	0001	0100	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	64.50	0.00	64.50	TONS	0.00	\$125.00	\$0.00
	0001	0110	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	600.00	0.00	600.00	SQYD	0.00	\$5.00	\$0.00
	0001	0120	6161005	CONSTRUCTION SIGNS	2,458.00	0.00	2,458.00	SQFT	0.00	\$6.00	\$0.00
	0001	0130	6161009	FLAG ASSEMBLY	10.00	0.00	10.00	EA	0.00	\$20.00	\$0.00
	0001	0140	6161025	CHANNELIZER (TRIM LINE)	770.00	0.00	770.00	EA	0.00	\$20.00	\$0.00
	0001	0150	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	0.00	\$2,500.00	\$0.00
	0001	0160	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	0.00	\$1,500.00	\$0.00
	0001	0170	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$176,000.00	\$0.00
	0001	0180	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	93,249.00	0.00	93,249.00	LF	0.00	\$0.16	\$0.00
	0001	0190	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	198,413.00	0.00	198,413.00	LF	0.00	\$0.11	\$0.00
	0001	0200	6209901	MISC.OPTIONAL TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$0.00	\$0.00
		0210	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	4,870.00	0.00	4,870.00	SQYD	0.00	\$9.50	\$0.00
	0001	0220	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	2,790.30	0.00	2,790.30	STA	0.00	\$10.50	\$0.00
	0001	0230	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	1,010.50	0.00	1,010.50	STA	0.00	\$10.50	\$0.00
	0010	0240	6061060	MGS GUARDRAIL	450.00	0.00	450.00	LF	0.00	\$23.00	\$0.00
	0010	0250	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	12.00	0.00	12.00	EA	0.00	\$3,000.00	\$0.00
	0010	0260	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	12.00	0.00	12.00	EA	0.00	\$2,900.00	\$0.00
	2P3246 - To			ate as of Report Generated Date							\$0.00
J2P3292	0001	0270	4091048	EMULSIFIED ASPHALT, SEAL COAT	35,550.00	0.00	35,550.00	GAL	0.00	\$2.40	\$0.00
	0001	0280	4094002 6123000A	SEAL COAT AGGREGATE, GRADE A2  TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	126,965.00	0.00	126,965.00	SQYD	0.00	\$0.93 \$500.00	\$0.00 \$0.00
	0001	0300	6161005	CONSTRUCTION SIGNS	1,200.00	0.00	1,200.00	SQFT	0.00	\$6.00	\$0.00
	0001	0310	6161009	FLAG ASSEMBLY	8.00	0.00	8.00	EA	0.00	\$20.00	\$0.00
	0001	0320	6161025	CHANNELIZER (TRIM LINE)	240.00	0.00	240.00	EA	0.00	\$20.00	\$0.00
	0001	0330	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$13,450.00	\$0.00
	0001	0340	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	48.00	0.00	48.00	LF	0.00	\$25.00	\$0.00
	0001	0350	6200018	WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	130.00	0.00	130.00	LF	0.00	\$25.00	\$0.00
	0001	0360	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	4.00	0.00	4.00	EA	0.00	\$300.00	\$0.00
	0001	0370	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	28,161.00	0.00	28,161.00	LF	0.00	\$0.16	\$0.00
	0001	0380	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	62,188.00	0.00	62,188.00	LF	0.00	\$0.20	\$0.00
	0001	0390	6209902	MISC.PREFORMED THERMOPLASTIC PAVEMENT MARKING - BICYCLE SYMBOL	12.00	0.00	12.00	EA	0.00	\$400.00	\$0.00
Project J J2S3288	2P3292 - To	0400	4091048	late as of Report Generated Date  EMULSIFIED ASPHALT, SEAL COAT	29,120.00	0.00	29,120.00	GAL	25,544.00	\$2.40	\$0.00 \$61,305.60
5230200	0001	0410	4094012	SEAL COAT AGGREGATE, GRADE B2	104,001.00	0.00	104,001.00	SQYD	104,001.00	\$0.60	\$62,400.60
		0410	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
	0001	0720	3120000A	THOSE OF THE VIELEN MODIFIED ATTENDATOR (TWA)	2.00	0.00	2.00	LA	2.00	ψυυυ.υυ	φ1,000.00

Page 7 of 12 Revision 4/1/2020



### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted C	Quantities a	and Value	es are b	ased on R	eport Generated date and can differ from the post	ted amount at the t	ime the	Estimate wa	s Gener	ated.		
Contract	Project	Category	Line	Item	Description	Bid	Net	Total	Unit	Total	Unit Price	Total Value POSTED

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191115-B01	J2S3288	0001	0430	6161005	CONSTRUCTION SIGNS	1,294.00	0.00	1,294.00	SQFT	670.76	\$6.00	\$4,024.56
		0001	0440	6161009	FLAG ASSEMBLY	8.00	0.00	8.00	EA	8.00	\$20.00	\$160.00
		0001	0450	6161025	CHANNELIZER (TRIM LINE)	285.00	0.00	285.00	EA	0.00	\$20.00	\$0.00
		0001	0460	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$4,500.00	\$4,500.00
		0001	0470	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	93,023.00	0.00	93,023.00	LF	74,418.00	\$0.11	\$8,185.98
		0001	0480	6206001C	4 IN, YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	66,892.00	0.00	66,892.00	LF	53,514.00	\$0.11	\$5,886.54
	Project J	2S3288 - To	tal Value	Posted to D	ate as of Report Generated Date							\$147,463.28
	J2S3298	0001	0490	4091048	EMULSIFIED ASPHALT, SEAL COAT	8,438.00	0.00	8,438.00	GAL	8,438.00	\$2.40	\$20,251.20
		0001	0500	4094012	SEAL COAT AGGREGATE, GRADE B2	30,136.00	0.00	30,136.00	SQYD	30,136.00	\$0.60	\$18,081.60
		0001	0510	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0520	6161005	CONSTRUCTION SIGNS	804.00	0.00	804.00	SQFT	433.76	\$6.00	\$2,602.56
		0001	0530	6161009	FLAG ASSEMBLY	8.00	0.00	8.00	EA	4.00	\$20.00	\$80.00
		0001	0540	6161025	CHANNELIZER (TRIM LINE)	150.00	0.00	150.00	EA	0.00	\$20.00	\$0.00
		0001	0550	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$11,800.00	\$11,800.00
		0001	0560	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	22,620.00	0.00	22,620.00	LF	18,096.00	\$0.11	\$1,990.56
		0001	0570	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	11,697.00	0.00	11,697.00	LF	9,358.00	\$0.11	\$1,029.38
	Project J	2S3298 - To	tal Value	Posted to D	ate as of Report Generated Date							\$56,835.30
	J2S3299	0001	0580	4091048	EMULSIFIED ASPHALT, SEAL COAT	145,051.00	0.00	145,051.00	GAL	66,890.00	\$2.40	\$160,536.00
		0001	0590	4094012	SEAL COAT AGGREGATE, GRADE B2	518,038.00	0.00	518,038.00	SQYD	231,506.00	\$0.60	\$138,903.60
		0001	0600	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.00
		0001	0610	6161005	CONSTRUCTION SIGNS	2,554.00	0.00	2,554.00	SQFT	384.50	\$6.00	\$2,307.00
		0001	0620	6161009	FLAG ASSEMBLY	8.00	0.00	8.00	EA	8.00	\$20.00	\$160.00
		0001	0630	6161025	CHANNELIZER (TRIM LINE)	240.00	0.00	240.00	EA	0.00	\$20.00	\$0.00
		0001	0640	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.25	\$35,704.00	\$8,926.00
		0001	0650	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	435,853.00	0.00	435,853.00	LF	0.00	\$0.10	\$0.00
		0001	0660	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	350,615.00	0.00	350,615.00	LF	0.00	\$0.10	\$0.00
	Project J	2S3299 - To	tal Value	Posted to D	ate as of Report Generated Date							\$310,832.60
	J2S3343	0001	0670	4091048	EMULSIFIED ASPHALT, SEAL COAT	4,700.00	0.00	4,700.00	GAL	0.00	\$2.40	\$0.00
		0001	0680	4094012	SEAL COAT AGGREGATE, GRADE B2	16,784.00	0.00	16,784.00	SQYD	0.00	\$0.60	\$0.00
		0001	0690	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.00
		0001	0700	6161005	CONSTRUCTION SIGNS	991.00	0.00	991.00	SQFT	0.00	\$6.00	\$0.00
		0001	0710	6161009	FLAG ASSEMBLY	8.00	0.00	8.00	EA	0.00	\$20.00	\$0.00
		0001	0720	6161025	CHANNELIZER (TRIM LINE)	280.00	0.00	280.00	EA	0.00	\$20.00	\$0.00
		0001	0730	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$4,500.00	\$0.00
		0001	0740	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	11,658.00	0.00	11,658.00	LF	0.00	\$0.11	\$0.00
		0001	0750	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	10,804.00	0.00	10,804.00	LF	0.00	\$0.11	\$0.00
	Project J	2S3343 - To	tal Value	Posted to D	ate as of Report Generated Date							\$0.00
191115-B01 Ove	rall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$515,131.18

Revision 4/1/2020 Page 8 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J2S3288

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location From Statio Log Mile	on/ Dist	tance St		Offset/ istance	Comments
0400	4091048	EMULSIFIED ASPHALT, SEAL COAT	6/17/20	6/22/20	7,166.00	GAL	0.0	.00		2.836		
		6/18/20	6/22/20	16,508.00	GAL	2.83	36		8.809			
			6/23/20	6/24/20	1,870.00	GAL	2.83	36		3.885		
0410	4094012	SEAL COAT AGGREGATE, GRADE B2	6/17/20	6/22/20	33,278.00	SQYD	0.0	.00		2.836		
			6/18/20	6/22/20	63,928.00	SQYD	2.83	36		8.809		
			6/23/20	6/24/20	6,795.00	SQYD	2.83	36		3.885		
0420	0420 6123000A TF	TRUCK OR TRAILER MOUNTED ATTEN (TMA)	6/29/20	6/30/20	2.00	EA	0.0	.00		8.809		
				6/30/20		EA	0.0	.00		8.809		
0430	6161005	CONSTRUCTION SIGNS	6/17/20	6/22/20	391.50	SQFT	0.0	.00		2.836		
			6/18/20	6/22/20	238.50	SQFT	2.83	36		8.809		
			6/29/20	6/30/20	40.76	SQFT	0.0	.00		8.809		
0440	6161009	FLAG ASSEMBLY	6/17/20	6/22/20	8.00	EA	0.0	.00		2.836		
0460	6181000	MOBILIZATION	6/17/20	6/22/20	1.00	LS	0.0	.00		2.836		
0470	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	6/29/20	6/30/20	74,418.00	LF	0.0	.00		8.809		
0480	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	6/29/20	6/30/20	53,514.00	LF	0.0	.00		8.809		

Project: J2S3298

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0490	4091048	EMULSIFIED ASPHALT, SEAL COAT	6/17/20	6/22/20	8,438.00	GAL		0.00		2.836		
0500	4094012	SEAL COAT AGGREGATE, GRADE B2	6/17/20	6/22/20	30,136.00	SQYD		0.00		2.305		
0510	6123000A	TRUCK OR TRAILER MOUNTED ATTEN (TMA)	6/29/20	6/30/20	2.00	EA		0.00		2.305		
0520	6161005	CONSTRUCTION SIGNS	6/17/20	6/22/20	393.00	SQFT		0.00		2.305		
			6/29/20	6/30/20	40.76	SQFT		0.00		2.305		
0530	6161009	FLAG ASSEMBLY	6/17/20	6/22/20	-4.00	EA		0.00		2.3.05		
				6/22/20	8.00	EA		0.00		2.836		
0550	6181000	MOBILIZATION	6/17/20	6/22/20	1.00	LS		0.00		2.305		
0560	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	6/29/20	6/30/20	18,096.00	LF		0.00		2.305		
0570	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	6/29/20	6/30/20	9,358.00	LF		0.00		2.305		

### Project: J2S3299

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0580	4091048	EMULSIFIED ASPHALT, SEAL COAT	6/24/20	6/26/20	20,550.00	GAL		39.627		46.116		
			6/25/20	6/30/20	16,985.00	GAL		35.125		40.513		
			6/26/20	6/29/20	9,320.00	GAL		32.609		35.567		
			6/29/20	6/30/20	20,035.00	GAL		26.842		32.609		
0590	4094012	SEAL COAT AGGREGATE, GRADE B2	6/24/20	6/26/20	70,940.00	SQYD		39.627		46.116		
			6/25/20	6/30/20	55,797.00	SQYD		35.125		40.513		
			6/26/20	6/29/20	33,719.00	SQYD		32.609		35.567		
			6/29/20	6/30/20	71,050.00	SQYD		26.842		32.609		
0610	6161005	CONSTRUCTION SIGNS	6/24/20	6/26/20	272.50	SQFT		39.627		46.116		
			6/29/20	6/30/20	112.00	SQFT		26.842		32.609		
0620	6161009	FLAG ASSEMBLY	6/24/20	6/26/20	8.00	EA		39.627		46.116		
0640	6181000	MOBILIZATION	6/24/20	6/26/20	0.25	LS		39.627		46.116		

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 9 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
MGS GUARDRAIL	Construction Stockpile		1	Apr 13, 2020	SYSTEM	\$4,801.50	Payment Estimate Item Adjustment generated Stockpile Transaction	
		- Total				\$4,801.50		
Construction Stockpile - Total						\$4,801.50		
<u> </u>						· · · · · ·		
MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		1	Apr 13, 2020	SYSTEM	\$17,988.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
		- Total				\$17,988.00		
Construction Stockpile - Total						\$17,988.00		
Total						\$17,988.00		
TYPE A CRASHWORTHY END	Construction		1	Apr 13,	SYSTEM	\$18,120.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
				2020			, , , ,	
		- Total				\$18,120.00		
Construction Stockpile - Total						\$18,120.00		
Total						\$18,120.00		
SEAL COAT AGGREGATE,	Construction		2	May 19,	SYSTEM	\$18,615.69	Payment Estimate Item Adjustment generated Stockpile Transaction	
GRADE A2	Stockpile				2020		,	, , 3.00.000
		- Total				\$18,615.69		
Construction Stockpile - Total						\$18,615.69		
Total						\$18,615.69		
EMULSIFIED ASPHALT SEAL	Material		5	Jun 30	SYSTEM	(\$61,305,60)		
COAT	material			2020			This adjustment offsets the original system-generated Overrun Payment	
				2020	OTOTEM	ψο 1,000.00	Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate.	
		- Total				\$0.00		
Material - Total						\$0.00		
EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	ACAD	5	Jul 1, 2020	vierss	(\$5,123.04)		
		ACAD - Tota	al			(\$5,123.04)		
Other Item Adjustment - Total						(\$5,123.04)		
Total						(\$5,123.04)		
SEAL COAT AGGREGATE, GRADE B2	Construction Stockpile		2	May 19, 2020	SYSTEM	\$15,254.37	Payment Estimate Item Adjustment generated Stockpile Transaction	
			5	Jun 30, 2020	SYSTEM	(\$15,254.37)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		- Total				\$0.00		
Construction Stockpile - Total						\$0.00		
SEAL COAT AGGREGATE, GRADE B2	Material		5	Jun 30, 2020	SYSTEM	(\$62,400.60)		
			5	Jun 30, 2020	SYSTEM	\$62,400.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 22 on the current Payment Estimate.	
		- Total	5		SYSTEM	\$62,400.60 \$0.00	Estimate Item Adjustment (0002) due to user buckj overridding Payment	
Material - Total		- Total	5		SYSTEM		Estimate Item Adjustment (0002) due to user buckj overridding Payment	
		- Total	5		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0002) due to user buckj overridding Payment	
Total	Matorical	- Total		2020		\$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0002) due to user buckj overridding Payment	
Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material	- Total	5	Jun 30, 2020	SYSTEM	\$0.00 \$0.00 \$0.00 (\$8,185.98)	Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 22 on the current Payment Estimate.	
Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT	Material			2020 Jun 30,		\$0.00 \$0.00 \$0.00 (\$8,185.98) \$8,185.98	Estimate Item Adjustment (0002) due to user buckj overridding Payment	
Total  4 IN. WHITE STANDARD  WATERBORNE PAVEMENT  MARKING PAINT, TYPE P  BEADS	Material	- Total	5	Jun 30, 2020 Jun 30,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$8,185.98)	Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 22 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment	
Total  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		5	Jun 30, 2020 Jun 30,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$8,185.98) \$8,185.98	Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 22 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment	
Total  4 IN. WHITE STANDARD  WATERBORNE PAVEMENT  MARKING PAINT, TYPE P  BEADS	Material		5	Jun 30, 2020 Jun 30,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$8,185.98) \$8,185.98	Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 22 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment	
Total  4 IN. WHITE STANDARD  WATERBORNE PAVEMENT  MARKING PAINT, TYPE P  BEADS  Material - Total	Material Material		5	Jun 30, 2020 Jun 30,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$8,185.98) \$8,185.98 \$0.00	Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 22 on the current Payment Estimate.  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment	
	MGS GUARDRAIL  Construction Stockpile - Total Total  MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)  Construction Stockpile - Total Total  TYPE A CRASHWORTHY END TERMINAL (MASH)  Construction Stockpile - Total Total  SEAL COAT AGGREGATE, GRADE A2  Construction Stockpile - Total Total  EMULSIFIED ASPHALT, SEAL COAT  Other Item Adjustment - Total Total  SEAL COAT AGGREGATE, GRADE B2  Construction Stockpile - Total  COAT	MGS GUARDRAIL  Construction Stockpile - Total  Total  MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)  Construction Stockpile - Total  Total  TYPE A CRASHWORTHY END TERMINAL (MASH)  Construction Stockpile - Total  Total  SEAL COAT AGGREGATE, GRADE A2  Construction Stockpile - Total  Total  EMULSIFIED ASPHALT, SEAL COAT  Material - Total  EMULSIFIED ASPHALT, SEAL COAT  Other Item Adjustment - Total  Total  SEAL COAT AGGREGATE, COnstruction Stockpile  Construction Stockpile - Total  Total  EMULSIFIED ASPHALT, SEAL COAT  Other Item Adjustment  Other Item Adjustment - Total  Total  SEAL COAT AGGREGATE, Construction Stockpile  Construction Stockpile - Total  SEAL COAT AGGREGATE, Material	MGS GUARDRAIL  MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)  TOtal  Construction Stockpile - Total  Total  TOTAL  Construction Stockpile - Total  TOTAL  TYPE A CRASHWORTHY END TERMINAL (MASH)  SEAL COAT AGGREGATE, CANTUCTION Stockpile  TOTAL  Construction Stockpile - Total  Total  SEAL COAT AGGREGATE, COAT  COAT  Material - Total  EMULSIFIED ASPHALT, SEAL COAT  Material - Total  EMULSIFIED ASPHALT, SEAL COAT  Other Item Adjustment - Total  Total  SEAL COAT AGGREGATE, COAT  COAT  Other Item Adjustment  ACAD - Total  Construction Stockpile - Total  Total  EMULSIFIED ASPHALT, SEAL COAT  Other Item Adjustment - Total  Total  SEAL COAT AGGREGATE, GRADE B2  Formula in the properties of the propertie	MGS GUARDRAIL Construction Stockpile - Total  Construction Stockpile - Total  MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)  Total  Total  Construction Stockpile - Total  Total  TYPE A CRASHWORTHY END TERMINAL (MASH)  SEAL COAT AGGREGATE, COAT COAT  EMULSIFIED ASPHALT, SEAL COAT  EMULSIFIED ASPHALT, SEAL COAT  COAT  Material - Total  SEAL COAT AGGREGATE, GRADE B2  Construction Stockpile - Total  SEAL COAT AGGREGATE, GRADE B2  Construction Stockpile - Total  Construction Stockpile - Total  SEAL COAT AGGREGATE, GRADE B2  Material SEAL COAT AGGREGATE, GRADE B2	MGS GUARDRAIL   Construction Stockpile   Total	Type	MGS GUARDRAIL   Construction   Stockpile   Total   S4,801.50	

Revision 4/1/2020 Page 10 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0480		Material	- Total				\$0.00	
	Material - Total						\$0.00	
0480 -	Total						\$0.00	
0490	EMULSIFIED ASPHALT, SEAL COAT	Material		5	Jun 30, 2020	SYSTEM	(\$20,251.20)	
				5	Jun 30, 2020	SYSTEM	\$20,251.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	ACAD	5	Jul 1, 2020	vierss	(\$1,692.30)	
			ACAD - Tota	al			(\$1,692.30)	
	Other Item Adjustment - Total						(\$1,692.30)	
0490 -	Total						(\$1,692.30)	
0500	SEAL COAT AGGREGATE, GRADE B2	Construction Stockpile		2	May 19, 2020	SYSTEM	\$4,423.42	Payment Estimate Item Adjustment generated Stockpile Transaction
				5	Jun 30, 2020	SYSTEM	(\$4,423.42)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
	SEAL COAT AGGREGATE, GRADE B2	Material		5	Jun 30, 2020	SYSTEM	(\$18,081.60)	
				5	Jun 30, 2020	SYSTEM	\$18,081.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate.
			- Total				\$0.00	Estimate Exception 20 on the surrout ayment Estimate.
	Material Total		- I Otal					
	Material - Total						\$0.00	
0500 -				_		0)10==11	\$0.00	
0560	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		5	Jun 30, 2020	SYSTEM	(\$1,990.56)	
				5	Jun 30, 2020	SYSTEM	\$1,990.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 25 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0560 -	Total						\$0.00	
0570	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	Material		5	Jun 30, 2020	SYSTEM	(\$1,029.38)	
	MARKING PAINT, TYPE P BEADS			5	Jun 30, 2020	SYSTEM	\$1,029.38	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 31 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0570 -	Total						\$0.00	
0580	EMULSIFIED ASPHALT, SEAL COAT	Material		5	Jun 30, 2020	SYSTEM	(\$160,536.00)	
				5	Jun 30, 2020	SYSTEM	\$160,536.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	EMULSIFIED ASPHALT, SEAL COAT	Other Item Adjustment	ACAD	5	Jul 1, 2020	vierss	(\$13,415.29)	
			ACAD - Tota	al			(\$13,415.29)	
	Other Item Adjustment - Total						(\$13,415.29)	
0580 -	· · · · · · · · · · · · · · · · · · ·						(\$13,415.29)	
0590	SEAL COAT AGGREGATE, GRADE B2	Construction Stockpile		2	May 19, 2020	SYSTEM	\$75,968.37	Payment Estimate Item Adjustment generated Stockpile Transaction
		,		5	Jun 30,	SYSTEM	(\$33,949.50)	Payment Estimate Item Adjustment generated Stockpile Transaction

Revision 4/1/2020 Page 11 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0590	SEAL COAT AGGREGATE, GRADE B2	Construction Stockpile			2020			
			- Total				\$42,018.87	
	Construction Stockpile - Total						\$42,018.87	
	SEAL COAT AGGREGATE, GRADE B2	Material		5	Jun 30, 2020	SYSTEM	(\$138,903.60)	
				5	Jun 30, 2020	SYSTEM	\$138,903.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 24 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0590 -	· Total						\$42,018.87	
0680	SEAL COAT AGGREGATE, GRADE B2	Construction Stockpile		2	May 19, 2020	SYSTEM	\$2,450.97	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$2,450.97	
	Construction Stockpile - Total						\$2,450.97	
0680 -	Total						\$2,450.97	
Overa	ıll - Total						\$83,764.40	

Revision 4/1/2020 Page 12 of 12