\$62,648.60



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 16, 2020

Progress Estima	S Estimate Number Contract ID Prime Contractor		191115-H01 Keith Simpson Contracting, LLC		2020 Original Contract Amount 5, 2020 Net Change Order Amount Current Contract Amount	t \$89,158.60
Approval Date						By User
July 16, 2020			Generated and Approved (ar	nd should be considered Dr	aft) at the Project Office Level by	connen1
July 16, 2020			Reviewed and Approved (and she	ould be considered Draft) a	t the Resident Engineer Level by	plottk1
July 20, 2020			Reviewed an	d Approved at the Central	Office Controllers Office Level by	greggd1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2021	December 1, 2021		46.27%

Contr	act Informational Da	ates
Date Description	Original Completion Date	Current Completion Date
Acceptance Date		
Awarded Date	December 4, 2019	December 4, 2019
Letting Date	November 15, 2019	November 15, 2019
Notice to Proceed Date	January 6, 2020	January 6, 2020
Open to Traffic Date		
Work Began Date for J9S3330	February 20, 2020	February 20, 2020

Date Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days
Milestone - Calendar Time JSP B - Calendar Days, J9S3330	June 22, 2020	July 21, 2020	Milestone Complete	

Milestones

Contract Total Pa	ay For Estimate No. 10			
		This Estimate	Previous	To Date
191115-H01				
	Total Posted Items Pay	\$62,648.60	\$770,442.40	\$833,091.00
	Gross Item Adjustments	\$84.89	\$45,957.52	\$46,042.41
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$816,399.92	\$879,133.41
Contract Total Pa	avable This Estimate:	\$62.733.49		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9S3226	0170	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	EA	\$3,000.000	2	\$6,000.00
Project J	9S3226 - ⁻	Total					\$6,000.00
J9S3330	0560	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$8.000	416.2	\$3,329.60
	0580	4019905	MISC.OPTIONAL PAVEMENT	SQYD	\$58.000	416.2	\$24,139.60
	0590	6113020	FURNISHING TYPE 2 ROCK BLANKET	CUYD	\$40.000	241.7	\$9,668.00
	0600	6113040	PLACING TYPE 2 ROCK BLANKET	CUYD	\$10.000	241.7	\$2,417.00
	0610	6149902	MISC.24 IN. FLAP GATE	EA	\$700.000	1	\$700.00
	0680	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$2.200	371	\$816.20
	0690	6206001C	$4\ \mbox{IN}.$ YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$2.200	45	\$99.00
	0700	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	SQYD	\$3.000	361.4	\$1,084.20
	0970	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	SQYD	\$95.000	111	\$10,545.00
	1020	7034222	SLAB ON CONCRETE BEAM	SQYD	\$350.000	11	\$3,850.00
Project J	9S3330 - ⁻	Total					\$56,648.60

Contract Adjustments This Estimate

Overall - Total

Revision 4/1/2020 Page 1 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 16, 2020

Progress Estimate Number 10

Contract ID191115-H01Pay Period StartJuly 1, 2020Original Contract Amount\$1,711,311.90Prime ContractorKeith Simpson Contracting, LLCPay Period EndJuly 15, 2020Net Change Order Amount\$89,158.60Current Contract Amount\$1,800,470.50

No Contract Adjustments Exist on Contract

oject	Line	Item Description	Adjustment	Other Item	Comments	Adjustment	Line Item	Adjustmen
mber	No.		Type	Adjustment Type		Quantity	Adjustment Unit Price	amount
3330	0540	POROUS BACKFILL	Material			-110	\$48.00	(\$5,280.00
	0540	POROUS BACKFILL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user connen1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	110	\$48.00	\$5,280.00
	0560	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-977.1	\$8.00	(\$7,816.80
	0560	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user connen1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	977.1	\$8.00	\$7,816.80
	0570	GRAVEL (A) OR CRUSHED STONE (B)	Material			-114.6	\$25.00	(\$2,865.00
	0570	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user connen1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	114.6	\$25.00	\$2,865.00
	0680	WATERBORNE PAVEMENT Adjustment Adjustment MARKING PAINT, TYPE P BEADS						\$81.62
	0690	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment					\$3.27
	0730	SEEDING - COOL SEASON MIXTURES	Material			-0.4	\$2,000.00	(\$800.00
	0730	SEEDING - COOL SEASON MIXTURES	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user connen1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	0.4	\$2,000.00	\$800.00
	0800	2 IN. PSST POST - 12 GA.	Material			-47	\$7.00	(\$329.00
	0800	2 IN. PSST POST - 12 GA.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user connen1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	47	\$7.00	\$329.00
	0810	POST ANCHOR FOR 2 IN. PSST - 12 GA.	Material			-36	\$12.00	(\$432.00
	0810	POST ANCHOR FOR 2 IN. PSST - 12 GA.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user connen1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	36	\$12.00	\$432.00
	0820	SHF-FLAT SHEET FLUORESCENT	Material			-36	\$18.00	(\$648.00
	0820	SHF-FLAT SHEET FLUORESCENT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user connen1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	36	\$18.00	\$648.00
	0900	SLAB ON CONCRETE BEAM	Material			-221	\$350.00	(\$77,350.00
	0900	SLAB ON CONCRETE BEAM	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item	221	\$350.00	\$77,350.00



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 16, 2020

Progress Estimate Number 10 Contract ID 191115-H01 Pay Period Start July 1, 2020 Original Contract Amount \$1,711,311.90 Pay Period End July 15, 2020 Original Contract Amount \$1,711,311.90 Pay Period End July 15, 2020 Original Contract Amount \$1,711,311.90 Original Contract Amount \$1,711,311.90 Original Contract Amount \$1,800,470.50 Original Contract Amount \$1,800,470

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
9\$3330					Adjustment (0008) due to user connen1 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
	0980	GALVANIZED CAST-IN- PLACE CONCRETE PILES (14 IN)	Material			-846	\$100.00	(\$84,600.00
	0980	GALVANIZED CAST-IN- PLACE CONCRETE PILES (14 IN)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user connen1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	846	\$100.00	\$84,600.00
	1010	SAFETY BARRIER CURB	Material			-183	\$80.00	(\$14,640.00
	1010	SAFETY BARRIER CURB	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user connen1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	183	\$80.00	\$14,640.00
	1020	SLAB ON CONCRETE BEAM	Material			-221	\$350.00	(\$77,350.00
	1020	SLAB ON CONCRETE BEAM	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user connen1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	221	\$350.00	\$77,350.00
	1030	27 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	Material			-218	\$275.00	(\$59,950.00
	1030	27 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) due to user connen1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	218	\$275.00	\$59,950.00
Total								\$84.89

Revision 4/1/2020 Page 3 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Col	ntract Project Informat	ion
Project Number	Federal Proj. Number	Project Description	Route	County		,	Location of Work
J9S3226		Bridge replacement	D	NEW MADRID	over drainage ditches 40 and	13	
J9S3330	FAS S702(56)	Bridge replacement	D	NEW MADRID	over drainage ditches 43 and	12	
Totals by .	Job Numbe	rs					
J9S3226		d Item Pay Item Adjustm		s Item Pay	This Estimate \$6,000.00 \$0.00 \$6,000.00	Previous \$0.00 \$13,257.52 \$13,257.52	To Date \$6,000.00 \$13,257.52 \$19,257.52
	Liquid	tive centive lated Damages Contract Adju		i	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00
J9S3330		d Item Pay Item Adjustm		s Item Pay	This Estimate \$56,648.60 \$84.89 \$56,733.49	Previous \$770,442.40 \$32,700.00 \$803,142.40	To Date \$827,091.00 \$32,784.89 \$859,875.89
	Liquio	tive centive lated Damages Contract Adju		i	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 4 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9S3330, Item 2064000, Project Item Line Number 0540, Material Set 206400096, Material 1009G5DRLS - Agg for Drainage Gr5 Limestone, Acceptance Action Generic 1009G5DRLS is insufficient.	QA and QC gradations need to be entered.	connen1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3330, Item 3040506, Project Item Line Number 0560, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	QA and QC gradations need to be entered.	connen1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3330, Item 3105002, Project Item Line Number 0570, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	QA and QC gradations need to be entered.	connen1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3330, Item 7021314, Project Item Line Number 0980, Material Set 702131496, Material 0501CCB1 - Concrete, Class B-1 No Air, Acceptance Action Generic 0501CCB1 is insufficient.	QC reports pending.	connen1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3330, Item 7034215, Project Item Line Number 1010, Material Set 703421596, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on 28 day cylinder break.	connen1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3330, Item 7034222, Project Item Line Number 0900, Material Set 703422296, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	QC report needs to be corrected.	connen1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3330, Item 7034222, Project Item Line Number 1020, Material Set 703422296, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	QC reports pending.	connen1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3330, Item 7056050A, Project Item Line Number 1030, Material Set 7056050A96, Material 1029GRRCPSVS - Girder Prestress Reinf Conc Voided Slab, Acceptance Action Generic 1029GRRCPSVS is insufficient.	Material needs to be reported.	connen1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3330, Item 8051000A, Project Item Line Number 0730, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	Free form needs to be entered.	connen1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3330, Item 8051000A, Project Item Line Number 0730, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient.	Free form needs to be entered.	connen1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3330, Item 9031270A, Project Item Line Number 0800, Material Set 9031270A96, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Certification on file, not yet entered.	connen1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3330, Item 9031271, Project Item Line Number 0810, Material Set 903127196, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Certification on file, not yet entered.	connen1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3330, Item 9035069A, Project Item Line Number 0820, Material Set 9035069A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Certification on file, not yet entered.	connen1	Overridden

Revision 4/1/2020 Page 5 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See report generated date)
91115-H01	J9S3226	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$3,500.00	\$0.0
		0001	0020	2064000	POROUS BACKFILL	204.00	0.00	204.00	CUYD	0.00	\$44.00	\$0.0
		0001	0030	2079909	MISC.MODIFIED LINEAR GRADING CLASS 2	4.20	0.00	4.20	STA	0.00	\$7,500.00	\$0.0
		0001	0040	3040163	TYPE 1 AGGREGATE FOR BASE (6 IN. THICK)	1,081.00	0.00	1,081.00	SQYD	0.00	\$8.00	\$0.0
		0001	0050	3049910	MISC.TYPE 5 AGGREGATE	143.00	0.00	143.00	TONS	0.00	\$28.00	\$0.0
		0001	0060	4019905	MISC.OPTIONAL PAVEMENT	906.10	0.00	906.10	SQYD	0.00	\$58.00	\$0.0
		0001	0070	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	126.00	0.00	126.00	CUYD	0.00	\$45.00	\$0.0
		0001	0800	6096041	PLACING TYPE 1 ROCK DITCH LINER	126.00	0.00	126.00	CUYD	0.00	\$15.00	\$0.0
		0001	0090	6113020	FURNISHING TYPE 2 ROCK BLANKET	741.00	0.00	741.00	CUYD	0.00	\$40.00	\$0.0
		0001	0100	6113040	PLACING TYPE 2 ROCK BLANKET	741.00	0.00	741.00	CUYD	0.00	\$10.00	\$0.0
		0001	0110	6149902	MISC.18 INCH FLAP GATE	1.00	0.00	1.00	EA	0.00	\$700.00	\$0.0
		0001	0120	6149902	MISC.24 INCH FLAP GATE	4.00	0.00	4.00	EA	0.00	\$800.00	\$0.0
		0001	0130	6161005	CONSTRUCTION SIGNS	443.00	0.00	443.00	SQFT	0.00	\$6.50	\$0.0
		0001	0140	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	0.00	\$35.00	\$0.0
		0001	0150	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	0.00	\$20.00	\$0.0
		0001	0160	6161030	TYPE III MOVEABLE BARRICADE	12.00	0.00	12.00	EA	0.00	\$125.00	\$0.0
		0001	0170	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	3.00	0.00	3.00	EA	2.00	\$3,000.00	\$6,000.0
		0001	0180	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$64,500.00	\$0.
		0001	0190	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	903.00	0.00	903.00	LF	0.00	\$2.25	\$0.
		0001	0200	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	113.00	0.00	113.00	LF	0.00	\$2.25	\$0
		0001	0210	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,167.00	0.00	1,167.00	SQYD	0.00	\$3.00	\$0
		0001	0220	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$5,800.00	\$0.
		0001	0230	7250418	18 IN. PIPE GROUP C	48.00	0.00	48.00	LF	0.00	\$30.00	\$0.
		0001	0240	7250424	24 IN. PIPE GROUP C	149.00	0.00	149.00	LF	0.00	\$40.00	\$0
		0001	0250	7320818A	18 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	1.00	0.00	1.00	EA	0.00	\$125.00	\$0
		0001	0260	7320824A	24 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	4.00	0.00	4.00	EA	0.00	\$200.00	\$0
		0001	0270	8051000A	SEEDING - COOL SEASON MIXTURES	1.00	0.00	1.00	ACRE	0.00	\$2,000.00	\$0
		0001	0280	8061006	ALTERNATE DITCH CHECK	165.00	0.00	165.00	LF	0.00	\$5.00	\$0
		0001	0290	8061016	SEDIMENT REMOVAL	15.00	0.00	15.00	CUYD	0.00	\$5.00	\$0
		0001	0300	8061017	TEMPORARY SEEDING AND MULCHING	1.00	0.00	1.00	ACRE	0.00	\$800.00	\$0
		0001	0310	8061019	SILT FENCE	701.00	0.00	701.00	LF	0.00	\$3.00	\$0
		0001	0320	8061050	TYPE C BERM	330.00	0.00	330.00	LF	0.00	\$10.00	\$0
		0010	0330	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	88.00	0.00	88.00	LF	0.00	\$32.00	\$0
		0010	0340	6061069	MGS BRIDGE APPROACH TRANSITION SECTION	4.00	0.00	4.00	EA	0.00	\$3,100.00	\$0
		0010	0350	6063014	(REGULAR/NO CURB) TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	0.00	\$2,900.00	\$0
		0070	0360	2061000	CLASS 1 EXCAVATION	70.00	0.00	70.00	CUYD	0.00	\$20.00	\$0
		0070	0370	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS		\$25,000.00	\$0
		0070	0380	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	110.00	0.00	110.00	SQYD	0.00	\$95.00	\$0
		0070	0390	7021314	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	540.00	0.00	540.00	LF	0.00	\$95.00	\$0
		0070	0400	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	0.00	\$3,500.00	\$0
		0070	0410	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	24.40	0.00	24.40	CUYD	0.00	\$1,000.00	\$0
		0070	0410	7032003	SAFETY BARRIER CURB	181.00	0.00	181.00	LF	0.00	\$80.00	\$0
		0070	0420	7034213	SLAB ON CONCRETE NU-GIRDER	209.00	0.00	209.00	SQYD	0.00	\$325.00	\$0
		0070	J4JU	1004221	ODAD ON CONCILIE NO-GINDER	208.00	0.00	209.00	עושט	0.00	φυ20.00	Φ0.

Revision 4/1/2020 Page 6 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
91115-H01	J9S3226	0070	0450	7123610	SLAB DRAIN	12.00	0.00	12.00	EA	0.00	\$250.00	\$0.0
		0070	0460	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$1,250.00	\$0.0
		0070	0470	7161000	PLAIN NEOPRENE BEARING PAD	6.00	0.00	6.00	EA	0.00	\$200.00	\$0.0
		0071	0480	2063300	CLASS 4 EXCAVATION	595.00	0.00	595.00	CUYD	0.00	\$25.00	\$0.0
		0071	0490	2069901	MISC.Dewatering	1.00	0.00	1.00	LS	0.00	\$38,000.00	\$0.0
		0071	0500	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	0.00	\$20,000.00	\$0.
		0071	0510	7034040	CLASS B-1 CONCRETE (CULVERTS-BRIDGE)	279.00	0.00	279.00	CUYD	0.00	\$600.00	\$0.
		0071	0520	7061020	REINFORCING STEEL (CULVERTS-BRIDGE)	38,600.00	0.00	38,600.00	LB	0.00	\$1.50	\$0.
	Project J	9S3226 - To	otal Value	Posted to D	ate as of Report Generated Date							\$6,000.
	J9S3330	0001	0530	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$5,000.00	\$5,000
		0001	0540	2064000	POROUS BACKFILL	110.00	0.00	110.00	CUYD	110.00	\$48.00	\$5,280
		0001	0550	2079909	MISC.MODIFIED LINEAR GRADING CLASS 2	9.80	0.00	9.80	STA	9.80	\$500.00	\$4,900
		0001	0560	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	830.00	147.10	977.10	SQYD	977.10	\$8.00	\$7,816
		0001	0570	3105002	GRAVEL (A) OR CRUSHED STONE (B)	223.00	0.00	223.00	TONS	114.60	\$25.00	\$2,865
		0001	0580	4019905	MISC.OPTIONAL PAVEMENT	830.00	147.10	977.10	SQYD	977.10	\$58.00	\$56,671
		0001	0590	6113020	FURNISHING TYPE 2 ROCK BLANKET	825.00	0.00	825.00	CUYD	636.00	\$40.00	\$25,440
		0001	0600	6113040	PLACING TYPE 2 ROCK BLANKET	825.00	0.00	825.00	CUYD	636.00	\$10.00	\$6,360
		0001	0610	6149902	MISC.24 IN. FLAP GATE	5.00	0.00	5.00	EA	5.00	\$700.00	\$3,500
		0001	0620	6161005	CONSTRUCTION SIGNS	539.00	0.00	539.00	SQFT	539.00	\$6.00	\$3,234
									EA	8.00	\$35.00	
		0001	0630	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	0.00	8.00				\$280
		0001	0640	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	4.00	\$20.00	\$8
		0001	0650	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	20.00	0.00	20.00	EA	20.00	\$185.00	\$3,700
		0001	0660	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	2.00	\$3,500.00	\$7,000
		0001	0670	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$70,000.00	\$70,000
		0001	0680	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,114.00	0.00	1,114.00	LF	1,033.00	\$2.20	\$2,27
		0001	0690	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	139.00	0.00	139.00	LF	130.00	\$2.20	\$28
		0001	0700	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,795.00	0.00	1,795.00	SQYD	953.00	\$3.00	\$2,85
		0001	0710	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$5,910.00	\$5,91
		0001	0720	7250424	24 IN. PIPE GROUP C	568.00	0.00	568.00	LF	568.00	\$30.00	\$17,04
		0001	0730	8051000A	SEEDING - COOL SEASON MIXTURES	1.10	0.00	1.10	ACRE	0.40	\$2,000.00	\$80
		0001	0740	8061005	ROCK DITCH CHECK	142.00	0.00	142.00	LF	0.00	\$10.00	\$1
		0001	0750	8061016	SEDIMENT REMOVAL	14.00	0.00	14.00	CUYD	0.00	\$5.00	\$
		0001	0760	8061017	TEMPORARY SEEDING AND MULCHING	1.10	0.00	1.10	ACRE	0.00	\$800.00	\$
		0001	0770	8061019	SILT FENCE	545.00	0.00	545.00	LF	0.00	\$3.00	\$
		0001	0780	8061050	TYPE C BERM	321.00	0.00	321.00	LF	50.00	\$10.00	\$50
		0010	0790	6063017	TYPE C CRASHWORTHY END TERMINAL	4.00	0.00	4.00	EA	4.00	\$20,000.00	\$80,00
		0040	0800	9031270A	2 IN. PSST POST - 12 GA.	47.00	0.00	47.00	LF	47.00	\$7.00	\$32
		0040	0810	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	36.00	0.00	36.00	LF	36.00	\$12.00	\$43
		0040	0820	9035069A	SHF-FLAT SHEET FLUORESCENT	36.00	0.00	36.00	SQFT	36.00	\$18.00	\$64
		0070	0830	2061000	CLASS 1 EXCAVATION	70.00	0.00	70.00	CUYD	70.00	\$15.00	\$1,05
		0070	0840	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS		\$21,525.00	\$21,52
			0850	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	111.00	0.00	111.00	SQYD	111.00	\$95.00	\$10,54
		0070	0860	7021314	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	400.00	215.00	615.00	LF	615.00	\$90.00	\$55,35
		0070										
		0070	0870	7025001	DYNAMIC PILE TESTING	2.00	1.00	3.00	EA	3.00	\$3,500.00	\$10,50
		0070	0880	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	22.80	0.00	22.80	CUYD	22.80	\$1,000.00	\$22,80

Page 7 of 16 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191115-H01	J9S3330	0070	0890	7034215	SAFETY BARRIER CURB	183.00	0.00	183.00	LF	183.00	\$80.00	\$14,640.00
		0070	0900	7034222	SLAB ON CONCRETE BEAM	221.00	0.00	221.00	SQYD	221.00	\$350.00	\$77,350.00
		0070	0910	7056050A	27 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	218.00	0.00	218.00	LF	218.00	\$275.00	\$59,950.00
		0070	0920	7123610	SLAB DRAIN	14.00	0.00	14.00	EA	14.00	\$215.00	\$3,010.00
		0070	0930	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,250.00	\$2,500.00
		0070	0940	7161000	PLAIN NEOPRENE BEARING PAD	6.00	0.00	6.00	EA	6.00	\$200.00	\$1,200.00
		0071	0950	2061000	CLASS 1 EXCAVATION	50.00	0.00	50.00	CUYD	50.00	\$20.00	\$1,000.00
		0071	0960	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$25,000.00	\$25,000.00
		0071	0970	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	111.00	0.00	111.00	SQYD	111.00	\$95.00	\$10,545.00
		0071	0980	7021314	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	350.00	496.00	846.00	LF	846.00	\$100.00	\$84,600.00
		0071	0990	7025001	DYNAMIC PILE TESTING	2.00	1.00	3.00	EA	3.00	\$3,500.00	\$10,500.00
		0071	1000	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	22.80	0.00	22.80	CUYD	22.80	\$1,000.00	\$22,800.00
		0071	1010	7034215	SAFETY BARRIER CURB	183.00	0.00	183.00	LF	183.00	\$80.00	\$14,640.00
		0071	1020	7034222	SLAB ON CONCRETE BEAM	221.00	0.00	221.00	SQYD	221.00	\$350.00	\$77,350.00
		0071	1030	7056050A	27 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	218.00	0.00	218.00	LF	218.00	\$275.00	\$59,950.00
		0071	1040	7123610	SLAB DRAIN	14.00	0.00	14.00	EA	14.00	\$215.00	\$3,010.00
		0071	1050	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,250.00	\$2,500.00
		0071	1060	7161000	PLAIN NEOPRENE BEARING PAD	6.00	0.00	6.00	EA	6.00	\$200.00	\$1,200.00
		0071	5101	7025004	DYNAMIC PILE RESTRIKE TESTING	0.00	1.00	1.00	EA	1.00	\$3,500.00	\$3,500.00
	Project J	9S3330 - To	tal Value	Posted to D	ate as of Report Generated Date							\$910,219.20
191115-H01 Ove	erall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$916,219.20

Revision 4/1/2020 Page 8 of 16



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9S3226

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0170	6161098A	CMS W/O COMMUNICATION INTERFACE, CONT F/	7/15/20	7/16/20	2.00	EA	Bridge Project A8648.	662+01		874+98		

Project: J9S3330

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0560	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	7/10/20	7/10/20	416.20	SQYD	Bridge A8821	826+95		829+73		
0580	4019905	MISC.	7/15/20	7/16/20	416.20	SQYD	Bridge A8821	826+95		829+73		
0590	6113020	FURNISHING TYPE 2 ROCK BLANKET	7/8/20	7/8/20	16.10	CUYD	Correction to quantity in front of End Bent #2. 8' 2" X 26.66' X 2'	828+70				
				7/8/20	22.00	CUYD	Correction to quantity in front of End Bent #1 11' 2" X 26.66' X 2'	827+95				
				7/8/20	32.90	CUYD	SE Quad of A8821.	828+70				
				7/8/20	41.80	CUYD	NW Quad of A8821	827+95				
				7/8/20	47.30	CUYD	SW Quad of A8821.	827+95				
				7/8/20	81.60	CUYD	NE Quad of A8821.	828+70				
0600	6113040	PLACING TYPE 2 ROCK BLANKET	7/8/20	7/8/20	16.10	CUYD	Correction to quantity in front of End Bent #2, A8821. 8' 2" X 26.66' X 2'	828+70				
				7/8/20	22.00	CUYD	Correction to quantity in front of End Bent #1, A8821 11' 2" X 26.66' X 2'	827+95				
				7/8/20	32.90	CUYD	SE Quad of A8821.	828+70				
				7/8/20	41.80	CUYD	NW Quad of A8821.	827+95				
				7/8/20	47.30	CUYD	SW Quad of A8821.	827+95				
				7/8/20	81.60	CUYD	NE Quad of A8821.	828+70				
0610	6149902	MISC. DRAINAGE FITTINGS	7/9/20	7/10/20	1.00	EA	Bridge A8821	828+91.13	LT			
0680	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	7/9/20	7/10/20	371.00	LF	Bridge A8820	496+84	LT and RT	500+54	LT and RT	
0690	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	7/9/20	7/10/20	45.00	LF	Bridge A8820	496+84	CL	500+54	CL	
0700	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	7/8/20	7/8/20	23.70	SQYD	Correction to quantity in front of End Bent #2.	828+70				
				7/8/20	32.60	SQYD	Correction to quantity in front of End Bent #1.	827+95				
				7/8/20	49.10	SQYD	SE Quad of A8821.	828+70				
				7/8/20	62.70	SQYD	NW Quad of A8821.	827+95				
				7/8/20	70.90	SQYD	SW Quad of A8821.	827+95				
				7/8/20	122.40	SQYD	NE Quad of A8821.	828+70				
0970	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	7/15/20	7/16/20	111.00	SQYD	Bridge A8821	827+75		828+90		
1020	7034222	SLAB ON CONCRETE BEAM	7/13/20	7/14/20	11.00	SQYD	Sealed Bridge A8821.	827+94.62		828+70.12		

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 9 of 16



	5	A 11	0.11		0	0 1 1		2 1
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0340	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)			2	Mar 16, 2020	SYSTEM	\$6,628.76	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$6,628.76	
	Construction Stockpile - Total						\$6,628.76	
0340 -	Total						\$6,628.76	
0350	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		2	Mar 16, 2020	SYSTEM	\$6,628.76	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$6,628.76	
	Construction Stockpile - Total						\$6,628.76	
0350 -	Total						\$6,628.76	
0540	POROUS BACKFILL	Material		4	Apr 15, 2020	SYSTEM	(\$2,630.40)	
				4	Apr 15, 2020	SYSTEM	\$2,630.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user connen1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				5	May 1, 2020	SYSTEM	(\$2,630.40)	
				5	May 1, 2020	SYSTEM	\$2,630.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user connen1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				6	May 18, 2020	SYSTEM	(\$2,630.40)	
				6	May 18, 2020	SYSTEM	\$2,630.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user connen1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				7	Jun 2, 2020	SYSTEM	(\$2,630.40)	
				7	Jun 2, 2020	SYSTEM	\$2,630.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user evansk overridding Payment Estimate Exception 1 on the current Payment Estimate.
				8	Jun 16, 2020	SYSTEM	(\$2,630.40)	
				8	Jun 16, 2020	SYSTEM	\$2,630.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user connen1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				9	Jun 30, 2020	SYSTEM	(\$5,280.00)	
				9	Jun 30, 2020	SYSTEM	\$5,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user connen1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				10	Jul 16, 2020	SYSTEM	(\$5,280.00)	
				10	Jul 16, 2020	SYSTEM	\$5,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user connen1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0540 -	Total						\$0.00	
0560	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		8	Jun 16, 2020	SYSTEM	(\$4,487.20)	
				8	Jun 16, 2020	SYSTEM	\$4,487.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user connen1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				9	Jun 30, 2020	SYSTEM	(\$4,487.20)	
				9	Jun 30, 2020	SYSTEM	\$4,487.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user connen1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				10	Jul 16, 2020	SYSTEM	(\$7,816.80)	
				10	Jul 16, 2020	SYSTEM	\$7,816.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user connen1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	

Revision 4/1/2020 Page 10 of 16



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0560	Material - Total						\$0.00	
0560 -	·Total						\$0.00	
0570	GRAVEL (A) OR CRUSHED STONE (B)	Material		9	Jun 30, 2020	SYSTEM	(\$2,865.00)	
				9	Jun 30, 2020	SYSTEM	\$2,865.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user connen1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				10	Jul 16, 2020	SYSTEM	(\$2,865.00)	
				10	Jul 16, 2020	SYSTEM	\$2,865.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user connen1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0570 -	· Total						\$0.00	
0610	MISC. 24 IN. FLAP GATE	Material		5	May 1, 2020	SYSTEM	(\$2,800.00)	
				5	May 1, 2020	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user connen1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				6	May 18, 2020	SYSTEM	(\$2,800.00)	
				6	May 18, 2020	SYSTEM	\$2,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user connen1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0610 -	· Total						\$0.00	
0610 -	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		9	Jun 30, 2020	SYSTEM	(\$816.20)	
	BEADS			9	Jun 30, 2020	SYSTEM	\$816.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user connen1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL	10	Jul 16, 2020	connen1	\$81.62	Bridge Project A8820.
			REFL - Tota	d .			\$81.62	
	Other Item Adjustment - Total						\$81.62	
0680 -	Total						\$81.62	
0690	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		9	Jun 30, 2020	SYSTEM	(\$99.00)	
	BEADS			9	Jun 30, 2020	SYSTEM	\$99.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user connen1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL	10	Jul 16, 2020	connen1	\$3.27	Bridge Project A8820
			REFL - Tota	ıl			\$3.27	
	Other Item Adjustment - Total						\$3.27	
0690 -	Total						\$3.27	
0700	PERMANENT EROSION CONTROL GEOTEXTILE	Material		3	Apr 3, 2020	SYSTEM	(\$373.20)	
				3	Apr 3, 2020	SYSTEM	\$373.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user connen1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				4	Apr 15, 2020	SYSTEM	(\$373.20)	

Revision 4/1/2020 Page 11 of 16



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Lille	Description	Type	Adjustment Type		Date	By	Amount	Nemars
0700	PERMANENT EROSION CONTROL GEOTEXTILE	Material		4	Apr 15, 2020	SYSTEM	\$373.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user connen1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0700 -	Total						\$0.00	
0720	24 IN. PIPE GROUP C	Material		5	May 1, 2020	SYSTEM	(\$10,530.00)	
				5	May 1, 2020	SYSTEM	\$10,530.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user connen1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				6	May 18, 2020	SYSTEM	(\$10,530.00)	
				6	May 18, 2020	SYSTEM	\$10,530.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user connen1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0720 -	Total						\$0.00	
0730	SEEDING - COOL SEASON MIXTURES	Material		9	Jun 30, 2020	SYSTEM	(\$800.00)	
				9	Jun 30, 2020	SYSTEM	\$800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user connen1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				10	Jul 16, 2020	SYSTEM	(\$800.00)	
				10	Jul 16, 2020	SYSTEM	\$800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user connen1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0730 -	Total						\$0.00	
0790	TYPE C CRASHWORTHY END TERMINAL	Construction Stockpile		2	Mar 16, 2020	SYSTEM	\$32,700.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$32,700.00	
	Construction Stockpile - Total						\$32,700.00	
0790 -	Total						\$32,700.00	
0800	2 IN. PSST POST - 12 GA.	Material		9	Jun 30, 2020	SYSTEM	(\$329.00)	
				9	Jun 30, 2020	SYSTEM	\$329.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user connen1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				10	Jul 16, 2020	SYSTEM	(\$329.00)	
				10	Jul 16, 2020	SYSTEM	\$329.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user connen1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0800 -	Total						\$0.00	
0810	POST ANCHOR FOR 2 IN. PSST - 12 GA.	Material		9	Jun 30, 2020	SYSTEM	(\$432.00)	
				9	Jun 30, 2020	SYSTEM	\$432.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user connen1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				10	Jul 16, 2020	SYSTEM	(\$432.00)	
				10	Jul 16, 2020	SYSTEM	\$432.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user connen1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
							\$0.00	
0810 -	- Total							

Revision 4/1/2020 Page 12 of 16



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
0820	SHF-FLAT SHEET FLUORESCENT	Material		9	Jun 30, 2020	SYSTEM	(\$648.00)									
				9	Jun 30, 2020	SYSTEM	\$648.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user connen1 overridding Payment Estimate Exception 19 on the current Payment Estimate.								
				10	Jul 16, 2020	SYSTEM	(\$648.00)									
				10	Jul 16, 2020	SYSTEM	\$648.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user connen1 overridding Payment Estimate Exception 13 on the current Payment Estimate.								
			- Total				\$0.00									
	Material - Total						\$0.00									
0820 -	· Total						\$0.00									
0850	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		8	Jun 16, 2020	SYSTEM										
				8	Jun 16, 2020	SYSTEM	\$10,545.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user connen1 overridding Payment Estimate Exception 3 on the current Payment Estimate.								
			- Total				\$0.00									
	Material - Total						\$0.00									
0850 -	· Total						\$0.00									
0860	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Material		2	Mar 16, 2020	SYSTEM	(\$55,350.00)									
				2	Mar 16, 2020	SYSTEM	\$55,350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user connen1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
				3	Apr 3, 2020	SYSTEM	(\$55,350.00)									
				3	Apr 3, 2020	SYSTEM	\$55,350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user connen1 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
				4	Apr 15, 2020	SYSTEM	(\$55,350.00)									
				4	Apr 15, 2020	SYSTEM	\$55,350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user connen1 overridding Payment Estimate Exception 4 on the current Payment Estimate.								
				5	May 1, 2020	SYSTEM	(\$55,350.00)									
				5	May 1, 2020	SYSTEM	\$55,350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user connen1 overridding Payment Estimate Exception 4 on the current Payment Estimate.								
				6	May 18, 2020	SYSTEM	(\$55,350.00)									
				6	May 18, 2020	SYSTEM	\$55,350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user connen1 overridding Payment Estimate Exception 4 on the current Payment Estimate.								
			- Total				\$0.00									
	Material - Total						\$0.00									
0860 -	· Total						\$0.00									
0880	CLASS B CONCRETE (SUBSTRUCTURE)	Material		3	Apr 3, 2020	SYSTEM	(\$22,800.00)									
								3	Apr 3, 2020	SYSTEM	\$22,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user connen1 overridding Payment Estimate Exception 4 on the current Payment Estimate.				
												4	Apr 15, 2020	SYSTEM	(\$22,800.00)	
															4	4
				5	May 1, 2020	SYSTEM	(\$22,800.00)									
					5	5	5	5	!	5	May 1, 2020	SYSTEM	\$22,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user connen1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
				6	May 18, 2020	SYSTEM	(\$22,800.00)									

Revision 4/1/2020 Page 13 of 16



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0880	CLASS B CONCRETE (SUBSTRUCTURE)	Material	7,7,2	6	May 18, 2020	SYSTEM	\$22,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user connen1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
			- Total				\$0.00	Zominio Zicopion o on tio out out ajmon Zominio.	
	Material - Total						\$0.00		
0880 -	· Total						\$0.00		
0890	SAFETY BARRIER CURB	Material		5	May 1, 2020	SYSTEM	(\$14,640.00)		
				5	May 1, 2020	SYSTEM	\$14,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user connen1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
				6	May 18, 2020	SYSTEM	(\$14,640.00)		
				6	May 18, 2020	SYSTEM	\$14,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user connen1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
						7	Jun 2, 2020	SYSTEM	(\$14,640.00)
				7	Jun 2, 2020	SYSTEM	\$14,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user evansk overridding Payment Estimate Exception 5 on the current Payment Estimate.	
				8	Jun 16, 2020	SYSTEM	(\$14,640.00)		
				8	Jun 16, 2020	SYSTEM	\$14,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user connen1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
				9	Jun 30, 2020	SYSTEM	(\$14,640.00)		
				9	Jun 30, 2020	SYSTEM	\$14,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user connen1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
							60.00		
			- Total				\$0.00		
	Material - Total		- Total				\$0.00		
0890 -	Material - Total Total		- Total						
0890 -		Material	- Total	3	Apr 3, 2020	SYSTEM	\$0.00		
	· Total	Material	- Total	3		SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user connen1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
	· Total	Material	- Total		2020 Apr 3,		\$0.00 \$0.00 (\$15,470.00)	Estimate Item Adjustment (0004) due to user connen1 overridding Payment	
	· Total	Material	- Total	3	2020 Apr 3, 2020 Apr 15,	SYSTEM	\$0.00 \$0.00 (\$15,470.00) \$15,470.00	Estimate Item Adjustment (0004) due to user connen1 overridding Payment	
	· Total	Material	- Total	3	2020 Apr 3, 2020 Apr 15, 2020 Apr 15,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$15,470.00) \$15,470.00 (\$73,500.00)	Estimate Item Adjustment (0004) due to user connen1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user connen1 overridding Payment	
	· Total	Material	- Total	3 4 4	2020 Apr 3, 2020 Apr 15, 2020 Apr 15, 2020 May 1,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$15,470.00) \$15,470.00 (\$73,500.00) \$73,500.00	Estimate Item Adjustment (0004) due to user connent overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user connent overridding Payment	
	· Total	Material	- Total	3 4 4 5	2020 Apr 3, 2020 Apr 15, 2020 Apr 15, 2020 May 1, 2020 May 1,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$15,470.00) \$15,470.00 (\$73,500.00) \$73,500.00	Estimate Item Adjustment (0004) due to user connent overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user connent overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user connent overridding Payment	
	· Total	Material	- Total	3 4 4 5 5	2020 Apr 3, 2020 Apr 15, 2020 Apr 15, 2020 May 1, 2020 May 1, 2020 May 18, 18, 18, 18, 18, 18, 18, 18, 18, 18,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$15,470.00) \$15,470.00 (\$73,500.00) \$73,500.00 (\$73,500.00)	Estimate Item Adjustment (0004) due to user connent overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user connent overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user connent overridding Payment	
	· Total	Material	- Total	3 4 4 5 5 6	2020 Apr 3, 2020 Apr 15, 2020 Apr 15, 2020 May 1, 2020 May 1, 2020 May 18, 2020 May 18, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$15,470.00) \$15,470.00 (\$73,500.00) \$73,500.00 (\$73,500.00) \$73,500.00 (\$73,500.00)	Estimate Item Adjustment (0004) due to user connen1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user connen1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user connen1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user connen1 overridding Payment Estimate Item Adjustment (0007) due to user connen1 overridding Payment	
	· Total	Material	- Total	3 4 4 5 5 6 6	2020 Apr 3, 2020 Apr 15, 2020 Apr 15, 2020 May 1, 2020 May 18, 2020 May 18, 2020 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$15,470.00) \$15,470.00 (\$73,500.00) \$73,500.00 (\$73,500.00) \$73,500.00 (\$73,500.00)	Estimate Item Adjustment (0004) due to user connen1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user connen1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user connen1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user connen1 overridding Payment Estimate Item Adjustment (0007) due to user connen1 overridding Payment	
	· Total	Material	- Total	3 4 4 5 5 6 6 7 7	2020 Apr 3, 2020 Apr 15, 2020 Apr 15, 2020 Apr 15, 2020 May 1, 2020 May 18, 2020 Jun 2, 2020 Jun 2, 1020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$15,470.00) \$15,470.00 (\$73,500.00) \$73,500.00 (\$73,500.00) \$73,500.00 (\$73,500.00)	Estimate Item Adjustment (0004) due to user connen1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user connen1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user connen1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user connen1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 15 on the current Payment Estimate.	
	· Total	Material	- Total	3 4 4 5 5 5 6 6 7 7 7	2020 Apr 3, 2020 Apr 15, 2020 Apr 15, 2020 May 1, 2020 May 1, 2020 May 18, 2020 Jun 2, 2020 Jun 16, 16, 16, 16, 16, 16, 16, 16, 16, 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$15,470.00) \$15,470.00 (\$73,500.00) \$73,500.00 (\$73,500.00) \$73,500.00 (\$73,500.00) \$73,500.00 (\$73,500.00)	Estimate Item Adjustment (0004) due to user connen1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user connen1 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user connen1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user connen1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 15 on the current Payment Estimate.	

Revision 4/1/2020 Page 14 of 16



1.7	D:	A allowed	041	F :	0 1	0 1 1	A	D 1
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0900	SLAB ON CONCRETE BEAM	Material		9	Jun 30, 2020	SYSTEM	\$77,350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user connen1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				10	Jul 16, 2020	SYSTEM	(\$77,350.00)	
				10	Jul 16, 2020	SYSTEM	\$77,350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user connen1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0900 -	· Total						\$0.00	
0910	27 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	Material		3	Apr 3, 2020	SYSTEM	(\$59,950.00)	
				3	Apr 3, 2020	SYSTEM	\$59,950.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user connen1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				4	Apr 15, 2020	SYSTEM	(\$59,950.00)	
				4	Apr 15, 2020	SYSTEM	\$59,950.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user connen1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				5	May 1, 2020	SYSTEM	(\$59,950.00)	
				5	May 1, 2020	SYSTEM	\$59,950.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user connen1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				6	May 18, 2020	SYSTEM	(\$59,950.00)	
				6	May 18, 2020	SYSTEM	\$59,950.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user connen1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0910 -	· Total						\$0.00	
0930	VERTICAL DRAIN AT END BENTS	Material		4	Apr 15, 2020	SYSTEM	(\$2,500.00)	
				4	Apr 15, 2020	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user connen1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total							
0930 -	Total						\$0.00	
0980	GALVANIZED CAST-IN-PLACE						\$0.00 \$0.00	
	CONCRETE PILES (14 IN)	Material		6	May 18, 2020	SYSTEM		
	CONCRETE PILES (14 IN)	Material		6		SYSTEM	\$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user connen1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
	CONCRETE PILES (14 IN)	Material			2020 May 18,		\$0.00 (\$35,000.00)	Estimate Item Adjustment (0009) due to user connen1 overridding Payment
	CONCRETE PILES (14 IN)	Material		6	2020 May 18, 2020 Jun 2,	SYSTEM	\$0.00 (\$35,000.00) \$35,000.00	Estimate Item Adjustment (0009) due to user connen1 overridding Payment
	CONCRETE PILES (14 IN)	Material		7	2020 May 18, 2020 Jun 2, 2020 Jun 2,	SYSTEM	\$0.00 (\$35,000.00) \$35,000.00 (\$35,000.00)	Estimate Item Adjustment (0009) due to user connen1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user evansk overridding Payment
	CONCRETE PILES (14 IN)	Material		6 7 7	2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16,	SYSTEM SYSTEM	\$0.00 (\$35,000.00) \$35,000.00 (\$35,000.00) \$35,000.00	Estimate Item Adjustment (0009) due to user connen1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user evansk overridding Payment
	CONCRETE PILES (14 IN)	Material		6 7 7 8	2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$35,000.00) \$35,000.00 (\$35,000.00) \$35,000.00 (\$84,600.00)	Estimate Item Adjustment (0009) due to user connen1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user evansk overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user connen1 overridding Payment
	CONCRETE PILES (14 IN)	Material		6 7 7 8 8	2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$35,000.00) \$35,000.00 (\$35,000.00) \$35,000.00 (\$84,600.00)	Estimate Item Adjustment (0009) due to user connen1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user evansk overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user connen1 overridding Payment
	CONCRETE PILES (14 IN)	Material		6 7 7 8 8 8 9	2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 30, 2020 Jun 30,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$35,000.00) \$35,000.00 (\$35,000.00) \$35,000.00 (\$84,600.00) (\$84,600.00)	Estimate Item Adjustment (0009) due to user connen1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user evansk overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user connen1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user connen1 overridding Payment Estimate Item Adjustment (0013) due to user connen1 overridding Payment

Revision 4/1/2020 Page 15 of 16



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0980	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Material						Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0980 -	Total						\$0.00	
1000	CLASS B CONCRETE (SUBSTRUCTURE)	Material		7	Jun 2, 2020	SYSTEM	(\$22,800.00)	
				7	Jun 2, 2020	SYSTEM	\$22,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user evansk overridding Payment Estimate Exception 3 on the current Payment Estimate.
				8	Jun 16, 2020	SYSTEM	(\$22,800.00)	
				8	Jun 16, 2020	SYSTEM	\$22,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user connen1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1000 -	Total						\$0.00	
1010	SAFETY BARRIER CURB	Material		9	Jun 30, 2020	SYSTEM	(\$14,640.00)	
				9	Jun 30, 2020	SYSTEM	\$14,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user connen1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				10	Jul 16, 2020	SYSTEM	(\$14,640.00)	
				10	Jul 16, 2020	SYSTEM	\$14,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user connen1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1010 -	Total						\$0.00	
1020	SLAB ON CONCRETE BEAM	Material		8	Jun 16, 2020	SYSTEM	(\$46,410.00)	
				8	Jun 16, 2020	SYSTEM	\$46,410.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user connen1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				10	Jul 16, 2020	SYSTEM	(\$77,350.00)	
				10	Jul 16, 2020	SYSTEM	\$77,350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user connen1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	Total						\$0.00	
1030	27 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	Material		8	Jun 16, 2020	SYSTEM	(\$59,950.00)	
				8	Jun 16, 2020	SYSTEM	\$59,950.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user connen1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				9	Jun 30, 2020	SYSTEM	(\$59,950.00)	
				9	Jun 30, 2020	SYSTEM	\$59,950.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user connen1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				10	Jul 16, 2020	SYSTEM	(\$59,950.00)	
				10	Jul 16, 2020	SYSTEM	\$59,950.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user connen1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1030 -	Total						\$0.00	
Overa	II - Total						\$46,042.41	

Revision 4/1/2020 Page 16 of 16