

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 17, 2020

March 9, 2020

March 9, 2020

_	timate Number 10	Contract ID Prime Contractor	191213-C06 Ideker, Inc.	Pay Perio		August 2, August 15		Net Chang	ontract Amount e Order Amount entract Amount	\$2,130,919.51 \$0.00 \$2,130,919.51	
Approval Date										By User	
August 17, 2020		Ge	nerated and A	pproved (a	nd should	be conside	red Draf	t) at the Proj	ect Office Level by	hathak1	
August 17, 2020		Review	ed and Appro	and Approved (and should be considered Draft) at the Resident Engineer Level by karlic1							
August 18, 2020			F	Reviewed a	nd Approv	ed at the C	entral Of	fice Controll	ers Office Level by	greggd1	
Original Com	pletion Date	Current Completi	on Date	Actua	l Complet	tion Date		% of Curr	ent Contract Amoun	t Complete	
Novembe	r 1, 2020	November 1, 2	2020						94.74%		
Co	ontract Information	al Dates					Miles	stones			
Date Description	Original Completion Date	Current Completion Date		escription	Original Completion Date		_	urrent etion Date	Days Remaining or Milestone	Diary Charge Days	
Acceptance Date			Mileston Calenda		July 15,	2020	July 15	, 2020	Milestone Complet	e	
Awarded Date	January 9, 2020	January 9, 2020									
Letting Date	December 13, 2019	December 13, 2019									

This Estimate	Previous	To Date	
\$0.00	\$2,018,860.40	\$2,018,860.40	
\$0.00	(\$153,968.65)	(\$153,968.65)	
\$0.00	\$0.00	\$0.00	
\$0.00	\$0.00	\$0.00	
\$0.00	\$0.00	\$0.00	
\$0.00	\$0.00	\$0.00	
	\$1,864,891.75	\$1,864,891.75	
\$0.00			
	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$2,018,860.40 (5153,968.65) \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$1,864,891.75	\$0.00 \$2,018,860.40 \$2,018,860.40 \$0.00 \$153,968.65) \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$1,864,891.75 \$1,864,891.75

Items Paid This Estimate Period

No Data Available

Notice to

Proceed Date Open to Traffic Date Work Began Date

Contract Adjustments This Estimate

		stments Exist on Contract						
Line Item	<u>Adjust</u>	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3276	0070	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)	Material			-11,532.22	\$60.53	(\$698,045.28)
	0070	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	11,532.22	\$60.53	\$698,045.28
	0100	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-306.7	\$443.15	(\$135,914.10)
	0100	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user hathak1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	306.7	\$443.15	\$135,914.10

Revision 4/1/2020 Page 1 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 17, 2020

Progress Estimate Number
10

Contract ID
191213-C06
Pay Period Start
Pay Period End
August 15, 2020
Original Contract Amount
Net Change Order Amount
Current Contract Amount
\$2,130,919.51

							σαιιτ ψ2,	100,515.51
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3276	0140	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-566	\$5.45	(\$3,084.70)
	0140	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user hathak1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	566	\$5.45	\$3,084.70
	0220	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-9	\$31.00	(\$279.00)
	0220	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-33	\$31.00	(\$1,023.00)
	0220	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 14 on the current Payment Estimate.	9	\$31.00	\$279.00
	0220	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user hathak1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	33	\$31.00	\$1,023.00
	0230	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-41,830	\$0.14	(\$5,856.20)
	0230	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	41,830	\$0.14	\$5,856.20
	0240	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-62,980	\$0.20	(\$12,596.00)
	0240	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	62,980	\$0.20	\$12,596.00
Total								\$0.00

Revision 4/1/2020 Page 2 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Cor	ntract Project Informati	on
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4P3276	FAS S301(93)	Coldmill and resurface	92	PLATTE	from MO River to Route 273		
Totals by J	Job Numb	ers					
J4P3276		ed Item Pay s Item Adjustm		s Item Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$2,018,860.40 (\$153,968.65) \$1,864,891.75	To Date \$2,018,860.40 (\$153,968.65) \$1,864,891.75
	Liqui	itive centive dated Damages r Contract Adju		i	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 3 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Ferrou			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 4030101, Project Item Line Number 0070, Material Set 403010196, Material 0403SP125CLG - Superpave 12.5 mm, Des C 80 Gyros, Acceptance Action Generic AspHigh is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6131010, Project Item Line Number 0100, Material Set 613101096, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6131015, Project Item Line Number 0140, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6200015, Project Item Line Number 0220, Material Set 620001596, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6205901A, Project Item Line Number 0230, Material Set 6205901A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6205901A, Project Item Line Number 0230, Material Set 6205901A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6205902A, Project Item Line Number 0240, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3276, Item 6205902A, Project Item Line Number 0240, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-C06, Contract Project J4P3276, Project Item Line Number 0040, Contract Line Item Number 0040, Item 3049910, Minor Item.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-C06, Contract Project J4P3276, Project Item Line Number 0060, Contract Line Item Number 0060, Item 4030015, Minor Item.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-C06, Contract Project J4P3276, Project Item Line Number 0150, Contract Line Item Number 0150, Item 6133020, Minor Item.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-C06, Contract Project J4P3276, Project Item Line Number 0220, Contract Line Item Number 0220, Item 6200015, Minor Item.	No Remark was entered by Engineer	hathak1	Overridden

Revision 4/1/2020 Page 4 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-C06	J4P3276	0001	0010	1099901	MISC.ELECTRONIC TICKETING	1.00	0.00	1.00	LS	1.00	\$1,000.00	\$1,000.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$9,200.00	\$9,200.00
		0001	0030	2153000	SHAPING SLOPES, CLASS III	4.00	0.00	4.00	100F	4.00	\$1,400.00	\$5,600.00
		0001	0040	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	490.00	0.00	490.00	TONS	1,032.86	\$61.48	\$63,500.23
		0001	0050	3105002	GRAVEL (A) OR CRUSHED STONE (B)	68.00	0.00	68.00	TONS	0.00	\$133.27	\$0.00
		0001	0060	4030015	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP048F MIX)	4,983.00	0.00	4,983.00	TONS	5,015.03	\$72.01	\$361,132.31
		0001	0070	4030101	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)	16,619.00	0.00	16,619.00	TONS	15,532.22	\$60.53	\$940,165.28
		0001	0800	4071005	TACK COAT	23,264.00	0.00	23,264.00	GAL	19,544.00	\$2.50	\$48,860.00
		0001	0090	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$1,000.00	\$2,000.00
		0001	0100	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	320.00	0.00	320.00	SQYD	306.70	\$443.15	\$135,914.10
		0001	0110	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	32.00	0.00	32.00	SQYD	0.00	\$1.20	\$0.00
		0001	0120	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	32.00	0.00	32.00	SQYD	0.00	\$1.20	\$0.00
		0001	0130	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	1,200.00	0.00	1,200.00	LF	1,123.00	\$1.50	\$1,684.50
		0001	0140	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	800.00	0.00	800.00	EA	566.00	\$5.45	\$3,084.70
		0001	0150	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	363.90	0.00	363.90	TONS	447.10	\$94.22	\$42,125.76
		0001	0160	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	2,202.10	0.00	2,202.10	SQYD	2,179.10	\$49.12	\$107,037.39
		0001	0170	6161005	CONSTRUCTION SIGNS	1,429.00	0.00	1,429.00	SQFT	559.50	\$6.00	\$3,357.00
		0001	0180	6161009	FLAG ASSEMBLY	13.00	0.00	13.00	EA	12.00	\$25.00	\$300.00
		0001	0190	6161025	CHANNELIZER (TRIM LINE)	163.00	0.00	163.00	EA	163.00	\$12.00	\$1,956.00
		0001	0200	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.00
		0001	0210	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$124,822.36	\$124,822.36
		0001	0220	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	24.00	0.00	24.00	LF	33.00	\$31.00	\$1,023.00
		0001	0230	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	59,369.00	0.00	59,369.00	LF	41,830.00	\$0.14	\$5,856.20
		0001	0240	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	85,346.00	0.00	85,346.00	LF	62,980.00	\$0.20	\$12,596.00
		0001	0250	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	109,447.00	0.00	109,447.00	SQYD	72,974.00	\$0.74	\$54,000.76
		0001	0260	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	4,153.00	0.00	4,153.00	SQYD	934.00	\$6.69	\$6,248.46
		0001	0270	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	814.10	0.00	814.10	STA	686.80	\$16.88	\$11,593.18
		0001	0280	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	407.00	0.00	407.00	STA	387.10	\$18.98	\$7,347.16
		0010	0290	6061060	MGS GUARDRAIL	1,476.00	0.00	1,476.00	LF	1,476.00	\$24.00	\$35,424.00
		0010	0300	6061074	MGS HEIGHT AND BLOCK TRANSITION	8.00	0.00	8.00	EA	8.00	\$604.00	\$4,832.00
		0010	0310	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	8.00	0.00	8.00	EA	8.00	\$2,900.00	\$23,200.00
					Date as of Report Generated Date							\$2,018,860.40
191213-C06 Ove	erall - Total	Value Pos	ted to Dat	te as of Repo	ort Generated Date							\$2,018,860.40

Revision 4/1/2020 Page 5 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details from Line Item agency views.

No Agency View Details Exist

Page 6 of 14 Revision 4/1/2020



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0040	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material		6	Jun 16, 2020	SYSTEM	(\$63,500.23)	
				6	Jun 16, 2020	SYSTEM	\$63,500.23	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user hathak1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				7	Jul 1, 2020	SYSTEM	(\$63,500.23)	
				7	Jul 1, 2020	SYSTEM	\$63,500.23	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user hathak1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Other Item Adjustment	OADJ	7	Jul 1, 2020	hathak1	(\$33,375.03)	Adjustment for payment being made by the system for overrun.
		ŕ		8	Jul 15, 2020	hathak1	\$33,375.03	Overrun readjustment to correct system adjustment made on 7/15/20.
			OADJ - Tota	al			\$0.00	
	MISC. PERMANENT AGGREGATE EDGE		OVRN		Jun 16,	wilsor2	(\$33,375.03)	Pay tp PQ
	TREATMENT		OVKN		2020		,	* '
				7	Jul 1, 2020	SYSTEM	\$33,375.03	Pay tp PQ
			OVRN - Tot	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Overrun	Overrun	6	Jun 16, 2020	SYSTEM	\$20,279.79	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 18 on the current Payment Estimate.
				6	Jun 16, 2020	SYSTEM	\$13,095.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) overridding Payment Estimate Exception 18 on the current Payment Estimate.
				6	Jun 16, 2020	SYSTEM	(\$33,375.03)	
				7	Jul 1, 2020	SYSTEM	(\$33,375.03)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				7	Jul 1, 2020	SYSTEM	\$33,375.03	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 15 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$33,375.03)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
			Overrun - T	otal			(\$33,375.03)	
	Overrun - Total						(\$33,375.03)	
0040 -	· Total						(\$33,375.03)	
0060	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP048F MIX)		ACAD	5	Jun 2, 2020	hathak1		A/C Adjustment for 5015.03 tons of SP048 placed between May 16, 2020 and June 1, 2020.
			ACAD - Tot	al			(\$8,462.87)	
	Other Item Adjustment - Total						(\$8,462.87)	
	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP048F MIX)	Overrun	Overrun	5	Jun 2, 2020	SYSTEM	(\$2,187.38)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			Overrun - T	otal			(\$2,187.38)	
	Overrun - Total						(\$2,187.38)	
	ASPHALTIC CONCRETE MIXTURE PG	Price		5	Jun 2,	SYSTEM	(\$18,647.89)	Reference Item Price Adjustment Index Adjustment Type applied
	64-22 (SP048F MIX)		- Total		2020	5.51EW	(\$18,647.89)	is FUEL
			- Total					
	Price - Total						(\$18,647.89)	
0060	Total						(\$29,298.14)	
0070	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)	Material		6	Jun 16, 2020	SYSTEM	(\$940,165.28)	
				6	Jun 16, 2020	SYSTEM	\$940,165.28	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user hathak1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				7	Jul 1,	SYSTEM	(\$940,165.28)	

Revision 4/1/2020 Page 7 of 14



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0070	ASPHALTIC CONCRETE MIXTURE PG	Material			2020			
	64-22 (SP125C MIX)			7	Jul 1, 2020	SYSTEM	\$940,165.28	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user hathak1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$940,165.28)	
				8	Jul 15, 2020	SYSTEM	\$940,165.28	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user hathak1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$698,045.28)	
				9	Aug 3, 2020	SYSTEM	\$698,045.28	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user hathak1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$698,045.28)	
				10	Aug 17, 2020	SYSTEM	\$698,045.28	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)	Other Item Adjustment	ACAD	6	Jun 16, 2020	hathak1	(\$30,579.06)	For 15,532.22 tons of SP125C placed between June 2, 2020 and June 15, 2020
			ACAD - Tot	al			(\$30,579.06)	
	Other Item Adjustment - Total						(\$30,579.06)	
	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)	Price		6	Jun 16, 2020	SYSTEM	(\$52,598.32)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$52,598.32)	
	Price - Total						(\$52,598.32)	
	1.1							
0070 -							(\$83,177.38)	
0070 -		Material		5	Jun 2, 2020	SYSTEM		
	- Total	Material		5		SYSTEM SYSTEM	(\$83,177.38)	
	- Total	Material			2020 Jun 16,		(\$83,177.38) (\$22,500.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
	- Total	Material	- Total	6	2020 Jun 16, 2020 Jun 16,	SYSTEM	(\$83,177.38) (\$22,500.00) (\$48,860.00)	Payment Estimate Item Adjustment (0020) due to user hathak1 overridding Payment Estimate Exception 3 on the current
	- Total	Material	- Total	6	2020 Jun 16, 2020 Jun 16,	SYSTEM	(\$83,177.38) (\$22,500.00) (\$48,860.00) \$48,860.00	Payment Estimate Item Adjustment (0020) due to user hathak1 overridding Payment Estimate Exception 3 on the current
	TACK COAT TACK TACK TACK TACK TACK TACK TACK TACK	Material MaterialCredit	- Total	6	2020 Jun 16, 2020 Jun 16,	SYSTEM	(\$83,177.38) (\$22,500.00) (\$48,860.00) \$48,860.00 (\$22,500.00)	Payment Estimate Item Adjustment (0020) due to user hathak1 overridding Payment Estimate Exception 3 on the current
	TACK COAT TACK TACK TACK TACK TACK TACK TACK TACK		- Total	6	Jun 16, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM	(\$83,177.38) (\$22,500.00) (\$48,860.00) \$48,860.00 (\$22,500.00) (\$22,500.00)	Payment Estimate Item Adjustment (0020) due to user hathak1 overridding Payment Estimate Exception 3 on the current
	TACK COAT TACK TACK TACK TACK TACK TACK TACK TACK			6	Jun 16, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM	(\$83,177.38) (\$22,500.00) (\$48,860.00) \$48,860.00 (\$22,500.00) (\$22,500.00) \$22,500.00	Payment Estimate Item Adjustment (0020) due to user hathak1 overridding Payment Estimate Exception 3 on the current
	TACK COAT Material - Total TACK COAT			6	Jun 16, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM	(\$83,177.38) (\$22,500.00) (\$48,860.00) \$48,860.00 (\$22,500.00) (\$22,500.00) \$22,500.00	Payment Estimate Item Adjustment (0020) due to user hathak1 overridding Payment Estimate Exception 3 on the current
	Material - Total TACK COAT TACK COAT	MaterialCredit Other Item	- Total MDPA	6 6 5 6	2020 Jun 16, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM	(\$83,177.38) (\$22,500.00) (\$48,860.00) \$48,860.00 (\$22,500.00) (\$22,500.00) \$22,500.00 \$22,500.00 (\$22,500.00)	Payment Estimate Item Adjustment (0020) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
	Material - Total TACK COAT MaterialCredit - Total TACK COAT	MaterialCredit Other Item	- Total	6 6 5 6	Jun 16, 2020 Jun 16, 2020 Jun 16, 2020 Jun 2, 2020 Jun 16, 2020 Jun 2, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM hathak1	(\$83,177.38) (\$22,500.00) (\$48,860.00) \$48,860.00 (\$22,500.00) (\$22,500.00) \$22,500.00 \$22,500.00 \$22,500.00	Payment Estimate Item Adjustment (0020) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate. Inspector needs to enter material report for this item. This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on
0080	Material - Total TACK COAT MaterialCredit - Total TACK COAT Other Item Adjustment - Total	MaterialCredit Other Item	- Total MDPA	6 6 5 6	Jun 16, 2020 Jun 16, 2020 Jun 16, 2020 Jun 2, 2020 Jun 16, 2020 Jun 2, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM hathak1	(\$83,177.38) (\$22,500.00) (\$48,860.00) \$48,860.00 (\$22,500.00) (\$22,500.00) \$22,500.00 \$22,500.00 (\$22,500.00)	Payment Estimate Item Adjustment (0020) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate. Inspector needs to enter material report for this item. This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on
0080	Material - Total TACK COAT MaterialCredit - Total TACK COAT	MaterialCredit Other Item	- Total MDPA	6 6 5 6	Jun 16, 2020 Jun 16, 2020 Jun 16, 2020 Jun 2, 2020 Jun 16, 2020 Jun 2, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM hathak1	(\$83,177.38) (\$22,500.00) (\$48,860.00) \$48,860.00 (\$22,500.00) (\$22,500.00) \$22,500.00 \$22,500.00 (\$22,500.00) \$22,500.00	Payment Estimate Item Adjustment (0020) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate. Inspector needs to enter material report for this item. This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on
0080	Material - Total TACK COAT MaterialCredit - Total TACK COAT TACK COAT Other Item Adjustment - Total FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH	MaterialCredit Other Item	- Total MDPA	6 6 5 6	Jun 16, 2020 Jun 16, 2020 Jun 16, 2020 Jun 2, 2020 Jun 16, 2020 Jun 2, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM hathak1 wilsor2	(\$83,177.38) (\$22,500.00) (\$48,860.00) \$48,860.00 (\$22,500.00) (\$22,500.00) \$22,500.00 \$22,500.00 (\$22,500.00) \$0.00	Payment Estimate Item Adjustment (0020) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate. Inspector needs to enter material report for this item. This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on
0080	Material - Total TACK COAT MaterialCredit - Total TACK COAT Other Item Adjustment - Total FURNISHING AND PLACING CONCRETE	MaterialCredit Other Item Adjustment	- Total MDPA	6 6 5 6	Jun 16, 2020 May 18, May 18,	SYSTEM SYSTEM SYSTEM hathak1 wilsor2	(\$83,177.38) (\$22,500.00) (\$48,860.00) \$48,860.00 (\$22,500.00) (\$22,500.00) \$22,500.00 \$22,500.00 (\$22,500.00) \$22,500.00 \$0.00	Payment Estimate Item Adjustment (0020) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate. Inspector needs to enter material report for this item. This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on

Revision 4/1/2020 Page 8 of 14



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0100	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH	Material		6	Jun 16, 2020	SYSTEM	(\$135,914.10)	
	PAVEMENT REPAIR			6	Jun 16, 2020	SYSTEM	\$135,914.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user hathak1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				7	Jul 1, 2020	SYSTEM	(\$135,914.10)	
				7	Jul 1, 2020	SYSTEM	\$135,914.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user hathak1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$135,914.10)	
				8	Jul 15, 2020	SYSTEM	\$135,914.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hathak1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$135,914.10)	
				9	Aug 3, 2020	SYSTEM	\$135,914.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hathak1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$135,914.10)	
				10	Aug 17, 2020	SYSTEM	\$135,914.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user hathak1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				(\$135,914.10)	
	Material - Total						(\$135,914.10)	
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	MaterialCredit		6	Jun 16, 2020	SYSTEM	\$135,914.10	
			- Total				\$135,914.10	
	MaterialCredit - Total						\$135,914.10	
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Other Item Adjustment	MDPA	5	Jun 2, 2020	hathak1	\$135,914.10	Inspector needs to enter material report for this item.
	TAVEMENT NELTAIN			6	Jun 16, 2020	wilsor2	(\$135,914.10)	This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on Estimate 0005 by Hathak1.
			MDPA - Tot	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0100 -		Material		4	May 10	OVOTEL	\$0.00	
0140	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		4	May 18, 2020	SYSTEM	(\$3,084.70)	
				4	May 18, 2020	SYSTEM	\$3,084.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$3,084.70)	
				6	Jun 16, 2020	SYSTEM	(\$3,084.70)	
				6	Jun 16, 2020	SYSTEM	\$3,084.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				7	Jul 1, 2020	SYSTEM	(\$3,084.70)	
				7	Jul 1, 2020	SYSTEM	\$3,084.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user hathak1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$3,084.70)	
				8	Jul 15,	SYSTEM	\$3,084.70	This adjustment offsets the original system-generated Overrun

Revision 4/1/2020 Page 9 of 14



Material Total	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
9	0140	AND INSTALLATION) FOR FULL DEPTH	Material			2020			overridding Payment Estimate Exception 5 on the current
2000 Payment Estimate Registered, (0003) due to user hathat seminary Payment Estimate Exception 5 on the current Payment Estimate International Exception 6 on the current Payment Estim					9		SYSTEM	(\$3,084.70)	
10					9		SYSTEM	\$3,084.70	Payment Estimate Item Adjustment (0006) due to user hathak1 overridding Payment Estimate Exception 5 on the current
Additional					10		SYSTEM	(\$3,084.70)	
Material - Total					10		SYSTEM	\$3,084.70	Payment Estimate Item Adjustment (0005) due to user hathak1 overridding Payment Estimate Exception 5 on the current
DOWEL BAY (DRILLING, FURNISHING) Material Credit				- Total				(\$3,084.70)	
AND INSTRUCTION SIGNS Material Crodit AND INSTRUCTION SIGNS Molerial CONSTRUCTION SIGNS Molerial AND INSTRUCTION SIGNS AND INSTRUCT		Material - Total						(\$3,084.70)	
Material Credit - Total DAYEL BAR (DRILLING, FURNISHING AD (Day 18) Adjustment Support S		AND INSTALLATION) FOR FULL DEPTH	MaterialCredit		6		SYSTEM	\$3,084.70	
DOWEL BAR DIDITION SIGNS Material - Total				- Total				\$3,084.70	
AND INSTALLATION FOR FULL DEPTH PAVEMENT REPAIR 2020		MaterialCredit - Total						\$3,084.70	
MDPA - Total S0.00 System Sys		AND INSTALLATION) FOR FULL DEPTH		MDPA	5		hathak1	\$3,084.70	Inspector needs to enter material report for this item.
Other Item Adjustment - Total \$0.00		· //vemettitei/iit			6		wilsor2	(\$3,084.70)	estimate, as a manual adjustment was made previously on
Sum				MDPA - Tota	al			\$0.00	
Display		Other Item Adjustment - Total						\$0.00	
STUMINOUS MATERIAL FOR CLASS C 2020	0140 -	- Total						\$0.00	
Overrun - Total	0150	BITUMINOUS MATERIAL FOR CLASS C	Overrun	Overrun	4		SYSTEM	(\$7,839.10)	
CONSTRUCTION SIGNS Material				Overrun - To	otal			(\$7,839.10)	
CONSTRUCTION SIGNS Material								(\$7,839.10)	
2020	0150 -	- Total						(\$7,839.10)	
2020 Payment Estimate Item Adjustment (0004) due to user hathat 1 overridding Payment Estimate Exception 6 on the current	0170	CONSTRUCTION SIGNS	Material			2020			
2020 6					4		SYSTEM	\$3,357.00	Payment Estimate Item Adjustment (0004) due to user hathak1 overridding Payment Estimate Exception 6 on the current
2020 6 Jun 16, 2020 8 SYSTEM \$3,357.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user hathak1 overridding Payment Estimate Exception 9 on the current Payment Estimate. CONSTRUCTION SIGNS MaterialCredit 6 Jun 16, 2020 SYSTEM \$3,357.00 CONSTRUCTION SIGNS Other Item Adjustment MDPA 5 Jun 2, 2020 Inspector needs to enter material report for this item. CONSTRUCTION SIGNS Other Item Adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on Estimate 0005 by Hathak1. MDPA - Total \$0.00 Other Item Adjustment - Total \$0.00					5		SYSTEM	(\$3,357.00)	
Payment Estimate Item Adjustment (0026) due to user hathak1 overridding Payment Estimate Exception 9 on the current Payment Estimate Exception 9 on the current Payment Estimate Exception 9 on the current Payment Estimate. Total					6		SYSTEM	(\$3,357.00)	
Material - Total CONSTRUCTION SIGNS MaterialCredit 6 Jun 16, 2020 \$YSTEM \$3,357.00 - Total \$3,357.00 MaterialCredit - Total \$3,357.00 CONSTRUCTION SIGNS Other Item Adjustment MDPA 5 Jun 2, 2020 hathak1 \$3,357.00 Inspector needs to enter material report for this item. MDPA - Total \$0.00 Other Item Adjustment - Total \$0.00 Other Item Adjustment - Total \$0.00					6		SYSTEM	\$3,357.00	Payment Estimate Item Adjustment (0026) due to user hathak1 overridding Payment Estimate Exception 9 on the current
CONSTRUCTION SIGNS MaterialCredit 6 Jun 16, 2020 \$3,357.00 MaterialCredit - Total \$3,357.00 MaterialCredit - Total \$3,357.00 CONSTRUCTION SIGNS Other Item Adjustment MDPA 5 Jun 2, 2020 hathak1 \$3,357.00 Inspector needs to enter material report for this item. MDPA - Total \$0.00 Other Item Adjustment - Total \$0.00				- Total					
- Total \$3,357.00 MaterialCredit - Total \$3,357.00 CONSTRUCTION SIGNS Other Item Adjustment Adjustment MDPA 5 Jun 2, 2020 6 Jun 16, 2020 (\$3,357.00) This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on Estimate 0005 by Hathak1. MDPA - Total \$0.00 Other Item Adjustment - Total \$0.00		Material - Total						(\$3,357.00)	
MaterialCredit - Total CONSTRUCTION SIGNS Other Item Adjustment MDPA 5 Jun 2, 2020 hathak1 \$3,357.00 Inspector needs to enter material report for this item. MDPA - Total MDPA - Total \$3,357.00 Inspector needs to enter material report for this item. (\$3,357.00) This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on Estimate 0005 by Hathak1. MDPA - Total \$0.00		CONSTRUCTION SIGNS	MaterialCredit		6		SYSTEM		
CONSTRUCTION SIGNS Other Item Adjustment MDPA 5 Jun 2, 2020 hathak1 \$3,357.00 Inspector needs to enter material report for this item.				- Total					
Adjustment 2020 6 Jun 16, 2020 Wilsor2 (\$3,357.00) This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on Estimate 0005 by Hathak1. MDPA - Total \$0.00 Other Item Adjustment - Total					_				
2020 estimaté, as a manual adjustment was made previously on Estimate 0005 by Hathak1. MDPA - Total \$0.00 Other Item Adjustment - Total \$0.00		CONSTRUCTION SIGNS		MDPA		2020			· ·
Other Item Adjustment - Total \$0.00					6		wilsor2	(\$3,357.00)	estimate, as a manual adjustment was made previously on
				MDPA - Tota	al			\$0.00	
0170 - Total \$0.00		Other Item Adjustment - Total						\$0.00	
	0170 -	- Total						\$0.00	

Revision 4/1/2020 Page 10 of 14



Line								
	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0180	FLAG ASSEMBLY	Material		4	May 18, 2020	SYSTEM	(\$300.00)	
				4	May 18, 2020	SYSTEM	\$300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$300.00)	
				6	Jun 16, 2020	SYSTEM	(\$300.00)	
				6	Jun 16, 2020	SYSTEM	\$300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user hathak1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				(\$300.00)	
	Material - Total						(\$300.00)	
	FLAG ASSEMBLY	MaterialCredit		6	Jun 16, 2020	SYSTEM	\$300.00	
			- Total				\$300.00	
	MaterialCredit - Total						\$300.00	
	FLAG ASSEMBLY	Other Item Adjustment	MDPA	5	Jun 2, 2020	hathak1	\$300.00	Inspector needs to enter material report for this item.
				6	Jun 16, 2020	wilsor2	(\$300.00)	This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on Estimate 0005 by Hathak1.
			MDPA - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0180 -	· Total						\$0.00	
0190	CHANNELIZER (TRIM LINE)	Material		4	May 18, 2020	SYSTEM	(\$1,956.00)	
				4	May 18, 2020	SYSTEM	\$1,956.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user hathak1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				5	Jun 2, 2020	SYSTEM	(\$1,956.00)	
				6	Jun 16, 2020	SYSTEM	(\$1,956.00)	
				6	Jun 16, 2020	SYSTEM	\$1,956.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user hathak1 overridding Payment Estimate Exception 11 on the current
								Payment Estimate.
			- Total				(\$1,956.00)	
	Material - Total		- Total				(\$1,956.00) (\$1,956.00)	
	Material - Total CHANNELIZER (TRIM LINE)	MaterialCredit	- Total	6	Jun 16, 2020	SYSTEM		
		MaterialCredit	- Total	6		SYSTEM	(\$1,956.00)	
		MaterialCredit		6		SYSTEM	(\$1,956.00) \$1,956.00	
	CHANNELIZER (TRIM LINE)	MaterialCredit Other Item Adjustment				SYSTEM hathak1	(\$1,956.00) \$1,956.00 \$1,956.00	
	CHANNELIZER (TRIM LINE) MaterialCredit - Total	Other Item	- Total		2020 Jun 2,		(\$1,956.00) \$1,956.00 \$1,956.00 \$1,956.00	Payment Estimate.
	CHANNELIZER (TRIM LINE) MaterialCredit - Total	Other Item	- Total	5	Jun 2, 2020 Jun 16,	hathak1	(\$1,956.00) \$1,956.00 \$1,956.00 \$1,956.00 \$1,956.00	Inspector needs to enter material report for this item. This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on
	CHANNELIZER (TRIM LINE) MaterialCredit - Total	Other Item	- Total MDPA	5	Jun 2, 2020 Jun 16,	hathak1	(\$1,956.00) \$1,956.00 \$1,956.00 \$1,956.00 \$1,956.00 (\$1,956.00)	Inspector needs to enter material report for this item. This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on
0190 -	CHANNELIZER (TRIM LINE) MaterialCredit - Total CHANNELIZER (TRIM LINE) Other Item Adjustment - Total	Other Item	- Total MDPA	5	Jun 2, 2020 Jun 16,	hathak1	(\$1,956.00) \$1,956.00 \$1,956.00 \$1,956.00 \$1,956.00 (\$1,956.00)	Inspector needs to enter material report for this item. This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on
0190 - 0200	CHANNELIZER (TRIM LINE) MaterialCredit - Total CHANNELIZER (TRIM LINE) Other Item Adjustment - Total Total CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	Other Item	- Total MDPA	5	Jun 2, 2020 Jun 16,	hathak1	(\$1,956.00) \$1,956.00 \$1,956.00 \$1,956.00 \$1,956.00) (\$1,956.00)	Inspector needs to enter material report for this item. This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on
	CHANNELIZER (TRIM LINE) MaterialCredit - Total CHANNELIZER (TRIM LINE) Other Item Adjustment - Total Total CHANGEABLE MESSAGE SIGN	Other Item Adjustment	- Total MDPA	5 6	Jun 2, 2020 Jun 16, 2020	hathak1 wilsor2	(\$1,956.00) \$1,956.00 \$1,956.00 \$1,956.00 \$1,956.00 (\$1,956.00) \$0.00 \$0.00	Inspector needs to enter material report for this item. This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on

Revision 4/1/2020 Page 11 of 14



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0200	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material		6	Jun 16, 2020	SYSTEM	(\$5,000.00)	
				6	Jun 16, 2020	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user hathak1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				(\$5,000.00)	
	Material - Total						(\$5,000.00)	
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	MaterialCredit		6	Jun 16, 2020	SYSTEM	\$5,000.00	
		- Total				\$5,000.00		
	MaterialCredit - Total					\$5,000.00		
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Other Item Adjustment	MDPA	5	Jun 2, 2020	hathak1	\$5,000.00	Inspector needs to enter material report for this item.
				6	Jun 16, 2020	wilsor2	(\$5,000.00)	This adjustment is to offset the Material Credit provided on this estimate, as a manual adjustment was made previously on Estimate 0005 by Hathak1.
		MDPA - Tota	al			\$0.00		
	Other Item Adjustment - Total						\$0.00	
0200 -	Total						\$0.00	
0220	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		6	Jun 16, 2020	SYSTEM	(\$1,023.00)	
				6	Jun 16, 2020	SYSTEM	\$1,023.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user hathak1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				7	Jul 1, 2020	SYSTEM	(\$1,023.00)	
				7	Jul 1, 2020	SYSTEM	\$1,023.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hathak1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$1,023.00)	
				8	Jul 15, 2020	SYSTEM	\$1,023.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$1,023.00)	
				9	Aug 3, 2020	SYSTEM	\$1,023.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$1,023.00)	
				10	Aug 17, 2020	SYSTEM	\$1,023.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user hathak1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total						\$0.00	
		Other Item Adjustment	OADJ	7	Jul 1, 2020	hathak1	(\$279.00)	Adjustment for payment being made by the system for overrun.
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE		OADJ - Tota	ıl			(\$279.00)	
			OVRN	6	Jun 16, 2020	wilsor2	(\$279.00)	Pay to PQ
				7	Jul 1, 2020	SYSTEM	\$279.00	Pay to PQ
		OVRN - Tota	al			\$0.00		
	Other Item Adjustment - Total					(\$279.00)		
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Overrun	Overrun	6	Jun 16, 2020	SYSTEM	\$279.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) overridding Payment Estimate Exception 21 on the current Payment Estimate.

Revision 4/1/2020 Page 12 of 14



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type		Date	Ву		
0220	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Overrun	Overrun	6	Jun 16, 2020	SYSTEM	(\$279.00)	
				7	Jul 1, 2020	SYSTEM	(\$279.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				7	Jul 1, 2020	SYSTEM	\$279.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 18 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$279.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				8	Jul 15, 2020	SYSTEM	\$279.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 14 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$279.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				9	Aug 3, 2020	SYSTEM	\$279.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 14 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$279.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				10	Aug 17, 2020	SYSTEM	\$279.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 14 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0220 -	Total						(\$279.00)	
0230	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		6	Jun 16, 2020	SYSTEM	(\$5,856.20)	
				6	Jun 16, 2020	SYSTEM	\$5,856.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user hathak1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				7	Jul 1, 2020	SYSTEM	(\$5,856.20)	
				7	Jul 1, 2020	SYSTEM	\$5,856.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user hathak1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$5,856.20)	
				8	Jul 15, 2020	SYSTEM	\$5,856.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$5,856.20)	
				9	Aug 3, 2020	SYSTEM	\$5,856.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				10		SYSTEM	\$5,856.20 (\$5,856.20)	Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 7 on the current
					2020 Aug 17,			Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 7 on the current
			- Total	10	Aug 17, 2020 Aug 17,	SYSTEM	(\$5,856.20)	Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user hathak1 overridding Payment Estimate Exception 7 on the current
	Material - Total		- Total	10	Aug 17, 2020 Aug 17,	SYSTEM	(\$5,856.20) \$5,856.20	Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user hathak1 overridding Payment Estimate Exception 7 on the current
0230 -			- Total	10	Aug 17, 2020 Aug 17,	SYSTEM	(\$5,856.20) \$5,856.20 \$0.00	Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user hathak1 overridding Payment Estimate Exception 7 on the current
0230 - 0240	Total 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L	Material	- Total	10	Aug 17, 2020 Aug 17,	SYSTEM	(\$5,856.20) \$5,856.20 \$0.00	Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user hathak1 overridding Payment Estimate Exception 7 on the current
	Total 6 IN. WHITE HIGH BUILD WATERBORNE	Material	- Total	10	2020 Aug 17, 2020 Aug 17, 2020 Jun 16,	SYSTEM	(\$5,856.20) \$5,856.20 \$0.00 \$0.00	Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user hathak1 overridding Payment Estimate Exception 7 on the current
	Total 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L	Material	- Total	10 10	2020 Aug 17, 2020 Aug 17, 2020 Jun 16, 2020 Jun 16,	SYSTEM SYSTEM SYSTEM	(\$5,856.20) \$5,856.20 \$0.00 \$0.00 \$0.00 (\$12,596.00)	Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user hathak1 overridding Payment Estimate Item Adjustment (0034) due to user hathak1 overridding Payment Estimate Exception 16 on the current

Revision 4/1/2020 Page 13 of 14



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0240	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material						overridding Payment Estimate Exception 13 on the current Payment Estimate.
				8	Jul 15, 2020	SYSTEM	(\$12,596.00)	
				8	Jul 15, 2020	SYSTEM	\$12,596.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user hathak1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				9	Aug 3, 2020	SYSTEM	(\$12,596.00)	
				9	Aug 3, 2020	SYSTEM	\$12,596.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user hathak1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				10	Aug 17, 2020	SYSTEM	(\$12,596.00)	
				10	Aug 17, 2020	SYSTEM	\$12,596.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total						\$0.00	
0240 -	· Total						\$0.00	
0290	MGS GUARDRAIL	Construction Stockpile		1	Apr 2, 2020	SYSTEM	\$15,841.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Jul 1, 2020	SYSTEM	(\$15,841.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
	MGS GUARDRAIL	Material		7	Jul 1, 2020	SYSTEM	(\$35,424.00)	
				7	Jul 1, 2020	SYSTEM	\$35,424.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0290 -	Total						\$0.00	
0300	MGS HEIGHT AND BLOCK TRANSITION	Construction Stockpile		1	Apr 2, 2020	SYSTEM	\$2,224.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Jul 1, 2020	SYSTEM	(\$2,224.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		- Total				\$0.00		
	Construction Stockpile - Total						\$0.00	
	MGS HEIGHT AND BLOCK TRANSITION	Material		7	Jul 1, 2020	SYSTEM	(\$4,832.00)	
				7	Jul 1, 2020	SYSTEM	\$4,832.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user hathak1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0300 -	Total						\$0.00	
0310	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		1	Apr 2, 2020	SYSTEM	\$12,248.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Jul 1, 2020	SYSTEM	(\$12,248.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
	- Total						\$0.00	
	Construction Stockpile - Total						\$0.00	
0310 -	Total						\$0.00	
Overa	II - Total				(\$153,968.65)			

Revision 4/1/2020 Page 14 of 14