

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 30, 2020

Progress Estima	ate Number	Contract ID 191213-C07 Prime Contractor Amino Brothers		er 16, 2020 Original Contract Amoun er 30, 2020 Net Change Order Amoun Current Contract Amount	nt (\$4,666.10)		
Approval Date					By User		
September 30, 2020		Generated an	d Approved (and should be considere	ed Draft) at the Project Office Level by	stephb1		
October 1, 2020		Reviewed and Ap	proved (and should be considered Dra	aft) at the Resident Engineer Level by	karlic1		
October 2, 2020			Reviewed and Approved at the Cer	ntral Office Controllers Office Level by	greggd1		
Original Comp	letion Date	% of Current Contract Amoun	nt Complete				
November	rember 1, 2020 November 1, 2020 60.11%						

No Milestones Exist for Contract

Contract Total Pa	y For Estimate No. 14				
		This Estimate	Previous	To Date	
191213-C07					
	Total Posted Items Pay	\$69,512.36	\$854,313.86	\$923,826.22	
	Gross Item Adjustments	\$134.40	(\$3,082.80)	(\$2,948.40)	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	·		\$851,231.06	\$920,877.82	
Contract Total Pa	yable This Estimate:	\$69,646.76			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4S3202	0040	2035500	EMBANKMENT IN PLACE	CUYD	\$48.650	125	\$6,081.25
	0070	2071000	LINEAR GRADING CLASS 1	STA	\$1,793.000	3.1	\$5,558.30
	0090	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$27.450	203.9	\$5,597.06
	0140	4039905	MISC.OPTIONAL PAVEMENT 2	SQYD	\$67.050	203.9	\$13,671.50
	0190	6113020	FURNISHING TYPE 2 ROCK BLANKET	CUYD	\$26.300	350	\$9,205.00
	0200	6113040	PLACING TYPE 2 ROCK BLANKET	CUYD	\$23.800	350	\$8,330.00
	0410	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$9,957.000	0.25	\$2,489.25
	0750	9029902	MISC.OPTIONAL TRAFFIC SIGNAL DETECTORS	EA	\$4,645.000	4	\$18,580.00
Project J4S32	02 - Total						\$69,512.36
Overall - Tota							\$69,512.36

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	<u>Adjustr</u>	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3202	0090	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-2,404.2	\$27.45	(\$65,995.29)
	0090	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	2,404.2	\$27.45	\$65,995.29
	0130	MISC.	Material			-1,263.1	\$67.05	(\$84,690.86)
	0130	MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	1,263.1	\$67.05	\$84,690.86
	0170	8 IN. CONCRETE MEDIAN STRIP	Material			-28.3	\$102.00	(\$2,886.60)

Revision 4/1/2020 Page 1 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 30, 2020

Progress Estimate Number
14 Contract ID 191213-C07 Pay Period Start September 16, 2020 Original Contract Amount \$1,541,538.88 Pay Period End September 30, 2020 Original Contract Amount \$4,666.10 Current Contract Amount \$1,541,538.88 Pay Period End September 30, 2020 Original Contract Amount \$4,666.10 Current Contract Amount \$1,541,538.88 Pay Period End September 30, 2020 Original Contract Amount \$4,666.10 Current Contract Amount \$4,666.10 Curre

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3202	0170	8 IN. CONCRETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	28.3	\$102.00	\$2,886.60
	0190	FURNISHING TYPE 2 ROCK BLANKET	Material			-350	\$26.30	(\$9,205.00)
	0190	FURNISHING TYPE 2 ROCK BLANKET	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	350	\$26.30	\$9,205.00
	0350	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Other Item Adjustment	Material Discrepancy Payment Adjustment	This adjustment offsets the negative adjustment made on estimate 11.			\$132.00
	0360	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Other Item Adjustment	Material Discrepancy Payment Adjustment	This adjustment offsets the negative adjustment made on estimate 11.			\$2.40
	0420	CLASS B-1 CONCRETE (CULVERTS)	Material			-143.2	\$747.00	(\$106,970.40)
	0420	CLASS B-1 CONCRETE (CULVERTS)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user stephb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	143.2	\$747.00	\$106,970.40
	0430	REINFORCING STEEL (CULVERTS)	Material			-25,070	\$1.55	(\$38,858.50)
	0430	REINFORCING STEEL (CULVERTS)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	25,070	\$1.55	\$38,858.50
	0750	MISC.	Material			-4	\$4,645.00	(\$18,580.00)
	0750	MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user stephb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	4	\$4,645.00	\$18,580.00
otal								\$134.40

Revision 4/1/2020 Page 2 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4S3202	FAS S301(62)	Intersection improvements, grading, drainage	9	PLATTE	at Mattox Road		
Totals by J	Job Numbe	rs					
J4S3202		d Item Pay Item Adjustmer	its Gross It	tem Pay	This Estimate \$69,512.36 \$134.40 \$69,646.76	Previous \$854,313.86 (\$3,082.80) \$851,231.06	To Date \$923,826.22 (\$2,948.40) \$920,877.82
	Liquid	tive centive lated Damages Contract Adjust	ments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 3 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 3040506, Project Item Line Number 0090, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Working with materials to resolve discrepancy.	stephb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 4039905, Project Item Line Number 0130, Material Set 403990596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with materials to resolve discrepancy.	stephb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 6083008, Project Item Line Number 0170, Material Set 608300896, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with materials to resolve discrepancy.	stephb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 6083008, Project Item Line Number 0170, Material Set 608300896, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Working with materials to resolve discrepancy.	stephb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 6113020, Project Item Line Number 0190, Material Set 611302096, Material 0611EPM - Embankment Protection Material, Acceptance Action Generic 0611EPM is insufficient.	Working with materials to resolve discrepancy.	stephb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 7034041, Project Item Line Number 0420, Material Set 703404196, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Working with materials to resolve discrepancy.	stephb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 7061030, Project Item Line Number 0430, Material Set 706103096, Material 1036RSDFPL42M32 - Reinforcing Steel No. 10/M32 Gr 60/M420@, Acceptance Action Generic ReSteelBars is insufficient.	Working with materials to resolve discrepancy.	stephb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 7061030, Project Item Line Number 0430, Material Set 706103096, Material 1036RSDFPL42M36 - Reinforcing Steel No. 11/M36 Gr 60/M420@, Acceptance Action Generic ReSteelBars is insufficient.	Working with materials to resolve discrepancy.	stephb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 9029902, Project Item Line Number 0750, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with materials to resolve discrepancy.	stephb1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-C07, Contract Project J4S3202, Project Item Line Number 0320, Contract Line Item Number 0320, Item 6200015, Minor Item.	Item overrun will be addressed on a later change order.	stephb1	Overridden

Revision 4/1/2020 Page 4 of 17



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					eport Generated date and can differ from the posted am							
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-C07	J4S3202	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	1.00	\$17,260.00	\$17,260.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.75	\$46,719.00	\$35,039.25
		0001	0030	2031000	CLASS A EXCAVATION	974.00	0.00	974.00	CUYD	597.00	\$75.35	\$44,983.95
		0001	0040	2035500	EMBANKMENT IN PLACE	602.00	0.00	602.00	CUYD	277.00	\$48.65	\$13,476.05
		0001	0050	2036000	COMPACTING EMBANKMENT	635.00	0.00	635.00	CUYD	598.00	\$52.50	\$31,395.00
		0001	0060	2063300	CLASS 4 EXCAVATION	920.00	0.00	920.00	CUYD	920.00	\$36.40	\$33,488.00
		0001	0070	2071000	LINEAR GRADING CLASS 1	8.70	0.00	8.70	STA	7.60	\$1,793.00	\$13,626.80
		0001	0080	2153000	SHAPING SLOPES, CLASS III	2.00	0.00	2.00	100F	2.00	\$1,171.00	\$2,342.00
		0001	0090	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	3,082.00	0.00	3,082.00	SQYD	2,404.20	\$27.45	\$65,995.29
		0001	0100	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	111.00	0.00	111.00	TONS	0.00	\$56.55	\$0.00
		0001	0110	4010151	TYPE A3 SHOULDER	64.30	0.00	64.30	SQYD	0.00	\$86.50	\$0.00
		0001	0120	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	370.90	0.00	370.90	TONS	0.00	\$129.00	\$0.00
		0001	0130	4039905	MISC.OPTIONAL PAVEMENT 1	1,263.10	0.00	1,263.10	SQYD	1,263.10	\$67.05	\$84,690.86
		0001	0140	4039905	MISC.OPTIONAL PAVEMENT 2	1,754.80	0.00	1,754.80	SQYD	1,141.10	\$67.05	\$76,510.76
		0001	0150	4071005	TACK COAT	306.00	0.00	306.00	GAL	0.00	\$3.20	\$0.00
		0001	0160	6071050	CHAIN-LINK FENCE (RETAINING WALLS)	318.00	0.00	318.00	LF	0.00	\$52.70	\$0.00
		0001	0170	6083008	8 IN. CONCRETE MEDIAN STRIP	28.30	0.00	28.30	SQYD	28.30	\$102.00	\$2,886.60
		0001	0180	6085007	PAVED APPROACH, 7 IN.	253.80	0.00	253.80	SQYD	0.00	\$81.60	\$0.00
		0001	0190	6113020	FURNISHING TYPE 2 ROCK BLANKET	735.00	0.00	735.00	CUYD	350.00	\$26.30	\$9,205.00
		0001	0200	6113040	PLACING TYPE 2 ROCK BLANKET	735.00	0.00	735.00	CUYD	350.00	\$23.80	\$8,330.00
		0001	0210	6161005	CONSTRUCTION SIGNS	896.00	0.00	896.00	SQFT	670.00	\$5.85	\$3,919.50
		0001	0220	6161008	ADVANCED WARNING RAIL SYSTEM	6.00	0.00	6.00	EA	6.00	\$29.30	\$175.80
		0001	0230	6161009	FLAG ASSEMBLY	6.00	0.00	6.00	EA	6.00	\$29.30	\$175.80
		0001	0240	6161025	CHANNELIZER (TRIM LINE)	76.00	0.00	76.00	EA	76.00	\$29.30	\$2,226.80
		0001	0250	6161030	TYPE III MOVEABLE BARRICADE	16.00	0.00	16.00	EA	16.00	\$146.00	\$2,336.00
		0001	0260	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$1,757.00	\$3,514.00
		0001	0270	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	5.00	0.00	5.00	EA	4.00	\$4,686.00	\$18,744.00
		0001	0280	6172000	CONCRETE TRAFFIC BARRIER, TYPE B	146.00	0.00	146.00	LF	0.00	\$152.00	\$0.00
		0001	0290	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$126,626.00	\$94,969.50
		0001	0300	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0001	0310	6191000	PAVEMENT EDGE TREATMENT	1,423.00	0.00	1,423.00	LF	0.00	\$5.75	\$0.00
		0001	0320	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	222.00	0.00	222.00	LF	306.00	\$17.55	\$5,370.30
		0001	0330	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	29.00	-14.00	15.00	LF	15.00	\$17.55	\$263.25
		0001	0340	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	10.00	0.00	10.00	EA	9.00	\$187.00	\$1,683.00
		0001	0350	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,223.00	125.00	2,348.00	LF	2,348.00	\$0.30	\$704.40
		0001	0360	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,722.00	6.00	2,728.00	LF	2,728.00	\$0.40	\$1,091.20
		0001	0370	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,757.00	0.00	1,757.00	LF	62.00	\$0.25	\$15.50
		0001	0380	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	2,219.00	0.00	2,219.00	LF	315.00	\$0.25	\$78.75
		0001	0390	6207001	PAVEMENT MARKING REMOVAL	1,137.00	9.00	1,146.00	LF	1,146.00	\$1.15	\$1,317.90
		0001	0400	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	748.00	0.00	748.00	SQYD	0.00	\$21.10	\$0.00
		0001	0410	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$9,957.00	\$9,957.00
		0001	0420	7034041	CLASS B-1 CONCRETE (CULVERTS)	417.20	0.00	417.20	CUYD	143.20	\$747.00	\$106,970.40
		0001	0430	7061030	REINFORCING STEEL (CULVERTS)	62,880.00	0.00	62,880.00	LB	25,070.00	\$1.55	\$38,858.50
		0001	0440	7250415	15 IN. PIPE GROUP C	34.00	0.00	34.00	LF	0.00	\$69.35	\$0.00
Revision 4/1/203	20											Page 5 of 17

Page 5 of 17 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-C07	J4S3202	0001	0450	7320815A	15 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	2.00	0.00	2.00	EA	0.00	\$1,075.00	\$0.00
		0001	0460	8051000A	SEEDING - COOL SEASON MIXTURES	0.80	0.00	0.80	ACRE	0.40	\$3,502.00	\$1,400.80
		0001	0470	8061004	SEDIMENT TRAP ROCK	6.80	0.00	6.80	CUYD	6.80	\$226.00	\$1,536.80
		0001	0480	8061005	ROCK DITCH CHECK	716.00	-716.00	0.00	LF	0.00	\$31.40	\$0.00
		0001	0490	8061016	SEDIMENT REMOVAL	74.00	0.00	74.00	CUYD	0.00	\$80.05	\$0.00
		0001	0500	8061019	SILT FENCE	1,250.00	0.00	1,250.00	LF	1,137.00	\$1.85	\$2,103.45
		0010	0510	6061074	MGS HEIGHT AND BLOCK TRANSITION	2.00	0.00	2.00	EA	2.00	\$1,171.00	\$2,342.00
		0010	0520	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	2.00	\$3,514.00	\$7,028.00
		0030	0530	9020213	SIGNAL HEAD, TYPE 3S	3.00	0.00	3.00	EA	3.00	\$879.00	\$2,637.00
		0030	0540	9020513	SIGNAL HEAD, TYPE 3B	9.00	0.00	9.00	EA	9.00	\$1,078.00	\$9,702.00
		0030	0550	9020514	SIGNAL HEAD, TYPE 4B	2.00	0.00	2.00	EA	2.00	\$1,335.00	\$2,670.00
		0030	0560	9020833	SH-FLAT SHEET - SIGNAL SIGN	53.00	0.00	53.00	SQFT	53.00	\$49.80	\$2,639.40
		0030	0570	9020834	SIGNAL SIGN, MOUNTING HARDWARE	6.00	0.00	6.00	EA	6.00	\$70.30	\$421.80
		0030	0580	9022651	LUMINAIRE LED-A, 120 VOLT COMPATIBLE	4.00	0.00	4.00	EA	4.00	\$285.00	\$1,140.00
		0030	0590	9023135	POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM	1.00	0.00	1.00	EA	1.00	\$8,715.00	\$8,715.00
		0030	0600	9023145	POST, TYPE CL, 45 FT. ARM OR 13.7 M ARM	1.00	0.00	1.00	EA	1.00	\$11,948.00	\$11,948.00
		0030	0610	9023150	POST, TYPE CL, 50 FT. ARM OR 15.2 M ARM	2.00	0.00	2.00	EA	2.00	\$11,772.00	\$23,544.00
		0030	0620	9024281	CONTROLLER ASSEMBLY HOUSING, KEYBOARD ENTRY, 8 PHASE NEMA CONTROLLER	1.00	0.00	1.00	EA	1.00	\$15,860.00	\$15,860.00
		0030	0630	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	145.00	0.00	145.00	LF	145.00	\$11.15	\$1,616.75
		0030	0640	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	164.00	0.00	164.00	LF	164.00	\$11.35	\$1,861.40
		0030	0650	9027200	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	195.00	0.00	195.00	LF	195.00	\$12.70	\$2,476.50
		0030	0660	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	195.00	0.00	195.00	LF	195.00	\$14.25	\$2,778.75
		0030	0670	9028100	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	360.00	0.00	360.00	LF	360.00	\$4.15	\$1,494.00
		0030	0680	9028206	CABLE, 6 AWG 1 CONDUCTOR, POWER	210.00	0.00	210.00	LF	210.00	\$2.25	\$472.50
		0030	0690	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	1,140.00	0.00	1,140.00	LF	1,140.00	\$1.45	\$1,653.00
		0030	0700	9028311	CABLE, 16 AWG 7 CONDUCTOR	2,280.00	0.00	2,280.00	LF	2,280.00	\$2.00	\$4,560.00
		0030	0710	9028620	POWER SUPPLY ASSEMBLY, TYPE 2	1.00	0.00	1.00	EA	1.00	\$5,201.00	\$5,201.00
		0030	0720	9028811	PULL BOX, PREFORMED CLASS 2	3.00	0.00	3.00	EA	3.00	\$1,839.00	\$5,517.00
		0030	0730	9028812	PULL BOX, PREFORMED CLASS 3	1.00	0.00	1.00	EA	1.00	\$2,694.00	\$2,694.00
		0030	0740	9029100	BASE, CONCRETE	14.80	0.00	14.80	CUYD	14.80	\$1,617.00	\$23,931.60
		0030	0750	9029902	MISC.OPTIONAL TRAFFIC SIGNAL DETECTORS	4.00	0.00	4.00	EA	4.00	\$4,645.00	\$18,580.00
		0040	0760	9031010	CONCRETE FOOTINGS, EMBEDDED	0.90	0.00	0.90	CUYD	0.45	\$1,611.00	\$724.95
		0040	0770	9031250A	U-CHANNEL POST, 3 LB	7.00	0.00	7.00	LF	7.00	\$19.05	\$133.35
		0040	0780	9031270A	2 IN. PSST POST - 12 GA.	160.00	0.00	160.00	LF	80.00	\$15.80	\$1,264.00
		0040	0790	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	30.00	0.00	30.00	LF	15.00	\$41.60	\$624.00
		0040	0800	9035004A	SH-FLAT SHEET	24.00	0.00	24.00	SQFT	15.00	\$22.55	\$338.25
		0040	0810	9035069A	SHF-FLAT SHEET FLUORESCENT	26.00	0.00	26.00	SQFT	0.00	\$26.35	\$0.00
		0050	0820	9109902	MISC.MODOT WIRELESS RADIO, WITH CABLE	2.00	0.00	2.00	EA	2.00	\$8,001.00	\$16,002.00
		0050	5001	8061006	ALTERNATE DITCH CHECK	0.00	716.00	716.00	LF	160.00	\$20.50	\$3,280.00
		0001	5002	4039905	MISC.High Early Strength Concrete	0.00	0.00	0.00	SQYD	0.00	\$76.79	\$0.00
		0001	5003	9039901	MISC.Brulez Concrete Placer	0.00	1.00	1.00	LS	1.00	\$3,333.75	\$3,333.75
	Project J	4S3202 - <u>T</u> c	otal Value	Posted to D	ate as of Report Generated Date							\$923,826.20
191213-C07 Ove	erall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$923,826.20

Page 6 of 17 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4S3202

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0040	2035500	EMBANKMENT IN PLACE	9/19/20	9/24/20	125.00	CUYD	East Culvert	5+47		9+01		
0070	2071000	LINEAR GRADING CLASS 1	9/19/20	9/24/20	3.10	STA	Existing Road Bed and Turn Around.	0+16		5+71		
0090	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	9/19/20	9/24/20	203.90	SQYD	Over East Culvert	7+41.45		8+89.36		
0140	4039905	MISC.	9/19/20	9/24/20	203.90	SQYD	Over East Culvert	7+41.45		8+89.36		
0190	6113020	FURNISHING TYPE 2 ROCK BLANKET	9/19/20	9/24/20	350.00	CUYD	East Culvert	8+02		8+02		
0200	6113040	PLACING TYPE 2 ROCK BLANKET	9/19/20	9/24/20	350.00	CUYD	East Culvert	8+02		8+02		
0410	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	9/19/20	9/24/20	0.25	LS	East and West Culvert	8+02		5+86		
0750	9029902	MISC.	9/19/20	9/24/20	4.00	EA	Optional Detection System at Mattox and Platte Rd.	7+56.6		7+74		

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 7 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0040	EMBANKMENT IN PLACE	Material		2	Apr 2, 2020	SYSTEM	(\$1,313.55)	
				2	Apr 2, 2020	SYSTEM	\$1,313.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				3	Apr 17, 2020	SYSTEM	(\$1,313.55)	
				3	Apr 17, 2020	SYSTEM	\$1,313.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				4	May 1, 2020	SYSTEM	(\$1,313.55)	
				4	May 1, 2020	SYSTEM	\$1,313.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				5	May 18, 2020	SYSTEM	(\$1,313.55)	
				5	May 18, 2020	SYSTEM	\$1,313.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				6	Jun 2, 2020	SYSTEM	(\$1,313.55)	
				6	Jun 2, 2020	SYSTEM	\$1,313.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0040 -								
	Total						\$0.00	
0050	COMPACTING EMBANKMENT	Material		2	Apr 2, 2020	SYSTEM	\$0.00 (\$20,475.00)	
		Material		2		SYSTEM SYSTEM		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		Material			2020 Apr 2,		(\$20,475.00)	Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current
		Material		2	2020 Apr 2, 2020 Apr 17,	SYSTEM	(\$20,475.00) \$20,475.00	Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current
		Material		2	2020 Apr 2, 2020 Apr 17, 2020 Apr 17,	SYSTEM	(\$20,475.00) \$20,475.00 (\$20,475.00)	Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user stephb1 overridding Payment Estimate Exception 2 on the current
		Material		3	2020 Apr 2, 2020 Apr 17, 2020 Apr 17, 2020 May 1,	SYSTEM SYSTEM SYSTEM	(\$20,475.00) \$20,475.00 (\$20,475.00) \$20,475.00	Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user stephb1 overridding Payment Estimate Exception 2 on the current
		Material		3 3 4	2020 Apr 2, 2020 Apr 17, 2020 Apr 17, 2020 May 1, 2020 May 1,	SYSTEM SYSTEM SYSTEM	(\$20,475.00) \$20,475.00 (\$20,475.00) \$20,475.00 (\$27,982.50)	Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current
		Material		2 3 3 4 4	2020 Apr 2, 2020 Apr 17, 2020 Apr 17, 2020 May 1, 2020 May 1, 2020 May 18,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$20,475.00) \$20,475.00 (\$20,475.00) \$20,475.00 (\$27,982.50) \$27,982.50	Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current
		Material		2 3 3 4 4 5	2020 Apr 2, 2020 Apr 17, 2020 Apr 17, 2020 May 1, 2020 May 18, 2020 May 18, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$20,475.00) \$20,475.00 (\$20,475.00) \$20,475.00 (\$27,982.50) \$27,982.50	Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current
		Material		2 3 3 4 4 5 5	2020 Apr 2, 2020 Apr 17, 2020 Apr 17, 2020 May 1, 2020 May 18, 2020 May 18, 2020 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$20,475.00) \$20,475.00 (\$20,475.00) \$20,475.00 (\$27,982.50) \$27,982.50 (\$27,982.50)	Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current
		Material	- Total	2 3 3 4 4 5 5	2020 Apr 2, 2020 Apr 17, 2020 Apr 17, 2020 Apr 17, 2020 May 1, 2020 May 18, 2020 Jun 2, 2020 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$20,475.00) \$20,475.00 (\$20,475.00) \$20,475.00 (\$27,982.50) \$27,982.50 (\$27,982.50) \$27,982.50	Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		Material	- Total	2 3 3 4 4 5 5	2020 Apr 2, 2020 Apr 17, 2020 Apr 17, 2020 Apr 17, 2020 May 1, 2020 May 18, 2020 Jun 2, 2020 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$20,475.00) \$20,475.00 (\$20,475.00) \$20,475.00 (\$27,982.50) \$27,982.50 (\$27,982.50) \$27,982.50 (\$27,982.50)	Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
	COMPACTING EMBANKMENT	Material	- Total	2 3 3 4 4 5 5	2020 Apr 2, 2020 Apr 17, 2020 Apr 17, 2020 Apr 17, 2020 May 1, 2020 May 18, 2020 Jun 2, 2020 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$20,475.00) \$20,475.00 (\$20,475.00) \$20,475.00 (\$27,982.50) \$27,982.50 (\$27,982.50) \$27,982.50 (\$27,982.50) \$27,982.50	Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
0050	COMPACTING EMBANKMENT	Material	- Total	2 3 3 4 4 5 5	2020 Apr 2, 2020 Apr 17, 2020 Apr 17, 2020 Apr 17, 2020 May 1, 2020 May 18, 2020 Jun 2, 2020 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$20,475.00) \$20,475.00 (\$20,475.00) \$20,475.00 (\$27,982.50) \$27,982.50 (\$27,982.50) \$27,982.50 (\$27,982.50) \$27,982.50	Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.

Revision 4/1/2020 Page 8 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0090	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material	.,,,,,		2020			Payment Estimate Item Adjustment (0026) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				4	May 1, 2020	SYSTEM	(\$60,398.24)	
				4	May 1, 2020	SYSTEM	\$60,398.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				5	May 18, 2020	SYSTEM	(\$60,398.24)	
				5	May 18, 2020	SYSTEM	\$60,398.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				6	Jun 2, 2020	SYSTEM	(\$60,398.24)	
				6	Jun 2, 2020	SYSTEM	\$60,398.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				7	Jun 16, 2020	SYSTEM	(\$60,398.24)	
				7	Jun 16, 2020	SYSTEM	\$60,398.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				8	Jun 30, 2020	SYSTEM	(\$60,398.24)	
				8	Jul 1, 2020	SYSTEM	\$60,398.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				9	Jul 15, 2020	SYSTEM	(\$60,398.24)	
				9	Jul 15, 2020	SYSTEM	\$60,398.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				10	Aug 3, 2020	SYSTEM	(\$60,398.24)	
				10	Aug 3, 2020	SYSTEM	\$60,398.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				11	Aug 17, 2020	SYSTEM	(\$60,398.24)	
				11	Aug 17, 2020	SYSTEM	\$60,398.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				12	Sep 1, 2020	SYSTEM	(\$60,398.24)	
				12	Sep 1, 2020	SYSTEM	\$60,398.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				13	Sep 15, 2020	SYSTEM	(\$60,398.24)	
				13	Sep 16, 2020	SYSTEM	\$60,398.24	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				14	Sep 30, 2020	SYSTEM	(\$65,995.29)	
				14	Sep 30, 2020	SYSTEM	\$65,995.29	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	

Revision 4/1/2020 Page 9 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
0090 -	- Total						\$0.00					
0130	MISC. OPTIONAL PAVEMENT 1	Material		3	Apr 17, 2020	SYSTEM	(\$62,812.44)					
				3	Apr 17, 2020	SYSTEM	\$62,812.44	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user stephb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.				
				4	May 1, 2020	SYSTEM	(\$84,690.86)					
				4	May 1, 2020	SYSTEM	\$84,690.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.				
				5	May 18, 2020	SYSTEM	(\$84,690.86)					
				5	May 18, 2020	SYSTEM	\$84,690.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.				
				6	Jun 2, 2020	SYSTEM	(\$84,690.86)					
				6	Jun 2, 2020	SYSTEM	\$84,690.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.				
				7	Jun 16, 2020	SYSTEM	(\$84,690.86)					
								7	Jun 16, 2020	SYSTEM	\$84,690.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				8	Jun 30, 2020	SYSTEM	(\$84,690.86)					
				8	Jul 1, 2020	SYSTEM	\$84,690.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
							9	Jul 15, 2020	SYSTEM	(\$84,690.86)		
				9	Jul 15, 2020	SYSTEM	\$84,690.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
				10	Aug 3, 2020	SYSTEM	(\$84,690.86)					
				10	Aug 3, 2020	SYSTEM	\$84,690.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
				11	Aug 17, 2020	SYSTEM	(\$84,690.86)					
							11	Aug 17, 2020	SYSTEM	\$84,690.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
				12	Sep 1, 2020	SYSTEM	(\$84,690.86)					
								12	Sep 1, 2020	SYSTEM	\$84,690.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				13	Sep 15, 2020	SYSTEM	(\$84,690.86)					
					13	Sep 16, 2020	SYSTEM	\$84,690.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
				14	Sep 30, 2020	SYSTEM	(\$84,690.86)					
				14	Sep 30, 2020	SYSTEM	\$84,690.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1				

Revision 4/1/2020 Page 10 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0130	MISC. OPTIONAL PAVEMENT 1	Material						overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0130 -	- Total						\$0.00	
0140	MISC. OPTIONAL PAVEMENT 2	Material		3	Apr 17, 2020	SYSTEM	(\$62,839.26)	
				3	Apr 17, 2020	SYSTEM	\$62,839.26	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user stephb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	MISC. OPTIONAL PAVEMENT 2	Other Item Adjustment	MDPA	12	Sep 1, 2020	stephb1	\$8,019.18	This adjustment offsets the negative adjustment made on estimate 3.
			MDPA - Tota	al			\$8,019.18	
	Other Item Adjustment - Total						\$8,019.18	
	MISC. OPTIONAL PAVEMENT 2	Overrun	Overrun	3	Apr 17, 2020	SYSTEM	\$8,019.18	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) overridding Payment Estimate Exception 15 on the current Payment Estimate.
				3	Apr 17, 2020	SYSTEM	(\$8,019.18)	
				3	Apr 17, 2020	stephb1	(\$8,019.18)	This is to adjust for the system generated overrun and will be added when the CO goes through.
			Overrun - To	otal			(\$8,019.18)	
	Overrun - Total						(\$8,019.18)	
0140 -	- Total						\$0.00	
0170	8 IN. CONCRETE MEDIAN STRIP	Material		4	May 1, 2020	SYSTEM	(\$2,886.60)	
				4	May 1, 2020	SYSTEM	\$2,886.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				5	May 18, 2020	SYSTEM	(\$2,886.60)	
				5	May 18, 2020	SYSTEM	\$2,886.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stephb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				6	Jun 2, 2020	SYSTEM	(\$2,886.60)	
				6	Jun 2, 2020	SYSTEM	\$2,886.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stephb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				7	Jun 16, 2020	SYSTEM	(\$2,886.60)	
				7	Jun 16, 2020	SYSTEM	\$2,886.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				8	Jun 30, 2020	SYSTEM	(\$2,886.60)	
				8	Jul 1, 2020	SYSTEM	\$2,886.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				9	Jul 15, 2020	SYSTEM	(\$2,886.60)	
				9	Jul 15, 2020	SYSTEM	\$2,886.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				10	Aug 3, 2020	SYSTEM	(\$2,886.60)	
				10	Aug 3,	SYSTEM	\$2,886.60	This adjustment offsets the original system-generated Overrun

Revision 4/1/2020 Page 11 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0170	8 IN. CONCRETE MEDIAN STRIP	Material	, , , , , , , , , , , , , , , , , , ,		2020			Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				11	Aug 17, 2020	SYSTEM	(\$2,886.60)	
				11	Aug 17, 2020	SYSTEM	\$2,886.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				12	Sep 1, 2020	SYSTEM	(\$2,886.60)	
				12	Sep 1, 2020	SYSTEM	\$2,886.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				13	Sep 15, 2020	SYSTEM	(\$2,886.60)	
				13	Sep 16, 2020	SYSTEM	\$2,886.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				14	Sep 30, 2020	SYSTEM	(\$2,886.60)	
				14	Sep 30, 2020	SYSTEM	\$2,886.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0170 -	Total						\$0.00	
0190	FURNISHING TYPE 2 ROCK BLANKET	Material		14	Sep 30, 2020	SYSTEM	(\$9,205.00)	
				14	Sep 30, 2020	SYSTEM	\$9,205.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0190 -							\$0.00	
0270	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	Material		1	Mar 16, 2020	SYSTEM	(\$14,058.00)	
	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED			1	Mar 16, 2020	SYSTEM	\$14,058.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0270 -							\$0.00	
0320	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		11	Aug 17, 2020	SYSTEM	(\$5,370.30)	
				11	Aug 17, 2020	SYSTEM	\$5,370.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Overrun	Overrun	11	Aug 17, 2020	SYSTEM	(\$1,474.20)	
				11	Aug 17, 2020	SYSTEM	\$1,474.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 13 on the current Payment Estimate.
				11	Aug 17, 2020	stephb1	(\$1,474.20)	Item overrun will be addressed on a later Change Order.
				12	Sep 1, 2020	SYSTEM	(\$1,474.20)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
			Overrun - To	otal			(\$2,948.40)	

Revision 4/1/2020 Page 12 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0320	Overrun - Total						(\$2,948.40)	
0320 -	- Total						(\$2,948.40)	
0330	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		11	Aug 17, 2020	SYSTEM	(\$263.25)	
				11	Aug 17, 2020	SYSTEM	\$263.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user stephb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0330 -	- Total						\$0.00	
0340	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		11	Aug 17, 2020	SYSTEM	(\$1,683.00)	
				11	Aug 17, 2020	SYSTEM	\$1,683.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user stephb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0340 -	- Total						\$0.00	
0350	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		11	Aug 17, 2020	SYSTEM	(\$798.90)	
	7,, 1, 1, 2, 2, 2, 3			11	Aug 17, 2020	SYSTEM	\$798.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Other Item Adjustment	MDPA	14	Sep 30, 2020	stephb1	\$132.00	This adjustment offsets the negative adjustment made on estimate 11.
			MDPA - Tota	al			\$132.00	
	Other Item Adjustment - Total						\$132.00	
	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS		Overrun	11	Aug 17, 2020	SYSTEM	(\$132.00)	
				11	Aug 17, 2020	SYSTEM	\$132.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 14 on the current Payment Estimate.
				11	Aug 17, 2020	stephb1	(\$132.00)	Item Overrun will be addressed on a later Change Order.
				12	Sep 1, 2020	SYSTEM	(\$37.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				13	Sep 15, 2020	SYSTEM	\$37.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',0.30000 - 0.30000, 'is applied (if non-zero).
			Overrun - To	otal			(\$132.00)	
	Overrun - Total						(\$132.00)	
0350 -	- Total						\$0.00	
0360	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material		11	Aug 17, 2020	SYSTEM	(\$1,091.20)	
	BEADS			11	Aug 17, 2020	SYSTEM	\$1,091.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS		MDPA	14	Sep 30, 2020	stephb1	\$2.40	This adjustment offsets the negative adjustment made on estimate 11.
			MDPA - Tota	al			\$2.40	
	Other Item Adjustment - Total						\$2.40	
	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L	Overrun	Overrun	11	Aug 17, 2020	SYSTEM	(\$2.40)	

Revision 4/1/2020 Page 13 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0360	BEADS	Overrun	Overrun	11	Aug 17, 2020	SYSTEM	\$2.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 15 on the current Payment Estimate.
				11	Aug 17, 2020	stephb1	(\$2.40)	Item will be addressed on a later change order.
				12	Sep 1, 2020	SYSTEM	(\$2.40)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				13	Sep 15, 2020	SYSTEM	\$2.40	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',0.40000 - 0.40000, 'is applied (if non-zero).
			Overrun - T	otal			(\$2.40)	
	Overrun - Total						(\$2.40)	
0360 -	Total						\$0.00	
0390	PAVEMENT MARKING REMOVAL	Overrun	Overrun	11	Aug 17, 2020	SYSTEM	(\$10.35)	
				13	Sep 15, 2020	SYSTEM	\$10.35	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1.15000 - 1.15000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0390 -							\$0.00	
0420	CLASS B-1 CONCRETE (CULVERTS)	Material		12	Sep 1, 2020	SYSTEM	(\$106,970.40)	
				12	Sep 1, 2020	SYSTEM	\$106,970.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stephb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				13	Sep 15, 2020	SYSTEM	(\$106,970.40)	
				13	Sep 16, 2020	SYSTEM	\$106,970.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stephb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				14	Sep 30, 2020	SYSTEM	(\$106,970.40)	
				14	Sep 30, 2020	SYSTEM	\$106,970.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stephb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0420 -	Total						\$0.00	
0430	REINFORCING STEEL (CULVERTS)	Material		12	Sep 1, 2020	SYSTEM	(\$38,858.50)	
				12	Sep 1, 2020	SYSTEM	\$38,858.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user stephb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				13	Sep 15, 2020	SYSTEM	(\$38,858.50)	
				13	Sep 16, 2020	SYSTEM	\$38,858.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user stephb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				14	Sep 30, 2020	SYSTEM	(\$38,858.50)	
				14	Sep 30, 2020	SYSTEM	\$38,858.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0430 -	Total						\$0.00	
0460	SEEDING - COOL SEASON MIXTURES	Material		3	Apr 17, 2020	SYSTEM	(\$1,400.80)	
				3	Apr 17,	SYSTEM	\$1,400.80	This adjustment offsets the original system-generated Overrun

Revision 4/1/2020 Page 14 of 17



Description August									
A	Line	Description		Adjustment				Amount	Remarks
Major System Sy	0460	SEEDING - COOL SEASON MIXTURES	Material			2020			overridding Payment Estimate Exception 7 on the current
Payment Edinate In Application (1000) due to user setword operating Payment Edinate Exception 1 on the current Payment Edinate Exception 2 on the Current Payment Edinate Exception 3 on the Current Payment Edinate Exception 4 on the Current Payment Edinate Exception 3 on the Current Payment Edinate Exception 4 on the Current Payment Edinate Exception 5 on the Current Payment Edinate Exception 6 on the Curren					4		SYSTEM	(\$1,400.80)	
Material - Total 1980 19					4		SYSTEM	\$1,400.80	Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 11 on the current
1945 1945				- Total				\$0.00	
Material Total		Material - Total						\$0.00	
	0460 -	Total						\$0.00	
Payment Eliminate Claimate Item Adjustment (10007) due to user schmool overriding Payment Eliminate Exception 5 on the current Payment Eliminate (1007) due to user schmool overriding Payment Eliminate Eliminate Exception 5 on the current Payment Eliminate (1007) due to user schmool overriding Payment Eliminate (1007) due to user schmool overriding Payment Eliminate (1007) due to user schmool overriding Payment Eliminate Exception 5 on the current Payment Eliminate Exception 6 on the current Payment Eliminate Exception 8 on the current Payment Eliminate Exception 6 on the current Payment Eliminate Exception 8 on the current Payment Eliminate	0510	MGS HEIGHT AND BLOCK TRANSITION	Material		4		SYSTEM	(\$2,342.00)	
Material - Total So.00					4		SYSTEM	\$2,342.00	Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 5 on the current
Section Sect				- Total				\$0.00	
TYPE A CRASHWORTHY END Malerial FRMINAL (MASH) Malerial FRMINAL (MASH) May 1, 2000 SYSTEM SY028.00 SYSTEM		Material - Total						\$0.00	
TERMINAL (MASH)	0510 -	Total						\$0.00	
Payment Estimate Item Adjustment (008) due to user schrood overriding Payment Estimate Exception 8 on the current Payment Estimate Payment Estimate Payment Payment Estimate Payment Payment Estimate Payment Payment Payment Estimate Payment Payme	0520		Material		4		SYSTEM	(\$7,028.00)	
Material - Total So.00					4		SYSTEM	\$7,028.00	Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 8 on the current
Substitution Subs				- Total				\$0.00	
Sh-FLAT SHEET - SIGNAL SIGN Material Sh-FLAT SHEET - SIGNAL SIGN Sh-FLAT SH-F		Material - Total						\$0.00	
2020 10	0520 -	Total						\$0.00	
Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 5 on the current Payment Estimate Estimate Exception 5 on the current Payment Estimate Item Adjustment (0010) due to user stephb1 overridding Payment Estimate Item Adjustment (0010) due to user stephb1 overridding Payment Estimate Exception 8 on the current Payment Estimate Item Adjustment (0010) due to user stephb1 overridding Payment Estimate Exception 8 on the current Payment Estimate Item Adjustment (0009) due to user stephb1 overridding Payment Estimate Exception 8 on the current Payment Estimate Item Adjustment (0009) due to user stephb1 overridding Payment Estimate Exception 8 on the current Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 4 on the current Payment Estimate Exception 5 on the current Payment Estimate Except	0560	SH-FLAT SHEET - SIGNAL SIGN	Material		10		SYSTEM	(\$2,639.40)	
2020 12 Sep 1, 2020 20					10		SYSTEM	\$2,639.40	Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 5 on the current
2020 12 Sep 1, 2020 20					11		SYSTEM	(\$2,639.40)	
2020 Payment Estimate Item Adjustment (0010) due to user stephble overridding Payment Estimate Exception 8 on the current Payment Estimate Exception 8 on the current Payment Estimate. 13					12		SYSTEM	(\$2,639.40)	
2020 13 Sep 16, 2020 2					12		SYSTEM	\$2,639.40	Payment Estimate Item Adjustment (0010) due to user stephb1 overridding Payment Estimate Exception 8 on the current
2020 Payment Estimate Item Adjustment (0009) due to user stephb1 overridding Payment Estimate Exception 8 on the current Payment Father Estimate Exception 8 on the current Payment Father Estimate Exception 8 on the current Payment Estimate. SH-FLAT SHEET - SIGNAL SIGN MaterialCredit 12 Sep 1, 2020 SYSTEM \$2,639.40					13		SYSTEM	(\$2,639.40)	
Material - Total					13		SYSTEM	\$2,639.40	Payment Estimate Item Adjustment (0009) due to user stephb1 overridding Payment Estimate Exception 8 on the current
SH-FLAT SHEET - SIGNAL SIGN MaterialCredit 12 Sep 1, 2020 SYSTEM \$2,639.40				- Total				(\$2,639.40)	
CONDUIT, 2 IN., TRENCH WITH TRACER WIRE 2		Material - Total						(\$2,639.40)	
Material Credit - Total Solution		SH-FLAT SHEET - SIGNAL SIGN	MaterialCredit		12		SYSTEM	\$2,639.40	
0560 - Total CONDUIT, 2 IN., TRENCH WITH TRACER WIRE CONDUIT, 2 IN., TRENCH WITH TRACER WIRE Description of the control of				- Total				\$2,639.40	
CONDUIT, 2 IN., TRENCH WITH TRACER WIRE Apr 2, 2020 SYSTEM (\$590.95)		MaterialCredit - Total						\$2,639.40	
WIRE 2020 Apr 2, 2020 Apr 2, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. - Total \$0.00	0560 -	Total						\$0.00	
Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. - Total \$0.00	0630		Material		2		SYSTEM	(\$590.95)	
					2		SYSTEM	\$590.95	Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 4 on the current
Material - Total \$0.00				- Total				\$0.00	
		Material - Total						\$0.00	

Revision 4/1/2020 Page 15 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0630 -	Total						\$0.00	
0640	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material		2	Apr 2, 2020	SYSTEM	(\$204.30)	
				2	Apr 2, 2020	SYSTEM	\$204.30	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0640 -	Total						\$0.00	
0650	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	Material		2	Apr 2, 2020	SYSTEM	(\$965.20)	
				2	Apr 2, 2020	SYSTEM	\$965.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stephb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0650 -	Total						\$0.00	
0660	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	Material		2	Apr 2, 2020	SYSTEM	(\$1,083.00)	
				2	Apr 2, 2020	SYSTEM	\$1,083.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0660 -	Total						\$0.00	
0710	POWER SUPPLY ASSEMBLY, TYPE 2	Material		3	Apr 17, 2020	SYSTEM	(\$5,201.00)	
				3	Apr 17, 2020	SYSTEM	\$5,201.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user stephb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0710 -							\$0.00	
0720	PULL BOX, PREFORMED CLASS 2	Material		3	Apr 17, 2020	SYSTEM	(\$5,517.00)	
				3	Apr 17, 2020	SYSTEM	\$5,517.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user stephb1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0720 -							\$0.00	
0730	PULL BOX, PREFORMED CLASS 3	Material		3	Apr 17, 2020	SYSTEM	(\$2,694.00)	
				3	Apr 17, 2020	SYSTEM	\$2,694.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user stephb1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0730 -							\$0.00	
0750	MISC. OPTIONAL TRAFFIC SIGNAL DETECTORS	Material		14	Sep 30, 2020	SYSTEM	(\$18,580.00)	
				14	Sep 30, 2020	SYSTEM	\$18,580.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stephb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	

Revision 4/1/2020 Page 16 of 17



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0750 -	Total						\$0.00	
0770	U-CHANNEL POST, 3 LB	Material		4	May 1, 2020	SYSTEM	(\$133.35)	
				4	May 1, 2020	SYSTEM	\$133.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0770 -	Total						\$0.00	
0800	SH-FLAT SHEET	Material		4	May 1, 2020	SYSTEM	(\$338.25)	
				4	May 1, 2020	SYSTEM	\$338.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0800 -	Total						\$0.00	
5001	ALTERNATE DITCH CHECK	Material		2	Apr 2, 2020	SYSTEM	(\$164.00)	
				2	Apr 2, 2020	SYSTEM	\$164.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total				\$0.00			
5001 -	Total						\$0.00	
Overa	ıll - Total				(\$2,948.40)			

Revision 4/1/2020 Page 17 of 17