98.35%



Missouri Department of Transportation Contractor's Pay Estimate Summary

November 1, 2020

Pay Estimate Created Date: December 1, 2020

| Progress Estima 18 | ate Number | | 1213-C07 nino Brothers Co. Inc | | er 16, 2020 Original Contract Amour er 1, 2020 Net Change Order Amou Current Contract Amoun | nt (\$4,666.10) |
|-----------------------|--------------------------|-------|-----------------------------------|-------------------------------|---|-----------------|
| Approval Date | | | | | | By User |
| December 2, 2020 | | G | Generated and Approv | ved (and should be considered | d Draft) at the Project Office Level by | stephb1 |
| December 2, 2020 | | Revie | ewed and Approved (a | and should be considered Dra | ft) at the Resident Engineer Level by | warrem1 |
| December 3, 2020 | | | Revie | wed and Approved at the Cen | tral Office Controllers Office Level by | greggd1 |
| Original Comp | Original Completion Date | | etion Date | Actual Completion Date | % of Current Contract Amou | nt Complete |

No Milestones Exist for Contract

November 1, 2020

| Contract Total Page | y For Estimate No. 18 | | | |
|---------------------|----------------------------|---------------|----------------|----------------|
| | | This Estimate | Previous | To Date |
| 191213-C07 | | | | |
| | Total Posted Items Pay | \$209,394.19 | \$1,302,107.45 | \$1,511,501.64 |
| | Gross Item Adjustments | \$525.06 | (\$2,948.40) | (\$2,423.34) |
| | Incentive | \$0.00 | \$0.00 | \$0.00 |
| | Disincentive | \$0.00 | \$0.00 | \$0.00 |
| | Liquidated Damage | \$0.00 | \$0.00 | \$0.00 |
| | Other Contract Adjustments | \$0.00 | \$0.00 | \$0.00 |
| | | | \$1,299,159.05 | \$1,509,078.30 |
| Contract Total Pag | yable This Estimate: | \$209,919.25 | | |

Items Paid This Estimate Period

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount |
|-------------------|----------------|--------------|--|------|---------------|-----------------------------|--------------------------------|
| J4S3202 | 0020 | 2022010 | REMOVAL OF IMPROVEMENTS | LS | \$46,719.000 | 0.25 | \$11,679.75 |
| | 0040 | 2035500 | EMBANKMENT IN PLACE | CUYD | \$48.650 | 75 | \$3,648.75 |
| | 0050 | 2036000 | COMPACTING EMBANKMENT | CUYD | \$52.500 | 37 | \$1,942.50 |
| | 0070 | 2071000 | LINEAR GRADING CLASS 1 | STA | \$1,793.000 | 0.4 | \$717.20 |
| | 0090 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | SQYD | \$27.450 | 83.9 | \$2,303.06 |
| | 0100 | 3049910 | MISC.PERMANENT AGGREGATE EDGE TREATMENT | TONS | \$56.550 | 116 | \$6,559.80 |
| | 0110 | 4010151 | TYPE A3 SHOULDER | SQYD | \$86.500 | 64.3 | \$5,561.95 |
| | 0120 | 4011209 | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) | TONS | \$129.000 | 426.1 | \$54,966.90 |
| | 0140 | 4039905 | MISC.OPTIONAL PAVEMENT 2 | SQYD | \$67.050 | 451.4 | \$30,266.37 |
| | 0150 | 4071005 | TACK COAT | GAL | \$3.200 | 289 | \$924.80 |
| | 0160 | 6071050 | CHAIN-LINK FENCE (RETAINING WALLS) | LF | \$52.700 | 120 | \$6,324.00 |
| | 0180 | 6085007 | PAVED APPROACH, 7 IN. | SQYD | \$81.600 | 253.8 | \$20,710.08 |
| | 0270 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | EA | \$4,686.000 | 1 | \$4,686.00 |
| | 0290 | 6181000 | MOBILIZATION | LS | \$126,626.000 | 0.25 | \$31,656.50 |
| | 0300 | 6181020 | ADDITIONAL MOBILIZATION FOR SEEDING | EA | \$600.000 | 1 | \$600.00 |
| | 0310 | 6191000 | PAVEMENT EDGE TREATMENT | LF | \$5.750 | 1,423 | \$8,182.25 |
| | 0320 | 6200015 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | LF | \$17.550 | -84 | (\$1,474.20) |
| | 0340 | 6200021 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | EA | \$187.000 | 1 | \$187.00 |
| | 0370 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | LF | \$0.250 | 1,687 | \$421.75 |
| | 0380 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | LF | \$0.250 | 2,698 | \$674.50 |
| | 0400 | 6224010 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | SQYD | \$21.100 | 661.3 | \$13,953.43 |
| | 0460 | 8051000A | SEEDING - COOL SEASON MIXTURES | ACRE | \$3,502.000 | 0.4 | \$1,400.80 |
| | 0760 | 9031010 | CONCRETE FOOTINGS, EMBEDDED | CUYD | \$1,611.000 | 0.45 | \$724.95 |
| | 0780 | 9031270A | 2 IN. PSST POST - 12 GA. | LF | \$15.800 | 80 | \$1,264.00 |

Revision 4/1/2020 Page 1 of 22



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 1, 2020

| Progress Estimate Number | Contract ID | 191213-C07 | | Pay Period Start | November 16, 2020 | Original Contract Amount | \$1,541,538.88 |
|--------------------------|-------------------------|--------------------|------|------------------|-------------------|---------------------------------|----------------|
| 18 | Prime Contractor | Amino Brothers Co. | Inc. | Pay Period End | December 1, 2020 | Net Change Order Amount | (\$4,666.10) |
| 10 | | | | | | Current Contract Amount | \$1,536,872.78 |

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount |
|-------------------|----------------|--------------|-------------------------------------|------|------------|-----------------------------|--------------------------------|
| J4S3202 | 0790 | 9031271 | POST ANCHOR FOR 2 IN. PSST - 12 GA. | LF | \$41.600 | 15 | \$624.00 |
| | 0800 | 9035004A | SH-FLAT SHEET | SQFT | \$22.550 | 9 | \$202.95 |
| | 0810 | 9035069A | SHF-FLAT SHEET FLUORESCENT | SQFT | \$26.350 | 26 | \$685.10 |
| Project J | 4S3202 - | Total | | | | | \$209,394,19 |

Overall - Total \$209,394.19

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

| Project | Line | Item Description | Adjustment | Other Item | Comments | Adjustment | Line Item | Adjustment |
|---------|------|--|--------------------------|--|---|------------|--------------------------|------------------------|
| Number | No. | item Description | Туре | Adjustment Type | Comments | Quantity | Adjustment Unit Price | amount |
| 4S3202 | 0090 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Material | | | -3,082 | \$27.45 | (\$84,600.90 |
| | 0090 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | 3,082 | \$27.45 | \$84,600.90 |
| | 0100 | MISC. | Overrun | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 17 on the current Payment Estimate. | 5 | \$56.55 | \$282.75 |
| | 0100 | MISC. | Overrun | | | -5 | \$56.55 | (\$282.75 |
| | 0100 | MISC. | Material | | | -116 | \$56.55 | (\$6,559.80 |
| | 0100 | MISC. | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | 116 | \$56.55 | \$6,559.80 |
| | 0110 | TYPE A3 SHOULDER | Material | | | -64.3 | \$86.50 | (\$5,561.95 |
| | 0110 | TYPE A3 SHOULDER | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user stephb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | 64.3 | \$86.50 | \$5,561.95 |
| | 0120 | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) | Overrun | | | -55.2 | \$129.00 | (\$7,120.80) |
| | 0120 | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) | Overrun | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 18 on the current Payment Estimate. | 55.2 | \$129.00 | \$7,120.80 |
| | 0120 | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) | Other Item Adjustment | Asphalt Cement Price Adjustment | BP1 20-16 AC Price Adjustment, Installed on 11/17/2020 Current Index: 390 Base Index: 457.5 Difference: -67.5 Quantity: 426.10 Tons Virgin AC: 3.30% Adjustment: -\$949.14 | | | (\$949.14 ₎ |
| | 0130 | MISC. | Material | | | -1,263.1 | \$67.05 | (\$84,690.86 |
| | 0130 | MISC. | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user stephb1 overridding Payment Estimate Exception 7 on | 1,263.1 | \$67.05 | \$84,690.86 |

Revision 4/1/2020 Page 2 of 22



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 1, 2020

| ject nber | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
|--------------|-------------|--|--------------------|----------------------------------|---|------------------------|---------------------------------------|-------------------|
| 3202 | | | | | the current Payment Estimate. | | | |
| | 0160 | CHAIN-LINK FENCE (RETAINING WALLS) | Material | | | -120 | \$52.70 | (\$6,324.00 |
| | 0160 | CHAIN-LINK FENCE (RETAINING WALLS) | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0013) due to user stephb1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | 120 | \$52.70 | \$6,324.00 |
| | 0170 | 8 IN. CONCRETE MEDIAN STRIP | Material | | | -28.3 | \$102.00 | (\$2,886.60 |
| | 0170 | 8 IN. CONCRETE MEDIAN STRIP | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user stephb1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | 28.3 | \$102.00 | \$2,886.60 |
| | 0180 | PAVED APPROACH, 7 IN. | Material | | | -253.8 | \$81.60 | (\$20,710.08 |
| | 0180 | PAVED APPROACH, 7 IN. | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user stephb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. | 253.8 | \$81.60 | \$20,710.08 |
| | 0280 | CONCRETE TRAFFIC BARRIER, TYPE B | Material | | | -146 | \$152.00 | (\$22,192.00 |
| | 0280 | CONCRETE TRAFFIC BARRIER, TYPE B | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) due to user stephb1 overridding Payment Estimate Exception 13 on the current Payment Estimate. | 146 | \$152.00 | \$22,192.00 |
| | 0320 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | Overrun | | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',17.55000 - 17.55000, 'is applied (if non-zero). | 84 | \$17.55 | \$1,474.20 |
| | 0380 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Overrun | | | -794 | \$0.25 | (\$198.50 |
| | 0380 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Overrun | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 19 on the current Payment Estimate. | 794 | \$0.25 | \$198.50 |
| | 0420 | CLASS B-1 CONCRETE (CULVERTS) | Material | | | -417.2 | \$747.00 | (\$311,648.40 |
| | 0420 | CLASS B-1 CONCRETE (CULVERTS) | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0014) due to user stephb1 overridding Payment Estimate Exception 15 on the current Payment Estimate. | 417.2 | \$747.00 | \$311,648.40 |
| | 0460 | SEEDING - COOL SEASON MIXTURES | Material | | | -0.8 | \$3,502.00 | (\$2,801.60 |
| | 0460 | SEEDING - COOL SEASON MIXTURES | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0015) due to user stephb1 overridding Payment Estimate Exception 16 on the current Payment Estimate. | 0.8 | \$3,502.00 | \$2,801.60 |

Revision 4/1/2020 Page 3 of 22



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | | | | | | Contract Project Information | |
|-------------------|----------------------------|--|-------|---------|---|--|---|
| Project Number | Federal Proj. Number | Project Description | Route | County | | | Location of Work |
| J4S3202 | FAS S301(62) | Intersection improvements, grading, drainage | 9 | PLATTE | at Mattox Road | | |
| otals by | Job Numbe | ers | | | | | |
| J4S3202 | | d Item Pay Item Adjustmer | | tem Pay | This Estimate \$209,394.19 \$525.06 \$209,919.25 | Previous \$1,302,107.45 (\$2,948.40) \$1,299,159.05 | To Date \$1,511,501.64 (\$2,423.34) \$1,509,078.30 |
| | Incent | | | | \$0.00 | \$0.00 | \$0.00 |
| | | centive dated Damages | | | \$0.00 \$0.00 | \$0.00 \$0.00 | \$0.00 \$0.00 |
| | | Contract Adjust | ments | | \$0.00 | \$0.00 | \$0.00 |

Revision 4/1/2020 Page 4 of 22



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions / Discrepencies | Explanation | Entered By | Status |
|---|---|---------------|--------------|
| Estimate Exception Type: Exceeded Completion Time Exception: Contract 191213-C07, Time ID 00 DT, Time Type Completion Date, Current Completion Date 11/1/2020 11:59:00 PM. | Waiting on time extension change order to be signed and returned from contractor. | stephb1 | Acknowledged |
| Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 3040506, Project Item Line Number 0090, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient. | Working with materials and contractor to resolve discrepancy. | stephb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 3049910, Project Item Line Number 0100, Material Set 304991096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient. | Working with the contractor to receive aggregate tests. | stephb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 4010151, Project Item Line Number 0110, Material Set 401015196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | Working with materials and contractor to resolve discrepancy. | stephb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 4010151, Project Item Line Number 0110, Material Set 401015196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient. | Working with the contractor to resolve aggregate discrepancy. | stephb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 4010151, Project Item Line Number 0110, Material Set 401015196, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient. | Working with the contractor to resolve discrepancy. | stephb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 4039905, Project Item Line Number 0130, Material Set 403990596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient. | Working with the contractor to resolve discrepancy. | stephb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 6071050, Project Item Line Number 0160, Material Set 607105096, Material 1043FMCLFBAC60 - Chain Link Fence Fabric Alum Coated 60", Acceptance Action Generic 1043FMCLFBAC60 is insufficient. | Waiting on fence certification. | stephb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 6083008, Project Item Line Number 0170, Material Set 608300896, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient. | Working with contractor to resolve discrepancy. | stephb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 6085007, Project Item Line Number 0180, Material Set 608500796, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient. | Working with materials and contractor to resolve discrepancy. | stephb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 6085007, Project Item Line Number 0180, Material Set 608500796, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient. | Waiting on PAL form for the paved approach. | stephb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 6172000, Project Item Line Number 0280, Material Set 617200096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. | Waiting on QC test results. | stephb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 6172000, Project Item Line Number 0280, Material Set 617200096, Material 1036RSDFEC42M13 - Rein Steel EC No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient. | Waiting on PAL form from contractor. | stephb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 6172000, Project Item Line Number 0280, Material Set 617200096, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient. | Waiting on PAL form from contractor. | stephb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 7034041, Project Item Line Number 0420, Material Set 703404196, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. | Waiting on QC test results. | stephb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J4S3202, Item 8051000A, Project Item Line Number 0460, Material Set 8051000A96, Material 0802MLHS - Hydro Straw, Acceptance Action Generic 0802MLHS is insufficient. | Working with materials to resolve discrepancy. | stephb1 | Overridden |
| Estimate Exception Type: Item Overrun: Contract 191213-C07, Contract Project J4S3202, Project Item Line Number 0100, Contract Line Item Number 0100, Item 3049910, Minor Item. | Discrepancy will be resolved on a later change order. | stephb1 | Overridden |
| Estimate Exception Type: Item Overrun: Contract 191213-C07, Contract Project J4S3202, Project Item Line Number 0120, Contract Line Item Number 0120, Item 4011209, Minor Item. | Discrepancy will be resolved on a later change order. | stephb1 | Overridden |
| Estimate Exception Type: Item Overrun: Contract 191213-C07, Contract Project J4S3202, Project Item ine Number 0380, Contract Line Item Number 0380, Item 6206001C, Minor Item. | Discrepancy will be resolved on a later change order. | stephb1 | Overridden |

Revision 4/1/2020 Page 5 of 22



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Note: Posted Q | uantities | and Valu | es are b | ased on R | eport Generated date and can differ from the posted am | ount at the | time the | Estimate w | as Gene | erated. | | |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|---------|------------------------------------|--------------|--|
| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
| 191213-C07 | J4S3202 | 0001 | 0010 | 2013000 | CLEARING AND GRUBBING | 1.00 | 0.00 | 1.00 | ACRE | 1.00 | \$17,260.00 | \$17,260.00 |
| | | 0001 | 0020 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$46,719.00 | \$46,719.00 |
| | | 0001 | 0030 | 2031000 | CLASS A EXCAVATION | 974.00 | 0.00 | 974.00 | CUYD | 974.00 | \$75.35 | \$73,390.90 |
| | | 0001 | 0040 | 2035500 | EMBANKMENT IN PLACE | 602.00 | 0.00 | 602.00 | CUYD | 602.00 | \$48.65 | \$29,287.30 |
| | | 0001 | 0050 | 2036000 | COMPACTING EMBANKMENT | 635.00 | 0.00 | 635.00 | CUYD | 635.00 | \$52.50 | \$33,337.50 |
| | | 0001 | 0060 | 2063300 | CLASS 4 EXCAVATION | 920.00 | 0.00 | 920.00 | CUYD | 920.00 | \$36.40 | \$33,488.00 |
| | | 0001 | 0070 | 2071000 | LINEAR GRADING CLASS 1 | 8.70 | 0.00 | 8.70 | STA | 8.70 | \$1,793.00 | \$15,599.10 |
| | | 0001 | 0080 | 2153000 | SHAPING SLOPES, CLASS III | 2.00 | 0.00 | 2.00 | 100F | 2.00 | \$1,171.00 | \$2,342.00 |
| | | 0001 | 0090 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 3,082.00 | 0.00 | 3,082.00 | SQYD | 3,082.00 | \$27.45 | \$84,600.90 |
| | | 0001 | 0100 | 3049910 | MISC.PERMANENT AGGREGATE EDGE TREATMENT | 111.00 | 0.00 | 111.00 | TONS | 116.00 | \$56.55 | \$6,559.80 |
| | | 0001 | 0110 | 4010151 | TYPE A3 SHOULDER | 64.30 | 0.00 | 64.30 | SQYD | 64.30 | \$86.50 | \$5,561.95 |
| | | 0001 | 0120 | 4011209 | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) | 370.90 | 0.00 | 370.90 | TONS | 426.10 | \$129.00 | \$54,966.90 |
| | | 0001 | 0130 | 4039905 | MISC.OPTIONAL PAVEMENT 1 | 1,263.10 | 0.00 | 1,263.10 | SQYD | 1,263.10 | \$67.05 | \$84,690.86 |
| | | 0001 | 0140 | 4039905 | MISC.OPTIONAL PAVEMENT 2 | 1,754.80 | 0.00 | 1,754.80 | SQYD | 1,754.80 | \$67.05 | \$117,659.34 |
| | | 0001 | 0150 | 4071005 | TACK COAT | 306.00 | 0.00 | 306.00 | GAL | 289.00 | \$3.20 | \$924.80 |
| | | 0001 | 0160 | 6071050 | CHAIN-LINK FENCE (RETAINING WALLS) | 318.00 | 0.00 | 318.00 | LF | 120.00 | \$52.70 | \$6,324.00 |
| | | 0001 | 0170 | 6083008 | 8 IN. CONCRETE MEDIAN STRIP | 28.30 | 0.00 | 28.30 | SQYD | 28.30 | \$102.00 | \$2,886.60 |
| | | 0001 | 0180 | 6085007 | PAVED APPROACH, 7 IN. | 253.80 | 0.00 | 253.80 | SQYD | 253.80 | \$81.60 | \$20,710.08 |
| | | 0001 | 0190 | 6113020 | FURNISHING TYPE 2 ROCK BLANKET | 735.00 | 0.00 | 735.00 | CUYD | 735.00 | \$26.30 | \$19,330.50 |
| | | 0001 | 0200 | 6113040 | PLACING TYPE 2 ROCK BLANKET | 735.00 | 0.00 | 735.00 | CUYD | 735.00 | \$23.80 | \$17,493.00 |
| | | 0001 | 0210 | 6161005 | CONSTRUCTION SIGNS | 896.00 | 0.00 | 896.00 | SQFT | 670.00 | \$5.85 | \$3,919.50 |
| | | 0001 | 0220 | 6161008 | ADVANCED WARNING RAIL SYSTEM | 6.00 | 0.00 | 6.00 | EA | 6.00 | \$29.30 | \$175.80 |
| | | 0001 | 0230 | 6161009 | FLAG ASSEMBLY | 6.00 | 0.00 | 6.00 | EA | 6.00 | \$29.30 | \$175.80 |
| | | 0001 | 0240 | 6161025 | CHANNELIZER (TRIM LINE) | 76.00 | 0.00 | 76.00 | EA | 76.00 | \$29.30 | \$2,226.80 |
| | | 0001 | 0250 | 6161030 | TYPE III MOVEABLE BARRICADE | 16.00 | 0.00 | 16.00 | EA | 16.00 | \$146.00 | \$2,336.00 |
| | | 0001 | 0260 | 6161040 | FLASHING ARROW PANEL | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,757.00 | \$3,514.00 |
| | | 0001 | 0270 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 5.00 | 0.00 | 5.00 | EA | 5.00 | \$4,686.00 | \$23,430.00 |
| | | 0001 | 0280 | 6172000 | CONCRETE TRAFFIC BARRIER, TYPE B | 146.00 | 0.00 | 146.00 | LF | 146.00 | \$152.00 | \$22,192.00 |
| | | 0001 | 0290 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$126,626.00 | \$126,626.00 |
| | | 0001 | 0300 | 6181020 | ADDITIONAL MOBILIZATION FOR SEEDING | 4.00 | 0.00 | 4.00 | EA | 1.00 | \$600.00 | \$600.00 |
| | | 0001 | 0310 | 6191000 | PAVEMENT EDGE TREATMENT | 1,423.00 | 0.00 | 1,423.00 | LF | 1,423.00 | \$5.75 | \$8,182.25 |
| | | 0001 | 0320 | 6200015 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | 222.00 | 0.00 | 222.00 | LF | 222.00 | \$17.55 | \$3,896.10 |
| | | 0001 | 0330 | 6200018 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW | 29.00 | -14.00 | 15.00 | LF | 15.00 | \$17.55 | \$263.25 |
| | | 0001 | 0340 | 6200021 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | 10.00 | 0.00 | 10.00 | EA | 10.00 | \$187.00 | \$1,870.00 |
| | | 0001 | 0350 | 6205901A | 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 2,223.00 | 125.00 | 2,348.00 | LF | 2,348.00 | \$0.30 | \$704.40 |
| | | 0001 | 0360 | 6205902A | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 2,722.00 | 6.00 | 2,728.00 | LF | 2,728.00 | \$0.40 | \$1,091.20 |
| | | 0001 | 0370 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 1,757.00 | 0.00 | 1,757.00 | LF | 1,749.00 | \$0.25 | \$437.25 |
| | | 0001 | 0380 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 2,219.00 | 0.00 | 2,219.00 | LF | 3,013.00 | \$0.25 | \$753.25 |
| | | 0001 | 0390 | 6207001 | PAVEMENT MARKING REMOVAL | 1,137.00 | 9.00 | 1,146.00 | LF | 1,146.00 | \$1.15 | \$1,317.90 |
| | | 0001 | 0400 | 6224010 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | 748.00 | 0.00 | 748.00 | SQYD | 661.30 | \$21.10 | \$13,953.43 |
| | | 0001 | 0410 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$9,957.00 | \$9,957.00 |
| | | 0001 | 0420 | 7034041 | CLASS B-1 CONCRETE (CULVERTS) | 417.20 | 0.00 | 417.20 | CUYD | 417.20 | \$747.00 | \$311,648.40 |
| | | 0001 | 0430 | 7061030 | REINFORCING STEEL (CULVERTS) | 62,880.00 | 0.00 | 62,880.00 | LB | 62,880.00 | \$1.55 | \$97,464.00 |
| | | 0001 | 0440 | 7250415 | 15 IN. PIPE GROUP C | 34.00 | 0.00 | 34.00 | LF | 34.00 | \$69.35 | \$2,357.90 |
| Revision 4/1/203 | 20 | | | | | | | | | | | Page 6 of 22 |

Page 6 of 22 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|----------|-------------|--------------|---|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 191213-C07 | J4S3202 | 0001 | 0450 | 7320815A | 15 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,075.00 | \$2,150.00 |
| | | 0001 | 0460 | 8051000A | SEEDING - COOL SEASON MIXTURES | 0.80 | 0.00 | 0.80 | ACRE | 0.80 | \$3,502.00 | \$2,801.60 |
| | | 0001 | 0470 | 8061004 | SEDIMENT TRAP ROCK | 6.80 | 0.00 | 6.80 | CUYD | 6.80 | \$226.00 | \$1,536.80 |
| | | 0001 | 0480 | 8061005 | ROCK DITCH CHECK | 716.00 | -716.00 | 0.00 | LF | 0.00 | \$31.40 | \$0.00 |
| | | 0001 | 0490 | 8061016 | SEDIMENT REMOVAL | 74.00 | 0.00 | 74.00 | CUYD | 0.00 | \$80.05 | \$0.00 |
| | | 0001 | 0500 | 8061019 | SILT FENCE | 1,250.00 | 0.00 | 1,250.00 | LF | 1,137.00 | \$1.85 | \$2,103.45 |
| | | 0010 | 0510 | 6061074 | MGS HEIGHT AND BLOCK TRANSITION | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,171.00 | \$2,342.00 |
| | | 0010 | 0520 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$3,514.00 | \$7,028.00 |
| | | 0030 | 0530 | 9020213 | SIGNAL HEAD, TYPE 3S | 3.00 | 0.00 | 3.00 | EA | 3.00 | \$879.00 | \$2,637.00 |
| | | 0030 | 0540 | 9020513 | SIGNAL HEAD, TYPE 3B | 9.00 | 0.00 | 9.00 | EA | 9.00 | \$1,078.00 | \$9,702.00 |
| | | 0030 | 0550 | 9020514 | SIGNAL HEAD, TYPE 4B | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,335.00 | \$2,670.00 |
| | | 0030 | 0560 | 9020833 | SH-FLAT SHEET - SIGNAL SIGN | 53.00 | 0.00 | 53.00 | SQFT | 53.00 | \$49.80 | \$2,639.40 |
| | | 0030 | 0570 | 9020834 | SIGNAL SIGN, MOUNTING HARDWARE | 6.00 | 0.00 | 6.00 | EA | 6.00 | \$70.30 | \$421.80 |
| | | 0030 | 0580 | 9022651 | LUMINAIRE LED-A, 120 VOLT COMPATIBLE | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$285.00 | \$1,140.00 |
| | | 0030 | 0590 | 9023135 | POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$8,715.00 | \$8,715.00 |
| | | 0030 | 0600 | 9023145 | POST, TYPE CL, 45 FT. ARM OR 13.7 M ARM | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$11,948.00 | \$11,948.00 |
| | | 0030 | 0610 | 9023150 | POST, TYPE CL, 50 FT. ARM OR 15.2 M ARM | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$11,772.00 | \$23,544.00 |
| | | 0030 | 0620 | 9024281 | CONTROLLER ASSEMBLY HOUSING, KEYBOARD ENTRY, 8 PHASE NEMA CONTROLLER | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$15,860.00 | \$15,860.00 |
| | | 0030 | 0630 | 9025200 | CONDUIT, 2 IN., TRENCH WITH TRACER WIRE | 145.00 | 0.00 | 145.00 | LF | 145.00 | \$11.15 | \$1,616.75 |
| | | 0030 | 0640 | 9025300 | CONDUIT, 3 IN., TRENCH WITH TRACER WIRE | 164.00 | 0.00 | 164.00 | LF | 164.00 | \$11.35 | \$1,861.40 |
| | | 0030 | 0650 | 9027200 | CONDUIT, 2 IN., PUSHED WITH TRACER WIRE | 195.00 | 0.00 | 195.00 | LF | 195.00 | \$12.70 | \$2,476.50 |
| | | 0030 | 0660 | 9027300 | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE | 195.00 | 0.00 | 195.00 | LF | 195.00 | \$14.25 | \$2,778.75 |
| | | 0030 | 0670 | 9028100 | CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET | 360.00 | 0.00 | 360.00 | LF | 360.00 | \$4.15 | \$1,494.00 |
| | | 0030 | 0680 | 9028206 | CABLE, 6 AWG 1 CONDUCTOR, POWER | 210.00 | 0.00 | 210.00 | LF | 210.00 | \$2.25 | \$472.50 |
| | | 0030 | 0690 | 9028208 | CABLE, 8 AWG 1 CONDUCTOR, POWER | 1,140.00 | 0.00 | 1,140.00 | LF | 1,140.00 | \$1.45 | \$1,653.00 |
| | | 0030 | 0700 | 9028311 | CABLE, 16 AWG 7 CONDUCTOR | 2,280.00 | 0.00 | 2,280.00 | LF | 2,280.00 | \$2.00 | \$4,560.00 |
| | | 0030 | 0710 | 9028620 | POWER SUPPLY ASSEMBLY, TYPE 2 | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$5,201.00 | \$5,201.00 |
| | | 0030 | 0720 | 9028811 | PULL BOX, PREFORMED CLASS 2 | 3.00 | 0.00 | 3.00 | EA | 3.00 | \$1,839.00 | \$5,517.00 |
| | | 0030 | 0730 | 9028812 | PULL BOX, PREFORMED CLASS 3 | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$2,694.00 | \$2,694.00 |
| | | 0030 | 0740 | 9029100 | BASE, CONCRETE | 14.80 | 0.00 | 14.80 | CUYD | 14.80 | \$1,617.00 | \$23,931.60 |
| | | 0030 | 0750 | 9029902 | MISC.OPTIONAL TRAFFIC SIGNAL DETECTORS | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$4,645.00 | \$18,580.00 |
| | | 0040 | 0760 | 9031010 | CONCRETE FOOTINGS, EMBEDDED | 0.90 | 0.00 | 0.90 | CUYD | 0.90 | \$1,611.00 | \$1,449.90 |
| | | 0040 | 0770 | 9031250A | U-CHANNEL POST, 3 LB | 7.00 | 0.00 | 7.00 | LF | 7.00 | \$19.05 | \$133.35 |
| | | 0040 | 0780 | 9031270A | 2 IN. PSST POST - 12 GA. | 160.00 | 0.00 | 160.00 | LF | 160.00 | \$15.80 | \$2,528.00 |
| | | 0040 | 0790 | 9031271 | POST ANCHOR FOR 2 IN. PSST - 12 GA. | 30.00 | 0.00 | 30.00 | LF | 30.00 | \$41.60 | \$1,248.00 |
| | | 0040 | 0800 | 9035004A | SH-FLAT SHEET | 24.00 | 0.00 | 24.00 | SQFT | 24.00 | \$22.55 | \$541.20 |
| | | 0040 | 0810 | 9035069A | SHF-FLAT SHEET FLUORESCENT | 26.00 | 0.00 | 26.00 | SQFT | 26.00 | \$26.35 | \$685.10 |
| | | 0050 | 0820 | 9109902 | MISC.MODOT WIRELESS RADIO, WITH CABLE | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$8,001.00 | \$16,002.00 |
| | | 0050 | 5001 | 8061006 | ALTERNATE DITCH CHECK | 0.00 | 716.00 | 716.00 | LF | 160.00 | \$20.50 | \$3,280.00 |
| | | 0001 | 5002 | 4039905 | MISC.High Early Strength Concrete | 0.00 | 0.00 | 0.00 | SQYD | 0.00 | \$76.79 | \$0.00 |
| | | 0001 | 5003 | 9039901 | MISC.Brulez Concrete Placer | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$3,333.75 | \$3,333.75 |
| | Project J | | | | late as of Report Generated Date | | | | | | | \$1,511,501.60 |
| 191213-C07 Ove | | | | | ort Generated Date | | | | | | | \$1,511,501.60 |

Page 7 of 22 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4S3202

| Line Number | Item Code | Description | DWR Date | DWR Approval Date | Quantity Posted | Units | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------|--|-------------|-------------------------|--------------------|-------|--|------------------------------|---------------------|----------------------------|---------------------|----------|
| 0020 | 2022010 | REMOVAL OF IMPROVEMENTS | 11/24/20 | 11/24/20 | 0.25 | LS | Route 9 EB Shoulder. | 290+49 | | 284+92 | | |
| 0040 | 2035500 | EMBANKMENT IN PLACE | 11/24/20 | 11/24/20 | 75.00 | CUYD | West entrance. | 5+39.15 | | 9+01.55 | | |
| 0050 | 2036000 | COMPACTING EMBANKMENT | 11/24/20 | 11/24/20 | 37.00 | CUYD | West entrance | 5+39.15 | | 9+01.55 | | |
| 0070 | 2071000 | LINEAR GRADING CLASS 1 | 11/24/20 | 11/24/20 | 0.40 | STA | West entrance | 5+39.15 | | 9+01.55 | | |
| 0090 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 11/24/20 | 11/24/20 | 83.90 | SQYD | Pavement in radius. | 0+11.49 | | 0+63.34 | | |
| 0100 | 3049910 | MISC. AGGREGATE FOR BASE | 11/23/20 | 11/23/20 | 116.00 | TONS | NW Platte Rd. | 0+16.54 | | 14+66.51 | | |
| 0110 | 4010151 | TYPE A3 SHOULDER | 11/30/20 | 12/1/20 | 64.30 | SQYD | Route 9 right shoulder. | 284+22.14 | | 284+92.33 | | |
| 0120 | 4011209 | BIT. PAVEMENT MIXTURE PG64-22 (BP-1) | 11/17/20 | 11/18/20 | 426.10 | TONS | NW Platte Rd and Mattox Rd entrance | 4+59.7 | | 0+16.54 | | |
| 0140 | 4039905 | MISC. | 11/24/20 | 11/24/20 | 451.40 | SQYD | Pavement in radius. | 0+11.49 | | 0+63.34 | | |
| 0150 | 4071005 | TACK COAT | 11/17/20 | 11/18/20 | 289.00 | GAL | NW Platte Rd and Mattox Rd entrance. | 4+59.7 | | 0+16.54 | | |
| 0160 | 6071050 | CHAIN-LINK FENCE (RETAINING WALLS) | 11/30/20 | 12/1/20 | 120.00 | LF | Top slab for east and west culvert. | 5+96 | | 8+02 | | |
| 0180 | 6085007 | PAVED APPROACH, 7 IN. | 11/30/20 | 12/1/20 | 253.80 | SQYD | Paved approach. | 5+39.15 | | 3+33.64 | | |
| 0270 | 6161098A | CMS W/O COMMUNICATION INTERFACE, CONT F/ | 11/30/20 | 12/1/20 | 1.00 | EA | Additional CMS Board for north of project on N Helena Ave. | 284+77 | | 294+49 | | |
| 0290 | 6181000 | MOBILIZATION | 11/24/20 | 11/24/20 | 0.25 | LS | Final mobilization payment for 100% job completion. | 290+49 | | 294+90 | | |
| 0300 | 6181020 | | 11/24/20 | 11/24/20 | 1.00 | EA | Mobilization cost for remaining seed for project. | 290+49 | | 294+90 | | |
| 0310 | 6191000 | PAVEMENT EDGE TREATMENT | 11/23/20 | 11/23/20 | 1,423.00 | LF | Route 9 | 290+89 | | 294+90 | | |
| 0320 | 6200015 | PREF THERMO PVMT MARK, 24 IN WHIT | 11/30/20 | 12/1/20 | -84.00 | LF | Route 9 Stopbars. | 292+00 | | 295+04 | | |
| 0340 | 6200021 | PREF THERMO PVMT MARK, LT/RT ARROW | 11/23/20 | 11/23/20 | 1.00 | EA | NW Platte Rd. | 10+50 | | 14+44 | | |
| 0370 | 6206000C | 4 IN. WHITE WATERBORNE PAVEMENT MARKING | 11/23/20 | 11/23/20 | 1,687.00 | LF | NW Platte Rd. | 10+50 | | 14+44 | | |
| 0380 | 6206001C | 4 IN. YELLOW WATERBORNE PAVEMENT MARKING | 11/23/20 | 11/23/20 | 2,698.00 | LF | NW Platte Rd. | 15+40 | | 17+57 | | |
| 0400 | 6224010 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | 11/17/20 | 11/18/20 | 661.30 | SQYD | NW Platte Rd. | 4+59.7 | | 0+16.54 | | |
| 0460 | 8051000A | SEEDING - COOL SEASON MIXTURES | 11/24/20 | 11/24/20 | 0.40 | ACRE | NW Platte Rd. | 0+16.54 | | 9+01.55 | | |
| 0760 | 9031010 | CONCRETE FOOTINGS, EMBEDDED | 11/30/20 | 12/1/20 | 0.45 | CUYD | Route 9 construction signs. | 285+00 | | 287+66 | | |
| 0780 | 9031270A | 2 IN. PSST POST - 12 GA. | 11/30/20 | 12/1/20 | 80.00 | LF | Route 9 and NW Platte Rd construction signs. | 291+26 | | 8+59 | | |
| 0790 | 9031271 | POST ANCHOR FOR 2 IN. PSST - 12 GA. | 11/30/20 | 12/1/20 | 15.00 | LF | Route 9 and NW Platte Rd construction signs. | 291+26 | | 8+59 | | |
| 0800 | 9035004A | SH-FLAT SHEET | 11/30/20 | 12/1/20 | 9.00 | SQFT | Route 9 Construction signs. | 294+09 | | 8+59 | | |
| 0810 | 9035069A | SHF-FLAT SHEET FLUORESCENT | 11/30/20 | 12/1/20 | 26.00 | SQFT | Route 9 and NW Platte Rd construction signs. | 294+09 | | 15+76 | | |
| | | | | | | | | | | | | |

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 8 of 22



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|---|--------------------|---------------------------------------|---------------------------------|---|--|--|--|
| 0040 | EMBANKMENT IN PLACE | Material | , , , , , , , , , , , , , , , , , , , | 2 | Apr 2, 2020 | SYSTEM | (\$1,313.55) | |
| | | | | 2 | Apr 2, 2020 | SYSTEM | \$1,313.55 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 3 | Apr 17, 2020 | SYSTEM | (\$1,313.55) | |
| | | | | 3 | Apr 17, 2020 | SYSTEM | \$1,313.55 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 4 | May 1, 2020 | SYSTEM | (\$1,313.55) | |
| | | | | 4 | May 1, 2020 | SYSTEM | \$1,313.55 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 5 | May 18, 2020 | SYSTEM | (\$1,313.55) | |
| | | | | 5 | May 18, 2020 | SYSTEM | \$1,313.55 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 6 | Jun 2, 2020 | SYSTEM | (\$1,313.55) | |
| | | | | 6 | Jun 2, 2020 | SYSTEM | \$1,313.55 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | | | | | | | | |
| 0040 - | - Total | | | | | | \$0.00 | |
| 0040 - | COMPACTING EMBANKMENT | Material | | 2 | Apr 2, 2020 | SYSTEM | \$0.00 (\$20,475.00) | |
| | | Material | | 2 | | SYSTEM SYSTEM | | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | Material | | | 2020 Apr 2, | | (\$20,475.00) | Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current |
| | | Material | | 2 | 2020 Apr 2, 2020 Apr 17, | SYSTEM | (\$20,475.00) \$20,475.00 | Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current |
| | | Material | | 2 | 2020 Apr 2, 2020 Apr 17, 2020 Apr 17, | SYSTEM | (\$20,475.00) \$20,475.00 (\$20,475.00) | Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user stephb1 overridding Payment Estimate Exception 2 on the current |
| | | Material | | 3 | 2020 Apr 2, 2020 Apr 17, 2020 Apr 17, 2020 May 1, | SYSTEM SYSTEM SYSTEM | (\$20,475.00) \$20,475.00 (\$20,475.00) \$20,475.00 | Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user stephb1 overridding Payment Estimate Exception 2 on the current |
| | | Material | | 3 3 4 | 2020 Apr 2, 2020 Apr 17, 2020 Apr 17, 2020 May 1, 2020 May 1, | SYSTEM SYSTEM SYSTEM | (\$20,475.00) \$20,475.00 (\$20,475.00) \$20,475.00 (\$27,982.50) | Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current |
| | | Material | | 2 3 3 4 4 | 2020 Apr 2, 2020 Apr 17, 2020 Apr 17, 2020 May 1, 2020 May 1, 2020 May 18, | SYSTEM SYSTEM SYSTEM SYSTEM | (\$20,475.00) \$20,475.00 (\$20,475.00) \$20,475.00 (\$27,982.50) \$27,982.50 | Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current |
| | | Material | | 2 3 3 4 4 5 | 2020 Apr 2, 2020 Apr 17, 2020 Apr 17, 2020 May 1, 2020 May 18, 2020 May 18, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$20,475.00) \$20,475.00 (\$20,475.00) \$20,475.00 (\$27,982.50) \$27,982.50 | Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current |
| | | Material | | 2 3 3 4 4 5 5 | 2020 Apr 2, 2020 Apr 17, 2020 Apr 17, 2020 May 1, 2020 May 18, 2020 May 18, 2020 Jun 2, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$20,475.00) \$20,475.00 (\$20,475.00) \$20,475.00 (\$27,982.50) \$27,982.50 (\$27,982.50) | Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current |
| | | Material | - Total | 2 3 3 4 4 5 5 | 2020 Apr 2, 2020 Apr 17, 2020 Apr 17, 2020 Apr 17, 2020 May 1, 2020 May 18, 2020 Jun 2, 2020 Jun 2, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$20,475.00) \$20,475.00 (\$20,475.00) \$20,475.00 (\$27,982.50) \$27,982.50 (\$27,982.50) \$27,982.50 | Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| 0050 | COMPACTING EMBANKMENT Material - Total | Material | - Total | 2 3 3 4 4 5 5 | 2020 Apr 2, 2020 Apr 17, 2020 Apr 17, 2020 Apr 17, 2020 May 1, 2020 May 18, 2020 Jun 2, 2020 Jun 2, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$20,475.00) \$20,475.00 (\$20,475.00) \$20,475.00 (\$27,982.50) \$27,982.50 (\$27,982.50) \$27,982.50 (\$27,982.50) | Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | COMPACTING EMBANKMENT Material - Total | Material | - Total | 2 3 3 4 4 5 5 | 2020 Apr 2, 2020 Apr 17, 2020 Apr 17, 2020 Apr 17, 2020 May 1, 2020 May 18, 2020 Jun 2, 2020 Jun 2, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$20,475.00) \$20,475.00 (\$20,475.00) \$20,475.00 (\$27,982.50) \$27,982.50 (\$27,982.50) \$27,982.50 (\$27,982.50) \$27,982.50 | Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| 0050 | COMPACTING EMBANKMENT Material - Total | Material | - Total | 2 3 3 4 4 5 5 | 2020 Apr 2, 2020 Apr 17, 2020 Apr 17, 2020 Apr 17, 2020 May 1, 2020 May 18, 2020 Jun 2, 2020 Jun 2, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$20,475.00) \$20,475.00 (\$20,475.00) \$20,475.00 (\$27,982.50) \$27,982.50 (\$27,982.50) \$27,982.50 (\$27,982.50) \$27,982.50 | Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |

Revision 4/1/2020 Page 9 of 22



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|------|--|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| 0090 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Material | | | 2020 | | | Payment Estimate Item Adjustment (0026) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 4 | May 1, 2020 | SYSTEM | (\$60,398.24) | |
| | | | | 4 | May 1, 2020 | SYSTEM | \$60,398.24 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 5 | May 18, 2020 | SYSTEM | (\$60,398.24) | |
| | | | | 5 | May 18, 2020 | SYSTEM | \$60,398.24 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 6 | Jun 2, 2020 | SYSTEM | (\$60,398.24) | |
| | | | | 6 | Jun 2, 2020 | SYSTEM | \$60,398.24 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 7 | Jun 16, 2020 | SYSTEM | (\$60,398.24) | |
| | | | | 7 | Jun 16, 2020 | SYSTEM | \$60,398.24 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 8 | Jun 30, 2020 | SYSTEM | (\$60,398.24) | |
| | | | | 8 | Jul 1, 2020 | SYSTEM | \$60,398.24 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 9 | Jul 15, 2020 | SYSTEM | (\$60,398.24) | |
| | | | | 9 | Jul 15, 2020 | SYSTEM | \$60,398.24 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 10 | Aug 3, 2020 | SYSTEM | (\$60,398.24) | |
| | | | | 10 | Aug 3, 2020 | SYSTEM | \$60,398.24 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 11 | Aug 17, 2020 | SYSTEM | (\$60,398.24) | |
| | | | | 11 | Aug 17, 2020 | SYSTEM | \$60,398.24 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 12 | Sep 1, 2020 | SYSTEM | (\$60,398.24) | |
| | | | | 12 | Sep 1, 2020 | SYSTEM | \$60,398.24 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 13 | Sep 15, 2020 | SYSTEM | (\$60,398.24) | |
| | | | | 13 | Sep 16, 2020 | SYSTEM | \$60,398.24 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 14 | Sep 30, 2020 | SYSTEM | (\$65,995.29) | |
| | | | | 14 | Sep 30, 2020 | SYSTEM | \$65,995.29 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 15 | Oct 16, 2020 | SYSTEM | (\$70,450.42) | |

Revision 4/1/2020 Page 10 of 22



| Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks |
|--------|--|--------------------------|--------------------|--------|-----------------|---------|---------------|--|
| | | Туре | Adjustment Type | Number | Date | Ву | | |
| 0090 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Material | | 15 | Oct 16, 2020 | SYSTEM | \$70,450.42 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 16 | Nov 2, 2020 | SYSTEM | (\$70,450.42) | |
| | | | | 16 | Nov 2, 2020 | SYSTEM | \$70,450.42 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 17 | Nov 16, 2020 | SYSTEM | (\$82,297.84) | |
| | | | | 17 | Nov 16, 2020 | SYSTEM | \$82,297.84 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 18 | Dec 2, 2020 | SYSTEM | (\$84,600.90) | |
| | | | | 18 | Dec 2, 2020 | SYSTEM | \$84,600.90 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 19 | Dec 3, 2020 | SYSTEM | (\$84,600.90) | |
| | | | - Total | | | | (\$84,600.90) | |
| | Material - Total | | | | | | (\$84,600.90) | |
| 0090 - | · Total | | | | | | (\$84,600.90) | |
| 0100 | MISC. PERMANENT AGGREGATE EDGE TREATMENT | Material | | 18 | Dec 2, 2020 | SYSTEM | (\$6,559.80) | |
| | | | | 18 | Dec 2, 2020 | SYSTEM | \$6,559.80 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 19 | Dec 3, 2020 | SYSTEM | (\$6,559.80) | |
| | | | - Total | | | | (\$6,559.80) | |
| | Material - Total | | | | | | (\$6,559.80) | |
| | MISC. PERMANENT AGGREGATE EDGE TREATMENT | Overrun | Overrun | 18 | Dec 2, 2020 | SYSTEM | \$282.75 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | 18 | Dec 2, 2020 | SYSTEM | (\$282.75) | |
| | | | | 19 | Dec 3, 2020 | SYSTEM | (\$282.75) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | 19 | Dec 3, 2020 | SYSTEM | \$282.75 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | Overrun - T | otal | | | \$0.00 | |
| | Overrun - Total | | | | | | \$0.00 | |
| | ·Total | | | | | | (\$6,559.80) | |
| 0110 | TYPE A3 SHOULDER | Material | | 18 | Dec 2, 2020 | SYSTEM | (\$5,561.95) | |
| | | | | 18 | Dec 2, 2020 | SYSTEM | \$5,561.95 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user stephb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | 19 | Dec 3, 2020 | SYSTEM | (\$5,561.95) | |
| | | | - Total | | | | (\$5,561.95) | |
| | Material - Total | | | | | | (\$5,561.95) | |
| 0110 - | · Total | | | | | | (\$5,561.95) | |
| 0120 | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) | Other Item Adjustment | ACAD | 18 | Dec 2, 2020 | stephb1 | (\$949.14) | BP1 20-16 AC Price Adjustment, Installed on 11/17/2020 Current Index: 390 Base Index: 457.5 Difference: -67.5 Quantity: 426.10 Tons Virgin AC: 3.30% |

Revision 4/1/2020 Page 11 of 22



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|---|--------------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| 0120 | | Other Item Adjustment | | | | | | Adjustment: -\$949.14 |
| | | Adjustificiti | ACAD - Tota | al | | | (\$949.14) | |
| | Other Item Adjustment - Total | | | | | | (\$949.14) | |
| | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) | Overrun | Overrun | 18 | Dec 2, 2020 | SYSTEM | (\$7,120.80) | |
| | | | | 18 | Dec 2, 2020 | SYSTEM | \$7,120.80 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | | 19 | Dec 3, 2020 | SYSTEM | (\$7,120.80) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | Overrun - T | otal | | | (\$7,120.80) | |
| | Overrun - Total | | | | | | (\$7,120.80) | |
| 0120 - | Total | | | | | | (\$8,069.94) | |
| 0130 | MISC. OPTIONAL PAVEMENT 1 | Material | | 3 | Apr 17, 2020 | SYSTEM | (\$62,812.44) | |
| | | | | 3 | Apr 17, 2020 | SYSTEM | \$62,812.44 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user stephb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | 4 | May 1, 2020 | SYSTEM | (\$84,690.86) | |
| | | | | 4 | May 1, 2020 | SYSTEM | \$84,690.86 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | 5 | May 18, 2020 | SYSTEM | (\$84,690.86) | |
| | | | | 5 | May 18, 2020 | SYSTEM | \$84,690.86 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | 6 | Jun 2, 2020 | SYSTEM | (\$84,690.86) | |
| | | | | 6 | Jun 2, 2020 | SYSTEM | \$84,690.86 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | 7 | Jun 16, 2020 | SYSTEM | (\$84,690.86) | |
| | | | | 7 | Jun 16, 2020 | SYSTEM | \$84,690.86 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 8 | Jun 30, 2020 | SYSTEM | (\$84,690.86) | |
| | | | | 8 | Jul 1, 2020 | SYSTEM | \$84,690.86 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 9 | Jul 15, 2020 | SYSTEM | (\$84,690.86) | |
| | | | | 9 | Jul 15, 2020 | SYSTEM | \$84,690.86 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 10 | Aug 3, 2020 | SYSTEM | (\$84,690.86) | |
| | | | | 10 | Aug 3, 2020 | SYSTEM | \$84,690.86 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 11 | Aug 17, 2020 | SYSTEM | (\$84,690.86) | |
| | | | | 11 | Aug 17, 2020 | SYSTEM | \$84,690.86 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 12 | Sep 1, | SYSTEM | (\$84,690.86) | |

Revision 4/1/2020 Page 12 of 22



| | | A 11 / | 011 | | 0 | 0 | | 5 . |
|---------------------------|----------------------------------|--------------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
| 0130 | MISC. OPTIONAL PAVEMENT 1 | Material | | | 2020 | | | |
| | | | | 12 | Sep 1, 2020 | SYSTEM | \$84,690.86 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 13 | Sep 15, 2020 | SYSTEM | (\$84,690.86) | |
| | | | | 13 | Sep 16, 2020 | SYSTEM | \$84,690.86 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 14 | Sep 30, 2020 | SYSTEM | (\$84,690.86) | |
| | | | | 14 | Sep 30, 2020 | SYSTEM | \$84,690.86 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 15 | Oct 16, 2020 | SYSTEM | (\$84,690.86) | |
| | | | | 15 | Oct 16, 2020 | SYSTEM | \$84,690.86 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 16 | Nov 2, 2020 | SYSTEM | (\$84,690.86) | |
| | | | | 16 | Nov 2, 2020 | SYSTEM | \$84,690.86 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 17 | Nov 16, 2020 | SYSTEM | (\$84,690.86) | |
| | | | | 17 | Nov 16, 2020 | SYSTEM | \$84,690.86 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 18 | Dec 2, 2020 | SYSTEM | (\$84,690.86) | |
| | | | | 18 | Dec 2, 2020 | SYSTEM | \$84,690.86 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user stephb1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | 19 | Dec 3, 2020 | SYSTEM | (\$84,690.86) | |
| | | | - Total | | | | (\$84,690.86) | |
| | Material - Total | | | | | | (\$84,690.86) | |
| 0130 - 0140 | Total MISC. OPTIONAL PAVEMENT 2 | Material | | 3 | Apr 17 | SVSTEM | (\$84,690.86) | |
| 0140 | MISC. OPTIONAL PAVEMENT 2 | iviateriai | | | Apr 17, 2020 | SYSTEM | (\$62,839.26) | |
| | | | | 3 | Apr 17, 2020 | SYSTEM | \$62,839.26 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user stephb1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | MISC. OPTIONAL PAVEMENT 2 | Other Item Adjustment | MDPA | | Sep 1, 2020 | stephb1 | \$8,019.18 | This adjustment offsets the negative adjustment made on estimate 3. |
| | | | MDPA - Tot | al | | | \$8,019.18 | |
| | Other Item Adjustment - Total | | | | | | \$8,019.18 | |
| | MISC. OPTIONAL PAVEMENT 2 | Overrun | Overrun | | Apr 17, 2020 | SYSTEM | \$8,019.18 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | 3 | Apr 17, 2020 | SYSTEM | (\$8,019.18) | |
| | | | | | | | | |
| | | | | 3 | Apr 17, 2020 | stephb1 | (\$8,019.18) | This is to adjust for the system generated overrun and will be added when the CO goes through. |
| | | | Overrun - T | | | stephb1 | (\$8,019.18) | |

Revision 4/1/2020 Page 13 of 22



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|------------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|--|
| 0140 - | Total | | | | | | \$0.00 | |
| 0160 | CHAIN-LINK FENCE (RETAINING WALLS) | Material | | 18 | Dec 2, 2020 | SYSTEM | (\$6,324.00) | |
| | | | | 18 | Dec 2, 2020 | SYSTEM | \$6,324.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user stephb1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | 19 | Dec 3, 2020 | SYSTEM | (\$6,324.00) | |
| | | | - Total | | | | (\$6,324.00) | |
| | Material - Total | | | | | | (\$6,324.00) | |
| 0160 - | Total | | | | | | (\$6,324.00) | |
| 0170 | 8 IN. CONCRETE MEDIAN STRIP | Material | | 4 | May 1, 2020 | SYSTEM | (\$2,886.60) | |
| | | | | 4 | May 1, 2020 | SYSTEM | \$2,886.60 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | 5 | May 18, 2020 | SYSTEM | (\$2,886.60) | |
| | | | | 5 | May 18, 2020 | SYSTEM | \$2,886.60 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stephb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | 6 | Jun 2, 2020 | SYSTEM | (\$2,886.60) | |
| | | | | 6 | Jun 2, 2020 | SYSTEM | \$2,886.60 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stephb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | 7 | Jun 16, 2020 | SYSTEM | (\$2,886.60) | |
| | | | | 7 | Jun 16, 2020 | SYSTEM | \$2,886.60 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 8 | Jun 30, 2020 | SYSTEM | (\$2,886.60) | |
| | | | | 8 | Jul 1, 2020 | SYSTEM | \$2,886.60 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | 9 | Jul 15, 2020 | SYSTEM | (\$2,886.60) | |
| | | | | 9 | Jul 15, 2020 | SYSTEM | \$2,886.60 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 10 | Aug 3, 2020 | SYSTEM | (\$2,886.60) | |
| | | | | 10 | Aug 3, 2020 | SYSTEM | \$2,886.60 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 11 | Aug 17, 2020 | SYSTEM | (\$2,886.60) | |
| | | | | 11 | Aug 17, 2020 | SYSTEM | \$2,886.60 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 12 | Sep 1, 2020 | SYSTEM | (\$2,886.60) | |
| | | | | 12 | Sep 1, 2020 | SYSTEM | \$2,886.60 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 13 | Sep 15, 2020 | SYSTEM | (\$2,886.60) | |
| | | | | 13 | Sep 16, | SYSTEM | \$2,886.60 | This adjustment offsets the original system-generated Overrun |

Revision 4/1/2020 Page 14 of 22



| SIN. CONCRETE MEDIAN STRIP Maleful | Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks |
|---|--------|--------------------------------|------------|--------------------|--------|---------|---------|---------------|--|
| | | | Туре | Adjustment Type | Number | Date | Ву | | |
| 1 | 0170 | 8 IN. CONCRETE MEDIAN STRIP | Material | | | 2020 | | | overridding Payment Estimate Exception 3 on the current |
| Part | | | | | 14 | | SYSTEM | (\$2,886.60) | |
| 1 | | | | | 14 | | SYSTEM | \$2,886.60 | Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 3 on the current |
| Payment Estimate Bran Adjustment (003) due to user stephed | | | | | 15 | | SYSTEM | (\$2,886.60) | |
| 1 | | | | | 15 | | SYSTEM | \$2,886.60 | Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 3 on the current |
| Payment Estimate Exception 4 on the current Payment Estimate Item Adjustment (IOUCs) due to user slephth Payment Estimate Item Adjustment (IOUCs) due to user slephth Payment Estimate Item Adjustment (IOUCs) due to user slephth Payment Estimate Payme | | | | | 16 | | SYSTEM | (\$2,886.60) | |
| 17 | | | | | 16 | | SYSTEM | \$2,886.60 | Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 4 on the current |
| Payment Estimate Run Aglustment (0003) does to user stephols overriding Payment Estimate Exception 4 on the current Payment Estimate Exception 9 on the current Payment Estimate Exception 10 on the current Payment Estimate Exception 5 on the current Payment Estimate Exception 1 | | | | | 17 | | SYSTEM | (\$2,886.60) | |
| 18 | | | | | 17 | | SYSTEM | \$2,886.60 | Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 4 on the current |
| Payment Estimate Item Adjustment (0010) due to user stepht1 | | | | | 18 | | SYSTEM | (\$2,886.60) | |
| Total | | | | | 18 | | SYSTEM | \$2,886.60 | Payment Estimate Item Adjustment (0010) due to user stephb1 overridding Payment Estimate Exception 9 on the current |
| Material - Total | | | | | 19 | | SYSTEM | (\$2,886.60) | |
| Part | | | | - Total | | | | (\$2,886.60) | |
| Pave Dapproach, 7 in. Material 18 Dec 2, 2020 20 | | Material - Total | | | | | | (\$2,886.60) | |
| 18 | 0170 - | Total | | | | | | (\$2,886.60) | |
| 2020 Payment Estimate Item Adjustment (0011) due to user stephb1 overridding Payment Estimate Exception 10 on the current Payment Estimate Exception 5 on the current Payment Estimate Exception 1 on the current Payment Estimate Exc | 0180 | PAVED APPROACH, 7 IN. | Material | | 18 | | SYSTEM | (\$20,710.08) | |
| Autorial - Total | | | | | 18 | | SYSTEM | \$20,710.08 | Payment Estimate Item Adjustment (0011) due to user stephb1 overridding Payment Estimate Exception 10 on the current |
| Material - Total (\$20,710.08) | | | | | 19 | | SYSTEM | (\$20,710.08) | |
| 14 | | | | - Total | | | | (\$20,710.08) | |
| FURNISHING TYPE 2 ROCK BLANKET Material 14 Sep 30, 2020 14 Sep 30, 2020 15 Sep 30, 2020 16 Sep 30, 2020 17 Sep 30, 2020 18 Sep 30, 2020 19 Sep 30, 2020 19 Sep 30, 2020 10 Sep 30, 2020 11 Sep 30, 2020 12 Sep 30, 2020 13 Sep 30, 2020 14 Sep 30, 2020 15 Sep 30, 2020 16 Sep 30, 2020 17 Sep 30, 2020 18 Sep 30, 2020 19 Sep 30, 2020 10 Sep 30, 2020 | | Material - Total | | | | | | (\$20,710.08) | |
| 2020 14 Sep 30, 2020 2 | 0180 - | Total | | | | | | (\$20,710.08) | |
| Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. - Total S0.00 Material - Total S0.00 CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Item Adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate Exception 1 on the current Payment Estimate So.00 Material - Total S0.00 Material - Total S0.00 SYSTEM \$14,058.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | 0190 | FURNISHING TYPE 2 ROCK BLANKET | Material | | 14 | | SYSTEM | (\$9,205.00) | |
| Material - Total CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR RETAINED PURNISHED, CONTRACTOR RETAINED A material - Total Material - Total S0.00 (\$14,058.00) This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate Exception 1 on the current Payment Estimate Succession 1 on the current Payment Estimate Succession 2 overridding Payment Estimate Exception 1 on the current Payment Estimate Succession 2 overridding Payment Estimate Exception 1 on the current Payment Estimate Succession 2 overridding Payment Estimate Exception 1 on the current Payment Estimate Succession 2 overridding Payment Estimate Exception 1 on the current Payment Estimate Succession 2 overridding Payment Estimate Exception 1 on the current Payment Estimate Exception 1 on the current Payment Estimate Succession 2 overridding Payment Estimate Exception 1 on the current Payment Estimate Exception 1 on the current Payment Estimate Succession 2 overridding Payment Estimate Exception 1 on the current Payment Estimate Succession 2 overridding Payment Estimate Exception 3 overridding Payment Estimate Exception 1 on the current Payment Estimate Succession 2 overridding Payment Estimate Exception 3 overridding Payment Estimate Succession | | | | | 14 | | SYSTEM | | Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 5 on the current |
| D190 - Total CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR RETAINED PURNISHED, CONTRACTOR RETAINED INTERFACE, CONTRACTOR RETAINED IN | | | | - Total | | | | | |
| CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR RETAINED 1 Mar 16, 2020 1 Mar 16, 2020 2020 1 Mar 16, 2020 2020 2020 2020 2020 2020 2020 202 | | | | | | | | | |
| WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED 1 Mar 16, 2020 1 Mar 16, 2020 1 Mar 16, 2020 1 Mar 16, 2020 1 SYSTEM \$14,058.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. 1 Total \$0.00 | 0190 - | Total | | | | | | \$0.00 | |
| FURNISHED, CONTRACTOR RETAINED 1 Mar 16, 2020 Nat 16, 2020 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00 | 0270 | WITHOUT COMMUNICATION | Material | | 1 | | SYSTEM | (\$14,058.00) | |
| Material - Total \$0.00 | | | | | 1 | | SYSTEM | \$14,058.00 | Payment Estimate Item Adjustment (0001) due to user stephb1 overridding Payment Estimate Exception 1 on the current |
| | | | | - Total | | | | \$0.00 | |
| 270 - Total \$0.00 | | Material - Total | | | | | | \$0.00 | |
| | 0270 - | Total | | | | | | \$0.00 | |

Revision 4/1/2020 Page 15 of 22



| Line | Description | Adjustment | Other | Est. | Crootes | Created | Amount | Remarks |
|--------|---|--------------------|--------------------|--------|-----------------|---------|---------------|--|
| Line | Description | Adjustment Type | Adjustment Type | Number | Created Date | By | Amount | remarks |
| 0280 | CONCRETE TRAFFIC BARRIER, TYPE B | Material | | 15 | Oct 16, 2020 | SYSTEM | (\$22,192.00) | |
| | | | | 15 | Oct 16, 2020 | SYSTEM | \$22,192.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | 16 | Nov 2, 2020 | SYSTEM | (\$22,192.00) | |
| | | | | 16 | Nov 2, 2020 | SYSTEM | \$22,192.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | 17 | Nov 16, 2020 | SYSTEM | (\$22,192.00) | |
| | | | | 17 | Nov 16, 2020 | SYSTEM | \$22,192.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | 18 | Dec 2, 2020 | SYSTEM | (\$22,192.00) | |
| | | | | 18 | Dec 2, 2020 | SYSTEM | \$22,192.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user stephb1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | 19 | Dec 3, 2020 | SYSTEM | (\$22,192.00) | |
| | | | - Total | | | | (\$22,192.00) | |
| | Material - Total | | | | | | (\$22,192.00) | |
| 0280 - | Total | | | | | | (\$22,192.00) | |
| 0320 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | Material | | 11 | Aug 17, 2020 | SYSTEM | (\$5,370.30) | |
| | | | | 11 | Aug 17, 2020 | SYSTEM | \$5,370.30 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stephb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | Overrun | Overrun | 11 | Aug 17, 2020 | SYSTEM | (\$1,474.20) | |
| | | | | 11 | Aug 17, 2020 | SYSTEM | \$1,474.20 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | 11 | Aug 17, 2020 | stephb1 | (\$1,474.20) | Item overrun will be addressed on a later Change Order. |
| | | | | 12 | Sep 1, 2020 | SYSTEM | (\$1,474.20) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | 18 | Dec 2, 2020 | SYSTEM | \$1,474.20 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',17.55000 - 17.55000, 'is applied (if non-zero). |
| | | | Overrun - T | otal | | | (\$1,474.20) | |
| | Overrun - Total | | | | | | (\$1,474.20) | |
| 0320 - | Total | | | | | | (\$1,474.20) | |
| 0330 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW | Material | | 11 | Aug 17, 2020 | SYSTEM | (\$263.25) | |
| | | | | 11 | Aug 17, 2020 | SYSTEM | \$263.25 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user stephb1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0330 - | Total | | | | | | \$0.00 | |
| 0340 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT | Material | | 11 | Aug 17, 2020 | SYSTEM | (\$1,683.00) | |
| | ARROW | | | 11 | Aug 17, 2020 | SYSTEM | \$1,683.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user stephb1 overridding Payment Estimate Exception 7 on the current |

Revision 4/1/2020 Page 16 of 22



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|---|--------------------------|-----------------------------|----------------|--|--------------------------------------|--|--|
| 0340 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | Material | | | | | | Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0340 - | - Total | | | | | | \$0.00 | |
| 0350 | 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Material | | 11 | Aug 17, 2020 | SYSTEM | (\$798.90) | |
| | , | | | 11 | Aug 17, 2020 | SYSTEM | \$798.90 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Other Item Adjustment | MDPA | | Sep 30, 2020 | stephb1 | \$132.00 | This adjustment offsets the negative adjustment made on estimate 11. |
| | | | MDPA - Tot | al | | | \$132.00 | |
| | Other Item Adjustment - Total | | | | | | \$132.00 | |
| | 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Overrun | Overrun | 11 | Aug 17, 2020 | SYSTEM | (\$132.00) | |
| | 7,MN, 111 2 2 32,130 | | | 11 | Aug 17, 2020 | SYSTEM | \$132.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | 11 | Aug 17, 2020 | stephb1 | (\$132.00) | Item Overrun will be addressed on a later Change Order. |
| | | | | 12 | Sep 1, 2020 | SYSTEM | (\$37.50) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | 13 | Sep 15, 2020 | SYSTEM | \$37.50 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',0.30000 - 0.30000, 'is applied (if non-zero). |
| | | | Overrun - T | otal | | | (\$132.00) | |
| | Overrun - Total | | | | | | (\$132.00) | |
| 0350 - | - Total | | | | | | \$0.00 | |
| | | Matarial | | 11 | Aug 17, 2020 | SYSTEM | (\$1,091.20) | |
| 0360 | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | iviateriai | | | 2020 | | | |
| | | waterial | | 11 | Aug 17, 2020 | SYSTEM | \$1,091.20 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | PAVEMENT MARKING PAINT, TYPE L | Material | - Total | 11 | Aug 17, | SYSTEM | \$1,091.20 \$0.00 | Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 11 on the current |
| | PAVEMENT MARKING PAINT, TYPE L | wateriai | - Total | 11 | Aug 17, | SYSTEM | | Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 11 on the current |
| | PAVEMENT MARKING PAINT, TYPE L BEADS | Other Item | MDPA | 14 | Aug 17, | SYSTEM stephb1 | \$0.00 \$0.00 \$2.40 | Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 11 on the current |
| | PAVEMENT MARKING PAINT, TYPE L BEADS Material - Total 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L | Other Item | | 14 | Aug 17, 2020 | | \$0.00 \$0.00 | Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the negative adjustment made on |
| | PAVEMENT MARKING PAINT, TYPE L BEADS Material - Total 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L | Other Item | MDPA | 14 | Aug 17, 2020 | | \$0.00 \$0.00 \$2.40 | Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the negative adjustment made on |
| | PAVEMENT MARKING PAINT, TYPE L BEADS Material - Total 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS Other Item Adjustment - Total 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L | Other Item Adjustment | MDPA | 14 al | Aug 17, 2020 | stephb1 | \$0.00 \$0.00 \$2.40 | Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the negative adjustment made on |
| | PAVEMENT MARKING PAINT, TYPE L BEADS Material - Total 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS Other Item Adjustment - Total 6 IN. WHITE HIGH BUILD WATERBORNE | Other Item Adjustment | MDPA - Tot | 14 al | Aug 17, 2020 Sep 30, 2020 | stephb1 | \$0.00 \$0.00 \$2.40 \$2.40 | Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the negative adjustment made on |
| | PAVEMENT MARKING PAINT, TYPE L BEADS Material - Total 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS Other Item Adjustment - Total 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L | Other Item Adjustment | MDPA - Tot | 14 al | Aug 17, 2020 Sep 30, 2020 Aug 17, 2020 Aug 17, 2020 | stephb1 | \$0.00 \$0.00 \$2.40 \$2.40 \$2.40 (\$2.40) | Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the negative adjustment made on estimate 11. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment |
| | PAVEMENT MARKING PAINT, TYPE L BEADS Material - Total 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS Other Item Adjustment - Total 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L | Other Item Adjustment | MDPA - Tot | 14 11 11 | Aug 17, 2020 Sep 30, 2020 Aug 17, 2020 Aug 17, 2020 Aug 17, 2020 | stephb1 SYSTEM SYSTEM | \$0.00 \$0.00 \$2.40 \$2.40 (\$2.40) \$2.40 | Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the negative adjustment made on estimate 11. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | PAVEMENT MARKING PAINT, TYPE L BEADS Material - Total 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS Other Item Adjustment - Total 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L | Other Item Adjustment | MDPA - Tot | 14 11 11 | Aug 17, 2020 Sep 30, 2020 Aug 17, 2020 Aug 17, 2020 Aug 17, 2020 Sep 1, | stephb1 SYSTEM SYSTEM stephb1 | \$0.00 \$0.00 \$2.40 \$2.40 \$2.40 (\$2.40) | Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the negative adjustment made on estimate 11. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 15 on the current Payment Estimate. Item will be addressed on a later change order. |
| | PAVEMENT MARKING PAINT, TYPE L BEADS Material - Total 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS Other Item Adjustment - Total 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L | Other Item Adjustment | MDPA - Tot | 11 11 11 12 13 | Aug 17, 2020 Sep 30, 2020 Aug 17, 2020 Aug 17, 2020 Sep 1, 2020 Sep 15, | stephb1 SYSTEM SYSTEM stephb1 SYSTEM | \$0.00 \$0.00 \$2.40 \$2.40 \$2.40 (\$2.40) (\$2.40) | Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the negative adjustment made on estimate 11. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 15 on the current Payment Estimate. Item will be addressed on a later change order. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments |
| | PAVEMENT MARKING PAINT, TYPE L BEADS Material - Total 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS Other Item Adjustment - Total 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L | Other Item Adjustment | MDPA - Tot | 11 11 11 12 13 | Aug 17, 2020 Sep 30, 2020 Aug 17, 2020 Aug 17, 2020 Sep 1, 2020 Sep 15, | stephb1 SYSTEM SYSTEM stephb1 SYSTEM | \$0.00 \$0.00 \$2.40 \$2.40 (\$2.40) (\$2.40) (\$2.40) (\$2.40) | Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the negative adjustment made on estimate 11. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 15 on the current Payment Estimate. Item will be addressed on a later change order. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments |
| 0360 | Material - Total 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS Other Item Adjustment - Total 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Other Item Adjustment | MDPA - Tot | 11 11 11 12 13 | Aug 17, 2020 Sep 30, 2020 Aug 17, 2020 Aug 17, 2020 Sep 1, 2020 Sep 15, | stephb1 SYSTEM SYSTEM stephb1 SYSTEM | \$0.00 \$0.00 \$2.40 \$2.40 \$2.40 (\$2.40) (\$2.40) \$2.40 (\$2.40) | Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the negative adjustment made on estimate 11. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 15 on the current Payment Estimate. Item will be addressed on a later change order. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments |

Revision 4/1/2020 Page 17 of 22



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|-------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|--|
| 0380 | WATERBORNE PAVEMENT MARKING | Overrun | Overrun | | 2020 | | | |
| | PAINT, TYPE P BEADS | | | 18 | Dec 2, 2020 | SYSTEM | \$198.50 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | 19 | Dec 3, 2020 | SYSTEM | (\$198.50) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | Overrun - To | otal | | | (\$198.50) | |
| | Overrun - Total | | | | | | (\$198.50) | |
| 0380 - | · Total | | | | | | (\$198.50) | |
| 0390 | PAVEMENT MARKING REMOVAL | Overrun | Overrun | 11 | Aug 17, 2020 | SYSTEM | (\$10.35) | |
| | | | | 13 | Sep 15, 2020 | SYSTEM | \$10.35 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1.15000 - 1.15000, 'is applied (if non-zero). |
| | | | Overrun - To | otal | | | \$0.00 | |
| | Overrun - Total | | | | | | \$0.00 | |
| 0390 - | · Total | | | | | | \$0.00 | |
| 0420 | CLASS B-1 CONCRETE (CULVERTS) | Material | | 12 | Sep 1, 2020 | SYSTEM | (\$106,970.40) | |
| | | | | 12 | Sep 1, 2020 | SYSTEM | \$106,970.40 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stephb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | 13 | Sep 15, 2020 | SYSTEM | (\$106,970.40) | |
| | | | | 13 | Sep 16, 2020 | SYSTEM | \$106,970.40 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stephb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | 14 | Sep 30, 2020 | SYSTEM | (\$106,970.40) | |
| | | | | 14 | Sep 30, 2020 | SYSTEM | \$106,970.40 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stephb1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | 15 | Oct 16, 2020 | SYSTEM | (\$256,370.40) | |
| | | | | 15 | Oct 16, 2020 | SYSTEM | \$256,370.40 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stephb1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | 16 | Nov 2, 2020 | SYSTEM | (\$311,648.40) | |
| | | | | 16 | Nov 2, 2020 | SYSTEM | \$311,648.40 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stephb1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | 17 | Nov 16, 2020 | SYSTEM | (\$311,648.40) | |
| | | | | 17 | Nov 16, 2020 | SYSTEM | \$311,648.40 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stephb1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | 18 | Dec 2, 2020 | SYSTEM | (\$311,648.40) | |
| | | | | 18 | Dec 2, 2020 | SYSTEM | \$311,648.40 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user stephb1 overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | 19 | Dec 3, 2020 | SYSTEM | (\$311,648.40) | |
| | | | - Total | | | | (\$311,648.40) | |
| | Material - Total | | | | | | (\$311,648.40) | |
| 0420 | Total | | | | | | (\$311,648.40) | |
| 0430 | REINFORCING STEEL (CULVERTS) | Material | | 12 | Sep 1, 2020 | SYSTEM | (\$38,858.50) | |

Revision 4/1/2020 Page 18 of 22



| Paymone Estimate Exception 6 on the outrent |
|--|
| |
| Payment Estimate Internal December 1 |
| 14 |
| Part |
| 15 |
| Payment Estimate Exception (0006) due to user stephbly overridding Payment Estimate (Exception 9 on the current Payment Estimate). |
| 16 |
| Payment Estimate Item Adjustment (0006) due to user stephble overriding Payment Estimate Exception 10 on the current Payment Estimate Item Adjustment (0006) due to user stephble overridding Payment Estimate Exception 9 on the current Payment Estimate Exception 10 on the current Payment Estimate Exception 11 on the current Payment Estimate Exception 12 on the current Payment Estimate Exception 12 on the current Payment Estimate Exception 13 on the current Payment Estimate Exception 14 on the current Payment Estimate Exception 15 on the current Payment Estimate Exception 15 on the current Payment Estimate Exception 16 on the current Payment Estimate Exception 17 on the current Payment Estimate Ex |
| 2020 17 |
| Payment Estimate Item Adjustment (0009) due to user stephbl overriding Payment Estimate Exception 9 on the current Payment Item Payment Estimate Exception 9 on the current Payment Item Payment Estimate Exception 9 on the current Payment Item Payment Estimate Exception 9 on the current Payment Item Payment Estimate Exception 9 on the current Payment Item Payment Payment Payment Item Payment Pay |
| Material - Total S0.00 |
| 15 IN. PIPE GROUP C |
| 15 IN. PIPE GROUP C Material 17 |
| 2020 17 |
| Payment Estimate tem Adjustment (0007) due to user stephb1 overridding Payment Estimate Exception 11 on the current Payment In Payment In Payment In Payment In Payment In International Source Seedings of the Payment International Source Seeding |
| Material - Total SEEDING - COOL SEASON MIXTURES Material Apr 17, 2020 SYSTEM (\$1,400.80) This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user stephb1 overridding Payment Estimate Exception 7 on the current Payment Estimate. May 1, 2020 May 1, 2020 May 1, 2020 May 1, 2020 SYSTEM (\$1,400.80) This adjustment offsets the original system-generated Overrun Payment Estimate Exception 7 on the current Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 11 on the current Payment Estimate Exception 12 on the current Payment Estimate Exception 13 on the current Payment Estimate Exception 13 on the current Payment Estimate Exception 14 on the current Payment Estimate Exception 15 on the c |
| SEEDING - COOL SEASON MIXTURES Material 3 |
| SEEDING - COOL SEASON MIXTURES Material 3 |
| 2020 Apr 17, 2020 SYSTEM \$1,400.80 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user stephb1 overridding Payment Estimate Exception 7 on the current Payment Estimate. May 1, 2020 May 1, 2020 SYSTEM \$1,400.80 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 11 on the current Payment Estimate Exception 11 on the current Payment Estimate. |
| 2020 Payment Estimate Item Adjustment (0028) due to user stephb1 overridding Payment Estimate Exception 7 on the current Payment Estimate. 4 May 1, 2020 4 May 1, 2020 5 SYSTEM \$1,400.80 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 11 on the current Payment Estimate Exception 11 on the current Payment Estimate. |
| 2020 4 May 1, 2020 SYSTEM \$1,400.80 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| 2020 Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 11 on the current Payment Estimate. 18 Dec 2, SYSTEM (\$2,801.60) |
| |
| |
| 18 Dec 2, 2020 \$YSTEM \$2,801.60 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user stephb1 overridding Payment Estimate Exception 16 on the current |
| Payment Estimate. |
| Payment Estimate. 19 Dec 3, 2020 (\$2,801.60) |
| 19 Dec 3, SYSTEM (\$2,801.60) |

Revision 4/1/2020 Page 19 of 22



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|--|
| 0460 - | Total | | | | | | (\$2,801.60) | |
| 0510 | MGS HEIGHT AND BLOCK TRANSITION | Material | | 4 | May 1, 2020 | SYSTEM | (\$2,342.00) | |
| | | | | 4 | May 1, 2020 | SYSTEM | \$2,342.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0510 - | Total | | | | | | \$0.00 | |
| 0520 | TYPE A CRASHWORTHY END TERMINAL (MASH) | Material | | 4 | May 1, 2020 | SYSTEM | (\$7,028.00) | |
| | | | | 4 | May 1, 2020 | SYSTEM | \$7,028.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0520 - | Total | | | | | | \$0.00 | |
| 0560 | SH-FLAT SHEET - SIGNAL SIGN | Material | | 10 | Aug 3, 2020 | SYSTEM | (\$2,639.40) | |
| | | | | 10 | Aug 3, 2020 | SYSTEM | \$2,639.40 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | 11 | Aug 17, 2020 | SYSTEM | (\$2,639.40) | |
| | | | | 12 | Sep 1, 2020 | SYSTEM | (\$2,639.40) | |
| | | | | 12 | Sep 1, 2020 | SYSTEM | \$2,639.40 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user stephb1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | 13 | Sep 15, 2020 | SYSTEM | (\$2,639.40) | |
| | | | | 13 | Sep 16, 2020 | SYSTEM | \$2,639.40 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user stephb1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | - Total | | | | (\$2,639.40) | |
| | Material - Total | | | | | | (\$2,639.40) | |
| | SH-FLAT SHEET - SIGNAL SIGN | MaterialCredit | | 12 | Sep 1, 2020 | SYSTEM | \$2,639.40 | |
| | | | - Total | | | | \$2,639.40 | |
| | MaterialCredit - Total | | | | | | \$2,639.40 | |
| 0560 - | Total | | | | | | \$0.00 | |
| 0630 | CONDUIT, 2 IN., TRENCH WITH TRACER WIRE | Material | | 2 | Apr 2, 2020 | SYSTEM | (\$590.95) | |
| | | | | 2 | Apr 2, 2020 | SYSTEM | \$590.95 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stephb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0630 - | Total | | | | | | \$0.00 | |
| 0640 | CONDUIT, 3 IN., TRENCH WITH TRACER WIRE | Material | | 2 | Apr 2, 2020 | SYSTEM | (\$204.30) | |
| | | | | 2 | Apr 2, 2020 | SYSTEM | \$204.30 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stephb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0640 - | Total | | | | | | \$0.00 | |

Revision 4/1/2020 Page 20 of 22



| Lina | Description | A alice at man a mat | Other | Fet | Created | Created | Amazimt | Demonto |
|--------|---|----------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
| 0650 | CONDUIT, 2 IN., PUSHED WITH TRACER WIRE | Material | | 2 | Apr 2, 2020 | SYSTEM | (\$965.20) | |
| | | | | 2 | Apr 2, 2020 | SYSTEM | \$965.20 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stephb1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0650 - | Total | | | | | | \$0.00 | |
| 0660 | CONDUIT, 3 IN., PUSHED WITH TRACER WIRE | Material | | 2 | Apr 2, 2020 | SYSTEM | (\$1,083.00) | |
| | | | | 2 | Apr 2, 2020 | SYSTEM | \$1,083.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stephb1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | - Total | | | | \$0.00 | | |
| | Material - Total | | | | | | \$0.00 | |
| 0660 - | Total | | | | | | \$0.00 | |
| 0710 | POWER SUPPLY ASSEMBLY, TYPE 2 | Material | | 3 | Apr 17, 2020 | SYSTEM | (\$5,201.00) | |
| | | | | 3 | Apr 17, 2020 | SYSTEM | \$5,201.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user stephb1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0710 - | Total | | | | | | \$0.00 | |
| 0720 | PULL BOX, PREFORMED CLASS 2 | Material | | 3 | Apr 17, 2020 | SYSTEM | (\$5,517.00) | |
| | | | | 3 | Apr 17, 2020 | SYSTEM | \$5,517.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user stephb1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0720 - | Total | | | | | | \$0.00 | |
| 0730 | PULL BOX, PREFORMED CLASS 3 | Material | | 3 | Apr 17, 2020 | SYSTEM | (\$2,694.00) | |
| | | | | 3 | Apr 17, 2020 | SYSTEM | \$2,694.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user stephb1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | - Total | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0730 - | Total | | | | | | \$0.00 | |
| 0750 | MISC. OPTIONAL TRAFFIC SIGNAL DETECTORS | Material | | 14 | Sep 30, 2020 | SYSTEM | (\$18,580.00) | |
| | | | | 14 | Sep 30, 2020 | SYSTEM | \$18,580.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stephb1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0750 - | Total | | | | | | \$0.00 | |
| 0770 | U-CHANNEL POST, 3 LB | Material | | 4 | May 1, 2020 | SYSTEM | (\$133.35) | |
| | | | | 4 | May 1, 2020 | SYSTEM | \$133.35 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | \$0.00 | | | |
| 0770 - | Total | | | | | | \$0.00 | |
| | | | | | | | | |

Revision 4/1/2020 Page 21 of 22



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----------------|-----------------------|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|--|
| 0800 | SH-FLAT SHEET | Material | | 4 | May 1, 2020 | SYSTEM | (\$338.25) | |
| | | | | 4 | May 1, 2020 | SYSTEM | \$338.25 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | - Total | | | | \$0.00 | | |
| | Material - Total | | | | | | \$0.00 | |
| 0800 - Total | | | | | | | \$0.00 | |
| 5001 | ALTERNATE DITCH CHECK | Material | | 2 | Apr 2, 2020 | SYSTEM | (\$164.00) | |
| | | | | 2 | Apr 2, 2020 | SYSTEM | \$164.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stephb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | - Total | | | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 5001 - | Total | | | | \$0.00 | | | |
| Overall - Total | | | | | | | (\$557,718.83) | |

Revision 4/1/2020 Page 22 of 22