

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 7, 2022

| Final Estimate Number | Contract ID | 191213-D04 | Pay Period Start | December 16, 202 | 0 Original Contract Amount | \$721,649.68 |
|-----------------------|-----------------|------------------------------|------------------|------------------|----------------------------|--------------|
| q | Prime Contracto | r Comanche Construction, Inc | Pay Period End | April 1, 2022 | Net Change Order Amount | \$29,767.25 |
| • | | | | | Current Contract Amount | \$751,416.93 |

| Approval Date | | By User |
|----------------------|--|---------|
| April 7, 2022 | Generated and Approved (and should be considered Draft) at the Project Office Level by | browns1 |
| December 7, 2022 | Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by | holdtc |
| December 19, 2022 | Reviewed and Approved at the Central Office Controllers Office Level by | ramses1 |

| Original Completion Date | Current Completion Date | Actual Completion Date | % of Current Contract Amount Complete |
|--------------------------|-------------------------|------------------------|---------------------------------------|
| December 1, 2020 | December 1, 2020 | November 12, 2020 | 100.00% |

| | Contract Informational Dat | es | Milestones |
|------------------------|----------------------------|--------------------------------|----------------------------------|
| Date Description | Original Completion Date | Current Completion Date | No Milestones Exist for Contract |
| Acceptance Date | April 6, 2021 | April 6, 2021 | |
| Awarded Date | January 9, 2020 | January 9, 2020 | |
| Letting Date | December 13, 2019 | December 13, 2019 | |
| Notice to Proceed Date | February 10, 2020 | February 10, 2020 | |
| Open to Traffic Date | | | |
| Work Began Date | September 16, 2020 | September 16, 2020 | |

| Contract Total Pay For Estimate No. 9 | | | | |
|---------------------------------------|---------------|--------------|--------------|--|
| | This Estimate | Previous | To Date | |
| 191213-D04 | | | | |
| Total Posted Items Pay | (\$10,327.35) | \$761,744.28 | \$751,416.93 | |
| Gross Item Adjustments | \$0.00 | \$0.00 | \$0.00 | |
| Incentive | \$0.00 | \$0.00 | \$0.00 | |
| Disincentive | \$0.00 | \$0.00 | \$0.00 | |
| Liquidated Damage | \$0.00 | \$0.00 | \$0.00 | |
| Other Contract Adjustments | \$0.00 | \$0.00 | \$0.00 | |
| | | \$761,744.28 | \$751,416.93 | |
| Contract Total Payable This Estimate: | (\$10,327.35) | | | |

Items Paid This Estimate Period

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount |
|-----------------|-------------|-----------|---------------------------|------|------------|-----------------------|--------------------------|
| J5S3261 | 0370 | 7172054 | OPEN CELL FOAM JOINT SEAL | LF | \$187.770 | -55 | (\$10,327.35) |
| Project J5S3261 | - Total | | | | | | (\$10,327.35) |
| Overall - Total | | | | | | | (\$10.327.35) |

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

No Data Available


Page 1 of 13 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | | | | | (| Contract Project Information | | |
|-------------------|------------------------------------|----------------------------|---------|----------|--|---|---|--|
| Project Number | Federal Proj. Number | Project Description | Route | County | | | Location of Work | |
| J5S3261 | FAS S401(65) | Bridge rehabilitation | Various | CALLAWAY | over Route 54 include County | s Route 94 over Little Taverr | n Creek in Callaway County and West | t Main Street over Route 54/Route 63 in Co |
| Totals by | Job Numbe | rs | | | | | | |
| | | | | | | | | |
| J5S3261 | | | | | This Estimate | Previous | To Date | 1 |
| • | Poste | d Item Pay | | | This Estimate (\$10,327.35) | Previous \$761,744.28 | To Date \$751,416.93 | |
| • | Poste | | ents | | | | | |
| • | Poste | d Item Pay | | Item Pay | (\$10,327.35) | \$761,744.28 | \$751,416.93 | |
| • | Poste | d Item Pay Item Adjustm | | Item Pay | (\$10,327.35) \$0.00 | \$761,744.28 \$0.00 | \$751,416.93 \$0.00 | |
| • | Poste Gross | d Item Pay Item Adjustm | | Item Pay | (\$10,327.35) \$0.00 (\$10,327.35) | \$761,744.28 \$0.00 \$761,744.28 | \$751,416.93 \$0.00 \$751,416.93 | |
| • | Poste Gross Incent Disino | d Item Pay Item Adjustm | Gross | Item Pay | (\$10,327.35) \$0.00 (\$10,327.35) \$0.00 | \$761,744.28 \$0.00 \$761,744.28 \$0.00 | \$751,416.93 \$0.00 \$751,416.93 \$0.00 | |

Revision 4/1/2020 Page 2 of 13





Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Revision 4/1/2020 Page 3 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTE To Date (See repor generated date) |
|-------------------------|---|-------------|-------------|--------------|---|-----------------|------------------------|------------------------------|---------|------------------------------------|-------------|--|
| 191213-D04 | J5S3261 | 0001 | 0010 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | | \$33,904.41 | \$33,904.4 |
| | | 0001 | 0020 | 6161005 | CONSTRUCTION SIGNS | 2,116.00 | 0.00 | 2,116.00 | SQFT | 2,116.00 | \$8.48 | \$17,943.6 |
| | | 0001 | 0030 | 6161008 | ADVANCED WARNING RAIL SYSTEM | 16.00 | 0.00 | 16.00 | EA | 16.00 | \$47.71 | \$763.3 |
| | | 0001 | 0040 | 6161009 | FLAG ASSEMBLY | 14.00 | 0.00 | 14.00 | EA | 14.00 | \$26.51 | \$371. |
| | | 0001 | 0050 | 6161024 | CHANNELIZER (TRIM LINE) WITH LIGHT | 155.00 | 0.00 | 155.00 | EA | 155.00 | \$21.20 | \$3,286.0 |
| | | 0001 | 0060 | 6161025 | CHANNELIZER (TRIM LINE) | 60.00 | 0.00 | 60.00 | EA | 60.00 | \$21.20 | \$1,272.0 |
| | | 0001 | 0070 | 6161031 | TYPE III MOVEABLE BARRICADE WITH LIGHTS | 16.00 | 0.00 | 16.00 | EA | 16.00 | \$159.03 | \$2,544.4 |
| | | 0001 | 0080 | 6161033 | DIRECTIONAL INDICATOR BARRICADE | 48.00 | 0.00 | 48.00 | EA | 48.00 | \$68.91 | \$3,307. |
| | | 0001 | 0090 | 6161040 | FLASHING ARROW PANEL | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$901.19 | \$1,802. |
| | | 0001 | 0100 | 6161055 | SEQUENTIAL FLASHING WARNING LIGHT | 48.00 | 0.00 | 48.00 | EA | 48.00 | \$53.01 | \$2,544 |
| | | 0001 | 0110 | 6161099 | CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 10.00 | 0.00 | 10.00 | EA | 10.00 | \$3,710.80 | \$37,108. |
| | | 0001 | 0120 | 6162000A | WORK ZONE TRAFFIC SIGNAL SYSTEM | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$6,149.32 | \$6,149 |
| | | 0001 | 0130 | 6162004 | TEMPORARY SHORT-TERM RUMBLE STRIPS | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$2,650.57 | \$10,602 |
| | | 0001 | 0140 | 6181000 | MOBILIZATION | 1.00 | -1.00 | 0.00 | LS | 0.00 | \$70,445.48 | \$0 |
| | | 0001 | 0141 | 6181000 | MOBILIZATION | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$66,858.48 | \$66,858 |
| | | 0001 | 0150 | 6200012 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE | 62.00 | 0.00 | 62.00 | LF | 62.00 | \$12.72 | \$788 |
| | | 0001 | 0160 | 6200021 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$371.08 | \$742 |
| | | 0001 | 0170 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 4,694.00 | 0.00 | 4,694.00 | LF | 4,694.00 | \$0.27 | \$1,267 |
| | | 0001 | 0180 | 6206001C | 4 IN, YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 3,593.00 | 0.00 | 3,593.00 | LF | 3,593.00 | \$0.27 | \$970 |
| | | 0001 | 0190 | 6207001 | PAVEMENT MARKING REMOVAL | 10,626.00 | -7,745.00 | 2,881.00 | LF | 2,881.00 | \$0.80 | \$2,30 |
| | | 0001 | 0200 | 6207002 | PAVEMENT MARKING REMOVAL (SYMBOLS) | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$106.03 | \$212 |
| | | 0001 | 0210 | 6208063 | TEMPORARY PAVEMENT MARKING | 2,511.00 | -2,511.00 | 0.00 | EA | 0.00 | \$1.59 | \$0 |
| | | 0010 | 0220 | 6061010 | GUARDRAIL TYPE A | 400.00 | 0.00 | 400.00 | LF | 400.00 | \$25.45 | \$10,180 |
| | | 0010 | 0230 | 6061074 | MGS HEIGHT AND BLOCK TRANSITION | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$742.16 | \$1,48 |
| | | 0010 | 0240 | 6062200A | BRIDGE ANCHOR SECTION, 6.5 FT. POSTS (SAFETY BARRIER CURB) (ROADWAY AND REHABILITATION WORK ONLY) | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$2,544.55 | \$10,17 |
| | | 0010 | 0250 | 6062303 | ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$530.11 | \$2,12 |
| | | 0010 | 0260 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$3,074.66 | \$6,14 |
| | | 0010 | 0270 | 6066610 | END ANCHOR | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,272.28 | \$2,544 |
| | | 0030 | 0280 | 9029902 | MISC.GRIDSMART DETECTION SYSTEM | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$39,964.44 | \$39,96 |
| | | 0070 | 0290 | 6239905 | MISC.Methyl Methacrylate (MMA) Slurry Polymer Concrete Overlay | 1,335.00 | 0.00 | 1,335.00 | SQYD | 1,335.00 | \$132.53 | \$176,92 |
| | | 0070 | 0300 | 7040113 | CLEANING AND EPOXY COATING | 180.00 | 0.00 | 180.00 | SQFT | 180.00 | \$37.11 | \$6,67 |
| | | 0070 | 0310 | 7110200 | PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY) | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$4,240.92 | \$4,24 |
| | | 0070 | 0320 | 7172054 | OPEN CELL FOAM JOINT SEAL | 78.00 | 0.00 | 78.00 | LF | 78.00 | \$168.30 | \$13,12 |
| | | 0071 | 0330 | 6233000 | EPOXY POLYMER WEARING SURFACE | 442.00 | 0.00 | 442.00 | SQYD | 442.00 | \$90.12 | \$39,83 |
| | | 0072 | 0340 | 6239905 | MISC.Methyl Methacrylate (MMA) Slurry Polymer Concrete Overlay | 1,114.00 | 0.00 | 1,114.00 | SQYD | 1,114.00 | \$132.53 | \$147,63 |
| | | 0072 | 0350 | 7040113 | CLEANING AND EPOXY COATING | 448.00 | 0.00 | 448.00 | SQFT | 448.00 | \$37.11 | \$16,62 |
| | | 0072 | 0360 | 7119905 | MISC.penetrating sealer | 328.00 | 0.00 | 328.00 | SQYD | 328.00 | \$45.07 | \$14,78 |
| | | 0072 | 0370 | 7172054 | OPEN CELL FOAM JOINT SEAL | 110.00 | -55.00 | 55.00 | LF | 55.00 | \$187.77 | \$10,32 |
| | | 0001 | 5001 | 6189901 | MISC.Adjust Mobilization for Contract Bond | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$3,587.00 | \$3,58 |
| | | 0001 | 5002 | 6181000 | MOBILIZATION | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$3,206.04 | \$3,20 |
| | | 0070 | 5003 | 7040108 | MODIFIED DECK REPAIR | 0.00 | 132.00 | 132.00 | SQFT | 132.00 | \$199.81 | \$26,37 |
| | | 0070 | 5004 | 2153000 | SHAPING SLOPES, CLASS III | 0.00 | 4.50 | 4.50 | 100F | 4.50 | \$1,890.00 | \$8,50 |
| | 0072 5005 7172054 OPEN CELL FOAM JOINT SEAL | | 0.00 | 55.00 | 55.00 | LF | 55.00 | \$221.77 | \$12,19 | | | |
| | Project I | 5S3261 - To | tal Value | Posted to F | ate as of Report Generated Date | | | | | | | \$751,41 |

Revision 4/1/2020 Page 4 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|------------|-------------|---------------|--------------------|-----------------|------------------------|------------------------------|------|-----------------------------|------------|--|
| 191213-D04 Ove | rall - Total | Value Post | ed to Dat | te as of Repo | ort Generated Date | | | | | Qty | | \$751,416.93 |

Revision 4/1/2020 Page 5 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5S3261

| Line Number | Item Code | Description | DWR Date | DWR Approval Date | Quantity Posted | | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------|---------------------------|-------------|-------------------------|--------------------|----|-----------------------------|---------------------------------|---------------------|-------------------------------|---------------------|--|
| 0370 | 7172054 | OPEN CELL FOAM JOINT SEAL | 1/7/21 | 1/7/21 | -55.00 | LF | Bridge A46622 End Bent No 1 | | | | | Mistakenly paid the full posted quantity of 110 LF before I did an change order and contingent item. |

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 6 of 13





| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| 5S3261 | 0150 | PREF THERMO PAVMT MARKING, 12 IN WHITE | Material | | 5 | Nov 3, 2020 | SYSTEM | \$788.64 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | WITTE | | | 5 | Nov 3, 2020 | SYSTEM | (\$788.64) | |
| | | | | | 6 | Nov 16, 2020 | SYSTEM | \$788.64 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 6 | Nov 16, 2020 | SYSTEM | (\$788.64) | |
| | | | | | 7 | Dec 3, 2020 | SYSTEM | \$788.64 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user browns1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 7 | Dec 3, 2020 | SYSTEM | (\$788.64) | |
| | | | | | 8 | Dec 16, 2020 | SYSTEM | \$788.64 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 8 | Dec 16, 2020 | SYSTEM | (\$788.64) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | al | | | | \$0.00 | |
| | 0150 - | Total | | | | | | \$0.00 | |
| | 0160 | PREF THERMO PVMT MARK, LT/RT ARROW | Material | | 4 | Oct 16, 2020 | SYSTEM | \$742.16 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user taylod2 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 4 | Oct 16, 2020 | SYSTEM | (\$742.16) | |
| | | | | | 5 | Nov 3, 2020 | SYSTEM | \$742.16 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 5 | Nov 3, 2020 | SYSTEM | (\$742.16) | |
| | | | | | 6 | Nov 16, 2020 | SYSTEM | \$742.16 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 6 | Nov 16, 2020 | SYSTEM | (\$742.16) | |
| | | | | | 7 | Dec 3, 2020 | SYSTEM | \$742.16 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user browns1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 7 | Dec 3, 2020 | SYSTEM | (\$742.16) | |
| | | | | | 8 | Dec 16, 2020 | SYSTEM | \$742.16 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 8 | Dec 16, 2020 | SYSTEM | (\$742.16) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 0160 - | Total | | | | | | \$0.00 | |
| | 0170 | 4 IN. WHITE WATERBORNE PAVEMENT | Material | | 4 | Oct 16, 2020 | SYSTEM | \$232.36 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user taylod2 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | MARKING | | | 4 | Oct 16, 2020 | SYSTEM | (\$232.36) | |
| | | | | | 5 | Nov 3, 2020 | SYSTEM | \$1,267.38 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 5 | Nov 3, 2020 | SYSTEM | (\$1,267.38) | |
| | | | | | 6 | Nov 16, 2020 | SYSTEM | \$1,267.38 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 6 | Nov 16, | SYSTEM | (\$1,267.38) | |



MoDOT

Line Item Adjustments by Estimate

| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | |
|---------|--------|--|---------------------------|-----------------------------|----------------|-----------------|---------------|----------------|---|----------|---|
| S3261 | 0170 | 4 IN. WHITE | Material | | | 2020 | | | | | |
| | | WATERBORNE PAVEMENT MARKING | | | 7 | Dec 3, 2020 | SYSTEM | \$1,267.38 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user browns1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | |
| | | | | | 7 | Dec 3, 2020 | SYSTEM | (\$1,267.38) | | | |
| | | | | | 8 | Dec 16, 2020 | SYSTEM | \$1,267.38 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate. | | |
| | | | | | 8 | Dec 16, 2020 | SYSTEM | (\$1,267.38) | | | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - To | tal | | | | \$0.00 | | | |
| | 0170 - | Total | | | | | | \$0.00 | | | |
| | 0180 | 4 IN. YELLOW WATERBORNE PAVEMENT | Material | | 4 | Oct 16, 2020 | SYSTEM | \$136.86 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user taylod2 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | |
| | | MARKING | | | 4 | Oct 16, 2020 | SYSTEM | (\$136.86) | | | |
| | | | | | 5 | Nov 3, 2020 | SYSTEM | \$970.11 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate. | | |
| | | | | | 5 | Nov 3, 2020 | SYSTEM | (\$970.11) | | | |
| | | | | | 6 | Nov 16, 2020 | SYSTEM | \$970.11 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate. | | |
| | | | | | 6 | Nov 16, 2020 | SYSTEM | (\$970.11) | | | |
| | | | | | | | 7 | Dec 3, 2020 | SYSTEM | \$970.11 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user browns1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 7 | Dec 3, 2020 | SYSTEM | (\$970.11) | | | |
| | | | | | 8 | Dec 16, 2020 | SYSTEM | \$970.11 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate. | | |
| | | | | | 8 | Dec 16, 2020 | SYSTEM | (\$970.11) | | | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - To | tal | | | | \$0.00 | | | |
| | 0180 - | Total | | | | | | \$0.00 | | | |
| | 0220 | GUARDRAIL TYPE A | Construction Stockpile | | 5 | Nov 3, 2020 | SYSTEM | (\$4,168.00) | Payment Estimate Item Adjustment generated Stockpile Transaction | | |
| | | | | - Total | | | | (\$4,168.00) | | | |
| | | | Construction | Stockpile - 1 | Γotal | | | (\$4,168.00) | | | |
| | | | Construction Stockpile | | 1 | Feb 3, 2020 | SYSTEM | \$4,168.00 | Payment Estimate Item Adjustment generated Stockpile Transaction | | |
| | | | STMI | - Total | | | | \$4,168.00 | | | |
| | | | Construction | Stockpile S | TMI - Total | | | \$4,168.00 | | | |
| | 0220 - | Total | | | | | | \$0.00 | | | |
| | 0230 | MGS HEIGHT AND BLOCK | Construction Stockpile | | 5 | Nov 3, 2020 | SYSTEM | (\$540.80) | Payment Estimate Item Adjustment generated Stockpile Transaction | | |
| | | TRANSITION | | - Total | | | | (\$540.80) | | | |
| | | | Construction | Stockpile - 1 | Γotal | | | (\$540.80) | | | |
| | | | Construction Stockpile | | 1 | Feb 3, 2020 | SYSTEM | \$540.80 | Payment Estimate Item Adjustment generated Stockpile Transaction | | |
| | | | STMI | - Total | | | | \$540.80 | | | |
| | | | Construction | Stockpile S | TMI - Total | | | \$540.80 | | | |
| | | | Material | | 5 | Nov 3, 2020 | SYSTEM | \$1,484.32 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate. | | |





| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|---|---|-----------------------------|----------------|-----------------|---------------|--------------------------|---|
| J5S3261 | 0230 | MGS HEIGHT AND BLOCK TRANSITION | Material | 71 | 5 | Nov 3, 2020 | SYSTEM | (\$1,484.32) | |
| | | | | | 6 | Nov 16, 2020 | SYSTEM | \$1,484.32 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 6 | Nov 16, 2020 | SYSTEM | (\$1,484.32) | |
| | | | | | 7 | Dec 3, 2020 | SYSTEM | \$1,484.32 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user browns1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 7 | Dec 3, 2020 | SYSTEM | (\$1,484.32) | |
| | | | | | 8 | Dec 16, 2020 | SYSTEM | \$1,484.32 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 8 | Dec 16, 2020 | SYSTEM | (\$1,484.32) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0230 - | Total | | | | | | \$0.00 | |
| | 0240 | BRIDGE ANCHOR SECTION, 6 5 FT. POSTS | Construction Stockpile | | 5 | Nov 3, 2020 | SYSTEM | (\$4,076.00) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | - Total | | | | (\$4,076.00) | |
| | | | Construction | Stockpile - 1 | Γotal | | | (\$4,076.00) | |
| | | | Construction Stockpile | | 1 | Feb 3, 2020 | SYSTEM | \$4,076.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | STMI | - Total | | | | \$4,076.00 | |
| | | | Construction Stockpile STMI - Total | | | | | \$4,076.00 | |
| | 0240 - | Total | | | | | | \$0.00 | |
| | 0250 | ASYMMETRICAL TRNS. SEC., 6.5 FT. POSTS | Construction Stockpile | | 5 | Nov 3, 2020 | SYSTEM | (\$612.00) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | - Total | | | | (\$612.00) | |
| | | | Construction | Stockpile - 1 | Γotal | | | (\$612.00) | |
| | | | Construction Stockpile STMI | | 1 | Feb 3, 2020 | SYSTEM | \$612.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | - Total | | | | \$612.00 | |
| | | | Construction Stockpile STMI - Total | | | | | \$612.00 | |
| | 0250 - | Total | | | | | | \$0.00 | |
| | 0260 | TYPE A CRASHWORTHY END TERMINAL (MASH) | Construction Stockpile | | 5 | Nov 3, 2020 | SYSTEM | (\$3,020.00) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | - Total | | | | (\$3,020.00) | |
| | | | Construction | Stockpile - 1 | | | | (\$3,020.00) | |
| | | | Construction Stockpile STMI | - Total | 1 | Feb 3, 2020 | SYSTEM | \$3,020.00 \$3,020.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | Construction | | TMI - Tota | | | \$3,020.00 | |
| | 0260 | Construction Stockpile STMI - Total 60 - Total | | | | | | | |
| | | | O-mat " | | - | No. 0 | OVOTEL | \$0.00 | Down and Falling to House Adjustment and the 100 of 17 To 17 |
| | 0270 | END ANCHOR | Construction Stockpile Construction Construction Stockpile STMI | - Total | 5 | Nov 3, 2020 | SYSTEM | (\$1,064.00) | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | | | Total | | | (\$1,064.00) | |
| | | | | - Stockpile - | | Eob 2 | CVCTEM | | Doument Estimate Item Adjustment generated Steelwile Transaction |
| | | | | - Total | 1 | Feb 3, 2020 | SYSTEM | \$1,064.00 \$1,064.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | Construction | | TMI - Tota | | | \$1,064.00 | |
| | 0270 - | Total | Sonstruction | -экоскрпе 5 | -mrota | | | | |
| | | | 0 1 " | | | 0.1.15 | 0)/0==: | \$0.00 | B 15 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 |
| | 0290 | MISC. | Construction Stockpile | | 4 | Oct 16, 2020 | SYSTEM | (\$77,587.54) | Payment Estimate Item Adjustment generated Stockpile Transaction |



MoDOT

Line Item Adjustments by Estimate

| | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|----------------|--|---------------------------|-------------------------------|----------------------------|---|--------------------------------|--|--|
| J5S3261 | 0290 | MISC. | Construction Stockpile | - Total | | | | (\$77,587.54) | |
| | | | Construction | onstruction Stockpile - Total | | | | | |
| | | | Construction Stockpile | | 3 | Oct 1, 2020 | SYSTEM | \$77,587.54 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | STMI | - Total | | | | \$77,587.54 | |
| | | | Construction | Stockpile ST | MI - Total | | | \$77,587.54 | |
| | | | Material | | 4 | Oct 16, 2020 | SYSTEM | \$176,927.55 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user taylod2 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 4 | Oct 16, 2020 | SYSTEM | (\$176,927.55) | |
| | | | | | 5 | Nov 3, 2020 | SYSTEM | \$176,927.55 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user hensor overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 5 | Nov 3, 2020 | SYSTEM | (\$176,927.55) | |
| | | | | | 6 | Nov 16, 2020 | SYSTEM | \$176,927.55 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 6 | Nov 16, 2020 | SYSTEM | (\$176,927.55) | |
| | | | | | 7 | Dec 3, 2020 | SYSTEM | \$176,927.55 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user browns1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 7 | Dec 3, 2020 | SYSTEM | (\$176,927.55) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 0290 - | · Total | | | | | | \$0.00 | |
| | 0300 | CLEANING AND EPOXY COATING | Material | | 4 | Oct 16, 2020 | SYSTEM | \$6,679.80 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user taylod2 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 4 | Oct 16, | SYSTEM | (\$0.070.00) | |
| | | | | | Ť | 2020 | | (\$6,679.80) | |
| | | | | | 5 | | SYSTEM | \$6,679.80 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user hensor overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | | 2020 Nov 3, | SYSTEM | , , , | Estimate Item Adjustment (0013) due to user hensor overridding Payment |
| | | | | - Total | 5 | 2020 Nov 3, 2020 Nov 3, | | \$6,679.80 | Estimate Item Adjustment (0013) due to user hensor overridding Payment |
| | | | Material - Tot | | 5 | 2020 Nov 3, 2020 Nov 3, | | \$6,679.80 (\$6,679.80) | Estimate Item Adjustment (0013) due to user hensor overridding Payment |
| | 0300 - | · Total | Material - Tot | | 5 | 2020 Nov 3, 2020 Nov 3, | | \$6,679.80 (\$6,679.80) | Estimate Item Adjustment (0013) due to user hensor overridding Payment |
| | 0300 - 0310 | PROTECTIVE COATING - CONCRETE | | | 5 | 2020 Nov 3, 2020 Nov 3, | | \$6,679.80 (\$6,679.80) \$0.00 | Estimate Item Adjustment (0013) due to user hensor overridding Payment |
| | | PROTECTIVE COATING - | | | 5 | 2020 Nov 3, 2020 Nov 3, 2020 | SYSTEM | \$6,679.80 (\$6,679.80) \$0.00 \$0.00 | Estimate Item Adjustment (0013) due to user hensor overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user taylod2 overridding Payment |
| | | PROTECTIVE COATING - CONCRETE | | | 5 | 2020 Nov 3, 2020 Nov 3, 2020 Oct 16, 2020 | SYSTEM | \$6,679.80 (\$6,679.80) \$0.00 \$0.00 \$4,240.92 | Estimate Item Adjustment (0013) due to user hensor overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user taylod2 overridding Payment |
| | | PROTECTIVE COATING - CONCRETE | | | 5 5 4 4 | 2020 Nov 3, 2020 Nov 3, 2020 Oct 16, 2020 Oct 16, 2020 Nov 3, | SYSTEM SYSTEM | \$6,679.80 (\$6,679.80) \$0.00 \$0.00 \$4,240.92 | Estimate Item Adjustment (0013) due to user hensor overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user taylod2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user hensor overridding Payment |
| | | PROTECTIVE COATING - CONCRETE | | | 5 5 4 4 5 5 | 2020 Nov 3, 2020 Nov 3, 2020 Oct 16, 2020 Nov 3, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM | \$6,679.80 (\$6,679.80) \$0.00 \$0.00 \$4,240.92 (\$4,240.92) | Estimate Item Adjustment (0013) due to user hensor overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user taylod2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user hensor overridding Payment |
| | | PROTECTIVE COATING - CONCRETE | | tal - Total | 5 5 4 4 5 5 | 2020 Nov 3, 2020 Nov 3, 2020 Oct 16, 2020 Nov 3, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM | \$6,679.80 (\$6,679.80) \$0.00 \$0.00 \$4,240.92 (\$4,240.92) \$4,240.92 | Estimate Item Adjustment (0013) due to user hensor overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user taylod2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user hensor overridding Payment |
| | 0310 | PROTECTIVE COATING - CONCRETE | Material | tal - Total | 5 5 4 4 5 5 | 2020 Nov 3, 2020 Nov 3, 2020 Oct 16, 2020 Nov 3, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM | \$6,679.80 (\$6,679.80) \$0.00 \$0.00 \$4,240.92 (\$4,240.92) \$4,240.92 (\$4,240.92) | Estimate Item Adjustment (0013) due to user hensor overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user taylod2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user hensor overridding Payment |
| | 0310 | PROTECTIVE COATING - CONCRETE BENTS AND | Material Material - Tot | tal - Total | 5 5 4 4 5 5 | 2020 Nov 3, 2020 Nov 3, 2020 Oct 16, 2020 Nov 3, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM | \$6,679.80 \$0.00 \$0.00 \$0.00 \$4,240.92 (\$4,240.92) \$4,240.92 (\$4,240.92) | Estimate Item Adjustment (0013) due to user hensor overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user taylod2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user hensor overridding Payment |
| | 0310 - | PROTECTIVE COATING - CONCRETE BENTS AND Total OPEN CELL FOAM JOINT | Material Material - Tot | tal - Total | 5 5 4 4 5 5 | 2020 Nov 3, 2020 Nov 3, 2020 Oct 16, 2020 Nov 3, 2020 Nov 3, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM | \$6,679.80 (\$6,679.80) \$0.00 \$0.00 \$4,240.92 (\$4,240.92) \$4,240.92 (\$4,240.92) \$0.00 \$0.00 | Estimate Item Adjustment (0013) due to user hensor overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user taylod2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 14 on the current Payment Estimate. |

Dec 20, 2022



Line Item Adjustments by Estimate

| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | |
|---------|--------|--|--------------------|-----------------------------|----------------|-----------------|----------------|-----------------|--|--|---|--|--|--|--|---|-----------------|--------|----------------|
| J5S3261 | 0320 | OPEN CELL FOAM JOINT SEAL | | | | | | | Estimate Exception 13 on the current Payment Estimate. | | | | | | | | | | |
| | | | | | 6 | Nov 16, 2020 | SYSTEM | (\$13,127.40) | | | | | | | | | | | |
| | | | | | 7 | Dec 3, 2020 | SYSTEM | \$13,127.40 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user browns1 overridding Payment Estimate Exception 13 on the current Payment Estimate. | | | | | | | | | | |
| | | | | | 7 | Dec 3, 2020 | SYSTEM | (\$13,127.40) | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | | | | | | | |
| | 0320 - | Total | | | | | | \$0.00 | | | | | | | | | | | |
| | 0330 | EPOXY POLYMER WEARING SURFACE | Material | | 5 | Nov 3, 2020 | SYSTEM | \$39,833.04 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user hensor overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | | | | | |
| | | SURFACE | | | 5 | Nov 3, 2020 | SYSTEM | (\$39,833.04) | | | | | | | | | | | |
| | | | | | 6 | Nov 16, 2020 | SYSTEM | \$39,833.04 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user hensor overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | | | | | |
| | | | | | 6 | Nov 16, 2020 | SYSTEM | (\$39,833.04) | | | | | | | | | | | |
| | | | | | 7 | Dec 3, 2020 | SYSTEM | \$39,833.04 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user browns1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | | | | | |
| | | | | | 7 | Dec 3, 2020 | SYSTEM | (\$39,833.04) | | | | | | | | | | | |
| | | | | | 8 | Dec 16, 2020 | SYSTEM | \$39,833.04 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | | | | | |
| | | | | | 8 | Dec 16, 2020 | SYSTEM | (\$39,833.04) | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | |
| | | | Material - Total | | | | | \$0.00 | | | | | | | | | | | |
| | 0330 - | Total | | | | | | \$0.00 | | | | | | | | | | | |
| | 0340 | MISC. | ISC. Material | | 4 | Oct 16, 2020 | SYSTEM | \$147,638.42 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user taylod2 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | | | | | | | | |
| | | | | | 4 | Oct 16, 2020 | SYSTEM | (\$147,638.42) | | | | | | | | | | | |
| | | | | | 5 | Nov 3, 2020 | SYSTEM | \$147,638.42 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user hensor overridding Payment Estimate Exception 11 on the current Payment Estimate. | | | | | | | | | | |
| | | | | | | 5 | Nov 3, 2020 | SYSTEM | (\$147,638.42) | | | | | | | | | | |
| | | | | | | | 6 | Nov 16, 2020 | SYSTEM | \$147,638.42 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user hensor overridding Payment Estimate Exception 11 on the current Payment Estimate. | | | | | | | | |
| | | | | | | | | | | | | | | | | 6 | Nov 16, 2020 | SYSTEM | (\$147,638.42) |
| | | | | | | 7 | Dec 3, 2020 | SYSTEM | \$147,638.42 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user browns1 overridding Payment Estimate Exception 11 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 7 | Dec 3, 2020 | SYSTEM | (\$147,638.42) | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | | | | | | | | |
| | 0340 - | Total | | | | | | \$0.00 | | | | | | | | | | | |
| | 0350 | CLEANING AND EPOXY COATING | EPOXY | | 5 | Nov 3, 2020 | SYSTEM | \$16,625.28 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user hensor overridding Payment Estimate Exception 13 on the current Payment Estimate. | | | | | | | | | | |
| | | | | | 5 | Nov 3, 2020 | SYSTEM | (\$16,625.28) | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | |





| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------------|------------------------------------|--------------------|------------------------------------|---------------------|---|------------------------------------|--|---|
| J5S3261 | 0350 | CLEANING AND EPOXY COATING | Material - To | tal | | | | \$0.00 | |
| | 0350 - | - Total | | | | | | \$0.00 | |
| | 0360 | MISC. | Material | | 3 | Oct 1, 2020 | SYSTEM | \$14,782.96 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user taylod2 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 3 | Oct 1, 2020 | SYSTEM | (\$14,782.96) | |
| | | | | | 4 | Oct 16, 2020 | SYSTEM | \$14,782.96 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user taylod2 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 4 | Oct 16, 2020 | SYSTEM | (\$14,782.96) | |
| | | | | | 5 | Nov 3, 2020 | SYSTEM | \$14,782.96 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user hensor overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | | 5 | Nov 3, 2020 | SYSTEM | (\$14,782.96) | |
| | | | | | 6 | Nov 16, 2020 | SYSTEM | \$14,782.96 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user hensor overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 6 | Nov 16, 2020 | SYSTEM | (\$14,782.96) | |
| | | | | | 7 | Dec 3, 2020 | SYSTEM | \$14,782.96 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user browns1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 7 | Dec 3, 2020 | SYSTEM | (\$14,782.96) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Total | | | | | \$0.00 | |
| | 0360 - Total | | | | | | | \$0.00 | |
| | 0370 | OPEN CELL FOAM JOINT SEAL | Material | | 5 | Nov 3, 2020 | SYSTEM | \$20,654.70 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user hensor overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | 5 | Nov 3, | SYSTEM | (\$20,654.70) | |
| | | | | | | 2020 | | | |
| | | | | | 6 | Nov 16, 2020 | SYSTEM | \$20,654.70 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 6 | Nov 16, | SYSTEM | \$20,654.70 (\$20,654.70) | Estimate Item Adjustment (0011) due to user hensor overridding Payment |
| | | | | | | Nov 16, 2020 | | | Estimate Item Adjustment (0011) due to user hensor overridding Payment |
| | | | | | 6 | Nov 16, 2020 Nov 16, 2020 Dec 3, | SYSTEM | (\$20,654.70) | Estimate Item Adjustment (0011) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user browns1 overridding Payment |
| | | | | - Total | 6 | Nov 16, 2020 Nov 16, 2020 Dec 3, 2020 Dec 3, | SYSTEM SYSTEM | (\$20,654.70) \$20,654.70 (\$20,654.70) | Estimate Item Adjustment (0011) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user browns1 overridding Payment |
| | | | Material - To | tal | 6 7 7 | Nov 16, 2020 Nov 16, 2020 Dec 3, 2020 Dec 3, 2020 | SYSTEM SYSTEM SYSTEM | (\$20,654.70) \$20,654.70 (\$20,654.70) \$0.00 | Estimate Item Adjustment (0011) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user browns1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | Material - To | | 7 7 8 | Nov 16, 2020 Nov 16, 2020 Dec 3, 2020 Dec 3, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM | (\$20,654.70) \$20,654.70 (\$20,654.70) \$0.00 \$0.00 (\$10,327.35) | Estimate Item Adjustment (0011) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user browns1 overridding Payment Estimate Exception 14 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | tal Overrun | 6 7 7 7 8 8 8 8 8 | Nov 16, 2020 Nov 16, 2020 Dec 3, 2020 Dec 3, 2020 Dec 16, | SYSTEM SYSTEM SYSTEM | (\$20,654.70) \$20,654.70 (\$20,654.70) \$0.00 \$0.00 (\$10,327.35) \$10,327.35 | Estimate Item Adjustment (0011) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user browns1 overridding Payment Estimate Exception 14 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates |
| | | | Overrun | Overrun Overrun Overrun - To | 6 7 7 7 8 8 8 8 8 | Nov 16, 2020 Nov 16, 2020 Dec 3, 2020 Dec 3, 2020 Dec 16, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM | (\$20,654.70) \$20,654.70 (\$20,654.70) \$0.00 \$0.00 (\$10,327.35) \$10,327.35 | Estimate Item Adjustment (0011) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user browns1 overridding Payment Estimate Exception 14 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment |
| | | | | Overrun Overrun Overrun - To | 6 7 7 7 8 8 8 8 8 | Nov 16, 2020 Nov 16, 2020 Dec 3, 2020 Dec 3, 2020 Dec 16, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM | (\$20,654.70) \$20,654.70 (\$20,654.70) \$0.00 \$0.00 (\$10,327.35) \$10,327.35 | Estimate Item Adjustment (0011) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user browns1 overridding Payment Estimate Exception 14 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment |
| | | -Total | Overrun - To | Overrun Overrun Overrun - To | 6 7 7 7 8 8 8 Ootal | Nov 16, 2020 Nov 16, 2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$20,654.70) \$20,654.70 (\$20,654.70) \$0.00 \$0.00 (\$10,327.35) \$10,327.35 \$0.00 \$0.00 | Estimate Item Adjustment (0011) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user browns1 overridding Payment Estimate Exception 14 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | 0370 - | - Total MODIFIED DECK REPAIR | Overrun - To | Overrun Overrun Overrun - To | 6 7 7 8 8 8 8 8 8 | Nov 16, 2020 Nov 16, 2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$20,654.70) \$20,654.70 (\$20,654.70) \$0.00 \$0.00 (\$10,327.35) \$10,327.35 \$0.00 \$0.00 \$26,374.92 | Estimate Item Adjustment (0011) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user browns1 overridding Payment Estimate Exception 14 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment |
| | | MODIFIED DECK | Overrun - To | Overrun Overrun - T | 6 7 7 7 8 8 8 Ootal | Nov 16, 2020 Nov 16, 2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$20,654.70) \$20,654.70 (\$20,654.70) \$0.00 \$0.00 (\$10,327.35) \$10,327.35 \$0.00 \$0.00 \$26,374.92 | Estimate Item Adjustment (0011) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user browns1 overridding Payment Estimate Exception 14 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user hensor overridding Payment |
| | | MODIFIED DECK | Overrun - To | Overrun - T Overrun - T tal | 6 7 7 8 8 8 8 8 8 | Nov 16, 2020 Nov 16, 2020 Dec 3, 2020 Dec 16, 2020 Dec 16, 2020 Dec 16, 2020 Dec 16, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$20,654.70) \$20,654.70 (\$20,654.70) \$0.00 \$0.00 (\$10,327.35) \$10,327.35 \$0.00 \$0.00 \$26,374.92 | Estimate Item Adjustment (0011) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user browns1 overridding Payment Estimate Exception 14 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user hensor overridding Payment |



Dec 20, 2022

| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----------|--------------|---------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| J5S3261 | 5003 - Total | | | | | | | \$0.00 | |
| | 5005 | OPEN CELL FOAM JOINT SEAL | Material | | 8 | Dec 16, 2020 | SYSTEM | \$12,197.13 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 8 | Dec 16, 2020 | SYSTEM | (\$12,197.13) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 5005 - | Total | | | | | | \$0.00 | |
| J5S3261 | - Total | | | | | | | \$0.00 | |
| Overall - | Total | | | | | | | \$0.00 | |