

Pay Estimate Created Date: September 16, 2020

Progress Estima	ate Number	Contract ID Prime Contractor	191213-D05 Willard Asphalt Pavin		Pay Period Start Pay Period End			Original Contract Amou Net Change Order Amou Current Contract Amou	int (\$176,344.63)
Approval Date									By User
September 16, 2020			Generated an	d Appro	ved (and should b	e considere	d Draft) at	the Project Office Level by	moorec1
September 16, 2020			Reviewed and App	proved (a	and should be cor	nsidered Dra	ft) at the I	Resident Engineer Level by	abbote1
September 16, 2020				Revie	wed and Approve	d at the Cen	tral Office	Controllers Office Level by	greggd1
Original Comp	letion Date	Current Co	ompletion Date	Ac	tual Completion	Date	%	of Current Contract Amou	int Complete
November	1, 2020	Novem	ber 1, 2020					96.93%	

No Milestones Exist for Contract

Contract Total Pa	y For Estimate No. 11			
		This Estimate	Previous	To Date
191213-D05				
	Total Posted Items Pay	\$384,864.65	\$3,403,439.92	\$3,788,304.57
	Gross Item Adjustments	(\$54,713.05)	(\$160,437.14)	(\$215,150.19)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	-		\$3,243,002.78	\$3,573,154.38
Contract Total Pa	yable This Estimate:	\$330,151.60		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5S3280	0100	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	TONS	\$60.350	5,006.7	\$302,154.35
	0110	4071005	TACK COAT	GAL	\$2.200	5,316	\$11,695.20
	0360	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	STA	\$11.000	1,286.3	\$14,149.30
	0370	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	STA	\$11.000	792.8	\$8,720.80
	0430	8051000A	SEEDING - COOL SEASON MIXTURES	ACRE	\$2,150.000	-4.7	(\$10,105.00)
	0500	6061060	MGS GUARDRAIL	LF	\$22.000	1,000	\$22,000.00
	0510	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	EA	\$3,000.000	4	\$12,000.00
	0520	6061080	MGS END ANCHOR	EA	\$1,200.000	3	\$3,600.00
	0540	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$2,950.000	7	\$20,650.00
Project J5S3	280 - Total						\$384,864.65
Overall - Tot	al						\$384,864.65

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3280	0040	FURNISHING ROCK FILL	Material			-21	\$30.00	(\$630.00)
	0040	FURNISHING ROCK FILL	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	21	\$30.00	\$630.00
	0800	GRAVEL (A) OR CRUSHED STONE (B)	Material			-33.2	\$225.00	(\$7,470.00)
	0080	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user moorec1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	33.2	\$225.00	\$7,470.00
	0090	BITUMINOUS PAVEMENT	Material			-6,598.2	\$50.75	(\$334,858.65)

Revision 4/1/2020 Page 1 of 24



Pay Estimate Created Date: September 16, 2020

Progress Estimate Number
11 1 1 1 1 1 1 1 2 1 3 - D05 Prime Contract ID 191213-D05 Pay Period Start September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 15, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 15, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 15, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End

						,	0,000,000.00
Line r No.		Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
0	MIXTURE PG64-22 (BASE)						
0090	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user moorec1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	6,598.2	\$50.75	\$334,858.65
0100	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	2,172.6	(\$2.46)	(\$5,337.64
0100	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	2,834.1	(\$2.46)	(\$6,962.82
0100	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	Asphalt Cement Price Adjustment	Adjustment calculation saved to eProjects: "191213_D05_J5S3280_AC_Adjustment_20200915"			(\$13,142.59
0110	TACK COAT	Material			-25,307	\$2.20	(\$55,675.40
0110	TACK COAT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	25,307	\$2.20	\$55,675.40
0120	FURNISHING TYPE 2 ROCK DITCH LINER	Material			-9	\$29.50	(\$265.50
0120	FURNISHING TYPE 2 ROCK DITCH LINER	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user moorec1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	9	\$29.50	\$265.50
0140	ROCK LINING	Material			-41	\$215.00	(\$8,815.00
0140) ROCK LINING	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user moorec1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	41	\$215.00	\$8,815.00
0230	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Material			-238	\$20.00	(\$4,760.00
0230	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	238	\$20.00	\$4,760.00
0270	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-44	\$27.75	(\$1,221.00
0270	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user moorec1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	44	\$27.75	\$1,221.00
0280	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	Material			-2	\$1,000.00	(\$2,000.00
0280	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0011) due to user moorec1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	2	\$1,000.00	\$2,000.00
0290	TEMPORARY REMOVABLE MARKING TAPE, 24 IN.,	Material			-44	\$0.20	(\$8.80



Pay Estimate Created Date: September 16, 2020

Progress Estimate Number
11 1 1 1 1 1 1 2 1 3 - D05 Prime Contract ID 191213-D05 Pay Period Start September 2, 2020 Original Contract Amount September 15, 2020 Original Contract Amount (\$4,084,678.21 Pay Period End September 15, 2020 Original Contract Amount Current Contract Amount \$3,908,333.58 Pay Period End September 2, 2020 Original Contract Amount (\$176,344.63) Original Contract Amount \$4,084,678.21 Pay Period End September 15, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 15, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 15, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 15, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 15, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 15, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 15, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contract Amount \$4,084,678.21 Pay Period End September 2, 2020 Original Contr

						eni Contract		3,900,333.30
er	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
30		WHITE						
	0290	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) due to user moorec1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	44	\$0.20	\$8.80
	0300	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-87,538.2	\$0.11	(\$9,629.20
	0300	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0013) due to user moorec1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	87,538.2	\$0.11	\$9,629.20
	0310	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material			-82,017.4	\$0.09	(\$7,381.57
	0310	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0014) due to user moorec1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	82,017.4	\$0.09	\$7,381.57
	0390	CLASS B-1 CONCRETE (CULVERTS)	Material			-138	\$1,500.00	(\$207,000.00
	0390	CLASS B-1 CONCRETE (CULVERTS)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0015) due to user moorec1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	138	\$1,500.00	\$207,000.00
	0420	78 IN. PIPE GROUP C	Material			-16	\$320.00	(\$5,120.00
	0420	78 IN. PIPE GROUP C	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0016) due to user moorec1 overridding Payment Estimate Exception 27 on the current Payment Estimate.	16	\$320.00	\$5,120.00
	0430	SEEDING - COOL SEASON MIXTURES	Material			-18.6	\$2,150.00	(\$39,990.00
	0430	SEEDING - COOL SEASON MIXTURES	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0027) due to user moorec1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	18.6	\$2,150.00	\$39,990.00
	0450	ROCK DITCH CHECK	Material			-615	\$10.75	(\$6,611.25
	0450	ROCK DITCH CHECK	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0017) due to user moorec1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	615	\$10.75	\$6,611.25
	0460	ALTERNATE DITCH CHECK	Material			-100	\$8.50	(\$850.00
	0460	ALTERNATE DITCH CHECK	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0018) due to user moorec1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	100	\$8.50	\$850.00
	0500	MGS GUARDRAIL	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$10,420.00
	0510	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$5,174.00
	0520	MGS END ANCHOR	Construction		Payment Estimate Item Adjustment generated			(\$1,596.00

Revision 4/1/2020 Page 3 of 24



Pay Estimate Created Date: September 16, 2020

Progress Estimate Number
11 1 1 1 1 1 1 2 1 3 - D05 Prime Contract ID Prime Contractor Willard Asphalt Paving, Inc. Pay Period Start September 2, 2020 Prime Contractor Willard Asphalt Paving, Inc. Pay Period End September 15, 2020 Prime Contract Amount Current Contract Amount 3,3,908,333.58

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3280			Stockpile		Stockpile Transaction			
	0540	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$12,080.00)
	0580	CLASS B-1 CONCRETE (CULVERTS-BRIDGE)	Material			-21.8	\$3,300.00	(\$71,940.00)
	0580	CLASS B-1 CONCRETE (CULVERTS-BRIDGE)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0023) due to user moorec1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	21.8	\$3,300.00	\$71,940.00
	0590	REINFORCING STEEL (CULVERTS-BRIDGE)	Material			-8,160	\$2.00	(\$16,320.00)
	0590	REINFORCING STEEL (CULVERTS-BRIDGE)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0024) due to user moorec1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	8,160	\$2.00	\$16,320.00
	0630	CLEANING AND EPOXY COATING	Material			-161	\$42.10	(\$6,778.10)
	0630	CLEANING AND EPOXY COATING	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0025) due to user moorec1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	161	\$42.10	\$6,778.10
	0640	BRIDGE GUARDRAIL (THRIE BEAM)	Material			-63	\$300.00	(\$18,900.00)
	0640	BRIDGE GUARDRAIL (THRIE BEAM)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0026) due to user moorec1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	63	\$300.00	\$18,900.00
Total								(\$54,713.05)

Revision 4/1/2020 Page 4 of 24



					Co	ontract Project Information	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J5S3280	FAS S401(70)	Resurface and add shoulders	U, T	MILLER	from Route 42 to Crocker		
Γotals by J	Job Numbe	rs					
J5S3280					This Estimate	Previous	To Date
		d Item Pay Item Adjustm	ents		\$384,864.65 (\$54,713.05)	\$3,403,439.92 (\$160,437.14)	\$3,788,304.57 (\$215,150.19)
		•	Gross	Item Pay	\$330,151.60	\$3,243,002.78	\$3,573,154.38
	Incent	ive			\$0.00	\$0.00	\$0.00
	Disino				\$0.00	\$0.00	\$0.00
	Liquid	lated Damages	s		\$0.00	\$0.00	\$0.00
	Other	Contract Adiu	stments		\$0.00	\$0.00	\$0.00

Revision 4/1/2020 Page 5 of 24



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 2142000, Project Item Line Number 0040, Material Set 214200096, Material 0214STRF - Stone for Rock Fill, Acceptance Action Generic 0214STRF is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 3105002, Project Item Line Number 0080, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 4013000, Project Item Line Number 0090, Material Set 401300096, Material 0401BPPMBB - Plant Mix Bituminous Base, Acceptance Action Generic AspLow is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 4071005, Project Item Line Number 0110, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 6096020, Project Item Line Number 0120, Material Set 609602096, Material 0609PDDL - Paved Drainage Material for Ditch Liner, Acceptance Action Generic 0609PDDL is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 6096020, Project Item Line Number 0120, Material Set 609602096, Material 0609PDDL - Paved Drainage Material for Ditch Liner, Acceptance Action Generic PipeDrainageMisc is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 6097000, Project Item Line Number 0140, Material Set 609700096, Material 0611EPM - Embankment Protection Material, Acceptance Action Generic 0611EPM is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 6173600D, Project Item Line Number 0230, Material Set 6173600D96, Material 0617TCRCTF - Type F Concrete Traffic Barrier, Acceptance Action Generic 0617TCRCTF is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 6200015, Project Item Line Number 0270, Material Set 620001596, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 6200033, Project Item Line Number 0280, Material Set 620003396, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 6205309, Project Item Line Number 0290, Material Set 620530996, Material 1048PMT - Marking Tape, Acceptance Action Generic 1048PMT is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 6206000C, Project Item Line Number 0300, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 6206000C, Project Item Line Number 0300, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 6206001C, Project Item Line Number 0310, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 6206001C, Project Item Line Number 0310, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 7034040, Project Item Line Number 0580, Material Set 703404096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 7034040, Project Item Line Number 0580, Material Set 703404096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 7034040, Project Item Line Number 0580, Material Set 703404096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 7034041, Project Item Line Number 0390, Material Set 703404196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 7034041, Project Item Line Number 0390, Material Set 703404196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 7034041, Project Item Line Number 0390, Material Set 703404196, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 7040113, Project Item Line Number 0630, Material Set 704011396, Material 1039ERBCT3 - Type III Epoxy Resin for Conc Patch Cmp, Acceptance Action Generic 1039ERBCT3 is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 7061020, Project Item Line Number 0590, Material Set 706102096, Material 1036RSDFPL42M29 - Reinforcing Steel No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Pending QC/QA test results/reports.	moorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 7061020, Project Item Line Number 0590, Material Set 706102096, Material 1036RSDFPL42M32 - Reinforcing Steel No. 10/M32 Gr	Pending QC/QA test results/reports.	moorec1	Overridden

Revision 4/1/2020 Page 6 of 24



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation E	Entered By	Status
60/M420@, Acceptance Action Generic ReSteelBars is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 7061020, Project Item Line Number 0590, Material Set 706102096, Material 1036RSDFPL42M36 - Reinforcing Steel No. 11/M36 Gr 60/M420@, Acceptance Action Generic ReSteelBars is insufficient.	Pending QC/QA test results/reports.	noorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 7134000, Project Item Line Number 0640, Material Set 713400096, Material 1040GRTBCAT2 - Steel Thrie Beam for Class A Type 2, Acceptance Action Generic 1040GRTBCAT2 is insufficient.	Pending QC/QA test results/reports.	noorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 7250478, Project Item Line Number 0420, Material Set 725047896, Material 1020CPCSZC.078 - CulvPipe Zn Ctd Corrug Stl 78" 1980mm, Acceptance Action Generic 1020CPCSZC.078 is insufficient.	Pending QC/QA test results/reports.	noorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 8051000A, Project Item Line Number 0430, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient.	Pending QC/QA test results/reports.	noorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 8051000A, Project Item Line Number 0430, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Pending QC/QA test results/reports.	noorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 8061005, Project Item Line Number 0450, Material Set 806100596, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Pending QC/QA test results/reports.	noorec1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3280, Item 8061006, Project Item Line Number 0460, Material Set 806100696, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Pending QC/QA test results/reports.	noorec1	Overridden

Revision 4/1/2020 Page 7 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted am Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-D05	J5S3280	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$20,000.00	\$0.00
		0001	0020	2063300	CLASS 4 EXCAVATION	100.00	0.00	100.00	CUYD	100.00	\$100.00	\$10,000.00
		0001	0030	2079909	MISC.MODIFIED LINEAR GRADING, CLASS II	1,576.10	0.00	1,576.10	STA	1,576.10	\$270.00	\$425,547.00
		0001	0040	2142000	FURNISHING ROCK FILL	21.00	0.00	21.00	CUYD	21.00	\$30.00	\$630.00
		0001	0050	2143000	PLACING ROCK FILL	21.00	0.00	21.00	CUYD	21.00	\$180.00	\$3,780.00
		0001	0060	2153000	SHAPING SLOPES, CLASS III	43.00	0.00	43.00	100F	43.00	\$950.00	\$40,850.00
		0001	0070	2163500	PARTIAL REMOVAL OF CULVERT CONCRETE	1.00	0.00	1.00	LS	1.00	\$52,000.00	\$52,000.00
		0001	0080	3105002	GRAVEL (A) OR CRUSHED STONE (B)	148.00	0.00	148.00	TONS	33.20	\$225.00	\$7,470.00
		0001	0090	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	12,651.90	-53.70	12,598.20	TONS	12,598.20	\$50.75	\$639,358.65
		0001	0100	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	26,255.00	40.70	26,295.70	TONS	26,295.70	\$60.35	\$1,586,945.50
		0001	0110	4071005	TACK COAT	28,214.00	-2,907.00	25,307.00	GAL	25,307.00	\$2.20	\$55,675.40
		0001	0120	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	9.00	0.00	9.00	CUYD	9.00	\$29.50	\$265.50
		0001	0130	6096042	PLACING TYPE 2 ROCK DITCH LINER	9.00	0.00	9.00	CUYD	9.00	\$420.00	\$3,780.00
		0001	0135	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	1,500.00	-1,300.00	200.00	LF	200.00	\$10.00	\$2,000.00
		0001	0140	6097000	ROCK LINING	41.00	0.00	41.00	CUYD	41.00	\$215.00	\$8,815.00
		0001	0150	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARRELS)	4.00	-2.00	2.00	EA	2.00	\$1,800.00	\$3,600.00
		0001	0155	6122020	REPLACEMENT SAND BARREL	1.00	-1.00	0.00	EA	0.00	\$150.00	\$0.00
		0001	0156	6122030	IMPACT ATTENUATOR (RELOCATION)	6.00	-4.00	2.00	EA	2.00	\$750.00	\$1,500.00
		0001	0160	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1.00	\$0.00
		0001	0170	6161005	CONSTRUCTION SIGNS	2,164.00	0.00	2,164.00	SQFT	1,346.50	\$6.50	\$8,752.25
		0001	0180	6161009	FLAG ASSEMBLY	14.00	3.00	17.00	EA	14.00	\$20.00	\$280.00
		0001	0190	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	100.00	\$22.00	\$2,200.00
		0001	0200	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$4,000.00	\$8,000.00
		0001	0210	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$4,800.00	\$4,800.00
		0001	0220	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	8.00	-4.00	4.00	EA	4.00	\$1,800.00	\$7,200.00
		0001	0230	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	2,500.00	-2,262.00	238.00	LF	238.00	\$20.00	\$4,760.00
		0001	0240	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$121,000.00	\$121,000.00
		0001	0250	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	-3.00	1.00	EA	1.00	\$600.00	\$600.00
		0001	0260	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, $ 6 \text{IN}. $ WHITE	130.00	0.00	130.00	LF	0.00	\$6.75	\$0.00
		0001	0270	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	78.00	0.00	78.00	LF	44.00	\$27.75	\$1,221.00
		0001	0280	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	2.00	0.00	2.00	EA	2.00	\$1,000.00	\$2,000.00
		0001	0290	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	140.00	-96.00	44.00	LF	44.00	\$0.20	\$8.80
		0001	0300	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	271,424.00	0.00	271,424.00	LF	87,538.20	\$0.11	\$9,629.20
		0001	0310	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	249,971.00	0.00	249,971.00	LF	82,017.40	\$0.09	\$7,381.57
		0001	0320	6207001	PAVEMENT MARKING REMOVAL	8,000.00	-7,170.00	830.00	LF	830.00	\$0.70	\$581.00
		0001	0330	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	3,195.00	-847.00	2,348.00	LF	2,348.00	\$1.75	\$4,109.00
		0001	0340	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,098.00	0.00	1,098.00	SQYD	1,098.00	\$12.45	\$13,670.10
		0001	0350	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,909.00	0.00	1,909.00	SQYD	1,909.00	\$11.35	\$21,667.15
		0001	0360	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	1,286.30	0.00	1,286.30	STA	1,286.30	\$11.00	\$14,149.30
		0001	0370	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	792.80	0.00	792.80	STA	792.80	\$11.00	\$8,720.80
		0001	0380	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$10,000.00	\$10,000.00
		0001	0390	7034041	CLASS B-1 CONCRETE (CULVERTS)	138.00	0.00	138.00	CUYD	138.00	\$1,500.00	\$207,000.00
		0001	0400	7061030	REINFORCING STEEL (CULVERTS)	24,120.00	0.00	24,120.00	LB	24,120.00	\$2.00	\$48,240.00
		0001	0410	7250424	24 IN. PIPE GROUP C	32.00	-32.00	0.00	LF	0.00	\$135.00	\$0.00

Revision 4/1/2020 Page 8 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract n.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
1213-D05	J5S3280	0001	0420	7250478	78 IN. PIPE GROUP C	16.00	0.00	16.00	LF	16.00	\$320.00	\$5,120.00
		0001	0430	8051000A	SEEDING - COOL SEASON MIXTURES	37.20	-13.90	23.30	ACRE	18.60	\$2,150.00	\$39,990.00
		0001	0440	8061004	SEDIMENT TRAP ROCK	92.20	-92.20	0.00	CUYD	0.00	\$56.75	\$0.00
		0001	0450	8061005	ROCK DITCH CHECK	4,915.00	-4,300.00	615.00	LF	615.00	\$10.75	\$6,611.25
		0001	0460	8061006	ALTERNATE DITCH CHECK	614.00	-514.00	100.00	LF	100.00	\$8.50	\$850.00
		0001	0470	8061016	SEDIMENT REMOVAL	602.00	0.00	602.00	CUYD	24.00	\$18.00	\$432.00
		0001	0480	8061017	TEMPORARY SEEDING AND MULCHING	7.40	-7.40	0.00	ACRE	0.00	\$1,650.00	\$0.00
		0001	0490	8061019	SILT FENCE	3,072.00	-2,372.00	700.00	LF	700.00	\$2.20	\$1,540.00
		0010	0500	6061060	MGS GUARDRAIL	2,525.00	0.00	2,525.00	LF	2,525.00	\$22.00	\$55,550.00
		0010	0510	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	8.00	0.00	8.00	EA	8.00	\$3,000.00	\$24,000.00
		0010	0520	6061080	MGS END ANCHOR	8.00	0.00	8.00	EA	8.00	\$1,200.00	\$9,600.0
		0010	0530	6061081	MGS BRIDGE APPROACH TRANSITION (THRIE-BEAM BRIDGE)	8.00	0.00	8.00	EA	8.00	\$3,600.00	\$28,800.0
		0010	0540	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	24.00	-1.00	23.00	EA	23.00	\$2,950.00	\$67,850.0
		0040	0550	9039901	MISC.Adjust Existing Signs	1.00	0.00	1.00	LS	0.00	\$4,200.00	\$0.0
		0070	0560	2161501	REMOVAL OF ASPHALT WEARING SURFACE	184.00	0.00	184.00	SQFT	184.00	\$4.00	\$736.0
		0070	0570	2163500	PARTIAL REMOVAL OF CULVERT CONCRETE	1.00	0.00	1.00	LS	1.00	\$26,000.00	\$26,000.0
		0070	0580	7034040	CLASS B-1 CONCRETE (CULVERTS-BRIDGE)	17.90	3.90	21.80	CUYD	21.80	\$3,300.00	\$71,940.0
		0070	0590	7061020	REINFORCING STEEL (CULVERTS-BRIDGE)	7,480.00	680.00	8,160.00	LB	8,160.00	\$2.00	\$16,320.0
		0070	0600	7122300	BRIDGE RAIL (TWO TUBE STRUCTURAL STEEL)	107.00	0.00	107.00	LF	107.00	\$300.00	\$32,100.0
		0071	0610	7039902	MISC.Curb Modification	4.00	0.00	4.00	EA	4.00	\$5,000.00	\$20,000.0
		0072	0620	2169903	MISC.Removal of Existing Bridge Rail	70.00	0.00	70.00	LF	70.00	\$100.00	\$7,000.0
		0072	0630	7040113	CLEANING AND EPOXY COATING	161.00	0.00	161.00	SQFT	161.00	\$42.10	\$6,778.1
		0072	0640	7134000	BRIDGE GUARDRAIL (THRIE BEAM)	63.00	0.00	63.00	LF	63.00	\$300.00	\$18,900.0
		0001	5001	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	0.00	10.00	10.00	EA	0.00	\$185.00	\$0.0
		0001	5002	6189901	MISC.Mobilization (Additional Traffic Control Devices)	0.00	1.00	1.00	LS	0.00	\$800.00	\$0.0
		0070	5003	7069902	MISC.Resin Anchors (Culverts-Bridge Extensions)	0.00	43.00	43.00	EA	0.00	\$100.00	\$0.0
	Project J	5S3280 - To	tal Value	Posted to D	Pate as of Report Generated Date							\$3,788,304.5
13-D05 Ove	erall - Total	Value Pos	ted to Da	te as of Repo	ort Generated Date							\$3,788,304.5

Revision 4/1/2020 Page 9 of 24



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5S3280

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0100	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	9/2/20	9/16/20	2,172.60	TONS	Route U	LM 11.400	RT	LM 15.356	RT	
			9/3/20	9/16/20	2,834.10	TONS	Route U	LM 9.700	LT	LM 15.356	LT	
0110	4071005	TACK COAT	9/2/20	9/16/20	2,199.00	GAL	Route U	LM 11.400	RT	LM 15.356	RT	
			9/3/20	9/16/20	3,117.00	GAL	Route U	LM 9.700	LT	LM 15.356	LT	
0360	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	9/10/20	9/16/20	1,286.30	STA	Route U	LM 0.000	LT/RT	LM 15.016	LT/RT	
0370	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	9/10/20	9/16/20	792.80	STA	Route U	LM 0.000	LT/RT	LM 15.016	LT/RT	
0430	8051000A	SEEDING - COOL SEASON MIXTURES	8/7/20	9/3/20	-4.70	ACRE	Route U	LM 0.000	LT/RT	LM 15.356	LT/RT	Incorrect posting comment: "Paying 80% until final stabilization is reached. (xxx acres)(80%) = xxx acres" Correct posting comment: "Paying 80% until final stabilization is reached. (23.3 acres)(80%) = 18.6 acres" (Correct pay of 18.6 acres) - (Incorrect pay of 23.3 acre = Correction of 4.7 acres.
0500	6061060	MGS GUARDRAIL	9/2/20	9/16/20	900.00	LF	Route T	LM 9.070	LT/RT	LM 9.190	LT/RT	
			9/3/20	9/16/20	100.00	LF	Route T Bridge A2928	LM 4.718	LT/RT	LM 4.918	LT/RT	
0510	6061069	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	9/3/20	9/16/20	4.00	EA	Route T Bridge A2928	LM 4.718	LT/RT	LM 4.918	LT/RT	
0520	6061080	MGS END ANCHOR	9/2/20	9/16/20	3.00	EA	Route T	LM 9.070	LT/RT	LM 9.190	LT/RT	
0540	6063014	TYPE A CRSHWTHY END TERMINAL (MASH)	9/2/20	9/16/20	3.00	EA	Route T	LM 9.070	LT/RT	LM 9.190	LT/RT	
			9/3/20	9/16/20	4.00	EA	Route T Bridge A2928	LM 4.718	LT/RT	LM 4.918	LT/RT	

The information below this line are details from Line Item agency views.

No Agency View Details Exist

Revision 4/1/2020 Page 10 of 24



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
0040	FURNISHING ROCK FILL	Material		3	May 18, 2020	SYSTEM	(\$300.00)																	
				3	May 18, 2020	SYSTEM	\$300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user moorec1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																
				4	Jun 2, 2020	SYSTEM	(\$630.00)																	
				4	Jun 2, 2020	SYSTEM	\$630.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user moorec1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																
				5	Jun 16, 2020	SYSTEM	(\$630.00)																	
				5	Jun 16, 2020	SYSTEM	\$630.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user moorec1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																
				6	Jul 1, 2020	SYSTEM	(\$630.00)																	
				6	Jul 1, 2020	SYSTEM	\$630.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user moorec1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																
				7	Jul 16, 2020	SYSTEM	(\$630.00)																	
				7	Jul 16, 2020	SYSTEM	\$630.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user moorec1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																
				8	Aug 3, 2020	SYSTEM	(\$630.00)																	
				8	Aug 3, 2020	SYSTEM	\$630.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																
					9	Aug 17, 2020	SYSTEM	(\$630.00)																
					9	Aug 17, 2020	SYSTEM	\$630.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user moorec1 overridding Payment Estimate Exception 1 on the current Payment Estimate.															
									10	Sep 2, 2020	SYSTEM	(\$630.00)												
				10	Sep 2, 2020	SYSTEM	\$630.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																
					11	Sep 16, 2020	SYSTEM	(\$630.00)																
				11	Sep 16, 2020	SYSTEM	\$630.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																
			- Total				\$0.00																	
0040	Material - Total - Total						\$0.00 \$0.00																	
0080	GRAVEL (A) OR CRUSHED STONE (B)	Material		8	Aug 3, 2020	SYSTEM	(\$7,470.00)																	
	OTONE (B)	Material																		8	Aug 3, 2020	SYSTEM	\$7,470.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user moorec1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
																								9
				9	Aug 17, 2020	SYSTEM	\$7,470.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user moorec1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																
				10	Sep 2, 2020	SYSTEM	(\$7,470.00)																	
				10	Sep 2, 2020	SYSTEM	\$7,470.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user moorec1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																
				11	Sep 16, 2020	SYSTEM	(\$7,470.00)																	
				11	Sep 16, 2020	SYSTEM	\$7,470.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user moorec1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																

Revision 4/1/2020 Page 11 of 24



Aug. 17 SySTEM S328,865.50 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 2 on the current Payment Estimate (D002) due to use monocer to veerdiding Payme Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Payment Estimate Extended Exception 3 on the current Payment Estimate Exception 3 on the current Payment Estimate Extended Exception 3 on the current	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
Section Sect	0080		Material	- Total				\$0.00	
		Material - Total						\$0.00	
MIXTURE PG64-22 (BASE)	0080	- Total						\$0.00	
2020 2020	0090		Material		6		SYSTEM	(\$628,386.50)	
2020 7					6		SYSTEM	\$628,386.50	Estimate Item Adjustment (0007) due to user moorec1 overridding Payment
2000 Estimate Item Adjustment (0002) due to user moored toverridding Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Payment Estimate. 10					7		SYSTEM	(\$323,886.50)	
2020 8					7		SYSTEM	\$323,886.50	Estimate Item Adjustment (0002) due to user moorec1 overridding Payment
2020 Sestimate Lem Adjustment (0002) due to user moorect overridding Payment Estimate Estim					8		SYSTEM	(\$334,858.65)	
Price - Total					8		SYSTEM	\$334,858.65	Estimate Item Adjustment (0002) due to user moorec1 overridding Payment
2020 Sep 2, 2020 SySTEM (\$334,858.65) 10					9		SYSTEM	(\$334,858.65)	
10 Sep 2, 2020 20					9		SYSTEM	\$334,858.65	Estimate Item Adjustment (0008) due to user moorec1 overridding Payment
2020 Estimate Item Adjustment (0011) due to user moorect overridding Paymer Estimate Exception 3 on the current Payment Estimate.					10		SYSTEM	(\$334,858.65)	
2020 11 Sep 16, 2020 2					10		SYSTEM	\$334,858.65	Estimate Item Adjustment (0011) due to user moorec1 overridding Payment
Solution					11		SYSTEM	(\$334,858.65)	
Material - Total S0.00					11		SYSTEM	\$334,858.65	Estimate Item Adjustment (0005) due to user moorec1 overridding Payment
BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) Other Item Adjustment ACAD Other Item Adjustment - Total BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) Other Item Adjustment - Total BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) Other Item Adjustment - Total Other Item Adjustment - Total BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) Other Item Adjustment - Total Other Item Adjustment - Total BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) Other Item Adjustment Index Adjustment Type applied is FUEL (\$415.10) (\$22,702.70) (\$22,702.70) (\$22,702.70) (\$22,702.70) Reference Item Price Adjustment Index Adjustment Type applied is FUEL (\$41,922.24) Reference Item Price Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index				- Total				\$0.00	
MIXTURE PG64-22 (BASE) Adjustment 2020		Material - Total						\$0.00	
ACAD - Total (\$22,702.70)				ACAD	6		moorec1	(\$22,287.60)	
Other Item Adjustment - Total BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) Price - Total Other Item Adjustment - Total Frice - Total Other Item Adjustment Index Adjustment Index Adjustment Type applied is FUEL (\$41,922.24) Reference Item Price Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Other Item Adjustment Index Adjustment Type appli					8		moorec1	(\$415.10)	
BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) Price 6 Jul 1, 2020 8 Aug 3, 2020 8 Aug 3, 2020 - Total (\$41,922.24) Reference Item Price Adjustment Index Adjustment Type applied is FUEL (\$42,467.61) Price - Total (\$42,467.61) 0090 - Total (\$65,170.31) 0100 BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) 9 Aug 17, 2020 9 Aug 17, 2020 9 Aug 17, 2020 9 SYSTEM (\$505,274.34) This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate.				ACAD - Tota	al			(\$22,702.70)	
MIXTURE PG64-22 (BASE)		Other Item Adjustment - Total						(\$22,702.70)	
2020			Price		6		SYSTEM	(\$41,922.24)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
Price - Total (\$42,467.61) 0090 - Total (\$65,170.31) 0100 BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) 9 Aug 17, 2020 9 Aug 17, 2020 SYSTEM \$505,274.34 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					8	Aug 3, 2020	SYSTEM	(\$545.37)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
0090 - Total 0100 BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) 9 Aug 17, 2020 9 Aug 17, 2020 9 Aug 17, 2020 9 SYSTEM \$505,274.34 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate.				- Total				(\$42,467.61)	
0100 BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) 9 Aug 17, 2020 9 Aug 17, 2020 9 Aug 17, 2020 9 Aug 17, 2020 9 SYSTEM \$505,274.34 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		Price - Total						(\$42,467.61)	
MIXTURE PG64-22 (SURFACE LEVELING) 9 Aug 17, 2020 SYSTEM \$505,274.34 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	0090	- Total						(\$65,170.31)	
9 Aug 17, 2020 \$505,274.34 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	0100	MIXTURE PG64-22 (SURFACE	Material		9		SYSTEM	(\$505,274.34)	
40 Cop 2 CVCTFM (677 704 45)		LEVELING)			9		SYSTEM	\$505,274.34	Estimate Item Adjustment (0005) due to user moorec1 overridding Payment
10 Sep 2, SYSTEM (\$77,791.15) 2020					10	Sep 2, 2020	SYSTEM	(\$77,791.15)	
10 Sep 2, 2020 SYSTEM \$77,791.15 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					10		SYSTEM	\$77,791.15	Estimate Item Adjustment (0008) due to user moorec1 overridding Payment
- Total \$0.00				- Total				\$0.00	
Material - Total \$0.00		Material - Total						\$0.00	
BITUMINOUS PAVEMENT Other Item ACAD 9 Aug 17, moorec1 (\$21,977.55) Adjustment calculation saved to eProjects: MIXTURE PG64-22 (SURFACE Adjustment 20200815"		BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE		ACAD	9		moorec1	(\$21,977.55)	
LEVELING) 10 Sep 2 married (623,006,00). Adjustment calculation council to Discipling		LEVELING)			10	Sep 2, 2020	moorec1	(\$33,906.08)	Adjustment calculation saved to eProjects: "191213_D05_J5S3280_AC_Adjustment_20200901"

Revision 4/1/2020 Page 12 of 24



Line								
	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0100	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	ACAD	11	Sep 16, 2020	moorec1	(\$13,142.59)	Adjustment calculation saved to eProjects: "191213_D05_J5S3280_AC_Adjustment_20200915"
			ACAD - Total	al			(\$69,026.22)	
	Other Item Adjustment - Total						(\$69,026.22)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	Price		9	Aug 17, 2020	SYSTEM	(\$21,403.20)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
	LEVELING)			10	Sep 2, 2020	SYSTEM	(\$33,020.00)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				11	Sep 16, 2020	SYSTEM	(\$12,300.46)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$66,723.66)	
	Price - Total						(\$66,723.66)	
0100 -	· Total						(\$135,749.88)	
0110	TACK COAT	Material		9	Aug 17, 2020	SYSTEM	(\$16,040.20)	
				9	Aug 17, 2020	SYSTEM	\$16,040.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				10	Sep 2, 2020	SYSTEM	(\$43,980.20)	
				10	Sep 2, 2020	SYSTEM	\$43,980.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user moorec1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$55,675.40)	
				11	Sep 16, 2020	SYSTEM	\$55,675.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0110 -	· Total						\$0.00	
0120	FURNISHING TYPE 2 ROCK DITCH LINER	Material		5	Jun 16, 2020	SYSTEM	(\$265.50)	
					2020			
				5	Jun 16, 2020	SYSTEM	\$265.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user moorec1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				5	Jun 16,	SYSTEM	\$265.50 (\$265.50)	Estimate Item Adjustment (0002) due to user moorec1 overridding Payment
					Jun 16, 2020 Jul 1,			Estimate Item Adjustment (0002) due to user moorec1 overridding Payment
				6	Jun 16, 2020 Jul 1, 2020 Jul 1,	SYSTEM	(\$265.50)	Estimate Item Adjustment (0002) due to user moorec1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user moorec1 overridding Payment
				6	Jun 16, 2020 Jul 1, 2020 Jul 1, 2020 Jul 16,	SYSTEM SYSTEM	(\$265.50) \$265.50	Estimate Item Adjustment (0002) due to user moorec1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user moorec1 overridding Payment
				6 6 7	Jun 16, 2020 Jul 1, 2020 Jul 1, 2020 Jul 16, 2020 Jul 16,	SYSTEM SYSTEM	(\$265.50) \$265.50 (\$265.50)	Estimate Item Adjustment (0002) due to user moorec1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment
				6 6 7 7	Jun 16, 2020 Jul 1, 2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$265.50) \$265.50 (\$265.50) \$265.50	Estimate Item Adjustment (0002) due to user moorec1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment
				6 6 7 7 8 8	Jun 16, 2020 Jul 1, 2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	(\$265.50) \$265.50 (\$265.50) \$265.50	Estimate Item Adjustment (0002) due to user moorec1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user moorec1 overridding Payment Estimate Item Adjustment (0005) due to user moorec1 overridding Payment
				6 6 7 7 8 8 8 8	Jun 16, 2020 Jul 1, 2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 3, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$265.50) \$265.50 (\$265.50) \$265.50 (\$265.50)	Estimate Item Adjustment (0002) due to user moorec1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user moorec1 overridding Payment Estimate Item Adjustment (0005) due to user moorec1 overridding Payment
				6 6 7 7 8 8 8 9 9	Jun 16, 2020 Jul 1, 2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 3, 2020 Aug 17,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$265.50) \$265.50 (\$265.50) \$265.50 (\$265.50) \$265.50	Estimate Item Adjustment (0002) due to user moorec1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user moorec1 overridding Payment Estimate Item Adjustment (0010) due to user moorec1 overridding Payment Estimate Item Adjustment (0010) due to user moorec1 overridding Payment
				6 6 7 7 7 8 8 8 9 9	Jun 16, 2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 3, 2020 Aug 17, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$265.50) \$265.50 (\$265.50) \$265.50 (\$265.50) \$265.50 (\$265.50)	Estimate Item Adjustment (0002) due to user moorec1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user moorec1 overridding Payment Estimate Item Adjustment (0010) due to user moorec1 overridding Payment Estimate Item Adjustment (0010) due to user moorec1 overridding Payment
				6 6 7 7 7 8 8 8 9 9 10	Jun 16, 2020 Jul 1, 2020 Jul 1, 2020 Jul 16, 2020 Jul 16, 2020 Aug 3, 2020 Aug 17, 2020 Aug 17, 2020 Sep 2, 2020 Sep 2, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$265.50) \$265.50 (\$265.50) \$265.50 (\$265.50) \$265.50 (\$265.50)	Estimate Item Adjustment (0002) due to user moorec1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user moorec1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user moorec1 overridding Payment Estimate Item Adjustment (0013) due to user moorec1 overridding Payment Estimate Item Adjustment (0013) due to user moorec1 overridding Payment

Revision 4/1/2020 Page 13 of 24



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0120	FURNISHING TYPE 2 ROCK DITCH LINER	Material						Estimate Exception 5 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0120 -	Total						\$0.00		
0140	ROCK LINING	Material		3	May 18, 2020	SYSTEM	(\$2,171.50)		
				3	May 18, 2020	SYSTEM	\$2,171.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user moorec1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
				4	Jun 2, 2020	SYSTEM	(\$7,654.00)		
				4	Jun 2, 2020	SYSTEM	\$7,654.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user moorec1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
				5	Jun 16, 2020	SYSTEM	(\$8,815.00)		
				5	Jun 16, 2020	SYSTEM	\$8,815.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
				6	Jul 1, 2020	SYSTEM	(\$8,815.00)		
				6	Jul 1, 2020	SYSTEM	\$8,815.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user moorec1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
				7	Jul 16, 2020	SYSTEM	(\$8,815.00)		
				7	Jul 16, 2020	SYSTEM	\$8,815.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user moorec1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					8	Aug 3, 2020	SYSTEM	(\$8,815.00)	
				8	Aug 3, 2020	SYSTEM	\$8,815.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user moorec1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
				9	Aug 17, 2020	SYSTEM	(\$8,815.00)		
				9	Aug 17, 2020	SYSTEM	\$8,815.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user moorec1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
				10	Sep 2, 2020	SYSTEM	(\$8,815.00)		
				10	Sep 2, 2020	SYSTEM	\$8,815.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user moorec1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
				11	Sep 16, 2020	SYSTEM	(\$8,815.00)		
				11	Sep 16, 2020	SYSTEM	\$8,815.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user moorec1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0140 -	Total						\$0.00		
0230	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Material		5	Jun 16, 2020	SYSTEM	(\$4,000.00)		
	. S. SHORLES / INCIDINGED			5	Jun 16, 2020	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user moorec1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
				6	Jul 1, 2020	SYSTEM	(\$4,760.00)		
				6	Jul 1, 2020	SYSTEM	\$4,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user moorec1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
				7	Jul 16, 2020	SYSTEM	(\$4,760.00)		
				7	Jul 16,	SYSTEM	\$4,760.00	This adjustment offsets the original system-generated Overrun Payment	

Revision 4/1/2020 Page 14 of 24



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0230	TEMPORARY TRAFFIC BARRIER, CONTRACTOR	Material	. , , p c		2020			Estimate Item Adjustment (0005) due to user moorec1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
	FURNISHED / RETAINED			8	Aug 3, 2020	SYSTEM	(\$4,760.00)	·
				8	Aug 3, 2020	SYSTEM	\$4,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user moorec1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				9	Aug 17, 2020	SYSTEM	(\$4,760.00)	
				9	Aug 17, 2020	SYSTEM	\$4,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user moorec1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				10	Sep 2, 2020	SYSTEM	(\$4,760.00)	
				10	Sep 2, 2020	SYSTEM	\$4,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user moorec1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$4,760.00)	
				11	Sep 16, 2020	SYSTEM	\$4,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0230 -	· Total						\$0.00	
0270	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		10	Sep 2, 2020	SYSTEM	(\$1,221.00)	
	White			10	Sep 2, 2020	SYSTEM	\$1,221.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user moorec1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$1,221.00)	
				11	Sep 16, 2020	SYSTEM	\$1,221.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user moorec1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0270 -	Total						\$0.00	
0280	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	Material		10	Sep 2, 2020	SYSTEM	(\$2,000.00)	
	CRUSSING WARRER			10	Sep 2, 2020	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user moorec1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$2,000.00)	
				11	Sep 16, 2020	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user moorec1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0280 -	Total						\$0.00	
0290	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material		6	Jul 1, 2020	SYSTEM	(\$8.80)	
				6	Jul 1, 2020	SYSTEM	\$8.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user moorec1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$8.80)	
				7	Jul 16, 2020	SYSTEM	\$8.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user moorec1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$8.80)	
			8	Aug 3, 2020	SYSTEM	\$8.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user moorec1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	

Revision 4/1/2020 Page 15 of 24



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0290	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material		9	Aug 17, 2020	SYSTEM	(\$8.80)	
				9	Aug 17, 2020	SYSTEM	\$8.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user moorec1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				10	Sep 2, 2020	SYSTEM	(\$8.80)	
				10	Sep 2, 2020	SYSTEM	\$8.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user moorec1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$8.80)	
				11	Sep 16, 2020	SYSTEM	\$8.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user moorec1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0290 -	Total						\$0.00	
0300	4 IN. WHITE STANDARD WATERBORNE PAVEMENT	Material		10	Sep 2, 2020	SYSTEM	(\$9,629.20)	
	MARKING PAINT, TYPE P BEADS			10	Sep 2, 2020	SYSTEM	\$9,629.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user moorec1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$9,629.20)	
				11	Sep 16, 2020	SYSTEM	\$9,629.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user moorec1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0300 -	Total						\$0.00	
0310	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		10	Sep 2, 2020	SYSTEM	(\$7,381.57)	
	BEADS			10	Sep 2, 2020	SYSTEM	\$7,381.57	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user moorec1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$7,381.57)	
				11	Sep 16, 2020	SYSTEM	\$7,381.57	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user moorec1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0310 -	Total						\$0.00	
0390	CLASS B-1 CONCRETE (CULVERTS)	Material		1	Apr 17, 2020	SYSTEM	(\$8,250.00)	
				1	Apr 17, 2020	SYSTEM	\$8,250.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user moorec1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				2	May 4, 2020	SYSTEM	(\$24,900.00)	
				2	May 4, 2020	SYSTEM	\$24,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user moorec1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				3	May 18, 2020	SYSTEM	(\$73,500.00)	
				3	May 18, 2020	SYSTEM	\$73,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				4	Jun 2, 2020	SYSTEM	(\$163,500.00)	
				4	Jun 2, 2020	SYSTEM	\$163,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$207,000.00)	

Revision 4/1/2020 Page 16 of 24



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks	
		Туре	Adjustment Type		Date	Ву			
0390	CLASS B-1 CONCRETE (CULVERTS)	Material		5	Jun 16, 2020	SYSTEM	\$207,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user moorec1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
				6	Jul 1, 2020	SYSTEM	(\$207,000.00)		
				6	Jul 1, 2020	SYSTEM	\$207,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user moorec1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
				7	Jul 16, 2020	SYSTEM	(\$207,000.00)		
				7	Jul 16, 2020	SYSTEM	\$207,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user moorec1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
				8	Aug 3, 2020	SYSTEM	(\$207,000.00)		
				8	Aug 3, 2020	SYSTEM	\$207,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
				9	Aug 17, 2020	SYSTEM	(\$207,000.00)		
					9	Aug 17, 2020	SYSTEM	\$207,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user moorec1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				10	Sep 2, 2020	SYSTEM	(\$207,000.00)		
				10	Sep 2, 2020	SYSTEM	\$207,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user moorec1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
				11	Sep 16, 2020	SYSTEM	(\$207,000.00)		
					11	Sep 16, 2020	SYSTEM	\$207,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user moorec1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
			- Total					\$0.00	
			- I otal						
0390	Material - Total - Total		- Total				\$0.00		
0390	- Total REINFORCING STEEL	Material	- I otal	1	Apr 17, 2020	SYSTEM			
	- Total	Material	- I otal	1	Apr 17, 2020 Apr 17, 2020	SYSTEM SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
	- Total REINFORCING STEEL	Material	- Total		2020 Apr 17,		\$0.00 \$0.00 (\$1,806.00)	Estimate Item Adjustment (0009) due to user moorec1 overridding Payment	
	- Total REINFORCING STEEL	Material	- Total	1	2020 Apr 17, 2020 May 4,	SYSTEM	\$0.00 \$0.00 (\$1,806.00) \$1,806.00	Estimate Item Adjustment (0009) due to user moorec1 overridding Payment	
	- Total REINFORCING STEEL	Material	- Total	1	2020 Apr 17, 2020 May 4, 2020 May 4,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$1,806.00) \$1,806.00 (\$5,420.00)	Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment	
	- Total REINFORCING STEEL	Material	- Total	2	2020 Apr 17, 2020 May 4, 2020 May 4, 2020	SYSTEM SYSTEM	\$0.00 \$0.00 (\$1,806.00) \$1,806.00 (\$5,420.00) \$5,420.00	Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment	
	- Total REINFORCING STEEL	Material	- Total	2 2 3	2020 Apr 17, 2020 May 4, 2020 May 4, 2020 May 18, 2020 May 18, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$1,806.00) \$1,806.00 (\$5,420.00) \$5,420.00	Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user moorec1 overridding Payment	
	- Total REINFORCING STEEL	Material	- Total	1 2 2 3 3	2020 Apr 17, 2020 May 4, 2020 May 4, 2020 May 18, 2020 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$1,806.00) \$1,806.00 (\$5,420.00) \$5,420.00 (\$17,260.00)	Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user moorec1 overridding Payment	
	- Total REINFORCING STEEL	Material	- Total	1 2 2 2 3 3 3 4	2020 Apr 17, 2020 May 4, 2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$1,806.00) \$1,806.00 (\$5,420.00) \$5,420.00 (\$17,260.00) \$17,260.00	Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user moorec1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user moorec1 overridding Payment Estimate Item Adjustment (0004) due to user moorec1 overridding Payment	
	- Total REINFORCING STEEL	Material	- Total	1 2 2 2 3 3 4 4 4	2020 Apr 17, 2020 May 4, 2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$1,806.00) \$1,806.00 (\$5,420.00) \$5,420.00 (\$17,260.00) \$17,260.00 (\$38,100.00)	Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user moorec1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user moorec1 overridding Payment Estimate Item Adjustment (0004) due to user moorec1 overridding Payment	
	- Total REINFORCING STEEL	Material	- Total	1 2 2 2 3 3 4 4 4 5 5	2020 Apr 17, 2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$1,806.00) \$1,806.00 (\$5,420.00) \$5,420.00 (\$17,260.00) \$17,260.00 (\$38,100.00) \$38,100.00	Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user moorec1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user moorec1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user moorec1 overridding Payment Estimate Item Adjustment (0006) due to user moorec1 overridding Payment Estimate Item Adjustment (0006) due to user moorec1 overridding Payment	
	- Total REINFORCING STEEL	Material	- Total	1 2 2 3 3 3 4 4 5 5 5 5	2020 Apr 17, 2020 May 4, 2020 May 4, 2020 May 18, 2020 May 18, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$1,806.00) \$1,806.00 (\$5,420.00) \$5,420.00 (\$17,260.00) \$17,260.00 (\$38,100.00) \$38,100.00 (\$48,240.00)	Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user moorec1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user moorec1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user moorec1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user moorec1 overridding Payment Estimate Item Adjustment (0006) due to user moorec1 overridding Payment Estimate Item Adjustment (0006) due to user moorec1 overridding Payment	

Revision 4/1/2020 Page 17 of 24



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0400	REINFORCING STEEL (CULVERTS)	Material		7	Jul 16, 2020	SYSTEM	\$48,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user moorec1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$48,240.00)	
				8	Aug 3, 2020	SYSTEM	\$48,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user moorec1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				9	Aug 17, 2020	SYSTEM	(\$48,240.00)	
				9	Aug 17, 2020	SYSTEM	\$48,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user moorec1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0400 -	Total						\$0.00	
0420	78 IN. PIPE GROUP C	Material		4	Jun 2, 2020	SYSTEM	(\$5,120.00)	
				4	Jun 2, 2020	SYSTEM	\$5,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user moorec1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				5	Jun 16, 2020	SYSTEM	(\$5,120.00)	
				5	Jun 16, 2020	SYSTEM	\$5,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user moorec1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				6	Jul 1, 2020	SYSTEM	(\$5,120.00)	
				6	Jul 1, 2020	SYSTEM	\$5,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user moorec1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$5,120.00)	
				7	Jul 16, 2020	SYSTEM	\$5,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$5,120.00)	
				8	Aug 3, 2020	SYSTEM	\$5,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user moorec1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				9	Aug 17, 2020	SYSTEM	(\$5,120.00)	
				9	Aug 17, 2020	SYSTEM	\$5,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user moorec1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				10	Sep 2, 2020	SYSTEM	(\$5,120.00)	
				10	Sep 2, 2020	SYSTEM	\$5,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user moorec1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$5,120.00)	
				11	Sep 16, 2020	SYSTEM	\$5,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user moorec1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0420 -	Total						\$0.00	
0430	SEEDING - COOL SEASON MIXTURES	Material		9	Aug 17, 2020	SYSTEM	(\$50,095.00)	
				9	Aug 17, 2020	SYSTEM	\$50,095.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user moorec1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				10	Sep 2, 2020	SYSTEM	(\$50,095.00)	

Revision 4/1/2020 Page 18 of 24



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
0430	SEEDING - COOL SEASON MIXTURES	Material		10	Sep 2, 2020	SYSTEM	\$50,095.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user moorec1 overridding Payment Estimate Exception 29 on the current Payment Estimate.												
				11	Sep 16, 2020	SYSTEM	(\$39,990.00)													
				11	Sep 16, 2020	SYSTEM	\$39,990.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user moorec1 overridding Payment Estimate Exception 28 on the current Payment Estimate.												
			- Total				\$0.00													
	Material - Total						\$0.00													
0430 -	·Total						\$0.00													
0450	ROCK DITCH CHECK	Material		4	Jun 2, 2020	SYSTEM	(\$6,611.25)													
				4	Jun 2, 2020	SYSTEM	\$6,611.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user moorec1 overridding Payment Estimate Exception 10 on the current Payment Estimate.												
				5	Jun 16, 2020	SYSTEM	(\$6,611.25)													
				5	Jun 16, 2020	SYSTEM	\$6,611.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user moorec1 overridding Payment Estimate Exception 13 on the current Payment Estimate.												
				6	Jul 1, 2020	SYSTEM	(\$6,611.25)													
				6	Jul 1, 2020	SYSTEM	\$6,611.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user moorec1 overridding Payment Estimate Exception 17 on the current Payment Estimate.												
				7	Jul 16, 2020	SYSTEM	(\$6,611.25)													
				7	Jul 16, 2020	SYSTEM	\$6,611.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user moorec1 overridding Payment Estimate Exception 17 on the current Payment Estimate.												
				8	Aug 3, 2020	SYSTEM	(\$6,611.25)													
				8	Aug 3, 2020	SYSTEM	\$6,611.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user moorec1 overridding Payment Estimate Exception 24 on the current Payment Estimate.												
				9	Aug 17, 2020	SYSTEM	(\$6,611.25)													
				9	Aug 17, 2020	SYSTEM	\$6,611.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user moorec1 overridding Payment Estimate Exception 28 on the current Payment Estimate.												
				10	Sep 2, 2020	SYSTEM	(\$6,611.25)													
				10	Sep 2, 2020	SYSTEM	\$6,611.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user moorec1 overridding Payment Estimate Exception 31 on the current Payment Estimate.												
																	11	Sep 16, 2020	SYSTEM	(\$6,611.25)
				11	Sep 16, 2020	SYSTEM	\$6,611.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user moorec1 overridding Payment Estimate Exception 30 on the current Payment Estimate.												
			- Total				\$0.00													
	Material - Total						\$0.00													
0450 -	Total						\$0.00													
0460	ALTERNATE DITCH CHECK	Material		4	Jun 2, 2020	SYSTEM	(\$850.00)													
				4	Jun 2, 2020	SYSTEM	\$850.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user moorec1 overridding Payment Estimate Exception 11 on the current Payment Estimate.												
				5	Jun 16, 2020	SYSTEM	(\$850.00)													
				5	Jun 16, 2020	SYSTEM	\$850.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user moorec1 overridding Payment Estimate Exception 14 on the current Payment Estimate.												
				6	Jul 1, 2020	SYSTEM	(\$850.00)													

Revision 4/1/2020 Page 19 of 24



Makes Type						_	_		_
Part	0460	Description			Est. Number		Created By	Amount	Remarks
2000 7		ALTERNATE DITCH CHECK	Material		6		SYSTEM	\$850.00	Estimate Item Adjustment (0017) due to user moorec1 overridding Payment
					7		SYSTEM	(\$850.00)	
					7		SYSTEM	\$850.00	Estimate Item Adjustment (0011) due to user moorec1 overridding Payment
Aug 17, SYSTEM S850.00					8		SYSTEM	(\$850.00)	
					8		SYSTEM	\$850.00	Estimate Item Adjustment (0013) due to user moorec1 overridding Payment
Page					9		SYSTEM	(\$850.00)	
10					9		SYSTEM	\$850.00	Estimate Item Adjustment (0019) due to user moorec1 overridding Payment
2020 Stationale Exception 32 on the current Payment Estimate Exception 32 on the current Payment Estimate Estimate Exception 32 on the current Payment Estimate Statistics 11					10		SYSTEM	(\$850.00)	
1 Sep 16, SYSTEM \$850.00 This adjustment offises the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user moorest overridding Payment Estimate Exception 31 on the current Payment Estimate Es					10		SYSTEM	\$850.00	Estimate Item Adjustment (0025) due to user moorec1 overridding Payment
					11		SYSTEM	(\$850.00)	
Material - Total S0.00					11		SYSTEM	\$850.00	Estimate Item Adjustment (0018) due to user moorec1 overridding Payment
MGS GUARDRAIL Construction Stockpile 1				- Total				\$0.00	
MGS GUARDRAIL Construction Stockpile		Material - Total					\$0.00		
Stockpile 2020 8	0460	- Total						\$0.00	
2020	0500	MGS GUARDRAIL			1		SYSTEM	\$26,310.50	Payment Estimate Item Adjustment generated Stockpile Transaction
Construction Stockpile - Total S0.00					8		SYSTEM	(\$15,890.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
South Sout									
Solution Stockpile Transaction Solution Stockpile Transaction Solution Stockpile Solution Stockpile Solution Stockpile Solution					11		SYSTEM	(\$10,420.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) **No Construction Stockpile** **Indiana Payment Estimate Item Adjustment generated Stockpile Transaction **Payment Estimate Item Adjustment generated				- Total	11		SYSTEM	, , ,	Payment Estimate Item Adjustment generated Stockpile Transaction
TRANSITION SECTION (REGULAR/NO CURB) Slockpile 2020		Construction Stockpile - Total		- Total	11		SYSTEM	\$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
8 Aug 3, 2VSTEM (\$5,174.00) Payment Estimate Item Adjustment generated Stockpile Transaction 11 Sep 16, 2020 2	0500			- Total	11		SYSTEM	\$0.00 \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
Construction Stockpile - Total S0.00 Construction Stockpile - Total S0.00 S0.00 S0.00 S0.00 S0.00 S0.00 MGS END ANCHOR Construction Stockpile Apr 17, 2020 8 Aug 3, 2020 11 Sep 16, 2020 SYSTEM \$4,256.00 Payment Estimate Item Adjustment generated Stockpile Transaction S0.00 Construction Stockpile - Total S0.00 MGS BRIDGE APPROACH TRANSITION (THRIE-BEAM BRIDGE) MGS BRIDGE APPROACH TRANSITION (THRIE-BEAM BRIDGE) Stockpile 1 Apr 17, 2020 SYSTEM \$12,272.00 Payment Estimate Item Adjustment generated Stockpile Transaction	0500 0510	- Total MGS BRIDGE APPROACH TRANSITION SECTION		- Total		2020 Apr 17,		\$0.00 \$0.00 \$0.00	
Construction Stockpile - Total S0.00 MGS END ANCHOR MGS END ANCHOR Stockpile Total Apr 17, 2020 8 Aug 3, 2020 SYSTEM (\$2,660.00) Payment Estimate Item Adjustment generated Stockpile Transaction 11 Sep 16, 2020 SYSTEM (\$1,596.00) Payment Estimate Item Adjustment generated Stockpile Transaction Total Construction Stockpile - Total S0.00 Construction Stockpile - Total S0.00 MGS BRIDGE APPROACH TRANSITION (THRIE-BEAM BRIDGE) MGS BRIDGE 1 Apr 17, 2020 SYSTEM (\$1,596.00) Payment Estimate Item Adjustment generated Stockpile Transaction S0.00 Payment Estimate Item Adjustment generated Stockpile Transaction S0.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile 1 Apr 17, 2020 SYSTEM \$12,272.00 Payment Estimate Item Adjustment generated Stockpile Transaction		- Total MGS BRIDGE APPROACH TRANSITION SECTION		- Total	1	Apr 17, 2020 Aug 3,	SYSTEM	\$0.00 \$0.00 \$0.00 \$10,348.00	Payment Estimate Item Adjustment generated Stockpile Transaction
Solid Soli		- Total MGS BRIDGE APPROACH TRANSITION SECTION		- Total	1 8	Apr 17, 2020 Aug 3, 2020 Sep 16,	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$10,348.00 (\$5,174.00)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
MGS END ANCHOR Stockpile 1		- Total MGS BRIDGE APPROACH TRANSITION SECTION			1 8	Apr 17, 2020 Aug 3, 2020 Sep 16,	SYSTEM SYSTEM	\$0.00 \$0.00 \$10,348.00 \$10,348.00 (\$5,174.00)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
Stockpile 8 Aug 3, 2020 11 Sep 16, 2020 - Total Construction Stockpile - Total S0.00 Construction Stockpile - Total S0.00 MGS BRIDGE APPROACH TRANSITION (THRIE-BEAM BRIDGE) 1 Apr 17, 2020 6 Jul 1, SYSTEM (\$6,136.00) Payment Estimate Item Adjustment generated Stockpile Transaction		- Total MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)			1 8	Apr 17, 2020 Aug 3, 2020 Sep 16,	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$10,348.00 (\$5,174.00) (\$5,174.00)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
2020 11 Sep 16, 2020 SYSTEM (\$1,596.00) Payment Estimate Item Adjustment generated Stockpile Transaction - Total \$0.00 Construction Stockpile - Total \$0.00 0520 - Total \$0.00 MGS BRIDGE APPROACH TRANSITION (THRIE-BEAM BRIDGE)	0510	- Total MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) Construction Stockpile - Total			1 8	Apr 17, 2020 Aug 3, 2020 Sep 16,	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$10,348.00 (\$5,174.00) (\$5,174.00) \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
- Total \$0.00 Construction Stockpile - Total \$0.00 Construction Stockpile - Total \$0.00 MGS BRIDGE APPROACH TRANSITION (THRIE-BEAM BRIDGE) TRANSITION (THRIE-BEAM BRIDGE) TRANSITION (THRIE-BEAM BRIDGE) TRANSITION (THRIE-BEAM Stockpile Transaction (\$6,136.00) Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction	0510	- Total MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) Construction Stockpile - Total	Stockpile		1 8	Apr 17, 2020 Aug 3, 2020 Sep 16, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$10,348.00 (\$5,174.00) \$0.00 \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
Construction Stockpile - Total \$0.00 0520 - Total \$0.00 0530 MGS BRIDGE APPROACH TRANSITION (THRIE-BEAM BRIDGE) 1 Apr 17, 2020	0510	- Total MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) Construction Stockpile - Total	Stockpile		1 8 11	Apr 17, 2020 Aug 3, 2020 Sep 16, 2020 Apr 17, 2020 Aug 3, 4 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$10,348.00 (\$5,174.00) (\$5,174.00) \$0.00 \$0.00 \$4,256.00	Payment Estimate Item Adjustment generated Stockpile Transaction
Solution	0510	- Total MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) Construction Stockpile - Total	Stockpile		1 8 11 8	Apr 17, 2020 Aug 3, 2020 Sep 16, 2020 Aug 3, 2020 Sep 16, 2020 Aug 3, 2020 Sep 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$10,348.00 (\$5,174.00) (\$5,174.00) \$0.00 \$0.00 \$4,256.00 (\$2,660.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
MGS BRIDGE APPROACH TRANSITION (THRIE-BEAM BRIDGE) 1 Apr 17, SYSTEM \$12,272.00 Payment Estimate Item Adjustment generated Stockpile Transaction 5 Jul 1, SYSTEM (\$6,136.00) Payment Estimate Item Adjustment generated Stockpile Transaction	0510	- Total MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) Construction Stockpile - Total	Stockpile	- Total	1 8 11 8	Apr 17, 2020 Aug 3, 2020 Sep 16, 2020 Aug 3, 2020 Sep 16, 2020 Aug 3, 2020 Sep 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$10,348.00 (\$5,174.00) (\$5,174.00) \$0.00 \$0.00 \$4,256.00 (\$2,660.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
TRANSITION (THRIE-BEAM BRIDGE) BRIDGE) 6 Jul 1, SYSTEM (\$6,136.00) Payment Estimate Item Adjustment generated Stockpile Transaction	0510	- Total MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) Construction Stockpile - Total - Total MGS END ANCHOR	Stockpile	- Total	1 8 11 8	Apr 17, 2020 Aug 3, 2020 Sep 16, 2020 Aug 3, 2020 Sep 16, 2020 Aug 3, 2020 Sep 16, 6	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$10,348.00 (\$5,174.00) (\$5,174.00) \$0.00 \$0.00 \$4,256.00 (\$2,660.00) (\$1,596.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
6 Jul 1, SYSTEM (\$6,136.00) Payment Estimate Item Adjustment generated Stockpile Transaction	0510 0510 0520	- Total MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) Construction Stockpile - Total MGS END ANCHOR Construction Stockpile - Total	Stockpile	- Total	1 8 11 8	Apr 17, 2020 Aug 3, 2020 Sep 16, 2020 Aug 3, 2020 Sep 16, 2020 Aug 3, 2020 Sep 16, 6	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$10,348.00 (\$5,174.00) (\$5,174.00) \$0.00 \$0.00 \$4,256.00 (\$2,660.00) \$0.00 \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	0510 0510 0520	- Total MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) Construction Stockpile - Total - Total MGS END ANCHOR MGS BRIDGE APPROACH TRANSITION (THRIE-BEAM	Construction Stockpile Construction	- Total	1 8 11 8 11	Apr 17, 2020 Aug 3, 2020 Sep 16, 2020 Aug 3, 2020 Apr 17, 2020 Aug 3, 2020 Aug 3, 2020 Apr 17, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$10,348.00 (\$5,174.00) (\$5,174.00) \$0.00 \$0.00 \$4,256.00 (\$2,660.00) \$0.00 \$0.00	Payment Estimate Item Adjustment generated Stockpile Transaction
8 Aug 3, SYSTEM (\$6,136.00) Payment Estimate Item Adjustment generated Stockpile Transaction	0510 0510 0520	- Total MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) Construction Stockpile - Total - Total MGS END ANCHOR MGS BRIDGE APPROACH TRANSITION (THRIE-BEAM	Construction Stockpile Construction	- Total	1 8 11 8 11	Apr 17, 2020 Aug 3, 2020 Sep 16, 2020 Aug 3, 2020 Aug 3, 2020 Aug 3, 2020 Aug 3, 2020 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$10,348.00 (\$5,174.00) (\$5,174.00) \$0.00 \$0.00 \$4,256.00 (\$2,660.00) \$0.00 \$0.00 \$0.00 \$12,272.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction

Revision 4/1/2020 Page 20 of 24



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0530	MGS BRIDGE APPROACH TRANSITION (THRIE-BEAM BRIDGE)	Construction Stockpile			2020			
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0530 -	Total						\$0.00	
0540	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		1	Apr 17, 2020	SYSTEM	\$36,240.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Jul 1, 2020	SYSTEM	(\$6,040.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Aug 3, 2020	SYSTEM	(\$18,120.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				11	Sep 16, 2020	SYSTEM	(\$12,080.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0540 -	Total						\$0.00	
0580	CLASS B-1 CONCRETE (CULVERTS-BRIDGE)	Material		8	Aug 3, 2020	SYSTEM	(\$71,940.00)	
				8	Aug 3, 2020	SYSTEM	\$71,940.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user moorec1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				9	Aug 17, 2020	SYSTEM	(\$71,940.00)	
				9	Aug 17, 2020	SYSTEM	\$71,940.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user moorec1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				10	Sep 2, 2020	SYSTEM	(\$71,940.00)	
				10	Sep 2, 2020	SYSTEM	\$71,940.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user moorec1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$71,940.00)	
				11	Sep 16, 2020	SYSTEM	\$71,940.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user moorec1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	CLASS B-1 CONCRETE (CULVERTS-BRIDGE)	Other Item Adjustment	OADJ	10	Sep 2, 2020	moorec1	\$12,870.00	Correction for erroneous negative adjustment made on estimate 0009.
			OADJ - Tota	ıl			\$12,870.00	
	CLASS B-1 CONCRETE (CULVERTS-BRIDGE)		OVRN	8	Aug 3, 2020	moorec1	(\$12,870.00)	Correction for overpayment.
				9	Aug 17, 2020	moorec1	(\$12,870.00)	Correction for overpayment (pending change order.)
			OVRN - Tota	al			(\$25,740.00)	
	Other Item Adjustment - Total						(\$12,870.00)	
	CLASS B-1 CONCRETE (CULVERTS-BRIDGE)	Overrun	Overrun		Aug 3, 2020	SYSTEM	(\$12,870.00)	
				8	Aug 3, 2020	SYSTEM	\$12,870.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) overridding Payment Estimate Exception 26 on the current Payment Estimate.
				9	Aug 17, 2020	SYSTEM	(\$12,870.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				9	Aug 17, 2020	SYSTEM	\$12,870.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) overridding Payment Estimate Exception 30 on the current Payment Estimate.
				10	Sep 2, 2020	SYSTEM	(\$12,870.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				10	Sep 2, 2020	SYSTEM	\$12,870.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) overridding Payment Estimate Exception 33 on the current Payment Estimate.
			Overrun - To	otal			\$0.00	

Revision 4/1/2020 Page 21 of 24



Line		Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0580	Overrun -	Total		.,,,,,				\$0.00	
0580 -	· Total							(\$12,870.00)	
0590		REINFORCING STEEL (CULVERTS-BRIDGE)	Material		8	Aug 3, 2020	SYSTEM	(\$16,320.00)	
					8	Aug 3, 2020	SYSTEM	\$16,320.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user moorec1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					9	Aug 17, 2020	SYSTEM	(\$16,320.00)	
					9	Aug 17, 2020	SYSTEM	\$16,320.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user moorec1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					10	Sep 2, 2020	SYSTEM	(\$16,320.00)	
					10	Sep 2, 2020	SYSTEM	\$16,320.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user moorec1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					11	Sep 16, 2020	SYSTEM	(\$16,320.00)	
					11	Sep 16, 2020	SYSTEM	\$16,320.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user moorec1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				- Total				\$0.00	
	Material -	Total						\$0.00	
		REINFORCING STEEL (CULVERTS-BRIDGE)	Other Item Adjustment	OADJ	10	Sep 2, 2020	moorec1	\$1,360.00	Correction for erroneous negative adjustment made on estimate 0009.
			OADJ - Tota	Total			\$1,360.00		
	REINFORCING STEEL (CULVERTS-BRIDGE)		OVRN	8	Aug 3, 2020	moorec1	(\$1,360.00)	Correction for overpayment.	
				9	Aug 17, 2020	moorec1	(\$1,360.00)	Correction for overpayment (pending change order.)	
			OVRN - Total				(\$2,720.00)		
	Other Item	n Adjustment - Total					(\$1,360.00)		
		REINFORCING STEEL (CULVERTS-BRIDGE)		Overrun		Aug 3, 2020	SYSTEM	(\$1,360.00)	
					8	Aug 3, 2020	SYSTEM	\$1,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) overridding Payment Estimate Exception 27 on the current Payment Estimate.
					9	Aug 17, 2020	SYSTEM	(\$1,360.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					9	Aug 17, 2020	SYSTEM	\$1,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) overridding Payment Estimate Exception 31 on the current Payment Estimate.
					10	Sep 2, 2020	SYSTEM	(\$1,360.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					10	Sep 2, 2020	SYSTEM	\$1,360.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) overridding Payment Estimate Exception 34 on the current Payment Estimate.
				Overrun - Total				\$0.00	
	Overrun - Total							\$0.00	
0590 -	Total							(\$1,360.00)	
0600		DGE RAIL (TWO TUBE STRUCTURAL STEEL)			2	May 4, 2020	SYSTEM	\$24,075.00	Payment Estimate Item Adjustment generated Stockpile Transaction
					8	Aug 3, 2020	SYSTEM	(\$24,075.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00		
		ion Stockpile - Total					\$0.00		
	Total						0)/2==:	\$0.00	
0630	С	COATING COATING	Material		6	Jul 1, 2020	SYSTEM	(\$6,778.10)	This adjustment effects the spiritual system required 1000000000000000000000000000000000000
					6	Jul 1, 2020	SYSTEM	\$6,778.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user moorec1 overridding Payment Estimate Exception 11 on the current Payment Estimate.

Revision 4/1/2020 Page 22 of 24



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0630	CLEANING AND EPOXY COATING			7	Jul 16, 2020	SYSTEM	(\$6,778.10)	
				7	Jul 16, 2020	SYSTEM	\$6,778.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user moorec1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$6,778.10)	
				8	Aug 3, 2020	SYSTEM	\$6,778.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user moorec1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				9	Aug 17, 2020	SYSTEM	(\$6,778.10)	
				9	Aug 17, 2020	SYSTEM	\$6,778.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user moorec1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				10	Sep 2, 2020	SYSTEM	(\$6,778.10)	
				10	Sep 2, 2020	SYSTEM	\$6,778.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user moorec1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$6,778.10)	
				11	Sep 16, 2020	SYSTEM	\$6,778.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user moorec1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total					\$0.00		
0630 -	· Total						\$0.00	
0640	BRIDGE GUARDRAIL (THRIE BEAM)	Construction Stockpile		2	May 4, 2020	SYSTEM	\$15,435.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Jul 1, 2020	SYSTEM	(\$15,435.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		- Total				\$0.00		
	Construction Stockpile - Total					\$0.00		
	BRIDGE GUARDRAIL (THRIE BEAM)	Material		6	Jul 1, 2020	SYSTEM	(\$18,900.00)	
				6	Jul 1, 2020	SYSTEM	\$18,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user moorec1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				7	Jul 16, 2020	SYSTEM	(\$18,900.00)	
				7	Jul 16, 2020	SYSTEM	\$18,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user moorec1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				8	Aug 3, 2020	SYSTEM	(\$18,900.00)	
				8	Aug 3, 2020	SYSTEM	\$18,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user moorec1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				9	Aug 17, 2020	SYSTEM	(\$18,900.00)	
				9	Aug 17, 2020	SYSTEM	\$18,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user moorec1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				10	Sep 2, 2020	SYSTEM	(\$18,900.00)	
					Sep 2,	SYSTEM	\$18,900.00	This adjustment offsets the original system-generated Overrun Payment
				10	2020			Estimate Item Adjustment (0031) due to user moorec1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				11		SYSTEM	(\$18,900.00)	
					2020 Sep 16,	SYSTEM	(\$18,900.00)	
			- Total	11	2020 Sep 16, 2020 Sep 16,			Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user moorec1 overridding Payment
	Material - Total		- Total	11	2020 Sep 16, 2020 Sep 16,		\$18,900.00	Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user moorec1 overridding Payment

Revision 4/1/2020 Page 23 of 24



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0640 -	- Total						\$0.00	
Overa	all - Total						(\$215,150.19)	

Revision 4/1/2020 Page 24 of 24