

Pay Estimate Created Date: September 2, 2020

14	te Number	Contract ID Prime Contractor	Int\$2,283,871.00unt\$42,593.50nt\$2,326,464.50						
Approval Date						By User			
September 2, 2020	Generated and Approved (and should be considered Draft) at the Project Office Level by								
September 2, 2020		Re	eviewed and Appro	ved (and should be considered Drat	ft) at the Resident Engineer Level by	HILLSD1			
September 3, 2020			F	Reviewed and Approved at the Cent	tral Office Controllers Office Level by	greggd1			
Original Comple	etion Date	ate Current Completion Date Actual Completion Date % of Current Contract Amou							
July 1, 20	021	July 1	l, 2021		92.57%				

No Milestones Exist for Contract

This Estimate	Previous	To Date
\$202,613.30	\$1,950,899.54	\$2,153,512.84
(\$798.00)	\$3,669.29	\$2,871.29
\$0.00	\$0.00	\$0.00
\$0.00	\$0.00	\$0.00
\$0.00	\$0.00	\$0.00
\$0.00	\$0.00	\$0.00
	<mark>\$1,954,568.83</mark>	\$2,156,384.13
\$201,815.30		
	\$202,613.30 (\$798.00) \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$202,613.30 \$1,950,899.54 (\$798.00) \$3,669.29 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$1,954,568.83 \$1,954,568.83

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9S3224	0020	2064000	POROUS BACKFILL	CUYD	\$85.000	44.2	\$3,757.00
	0040	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$30.000	106.66	\$3,199.80
	0050	3049910	MISC.TYPE 1 OR TYPE 5 AGGR BASE	TONS	\$48.000	20.05	\$962.40
	0060	3105002	GRAVEL (A) OR CRUSHED STONE (B)	TONS	\$35.000	19.24	\$673.40
	0110	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	CUYD	\$36.000	-48.7	(\$1,753.20
	0120	6096042	PLACING TYPE 2 ROCK DITCH LINER	CUYD	\$18.000	-48.7	(\$876.60
	0130	6113020	FURNISHING TYPE 2 ROCK BLANKET	CUYD	\$38.000	185.6	\$7,052.80
	0140	6113040	PLACING TYPE 2 ROCK BLANKET	CUYD	\$13.000	185.6	\$2,412.80
	0160	6149902	MISC.24 IN FLAP GATE	EA	\$1,000.000	1	\$1,000.00
	0170	6149902	MISC.30 IN FLAP GATE	EA	\$1,200.000	1	\$1,200.00
	0180	6149902	MISC.36 IN FLAP GATE	EA	\$1,350.000	1	\$1,350.00
	0260	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.500	2,102	\$1,051.00
	0270	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.500	1,090	\$545.00
	0280	6207001	PAVEMENT MARKING REMOVAL	LF	\$0.500	3,766	\$1,883.0
	0300	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	SQYD	\$3.000	551.3	\$1,653.90
	0310	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$20,000.000	0.75	\$15,000.00
	0330	7250424	24 IN. PIPE GROUP C	LF	\$50.000	78	\$3,900.00
	0340	7250430	30 IN. PIPE GROUP C	LF	\$60.000	85	\$5,100.00
	0350	7250436	36 IN. PIPE GROUP C	LF	\$62.000	76	\$4,712.00
	0400	8061019	SILT FENCE	LF	\$3.000	160	\$480.0
	0460	2061000	CLASS 1 EXCAVATION	CUYD	\$40.000	31	\$1,240.00
	0510	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	CUYD	\$980.000	31	\$30,380.00
	0530	7034222	SLAB ON CONCRETE BEAM	SQYD	\$430.000	148	\$63,640.0



Pay Estimate Created Date: September 2, 2020

Progress	Estimate M 14		Contract ID 191213-H04 Pay Period Start August 16, 2020 Original Contract Amount \$2,283,871.00 Prime Contractor Robertson Contractors, Inc. Pay Period End September 1, 2020 Net Change Order Amount \$42,593.50 Current Contract Amount \$2,326,464.50						
Project Number	Line Number	ltem Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount		
J9S3224	0540	7056065	17 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	LF	\$285.000	152	\$43,320.00		
	0550	7123610	SLAB DRAIN	EA	\$220.000	10	\$2,200.00		
	0560	7151001	VERTICAL DRAIN AT END BENTS	EA	\$1,400.000	2	\$2,800.00		
	0570	7161000	PLAIN NEOPRENE BEARING PAD	EA	\$180.000	6	\$1,080.00		
	0790	7034212	SLAB ON STEEL	SQYD	\$465.000	10	\$4,650.00		
Project J9S3224 - Total									
Overall - Total									

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project lumber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
983224	0260	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	Other	50% of payment withheld on this estimate pending retroreflectivity results.			(\$525.50
	0270	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	Other	50% of payment withheld on this estimate pending retroreflectivity results.			(\$272.50
	0290	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-155.3	\$15.00	(\$2,329.50
	0290	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	155.3	\$15.00	\$2,329.50
	0460	CLASS 1 EXCAVATION	Overrun			-31	\$40.00	(\$1,240.00
	0460	CLASS 1 EXCAVATION	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	31	\$40.00	\$1,240.00
	0490	GALVANIZED CAST-IN- PLACE CONCRETE PILES (14 IN)	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-185	\$125.00	(\$23,125.00
	0490	GALVANIZED CAST-IN- PLACE CONCRETE PILES (14 IN)	Material			-401	\$125.00	(\$50,125.00
	0490	GALVANIZED CAST-IN- PLACE CONCRETE PILES (14 IN)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 7 on the current Payment Estimate.	185	\$125.00	\$23,125.00
	0490	PLACE CONCRETE PILES ger (14 IN)		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	401	\$125.00	\$50,125.00	
(0510	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-31	\$980.00	(\$30,380.00
	0510	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1	31	\$980.00	\$30,380.00



Pay Estimate Created Date: September 2, 2020

Progre		mate Number 4	Contract ID Prime Contra	191213- ctor Robertso		s, Inc. Pay Period End September 1, 2020 Net	Change Orde	t Amount \$2 er Amount \$4 t Amount \$2	42,593.50				
Project Number	Line No.	Item Des	Item Description		Item Description		Item Description		Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3224						overridding Payment Estimate Exception 2 on the current Payment Estimate.							
	0530	SLAB ON CON	CRETE BEAM	Material			-148	\$430.00	(\$63,640.00)				
	0530	SLAB ON CON	CRETE BEAM	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	148	\$430.00	\$63,640.00				
	0800	SAFETY B	ARRIER CURB	Material			-133	\$105.00	(\$13,965.00				
	0800	SAFETY B/	ARRIER CURB	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	133	\$105.00	\$13,965.00				
Total				1	1				(\$798.00)				



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information											
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work							
J9S3224	FAS S701(50)	Bridge replacement and 3 bridge rehabilitations	Z	STODDARD	from 4.4 miles west of Route 153 intersection to 3.0 miles east of Route 153 intersections							
J9S3224B	FAS S703(69)	2 Bridge replacement	Z	STODDARD	from 2 miles west of Route 153 intersection to 1 miles west of Route 153 intersection							

Totals by Job Numbers

3224	This Estimate	Previous	To Date
Posted Item Pay	\$202,613.30	\$1,155,488.34	\$1,358,101.64
Gross Item Adjustments	(\$798.00)	(\$6,106.95)	(\$6,904.95)
Gross Item Pay	\$201,815.30	\$1,149,381.39	\$1,351,196.69
1	* 0.00	* 0.00	* 0.00
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
3224B	This Estimate	Previous	To Date
Posted Item Pay	\$0.00	\$795,411.20	\$795,411.20
			\$795,411.20 \$9,776.24
Posted Item Pay	\$0.00	\$795,411.20	
Posted Item Pay Gross Item Adjustments Gross Item Pay	\$0.00 \$0.00 \$0.00	\$795,411.20 \$9,776.24 \$805,187.44	\$9,776.24 \$805,187.44
Posted Item Pay Gross Item Adjustments Gross Item Pay Incentive	\$0.00 \$0.00 \$0.00 \$0.00	\$795,411.20 \$9,776.24 \$805,187.44 \$0.00	\$9,776.24 \$805,187.44 \$0.00
Posted Item Pay Gross Item Adjustments Gross Item Pay Incentive Disincentive	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$795,411.20 \$9,776.24 \$805,187.44 \$0.00 \$0.00	\$9,776.24 \$805,187.44 \$0.00 \$0.00
Posted Item Pay Gross Item Adjustments Gross Item Pay Incentive	\$0.00 \$0.00 \$0.00 \$0.00	\$795,411.20 \$9,776.24 \$805,187.44 \$0.00	\$9,776.24 \$805,187.44 \$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9S3224, Item 7021314, Project Item Line Number 0490, Material Set 702131496, Material 0501CCB1 - Concrete, Class B-1 No Air, Acceptance Action Generic 0501CCB1 is insufficient.	Pending 28-day cylinder breaks.	chronf1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3224, Item 7032003, Project Item Line Number 0510, Material Set 703200396, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Pending 28-day cylinder breaks.	chronf1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3224, Item 7034215, Project Item Line Number 0800, Material Set 703421596, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Pending 28-day cylinder breaks.	chronf1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3224, Item 7034222, Project Item Line Number 0530, Material Set 703422296, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	Pending 28-day cylinder breaks.	chronf1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-H04, Contract Project J9S3224, Project Item Line Number 0290, Contract Line Item Number 0290, Item 6224010, Minor Item.	Overridden due to completed work. Pending signed change order from contractor.	chronf1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-H04, Contract Project J9S3224, Project Item Line Number 0460, Contract Line Item Number 0460, Item 2061000, Minor Item.	Overridden due to completed work. Pending signed change order from contractor.	chronf1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-H04, Contract Project J9S3224, Project Item Line Number 0490, Contract Line Item Number 0490, Item 7021314, Minor Item.	Overridden due to completed work. Pending signed change order from contractor.	chronf1	Overridden



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Note: Posted Q	I Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.											
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-H04	J9S3224	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.75	\$18,500.00	\$13,875.00
		0001	0020	2064000	POROUS BACKFILL	143.00	8.00	151.00	CUYD	151.00	\$85.00	\$12,835.00
		0001	0030	2079909	MISC.MODIFIED LINEAR GRADING CL 2	22.80	0.00	22.80	STA	14.94	\$2,400.00	\$35,856.00
		0001	0040	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	523.30	0.00	523.30	SQYD	429.68	\$30.00	\$12,890.40
		0001	0050	3049910	MISC.TYPE 1 OR TYPE 5 AGGR BASE	139.60	0.00	139.60	TONS	79.65	\$48.00	\$3,823.20
		0001	0060	3105002	GRAVEL (A) OR CRUSHED STONE (B)	318.00	0.00	318.00	TONS	139.74	\$35.00	\$4,890.90
		0001	0070	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	912.70	0.00	912.70	TONS	503.28	\$90.00	\$45,295.20
		0001	0080	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	216.40	0.00	216.40	TONS	169.29	\$90.00	\$15,236.10
		0001	0090	4029905	MISC.OPTIONAL PAVEMENT	320.00	0.00	320.00	SQYD	319.98	\$58.00	\$18,558.84
		0001	0100	4071005	TACK COAT	587.00	0.00	587.00	GAL	352.20	\$3.50	\$1,232.70
		0001	0110	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	1,036.00	0.00	1,036.00	CUYD	381.80	\$36.00	\$13,744.80
		0001	0120	6096042	PLACING TYPE 2 ROCK DITCH LINER	1,036.00	0.00	1,036.00	CUYD	381.80	\$18.00	\$6,872.40
		0001	0130	6113020	FURNISHING TYPE 2 ROCK BLANKET		0.00	1,172.00	CUYD	1,156.10	\$38.00	\$43,931.80
	0001 0001	0140	6113040	PLACING TYPE 2 ROCK BLANKET	1,172.00	0.00	0.00 1,172.00	CUYD	1,156.10	\$13.00	\$15,029.30	
		0150	6149902	MISC.18 IN FLAP GATE	1.00	0.00	1.00	EA 1.00	\$850.00	\$850.00		
		0001	0160	6149902	MISC.24 IN FLAP GATE	3.00	0.00	3.00	EA	3.00	\$1,000.00	\$3,000.00
		0001	0170	6149902	MISC.30 IN FLAP GATE	1.00	0.00	1.00	EA	1.00	\$1,200.00	\$1,200.00
		0001	0180	6149902	MISC.36 IN FLAP GATE	4.00	0.00	4.00	EA	4.00	\$1,350.00	\$5,400.00
		0001	0190	6161005	CONSTRUCTION SIGNS	602.00	-90.00	512.00	SQFT	512.00	\$8.00	\$4,096.00
			0200	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	8.00	16.00	EA	16.00	\$35.00	\$560.00
		0001	0210	6161009	FLAG ASSEMBLY	4.00	4.00	8.00	EA	8.00	\$20.00	\$160.00
		0001	0220	6161030	TYPE III MOVEABLE BARRICADE	12.00	0.00	12.00	EA	12.00	\$125.00	\$1,500.00
		0001	0230	6161052	WARNING LIGHT, TYPE B	24.00	0.00	24.00	EA	24.00	\$65.00	\$1,560.00
		0001	0240	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00
		0001	0250	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$105,000.00	\$0.00
		0001	0251	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$87,612.00	\$87,612.00
		0001	0260	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	4,227.00	0.00	4,227.00	LF	3,235.00	\$0.50	\$1,617.50
		0001	0270	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	4,215.00	0.00	4,215.00	LF	1,620.00	\$0.50	\$810.00
		0001	0280	6207001	PAVEMENT MARKING REMOVAL	7,068.00	0.00	7,068.00	LF	6,059.00	\$0.50	\$3,029.50
		0001	0290	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	285.00	0.00	285.00	SQYD	440.30	\$15.00	\$6,604.50
		0001	0300	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	5,422.00	0.00	5,422.00	SQYD	3,203.50	\$3.00	\$9,610.50
		0001	0310	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$20,000.00	\$20,000.00
		0001	0320	7250418	18 IN. PIPE GROUP C	77.00	0.00	77.00	LF	77.00	\$45.00	\$3,465.00
		0001	0330	7250424	24 IN. PIPE GROUP C	240.00	0.00 240.00	240.00	LF	240.00	\$50.00	\$12,000.00
		0001	0340	7250430	30 IN. PIPE GROUP C	85.00	0.00	85.00	LF	85.00	\$60.00	\$5,100.00
		0001	0350	7250436	36 IN. PIPE GROUP C	388.00	0.00	388.00	LF	388.00	\$62.00	\$24,056.00
		0001	0360	8051000A	SEEDING - COOL SEASON MIXTURES	1.00	0.00	1.00	ACRE	0.65	\$3,900.00	\$2,535.00
		0001	0370	8061005	ROCK DITCH CHECK	188.00	0.00	188.00	LF	0.00	\$15.00	\$0.00
		0001	0380	8061016	SEDIMENT REMOVAL	42.00	0.00	42.00	CUYD	0.00	\$5.00	\$0.00
		0001	0390	8061017	TEMPORARY SEEDING AND MULCHING	1.00	0.00	1.00	ACRE	0.00	\$800.00	\$0.00
		0001	0400	8061019	SILT FENCE	2,349.00	0.00	2,349.00	LF	865.00	\$3.00	\$2,595.00
		0001	0410	8061050	TYPE C BERM	676.00	0.00	676.00	LF	92.00	\$8.50	\$782.00
		0040	0420	9031270A	2 IN. PSST POST - 12 GA.	236.00	0.00	236.00	LF	180.00	\$7.00	\$1,260.00
		0040	0430	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	147.00	0.00	147.00	LF	111.00	\$12.00	\$1,332.00
		0040	0440	9035004A	SH-FLAT SHEET	9.00	0.00	9.00	SQFT	9.00	\$18.00	\$162.00



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Note: Posted Q	uantities a				port Generated date and can differ from the posted amo	unt at the t	ime the E	stimate was	Genera	ated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-H04	J9S3224	0040	0450	9035069A	SHF-FLAT SHEET FLUORESCENT	144.00	0.00	144.00	SQFT	108.00	\$18.00	\$1,944.00
		0070	0460	2061000	CLASS 1 EXCAVATION	60.00	0.00	60.00	CUYD	91.00	\$40.00	\$3,640.00
		0070	0470	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$20,000.00	\$20,000.00
		0070	0480	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	111.00	0.00	111.00	SQYD	0.00	\$135.00	\$0.00
		0070	0490	7021314	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	216.00	0.00	216.00	LF	401.00	\$125.00	\$50,125.00
		0070	0500	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.00
		0070	0510	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	31.00	0.00	31.00	CUYD	31.00	\$980.00	\$30,380.00
		0070	0520	7034215	SAFETY BARRIER CURB	139.00	0.00	139.00	LF	0.00	\$105.00	\$0.00
		0070	0530	7034222	SLAB ON CONCRETE BEAM	156.00	0.00	156.00	SQYD	148.00	\$430.00	\$63,640.00
		0070	0540	7056065	17 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	152.00	0.00	152.00	LF	152.00	\$285.00	\$43,320.00
		0070	0550	7123610	SLAB DRAIN	10.00	0.00	10.00	EA	10.00	\$220.00	\$2,200.00
		0070	0560	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,400.00	\$2,800.00
		0070	0570	7161000	PLAIN NEOPRENE BEARING PAD	6.00	0.00	6.00	EA	6.00	\$180.00	\$1,080.00
		0073	0580	2169901	MISC.Removal of Existing Superstructure	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.00
		0073	0590	7034212	SLAB ON STEEL	215.00	0.00	215.00	SQYD	215.00	\$450.00	\$96,750.00
	0073	0600	7034215	SAFETY BARRIER CURB	145.00	0.00	145.00	LF	145.00	\$100.00	\$14,500.00	
		0073	0610	7040101	SUBSTRUCTURE REPAIR (FORMED)	20.00	0.00	20.00	SQFT	2.00	\$345.00	\$690.00
	0073	0620	7040113	CLEANING AND EPOXY COATING	499.00	0.00	499.00	SQFT	0.00	\$11.00	\$0.00	
		0073	0630	7121111	FABRICATED STRUCTURAL LOW ALLOY STEEL (I-BEAM) A709, GRADE 50	24,100.00	0.00	24,100.00	LB	24,100.00	\$2.30	\$55,430.00
		0073	0640	7123610	SLAB DRAIN	14.00	0.00	14.00	EA	14.00	\$220.00	\$3,080.00
		0073	0650	7129901	MISC.Galvanizing Structural Steel	1.00	0.00	1.00	LS	1.00	\$16,500.00	\$16,500.00
		0073	0660	7161002	LAMINATED NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$320.00	\$2,560.00
		0073	0670	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	8.00	0.00	8.00	EA	8.00	\$1,300.00	\$10,400.00
		0074	0680	2169901	MISC.Removal of Existing Superstructure	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.00
		0074	0690	7034212	SLAB ON STEEL	253.00	0.00	253.00	SQYD	253.00	\$445.00	\$112,585.00
		0074	0700	7034215	SAFETY BARRIER CURB	170.00	0.00	170.00	LF	170.00	\$100.00	\$17,000.00
		0074	0710	7040101	SUBSTRUCTURE REPAIR (FORMED)	20.00	0.00	20.00	SQFT	10.00	\$350.00	\$3,500.00
		0074	0720	7040113	CLEANING AND EPOXY COATING	499.00	0.00	499.00	SQFT	0.00	\$11.00	\$0.00
		0074	0730	7121111	FABRICATED STRUCTURAL LOW ALLOY STEEL (I-BEAM) A709, GRADE 50	28,030.00	0.00	28,030.00	LB	28,030.00	\$2.25	\$63,067.50
		0074	0740	7123610	SLAB DRAIN	14.00	0.00	14.00	EA	14.00	\$220.00	\$3,080.00
		0074	0750	7129901	MISC.Galvanizing Structural Steel	1.00	0.00	1.00	LS	1.00	\$18,000.00	\$18,000.00
		0074	0760	7161002	LAMINATED NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$320.00	\$2,560.00
		0074	0770	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	8.00	0.00	8.00	EA	8.00	\$1,300.00	\$10,400.00
		0075	0780	2169901	MISC.Removal of Existing Superstructure	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.00
		0075	0790	7034212	SLAB ON STEEL	198.00	0.00	198.00	SQYD	198.00	\$465.00	\$92,070.00
		0075	0800	7034215	SAFETY BARRIER CURB	133.00	0.00	133.00	LF	133.00	\$105.00	\$13,965.00
		0075	0810	7040113	CLEANING AND EPOXY COATING	499.00	0.00	499.00	SQFT	0.00	\$11.00	\$0.00
		0075	0820	7121111	FABRICATED STRUCTURAL LOW ALLOY STEEL (I-BEAM) A709, GRADE 50	22,010.00	0.00	22,010.00	LB	22,010.00	\$2.35	\$51,723.50
		0075	0830	7123610	SLAB DRAIN	12.00	0.00	12.00	EA	12.00	\$220.00	\$2,640.00
		0075	0840	7129901	MISC.Galvanizing Structural Steel	1.00	0.00	1.00	LS	1.00	\$14,500.00	\$14,500.00
		0075	0850	7161002	LAMINATED NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$380.00	\$3,040.00
		0075	0860	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	8.00	0.00	8.00	EA	8.00	\$1,300.00	\$10,400.00
		0001	5001	6189901	MISC.Contract Bond. Mobilization was adjusted for Contract Bond.	0.00	1.00	1.00	LS	1.00	\$17,388.00	\$17,388.00
		0073	5002	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	0.00	1.00	1.00	CUYD	1.00	\$1,050.00	\$1,050.00
		0073	5003	7101000	REINFORCING STEEL (EPOXY COATED)	0.00	50.00	50.00	LB	50.00	\$1.50	\$75.00
		0075	5004	7040101	SUBSTRUCTURE REPAIR (FORMED)	0.00	3.00	3.00	SQFT	3.00	\$350.00	\$1,050.00



Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	port Generated date and can differ from the posted amou Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTED To Date (See report generated date)
191213-H04	Project J99	3224 - Tota	al Value F	Posted to Da	te as of Report Generated Date					Qty		\$1,358,101.64
1012101101	J9S3224B	0001	0870	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$9,500.00	\$9,500.00
		0001	0880	2064000	POROUS BACKFILL	72.00	17.00	89.00	CUYD	89.00	\$90.00	\$8,010.00
		0001	0890	2079909	MISC.MODIFIED LINEAR GRADING CL 2	10.10	0.00	10.10	STA	10.10	\$2,600.00	\$26,260.00
		0001	0900	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	96.70	-25.50	71.20	SQYD	71.20	\$50.00	\$3,560.00
		0001	0910	3049910	MISC.TYPE 1 OR TYPE 5 AGGR BASE	61.40	0.00	61.40	TONS	61.40	\$48.00	\$2,947.20
		0001	0920	3105002	GRAVEL (A) OR CRUSHED STONE (B)	146.00	0.00	146.00	TONS	146.00	\$35.00	\$5,110.00
		0001	0930	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	399.00	111.30	510.30	TONS	510.30	\$90.00	\$45,927.00
		0001	0940	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	96.90	0.00	96.90	TONS	96.90	\$90.00	\$8,721.00
		0001	0950	4071005	TACK COAT	249.00	0.00	249.00	GAL	249.00	\$3.50	\$871.50
		0001	0960	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	794.00	-76.00	718.00	CUYD	718.00	\$35.00	\$25,130.00
		0001	0970	6096042	PLACING TYPE 2 ROCK DITCH LINER 79	794.00	-76.00	718.00	CUYD	718.00	\$15.00	\$10,770.00
		0001	0980	6113020	FURNISHING TYPE 2 ROCK BLANKET	610.00	-11.00	599.00	CUYD	599.00	\$38.00	\$22,762.00
		0001	0990	6113040	PLACING TYPE 2 ROCK BLANKET	610.00	-11.00	599.00	CUYD	599.00	\$15.00	\$8,985.00
		0001	1000	6149902	MISC.24 IN FLAP GATE	3.00	0.00	3.00	EA	3.00	\$1,000.00	\$3,000.00
		0001	1010	6149902	MISC.36 IN FLAP GATE	2.00	0.00	2.00	EA	2.00	\$1,200.00	\$2,400.00
		0001	1020	6161005	CONSTRUCTION SIGNS	410.00	-184.00	226.00	SQFT	226.00	\$8.00	\$1,808.00
		0001	1030	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	0.00	8.00	EA	8.00	\$35.00	\$280.00
		0001	1040	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	4.00	\$20.00	\$80.00
		0001	1050	6161030	TYPE III MOVEABLE BARRICADE	12.00	6.00	18.00	EA	18.00	\$125.00	\$2,250.00
		0001	1060	6161052	WARNING LIGHT, TYPE B	24.00	-12.00	12.00	EA	12.00	\$55.00	\$660.00
		0001	1070	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00
		0001	1080	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$55,000.00	\$55,000.00
		0001	1090	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,870.00	1,343.00	3,213.00	LF	3,213.00	\$1.00	\$3,213.00
		0001 11)1 1100	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,088.00	2,098.00	3,186.00	LF	3,186.00	\$1.00	\$3,186.00
		0001	1110	6207001		6,978.00	-573.00	6,405.00	LF	6,405.00	\$0.50	\$3,202.50
		0001	1120	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	203.00	-37.00	166.00	SQYD	166.00	\$15.00	\$2,490.00
		0001	1130	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	3,621.00	-386.00	3,235.00	SQYD	3,235.00	\$2.50	\$8,087.50
		0001	1140	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$9,500.00	\$9,500.00
		0001	1150	7250424	24 IN. PIPE GROUP C	219.00	30.00	249.00	LF	249.00	\$55.00	\$13,695.00
		0001	1160	7250436	36 IN. PIPE GROUP C	148.00	0.00	148.00	LF	148.00	\$68.00	\$10,064.00
		0001	1170	8051000A	SEEDING - COOL SEASON MIXTURES	1.00	0.00	1.00	ACRE	0.50	\$3,900.00	\$1,950.00
		0001	1180	8061005	ROCK DITCH CHECK	94.00	-94.00	0.00	LF	0.00	\$15.00	\$0.00
		0001	1190	8061016	SEDIMENT REMOVAL	14.00	-14.00	0.00	CUYD	0.00	\$5.00	\$0.00
		0001	1200	8061017	TEMPORARY SEEDING AND MULCHING	1.00	-1.00	0.00	ACRE	0.00	\$800.00	\$0.00
		0001	1210	8061019	SILT FENCE	522.00	-422.00	100.00	LF	100.00	\$3.50	\$350.00
		0001	1220	8061050	TYPE C BERM	365.00	-286.00	79.00	LF	79.00	\$6.50	\$513.50
		0040	1230	9031270A	2 IN. PSST POST - 12 GA.	142.00	-21.00	121.00	LF	121.00	\$7.00	\$847.00
		0040	1240	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	78.00	0.00	78.00	LF	78.00	\$12.00	\$936.00
		0040	1250	9035004A	SH-FLAT SHEET	18.00	0.00	18.00	SQFT	18.00	\$18.00	\$324.00
		0040	1260	9035069A	SHF-FLAT SHEET FLUORESCENT	72.00	0.00	72.00	SQFT	72.00	\$18.00	\$1,296.00
		0070	1270	2061000	CLASS 1 EXCAVATION	60.00	25.00	85.00	CUYD	85.00	\$30.00	\$2,550.00
		0070	1280	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$20,000.00	\$20,000.00
		0070	1290	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	111.00			SQYD	111.00	\$130.00	\$14,430.00
		0070	1300	7021314	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	196.00	121.00	317.00	LF	317.00	\$120.00	\$38,040.00



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Contract Nm.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-H04	J9S3224B	0070	1310	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.00
		0070	1320	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	31.00	0.00	31.00	CUYD	31.00	\$980.00	\$30,380.00
		0070	1330	7034215	SAFETY BARRIER CURB	139.00	0.00	139.00	LF	139.00	\$100.00	\$13,900.00
		0070	1340	7034222	SLAB ON CONCRETE BEAM	156.00	0.00	156.00	SQYD	156.00	\$450.00	\$70,200.00
		0070	1350	7056065	17 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	152.00	0.00	152.00	LF	152.00	\$285.00	\$43,320.00
		0070	1360	7123610	SLAB DRAIN	10.00	0.00	10.00	EA	10.00	\$220.00	\$2,200.00
		0070	1370	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.00
		0070	1380	7161000	PLAIN NEOPRENE BEARING PAD	6.00	0.00	6.00	EA	6.00	\$200.00	\$1,200.00
		0071	1390	2061000	CLASS 1 EXCAVATION	50.00	-12.00	38.00	CUYD	38.00	\$30.00	\$1,140.00
		0071	1400	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.00
		0071	1410	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	113.00	0.00	113.00	SQYD	113.00	\$130.00	\$14,690.00
		0071	1420	7021314	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	176.00	193.00	369.00	LF	369.00	\$120.00	\$44,280.00
		0071	1430	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.00
		0071	1440	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	28.80	0.00	28.80	CUYD	28.80	\$1,050.00	\$30,240.00
		0071	1450	7034215	SAFETY BARRIER CURB	107.00	0.00	107.00	LF	107.00	\$105.00	\$11,235.00
		0071	1460	7034222	SLAB ON CONCRETE BEAM	156.00	0.00	156.00	SQYD	156.00	\$450.00	\$70,200.00
		0071	1470	7056065	17 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	152.00	0.00	152.00	LF	152.00	\$285.00	\$43,320.00
		0071	1480	7123610	SLAB DRAIN	10.00	0.00	10.00	EA	10.00	\$220.00	\$2,200.00
		0071	1490	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.00
		0071	1500	7161000	PLAIN NEOPRENE BEARING PAD	6.00	0.00	6.00	EA	6.00	\$200.00	\$1,200.00
	Project J98	63224B - To	otal Value	e Posted to D	Date as of Report Generated Date							\$795,411.20
191213-H04 Ove	erall - Total V	alue Poste	d to Date	as of Repor	t Generated Date							\$2,153,512.84



Project: J9S3224

Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number From Station/ Log Mile To Station/ Log Mile Description DWR Date DWR Quantity Units Posted Location Offset/ Distance Offset/ Distance Comments Code Approv Date 0020 2064000 POROUS BACKFILL 8/31/20 9/2/20 -0.20 CUYD A8747 rounding correction. 245+80.2 246+28.7 9/2/20 22.20 CUYD End bent 1 of Br A8747 245+80.20 9/2/20 22 20 CUYD End bent 2 of Br A8747 246+28 70 3040506 TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) 8/19/20 9/2/20 53.33 SQYD N02871 east approach 634+66 634+86 0040 9/2/20 53.33 SQYD N02871 west approach 633+80 634+00 0050 3049910 MISC. AGGREGATE FOR BASE 8/17/20 8/26/20 20.05 TONS Br. N02871. Type 5 aggregate shoulders. 632+35 637+00 Ticket quantity 3105002 GRAVEL (A) OR CRUSHED STONE (B) 19.24 TONS Br. N02871 entrances. 0060 8/17/20 8/26/20 633+13 634+92 Ticket quantity -238.30 CUYD Br. N02871. Subtracting quantities of 76.5, 34.4, 103.7, and 23.7 CUYD (Total of 238.3 CUYD). All ditch liner remeasured upon completion due to accidental double counting and calculation error during construction. 6096020 FURN. TYPE 2 ROCK DITCH LINER 8/19/20 9/2/20 -76.5 - 34.4 - 103.7 - 23.7 = -238.3 0110 632+90 634+00 9/2/20 11.10 CUYD N02871 NE pipe inlet 635+00 635+20 11.90 CUYD Br. N02871 southwest ditch at pipe inlet 9/2/20 633+45 633+65 9/2/20 25.20 CUYD Br. N02871 southwest ditch pipe outlet 633+85 634+25 9/2/20 30.80 CUYD Br. N02871 NW ditch foreslope. 633+82 Foreslope only. Ditch bottom used rock blanket. 633+30 9/2/20 44.80 CUYD Br. N02871 NW ditch pipe inlet 632+07 633+00 8/31/20 9/2/20 16.70 CUYD Ditch Southwest of Br. A8747 245+07 245+37 9/2/20 49 10 CUYD Ditch Northwest of Br A8747 244+87 245+40 -238.30 CUYD Br. N02871. Subtracting quantities of 76.5, 34.4, 103.7, and 23.7 CUYD (Total of 238.3 CUYD). All ditch liner remeasured upon completion due to accidental double counting and calculation error during construction. 0120 6096042 PLACING TYPE 2 ROCK DITCH LINER 8/19/20 9/2/20 632+90 634+00 -76.5 - 34.4 - 103.7 - 23.7 = -238.3 9/2/20 11.10 CUYD N02871 NE pipe inlet 635+00 635+20 11.90 CUYD Br. N02871 southwest ditch at pipe inlet 9/2/20 633+65 633+45 9/2/20 25.20 CUYD Br. N02871 southwest ditch pipe outlet 633+85 634+25 9/2/20 30.80 CUYD Br. N02871 NW ditch foreslope 633+30 633+82 Foreslope only. Ditch bottom used rock blanket. 9/2/20 44.80 CUYD Br. N02871 NW ditch pipe inlet 632+07 633+00 8/31/20 9/2/20 16.70 CUYD Ditch Southwest of Br. A8747 245+07 245+37 9/2/20 49.10 CUYD Ditch Northwest of Br. A8747 245+40 244+87 11.80 CUYD Br. N02871 rock blanket 0130 6113020 FURNISHING TYPE 2 ROCK BLANKET 8/19/20 9/2/20 634+00 antity added based on final measurement check of NW FBD rock blanket (108.6), west bank rock blanket (125.3), east bank rock blanket (168.9) Partial payment. Final measurement to be made at later date once complete. 86.80 CUYD Br. A8747. Plan section G-G to I-I. 9/2/20 246+33 87.00 CUYD Br. A8747. Plan section B-B to D-D. 9/2/20 245+80 Partial payment. Final measurement to be made at later date once complete. 0140 6113040 PLACING TYPE 2 ROCK BLANKET 8/19/20 9/2/20 11.80 CUYD Br. N02871 rock blanke 634+00 Quantity added based on final measurement check of entire area. NW FBD rock blanket (108.6), west bank rock blanket (125.3), east bank rock blanket (168.9) 9/2/20 86.80 CUYD Br A8747 Plan section G-G to I-I 246+33 Partial payment. Final measurement to be made at later 9/2/20 87.00 CUYD Br. A8747. Plan section B-B to D-D. 245+80 Partial payment. Final measurement to be made at later date once complete. 6149902 MISC. DRAINAGE FITTINGS 8/18/20 8/24/20 1.00 EA Br. A8747 southwest. 0160 245+50 RT 0170 6149902 MISC. DRAINAGE FITTINGS 8/31/20 9/2/20 1.00 EA Outflow end of Northeast Field entrance 30" pipe at the corner of Br. A8747. 246+65 0180 6149902 MISC. DRAINAGE FITTINGS 8/18/20 8/24/20 1.00 EA Br. A8747 northwest 245+50 LT 0260 6206000C 4 IN WHITE WATERBORNE PAVEMENT MARKING 8/26/20 8/26/20 974 00 LF Br. N02871 white edge line (LT 464', RT 510') 631+55 8/26/20 1 128 00 LF Br. N02861 white edge line (LT 565', RT 563') 578+00 0270 6206001C 4 IN. YELLOW WATERBORNE PAVEMENT MARKING 8/26/20 8/26/20 540.00 LF Br. N02861 yellow CL skips (54 x 10-ft) 570+48 CL 8/26/20 550.00 LF Br. N02871 yellow CL skips (55 x 10-ft) 623+64 CL 0280 6207001 PAVEMENT MARKING REMOVAL 8/26/20 8/26/20 938.00 LF Br. N02861 west double yellow (469' x 2) 570+48 CL LF Br. N02861 east double yellow (494' x 2) 586+57 CL 8/26/20 988.00 LF Br. N02871 west double yellow removal 8/31/20 9/2/20 910.00 623+60 628+80 Removal around skips (520 x 2) - (13 x 10) 9/2/20 930.00 LF Br. N02871 east double yellow removal 639+80 645+10 Removal around skips (530 x 2) - (13 x 10) -371.00 SQYD Br. N02871. Subtracting quantities of 76.5, 103.3, 155.6, and 35.6 SQYD (Total of 371 SQYD). All ditch liner remeasured upon completion due to accidential double counting and calculation error during construction. 0300 6240103A PERMANENT EROSION CONTROL GEOTEXTILE 8/19/20 9/2/20 632+90 634+00 -76 5 - 101 3 - 155 6 - 35 6 = -371 17.70 SQYD Br. N02871 rock blanket 9/2/20 634+00 antity added based on final measurement check of re rock blanket area (additional 11.8 CUYD rock blanket added for pay). 9/2/20 33.30 SQYD N02871 NE pipe inlet ditch liner 635+00 635+20 9/2/20 35.60 SQYD Br. N02871 southwest ditch at pipe inlet ditch line 633+45 633+65 9/2/20 75.60 SQYD Br. N02871 southwest ditch pipe outlet ditch liner 634+25 633+85 9/2/20 92.40 SQYD Br. N02871 NW ditch foreslope ditch line 633+30 633+82 Foreslope only. Ditch bottom used rock blanket. 134.30 SQYD Br. N02871 NW ditch pipe inlet ditch line 632+07 633+00 9/2/20 Partial payment. Final measurement to be made at later date once complete. 9/2/20 168.00 SQYD Br. A8747. Rock blanket. Plan section G-G to I-I. 246+33 9/2/20 168.20 SQYD Br. A8747. Rock Blanket. Plan section B-B to D-D. 245+80 Partial payment. Final measurement to be made at later 8/31/20 9/2/20 50.00 SQYD Ditch liner southwest of Br. A8747 245+37 9/2/20 147.20 SQYD Ditch liner northwest of Br. A8747 244+87 245+40 LS Br. N02861, Br. N02871, Br. A8747 0310 6274000 CONTRACTOR FURNISHED SURVEYING AND STAKI 9/1/20 9/2/20 0.75 243+25 637+00 0330 7250424 24 IN. PIPE CULVERT GROUP C 8/18/20 8/24/20 78.00 LF Br. A8747 southwest. 245+50 RT 0340 7250430 30 IN. PIPE CULVERT GROUP C 8/26/20 8/26/20 85.00 LF Br. A8747. Northeast. 246+65 LT 0350 7250436 36 IN. PIPE CULVERT GROUP C 8/18/20 8/24/20 76.00 LF Br. A8747 northwest 245+50 LT LF Northeast corner of Br. A8747 on slope of DD#4 0400 8061019 SILT FENCE 8/31/20 9/2/20 35.00 246+40 9/2/20 LF Southwest of Br. A8747 45.00 245+70 9/2/20 80.00 LF Northwest of Br. A8747 245+70 2061000 CLASS 1 EXCAVATION 8/17/20 8/26/20 13.00 CUYD Br. A8747. Additional quantity than plan excavated on 245+80 sured final quantity is 43 CUYD on west. 0460 8/26/20 18.00 CUYD Br. A8747. Additional quantity than plan excavated on 246+33 Measured final quantity is 48 CUYD on east 0510 7032003 CLASS B CONCRETE (SUBSTRUCTURE) 8/17/20 8/26/20 15.50 CUYD Br. A8747. Bent 1 245+80 8/18/20 8/24/20 15.50 CUYD Br. A8747. Bent 2 246+33 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0530	7034222	SLAB ON CONCRETE BEAM	8/27/20	8/31/20	148.00	SQYD	Br. A8747	245+80		246+33		95% payment. 5% remains for curing, sealing, and stripping forms.
0540	7056065	17 IN., PRESTRESSED CONC SPREAD BOX BM	8/21/20	8/24/20	152.00	LF	Br. A8747. Beam 1, 2, & 3.	245+80		246+33		
0550	7123610	SLAB DRAIN	8/27/20	8/31/20	10.00	EA	Br. A8747	245+80		246+33		
0560	7151001	VERTICAL DRAIN AT END BENTS	8/31/20	9/2/20	1.00	EA	End bent 1 of Br. A8747	245+80.20				
				9/2/20	1.00	EA	End bent 2 of Br. A8747	246+33.70				
0570	7161000	PLAIN NEOPRENE BEARING PAD	8/21/20	8/24/20	6.00	EA	Br. A8747. Bent 1 & 2.	245+80		246+33		
0790	7034212	SLAB ON STEEL	8/19/20	9/2/20	10.00	SQYD	Br. N02871	634+00		634+66		Remaining 5% payment for curing, sealing, and stripping forms.

The information below this line are details from Line Item agency views. No Agency View Details Exist



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
040	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		8	Jun 2, 2020	SYSTEM	(\$1,620.00)	
				8	Jun 2, 2020	SYSTEM	\$1,620.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$1,620.00)	
				9	Jun 16, 2020	SYSTEM	\$1,620.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				10	Jul 1, 2020	SYSTEM	(\$8,802.60)	
				10	Jul 1, 2020	SYSTEM	\$8,802.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
040 -	Total						\$0.00	
050	MISC. TYPE 1 OR TYPE 5 AGGR BASE	Material		8	Jun 2, 2020	SYSTEM	(\$1,105.92)	
				8	Jun 2, 2020	SYSTEM	\$1,105.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$1,105.92)	
				9	Jun 16, 2020	SYSTEM	\$1,105.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				10	Jul 1, 2020	SYSTEM	(\$1,105.92)	
				10	Jul 1, 2020	SYSTEM	\$1,105.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
050 -	Total						\$0.00	
060	GRAVEL (A) OR CRUSHED STONE (B)	Material		8	Jun 2, 2020	SYSTEM	(\$1,190.00)	
				8	Jun 2, 2020	SYSTEM	\$1,190.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$1,190.00)	
				9	Jun 16, 2020	SYSTEM	\$1,190.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				10	Jul 1, 2020	SYSTEM	(\$1,190.00)	
				10	Jul 1, 2020	SYSTEM	\$1,190.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	Total						\$0.00	
070	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Material		8	Jun 2, 2020	SYSTEM	(\$9,981.00)	
				8	Jun 2, 2020	SYSTEM	\$9,981.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 4 on the current



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0070	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Material						Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Other Item Adjustment	ACAD	8	Jun 2, 2020	chronf1	(\$191.30)	ACAD for 110.9 Tons of BB17-41.
				10	Jul 1, 2020	chronf1	(\$852.97)	ACAD for 329.65 Tons of BB17-41.
				13	Aug 17, 2020	chronf1	(\$1,320.15)	ACAD for 62.73 Tons of BB17-41.
			ACAD - Tota	al			(\$2,364.42)	
	Other Item Adjustment - Total						(\$2,364.42)	
0070 -	Total						(\$2,364.42)	
0080	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material		8	Jun 2, 2020	SYSTEM	(\$5,787.00)	
				8	Jun 2, 2020	SYSTEM	\$5,787.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	ACAD	8	Jun 2, 2020	chronf1	(\$116.80)	ACAD for 53.7 Tons of SL20-25.
				10	Jul 1, 2020	chronf1	(\$189.23)	ACAD for 58.0 Tons of SL20-25.
				10	Jul 1, 2020	chronf1	\$33.93	ACAD for -15.6 Tons of SL20-25. Overpayment was made on Estimate No. 8. Estimate No. 8 Price Index used for calculation. 38.1 Tons should have been used for ACAD instead of 53.7 Tons (38.1 - 53.7 = -15.6).
				13	Aug 17, 2020	chronf1	(\$1,942.10)	ACAD for 73.19 Tons of SL20-25.
			ACAD - Tota	al			(\$2,214.20)	
	Other Item Adjustment - Total						(\$2,214.20)	
0080 -	Total						(\$2,214.20)	
0090	MISC. OPTIONAL PAVEMENT	Material		8	Jun 2, 2020	SYSTEM	(\$6,186.28)	
				8	Jun 2, 2020	SYSTEM	\$6,186.28	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	MISC. OPTIONAL PAVEMENT	Other Item Adjustment	ACAD	8	Jun 2, 2020	chronf1	(\$105.81)	ACAD for 106.66 SY (BB17-41 and SL20-25).
				10	Jul 1, 2020	chronf1	(\$155.75)	ACAD for 106.66 SY.
				13	Aug 17, 2020	chronf1	(\$1,266.77)	ACAD for 106.66 SY.
			ACAD - Tota	al			(\$1,528.33)	
	Other Item Adjustment - Total						(\$1,528.33)	
0090 -	Total						(\$1,528.33)	
0100	TACK COAT	Material		8	Jun 2, 2020	SYSTEM	(\$351.05)	
				8	Jun 2, 2020	SYSTEM	\$351.05	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user chronf1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$351.05)	
				9	Jun 16, 2020	SYSTEM	\$351.05	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0100	TACK COAT	Material		10	Jul 1, 2020	SYSTEM	(\$914.20)	
				10	Jul 1, 2020	SYSTEM	\$914.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				11	Jul 15, 2020	SYSTEM	(\$914.20)	
				11	Jul 15, 2020	SYSTEM	\$914.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0100 -	Total						\$0.00	
0190	CONSTRUCTION SIGNS	Material		2	Mar 2, 2020	SYSTEM	(\$3,776.00)	
				2	Mar 2, 2020	SYSTEM	\$3,776.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0190 -	Total			_			\$0.00	
0200	ADVANCED WARNING RAIL SYSTEM	Material		2	Mar 2, 2020	SYSTEM	(\$560.00)	
				2	Mar 3, 2020	SYSTEM	\$560.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				3	Mar 17, 2020	SYSTEM	(\$560.00)	
			- Total				(\$560.00)	
	Material - Total						(\$560.00)	
	ADVANCED WARNING RAIL SYSTEM	MaterialCredit		4	Apr 2, 2020	SYSTEM	\$560.00	
			- Total				\$560.00	
	MaterialCredit - Total						\$560.00	
	ADVANCED WARNING RAIL SYSTEM	Overrun	Overrun	2	Mar 2, 2020	SYSTEM	(\$280.00)	
				2	Mar 2, 2020	SYSTEM	\$280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 8 on the current Payment Estimate.
				3	Mar 17, 2020	SYSTEM	(\$280.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				3	Mar 17, 2020	SYSTEM	\$280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 5 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0200 -	Total						\$0.00	
0210	FLAG ASSEMBLY	Material		2	Mar 2, 2020	SYSTEM	(\$160.00)	
				2	Mar 2, 2020	SYSTEM	\$160.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	FLAG ASSEMBLY	Overrun	Overrun	2	Mar 2, 2020	SYSTEM	(\$80.00)	
				2	Mar 2, 2020	SYSTEM	\$80.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 9 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0210	FLAG ASSEMBLY	Overrun	Overrun	3	Mar 17, 2020	SYSTEM	(\$80.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				3	Mar 17, 2020	SYSTEM	\$80.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0210 -	Total						\$0.00	
0240	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material		3	Mar 17, 2020	SYSTEM	(\$6,000.00)	
			- Total				(\$6,000.00)	
	Material - Total						(\$6,000.00)	
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	MaterialCredit		4	Apr 2, 2020	SYSTEM	\$6,000.00	
			- Total				\$6,000.00	
	MaterialCredit - Total						\$6,000.00	
0240 -	Total						\$0.00	
0260	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	OTHR	9	Jun 16, 2020	chronf1	(\$283.25)	50% of payment withheld on this estimate pending retroreflectivity results.
	BEADS			10	Jul 1, 2020	chronf1	\$283.25	Payment for 50% of posting that was previously withheld (retroreflectivity results accepted).
				14	Sep 2, 2020	chronf1	(\$525.50)	50% of payment withheld on this estimate pending retroreflectivit results.
			OTHR - Tota	al			(\$525.50)	
	Other Item Adjustment - Total						(\$525.50)	
0260 -	Total						(\$525.50)	
0270	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	OTHR		Jun 16, 2020	chronf1	(\$132.50)	50% of payment withheld on this estimate pending retroreflectivity results.
				10	Jul 1, 2020	chronf1	\$132.50	Payment for 50% of posting that was previously withheld (retroreflectivity results accepted).
			OTHR - Tota	14	Sep 2, 2020	chronf1	(\$272.50)	50% of payment withheld on this estimate pending retroreflectivity results.
			UTHR - Tota	31			(\$272.50)	
	Other Item Adjustment - Total						(\$272.50)	
0270 -		0	0	40		OVOTEN	(\$272.50)	
0290	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	Overrun	Overrun		2020	SYSTEM	(\$2,329.50)	
				13	Aug 17, 2020	SYSTEM	\$2,329.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				14	Sep 2, 2020	SYSTEM	(\$2,329.50)	Averaged Price Adjustment from this item on all previous paymer estimates of '0.00000' is applied (if non-zero).
				14	Sep 2, 2020	SYSTEM	\$2,329.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0290 -	Total						\$0.00	
0360	SEEDING - COOL SEASON MIXTURES	Material		8	Jun 2, 2020	SYSTEM	(\$780.00)	
				8	Jun 2, 2020	SYSTEM	\$780.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0360 ·	- Total						\$0.00	
0400	SILT FENCE	Material		7	May 19, 2020	SYSTEM	(\$1,635.00)	
				7	May 19, 2020	SYSTEM	\$1,635.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0400 ·	- Total						\$0.00	
0410	TYPE C BERM	Material		13	Aug 17, 2020	SYSTEM	(\$782.00)	
				13	Aug 17, 2020	SYSTEM	\$782.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0410 ·	- Total						\$0.00	
0460	CLASS 1 EXCAVATION	Overrun	Overrun	14	Sep 2, 2020	SYSTEM	(\$1,240.00)	
				14	Sep 2, 2020	SYSTEM	\$1,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
)460 ·	- Total						\$0.00	
0490	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Material		13	Aug 17, 2020	SYSTEM	(\$50,125.00)	
				13	Aug 17, 2020	SYSTEM	\$50,125.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				14	Sep 2, 2020	SYSTEM	(\$50,125.00)	
				14	Sep 2, 2020	SYSTEM	\$50,125.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Overrun	Overrun	13	Aug 17, 2020	SYSTEM	(\$23,125.00)	
				13	Aug 17, 2020	SYSTEM	\$23,125.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 7 on the current Payment Estimate.
				14	Sep 2, 2020	SYSTEM	(\$23,125.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				14	Sep 2, 2020	SYSTEM	\$23,125.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 7 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
)490 ·	- Total						\$0.00	
)510	CLASS B CONCRETE (SUBSTRUCTURE)	Material		14	Sep 2, 2020	SYSTEM	(\$30,380.00)	
				14	Sep 2, 2020	SYSTEM	\$30,380.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	- Total						\$0.00	



Image Name Data By Para Para 501 SLAB (M CONCAPE FE HBAM Montel Image Status Montel Status	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Image: second	LING	Decomption		Adjustment				, anount	
Image: State in the ima	0530	SLAB ON CONCRETE BEAM	Material		14		SYSTEM	(\$63,640.00)	
Distribution State of the second					14		SYSTEM	\$63,640.00	
Solution Stable ON STEEL Material Stable ON STEEL Stable ON STEEL Material Stable ON STEEL Stable ON STEEL <ths< td=""><td></td><td></td><td></td><td>- Total</td><td></td><td></td><td></td><td>\$0.00</td><td></td></ths<>				- Total				\$0.00	
90 SLAB ON STEEL Material 6 Myr 4 9'STEM (\$33,750.00) 9 Myr 5 SYSTEM \$33,750.00 The adjustment differs the original system generated Overunt Overriding Payment Estimate Ison/point of Stratus Escoption 9 on the current Overriding Payment Estimate Ison/point (Stratus Escoption 9 on the current Overriding Payment Estimate Ison/point (Stratus Escoption 9 on the current Payment Estimate Ison/point (Stratus Escoption 9 on the current Payment Estimate Ison/point (Stratus Escoption 9 on the current Payment Estimate Ison/point (Stratus Escoption 9 on the current Payment Estimate Ison/point (Stratus Escoption 9 on the current Payment Estimate Escoption 9 on the curent Payment Estimate Escoption 9 on the current Pay		Material - Total						\$0.00	
	0530 -	Total						\$0.00	
 	0590	SLAB ON STEEL	Material		6		SYSTEM	(\$33,750.00)	
 					6		SYSTEM	\$33,750.00	
					7		SYSTEM	(\$91,800.00)	
Image: state in the image: state image: stat					7		SYSTEM	\$91,800.00	
Image: Solution of the end of th					8		SYSTEM	(\$96,750.00)	
 					8		SYSTEM	\$96,750.00	
substrate tem Adjustment (001) due to user chronit payment Estimate. Payment Estimate tem Adjustment (001) due to user chronit payment Estimate. 10 Jul 1, 2020 SYSTEM (96,750.00) Material - Total - Total - Total 500 - Total - Total - Total 600 SAFETY BARRIER CURB Material 8 Jun 2, 2020 SYSTEM (514,500.00) 600 - Total - Total - Total - Total - Total 600 - Total - Total SYSTEM (514,500.00) 600 - Total - Total - Stimate tem Adjustment (0012) due to user chronit overriding Payment Estimate tem Adjustment (0012) due to user chronit overriding Payment Estimate tem Adjustment (0012) due to user chronit payment Estimate 600 - Total - Total SYSTEM (514,500.00) 600 - Total - Total - Total - Total - Total 600 - Total - Total - Total SUBSTRUCTURE REPAI					9		SYSTEM	(\$96,750.00)	
Image: state in the second state in the se					9		SYSTEM	\$96,750.00	
image: state of the s					10		SYSTEM	(\$96,750.00)	
Material - Total \$0.00 590 - Total \$0.00 600 SAFETY BARRIER CURB Material 8 Jun 2, 2020 SYSTEM (\$14,500.00) 600 SAFETY BARRIER CURB Material 8 Jun 2, 2020 SYSTEM \$14,500.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user chored overrun Payment Estimate Exception 11 on the current Payment Estimate Exception 8 on the current Payment Estimate Exception 8 on the current Payment Estimate Exception 8 on the cu					10		SYSTEM	\$96,750.00	
Se0 - Total \$0.00 SAFETY BARRIER CURB Material				- Total				\$0.00	
600 SAFETY BARRIER CURB Material 8 Jun 2, 2020 SYSTEM (\$14,500.00) Payment Estimate Item Adjustment (012) due to user chronth overriding Payment Estimate Item Adjustment (012) due to user chronth Payment Estimate Item Adjustment (012) due to user chronth Payment Estimate Item Adjustment (012) due to user chronth Payment Estimate Item Adjustment (012) due to user chronth Payment Estimate Item Adjustment (012) due to user chronth Payment Estimate Item Adjustment (012) due to user chronth Payment Estimate Item Adjustment (0006) due to user chronth Payment Estimate Item Adjustment (0006) due to user chronth Payment Estimate Item Adjustment (0006) due to user chronth Payment Estimate Item Adjustment (0006) due to user chronth Payment Estimate Item Adjustment (0006) due to user chronth Payment Estimate Item Adjustment (0006) due to user chronth Payment Estimate Item Adjustment (0006) due to user chronth Payment Estimate Item Adjustment (0006) due to user chronth Payment Estimate Item Adjustment (0006) due to user chronth Payment Estimate Item Adjustment (0006) due to user chronth Payment Estimate Item Adjustment (0006) due to user chronth Payment Estimate Item Adjustment (0006) due to user chronth Payment Estimate Item Adjustment (0006) due to user chronth Payment Estimate Item Adjustment (0006) due to user chronth Payment Estimate Item Adjustment (0006) due to user chronth Payment Item Item Adjustment (0006) due to user chronth Payment Item Item Item Item Item Item Item Ite		Material - Total						\$0.00	
Image: state in the state	0590 -	Total						\$0.00	
Image: state in the image: state in	0600	SAFETY BARRIER CURB	Material		8		SYSTEM	(\$14,500.00)	
Image: second					8		SYSTEM	\$14,500.00	
Autorial - Total 2020 Payment Estimate Item Adjustment (0006) due to user chronfl overridding Payment Estimate Exception 11 on the current Payment Estimate. 600 - Total - Total \$0.00 600 - Total \$0.00 610 SUBSTRUCTURE REPAIR (FORMED) Material 7 May 19, 2020 \$YSTEM \$\$690.00 7 May 19, 2020 \$YSTEM \$\$690.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user chronfl overridding Payment Estimate. 9 - Total \$0.00 This adjustment estimate. 10 - Total \$0.00 This adjustment offsets the original system estimate.					10		SYSTEM	(\$14,500.00)	
Material - Total \$0.00 600 - Total \$0.00 610 SUBSTRUCTURE REPAIR (FORMED) Material 7 May 19, 2020 SYSTEM (\$690.00) 7 May 19, 2020 SYSTEM \$600.00 7 May 19, 2020 SYSTEM \$690.00 9 - Total 7 May 19, 2020 SYSTEM \$690.00 10 - Total - Total \$600.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user chronf overridding Payment Estimate Exception 8 on the current Payment Estimate. 10 - Total \$0.00 \$0.00					10		SYSTEM	\$14,500.00	
600 - Total \$0.00 610 SUBSTRUCTURE REPAIR (FORMED) Material 7 May 19, 2020 SYSTEM (\$690.00) 7 May 19, 2020 SYSTEM \$690.00 This adjustment offsets the original system-generated Overnum Payment Estimate Item Adjustment (0008) due to user chronf overridding Payment Estimate Exception 8 on the current Payment Estimate. Material - Total				- Total				\$0.00	
And SUBSTRUCTURE REPAIR (FORMED) Material 7 May 19, 2020 SYSTEM (\$690.00) 7 May 19, 2020 SYSTEM (\$690.00) This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user chronf overridding Payment Estimate Exception 8 on the current Payment Estimate. Material - Total		Material - Total						\$0.00	
Image: state of the state o	0600 -	Total						\$0.00	
- Total 2020 Payment Estimate Item Adjustment (0008) due to user chronf overridding Payment Estimate Exception 8 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00	0610	SUBSTRUCTURE REPAIR (FORMED)	Material		7		SYSTEM	(\$690.00)	
Material - Total \$0.00					7		SYSTEM	\$690.00	
				- Total				\$0.00	
		Material - Total						\$0.00	
610 - Total \$0.00	0610 -	Total						\$0.00	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
630	FABRICATED STRUCTURAL LOW ALLOY STEEL (I-BEAM) A709, GRADE	Material		6	May 4, 2020	SYSTEM	(\$55,430.00)	
	50			6	May 5, 2020	SYSTEM	\$55,430.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				7	May 19, 2020	SYSTEM	(\$55,430.00)	
				7	May 19, 2020	SYSTEM	\$55,430.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user chronf1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
630 -	Total						\$0.00	
670	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	Material		7	May 19, 2020	SYSTEM	(\$10,400.00)	
				7	May 19, 2020	SYSTEM	\$10,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				8	Jun 2, 2020	SYSTEM	(\$10,400.00)	
				8	Jun 2, 2020	SYSTEM	\$10,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$10,400.00)	
				9	Jun 16, 2020	SYSTEM	\$10,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				10	Jul 1, 2020	SYSTEM	(\$10,400.00)	
				10	Jul 1, 2020	SYSTEM	\$10,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				11	Jul 15, 2020	SYSTEM	(\$10,400.00)	
				11	Jul 15, 2020	SYSTEM	\$10,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
670 -	Total						\$0.00	
690	SLAB ON STEEL	Material		9	Jun 16, 2020	SYSTEM	(\$62,300.00)	
				9	Jun 16, 2020	SYSTEM	\$62,300.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				10	Jul 1, 2020	SYSTEM	(\$112,585.00)	
				10	Jul 1, 2020	SYSTEM	\$112,585.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
690 -	Total						\$0.00	
700	SAFETY BARRIER CURB	Material		10	Jul 1, 2020	SYSTEM	(\$17,000.00)	
				10	Jul 1, 2020	SYSTEM	\$17,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user chronf1 overridding Payment Estimate Exception 10 on the current



			01	- .	0.1.1	0.1.1	A .	
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0700	SAFETY BARRIER CURB	Material						Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0700 -	Total						\$0.00	
0770	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	Material		9	Jun 16, 2020	SYSTEM	(\$10,400.00)	
				9	Jun 16, 2020	SYSTEM	\$10,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				10	Jul 1, 2020	SYSTEM	(\$10,400.00)	
				10	Jul 1, 2020	SYSTEM	\$10,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				11	Jul 15, 2020	SYSTEM	(\$10,400.00)	
				11	Jul 15, 2020	SYSTEM	\$10,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0770 -	Total						\$0.00	
0790	SLAB ON STEEL	Material		12	Jul 31, 2020	SYSTEM	(\$87,420.00)	
				12	Jul 31, 2020	SYSTEM	\$87,420.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				13	Aug 17, 2020	SYSTEM	(\$87,420.00)	
				13	Aug 17, 2020	SYSTEM	\$87,420.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0790 -	Total						\$0.00	
0800	SAFETY BARRIER CURB	Material		13	Aug 17, 2020	SYSTEM	(\$13,965.00)	
				13	Aug 17, 2020	SYSTEM	\$13,965.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				14	Sep 2, 2020	SYSTEM	(\$13,965.00)	
				14	Sep 2, 2020	SYSTEM	\$13,965.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0800 -	Total						\$0.00	
0860	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	Material		11	Jul 15, 2020	SYSTEM	(\$10,400.00)	
				11	Jul 15, 2020	SYSTEM	\$10,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0860 -	Total						\$0.00	
0880	POROUS BACKFILL	Overrun	Overrun	8	Jun 2,	SYSTEM	(\$1,530.00)	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0880	POROUS BACKFILL	Overrun	Overrun		2020			
				8	Jun 2, 2020	SYSTEM	\$1,530.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user chronf1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$1,530.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				9	Jun 16, 2020	SYSTEM	\$1,530.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0880 -	Total						\$0.00	
0900	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		6	May 4, 2020	SYSTEM	(\$690.00)	
				6	May 5, 2020	SYSTEM	\$690.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0900 -	Total						\$0.00	
0910	MISC. TYPE 1 OR TYPE 5 AGGR BASE	Material		6	May 4, 2020	SYSTEM	(\$1,619.52)	
				6	May 5, 2020	SYSTEM	\$1,619.52	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				10	Jul 1, 2020	SYSTEM	(\$2,947.20)	
				10	Jul 1, 2020	SYSTEM	\$2,947.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0910 -	Total						\$0.00	
0920	GRAVEL (A) OR CRUSHED STONE (B)	Material		6	May 4, 2020	SYSTEM	(\$2,695.00)	
				6	May 5, 2020	SYSTEM	\$2,695.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0920 -	Total						\$0.00	
0930	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Material		6	May 4, 2020	SYSTEM	(\$26,910.00)	
				6	May 5, 2020	SYSTEM	\$26,910.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				7	May 19, 2020	SYSTEM	(\$26,910.00)	
				7	May 19, 2020	SYSTEM	\$26,910.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Other Item Adjustment	ACAD	6	May 5, 2020	chronf1	\$68.77	ACAD for 299 Tons of BB17-41.
				9	Jun 16,	chronf1	(\$546.74)	ACAD for 211.3 Tons of BB17-41.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0930		Other Item Adjustment	ACAD - Tot	al			(\$477.97)	
	Other Item Adjustment - Total						(\$477.97)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Overrun	Overrun	9	Jun 16, 2020	SYSTEM	(\$10,017.00)	
				9	Jun 16, 2020	SYSTEM	\$9,081.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	\$936.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0930 -	Total						(\$477.97)	
0940	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material		6	May 4, 2020	SYSTEM	(\$4,725.00)	
				6	May 5, 2020	SYSTEM	\$4,725.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				7	May 19, 2020	SYSTEM	(\$4,725.00)	
				7	May 19, 2020	SYSTEM	\$4,725.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	ACAD	6	May 5, 2020	chronf1	\$15.23	ACAD for 52.5 Tons of SL20-25.
				9	Jun 16, 2020	chronf1	(\$144.86)	ACAD for 44.4 Tons of SL20-25.
			ACAD - Tot	al			(\$129.63)	
	Other Item Adjustment - Total						(\$129.63)	
0940 -	Total						(\$129.63)	
0950	TACK COAT	Material		6	May 4, 2020	SYSTEM	(\$451.50)	
				6	May 5, 2020	SYSTEM	\$451.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0950 -	Total						\$0.00	
1020	CONSTRUCTION SIGNS	Material		2	Mar 2, 2020	SYSTEM	(\$1,328.00)	
				2	Mar 2, 2020	SYSTEM	\$1,328.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
							\$0.00	
1020 -	Total					SYSTEM	(\$280.00)	
1020 - 1030	Total ADVANCED WARNING RAIL SYSTEM	Material		2	Mar 2, 2020	STOTEM	(+=====)	
		Material		2		SYSTEM	\$280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		Material			2020 Mar 2,		. ,	Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 4 on the current



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1030	Material - Total						(\$280.00)	
	ADVANCED WARNING RAIL SYSTEM	MaterialCredit		4	Apr 2, 2020	SYSTEM	\$280.00	
			- Total				\$280.00	
	MaterialCredit - Total						\$280.00	
1030 -	- Total						\$0.00	
1040	FLAG ASSEMBLY	Material		2	Mar 2, 2020	SYSTEM	(\$80.00)	
				2	Mar 2, 2020	SYSTEM	\$80.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1040 -	- Total						\$0.00	
1050	TYPE III MOVEABLE BARRICADE	Overrun	Overrun	3	Mar 17, 2020	SYSTEM	(\$750.00)	
				3	Mar 17, 2020	SYSTEM	\$750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
1050 -	- Total						\$0.00	
1070	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	Material		2	Mar 2, 2020	SYSTEM	(\$6,000.00)	
	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED			2	Mar 2, 2020	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user chronf1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				3	Mar 17, 2020	SYSTEM	(\$6,000.00)	
			- Total				(\$6,000.00)	
	Material - Total						(\$6,000.00)	
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	MaterialCredit		4	Apr 2, 2020	SYSTEM	\$6,000.00	
			- Total				\$6,000.00	
	MaterialCredit - Total						\$6,000.00	
1070 -	- Total						\$0.00	
1090	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P		OTHR	9	Jun 16, 2020	chronf1	(\$1,606.50)	50% of payment withheld on this estimate pending retroreflectivit results.
	BEADS			10	Jul 1, 2020	chronf1	\$1,606.50	Payment for 50% of posting that was previously withheld (retroreflectivity results accepted).
			OTHR - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Overrun	Overrun	9	Jun 16, 2020	SYSTEM	(\$1,343.00)	
	BEADS			9	Jun 16, 2020	SYSTEM	\$1,343.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
10 <u>90</u> -	- Total						\$0.00	
1100	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING	Other Item Adjustment	OTHR	9	Jun 16, 2020	chronf1	(\$946.50)	50% of payment withheld on this estimate pending retroreflectivit results.
	PAINT, TYPE P BEADS			10	Jul 1, 2020	chronf1	\$946.50	Payment for 50% of posting that was previously withheld (retroreflectivity results accepted).
			OTHR - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1100	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun	Overrun	9	Jun 16, 2020	SYSTEM	(\$805.00)	
	FAINT, FFE F BLADS			9	Jun 16, 2020	SYSTEM	\$805.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user chronf1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
1100 - `	Total						\$0.00	
1150	24 IN. PIPE GROUP C	Material		5	Apr 15, 2020	SYSTEM	(\$3,080.00)	
				5	Apr 15, 2020	SYSTEM	\$3,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	24 IN. PIPE GROUP C	Overrun	Overrun	8	Jun 2, 2020	SYSTEM	(\$1,650.00)	
				8	Jun 2, 2020	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$1,650.00)	Averaged Price Adjustment from this item on all previous paymen estimates of '0.00000' is applied (if non-zero).
				9	Jun 16, 2020	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
1150 - '							\$0.00	
1160	36 IN. PIPE GROUP C	Material		5	Apr 15, 2020	SYSTEM	(\$10,064.00)	
				5	Apr 15, 2020	SYSTEM	\$10,064.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1160 - `							\$0.00	
1170	SEEDING - COOL SEASON MIXTURES	Material		6	May 4, 2020	SYSTEM	(\$975.00)	
				6	May 5,	SYSTEM	¢075.00	This adjustes and affects the environmentation of a sector of the sector
				0	2020	STOTEM	\$975.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				7		SYSTEM	(\$975.00)	Payment Estimate Item Adjustment (0012) due to user chronf1 overridding Payment Estimate Exception 14 on the current
					2020 May 19,			Payment Estimate Item Adjustment (0012) due to user chronf1 overridding Payment Estimate Exception 14 on the current
-			- Total	7	2020 May 19, 2020 May 19,	SYSTEM	(\$975.00)	Payment Estimate Item Adjustment (0012) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 11 on the current
	Material - Total		- Total	7	2020 May 19, 2020 May 19,	SYSTEM	(\$975.00) \$975.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0012) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 11 on the current
	Total		- Total	7 7	2020 May 19, 2020 May 19, 2020	SYSTEM	(\$975.00) \$975.00 \$0.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0012) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 11 on the current
		Material	- Total	7 7 6	2020 May 19, 2020 May 19, 2020	SYSTEM SYSTEM SYSTEM	(\$975.00) \$975.00 \$0.00 \$0.00 \$0.00 (\$513.50)	Payment Estimate Item Adjustment (0012) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
1170 - 1220	Total	Material	- Total	7 7	2020 May 19, 2020 May 19, 2020 May 4,	SYSTEM	(\$975.00) \$975.00 \$0.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0012) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 11 on the current
	Total	Material	- Total	7 7 6	2020 May 19, 2020 May 19, 2020 May 4, 2020 May 4, 2020	SYSTEM SYSTEM SYSTEM	(\$975.00) \$975.00 \$0.00 \$0.00 \$0.00 (\$513.50)	Payment Estimate Item Adjustment (0012) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 19 on the current



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
1220	TYPE C BERM	Material	Туре					overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1220 -	l - Total						\$0.00	
1230	2 IN. PSST POST - 12 GA.	Material		6	May 4, 2020	SYSTEM	(\$504.00)	
				6	May 5, 2020	SYSTEM	\$504.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				7	May 19, 2020	SYSTEM	(\$504.00)	
				7	May 19, 2020	SYSTEM	\$504.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1230 ·	Total						\$0.00	
1240	POST ANCHOR FOR 2 IN. PSST - 12 GA.	Material		6	May 4, 2020	SYSTEM	(\$504.00)	
				6	May 5, 2020	SYSTEM	\$504.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				7	May 19, 2020	SYSTEM	(\$504.00)	
				7	May 19,	SYSTEM	\$504.00	This adjustment offsets the original system-generated Overrun
					2020			Payment Estimate Item Adjustment (0016) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	overridding Payment Estimate Exception 15 on the current
	Material - Total		- Total					overridding Payment Estimate Exception 15 on the current
1240 -	Material - Total - Total		- Total				\$0.00	overridding Payment Estimate Exception 15 on the current
1240 - 1250		Material	- Total	6		SYSTEM	\$0.00 \$0.00	overridding Payment Estimate Exception 15 on the current
	- Total	Material	- Total	6	2020 May 4,		\$0.00 \$0.00 \$0.00	overridding Payment Estimate Exception 15 on the current
	- Total	Material	- Total		2020 May 4, 2020 May 5,	SYSTEM	\$0.00 \$0.00 \$0.00 (\$324.00)	overridding Payment Estimate Exception 15 on the current Payment Estimate.
	- Total	Material	- Total	6	2020 May 4, 2020 May 5, 2020 May 19,	SYSTEM	\$0.00 \$0.00 \$324.00 \$324.00	overridding Payment Estimate Exception 15 on the current Payment Estimate.
	- Total	Material	- Total	6 7	2020 May 4, 2020 May 5, 2020 May 19, 2020 May 19,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$324.00) \$324.00 (\$324.00)	overridding Payment Estimate Exception 15 on the current Payment Estimate.
	- Total	Material		6 7	2020 May 4, 2020 May 5, 2020 May 19, 2020 May 19,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$324.00) \$324.00 (\$324.00) \$324.00	overridding Payment Estimate Exception 15 on the current Payment Estimate.
1250	Total SH-FLAT SHEET	Material		6 7	2020 May 4, 2020 May 5, 2020 May 19, 2020 May 19,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$324.00) \$324.00 (\$324.00) \$324.00	overridding Payment Estimate Exception 15 on the current Payment Estimate.
1250	Total SH-FLAT SHEET Material - Total			6 7	2020 May 4, 2020 May 5, 2020 May 19, 2020 May 19,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$324.00) \$324.00 (\$324.00) \$324.00 \$324.00 \$0.00	overridding Payment Estimate Exception 15 on the current Payment Estimate.
1250 -	Total SH-FLAT SHEET Material - Total Total			6 7 7	2020 May 4, 2020 May 5, 2020 May 19, 2020 May 19, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$324.00) \$324.00 (\$324.00) \$324.00 \$324.00 \$0.00 \$0.00	overridding Payment Estimate Exception 15 on the current Payment Estimate.
1250	Total SH-FLAT SHEET Material - Total Total			6 7 7 6	2020 May 4, 2020 May 5, 2020 May 19, 2020 May 19, 2020 May 19, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$324.00) \$324.00 (\$324.00) (\$324.00) \$324.00 \$324.00 \$0.00 \$0.00 \$0.00 (\$648.00)	overridding Payment Estimate Exception 15 on the current Payment Estimate.
1250	Total SH-FLAT SHEET Material - Total Total			6 7 7 6 6	2020 May 4, 2020 May 5, 2020 May 19, 2020 May 19, 2020 May 19, 2020 May 5, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$324.00) \$324.00 (\$324.00) \$324.00 \$324.00 \$324.00 \$0.00 \$0.00 \$0.00 \$0.00 \$648.00	overridding Payment Estimate Exception 15 on the current Payment Estimate.
1250	Total SH-FLAT SHEET Material - Total Total			6 7 7 6 6 6 7	2020 May 4, 2020 May 5, 2020 May 19, 2020 May 19, 2020 May 19, 2020 May 5, 2020 May 19, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$324.00) \$324.00 (\$324.00) \$324.00 \$324.00 \$324.00 \$0.00 \$0.00 \$0.00 \$0.00 \$648.00) \$648.00	overridding Payment Estimate Exception 15 on the current Payment Estimate.
1250 -	Total SH-FLAT SHEET Material - Total Total		- Total	6 7 7 6 6 6 7	2020 May 4, 2020 May 5, 2020 May 19, 2020 May 19, 2020 May 19, 2020 May 5, 2020 May 19, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$324.00) \$324.00 (\$324.00) \$324.00 \$324.00 \$324.00 \$0.00 \$0.00 \$0.00 \$648.00 \$648.00 \$648.00	overridding Payment Estimate Exception 15 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1270	CLASS 1 EXCAVATION	Overrun	Overrun	7	May 19, 2020	SYSTEM	(\$750.00)	
				7	May 19, 2020	SYSTEM	\$750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
1270 -	Total						\$0.00	
1290	BRIDGE APPROACH SLAB (MINOR ROAD)	Other Item Adjustment	ACAD	9	Jun 16, 2020	chronf1	(\$193.68)	ACAD for 111 SY (BB17-41 and SL20-25).
			ACAD - Tota	al			(\$193.68)	
	Other Item Adjustment - Total						(\$193.68)	
290 -	Total						(\$193.68)	
300	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Material		6	May 4, 2020	SYSTEM	(\$38,040.00)	
				6	May 5, 2020	SYSTEM	\$38,040.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				7	May 19, 2020	SYSTEM	(\$38,040.00)	
				7	May 19, 2020	SYSTEM	\$38,040.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				8	Jun 2, 2020	SYSTEM	(\$38,040.00)	
				8	Jun 2, 2020	SYSTEM	\$38,040.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user chronf1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Other Item Adjustment	OTHR	6	May 5, 2020	chronf1	\$3,840.00	This is payment for the splices on Bent 1 and Bent 2 on Br. A8748. Bent 1: 3 splices x 8LF/splice = $24LF$. Bent 2: 1 splice x 8LF/splice = 8LF. Total: $32LF \times 120/LF = 3,840$.
			OTHR - Tota	al			\$3,840.00	
	Other Item Adjustment - Total						\$3,840.00	
	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Overrun	Overrun	6	May 4, 2020	SYSTEM	\$14,520.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 24 on the current Payment Estimate.
				6	May 4, 2020	SYSTEM	(\$14,520.00)	
				7	May 19, 2020	SYSTEM	(\$14,520.00)	Averaged Price Adjustment from this item on all previous payme estimates of '0.00000' is applied (if non-zero).
				7	May 19, 2020	SYSTEM	\$14,520.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 19 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
300 -	Total						\$3,840.00	
320	CLASS B CONCRETE (SUBSTRUCTURE)	Material		7	May 19, 2020	SYSTEM	(\$30,380.00)	
				7	May 19, 2020	SYSTEM	\$30,380.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
320 -	Total						\$0.00	
1330	SAFETY BARRIER CURB	Material		8	Jun 2, 2020	SYSTEM	(\$13,900.00)	
				8	Jun 2,	SYSTEM	\$13,900.00	This adjustment offsets the original system-generated Overrun



kink initial information in the second in the	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
	1330	SAFETY BARRIER CURB	Material			2020			overridding Payment Estimate Exception 12 on the current
Image: state in tradition of the state in the s					9		SYSTEM	(\$13,900.00)	
Image: state in the state in thest in the state in thest in the state in the state in					9		SYSTEM	\$13,900.00	Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 8 on the current
Image: second					10		SYSTEM	(\$13,900.00)	
Material - Total Material - Total 90.00 90.00 1340 SLAB ON CONCRETE BEAM Material - Total 8 Jun.2 SVSTEM 66.00 Participation of factors the original system-generated Overnan Payment Estimate Exception 13 on the current Payment Estimate Exception 14 on the current Payment Estimate Exception 3					10		SYSTEM	\$13,900.00	Payment Estimate Item Adjustment (0009) due to user chronf1 overridding Payment Estimate Exception 12 on the current
H330 - Total SLAB ON CONCRETE BEAM Material Material 0 40.0 1340 SLAB ON CONCRETE BEAM Material 4 2000 SVSTEM \$50,600.00) This adjustment officis the original system-generated Overnut Payment Estimate Inference I				- Total					
1340 SLAB ON CONCRETE BEAM A Material Status Material A status 2 32.0 m m m m m m m m m m m m m m m m m m m									
Image: stand									
4 2020 cm Programmed Estimate Exception 13 on the current Provenside Programmed Estimate Exception 13 on the curent Provenside Programmed Esti	1340	SLAB ON CONCRETE BEAM	Material		8		SYSTEM	(\$66,600.00)	
Image: state in the					8		SYSTEM	\$66,600.00	Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 13 on the current
Image: second					10		SYSTEM	(\$70,200.00)	
Material - Total Second S					10		SYSTEM	\$70,200.00	Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 13 on the current
1340 Total S0.00 1410 BRIDGE APPROACH SLAB (MINOR ROAD) Matrial 7 May 19, 2020 SYSTEM \$14.690.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overriding Payment Estimate Exception 3 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 3 on the current Payment Estimate Material - Total - Total 50.00 Material - Total ACAD - Total 50.00 Metrial - Total ACAD - Total 517.52 Other Item Adjustment - Total ACAD - Total 517.52 Other Item Adjustment - Total 517.52 GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN) Metrial Apr 12, 2020 SYSTEM \$44.280.00 2020 SYSTEM \$44.280.00 CONCRETE PILES (14 IN) Metrial - Total SYSTEM \$44.280.00 <td< td=""><td></td><td></td><td></td><td>- Total</td><td></td><td></td><td></td><td>\$0.00</td><td></td></td<>				- Total				\$0.00	
1410 BRIDGE APPROACH SLAB (MINOR ROAD) Material ROAD Material ROAD 7 May 19, 2020 SYSTEM (\$14,690.00) This adjustment offsets the original system-generated Overnun Payment Estimate Item Adjustment (0007) due to user chronth overniding Payment Estimate Exception 3 on the current Payment Estimate Exception 4 on the current Payment Estimate Exception 1 on the current Payment Estimate Excepti		Material - Total						\$0.00	
$ \left \begin{array}{c c c c c c c c c c c c c c c c c c c $	1340 -	Total						\$0.00	
Image: Constraint of the second se	1410		Material		7		SYSTEM	(\$14,690.00)	
Material - Total S0.00 BRIDGE APPROACH SLAB (MINOR ROAD) Other Item Aguistment ACAD 6 May 5, 2020 chronf1 \$17.52 ACAD for 113 SY. ACAD - Total ACAD - Total \$17.52 ACAD for 113 SY. Other Item Adjustment - Total \$17.52 \$17.52 \$17.52 1410 - Total \$17.52 \$17.52 \$17.52 1420 GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN) Material \$4 Apr 2, 2020 \$YSTEM \$44,280.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate Exception 2 or Br. Adjustment GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN) O					7		SYSTEM	\$14,690.00	Payment Estimate Item Adjustment (0007) due to user chronf1
BRIDGE APPROACH SLAB (MINOR ROAD) Other Item Adjustment ACAD 6 May 5, 2020 chron11 \$17.52 ACAD for 113 SY. Interval of the Majustment - Total Image: ACAD - Total \$17.52 Image: ACAD - Total \$17.52 Image: ACAD - Total \$17.52 Image: ACAD - Total \$17.52 Image: ACAD - Total \$17.52 Image: ACAD - Total \$17.52 Image: Image: ACAD - Total \$17.52 Image: ACAD - Total \$17.52 Image:									
Image: Road Road Road Road Road Road Road Road				- Total				\$0.00	
Other Item Adjustment - Total \$17.52 Item - Total \$17.52 GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN) Material 4 Apr 2, 2020 SYSTEM (\$44,280.00) This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate Exception 1 on the current Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 payment Estim		Material - Total		- Total					
\$17.52 1410 - Total GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN) Material 4 Apr 2, 2020 SYSTEM \$44,280.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate. 5 Apr 15, 2020 SYSTEM \$44,280.00 This adjustment offsets the original system-generated Overrun Payment Estimate. 5 Apr 15, 2020 SYSTEM \$44,280.00 This adjustment offsets the original system-generated Overrun Payment Estimate. 6 Apr 15, 2020 SYSTEM \$44,280.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 1 on the current Payment Estimate Exception 1 on the current Payment Estimate. 7 Total SYSTEM \$44,280.00 This adjustment offsets the original system-generated Overrun Payment Estimate. 6 Apr 15, 2020 SYSTEM \$44,280.00 This adjustment offsets the original system-generated Overrun Payment Estimate. 7 Total SO.00 SYSTEM \$44,280.00 This adjustment offsets the original system-generated Overrun Payment Estimate. 6 Other Item CONCRETE PILES (14 IN) Other Item Adjustment Other Item Ad		BRIDGE APPROACH SLAB (MINOR			6		chronf1	\$0.00	Payment Estimate.
1420 GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN) Material 4 Apr 2, 2020 SYSTEM (\$44,280.00) This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate Exception 1 on the current Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment		BRIDGE APPROACH SLAB (MINOR		ACAD			chronf1	\$0.00 \$17.52	Payment Estimate.
CONCRETE PILES (14 IN) Image: Signal system sys		BRIDGE APPROACH SLAB (MINOR ROAD)		ACAD			chronf1	\$0.00 \$17.52 \$17.52	Payment Estimate.
Image: Second	1410 -	BRIDGE APPROACH SLAB (MINOR ROAD) Other Item Adjustment - Total		ACAD			chronf1	\$0.00 \$17.52 \$17.52 \$17.52 \$17.52	Payment Estimate.
Image: space of the space	1410 - 1420	BRIDGE APPROACH SLAB (MINOR ROAD) Other Item Adjustment - Total Total GALVANIZED CAST-IN-PLACE	Adjustment	ACAD	al	2020 Apr 2,		\$0.00 \$17.52 \$17.52 \$17.52 \$17.52	Payment Estimate.
Image: Constraint of the splices on Bent 1 and Bent 2 on BF. Other Item Other Item OTHR 4 Apr 2, 2020 Chronf1 \$6,720.00 GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN) Other Item OTHR 4 Apr 2, 2020 Chronf1 \$6,720.00		BRIDGE APPROACH SLAB (MINOR ROAD) Other Item Adjustment - Total Total GALVANIZED CAST-IN-PLACE	Adjustment	ACAD	al 4	2020 Apr 2, 2020 Apr 2,	SYSTEM	\$0.00 \$17.52 \$17.52 \$17.52 \$17.52 \$17.52 (\$44,280.00)	Payment Estimate. ACAD for 113 SY. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 1 on the current
Material - Total State State <td></td> <td>BRIDGE APPROACH SLAB (MINOR ROAD) Other Item Adjustment - Total Total GALVANIZED CAST-IN-PLACE</td> <td>Adjustment</td> <td>ACAD</td> <td>al 4 4</td> <td>2020 Apr 2, 2020 Apr 2, 2020 Apr 15,</td> <td>SYSTEM</td> <td>\$0.00 \$17.52 \$17.52 \$17.52 \$17.52 (\$44,280.00) \$44,280.00</td> <td>Payment Estimate. ACAD for 113 SY. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 1 on the current</td>		BRIDGE APPROACH SLAB (MINOR ROAD) Other Item Adjustment - Total Total GALVANIZED CAST-IN-PLACE	Adjustment	ACAD	al 4 4	2020 Apr 2, 2020 Apr 2, 2020 Apr 15,	SYSTEM	\$0.00 \$17.52 \$17.52 \$17.52 \$17.52 (\$44,280.00) \$44,280.00	Payment Estimate. ACAD for 113 SY. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 1 on the current
GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN) Adjustment OTHR 4 Apr 2, 2020 chronf1 \$6,720.00 chronf1 This is payment for the splices on Bent 1 and Bent 2 on Br. A8802. Bent 1: 3 splices x 8LF/splice = 24LF. Bent 2: 4 splices x 8LF/splice = 32LF. Total: 56LF x \$120/LF = \$6,720		BRIDGE APPROACH SLAB (MINOR ROAD) Other Item Adjustment - Total Total GALVANIZED CAST-IN-PLACE	Adjustment	ACAD	4 4 5	2020 Apr 2, 2020 Apr 2, 2020 Apr 2, 2020 Apr 15, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$17.52 \$17.52 \$17.52 \$17.52 (\$44,280.00) \$44,280.00 (\$44,280.00)	Payment Estimate. ACAD for 113 SY. ACAD for 113 SY. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 1 on the current
CONCRETE PILES (14 IN) Adjustment 2020 This is payment for the splices on Bent 1 and Bent 2 on Br. A8802. Bent 1: 3 splices x 8LF/splice = 24LF. Bent 2: 4 splices x 8LF/splice = 32LF. Total: 56LF x \$120/LF = \$6,720		BRIDGE APPROACH SLAB (MINOR ROAD) Other Item Adjustment - Total Total GALVANIZED CAST-IN-PLACE	Adjustment	ACAD	4 4 5	2020 Apr 2, 2020 Apr 2, 2020 Apr 2, 2020 Apr 15, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$17.52 \$17.52 \$17.52 (\$44,280.00) \$44,280.00 (\$44,280.00) \$44,280.00	Payment Estimate. ACAD for 113 SY. ACAD for 113 SY. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 1 on the current
		BRIDGE APPROACH SLAB (MINOR ROAD) Other Item Adjustment - Total Total GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Adjustment	ACAD	4 4 5	2020 Apr 2, 2020 Apr 2, 2020 Apr 2, 2020 Apr 15, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 \$17.52 \$17.52 \$17.52 (\$44,280.00) \$44,280.00 (\$44,280.00) \$44,280.00	Payment Estimate. ACAD for 113 SY. ACAD for 113 SY. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 1 on the current
		BRIDGE APPROACH SLAB (MINOR ROAD) Other Item Adjustment - Total Total GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN) Material - Total GALVANIZED CAST-IN-PLACE	Adjustment Material	ACAD ACAD - Tota	4 4 5 5	2020 Apr 2, 2020 Apr 2, 2020 Apr 15, 2020 Apr 15, 2020 Apr 15, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$17.52 \$17.52 \$17.52 \$17.52 (\$44,280.00) \$44,280.00 (\$44,280.00) \$44,280.00 \$44,280.00	Payment Estimate. ACAD for 113 SY. ACAD for 113 SY. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate. Chronf1 This is payment for the splices on Bent 1 and Bent 2 on Br. A8802. Bent 1: 3 splices x 8LF/splice = 24LF. Bent 2: 4 splices x



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
1420	Other Item Adjustment - Total		Туре				\$6,720.00	
	- Total						\$6,720.00	
1440	CLASS B CONCRETE	Material		4	Apr 2,	SYSTEM	(\$30,240.00)	
1440	(SUBSTRUCTURE)	Wateria			2020			
				4	Apr 2, 2020	SYSTEM	\$30,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				5	Apr 15, 2020	SYSTEM	(\$30,240.00)	
				5	Apr 15, 2020	SYSTEM	\$30,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1440	- Total						\$0.00	
1450	SAFETY BARRIER CURB	Material		5	Apr 15, 2020	SYSTEM	(\$11,235.00)	
				5	Apr 15, 2020	SYSTEM	\$11,235.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				6	May 4, 2020	SYSTEM	(\$11,235.00)	
				6	May 5, 2020	SYSTEM	\$11,235.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user chronf1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	Material - Total							
1450	- Total						\$0.00	
1450 1460		Material		4	Apr 2, 2020	SYSTEM	\$0.00 (\$66,600.00)	
	- Total	Material		4		SYSTEM SYSTEM		This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	- Total	Material			2020 Apr 2,		(\$66,600.00)	Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 5 on the current
	- Total	Material		4	2020 Apr 2, 2020 Apr 15,	SYSTEM	(\$66,600.00) \$66,600.00	Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 5 on the current
	- Total	Material		4	2020 Apr 2, 2020 Apr 15, 2020 Apr 15,	SYSTEM SYSTEM	(\$66,600.00) \$66,600.00 (\$70,200.00)	Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 6 on the current
	- Total	Material		4 5 5	2020 Apr 2, 2020 Apr 15, 2020 Apr 15, 2020 May 4,	SYSTEM SYSTEM SYSTEM	(\$66,600.00) \$66,600.00 (\$70,200.00) \$70,200.00	Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 6 on the current
	- Total	Material	- Total	4 5 5 6	2020 Apr 2, 2020 Apr 15, 2020 Apr 15, 2020 May 4, 2020 May 5,	SYSTEM SYSTEM SYSTEM	(\$66,600.00) \$66,600.00 (\$70,200.00) \$70,200.00 (\$70,200.00)	Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user chronf1 overridding Payment Estimate Exception 12 on the current
	- Total	Material	- Total	4 5 5 6	2020 Apr 2, 2020 Apr 15, 2020 Apr 15, 2020 May 4, 2020 May 5,	SYSTEM SYSTEM SYSTEM	(\$66,600.00) \$66,600.00 (\$70,200.00) \$70,200.00 (\$70,200.00) \$70,200.00	Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user chronf1 overridding Payment Estimate Exception 12 on the current
1460	Total SLAB ON CONCRETE BEAM	Material	- Total	4 5 5 6	2020 Apr 2, 2020 Apr 15, 2020 Apr 15, 2020 May 4, 2020 May 5,	SYSTEM SYSTEM SYSTEM	(\$66,600.00) \$66,600.00 (\$70,200.00) \$70,200.00 (\$70,200.00) \$70,200.00	Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user chronf1 overridding Payment Estimate Exception 12 on the current