Progress Estimate 15		Contract ID Prime Contrac	Contract ID 191213-H04 Pay Period Start September 2, 2020 Original Contract Amoun Prime Contractor Robertson Contractors, Inc. Pay Period End September 15, 2020 Net Change Order Amoun Current Contract Amount						
Approval Date						By User			
September 17, 2020	Generated and Approved (and should be considered Draft) at the Project Office Level by								
September 17, 2020			Reviewed and Appro	ved (and should be considered Dra	ft) at the Resident Engineer Level by	HILLSD1			
September 18, 2020			F	Reviewed and Approved at the Cent	tral Office Controllers Office Level by	greggd1			
Original Comple	etion Date	Pate Current Completion Date Actual Completion Date % of Current Contract Amount							
July 1, 20	21	Ju	uly 1, 2021		95.58%				

No Milestones Exist for Contract

Contract Total Pa	y For Estimate No. 15			
		This Estimate	Previous	To Date
191213-H04				
	Total Posted Items Pay	\$96,556.26	\$2,153,512.84	\$2,250,069.10
	Gross Item Adjustments	(\$2,071.72)	\$2,871.29	\$799.57
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	-		\$2,156,384.13	\$2,250,868.67
Contract Total Pa	yable This Estimate:	\$94,484.54		

Contract Total Payable This Estimate: Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9S3224	0010	2022010	REMOVAL OF IMPROVEMENTS	LS	\$18,500.000	0.25	\$4,625.00
	0030	2079909	MISC.MODIFIED LINEAR GRADING CL 2	STA	\$2,400.000	4.46	\$10,704.00
	0040	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$30.000	57.32	\$1,719.60
	0050	3049910	MISC.TYPE 1 OR TYPE 5 AGGR BASE	TONS	\$48.000	21.15	\$1,015.20
	0060	3105002	GRAVEL (A) OR CRUSHED STONE (B)	TONS	\$35.000	128.26	\$4,489.10
	0070	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	TONS	\$90.000	26.62	\$2,395.80
	0080	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	TONS	\$90.000	41.01	\$3,690.90
	0090	4029905	MISC.OPTIONAL PAVEMENT	SQYD	\$58.000	0.02	\$1.16
	0100	4071005	TACK COAT	GAL	\$3.500	88.8	\$310.80
	0110	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	CUYD	\$36.000	40.2	\$1,447.20
	0120	6096042	PLACING TYPE 2 ROCK DITCH LINER	CUYD	\$18.000	40.2	\$723.60
	0130	6113020	FURNISHING TYPE 2 ROCK BLANKET	CUYD	\$38.000	129.9	\$4,936.20
	0140	6113040	PLACING TYPE 2 ROCK BLANKET	CUYD	\$13.000	129.9	\$1,688.70
	0290	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	SQYD	\$15.000	283.7	\$4,255.50
	0300	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	SQYD	\$3.000	239.5	\$718.50
	0360	8051000A	SEEDING - COOL SEASON MIXTURES	ACRE	\$3,900.000	0.25	\$975.00
	0420	9031270A	2 IN. PSST POST - 12 GA.	LF	\$7.000	49	\$343.00
	0430	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	LF	\$12.000	36	\$432.00
	0450	9035069A	SHF-FLAT SHEET FLUORESCENT	SQFT	\$18.000	36	\$648.00
	0480	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	SQYD	\$135.000	111	\$14,985.0
	0520	7034215	SAFETY BARRIER CURB	LF	\$105.000	139	\$14,595.00
	0530	7034222	SLAB ON CONCRETE BEAM	SQYD	\$430.000	8	\$3,440.00
	0620	7040113	CLEANING AND EPOXY COATING	SQFT	\$11.000	499	\$5,489.00
	0720	7040113	CLEANING AND EPOXY COATING	SQFT	\$11.000	499	\$5,489.0



Progress Estimate Number Contract ID 191213-H04 Pay Period Start September 2, 2020 Original Contract Amou 15 15 Prime Contractor Robertson Contractors, Inc. Pay Period End September 15, 2020 Net Change Order Amou							
Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9S3224	0810	7040113	CLEANING AND EPOXY COATING	SQFT	\$11.000	499	\$5,489.00
Project J9S3	224 - Total						\$94,606.26
J9S3224B	1170	8051000A	SEEDING - COOL SEASON MIXTURES	ACRE	\$3,900.000	0.5	\$1,950.00
Project J9S3	224B - Tota	l					\$1,950.00
Overall - Tota	al						\$96,556.26

No Contract Adjustments Exist on Contract

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3224	0070	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	ACAD for 26.62 Tons of BB17-41.			(\$76.53)		
	0080			Withheld pending performance of segregated areas under traffic.			(\$2,500.00)	
	0080	80 BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) Other Item Adjustment AcAD Price Adjustment		ACAD for 41.01 Tons of SL20-37.			(\$87.15)	
	0130	FURNISHING TYPE 2 ROCK BLANKET	Overrun			-114	\$38.00	(\$4,332.00)
	0130	FURNISHING TYPE 2 ROCK BLANKET	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0030) due to user chronf1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	114	\$38.00	\$4,332.00
	0140	PLACING TYPE 2 ROCK BLANKET	Overrun			-114	\$13.00	(\$1,482.00)
	0140	PLACING TYPE 2 ROCK BLANKET	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0031) due to user chronf1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	114	\$13.00	\$1,482.00
	0260	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	Other	Payment for 50% of posting that was previously withheld (retroreflectivity results accepted).			\$525.50
	0270	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	Other	Payment for 50% of posting that was previously withheld (retroreflectivity results accepted).			\$272.50
	0290	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	Overrun			-121.4	\$15.00	(\$1,821.00)
	0290	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	Overrun			-95.6	\$15.00	(\$1,434.00)
C	0290	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0032) due to user chronf1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	121.4	\$15.00	\$1,821.00
	0290	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0033) due to user chronf1	95.6	\$15.00	\$1,434.00

Progre	ss Esti 1	mate Number 5	Contract ID Prime Contra	191213-ł ctor Robertsc		Pay Period Start September 2, 2020 Orig s, Inc. Pay Period End September 15, 2020 Net Cur		er Amount \$	70,288.50
Project Number	Line No.	Item De	scription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
9\$3224						overridding Payment Estimate Exception 13 on the current Payment Estimate.			
	0480		PROACH SLAB MINOR ROAD)	Other Item Adjustment	Asphalt Cement Price Adjustment	ACAD for 111 SY.			(\$206.04
	0480		PROACH SLAB MINOR ROAD)	Material			-111	\$135.00	(\$14,985.00
	0480		PROACH SLAB MINOR ROAD)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0034) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	111	\$135.00	\$14,985.00
	0490		IZED CAST-IN- NCRETE PILES (14 IN)	Material			-401	\$125.00	(\$50,125.00
	0490		IZED CAST-IN- NCRETE PILES (14 IN)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0038) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	401	\$125.00	\$50,125.00
	0510		B CONCRETE SSTRUCTURE)	Material			-31	\$980.00	(\$30,380.00
	0510		B CONCRETE 3STRUCTURE)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0039) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	31	\$980.00	\$30,380.00
	0520	SAFETY B	ARRIER CURB	Material			-139	\$105.00	(\$14,595.00
	0520	SAFETY B	ARRIER CURB	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0035) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	139	\$105.00	\$14,595.00
	0530	SLAB ON CON	ICRETE BEAM	Material			-156	\$430.00	(\$67,080.00
	0530	SLAB ON CON	ICRETE BEAM	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0036) due to user chronf1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	156		\$67,080.00
	0620	CLEANIN	G AND EPOXY COATING	Material			-499	\$11.00	(\$5,489.00
	0620	0 CLEANING AND EPOXY COATING		Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0040) due to user chronf1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	499	\$11.00	\$5,489.00
	0720	CLEANIN	G AND EPOXY COATING	Material			-499	\$11.00	(\$5,489.00
	0720	CLEANIN	G AND EPOXY COATING	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0041) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	499	\$11.00	\$5,489.00
	0800	SAFETY B	ARRIER CURB	Material			-133	\$105.00	(\$13,965.00)
	0800	SAFETY B	ARRIER CURB	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0037) due to user chronf1	133	\$105.00	\$13,965.00



Progre	ss Esti 1	mate Number 5	Contract ID Prime Contrac	191213-H ctor Robertso	Pay Period Start September 2, 2020 Original Contract Amount \$2,283,871.00 Inc. Pay Period End September 15, 2020 Net Change Order Amount \$70,288.50 Current Contract Amount \$2,354,159.50					
Project Number	Line No.	Item Description		Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
J9S3224						overridding Payment Estimate Exception 6 on the current Payment Estimate.				
	0810	CLEANING	G AND EPOXY COATING	Material			-499	\$11.00	(\$5,489.00)	
	0810 CLEANIN		EANING AND EPOXY COATING			This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0042) due to user chronf1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	499	\$11.00	\$5,489.00	
Total									(\$2,071.72)	



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information											
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work							
J9S3224	FAS S701(50)	Bridge replacement and 3 bridge rehabilitations	Z	STODDARD	from 4.4 miles west of Route 153 intersection to 3.0 miles east of Route 153 intersections							
J9S3224B	FAS S703(69)	2 Bridge replacement	Z	STODDARD	from 2 miles west of Route 153 intersection to 1 miles west of Route 153 intersection							

Totals by Job Numbers

S3224	This Estimate	Previous	To Date
Posted Item Pay	\$94,606.26	\$1,358,101.64	\$1,452,707.90
Gross Item Adjustments	(\$2,071.72)	(\$6,904.95)	(\$8,976.67)
Gross Item Pay	\$92,534.54	\$1,351,196.69	\$1,443,731.23
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
S3224B	This Estimate	Previous	To Date
Posted Item Pay	\$1,950.00	\$795,411.20	\$797,361.20
Posted Item Pay	\$1,950.00	\$795,411.20	\$797,361.20
Posted Item Pay Gross Item Adjustments Gross Item Pay	\$1,950.00 \$0.00 \$1,950.00	\$795,411.20 \$9,776.24 \$805,187.44	\$797,361.20 \$9,776.24 \$807,137.44
Posted Item Pay Gross Item Adjustments	\$1,950.00 \$0.00	\$795,411.20 \$9,776.24	\$797,361.20 \$9,776.24
Posted Item Pay Gross Item Adjustments Gross Item Pay Incentive	\$1,950.00 \$0.00 \$1,950.00 \$0.00	\$795,411.20 \$9,776.24 \$805,187.44 \$0.00	\$797,361.20 \$9,776.24 \$807,137.44 \$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9S3224, Item 5031011A, Project Item Line Number 0480, Material Set 5031011A96, Material 0401BPPMBB - Plant Mix Bituminous Base, Acceptance Action Generic AspLow is insufficient.	Work complete. Certification of mix needed from contractor.	chronf1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3224, Item 5031011A, Project Item Line Number 0480, Material Set 5031011A96, Material 0402SLPMSL - Plant Mix for Surface Leveling, Acceptance Action Generic AspSL is insufficient.	Work complete. Certification of mix needed from contractor.	chronf1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3224, Item 7021314, Project Item Line Number 0490, Material Set 702131496, Material 0501CCB1 - Concrete, Class B-1 No Air, Acceptance Action Generic 0501CCB1 is insufficient.	Work complete. 28 day break results needed from contractor.	chronf1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3224, Item 7032003, Project Item Line Number 0510, Material Set 703200396, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Work complete. 28 day break results needed from contractor.	chronf1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3224, Item 7034215, Project Item Line Number 0520, Material Set 703421596, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Work complete. Pending 28 day cylinder breaks.	chronf1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3224, Item 7034215, Project Item Line Number 0800, Material Set 703421596, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Work complete. Sample record left unauthorized in order to correct facility selection. Testing is complete.	chronf1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3224, Item 7034222, Project Item Line Number 0530, Material Set 703422296, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	Work complete. Pending 28 day cylinder breaks.	chronf1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3224, Item 7040113, Project Item Line Number 0810, Material Set 704011396, Material 1039ERBCT3 - Type III Epoxy Resin for Conc Patch Cmp, Acceptance Action Generic 1039ERBCT3 is insufficient.	Work complete. Cert needed from contractor.	chronf1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3224, Item 7040113, Project Item Line Number 0620, Material Set 704011396, Material 1039ERBCT3 - Type III Epoxy Resin for Conc Patch Cmp, Acceptance Action Generic 1039ERBCT3 is insufficient.	Work complete. Cert needed from contractor.	chronf1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3224, Item 7040113, Project Item Line Number 0720, Material Set 704011396, Material 1039ERBCT3 - Type III Epoxy Resin for Conc Patch Cmp, Acceptance Action Generic 1039ERBCT3 is insufficient.	Work complete. Cert needed from contractor.	chronf1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-H04, Contract Project J9S3224, Project Item Line Number 0130, Contract Line Item Number 0130, Item 6113020, Minor Item.	Pending change order. Due to condition of roadway ditches at Br. N02871, Type 2 Rock Blanket was required instead of Type 2 Ditch Liner.	chronf1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-H04, Contract Project J9S3224, Project Item Line Number 0140, Contract Line Item Number 0140, Item 6113040, Minor Item.	Pending change order. Due to condition of roadway ditches at Br. N02871, Type 2 Rock Blanket was required instead of Type 2 Ditch Liner.	chronf1	Overridden
Estimate Exception Type: Item Overrun: Contract 191213-H04, Contract Project J9S3224, Project Item Line Number 0290, Item 6224010, Minor Item.	Pending change order. Additional milling required on Br. A8747 due to existing road grade.	chronf1	Overridden



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Note: Posted Q	uantities a	and Value	s are ba	ased on Re	port Generated date and can differ from the posted amou	unt at the t	ime the E	stimate was	Genera	ted.			
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)	
191213-H04	J9S3224	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$18,500.00	\$18,500.00	
		0001	0020	2064000	POROUS BACKFILL	143.00	8.00	151.00	CUYD	151.00	\$85.00	\$12,835.00	
		0001	0030	2079909	MISC.MODIFIED LINEAR GRADING CL 2	22.80	0.00	22.80	STA	19.40	\$2,400.00	\$46,560.00	
		0001	0040	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	523.30	0.00	523.30	SQYD	487.00	\$30.00	\$14,610.00	
		0001	0050	3049910	MISC.TYPE 1 OR TYPE 5 AGGR BASE	139.60	0.00	139.60	TONS	100.80	\$48.00	\$4,838.40	
		0001	0060	3105002	GRAVEL (A) OR CRUSHED STONE (B)	318.00 0.0	0.00	318.00	TONS	268.00	\$35.00	\$9,380.00	
		0001	0070	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	912.70	0.00	912.70	TONS	529.90	\$90.00	\$47,691.00	
		0001	0080	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	216.40	0.00	216.40	TONS	210.30	\$90.00	\$18,927.00	
		0001	0090	4029905	MISC.OPTIONAL PAVEMENT	320.00	0.00	320.00	SQYD	320.00	\$58.00	\$18,560.00	
		0001	0100	4071005	TACK COAT	587.00	0.00	587.00	GAL	441.00	\$3.50	\$1,543.50	
		0001	0110	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	1,036.00	0.00	1,036.00	CUYD	422.00	\$36.00	\$15,192.00	
		0001		6096042		1,036.00	0.00	1,036.00	CUYD	422.00	\$18.00	\$7,596.00	
		0001	0130	6113020	FURNISHING TYPE 2 ROCK BLANKET	1,172.00	0.00	1,172.00	CUYD	1,286.00	\$38.00	\$48,868.00	
		0001	0140	6113040	PLACING TYPE 2 ROCK BLANKET	1,172.00	0.00	1,172.00	CUYD	1,286.00	\$13.00	\$16,718.00	
		0001	0150	6149902	MISC.18 IN FLAP GATE	1.00	0.00	1.00	EA	1.00	\$850.00	\$850.00	
		0001	0160	6149902	MISC.24 IN FLAP GATE	3.00	0.00	3.00	EA	3.00	\$1,000.00	\$3,000.00	
		0001	0170	6149902	MISC.30 IN FLAP GATE	1.00	0.00	1.00	EA	1.00	\$1,200.00	\$1,200.00	
		0001	0001 0180	0180	6149902	MISC.36 IN FLAP GATE		4.00 0.00		EA	4.00	\$1,350.00	\$5,400.00
		0001	0190	6161005	CONSTRUCTION SIGNS	602.00	-90.00	SQFT		512.00	\$8.00 \$35.00	\$4,096.00	
		0001	0200	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	8.00	16.00	EA	16.00		\$560.00	
		0001	0210	6161009	FLAG ASSEMBLY	4.00	4.00	8.00	EA	8.00	\$20.00	\$160.00	
		0001	0220	6161030	TYPE III MOVEABLE BARRICADE	12.00	0.00	12.00	EA	12.00	\$125.00	\$1,500.00	
		0001	0230	6161052	WARNING LIGHT, TYPE B	24.00	0.00	24.00	EA	24.00	\$65.00	\$1,560.00	
	C	0001 02	0240	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00	
		0001	0250	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$105,000.00	\$0.00	
		0001	0251	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$87,612.00	\$87,612.00	
		0001	0260	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	4,227.00	0.00	4,227.00	LF	3,235.00	\$0.50	\$1,617.50	
		0001	0270	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	4,215.00	0.00	4,215.00	LF	1,620.00	\$0.50	\$810.00	
		0001	0280	6207001	PAVEMENT MARKING REMOVAL	7,068.00	0.00	7,068.00	LF	6,059.00	\$0.50	\$3,029.50	
		0001	0290	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	285.00	222.00	507.00	SQYD	724.00	\$15.00	\$10,860.00	
		0001	0300	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	5,422.00	0.00	5,422.00	SQYD	3,443.00	\$3.00	\$10,329.00	
		0001	0310	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$20,000.00	\$20,000.00	
		0001	0320	7250418	18 IN. PIPE GROUP C	77.00	0.00	77.00	LF	77.00	\$45.00	\$3,465.00	
		0001	0330	7250424	24 IN. PIPE GROUP C	240.00	0.00	240.00	LF	240.00	\$50.00	\$12,000.00	
		0001	0340	7250430	30 IN. PIPE GROUP C	85.00	0.00	85.00	LF	85.00	\$60.00	\$5,100.00	
		0001	0350	7250436	36 IN. PIPE GROUP C	388.00	0.00	388.00	LF	388.00	\$62.00	\$24,056.00	
		0001	0360	8051000A	SEEDING - COOL SEASON MIXTURES	1.00	0.00	1.00	ACRE	0.90	\$3,900.00	\$3,510.00	
		0001	0370	8061005	ROCK DITCH CHECK	188.00	0.00	188.00	LF	0.00	\$15.00	\$0.00	
		0001	0380	8061016	SEDIMENT REMOVAL	42.00	0.00	42.00	CUYD	0.00	\$5.00	\$0.00	
		0001	0390	8061017	TEMPORARY SEEDING AND MULCHING	1.00	0.00	1.00	ACRE	0.00	\$800.00	\$0.00	
		0001	0400	8061019	SILT FENCE	2,349.00	0.00	2,349.00	LF	865.00	\$3.00	\$2,595.00	
		0001	0410	8061050	TYPE C BERM	676.00	0.00	676.00	LF	92.00	\$8.50	\$782.00	
		0040	0420	9031270A	2 IN. PSST POST - 12 GA.	236.00	0.00	236.00	LF	229.00	\$7.00	\$1,603.00	
		0040	0430	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	147.00	0.00	147.00	LF	147.00	\$12.00	\$1,764.00	
		0040	0440	9035004A	SH-FLAT SHEET	9.00	0.00	9.00	SQFT	9.00	\$18.00	\$162.00	



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Note: Posted Q	Posted Quantities and Values are based on Rep				port Generated date and can differ from the posted amou	unt at the t	ime the E	stimate was	Genera	ited.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-H04	J9S3224	0040	0450	9035069A	SHF-FLAT SHEET FLUORESCENT	144.00	0.00	144.00	SQFT	144.00	\$18.00	\$2,592.00
		0070	0460	2061000	CLASS 1 EXCAVATION	60.00	31.00	91.00	CUYD	91.00	\$40.00	\$3,640.00
		0070	0470	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$20,000.00	\$20,000.00
		0070	0480	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	111.00	0.00	111.00	SQYD	111.00	\$135.00	\$14,985.00
		0070	0490	7021314	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	216.00	185.00	401.00	LF	401.00	\$125.00	\$50,125.00
		0070	0500	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.00
		0070	0510	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	31.00	0.00	31.00	CUYD	31.00	\$980.00	\$30,380.00
		0070	0520	7034215	SAFETY BARRIER CURB	139.00 0.00	0.00 139.00	LF	139.00	\$105.00	\$14,595.00	
		0070	0530	7034222	SLAB ON CONCRETE BEAM	156.00	0.00	156.00	SQYD	156.00	\$430.00	\$67,080.00
		0070	0540	7056065	17 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	152.00	0.00	152.00	LF	152.00	\$285.00	\$43,320.00
		0070	0550	7123610	SLAB DRAIN	10.00	0.00	10.00	EA	10.00	\$220.00	\$2,200.00
		0070	0560	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,400.00	\$2,800.00
		0070	0570	7161000	PLAIN NEOPRENE BEARING PAD	6.00	0.00	6.00	EA	6.00	\$180.00	\$1,080.00
		0073	0580	2169901	MISC.Removal of Existing Superstructure	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.00
		0073	0590	7034212	SLAB ON STEEL	215.00	0.00	215.00	SQYD	215.00	\$450.00	\$96,750.00
		0073	0600	7034215	SAFETY BARRIER CURB	145.00	0.00	145.00	LF	145.00	\$100.00	\$14,500.00
		0073	0610	7040101	SUBSTRUCTURE REPAIR (FORMED)	20.00	0.00	20.00	SQFT	2.00	\$345.00	\$690.00
		0073	0620	7040113	CLEANING AND EPOXY COATING	499.00	0.00	499.00	SQFT	499.00	\$11.00	\$5,489.00
		0073	0630	7121111	FABRICATED STRUCTURAL LOW ALLOY STEEL (I-BEAM)	24,100.00	0.00	24,100.00	LB	24,100.00	\$2.30	\$55,430.00
					A709, GRADE 50							
		0073	0640	7123610		14.00	0.00	14.00	EA	14.00	\$220.00	\$3,080.00
		0073	0650	7129901	MISC.Galvanizing Structural Steel	1.00	0.00	1.00	LS	1.00	\$16,500.00	\$16,500.00
		0073		7161002	LAMINATED NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$320.00	\$2,560.00
		0074 0	0670	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	8.00	0.00	8.00	EA	8.00	\$1,300.00	\$10,400.00
			0680	2169901	MISC.Removal of Existing Superstructure	1.00 253.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.00
		0074	0690	7034212	SLAB ON STEEL SAFETY BARRIER CURB SUBSTRUCTURE REPAIR (FORMED)		0.00	253.00	SQYD	253.00	\$445.00	\$112,585.00
		0074	0700	7034215			0.00	170.00	LF	170.00	\$100.00	\$17,000.00
		0074	0710	7040101			0.00	20.00	SQFT	10.00	\$350.00	\$3,500.00
		0074	0720	7040113	CLEANING AND EPOXY COATING	499.00	0.00	499.00	SQFT	499.00	\$11.00	\$5,489.00
		0074	0730	7121111	FABRICATED STRUCTURAL LOW ALLOY STEEL (I-BEAM) A709, GRADE 50	28,030.00	0.00	28,030.00	LB	28,030.00	\$2.25	\$63,067.50
		0074	0740	7123610	SLAB DRAIN	14.00	0.00	14.00	EA	14.00	\$220.00	\$3,080.00
		0074	0750	7129901	MISC.Galvanizing Structural Steel	1.00	0.00	1.00	LS	1.00	\$18,000.00	\$18,000.00
		0074	0760	7161002	LAMINATED NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$320.00	\$2,560.00
		0074	0770	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	8.00	0.00	8.00	EA	8.00	\$1,300.00	\$10,400.00
		0075	0780	2169901	MISC.Removal of Existing Superstructure	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.00
		0075	0790	7034212	SLAB ON STEEL	198.00	0.00	198.00	SQYD	198.00	\$465.00	\$92,070.00
		0075	0800	7034215	SAFETY BARRIER CURB	133.00	0.00	133.00	LF	133.00	\$105.00	\$13,965.00
		0075	0810	7040113	CLEANING AND EPOXY COATING	499.00	0.00	499.00	SQFT	499.00	\$11.00	\$5,489.00
		0075	0820	7121111	FABRICATED STRUCTURAL LOW ALLOY STEEL (I-BEAM) A709, GRADE 50	22,010.00	0.00	22,010.00	LB	22,010.00	\$2.35	\$51,723.50
		0075	0830	7123610	SLAB DRAIN	12.00	0.00	12.00	EA	12.00	\$220.00	\$2,640.00
		0075	0840	7129901	MISC.Galvanizing Structural Steel	1.00	0.00	1.00	LS	1.00	\$14,500.00	\$14,500.00
		0075	0850	7161002	LAMINATED NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$380.00	\$3,040.00
		0075	0860	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	8.00	0.00	8.00	EA	8.00	\$1,300.00	\$10,400.00
		0001	5001	6189901	MISC.Contract Bond. Mobilization was adjusted for Contract Bond.	0.00	1.00	1.00	LS	1.00	\$17,388.00	\$17,388.00
		0073	5002	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	0.00	1.00	1.00	CUYD	1.00	\$1,050.00	\$1,050.00
		0073	5003	7101000	REINFORCING STEEL (EPOXY COATED)	0.00	50.00	50.00	LB	50.00	\$1.50	\$75.00
		0075	5004	7040101	SUBSTRUCTURE REPAIR (FORMED)	0.00	3.00	3.00	SQFT	3.00	\$350.00	\$1,050.00



Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					port Generated date and can differ from the posted amou							
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-H04	Project J9	53224 - Tot	al Value I	Posted to Da	te as of Report Generated Date							\$1,452,707.90
	J9S3224B	0001	0870	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$9,500.00	\$9,500.00
		0001	0880	2064000	POROUS BACKFILL	72.00	17.00	89.00	CUYD	89.00	\$90.00	\$8,010.00
		0001	0890	2079909	MISC.MODIFIED LINEAR GRADING CL 2	10.10	0.00	10.10	STA	10.10	\$2,600.00	\$26,260.00
		0001	0900	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	96.70	-25.50	71.20	SQYD	71.20	\$50.00	\$3,560.00
		0001	0910	3049910	MISC.TYPE 1 OR TYPE 5 AGGR BASE	61.40	0.00	61.40	TONS	61.40	\$48.00	\$2,947.20
		0001	0920	3105002	GRAVEL (A) OR CRUSHED STONE (B)	146.00	0.00	146.00	TONS	146.00	\$35.00	\$5,110.00
		0001	0930	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	399.00	111.30	510.30	TONS	510.30	\$90.00	\$45,927.00
		0001	0940	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	96.90	0.00	96.90	TONS	96.90	\$90.00	\$8,721.00
		0001	0950	4071005	TACK COAT	249.00	0.00	249.00	GAL	249.00	\$3.50	\$871.50
		0001	0960	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	794.00	-76.00	718.00	CUYD	718.00	\$35.00	\$25,130.00
		0001	0970	6096042	PLACING TYPE 2 ROCK DITCH LINER	794.00	-76.00	718.00	CUYD	718.00	\$15.00	\$10,770.00
		0001	0980	6113020	FURNISHING TYPE 2 ROCK BLANKET	610.00	-11.00	599.00	CUYD	599.00	\$38.00	\$22,762.00
		0001	0990	6113040	PLACING TYPE 2 ROCK BLANKET	610.00	-11.00	599.00	CUYD	599.00	\$15.00	\$8,985.00
		0001	1000	6149902	MISC.24 IN FLAP GATE	3.00	0.00	3.00	EA	3.00	\$1,000.00	\$3,000.00
		0001	1010	6149902	MISC.36 IN FLAP GATE	2.00	0.00	2.00	EA	2.00	\$1,200.00	\$2,400.00
			1020	6161005	CONSTRUCTION SIGNS	410.00	-184.00	226.00	SQFT	226.00	\$8.00	\$1,808.00
		0001	1020	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	0.00	8.00	EA	8.00	\$35.00	\$1,800.00
		0001										
		0001	1040	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	4.00	\$20.00	\$80.00
		0001	1050	6161030	TYPE III MOVEABLE BARRICADE	12.00	6.00	18.00	EA	18.00	\$125.00	\$2,250.00
		0001	1060	6161052	WARNING LIGHT, TYPE B	24.00	-12.00	12.00	EA	12.00	\$55.00	\$660.00
		0001	1070	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00
		0001	1080	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$55,000.00	\$55,000.00
		0001	1090	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,870.00	1,343.00	3,213.00	LF	3,213.00	\$1.00	\$3,213.00
		0001	1100	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,088.00	2,098.00	3,186.00	LF	3,186.00	\$1.00	\$3,186.00
		0001	1110	6207001	PAVEMENT MARKING REMOVAL	6,978.00	-573.00	6,405.00	LF	6,405.00	\$0.50	\$3,202.50
		0001	1120	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	203.00	-37.00	166.00	SQYD	166.00	\$15.00	\$2,490.00
		0001	1130	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	3,621.00	-386.00	3,235.00	SQYD	3,235.00	\$2.50	\$8,087.50
		0001	1140	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$9,500.00	\$9,500.00
		0001	1150	7250424	24 IN. PIPE GROUP C	219.00	30.00	249.00	LF	249.00	\$55.00	\$13,695.00
		0001	1160	7250436	36 IN. PIPE GROUP C	148.00	0.00	148.00	LF	148.00	\$68.00	\$10,064.00
		0001	1170	8051000A	SEEDING - COOL SEASON MIXTURES	1.00	0.00	1.00	ACRE	1.00	\$3,900.00	\$3,900.00
		0001	1180	8061005	ROCK DITCH CHECK	94.00	-94.00	0.00	LF	0.00	\$15.00	\$0.00
		0001	1190	8061016	SEDIMENT REMOVAL	14.00	-14.00	0.00	CUYD	0.00	\$5.00	\$0.00
		0001	1200	8061017	TEMPORARY SEEDING AND MULCHING	1.00	-1.00	0.00	ACRE	0.00	\$800.00	\$0.00
		0001	1210	8061019	SILT FENCE	522.00	-422.00	100.00	LF	100.00	\$3.50	\$350.00
		0001	1220	8061050	TYPE C BERM	365.00	-286.00	79.00	LF	79.00	\$6.50	\$513.50
		0040	1230	9031270A	2 IN. PSST POST - 12 GA.	142.00	-21.00	121.00	LF	121.00	\$7.00	\$847.00
		0040	1240	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	78.00	0.00	78.00	LF	78.00	\$12.00	\$936.00
		0040	1250	9035004A	SH-FLAT SHEET	18.00	0.00	18.00	SQFT	18.00	\$18.00	\$324.00
		0040	1260	9035069A	SHF-FLAT SHEET FLUORESCENT	72.00	0.00	72.00	SQFT	72.00	\$18.00	\$1,296.00
		0070	1270	2061000		60.00	25.00	85.00	CUYD	85.00	\$30.00	\$2,550.00
		0070	1280	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$20,000.00	\$20,000.00
		0070	1290		BRIDGE APPROACH SLAB (MINOR ROAD)	111.00	0.00	111.00	SQYD	111.00	\$130.00	\$14,430.00
		0070	1300	7021314	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	196.00	121.00	317.00	LF	317.00	\$120.00	\$38,040.00



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
191213-H04	J9S3224B	0070	1310	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.00
		0070	1320	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	31.00	0.00	31.00	CUYD	31.00	\$980.00	\$30,380.00
		0070	1330	7034215	SAFETY BARRIER CURB	139.00	0.00	139.00	LF	139.00	\$100.00	\$13,900.00
		0070	1340	7034222	SLAB ON CONCRETE BEAM	156.00	0.00	156.00	SQYD	156.00	\$450.00	\$70,200.00
		0070	1350	7056065	17 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	152.00	0.00	152.00	LF	152.00	\$285.00	\$43,320.00
		0070	1360	7123610	SLAB DRAIN	10.00	0.00	10.00	EA	10.00	\$220.00	\$2,200.00
		0070	1370	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.00
		0070	1380	7161000	PLAIN NEOPRENE BEARING PAD	6.00	0.00	6.00	EA	6.00	\$200.00	\$1,200.00
		0071	1390	2061000	CLASS 1 EXCAVATION	50.00	-12.00	38.00	CUYD	38.00	\$30.00	\$1,140.00
		0071	1400	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.00
		0071	1410	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	113.00	0.00	113.00	SQYD	113.00	\$130.00	\$14,690.00
		0071	1420	7021314	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	176.00	193.00	369.00	LF	369.00	\$120.00	\$44,280.00
		0071	1430	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.00
		0071	1440	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	28.80	0.00	28.80	CUYD	28.80	\$1,050.00	\$30,240.00
		0071	1450	7034215	SAFETY BARRIER CURB	107.00	0.00	107.00	LF	107.00	\$105.00	\$11,235.00
		0071	1460	7034222	SLAB ON CONCRETE BEAM	156.00	0.00	156.00	SQYD	156.00	\$450.00	\$70,200.00
		0071	1470	7056065	17 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	152.00	0.00	152.00	LF	152.00	\$285.00	\$43,320.00
		0071	1480	7123610	SLAB DRAIN	10.00	0.00	10.00	EA	10.00	\$220.00	\$2,200.00
		0071	1490	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.00
		0071	1500	7161000	PLAIN NEOPRENE BEARING PAD	6.00	0.00	6.00	EA	6.00	\$200.00	\$1,200.00
	Project J95	63224B - To	otal Value	e Posted to D	ate as of Report Generated Date							\$797,361.20
91213-H04 Ove	erall - Total V	alue Poste	d to Date	as of Repor	t Generated Date							\$2,250,069.10



Project: J9S3224

Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

ine. Imber	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0010	2022010	REMOVAL OF IMPROVEMENTS	9/15/20	9/16/20	0.25	LS	Br. A8747	243+57		248+55		
0030	2079909	MISC. GRADING	9/15/20	9/16/20	0.05	STA	Rounding correction	245+50				
				9/16/20	1.25	STA	Br. A8747 east	246+33		247+58		
				9/16/20	1.26	STA	Br. A8747 entrances	245+50		246+75		
				9/16/20	1.90	STA	Br. A8747 west	243+90		245+80		
0040	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	9/9/20	9/11/20	13.30	SQYD	Southwest of Br. A8747	245+10		245+60		
				9/11/20		SQYD		245+10		245+60		
				9/11/20		SQYD		246+53		247+3		
				9/11/20		SOYD	Northeast of Br A8747	246+53		247+3		
			9/15/20	9/16/20	0.02	SOYD		240+33		247+3		
0050	3049910	MISC. AGGREGATE FOR BASE	9/15/20	9/16/20	-0.01	TONS		244+21				
				9/16/20	7.74			246+53		247+47		SE 71-ft, NE 94-ft
				9/16/20	13.42	TONS	Br. A8747 west	244+21		245+60		SW 139-ft, NW 147-ft
0060	3105002	GRAVEL (A) OR CRUSHED STONE (B)	9/3/20	9/16/20	40.22	TONS	Br. N02871 entrances	633+13		634+92		Ticket quantity
			9/15/20	9/16/20	0.14	TONS	Rounding correction	245+50				
				9/16/20	87.90	TONS	Br. A8747 entrances	245+50		246+75		
0070	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BAS	9/10/20	9/16/20	26.62	TONS	Br. A8747	243+90		247+59		
0080	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	9/14/20	9/16/20	41.01	TONS	Br. A8747 East and West	243+90		247+59		Calculated quantity minus approach slab (separate item).
0090	4029905	MISC. BITUMINOUS PAVEMENT (SURF. LEVEL)	9/15/20	9/16/20	0.02	SQYD	Rounding correction.	634+66		633+80		
0100	4071005	TACK COAT	9/10/20	9/16/20	38.00	GAL	Br. A8747	243+90		247+59		
			9/14/20	9/16/20	-0.20	GAL	Rounding correction	243+90		247+59		
				9/16/20	51.00	GAL	Br A8747	243+90		247+59		
0110	6096020	FURN. TYPE 2 ROCK DITCH LINER	9/15/20	9/16/20	0.20	CUYD	Rounding correction	246+80				
0110	0000020	Torrest and the Errost Biron Enter	0/10/20	9/16/20		CUYD	5	246+80		247+20		40-ft x 27-ft
0120	6096042	PLACING TYPE 2 ROCK DITCH LINER	9/15/20	9/16/20		CUYD		246+80		247120		4010 X 2710
0120	0090042	PLACING TYPE 2 ROCK DITCH LINER	9/15/20				5			247+20		40-ft x 27-ft
				9/16/20	40.00	CUYD		246+80		247+20		40-ft x 27-ft
0130	6113020	FURNISHING TYPE 2 ROCK BLANKET	9/15/20	9/16/20		CUYD	5	246+33				
				9/16/20		CUYD		246+33		245+80		Total measurement all four corners of bridge.
				9/16/20	56.00	CUYD	Br. A8747 West	245+80				Measured minus previously partial payment quanti
				9/16/20	58.10	CUYD	Br. A8747 East	246+33				Measured minus previously partial payment quanti
0140	6113040	PLACING TYPE 2 ROCK BLANKET	9/15/20	9/16/20	0.10	CUYD	Rounding correction	246+33				
				9/16/20	15.70	CUYD	Br. A8747 rock drains	246+33		245+80		Total measurement all four corners of bridge.
				9/16/20	56.00	CUYD	Br. A8747 West	245+80				Measured minus previously partial payment quantit
				9/16/20	58.10	CUYD	Br. A8747 East	246+33				Measured minus previously partial payment quantit
0290	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	9/11/20	9/16/20	121.40	SQYD	West of Br. A8747	243+90		245+80		Four measurements: 5-ft x 21-ft, 36-ft x 7-ft, 14-ft x 10-ft x 5-ft
			9/14/20	9/16/20	-0.20	SQYD	Rounding correction.	246+84				
				9/16/20	162.50	SQYD	Br. A8747 East	246+84		247+59		
0300	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	9/15/20	9/16/20	0.10	SQYD	Rounding correction	245+80				
				9/16/20	23.60	SQYD	Br. A8747 rock drains	246+33		245+80		Total measurement all four corners of bridge.
				9/16/20	46.40	SQYD	Br. A8747 West Rock Blanket	245+80				Measured minus previously partial payment quanti
				9/16/20	49.40	SQYD	Br. A8747 East Rock Blanket	246+33				Measured minus previously partial payment quanti
				9/16/20	120.00	SQYD		246+80		247+20		incasured minus previously partial payment quanti
0360	00540004	SEEDING - COOL SEASON MIXTURES	9/15/20	9/16/20		ACRE		580+37		581+74		
0360	AUUUICUO	SEEDING - COOL SEASON MIXTURES	9/15/20	9/16/20		ACRE		245+50		246+75		
					0.20							
		2 IN. PSST POST - 12 GA.	9/15/20	9/16/20	49.00	LF		245+71.70		246+42.20		Object markers at all four corners of bridge.
0430	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	9/15/20	9/16/20	36.00	LF		245+71.70		246+42.20		Object markers at all four corners of bridge.
	9035069A	SHF-FLAT SHEET FLUORESCENT	9/15/20	9/16/20	36.00	SQFT		245+71.70		246+42.20		Object markers at all four corners of bridge.
0480	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	9/14/20	9/16/20	111.00	SQYD	Br. A8747	245+60		246+54		
0520	7034215	SAFETY BARRIER CURB	9/4/20	9/16/20	139.00	LF	Br. A8747	245+72		246+41		
0530	7034222	SLAB ON CONCRETE BEAM	9/15/20	9/16/20	8.00	SQYD	Br. A8747. 5% remaining payment for curing, sealing, and stripping forms.	245+80		246+33		
0620	7040113	CLEANING AND EPOXY COATING	9/9/20	9/11/20	499.00	SQFT	Br. N02851	528+32.60		529+5.31		
0720	7040113	CLEANING AND EPOXY COATING	9/10/20	9/16/20	499.00	SQFT	Br. N02861	580+63		581+48		

Project: J9S3224B

Line Number	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
1170	8051000A	SEEDING - COOL SEASON MIXTURES	9/15/20	9/16/20	0.50	ACRE	Br. A8802, Br. A8748 seeding acceptance	370+30		423+06		

The information below this line are details from Line Item agency views. No Agency View Details Exist



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
040	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		8	Jun 2, 2020	SYSTEM	(\$1,620.00)	
				8	Jun 2, 2020	SYSTEM	\$1,620.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$1,620.00)	
				9	Jun 16, 2020	SYSTEM	\$1,620.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				10	Jul 1, 2020	SYSTEM	(\$8,802.60)	
				10	Jul 1, 2020	SYSTEM	\$8,802.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
040 -	Total						\$0.00	
050	MISC. TYPE 1 OR TYPE 5 AGGR BASE	Material		8	Jun 2, 2020	SYSTEM	(\$1,105.92)	
				8	Jun 2, 2020	SYSTEM	\$1,105.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$1,105.92)	
				9	Jun 16, 2020	SYSTEM	\$1,105.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				10	Jul 1, 2020	SYSTEM	(\$1,105.92)	
				10	Jul 1, 2020	SYSTEM	\$1,105.92	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	- Total						\$0.00	
060	GRAVEL (A) OR CRUSHED STONE (B)	Material		8	Jun 2, 2020	SYSTEM	(\$1,190.00)	
				8	Jun 2, 2020	SYSTEM	\$1,190.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$1,190.00)	
				9	Jun 16, 2020	SYSTEM	\$1,190.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				10	Jul 1, 2020	SYSTEM	(\$1,190.00)	
				10	Jul 1, 2020	SYSTEM	\$1,190.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	- Total						\$0.00	
070	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Material		8	Jun 2, 2020	SYSTEM	(\$9,981.00)	
				8	Jun 2, 2020	SYSTEM	\$9,981.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 4 on the current



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
070	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Material						Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Other Item Adjustment	ACAD	8	Jun 2, 2020	chronf1	(\$191.30)	ACAD for 110.9 Tons of BB17-41.
				10	Jul 1, 2020	chronf1	(\$852.97)	ACAD for 329.65 Tons of BB17-41.
				13	Aug 17, 2020	chronf1	(\$1,320.15)	ACAD for 62.73 Tons of BB17-41.
				15	Sep 16, 2020	chronf1	(\$76.53)	ACAD for 26.62 Tons of BB17-41.
			ACAD - Tota	al			(\$2,440.95)	
	Other Item Adjustment - Total						(\$2,440.95)	
0070 -	Total						(\$2,440.95)	
080	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material		8	Jun 2, 2020	SYSTEM	(\$5,787.00)	
				8	Jun 2, 2020	SYSTEM	\$5,787.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	ACAD	8	Jun 2, 2020	chronf1	(\$116.80)	ACAD for 53.7 Tons of SL20-25.
				10	Jul 1, 2020	chronf1	(\$189.23)	ACAD for 58.0 Tons of SL20-25.
				10	Jul 1, 2020	chronf1	\$33.93	ACAD for -15.6 Tons of SL20-25. Overpayment was made on Estimate No. 8. Estimate No. 8 Price Index used for calculation 38.1 Tons should have been used for ACAD instead of 53.7 Tor (38.1 - 53.7 = -15.6).
				13	Aug 17, 2020	chronf1	(\$1,942.10)	ACAD for 73.19 Tons of SL20-25.
				15	Sep 16, 2020	chronf1	, ,	ACAD for 41.01 Tons of SL20-37.
			ACAD - Tota	al			(\$2,301.35)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)		OTHR		Sep 16, 2020	chronf1	(\$2,500.00)	Withheld pending performance of segregated areas under traffic
			OTHR - Tota	al			(\$2,500.00)	
	Other Item Adjustment - Total						(\$4,801.35)	
- 080	Total						(\$4,801.35)	
090	MISC. OPTIONAL PAVEMENT	Material		8	Jun 2, 2020	SYSTEM	(\$6,186.28)	
				8	Jun 2, 2020	SYSTEM	\$6,186.28	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	MISC. OPTIONAL PAVEMENT	Other Item Adjustment	ACAD	8	Jun 2, 2020	chronf1	(\$105.81)	ACAD for 106.66 SY (BB17-41 and SL20-25).
				10	Jul 1, 2020	chronf1	(\$155.75)	
				13	Aug 17, 2020	chronf1		ACAD for 106.66 SY.
			ACAD - Tota	ar			(\$1,528.33)	
	Other Item Adjustment - Total						(\$1,528.33)	
0090 -	Total						(\$1,528.33)	
0100	TACK COAT	Material		8	Jun 2, 2020	SYSTEM	(\$351.05)	
				8	Jun 2, 2020	SYSTEM	\$351.05	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user chronf1 overridding Payment Estimate Exception 7 on the current



Image: space	0100	TACK COAT			Number	Date	Ву			
Image: stand	0100	TACK COAT	Material							
Image: state in the state is a state									Payment Estimate.	
Image: stand					9		SYSTEM	(\$351.05)		
Image: stand					9		SYSTEM	\$351.05	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
Image: space of the					10		SYSTEM	(\$914.20)		
Image: state in the					10		SYSTEM	\$914.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
Image: state					11		SYSTEM	(\$914.20)		
Material - Total Vertual Solution Solution 0100 - Total 5000					11		SYSTEM	\$914.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
0100 Total Overrun 15 Sep 17. SVSTEM VSTEM (44.332.00) 0130 PURNISHING TYPE 2 ROCK BLANKET Overrun 15 Sep 17. SVSTEM SVSTEM (44.332.00) 0140 Overrun - Total Overrun - Total SVSTEM (44.332.00) This adjustment offsets the original system-generated Overrun Estimate Exception 11 on the curren Payment Estimate Esception 12 on the curren Payment Estimate Esception 10 on the curren Payment E				- Total				\$0.00		
1130 FURNISHING TYPE 2 ROCK BLANKET Overrun 15 Sep 17. 2020 SYSTEM (\$4,332.00) This adjustment offsets the original system-generated OV Payment Estimate Item Adjustment (0030) due to user of overriding Payment Estimate 0400 Overrun - Total Overrun - Total \$0.00 0130 PLACING TYPE 2 ROCK BLANKET Overrun \$15 Sep 17. 2020 SYSTEM \$4,332.00 This adjustment offsets the original system-generated OV Payment Estimate 0140 PLACING TYPE 2 ROCK BLANKET Overrun 15 Sep 17. 2020 SYSTEM \$1,482.00 0140 PLACING TYPE 2 ROCK BLANKET Overrun 15 Sep 17. 2020 SYSTEM \$1,482.00 0140 PLACING TYPE 2 ROCK BLANKET Overrun 15 Sep 17. 2020 SYSTEM \$1,482.00 0140 PLACING TYPE 2 ROCK BLANKET Overrun - Total 50.00 This adjustment offsets the original system-generated OV Payment Estimate Exception 12 on the current Payment Estimate Exception 12 on the current Payment Estimate Exception 12 on the current Payment Estimate Exception 13 on the current Payment Estimate This adjustment offsets the original system-generated OV Payment Estimate Exception 1 on the current Payment Estimate 0140 CONSTRUC		Material - Total						\$0.00		
Image: state in the	0100 -	Total						\$0.00		
$ \left \begin{array}{c c c c c c } & \left \begin{array}{c c c } & \left \begin{array}{c c c } & \left \begin{array}{c c } & \left \left \begin{array}{c c } & \left $	0130	FURNISHING TYPE 2 ROCK BLANKET	Overrun	Overrun	15		SYSTEM	(\$4,332.00)		
Overrun - TotalSourceSource0130 - TotalOverrun0SystemSy					15		SYSTEM	\$4,332.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user chronf1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
0130 - Total 9140 PLACING TYPE 2 ROCK BLANKET Overrun 15 Sep 17, 2020 SYSTEM (\$1,482.00) 0140 PLACING TYPE 2 ROCK BLANKET Overrun 15 Sep 17, 2020 SYSTEM \$1,482.00 This adjustment offsets the original system-generated OV Payment Estimate Item Adjustment (001) due to user choverridding Payment Estimate Exception 12 on the curren Payment Estimate. Overrun - Total Overrun - Total \$0.00 0140 - Total SYSTEM \$1,482.00 This adjustment offsets the original system-generated OV Payment Estimate. 0140 - Total CONSTRUCTION SIGNS Material 2 Mar 2, 2020 SYSTEM \$3,776.00 0140 - Total Total SYSTEM \$3,776.00 This adjustment offsets the original system-generated OV Payment Estimate Exception 1 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Payment				Overrun - T	otal			\$0.00		
0140 PLACING TYPE 2 ROCK BLANKET Overrun 15 Sep 17, 2020 SYSTEM (\$1,482.00) 15 Sep 17, 2020 SYSTEM \$1,482.00 This adjustment offsets the original system-generated OV Payment Estimate Exception 12 on the curren Payment Estimate 0140 - Total Overrun - Total S0.00 0140 - Total Verrun 12 Mar 2, 2020 SYSTEM (\$3,776.00) 0140 - Total - Total 2 Mar 2, 2020 SYSTEM \$3,776.00 This adjustment offsets the original system-generated OV Payment Estimate Exception 1 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Paym		Overrun - Total						\$0.00		
	0130 -	Total						\$0.00		
$ \left \begin{array}{c c c c c c } & \left \begin{array}{c c c c c } & \left \begin{array}{c c c c } & \left \begin{array}{c c c c } & \left \begin{array}{c c } & \left \left \begin{array}{c c } & \left \begin{array}{c c } & \left $	0140	PLACING TYPE 2 ROCK BLANKET	Overrun	Overrun	15		SYSTEM	(\$1,482.00)		
StoreStoreOverrun - TotalStoreStoreStore0140 - TotalStore <t< td=""><td></td><td></td><td></td><td></td><td>15</td><td></td><td>SYSTEM</td><td>\$1,482.00</td><td>This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user chronf1 overridding Payment Estimate Exception 12 on the current Payment Estimate.</td></t<>					15		SYSTEM	\$1,482.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user chronf1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
0140 - Total S0.00 0190 CONSTRUCTION SIGNS Material 2 Mar 2, 2020 SYSTEM (\$3,776.00) 2 Mar 2, 2020 SYSTEM \$3,776.00 This adjustment offsets the original system-generated OV Payment Estimate Item Adjustment (0005) due to user ch overridding Payment Estimate Exception 1 on the current Payment Estimate. • Total • Total • S0.00 Other Payment Estimate Item Adjustment (0005) due to user ch overridding Payment Estimate Exception 1 on the current Payment Estimate. Other Payment Estimate Item Adjustment Estimate Exception 1 on the current Payment Estimate. Other Payment Estimate Item Adjustment (0005) due to user ch overridding Payment Estimate. Other Payment Estimate Esception 1 on the current Payment Estimate. Other Payment Item Adjustment (0002) due to user ch overridding Payment Estimate. Other Payment Item Adjustment (0002) due to user ch overridding Payment Estimate. Other Payment Estimate Esception 3 on the current Payment Estimate. Other Payment Estimate. Soco				Overrun - T	otal			\$0.00		
0190 CONSTRUCTION SIGNS Material 2 Mar 2, 2020 SYSTEM (\$3,776.00) 2 Mar 2, 2020 SYSTEM \$3,776.00 This adjustment offsets the original system-generated OV Payment Estimate Item Adjustment (0005) due to user ch overriding Payment Estimate Estimate Exception 1 on the current Payment Estimate. - Total • Total • Total • Total • Subscription • OP • OP <td c<="" td=""><td></td><td>Overrun - Total</td><td></td><td></td><td></td><td></td><td></td><td>\$0.00</td><td></td></td>	<td></td> <td>Overrun - Total</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>\$0.00</td> <td></td>		Overrun - Total						\$0.00	
Advise Image: second	0140 -	- Total						\$0.00		
Advanced warm Advanced warm Material System	0190	CONSTRUCTION SIGNS	Material		2		SYSTEM	(\$3,776.00)		
Material - Total \$0.00 \$0.00 0190 - Total \$0.00 \$0.00 0200 ADVANCED WARNING RAIL SYSTEM Material 2 Mar 2, 2020 SYSTEM \$\$560.00 This adjustment offsets the original system-generated OV Payment Estimate Item Adjustment (0002) due to user ch overridding Payment Estimate Item Adjustment (0002) due to user ch overridding Payment Estimate. 3 Mar 17, 2020 SYSTEM \$\$\$60.00 \$\$\$					2		SYSTEM	\$3,776.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
0190 - Total \$0.00 0200 ADVANCED WARNING RAIL SYSTEM Material 2 Mar 2, 2020 SYSTEM (\$560.00) 2 Mar 3, 2020 SYSTEM \$560.00 This adjustment offsets the original system-generated OV Payment Estimate Item Adjustment (0002) due to user ch overridding Payment Estimate. 3 Mar 17, 2020 SYSTEM (\$560.00)				- Total				\$0.00		
0200 ADVANCED WARNING RAIL SYSTEM Material 2 Mar 2, 2020 SYSTEM (\$560.00) 2 Mar 3, 2020 SYSTEM \$S560.00 This adjustment offsets the original system-generated OV Payment Estimate Item Adjustment (0002) due to user ch overridding Payment Estimate. 3 Mar 17, 2020 SYSTEM \$\$560.00		Material - Total						\$0.00		
2020 2020	0190 -	Total						\$0.00		
2020 Payment Estimate Item Adjustment (0002) due to user ch overridding Payment Estimate Exception 3 on the current Payment Estimate. 3 Mar 17, 2020 SYSTEM (\$560.00)	0200	ADVANCED WARNING RAIL SYSTEM	Material		2		SYSTEM	(\$560.00)		
2020					2		SYSTEM	\$560.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
- Total (\$560.00)					3		SYSTEM	(\$560.00)		
(\$50.00)				- Total				(\$560.00)		
Material - Total (\$560.00)		Material - Total						(\$560.00)		
ADVANCED WARNING RAIL SYSTEM MaterialCredit 4 Apr 2, 2020 SYSTEM \$560.00		ADVANCED WARNING RAIL SYSTEM	MaterialCredit		4	Apr 2, 2020	SYSTEM			
- Total \$560.00				- Total				\$560.00		
MaterialCredit - Total \$560.00		MaterialCredit - Total						\$560.00		
		ADVANCED WARNING RAIL SYSTEM	Overrun	Overrun	2	Mar 2,	SYSTEM	(\$280.00)		



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0200	ADVANCED WARNING RAIL SYSTEM	Overrun	Overrun		2020			
				2	Mar 2, 2020	SYSTEM	\$280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 8 on the current Payment Estimate.
				3	Mar 17, 2020	SYSTEM	(\$280.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				3	Mar 17, 2020	SYSTEM	\$280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 5 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0200 ·	· Total						\$0.00	
0210	FLAG ASSEMBLY	Material		2	Mar 2, 2020	SYSTEM	(\$160.00)	
				2	Mar 2, 2020	SYSTEM	\$160.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	FLAG ASSEMBLY	Overrun	Overrun	2	Mar 2, 2020	SYSTEM	(\$80.00)	
				2	Mar 2, 2020	SYSTEM	\$80.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 9 on the current Payment Estimate.
				3	Mar 17, 2020	SYSTEM	(\$80.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				3	Mar 17, 2020	SYSTEM	\$80.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0210 ·	Total						\$0.00	
0240	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material		3	Mar 17, 2020	SYSTEM	(\$6,000.00)	
			- Total				(\$6,000.00)	
	Material - Total						(\$6,000.00)	
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	MaterialCredit		4	Apr 2, 2020	SYSTEM	\$6,000.00	
			- Total				\$6,000.00	
	MaterialCredit - Total						\$6,000.00	
0240 ·	MaterialCredit - Total							
	Total 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Other Item Adjustment	OTHR	9	Jun 16, 2020	chronf1	\$6,000.00 \$0.00 (\$283.25)	50% of payment withheld on this estimate pending retroreflectivity results.
	Total 4 IN. WHITE STANDARD WATERBORNE		OTHR	9 10		chronf1 chronf1	\$0.00	
	Total 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P		OTHR		2020 Jul 1,		\$0.00 (\$283.25)	Payment for 50% of posting that was previously withheld
	Total 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P		OTHR	10	2020 Jul 1, 2020 Sep 2,	chronf1	\$0.00 (\$283.25) \$283.25	results. Payment for 50% of posting that was previously withheld (retroreflectivity results accepted). 50% of payment withheld on this estimate pending retroreflectivity
	Total 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P		OTHR OTHR - Tota	10 14 15	2020 Jul 1, 2020 Sep 2, 2020 Sep 16,	chronf1 chronf1	\$0.00 (\$283.25) \$283.25 (\$525.50)	results. Payment for 50% of posting that was previously withheld (retroreflectivity results accepted). 50% of payment withheld on this estimate pending retroreflectivity results. Payment for 50% of posting that was previously withheld
	Total 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P			10 14 15	2020 Jul 1, 2020 Sep 2, 2020 Sep 16,	chronf1 chronf1	\$0.00 (\$283.25) \$283.25 (\$525.50) \$525.50	results. Payment for 50% of posting that was previously withheld (retroreflectivity results accepted). 50% of payment withheld on this estimate pending retroreflectivity results. Payment for 50% of posting that was previously withheld
0260	Total 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS			10 14 15	2020 Jul 1, 2020 Sep 2, 2020 Sep 16,	chronf1 chronf1	\$0.00 (\$283.25) \$283.25 (\$525.50) \$525.50 \$0.00	results. Payment for 50% of posting that was previously withheld (retroreflectivity results accepted). 50% of payment withheld on this estimate pending retroreflectivity results. Payment for 50% of posting that was previously withheld
0260	Total 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 0ther Item Adjustment - Total Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING			10 14 15 al	2020 Jul 1, 2020 Sep 2, 2020 Sep 16,	chronf1 chronf1	\$0.00 (\$283.25) \$283.25 (\$525.50) \$525.50 \$0.00 \$0.00	results. Payment for 50% of posting that was previously withheld (retroreflectivity results accepted). 50% of payment withheld on this estimate pending retroreflectivity results. Payment for 50% of posting that was previously withheld
0260 -	Total 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS Other Item Adjustment - Total Total 4 IN. YELLOW STANDARD	Adjustment	OTHR - Tota	10 14 15 al	2020 Jul 1, 2020 Sep 2, 2020 Sep 16, 2020 Jun 16,	chronf1 chronf1 chronf1	\$0.00 (\$283.25) \$283.25 (\$525.50) \$525.50 \$0.00 \$0.00	results. Payment for 50% of posting that was previously withheld (retroreflectivity results accepted). 50% of payment withheld on this estimate pending retroreflectivity results. Payment for 50% of posting that was previously withheld (retroreflectivity results accepted). 50% of payment withheld on this estimate pending retroreflectivity



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0270	4 IN. YELLOW STANDARD	Other Item	OTHR		2020			results.
	WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Adjustment		15	Sep 16, 2020	chronf1	\$272.50	Payment for 50% of posting that was previously withheld (retroreflectivity results accepted).
			OTHR - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0270 ·	Total						\$0.00	
0290	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	Overrun	Overrun	13	Aug 17, 2020	SYSTEM	(\$2,329.50)	
				13	Aug 17, 2020	SYSTEM	\$2,329.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				14	Sep 2, 2020	SYSTEM	(\$2,329.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				14	Sep 2, 2020	SYSTEM	\$2,329.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				15	Sep 17, 2020	SYSTEM	(\$3,255.00)	
				15	Sep 17, 2020	SYSTEM	\$1,821.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) due to user chronf1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				15	Sep 17, 2020	SYSTEM	\$1,434.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user chronf1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			Overrun - To	otal			\$0.00	
	Overrun - Total						AA AA	
							\$0.00	
0290 ·	Total						\$0.00 \$0.00	
0290 - 0360	Total SEEDING - COOL SEASON MIXTURES	Material		8	Jun 2, 2020	SYSTEM		
		Material		8		SYSTEM SYSTEM	\$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
		Material	- Total		2020 Jun 2,		\$0.00 (\$780.00)	Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 15 on the current
		Material	- Total		2020 Jun 2,		\$0.00 (\$780.00) \$780.00	Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 15 on the current
0360	SEEDING - COOL SEASON MIXTURES	Material	- Total		2020 Jun 2,		\$0.00 (\$780.00) \$780.00 \$0.00	Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 15 on the current
0360 0360 -	SEEDING - COOL SEASON MIXTURES	Material	- Total		2020 Jun 2,		\$0.00 (\$780.00) \$780.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 15 on the current
	SEEDING - COOL SEASON MIXTURES Material - Total Total		- Total	8	2020 Jun 2, 2020 May 19, 2020	SYSTEM	\$0.00 (\$780.00) \$780.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 15 on the current
0360 0360 -	SEEDING - COOL SEASON MIXTURES Material - Total Total SILT FENCE		- Total	8 7	2020 Jun 2, 2020 May 19, 2020 May 19,	SYSTEM SYSTEM	\$0.00 (\$780.00) \$780.00 \$0.00 \$0.00 (\$1,635.00) \$1,635.00	Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
0360 0360 -	SEEDING - COOL SEASON MIXTURES Material - Total Total			8 7	2020 Jun 2, 2020 May 19, 2020 May 19,	SYSTEM SYSTEM	\$0.00 (\$780.00) \$780.00 \$0.00 \$0.00 (\$1,635.00) \$1,635.00	Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
0360 - 0360 - 0400	SEEDING - COOL SEASON MIXTURES Material - Total Total SILT FENCE Material - Total Total	Material		8 7	2020 Jun 2, 2020 May 19, 2020 May 19,	SYSTEM SYSTEM	\$0.00 (\$780.00) \$780.00 \$0.00 \$0.00 (\$1,635.00) \$1,635.00	Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
0360 - 0360 - 0400 -	SEEDING - COOL SEASON MIXTURES Material - Total Total SILT FENCE Material - Total	Material		8 7 7 13	2020 Jun 2, 2020 May 19, 2020 May 19, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 (\$780.00) \$780.00 \$0.00 \$0.00 (\$1,635.00) \$1,635.00 \$1,635.00 \$0.00 \$0.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
0360	SEEDING - COOL SEASON MIXTURES Material - Total Total SILT FENCE Material - Total Total	Material		8 7 7 7	2020 Jun 2, 2020 May 19, 2020 May 19, 2020 Aug 17,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$780.00) \$780.00 \$0.00 \$0.00 (\$1,635.00) \$1,635.00 \$1,635.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
0360 - 0360 - 0400 -	SEEDING - COOL SEASON MIXTURES Material - Total Total SILT FENCE Material - Total Total	Material		8 7 7 13	2020 Jun 2, 2020 May 19, 2020 May 19, 2020 Aug 17, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 (\$780.00) \$780.00 \$0.00 \$0.00 (\$1,635.00) \$1,635.00 \$1,635.00 \$0.00 \$0.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
0360 - 0360 - 0400 -	SEEDING - COOL SEASON MIXTURES Material - Total Total SILT FENCE Material - Total Total	Material	- Total	8 7 7 13	2020 Jun 2, 2020 May 19, 2020 May 19, 2020 Aug 17, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 (\$780.00) \$780.00 \$0.00 \$0.00 (\$1,635.00) \$1,635.00 \$0.00 \$0.00 (\$782.00) \$782.00	Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
0360 - 0400 - 0410 -	SEEDING - COOL SEASON MIXTURES Material - Total Total SILT FENCE Material - Total Total TYPE C BERM	Material	- Total	8 7 7 13	2020 Jun 2, 2020 May 19, 2020 May 19, 2020 Aug 17, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 (\$780.00) \$780.00 \$0.00 \$0.00 (\$1,635.00) \$1,635.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$782.00)	Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
0360 0360 0400 0400 0410	SEEDING - COOL SEASON MIXTURES Material - Total Total Naterial - Total SILT FENCE Material - Total TYPE C BERM	Material	- Total	8 7 7 13 13	2020 Jun 2, 2020 May 19, 2020 May 19, 2020 Aug 17, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 (\$780.00) \$780.00 \$0.00 \$0.00 (\$1,635.00) \$1,635.00 \$0.00 \$0.00 \$0.00 \$782.00 \$782.00	Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
0360 - 0400 - 0410 - 0410 -	SEEDING - COOL SEASON MIXTURES Material - Total Total Naterial - Total SILT FENCE Material - Total TYPE C BERM Material - Total	Material	- Total	8 7 7 13 13	2020 Jun 2, 2020 May 19, 2020 May 19, 2020 Aug 17, 2020 Aug 17, 2020 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$780.00) \$780.00 \$0.00 \$0.00 (\$1,635.00) \$1,635.00 (\$1,635.00) \$1,635.00 (\$782.00) \$782.00 \$782.00 \$782.00 \$782.00	Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0460	Overrun - Total						\$0.00	
0460 -	Total						\$0.00	
0480	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		15	Sep 17, 2020	SYSTEM	(\$14,985.00)	
				15	Sep 17, 2020	SYSTEM	\$14,985.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	BRIDGE APPROACH SLAB (MINOR ROAD)	Other Item Adjustment		15	Sep 16, 2020	chronf1	(\$206.04)	ACAD for 111 SY.
			ACAD - Tota	al			(\$206.04)	
	Other Item Adjustment - Total						(\$206.04)	
0480 -	Total						(\$206.04)	
0490	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Material		13	Aug 17, 2020	SYSTEM	(\$50,125.00)	
				13	Aug 17, 2020	SYSTEM	\$50,125.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				14	Sep 2, 2020	SYSTEM	(\$50,125.00)	
				14	Sep 2, 2020	SYSTEM	\$50,125.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chron11 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				15	Sep 17, 2020	SYSTEM	(\$50,125.00)	
				15	Sep 17, 2020	SYSTEM	\$50,125.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Overrun	Overrun	13	Aug 17, 2020	SYSTEM	(\$23,125.00)	
				13	Aug 17, 2020	SYSTEM	\$23,125.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 7 on the current Payment Estimate.
				14	Sep 2, 2020	SYSTEM	(\$23,125.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				14	Sep 2, 2020	SYSTEM	\$23,125.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 7 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0490 -	Total						\$0.00	
0510	CLASS B CONCRETE (SUBSTRUCTURE)	Material		14	Sep 2, 2020	SYSTEM	(\$30,380.00)	
				14	Sep 2, 2020	SYSTEM	\$30,380.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				15	Sep 17, 2020	SYSTEM	(\$30,380.00)	
				15	Sep 17, 2020	SYSTEM	\$30,380.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
							00.00	
0510 -	Total						\$0.00	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0520	SAFETY BARRIER CURB	Material	1350	15	Sep 17, 2020	SYSTEM	\$14,595.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0520 -	Total						\$0.00	
0530	SLAB ON CONCRETE BEAM	Material		14	Sep 2, 2020	SYSTEM	(\$63,640.00)	
				14	Sep 2, 2020	SYSTEM	\$63,640.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				15	Sep 17, 2020	SYSTEM	(\$67,080.00)	
				15	Sep 17, 2020	SYSTEM	\$67,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user chronf1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0530 -	Total						\$0.00	
0590	SLAB ON STEEL	Material		6	May 4, 2020	SYSTEM	(\$33,750.00)	
				6	May 5, 2020	SYSTEM	\$33,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				7	May 19, 2020	SYSTEM	(\$91,800.00)	
				7	May 19, 2020	SYSTEM	\$91,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				8	Jun 2, 2020	SYSTEM	(\$96,750.00)	
				8	Jun 2, 2020	SYSTEM	\$96,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user chronf1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$96,750.00)	
				9	Jun 16, 2020	SYSTEM	\$96,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				10	Jul 1, 2020	SYSTEM	(\$96,750.00)	
				10	Jul 1, 2020	SYSTEM	\$96,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0590 -	Total						\$0.00	
0600	SAFETY BARRIER CURB	Material		8	Jun 2, 2020	SYSTEM	(\$14,500.00)	
				8	Jun 2, 2020	SYSTEM	\$14,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user chronf1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				10	Jul 1, 2020	SYSTEM	(\$14,500.00)	
				10	Jul 1, 2020	SYSTEM	\$14,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0600	Material - Total						\$0.00	
0600 -	Total						\$0.00	
0610	SUBSTRUCTURE REPAIR (FORMED)	Material		7	May 19, 2020	SYSTEM	(\$690.00)	
				7	May 19, 2020	SYSTEM	\$690.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user chronf1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0610 -	· Total						\$0.00	
0620	CLEANING AND EPOXY COATING	Material		15	Sep 17, 2020	SYSTEM	(\$5,489.00)	
				15	Sep 17, 2020	SYSTEM	\$5,489.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user chronf1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0620 -	Total						\$0.00	
0630	FABRICATED STRUCTURAL LOW ALLOY STEEL (I-BEAM) A709, GRADE 50	Material		6	May 4, 2020	SYSTEM	(\$55,430.00)	
				6	May 5, 2020	SYSTEM	\$55,430.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				7	May 19, 2020	SYSTEM	(\$55,430.00)	
				7	May 19, 2020	SYSTEM	\$55,430.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user chronf1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0630 -	Total						\$0.00	
0670	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	Material		7	May 19, 2020	SYSTEM	(\$10,400.00)	
				7	May 19, 2020	SYSTEM	\$10,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 10 on the current
								Payment Estimate.
				8	Jun 2, 2020	SYSTEM	(\$10,400.00)	Payment Esumate.
				8		SYSTEM SYSTEM	(\$10,400.00) \$10,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					2020 Jun 2,			This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 14 on the current
				8	2020 Jun 2, 2020 Jun 16,	SYSTEM	\$10,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 14 on the current
				8 9	2020 Jun 2, 2020 Jun 16, 2020 Jun 16,	SYSTEM SYSTEM	\$10,400.00 (\$10,400.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 10 on the current
				8 9 9	2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jul 1,	SYSTEM SYSTEM SYSTEM	\$10,400.00 (\$10,400.00) \$10,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 10 on the current
				8 9 9 10	2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jul 1, 2020 Jul 1,	SYSTEM SYSTEM SYSTEM	\$10,400.00 (\$10,400.00) \$10,400.00 (\$10,400.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				8 9 9 10 10	2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 Jul 1, 2020 Jul 1, 2020 Jul 15,	SYSTEM SYSTEM SYSTEM SYSTEM	\$10,400.00 (\$10,400.00) \$10,400.00 (\$10,400.00) \$10,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate.



0670 Material - Total \$0.00 \$0.00 0670 - Total \$0.00 \$0.00 0689 SLAB ON STEEL Material \$9 Jun 16, 2020 \$YSTEM \$62,300.00 This adjustment offsets the original system-generated OVP Payment Estimate Item Adjustment (0012) due to user chroweridding Payment Estimate Item Adjustment (0012) due to user chroweridding Payment Estimate Item Adjustment (0012) due to user chroweridding Payment Estimate Item Adjustment (0012) due to user chroweridding Payment Estimate Item Adjustment (0012) due to user chroweridding Payment Estimate Item Adjustment (0007) due to user chroweridding Payment Estimate Item Adjustment (0007) due to user chroweridding Payment Estimate Item Adjustment (0007) due to user chroweridding Payment Estimate Item Adjustment (0007) due to user chroweridding Payment Estimate Item Adjustment (0007) due to user chroweridding Payment Estimate Item Adjustment (0007) due to user chroweridding Payment Estimate Item Adjustment (0007) due to user chroweridding Payment Estimate Item Adjustment (0007) due to user chroweridding Payment Estimate Item Adjustment (0007) due to user chroweridding Payment Estimate Item Adjustment (0007) due to user chroweridding Payment Estimate Item Adjustment (0007) due to user chroweridding Payment Estimate Item Adjustment (0008) due to user chroweridding Payment Estimate Item Adjustment (0008) due to user chroweridding Payment Estimate Estimate Exception 10 on the current Payment Item Item Item Item Item Item Item Ite
0690 SLAB ON STEEL Material 9 Jun 16, 2020 SYSTEM (\$62,300.00) This adjustment offsets the original system-generated Over Payment Estimate Exception 6 on the current Payment Estimate Exception 10 on the current Payment Estimate Estimate Exception 10 on the current Payment Estimate Exception 10 on the curr
Image: Second
Image: state in the state
Image: state of the state o
Image: state in the image: state in
Material - Total \$0.00 0690 - Total \$0.00 0700 SAFETY BARRIER CURB Material 10 Jul 1, 2020 SYSTEM \$17,000.00 10 Jul 1, 2020 SYSTEM \$10,000 10 Jul
0690 - Total \$0.00 0700 SAFETY BARRIER CURB Material 10 Jul 1, 2020 SYSTEM (\$17,000.00) 10 Jul 1, 2020 SYSTEM \$17,000.00 This adjustment offsets the original system-generated Over Payment Estimate Item Adjustment (0008) due to user chroverridding Payment Estimate Exception 10 on the curren Payment Estimate. - Total
0700 SAFETY BARRIER CURB Material 10 Jul 1, 2020 SYSTEM (\$17,000.00) 10 Jul 1, 2020 SYSTEM \$17,000.00 This adjustment offsets the original system-generated Over Payment Estimate Item Adjustment (0008) due to user chrowerridding Payment Estimate Exception 10 on the current Payment Estimate. - Total - Total \$0.00
2020 2020 This adjustment offsets the original system-generated Over Payment Estimate Item Adjustment (0008) due to user char overridding Payment Estimate Exception 10 on the current Payment Estimate. - Total SYSTEM \$0.00
2020 Payment Estimate Item Adjustment (0008) due to user chi overridding Payment Estimate Exception 10 on the curren Payment Estimate. - Total \$0.00
Material - Total \$0.00
0700 - Total \$0.00
0720 CLEANING AND EPOXY COATING Material 15 Sep 17, 2020 SYSTEM (\$5,489.00)
15 Sep 17, 2020 SYSTEM \$5,489.00 This adjustment offsets the original system-generated Over Payment Estimate Item Adjustment (0041) due to user chi overridding Payment Estimate Exception 10 on the current Payment Estimate.
- Total \$0.00
Material - Total \$0.00
0720 - Total \$0.00
0770 LAMINATED NEOPRENE BEARING PAD ASSEMBLY Material 9 Jun 16, SYSTEM (\$10,400.00)
9 Jun 16, SYSTEM \$10,400.00 This adjustment offsets the original systems does not be current with the current string to the
Payment Estimate.
10 Jul 1, SYSTEM (\$10,400.00)
10 Jul 1, 2020 SYSTEM (\$10,400.00) 10 Jul 1, 2020 SYSTEM (\$10,400.00) 10 Jul 1, 2020 SYSTEM \$10,400.00) 10 Jul 1, 2020 SYSTEM \$10,400.00) 11 Jul 15, 2020 SYSTEM \$(\$10,400.00)
Image:
Image:
Image: Note: Service of the service
Image: Payment Estimate. Payment Estimate. Image: Payment Estimate. Image: Payment Estimate. Image: Payment Estimate. Im
Image: Figure 1 - Total
 Image: Constraint of the second of the se
Image: Figure



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0790	SLAB ON STEEL	Material	Туре					overridding Payment Estimate Exception 3 on the current
			- Total				\$0.00	Payment Estimate.
	Material - Total		- Total				\$0.00	
0790 -							\$0.00	
0800	SAFETY BARRIER CURB	Material		13	Aug 17, 2020	SYSTEM	(\$13,965.00)	
				13	Aug 17, 2020	SYSTEM	\$13,965.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				14	Sep 2, 2020	SYSTEM	(\$13,965.00)	
				14	Sep 2, 2020	SYSTEM	\$13,965.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				15	Sep 17, 2020	SYSTEM	(\$13,965.00)	
				15	Sep 17, 2020	SYSTEM	\$13,965.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0800 -	Total						\$0.00	
0810	CLEANING AND EPOXY COATING	Material		15	Sep 17, 2020	SYSTEM	(\$5,489.00)	
				15	Sep 17, 2020	SYSTEM	\$5,489.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0042) due to user chronf1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0810 -	Total						\$0.00	
0860	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	Material		11	Jul 15, 2020	SYSTEM	(\$10,400.00)	
				11	Jul 15, 2020	SYSTEM	\$10,400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0860 -	Total						\$0.00	
0880	POROUS BACKFILL	Overrun	Overrun	8	Jun 2, 2020	SYSTEM	(\$1,530.00)	
				8	Jun 2, 2020	SYSTEM	\$1,530.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user chronf1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$1,530.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				9	Jun 16, 2020	SYSTEM	\$1,530.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
	Overrun - Total						\$0.00	
	Overrun - Total						\$0.00	
0880 -	Total						\$0.00	
0900	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		6	May 4, 2020	SYSTEM	(\$690.00)	
				6	May 5, 2020	SYSTEM	\$690.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0900		Material	- Total				\$0.00	
	Material - Total						\$0.00	
900 -	Total						\$0.00	
910	MISC. TYPE 1 OR TYPE 5 AGGR BASE	Material		6	May 4, 2020	SYSTEM	(\$1,619.52)	
				6	May 5, 2020	SYSTEM	\$1,619.52	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				10	Jul 1, 2020	SYSTEM	(\$2,947.20)	
				10	Jul 1, 2020	SYSTEM	\$2,947.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
910 -	Total						\$0.00	
920	GRAVEL (A) OR CRUSHED STONE (B)	Material		6	May 4, 2020	SYSTEM	(\$2,695.00)	
				6	May 5, 2020	SYSTEM	\$2,695.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
920 -	Total						\$0.00	
0930	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Material		6	May 4, 2020	SYSTEM	(\$26,910.00)	
				6	May 5, 2020	SYSTEM	\$26,910.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				7	May 19, 2020	SYSTEM	(\$26,910.00)	
				7	May 19, 2020	SYSTEM	\$26,910.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)		ACAD	6	May 5, 2020	chronf1	\$68.77	ACAD for 299 Tons of BB17-41.
				9	Jun 16, 2020	chronf1	(\$546.74)	ACAD for 211.3 Tons of BB17-41.
			ACAD - Tot	al			(\$477.97)	
	Other Item Adjustment - Total						(\$477.97)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Overrun	Overrun	9	Jun 16, 2020	SYSTEM	(\$10,017.00)	
				9	Jun 16, 2020	SYSTEM	\$9,081.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	\$936.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
930 -	Total						(\$477.97)	
)940	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material		6	May 4, 2020	SYSTEM	(\$4,725.00)	
				6	May 5, 2020	SYSTEM	\$4,725.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 5 on the current



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0940	BITUMINOUS PAVEMENT MIXTURE	Material						Payment Estimate.
	PG64-22 (SURFACE LEVELING)			7	May 19, 2020	SYSTEM	(\$4,725.00)	
				7	May 19, 2020	SYSTEM	\$4,725.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	ACAD	6	May 5, 2020	chronf1	\$15.23	ACAD for 52.5 Tons of SL20-25.
				9	Jun 16, 2020	chronf1	(\$144.86)	ACAD for 44.4 Tons of SL20-25.
			ACAD - Tota	al			(\$129.63)	
	Other Item Adjustment - Total						(\$129.63)	
	Total						(\$129.63)	
0950	TACK COAT	Material		6	May 4, 2020	SYSTEM	(\$451.50)	
				6	May 5, 2020	SYSTEM	\$451.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
950 -	Total						\$0.00	
020	CONSTRUCTION SIGNS	Material		2	Mar 2, 2020	SYSTEM	(\$1,328.00)	
				2	Mar 2, 2020	SYSTEM	\$1,328.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
020 -	Total						\$0.00	
030	ADVANCED WARNING RAIL SYSTEM	Material		2	Mar 2, 2020	SYSTEM	(\$280.00)	
				2	Mar 2, 2020	SYSTEM	\$280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				3	Mar 17, 2020	SYSTEM	(\$280.00)	
			- Total	- Total			(\$280.00)	
	Material - Total						(\$280.00)	
	ADVANCED WARNING RAIL SYSTEM	MaterialCredit		4	Apr 2, 2020	SYSTEM	\$280.00	
			- Total				\$280.00	
	MaterialCredit - Total						\$280.00	
1030 -							\$0.00	
1040	FLAG ASSEMBLY	Material		2	Mar 2, 2020	SYSTEM	(\$80.00)	
				2	Mar 2, 2020	SYSTEM	\$80.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
040 -	Total						\$0.00	
1050	TYPE III MOVEABLE BARRICADE	Overrun	Overrun	3	Mar 17, 2020	SYSTEM	(\$750.00)	
				3	Mar 17,	SYSTEM	\$750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1050	TYPE III MOVEABLE BARRICADE	Overrun	Overrun					Payment Estimate.
			Overrun - T	otal	1		\$0.00	
	Overrun - Total						\$0.00	
1050 -							\$0.00	
1070	CHANGEABLE MESSAGE SIGN	Material		2	Mar 2,	SYSTEM	(\$6,000.00)	
	WITHOUT COMMUNICATION INTERFACE, CONTRACTOR				2020		,	
	FURNISHED, CONTRACTOR RETAINED			2	Mar 2, 2020	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user chronf1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				3	Mar 17, 2020	SYSTEM	(\$6,000.00)	
			- Total				(\$6,000.00)	
	Material - Total						(\$6,000.00)	
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	MaterialCredit		4	Apr 2, 2020	SYSTEM	\$6,000.00	
			- Total		1		\$6,000.00	
	MaterialCredit - Total						\$6,000.00	
1070 -	Total						\$0.00	
1090	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Other Item Adjustment	OTHR	9	Jun 16, 2020	chronf1	(\$1,606.50)	50% of payment withheld on this estimate pending retroreflectivity results.
	BEADS			10	Jul 1, 2020	chronf1	\$1,606.50	Payment for 50% of posting that was previously withheld (retroreflectivity results accepted).
			OTHR - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun	Overrun	9	Jun 16, 2020	SYSTEM	(\$1,343.00)	
				9	Jun 16, 2020	SYSTEM	\$1,343.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
1090 -	Total						\$0.00	
1100	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	OTHR	9	Jun 16, 2020	chronf1	(\$946.50)	50% of payment withheld on this estimate pending retroreflectivity results.
	FAINT, TITE F BEADS		OTHR - Tota	10	Jul 1, 2020	chronf1	\$946.50	Payment for 50% of posting that was previously withheld (retroreflectivity results accepted).
		al			\$0.00			
	Other Item Adjustment - Total						\$0.00	
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Overrun	Overrun		Jun 16, 2020	SYSTEM	(\$805.00)	
				9	Jun 16, 2020	SYSTEM	\$805.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user chronf1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
1100 -	Total						\$0.00	
1150	24 IN. PIPE GROUP C	Material		5	Apr 15, 2020	SYSTEM	(\$3,080.00)	
				5	Apr 15, 2020	SYSTEM	\$3,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
			Overrun	0	Jun 2,	SYSTEM	(\$1,650,00)	
	24 IN. PIPE GROUP C	Overrun	Overrun	0	2020	STOTEM	(\$1,650.00)	



	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1150	24 IN. PIPE GROUP C	Overrun	Overrun		2020			Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$1,650.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				9	Jun 16, 2020	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
1150 -	Total						\$0.00	
1160	36 IN. PIPE GROUP C	Material		5	Apr 15, 2020	SYSTEM	(\$10,064.00)	
				5	Apr 15, 2020	SYSTEM	\$10,064.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1160 -	Total				_		\$0.00	
1170	SEEDING - COOL SEASON MIXTURES	Material		6	May 4, 2020	SYSTEM	(\$975.00)	
				6	May 5, 2020	SYSTEM	\$975.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				7	May 19, 2020	SYSTEM	(\$975.00)	
				7	May 19, 2020	SYSTEM	\$975.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1170 -	Total						\$0.00	
1220		Material		6	May 4,	SYSTEM	(\$513.50)	
	TYPE C BERM	Material			2020		. ,	
	TYPE C BERM	material		6	2020 May 5, 2020	SYSTEM	\$513.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
	TYPE C BERM	index numbers		6	May 5,	SYSTEM	. ,	Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 19 on the current
	TYPE C BERM				May 5, 2020 May 19, 2020		\$513.50	Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 19 on the current
			- Total	7	May 5, 2020 May 19, 2020 May 19,	SYSTEM	\$513.50 (\$513.50) \$513.50 \$0.00	Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 13 on the current
	Material - Total		- Total	7	May 5, 2020 May 19, 2020 May 19,	SYSTEM	\$513.50 (\$513.50) \$513.50 \$0.00 \$0.00	Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 13 on the current
1220 -			- Total	7	May 5, 2020 May 19, 2020 May 19,	SYSTEM	\$513.50 (\$513.50) \$513.50 \$0.00	Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 13 on the current
1220 - 1230	Material - Total		- Total	7	May 5, 2020 May 19, 2020 May 19,	SYSTEM	\$513.50 (\$513.50) \$513.50 \$0.00 \$0.00	Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 13 on the current
	Material - Total Total		- Total	7 7	May 5, 2020 May 19, 2020 May 19, 2020 May 4,	SYSTEM	\$513.50 (\$513.50) \$513.50 \$0.00 \$0.00 \$0.00	Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 13 on the current
	Material - Total Total		- Total	7 7 6	May 5, 2020 May 19, 2020 May 19, 2020 May 4, 2020 May 4, 2020	SYSTEM SYSTEM SYSTEM	\$513.50 (\$513.50) \$513.50 \$0.00 \$0.00 \$0.00 (\$504.00)	Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 20 on the current
	Material - Total Total		- Total	7 7 6 6	May 5, 2020 May 19, 2020 May 19, 2020 May 4, 2020 May 4, 2020 May 5, 2020 May 19,	SYSTEM SYSTEM SYSTEM SYSTEM	\$513.50 (\$513.50) \$513.50 \$0.00 \$0.00 \$0.00 (\$504.00) \$504.00	Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 20 on the current
	Material - Total Total		- Total	7 7 6 6 7	May 5, 2020 May 19, 2020 May 19, 2020 May 19, 2020 May 4, 2020 May 5, 2020 May 19, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$513.50 (\$513.50) \$513.50 \$0.00 \$0.00 (\$504.00) \$504.00 (\$504.00)	Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
	Material - Total Total			7 7 6 6 7	May 5, 2020 May 19, 2020 May 19, 2020 May 19, 2020 May 4, 2020 May 5, 2020 May 19, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$513.50 (\$513.50) \$513.50 \$0.00 \$0.00 (\$504.00) \$504.00 \$504.00	Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 20 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1240	POST ANCHOR FOR 2 IN. PSST - 12 GA.	Material		6	May 4, 2020	SYSTEM	(\$504.00)	
				6	May 5, 2020	SYSTEM	\$504.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				7	May 19, 2020	SYSTEM	(\$504.00)	
				7	May 19, 2020	SYSTEM	\$504.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
240 -	Total						\$0.00	
1250	SH-FLAT SHEET	Material		6	May 4, 2020	SYSTEM	(\$324.00)	
				6	May 5, 2020	SYSTEM	\$324.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user chronf1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				7	May 19, 2020	SYSTEM	(\$324.00)	
				7	May 19, 2020	SYSTEM	\$324.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user chronf1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
250 -	Total						\$0.00	
1260	SHF-FLAT SHEET FLUORESCENT	Material		6	May 4, 2020	SYSTEM	(\$648.00)	
				6	May 5, 2020	SYSTEM	\$648.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user chronf1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				7	May 19, 2020	SYSTEM	(\$648.00)	
				7	May 19, 2020	SYSTEM	\$648.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user chronf1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
260 -	Total						\$0.00	
270	CLASS 1 EXCAVATION	Overrun	Overrun	7	May 19, 2020	SYSTEM	(\$750.00)	
				7	May 19, 2020	SYSTEM	\$750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
270 -	Total						\$0.00	
290	BRIDGE APPROACH SLAB (MINOR ROAD)		ACAD	9	Jun 16, 2020	chronf1	(\$193.68)	ACAD for 111 SY (BB17-41 and SL20-25).
	ACAD - Total						(\$193.68)	
	Other Item Adjustment - Total						(\$193.68)	
290 -	Total						(\$193.68)	
1300	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Material		6	May 4, 2020	SYSTEM	(\$38,040.00)	
				6	May 5, 2020	SYSTEM	\$38,040.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chron11 overridding Payment Estimate Exception 8 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1300	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Material		7	May 19, 2020	SYSTEM	(\$38,040.00)	
				7	May 19, 2020	SYSTEM	\$38,040.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				8	Jun 2, 2020	SYSTEM	(\$38,040.00)	
				8	Jun 2, 2020	SYSTEM	\$38,040.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user chronf1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Other Item Adjustment	OTHR	6	May 5, 2020	chronf1	\$3,840.00	This is payment for the splices on Bent 1 and Bent 2 on Br. A8748. Bent 1: 3 splices x 8LF/splice = 24LF. Bent 2: 1 splice x 8LF/splice = 8LF. Total: 32LF x \$120/LF = \$3,840.
			OTHR - Tota	al	1		\$3,840.00	
	Other Item Adjustment - Total						\$3,840.00	
	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Overrun	Overrun	6	May 4, 2020	SYSTEM	\$14,520.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 24 on the current Payment Estimate.
				6	May 4, 2020	SYSTEM	(\$14,520.00)	
				7	May 19, 2020	SYSTEM	(\$14,520.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				7	May 19, 2020	SYSTEM	\$14,520.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 19 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
300 -	Total						\$3,840.00	
320	CLASS B CONCRETE (SUBSTRUCTURE)	Material		7	May 19, 2020	SYSTEM	(\$30,380.00)	
				7	May 19, 2020	SYSTEM	\$30,380.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
320 -	Total						\$0.00	
330	SAFETY BARRIER CURB	Material		8	Jun 2, 2020	SYSTEM	(\$13,900.00)	
				8	Jun 2, 2020	SYSTEM	\$13,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				9	Jun 16, 2020	SYSTEM	(\$13,900.00)	
				9	Jun 16, 2020	SYSTEM	\$13,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				10	Jul 1, 2020	SYSTEM	(\$13,900.00)	
				10	Jul 1, 2020	SYSTEM	\$13,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user chronf1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
330 -	Total						\$0.00	
	SLAB ON CONCRETE BEAM	Material		8	Jun 2, 2020	SYSTEM	(\$66,600.00)	
340				8	Jun 2,	SYSTEM	\$66,600.00	This adjustment offsets the original system-generated Overrun



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
1340	SLAB ON CONCRETE BEAM	Material						overridding Payment Estimate Exception 13 on the current Payment Estimate.
				10	Jul 1, 2020	SYSTEM	(\$70,200.00)	
				10	Jul 1, 2020	SYSTEM	\$70,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1340 -	Total						\$0.00	
1410	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		7	May 19, 2020	SYSTEM	(\$14,690.00)	
				7	May 19, 2020	SYSTEM	\$14,690.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	BRIDGE APPROACH SLAB (MINOR ROAD)	Other Item Adjustment	ACAD	6	May 5, 2020	chronf1	\$17.52	ACAD for 113 SY.
			ACAD - Tot	al			\$17.52	
	Other Item Adjustment - Total						\$17.52	
1410 -	Total						\$17.52	
1420	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Material		4	Apr 2, 2020	SYSTEM	(\$44,280.00)	
				4	Apr 2, 2020	SYSTEM	\$44,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chron11 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				5	Apr 15, 2020	SYSTEM	(\$44,280.00)	
				5	Apr 15, 2020	SYSTEM	\$44,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)	Other Item Adjustment	OTHR	4	Apr 2, 2020	chronf1	\$6,720.00	chronf1 This is payment for the splices on Bent 1 and Bent 2 on Br. A8802. Bent 1: 3 splices x 8LF/splice = 24LF. Bent 2: 4 splices x 8LF/splice = 32LF. Total: 56LF x \$120/LF = \$6,720
			OTHR - Tot	al			\$6,720.00	
	Other Item Adjustment - Total						\$6,720.00	
1420 -	Total						\$6,720.00	
1440	CLASS B CONCRETE (SUBSTRUCTURE)	Material		4	Apr 2, 2020	SYSTEM	(\$30,240.00)	
				4	Apr 2, 2020	SYSTEM	\$30,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				5	Apr 15, 2020	SYSTEM	(\$30,240.00)	
				5	Apr 15, 2020	SYSTEM	\$30,240.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1440 -	Total						\$0.00	
1450	SAFETY BARRIER CURB	Material		5	Apr 15, 2020	SYSTEM	(\$11,235.00)	
				5	Apr 15, 2020	SYSTEM	\$11,235.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1450	SAFETY BARRIER CURB	Material						overridding Payment Estimate Exception 4 on the current Payment Estimate.
				6	May 4, 2020	SYSTEM	(\$11,235.00)	
				6	May 5, 2020	SYSTEM	\$11,235.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user chronf1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total					\$0.00		
1450 -	- Total			_			\$0.00	
1460	0 SLAB ON CONCRETE BEAM Material	Material		4	Apr 2, 2020	SYSTEM	(\$66,600.00)	
				4	Apr 2, 2020	SYSTEM	\$66,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				5	Apr 15, 2020	SYSTEM	(\$70,200.00)	
				5	Apr 15, 2020	SYSTEM	\$70,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				6	May 4, 2020	SYSTEM	(\$70,200.00)	
				6	May 5, 2020	SYSTEM	\$70,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user chronf1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1460 -	- Total						\$0.00	
Overa	all - Total						\$799.57	