

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 30, 2020

| Progress Estimate Number | Contract ID 191213-H04 | Pay Period Start September 16, 2020 Original Contract Amount \$2,283,871.00 |
|--------------------------|-------------------------------------|--|
| 16 | Prime Contractor Robertson Contract | tors, Inc. Pay Period End September 30, 2020 Net Change Order Amount \$70,288.50 |
| 10 | | Current Contract Amount \$2,354,159.50 |

| Approval Date | | By User |
|-----------------|--|---------|
| October 1, 2020 | Generated and Approved (and should be considered Draft) at the Project Office Level by | chronf1 |
| October 1, 2020 | Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by | HILLSD1 |
| October 2, 2020 | Reviewed and Approved at the Central Office Controllers Office Level by | greggd1 |

| Original Completion Date | Current Completion Date | Actual Completion Date | % of Current Contract Amount Complete |
|--------------------------|-------------------------|------------------------|---------------------------------------|
| July 1, 2021 | July 1, 2021 | September 23, 2020 | 95.72% |

No Milestones Exist for Contract

| Contract Total Pa | ay For Estimate No. 16 | | | | |
|--------------------------|----------------------------|---------------|----------------|----------------|--|
| | | This Estimate | Previous | To Date | |
| 191213-H04 | | | | | |
| | Total Posted Items Pay | \$3,333.00 | \$2,250,069.10 | \$2,253,402.10 | |
| | Gross Item Adjustments | (\$2,042.63) | \$799.57 | (\$1,243.06) | |
| | Incentive | \$0.00 | \$0.00 | \$0.00 | |
| | Disincentive | \$0.00 | \$0.00 | \$0.00 | |
| | Liquidated Damage | \$0.00 | \$0.00 | \$0.00 | |
| | Other Contract Adjustments | \$0.00 | \$0.00 | \$0.00 | |
| | | | \$2,250,868.67 | \$2,252,159.04 | |
| Contract Total Pa | ayable This Estimate: | \$1,290.37 | | | |

Items Paid This Estimate Period

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount | | | | |
|-------------------|----------------------|--------------|---|------|---------------|--------------------------|-----------------------------|--|--|--|--|
| J9S3224 | 0260 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | LF | \$0.500 | 2,217 | \$1,108.50 | | | | |
| | 0270 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | LF | \$0.500 | 2,422 | \$1,211.00 | | | | |
| | 0280 | 6207001 | PAVEMENT MARKING REMOVAL | LF | \$0.500 | 2,027 | \$1,013.50 | | | | |
| Project J9S | ject J9S3224 - Total | | | | | | | | | | |
| Overall - To | Overall - Total | | | | | | | | | | |

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
|-------------------|-------------|--|--|--|--|------------------------|---------------------------------------|----------------------|
| J9S3224 | 0070 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) | Other Item Adjustment | Asphalt Cement Price Adjustment | ACAD correction for 62.73 Tons of BB17-41 on Estimate No. 13. Actual adjustment is \$180.35. | | | \$1,320.15 |
| | 0070 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) | | | | | | (\$180.35) |
| | 0080 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | Other Item Adjustment | Asphalt Cement Price Adjustment | ACAD correction for 73.19 Tons of SL20-25 on Estimate No. 13. Actual adjustment is \$265.31. | | | \$1,942.10 |
| | 0080 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | Other Item Adjustment | Asphalt Cement Price Adjustment | ACAD correction for 73.19 Tons of SL20-25. | | | (\$265.31) |
| | 0090 | MISC. | MISC. Other Item Adjustment Cement Price Adjustment Price Adjustment | | | | | \$1,266.77 |
| | 0090 | MISC. | Other Item Adjustment | Asphalt Cement | ACAD correction for 106.66 SY plus 0.02 SY rounding correction. | | | (\$173.09) |

Revision 4/1/2020 Page 1 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 30, 2020

Progress Estimate Number
16 Contract ID 191213-H04 Pay Period Start September 16, 2020 Original Contract Amount \$2,283,871.00
Prime Contractor Robertson Contractors, Inc. Pay Period End September 30, 2020 Net Change Order Amount \$70,288.50
Current Contract Amount \$2,354,159.50

| oject mber | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
|---------------|-------------|--|--------------------------|----------------------------------|---|------------------------|---------------------------------------|----------------------|
| 3224 | | | | Price Adjustment | | | | |
| | 0130 | FURNISHING TYPE 2 ROCK BLANKET | Overrun | | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | -114 | \$38.00 | (\$4,332.00 |
| | 0130 | FURNISHING TYPE 2 ROCK BLANKET | Overrun | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | 114 | \$38.00 | \$4,332.00 |
| | 0140 | PLACING TYPE 2 ROCK BLANKET | Overrun | | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | -114 | \$13.00 | (\$1,482.00 |
| | 0140 | PLACING TYPE 2 ROCK BLANKET | Overrun | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user chronf1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | 114 | \$13.00 | \$1,482.00 |
| | 0260 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Overrun | | | -1,225 | \$0.50 | (\$612.50 |
| | 0260 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Overrun | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | 1,225 | \$0.50 | \$612.50 |
| | 0260 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Other Item Adjustment | Other | 20% of payment withheld on this estimate pending retroreflectivity results. | | | (\$221.70 |
| | 0270 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Other Item Adjustment | Other | 20% of payment withheld on this estimate pending retroreflectivity results. | | | (\$242.20 |
| | 0280 | PAVEMENT MARKING REMOVAL | Overrun | | | -1,018 | \$0.50 | (\$509.00 |
| | 0280 | PAVEMENT MARKING REMOVAL | Overrun | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate. | 1,018 | \$0.50 | \$509.00 |
| | 0290 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | Overrun | | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | -217 | \$15.00 | (\$3,255.00 |
| | 0290 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | Overrun | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 11 on the current Payment Estimate. | 217 | \$15.00 | \$3,255.00 |
| | 0480 | BRIDGE APPROACH SLAB (MINOR ROAD) | Material | | | -111 | \$135.00 | (\$14,985.00 |
| (| 0480 | BRIDGE APPROACH SLAB (MINOR ROAD) | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | 111 | \$135.00 | \$14,985.00 |
| | 0520 | SAFETY BARRIER CURB | Material | | | -139 | \$105.00 | (\$14,595.00 |
| | 0520 | SAFETY BARRIER CURB | Material | | This adjustment offsets the original system- | 139 | \$105.00 | \$14,595.00 |

Revision 4/1/2020 Page 2 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 30, 2020

Progress Estimate Number
16 Contract ID 191213-H04 Pay Period Start September 16, 2020 Original Contract Amount \$2,283,871.00
Prime Contractor Robertson Contractors, Inc. Pay Period End September 30, 2020 Net Change Order Amount \$70,288.50
Current Contract Amount \$2,354,159.50

| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
|-------------------|-------------|-------------------------------|--------------------|----------------------------------|--|------------------------|---------------------------------------|----------------------|
| J9S3224 | | | | | generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | | |
| | 0620 | CLEANING AND EPOXY COATING | Material | | | -499 | \$11.00 | (\$5,489.00) |
| | 0720 | CLEANING AND EPOXY COATING | Material | | | -499 | \$11.00 | (\$5,489.00) |
| | 0720 | CLEANING AND EPOXY COATING | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate. | 499 | \$11.00 | \$5,489.00 |
| | 0810 | CLEANING AND EPOXY COATING | Material | | | -499 | \$11.00 | (\$5,489.00) |
| | 0810 | CLEANING AND EPOXY COATING | Material | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | 499 | \$11.00 | \$5,489.00 |
| Total | | | | | | | | (\$2,042.63) |

Revision 4/1/2020 Page 3 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | | | | | (| Contract Project Information | |
|-------------------|----------------------------|--|-----------------|----------|---|--|---|
| Project Number | Federal Proj. Number | Project Description | Route | County | | | Location of Work |
| J9S3224 | FAS S701(50) | Bridge replacement and 3 bridge rehabilitations | Z | STODDARD | from 4.4 miles west | of Route 153 intersection to | 3.0 miles east of Route 153 intersecti |
| J9S3224B | FAS S703(69) | 2 Bridge replacement | Z | STODDARD | from 2 miles west o | f Route 153 intersection to 1 | miles west of Route 153 intersection |
| Totals by Jo | b Numbers | \$ | | | | | |
| J9S3224 | | Item Pay tem Adjustmen | ts Gross It | em Pay | This Estimate \$3,333.00 (\$2,042.63) \$1,290.37 | Previous \$1,452,707.90 (\$8,976.67) \$1,443,731.23 | To Date \$1,456,040.90 (\$11,019.30) \$1,445,021.60 |
| | | | ments | | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 |
| J9S3224B | | Item Pay tem Adjustmen | ts Gross Ite | em Pay | This Estimate \$0.00 \$0.00 \$0.00 | Previous \$797,361.20 \$9,776.24 \$807,137.44 | To Date \$797,361.20 \$9,776.24 \$807,137.44 |
| | | | ments | | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 |

Revision 4/1/2020 Page 4 of 29



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions / Discrepencies | Explanation | Entered By | Status |
|---|---|---------------|--------------|
| Estimate Exception Type: Insufficient Materials: Project J9S3224, Item 5031011A, Project Item Line Number 0480, Material Set 5031011A96, Material 0401BPPMBB - Plant Mix Bituminous Base, Acceptance Action Generic AspLow is insufficient. | Work complete. Certification of mix needed from contractor. | chronf1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J9S3224, Item 5031011A, Project Item Line Number 0480, Material Set 5031011A96, Material 0402SLPMSL - Plant Mix for Surface Leveling, Acceptance Action Generic AspSL is insufficient. | Work complete. Certification of mix needed from contractor. | chronf1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J9S3224, Item 7034215, Project Item Line Number 0520, Material Set 703421596, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. | Work complete. Pending 28 day cylinder breaks. | chronf1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J9S3224, Item 7040113, Project Item Line Number 0810, Material Set 704011396, Material 1039ERBCT3 - Type III Epoxy Resin for Conc Patch Cmp, Acceptance Action Generic 1039ERBCT3 is insufficient. | Work complete. Cert needed from contractor. | chronf1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J9S3224, Item 7040113, Project Item Line Number 0620, Material Set 704011396, Material 1039ERBCT3 - Type III Epoxy Resin for Conc Patch Cmp, Acceptance Action Generic 1039ERBCT3 is insufficient. | Cert needed from contractor. | chronf1 | Acknowledged |
| Estimate Exception Type: Insufficient Materials: Project J9S3224, Item 7040113, Project Item Line Number 0720, Material Set 704011396, Material 1039ERBCT3 - Type III Epoxy Resin for Conc Patch Cmp, Acceptance Action Generic 1039ERBCT3 is insufficient. | Work complete. Cert needed from contractor. | chronf1 | Overridden |
| Estimate Exception Type: Item Overrun: Contract 191213-H04, Contract Project J9S3224, Project Item Line Number 0130, Contract Line Item Number 0130, Item 6113020, Minor Item. | Pending contractor's signature on change order. | chronf1 | Overridden |
| Estimate Exception Type: Item Overrun: Contract 191213-H04, Contract Project J9S3224, Project Item Line Number 0140, Contract Line Item Number 0140, Item 6113040, Minor Item. | Pending contractor's signature on change order. | chronf1 | Overridden |
| Estimate Exception Type: Item Overrun: Contract 191213-H04, Contract Project J9S3224, Project Item Line Number 0260, Contract Line Item Number 0260, Item 6206000C, Minor Item. | Pending contractor's signature on change order. | chronf1 | Overridden |
| Estimate Exception Type: Item Overrun: Contract 191213-H04, Contract Project J9S3224, Project Item Line Number 0280, Contract Line Item Number 0280, Item 6207001, Minor Item. | Pending contractor's signature on change order. | chronf1 | Overridden |
| Estimate Exception Type: Item Overrun: Contract 191213-H04, Contract Project J9S3224, Project Item Line Number 0290, Contract Line Item Number 0290, Item 6224010, Minor Item. | Pending contractor's signature on change order. | chronf1 | Overridden |

Revision 4/1/2020 Page 5 of 29



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | port Generated date and can differ from the posted amor Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|----------|-------------|----------------------|---|----------------------|------------------------|------------------------|----------|-----------------------|-----------------------|--|
| 101212 H04 | 1063334 | 0004 | 0010 | 2022010 | DEMOVAL OF IMPROVEMENTS | 1.00 | | · | 1.0 | Qty | \$19 500 00 | |
| 191213-H04 | J9S3224 | 0001 | 0010 | 2022010 | POROUS BACKFILL | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$18,500.00 | \$18,500.00 |
| | | 0001 | 0020 | 2079909 | MISC.MODIFIED LINEAR GRADING CL 2 | 22.80 | 0.00 | 151.00 22.80 | STA | 151.00 | \$85.00 \$2,400.00 | \$12,835.00 \$46,560.00 |
| | | 0001 | 0030 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 523.30 | 0.00 | 523.30 | SQYD | 487.00 | \$30.00 | \$14,610.00 |
| | | 0001 | 0050 | 3049910 | MISC.TYPE 1 OR TYPE 5 AGGR BASE | 139.60 | 0.00 | 139.60 | TONS | 100.80 | \$48.00 | \$4,838.40 |
| | | 0001 | 0060 | 3105002 | GRAVEL (A) OR CRUSHED STONE (B) | 318.00 | 0.00 | 318.00 | TONS | 268.00 | \$35.00 | \$9,380.00 |
| | | 0001 | 0070 | 4013000 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) | 912.70 | 0.00 | 912.70 | TONS | 529.90 | \$90.00 | \$47,691.00 |
| | | 0001 | 0080 | 4020520 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE | 216.40 | 0.00 | 216.40 | TONS | 210.30 | \$90.00 | \$18,927.00 |
| | | 0001 | | | LEVELING) | | | | | | | |
| | | 0001 | 0090 | 4029905 | MISC.OPTIONAL PAVEMENT | 320.00 | 0.00 | 320.00 | SQYD | 320.00 | \$58.00 | \$18,560.00 |
| | | 0001 | 0100 | 4071005 | TACK COAT | 587.00 | 0.00 | 587.00 | GAL | 441.00 | \$3.50 | \$1,543.50 |
| | | 0001 | 0110 | 6096020 | FURNISHING TYPE 2 ROCK DITCH LINER | 1,036.00 | 0.00 | 1,036.00 | CUYD | 422.00 | \$36.00 | \$15,192.00 |
| | | 0001 | 0120 | 6096042 | PLACING TYPE 2 ROCK DITCH LINER | 1,036.00 | 0.00 | 1,036.00 | CUYD | 422.00 | \$18.00 | \$7,596.00 |
| | | 0001 | 0130 | 6113020 | FURNISHING TYPE 2 ROCK BLANKET | 1,172.00 | 0.00 | 1,172.00 | CUYD | 1,286.00 | \$38.00 | \$48,868.00 |
| | | 0001 | 0140 | 6113040 | PLACING TYPE 2 ROCK BLANKET | 1,172.00 | 0.00 | 1,172.00 | CUYD | 1,286.00 | \$13.00 | \$16,718.00 |
| | | 0001 | 0150 | 6149902 | MISC.18 IN FLAP GATE | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$850.00 | \$850.00 |
| | | 0001 | 0160 | 6149902 | MISC.24 IN FLAP GATE | 3.00 | 0.00 | 3.00 | EA | 3.00 | \$1,000.00 | \$3,000.00 |
| | | 0001 | 0170 | 6149902 | MISC.30 IN FLAP GATE | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$1,200.00 | \$1,200.00 |
| | | 0001 | 0180 | 6149902 | MISC.36 IN FLAP GATE | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$1,350.00 | \$5,400.00 |
| | | 0001 | 0190 | 6161005 | CONSTRUCTION SIGNS | 602.00 | -90.00 | 512.00 | SQFT | 512.00 | \$8.00 | \$4,096.00 |
| | | 0001 | 0200 | 6161008 | ADVANCED WARNING RAIL SYSTEM | 8.00 | 8.00 | 16.00 | EA | 16.00 | \$35.00 | \$560.00 |
| | | 0001 | 0210 | 6161009 | FLAG ASSEMBLY | 4.00 | 4.00 | 8.00 | EA | 8.00 | \$20.00 | \$160.00 |
| | | 0001 | 0220 | 6161030 | TYPE III MOVEABLE BARRICADE | 12.00 | 0.00 | 12.00 | EA | 12.00 | \$125.00 | \$1,500.00 |
| | | 0001 | 0230 | 6161052 | WARNING LIGHT, TYPE B | 24.00 | 0.00 | 24.00 | EA | 24.00 | \$65.00 | \$1,560.00 |
| | | 0001 | 0240 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$3,000.00 | \$6,000.00 |
| | | 0001 | 0250 | 6181000 | MOBILIZATION | 1.00 | -1.00 | 0.00 | LS | 0.00 | \$105,000.00 | \$0.00 |
| | | 0001 | 0251 | 6181000 | MOBILIZATION | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$87,612.00 | \$87,612.00 |
| | | 0001 | 0260 | 6206000C 6206001C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT | 4,227.00 4,215.00 | 0.00 | 4,227.00 4,215.00 | LF LF | 5,452.00 4,042.00 | \$0.50 \$0.50 | \$2,726.00 \$2,021.00 |
| | | 0001 | 0270 | 0200001C | MARKING PAINT, TYPE P BEADS | 4,215.00 | 0.00 | 4,215.00 | LF | 4,042.00 | φ0.50 | |
| | | 0001 | 0280 | 6207001 | PAVEMENT MARKING REMOVAL | 7,068.00 | 0.00 | 7,068.00 | LF | 8,086.00 | \$0.50 | \$4,043.00 |
| | | 0001 | 0290 | 6224010 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | 285.00 | 222.00 | 507.00 | SQYD | 724.00 | \$15.00 | \$10,860.00 |
| | | 0001 | 0300 | 6240103A | PERMANENT EROSION CONTROL GEOTEXTILE | 5,422.00 | 0.00 | 5,422.00 | SQYD | 3,443.00 | \$3.00 | \$10,329.00 |
| | | 0001 | 0310 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$20,000.00 | \$20,000.00 |
| | | 0001 | 0320 | 7250418 | 18 IN. PIPE GROUP C | 77.00 | 0.00 | 77.00 | LF | 77.00 | \$45.00 | \$3,465.00 |
| | | 0001 | 0330 | 7250424 | 24 IN. PIPE GROUP C | 240.00 | 0.00 | 240.00 | LF | 240.00 | \$50.00 | \$12,000.00 |
| | | 0001 | 0340 | 7250430 | 30 IN. PIPE GROUP C | 85.00 | 0.00 | 85.00 | LF | 85.00 | \$60.00 | \$5,100.00 |
| | | 0001 | 0350 | 7250436 | 36 IN. PIPE GROUP C | 388.00 | 0.00 | 388.00 | LF | 388.00 | \$62.00 | \$24,056.00 |
| | | 0001 | 0360 | 8051000A | SEEDING - COOL SEASON MIXTURES | 1.00 | 0.00 | 1.00 | ACRE | 0.90 | \$3,900.00 | \$3,510.00 |
| | | 0001 | 0370 | 8061005 | ROCK DITCH CHECK | 188.00 | 0.00 | 188.00 | LF | 0.00 | \$15.00 | \$0.00 |
| | | 0001 | 0380 | 8061016 | SEDIMENT REMOVAL | 42.00 | 0.00 | 42.00 | CUYD | 0.00 | \$5.00 | \$0.00 |
| | | 0001 | 0390 | 8061017 | TEMPORARY SEEDING AND MULCHING | 1.00 | 0.00 | 1.00 | ACRE | 0.00 | \$800.00 | \$0.00 |
| | | 0001 | 0400 | 8061019 | SILT FENCE | 2,349.00 | 0.00 | 2,349.00 | LF | 865.00 | \$3.00 | \$2,595.00 |
| | | 0001 | 0410 | 8061050 | TYPE C BERM | 676.00 | 0.00 | 676.00 | LF | 92.00 | \$8.50 | \$782.00 |
| | | 0040 | 0420 | 9031270A | 2 IN. PSST POST - 12 GA. | 236.00 | 0.00 | 236.00 | LF | 229.00 | \$7.00 | \$1,603.00 |
| | | 0040 | 0430 | 9031271 | POST ANCHOR FOR 2 IN. PSST - 12 GA. | 147.00 | 0.00 | 147.00 | LF | 147.00 | \$12.00 | \$1,764.00 |
| | | 0040 | 0440 | 9035004A | SH-FLAT SHEET | 9.00 | 0.00 | 9.00 | SQFT | 9.00 | \$18.00 | \$162.00 |

Page 6 of 29 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|----------|-------------|--------------|---|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 191213-H04 | J9S3224 | 0040 | 0450 | 9035069A | SHF-FLAT SHEET FLUORESCENT | 144.00 | 0.00 | 144.00 | SQFT | 144.00 | \$18.00 | \$2,592.00 |
| | | 0070 | 0460 | 2061000 | CLASS 1 EXCAVATION | 60.00 | 31.00 | 91.00 | CUYD | 91.00 | \$40.00 | \$3,640.00 |
| | | 0070 | 0470 | 2160500 | REMOVAL OF BRIDGES | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$20,000.00 | \$20,000.00 |
| | | 0070 | 0480 | 5031011A | BRIDGE APPROACH SLAB (MINOR ROAD) | 111.00 | 0.00 | 111.00 | SQYD | 111.00 | \$135.00 | \$14,985.00 |
| | | 0070 | 0490 | 7021314 | GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN) | 216.00 | 185.00 | 401.00 | LF | 401.00 | \$125.00 | \$50,125.00 |
| | | 0070 | 0500 | 7025001 | DYNAMIC PILE TESTING | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$2,500.00 | \$5,000.00 |
| | | 0070 | 0510 | 7032003 | CLASS B CONCRETE (SUBSTRUCTURE) | 31.00 | 0.00 | 31.00 | CUYD | 31.00 | \$980.00 | \$30,380.00 |
| | | 0070 | 0520 | 7034215 | SAFETY BARRIER CURB | 139.00 | 0.00 | 139.00 | LF | 139.00 | \$105.00 | \$14,595.00 |
| | | 0070 | 0530 | 7034222 | SLAB ON CONCRETE BEAM | 156.00 | 0.00 | 156.00 | SQYD | 156.00 | \$430.00 | \$67,080.00 |
| | | 0070 | 0540 | 7056065 | 17 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM | 152.00 | 0.00 | 152.00 | LF | 152.00 | \$285.00 | \$43,320.0 |
| | | 0070 | 0550 | 7123610 | SLAB DRAIN | 10.00 | 0.00 | 10.00 | EA | 10.00 | \$220.00 | \$2,200.0 |
| | | 0070 | 0560 | 7151001 | VERTICAL DRAIN AT END BENTS | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,400.00 | \$2,800.0 |
| | | 0070 | 0570 | 7161000 | PLAIN NEOPRENE BEARING PAD | 6.00 | 0.00 | 6.00 | EA | 6.00 | \$180.00 | \$1,080.0 |
| | | 0073 | 0580 | 2169901 | MISC.Removal of Existing Superstructure | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$15,000.00 | \$15,000.0 |
| | | 0073 | 0590 | 7034212 | SLAB ON STEEL | 215.00 | 0.00 | 215.00 | SQYD | 215.00 | \$450.00 | \$96,750.0 |
| | | 0073 | 0600 | 7034215 | SAFETY BARRIER CURB | 145.00 | 0.00 | 145.00 | LF | 145.00 | \$100.00 | \$14,500.0 |
| | | 0073 | 0610 | 7040101 | SUBSTRUCTURE REPAIR (FORMED) | 20.00 | 0.00 | 20.00 | SQFT | 2.00 | \$345.00 | \$690.0 |
| | | 0073 | 0620 | 7040113 | CLEANING AND EPOXY COATING | 499.00 | 0.00 | 499.00 | SQFT | 499.00 | \$11.00 | \$5,489.0 |
| | | 0073 | 0630 | 7121111 | FABRICATED STRUCTURAL LOW ALLOY STEEL (I-BEAM) | 24,100.00 | 0.00 | 24,100.00 | LB | 24,100.00 | \$2.30 | \$55,430.0 |
| | | | | | A709, GRADE 50 | | | | | | | |
| | | 0073 | 0640 | 7123610 | SLAB DRAIN | 14.00 | 0.00 | 14.00 | EA | 14.00 | \$220.00 | \$3,080.0 |
| | | 0073 | 0650 | 7129901 | MISC.Galvanizing Structural Steel | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$16,500.00 | \$16,500.0 |
| | | 0073 | 0660 | 7161002 | LAMINATED NEOPRENE BEARING PAD | 8.00 | 0.00 | 8.00 | EA | 8.00 | \$320.00 | \$2,560.0 |
| | | 0073 | 0670 | 7162000 | LAMINATED NEOPRENE BEARING PAD ASSEMBLY | 8.00 | 0.00 | 8.00 | EA | 8.00 | \$1,300.00 | \$10,400.0 |
| | | 0074 | 0680 | 2169901 | MISC.Removal of Existing Superstructure | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$15,000.00 | \$15,000.0 |
| | | 0074 | 0690 | 7034212 | SLAB ON STEEL | 253.00 | 0.00 | 253.00 | SQYD | 253.00 | \$445.00 | \$112,585.0 |
| | | 0074 | 0700 | 7034215 | SAFETY BARRIER CURB | 170.00 | 0.00 | 170.00 | LF | 170.00 | \$100.00 | \$17,000.0 |
| | | 0074 | 0710 | 7040101 | SUBSTRUCTURE REPAIR (FORMED) | 20.00 | 0.00 | 20.00 | SQFT | 10.00 | \$350.00 | \$3,500.0 |
| | | 0074 | 0720 | 7040113 | CLEANING AND EPOXY COATING | 499.00 | 0.00 | 499.00 | SQFT | 499.00 | \$11.00 | \$5,489.0 |
| | | 0074 | 0730 | 7121111 | FABRICATED STRUCTURAL LOW ALLOY STEEL (I-BEAM) A709, GRADE 50 | 28,030.00 | 0.00 | 28,030.00 | LB | 28,030.00 | \$2.25 | \$63,067.5 |
| | | 0074 | 0740 | 7123610 | SLAB DRAIN | 14.00 | 0.00 | 14.00 | EA | 14.00 | \$220.00 | \$3,080.0 |
| | | 0074 | 0750 | 7129901 | MISC.Galvanizing Structural Steel | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$18,000.00 | \$18,000.0 |
| | | 0074 | 0760 | 7161002 | LAMINATED NEOPRENE BEARING PAD | 8.00 | 0.00 | 8.00 | EA | 8.00 | \$320.00 | \$2,560.0 |
| | | 0074 | 0770 | 7162000 | LAMINATED NEOPRENE BEARING PAD ASSEMBLY | 8.00 | 0.00 | 8.00 | EA | 8.00 | \$1,300.00 | \$10,400.0 |
| | | 0075 | 0780 | 2169901 | MISC.Removal of Existing Superstructure | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$15,000.00 | \$15,000.0 |
| | | 0075 | 0790 | 7034212 | SLAB ON STEEL | 198.00 | 0.00 | 198.00 | SQYD | 198.00 | \$465.00 | \$92,070.0 |
| | | 0075 | 0800 | 7034215 | SAFETY BARRIER CURB | 133.00 | 0.00 | 133.00 | LF | 133.00 | \$105.00 | \$13,965.0 |
| | | 0075 | 0810 | 7040113 | CLEANING AND EPOXY COATING | 499.00 | 0.00 | 499.00 | SQFT | 499.00 | \$11.00 | \$5,489.0 |
| | | 0075 | 0820 | 7121111 | FABRICATED STRUCTURAL LOW ALLOY STEEL (I-BEAM) | 22,010.00 | 0.00 | 22,010.00 | LB | 22,010.00 | \$2.35 | \$51,723.5 |
| | | 0075 | 0830 | 7123610 | A709, GRADE 50 SLAB DRAIN | 12.00 | 0.00 | 12.00 | EA | 12.00 | \$220.00 | \$2,640.0 |
| | | | 0840 | 7129901 | MISC.Galvanizing Structural Steel | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$14,500.00 | \$14,500.0 |
| | | 0075 | 0850 | 7161002 | LAMINATED NEOPRENE BEARING PAD | 8.00 | 0.00 | 8.00 | EA | 8.00 | \$380.00 | \$3,040.0 |
| | | 0075 | 0860 | 7161002 | LAMINATED NEOPRENE BEARING PAD LAMINATED NEOPRENE BEARING PAD ASSEMBLY | 8.00 | 0.00 | 8.00 | EA | 8.00 | \$1,300.00 | |
| | | 0075 | | | | | | | | | | \$10,400.0 |
| | | 0001 | 5001 | 6189901 | MISC.Contract Bond. Mobilization was adjusted for Contract Bond. | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$17,388.00 | \$17,388.0 |
| | | 0073 | 5002 | 7032003 | CLASS B CONCRETE (SUBSTRUCTURE) | 0.00 | 1.00 | 1.00 | CUYD | 1.00 | \$1,050.00 | \$1,050.0 |
| | | 0073 | 5003 | 7101000 | REINFORCING STEEL (EPOXY COATED) | 0.00 | 50.00 | 50.00 | LB | 50.00 | \$1.50 | \$75.0 |
| | | 0075 | 5004 | 7040101 | SUBSTRUCTURE REPAIR (FORMED) | 0.00 | 3.00 | 3.00 | SQFT | 3.00 | \$350.00 | \$1,050.0 |

Page 7 of 29 Revision 4/1/2020



| Contract CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|----------------------|----------------|------------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 13-H04 | Project J95 | 3224 - Tot | al Value | Posted to Da | Ite as of Report Generated Date | | | | | | | \$1,456,040.90 |
| | J9S3224B | 0001 | 0870 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$9,500.00 | \$9,500.00 |
| | | 0001 | 0880 | 2064000 | POROUS BACKFILL | 72.00 | 17.00 | 89.00 | CUYD | 89.00 | \$90.00 | \$8,010.00 |
| | | 0001 | 0890 | 2079909 | MISC.MODIFIED LINEAR GRADING CL 2 | 10.10 | 0.00 | 10.10 | STA | 10.10 | \$2,600.00 | \$26,260.00 |
| | | 0001 | 0900 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 96.70 | -25.50 | 71.20 | SQYD | 71.20 | \$50.00 | \$3,560.00 |
| | | 0001 | 0910 | 3049910 | MISC.TYPE 1 OR TYPE 5 AGGR BASE | 61.40 | 0.00 | 61.40 | TONS | 61.40 | \$48.00 | \$2,947.20 |
| | | 0001 | 0920 | 3105002 | GRAVEL (A) OR CRUSHED STONE (B) | 146.00 | 0.00 | 146.00 | TONS | 146.00 | \$35.00 | \$5,110.00 |
| | | 0001 | 0930 | 4013000 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) | 399.00 | 111.30 | 510.30 | TONS | 510.30 | \$90.00 | \$45,927.00 |
| | | 0001 | 0940 | 4020520 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | 96.90 | 0.00 | 96.90 | TONS | 96.90 | \$90.00 | \$8,721.00 |
| | | 0001 | 0950 | 4071005 | TACK COAT | 249.00 | 0.00 | 249.00 | GAL | 249.00 | \$3.50 | \$871.50 |
| | | 0001 | 0960 | 6096020 | FURNISHING TYPE 2 ROCK DITCH LINER | 794.00 | -76.00 | 718.00 | CUYD | 718.00 | \$35.00 | \$25,130.00 |
| | | 0001 | 0970 | 6096042 | PLACING TYPE 2 ROCK DITCH LINER | 794.00 | -76.00 | 718.00 | CUYD | 718.00 | \$15.00 | \$10,770.00 |
| | | 0001 | 0980 | 6113020 | FURNISHING TYPE 2 ROCK BLANKET | 610.00 | -11.00 | 599.00 | CUYD | 599.00 | \$38.00 | \$22,762.00 |
| | | 0001 | 0990 | 6113040 | PLACING TYPE 2 ROCK BLANKET | 610.00 | -11.00 | 599.00 | CUYD | 599.00 | \$15.00 | \$8,985.00 |
| | | 0001 | 1000 | 6149902 | MISC.24 IN FLAP GATE | 3.00 | 0.00 | 3.00 | EA | 3.00 | \$1,000.00 | \$3,000.00 |
| | | 0001 | 1010 | 6149902 | MISC.36 IN FLAP GATE | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,200.00 | \$2,400.00 |
| | | 0001 | 1020 | 6161005 | CONSTRUCTION SIGNS | 410.00 | -184.00 | 226.00 | SQFT | 226.00 | \$8.00 | \$1,808.00 |
| | | 0001 | 1030 | 6161008 | ADVANCED WARNING RAIL SYSTEM | 8.00 | 0.00 | 8.00 | EA | 8.00 | \$35.00 | \$280.00 |
| | | 0001 | 1040 | 6161009 | FLAG ASSEMBLY | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$20.00 | \$80.00 |
| | | 0001 | 1050 | 6161030 | TYPE III MOVEABLE BARRICADE | 12.00 | 6.00 | 18.00 | EA | 18.00 | \$125.00 | \$2,250.00 |
| | | 0001 | 1060 | 6161052 | WARNING LIGHT, TYPE B | 24.00 | -12.00 | 12.00 | EA | 12.00 | \$55.00 | \$660.00 |
| | | 0001 | 1070 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$3,000.00 | \$6,000.0 |
| | | 0001 | 1080 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$55,000.00 | \$55,000.00 |
| | | 0001 | 1090 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 1,870.00 | 1,343.00 | 3,213.00 | LF | 3,213.00 | \$1.00 | \$3,213.0 |
| | | 0001 | 1100 | 6206001C | | 1,088.00 | 2,098.00 | 3,186.00 | LF | 3,186.00 | \$1.00 | \$3,186.0 |
| | | 0001 | 1110 | 6207001 | PAVEMENT MARKING REMOVAL | 6,978.00 | -573.00 | 6,405.00 | LF | 6,405.00 | \$0.50 | \$3,202.5 |
| | | 0001 | 1120 | 6224010 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | 203.00 | -37.00 | 166.00 | SQYD | 166.00 | \$15.00 | \$2,490.0 |
| | | 0001 | 1130 | 6240103A | PERMANENT EROSION CONTROL GEOTEXTILE | 3,621.00 | -386.00 | 3,235.00 | SQYD | 3,235.00 | \$2.50 | \$8,087.5 |
| | | 0001 | 1140 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$9,500.00 | \$9,500.0 |
| | | 0001 | 1150 | 7250424 | 24 IN. PIPE GROUP C | 219.00 | 30.00 | 249.00 | LF | 249.00 | \$55.00 | \$13,695.0 |
| | | 0001 | 1160 | 7250436 | 36 IN. PIPE GROUP C | 148.00 | 0.00 | 148.00 | LF | 148.00 | \$68.00 | \$10,064.0 |
| | | 0001 | 1170 | 8051000A | SEEDING - COOL SEASON MIXTURES | 1.00 | 0.00 | 1.00 | ACRE | 1.00 | \$3,900.00 | \$3,900.0 |
| | | 0001 | 1180 | 8061005 | ROCK DITCH CHECK | 94.00 | -94.00 | 0.00 | LF | 0.00 | \$15.00 | \$0.0 |
| | | 0001 | 1190 | 8061016 | SEDIMENT REMOVAL | 14.00 | -14.00 | 0.00 | CUYD | 0.00 | \$5.00 | \$0.0 |
| | | 0001 | 1200 | 8061017 | TEMPORARY SEEDING AND MULCHING | 1.00 | -1.00 | 0.00 | ACRE | 0.00 | \$800.00 | \$0.0 |
| | | 0001 | 1210 | 8061019 | SILT FENCE | 522.00 | -422.00 | 100.00 | LF | 100.00 | \$3.50 | \$350.0 |
| | | 0001 | 1220 | 8061050 | TYPE C BERM | 365.00 | -286.00 | 79.00 | LF | 79.00 | \$6.50 | \$513.5 |
| | | 0040 | 1230 | 9031270A | 2 IN. PSST POST - 12 GA. | 142.00 | -21.00 | 121.00 | LF | 121.00 | \$7.00 | \$847.0 |
| | | 0040 | 1240 | 9031271 | POST ANCHOR FOR 2 IN. PSST - 12 GA. | 78.00 | 0.00 | 78.00 | LF | 78.00 | \$12.00 | \$936.0 |
| | | 0040 | 1250 | 9035004A | | 18.00 | 0.00 | 18.00 | SQFT | 18.00 | \$18.00 | \$324.0 |
| | | 0040 | 1260 | 9035069A | | 72.00 | 0.00 | 72.00 | SQFT | 72.00 | \$18.00 | \$1,296.0 |
| | | 0070 | 1270 | 2061000 | CLASS 1 EXCAVATION | 60.00 | 25.00 | 85.00 | CUYD | 85.00 | \$30.00 | \$2,550.0 |
| | | 0070 | 1280 | 2160500 | REMOVAL OF BRIDGES | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$20,000.00 | \$20,000.00 |
| | | 0010 | | | | 7.00 | 2.00 | | | 1.00 | , | 0,000.0 |

Revision 4/1/2020 Page 8 of 29

7021314 GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN)

0070

196.00

121.00

317.00

317.00

\$120.00

\$38,040.00



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|-----------------|-------------|-------------|--------------|---|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 191213-H04 | J9S3224B | 0070 | 1310 | 7025001 | DYNAMIC PILE TESTING | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$2,500.00 | \$5,000.00 |
| | | 0070 | 1320 | 7032003 | CLASS B CONCRETE (SUBSTRUCTURE) | 31.00 | 0.00 | 31.00 | CUYD | 31.00 | \$980.00 | \$30,380.00 |
| | | 0070 | 1330 | 7034215 | SAFETY BARRIER CURB | 139.00 | 0.00 | 139.00 | LF | 139.00 | \$100.00 | \$13,900.00 |
| | | 0070 | 1340 | 7034222 | SLAB ON CONCRETE BEAM | 156.00 | 0.00 | 156.00 | SQYD | 156.00 | \$450.00 | \$70,200.00 |
| | | 0070 | 1350 | 7056065 | 17 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM | 152.00 | 0.00 | 152.00 | LF | 152.00 | \$285.00 | \$43,320.00 |
| | | 0070 | 1360 | 7123610 | SLAB DRAIN | 10.00 | 0.00 | 10.00 | EA | 10.00 | \$220.00 | \$2,200.00 |
| | | 0070 | 1370 | 7151001 | VERTICAL DRAIN AT END BENTS | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,500.00 | \$3,000.00 |
| | | 0070 | 1380 | 7161000 | PLAIN NEOPRENE BEARING PAD | 6.00 | 0.00 | 6.00 | EA | 6.00 | \$200.00 | \$1,200.00 |
| | | 0071 | 1390 | 2061000 | CLASS 1 EXCAVATION | 50.00 | -12.00 | 38.00 | CUYD | 38.00 | \$30.00 | \$1,140.00 |
| | | 0071 | 1400 | 2160500 | REMOVAL OF BRIDGES | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$15,000.00 | \$15,000.00 |
| | | 0071 | 1410 | 5031011A | BRIDGE APPROACH SLAB (MINOR ROAD) | 113.00 | 0.00 | 113.00 | SQYD | 113.00 | \$130.00 | \$14,690.00 |
| | | 0071 | 1420 | 7021314 | GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN) | 176.00 | 193.00 | 369.00 | LF | 369.00 | \$120.00 | \$44,280.00 |
| | | 0071 | 1430 | 7025001 | DYNAMIC PILE TESTING | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$2,500.00 | \$5,000.00 |
| | | 0071 | 1440 | 7032003 | CLASS B CONCRETE (SUBSTRUCTURE) | 28.80 | 0.00 | 28.80 | CUYD | 28.80 | \$1,050.00 | \$30,240.00 |
| | | 0071 | 1450 | 7034215 | SAFETY BARRIER CURB | 107.00 | 0.00 | 107.00 | LF | 107.00 | \$105.00 | \$11,235.00 |
| | | 0071 | 1460 | 7034222 | SLAB ON CONCRETE BEAM | 156.00 | 0.00 | 156.00 | SQYD | 156.00 | \$450.00 | \$70,200.00 |
| | | 0071 | 1470 | 7056065 | 17 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM | 152.00 | 0.00 | 152.00 | LF | 152.00 | \$285.00 | \$43,320.00 |
| | | 0071 | 1480 | 7123610 | SLAB DRAIN | 10.00 | 0.00 | 10.00 | EA | 10.00 | \$220.00 | \$2,200.00 |
| | | 0071 | 1490 | 7151001 | VERTICAL DRAIN AT END BENTS | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,500.00 | \$3,000.00 |
| | | 0071 | 1500 | 7161000 | PLAIN NEOPRENE BEARING PAD | 6.00 | 0.00 | 6.00 | EA | 6.00 | \$200.00 | \$1,200.00 |
| | Project J95 | 3224B - To | otal Value | Posted to D | Date as of Report Generated Date | | | | | | | \$797,361.20 |
| 191213-H04 Ove | erall - Total V | /alue Poste | d to Date | as of Repor | t Generated Date | | | | | | | \$2,253,402.10 |

Page 9 of 29 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work,

Project: J9S3224

| Line umber | Item Code | Description | DWR Date | DWR Approval Date | Quantity Posted | Units | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|---------------|--------------|--|-------------|-------------------------|--------------------|-------|--|---------------------------------|---------------------|-------------------------------|---------------------|----------|
| 0260 | 6206000C | 4 IN. WHITE WATERBORNE PAVEMENT MARKING | 9/16/20 | 9/21/20 | 1,092.00 | LF | Br. A8747 north edge line | 240+70 | LT | 251+62 | LT | |
| | | | | 9/21/20 | 1,125.00 | LF | Br. A8747 south edge line | 240+70 | RT | 251+95 | RT | |
| 0270 | 6206001C | 4 IN. YELLOW WATERBORNE PAVEMENT MARKING | 9/16/20 | 9/21/20 | 250.00 | LF | Br. A8747 yellow skips for EBL (25 skips x 10-ft) | 246+50 | CL | 256+50 | CL | |
| | | | | 9/21/20 | 1,032.00 | LF | Br. A8747 solid yellow no passing for WBL | 246+50 | CL | 256+82 | CL | |
| | | | | 9/21/20 | 1,140.00 | LF | Br. A8747 double yellow (570-ft x 2) | 240+80 | CL | 246+50 | CL | |
| 0280 | 6207001 | PAVEMENT MARKING REMOVAL | 9/16/20 | 9/21/20 | 322.00 | LF | Br. A8747 southwest white edge line | 240+70 | RT | 243+92 | RT | |
| | | | | 9/21/20 | 328.00 | LF | Br. A8747 northwest white edge line | 240+70 | LT | 243+98 | LT | |
| | | | | 9/21/20 | 402.00 | LF | Br. A8747 northeast white edge line | 247+60 | LT | 251+62 | LT | |
| | | | | 9/21/20 | 435.00 | LF | Br. A8747 southeast white edge line | 247+60 | RT | 251+95 | RT | |
| | | | | 9/21/20 | 540.00 | LF | Br. A8747 single solid yellow removal for EBL skips. | 251+42 | CL | 256+82 | CL | |

Revision 4/1/2020 Page 10 of 29



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|------------------------|--|
| 0040 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Material | Туро | 8 | Jun 2, 2020 | SYSTEM | (\$1,620.00) | |
| | | | | 8 | Jun 2, 2020 | SYSTEM | \$1,620.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 9 | Jun 16, 2020 | SYSTEM | (\$1,620.00) | |
| | | | | 9 | Jun 16, 2020 | SYSTEM | \$1,620.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 10 | Jul 1, 2020 | SYSTEM | (\$8,802.60) | |
| | | | | 10 | Jul 1, 2020 | SYSTEM | \$8,802.60 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0040 - | Total | | | | | | \$0.00 | |
| 0050 | MISC. TYPE 1 OR TYPE 5 AGGR BASE | Material | | 8 | Jun 2, 2020 | SYSTEM | (\$1,105.92) | |
| | | | | 8 | Jun 2, 2020 | SYSTEM | \$1,105.92 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 9 | Jun 16, 2020 | SYSTEM | (\$1,105.92) | |
| | | | | 9 | Jun 16, 2020 | SYSTEM | \$1,105.92 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 10 | Jul 1, 2020 | SYSTEM | (\$1,105.92) | |
| | | | | 10 | Jul 1, 2020 | SYSTEM | \$1,105.92 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0050 - | GRAVEL (A) OR CRUSHED STONE (B) | Material | | 8 | Jun 2, 2020 | SYSTEM | \$0.00 (\$1,190.00) | |
| | | | | 8 | Jun 2, 2020 | SYSTEM | \$1,190.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 9 | Jun 16, 2020 | SYSTEM | (\$1,190.00) | |
| | | | | 9 | Jun 16, 2020 | SYSTEM | \$1,190.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 10 | Jul 1, 2020 | SYSTEM | (\$1,190.00) | |
| | | | | 10 | Jul 1, 2020 | SYSTEM | \$1,190.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0060 - | | | | | | | \$0.00 | |
| 0070 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) | Material | | 8 | Jun 2, 2020 | SYSTEM | (\$9,981.00) | |
| | | | | 8 | Jun 2, 2020 | SYSTEM | \$9,981.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 4 on the current |

Revision 4/1/2020 Page 11 of 29



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|---|--------------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| 0070 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) | Material | | | | | | Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) | Other Item Adjustment | ACAD | 8 | Jun 2, 2020 | chronf1 | (\$191.30) | ACAD for 110.9 Tons of BB17-41. |
| | | | | 10 | Jul 1, 2020 | chronf1 | (\$852.97) | ACAD for 329.65 Tons of BB17-41. |
| | | | | 13 | Aug 17, 2020 | chronf1 | (\$1,320.15) | ACAD for 62.73 Tons of BB17-41. |
| | | | | 15 | Sep 16, 2020 | chronf1 | (\$76.53) | ACAD for 26.62 Tons of BB17-41. |
| | | | | 16 | Oct 1, 2020 | chronf1 | \$1,320.15 | ACAD correction for 62.73 Tons of BB17-41 on Estimate No. 13. Actual adjustment is -\$180.35. |
| | | | | 16 | Oct 1, 2020 | chronf1 | (\$180.35) | ACAD correction for 62.73 Tons of BB17-41. |
| | | | ACAD - Tota | al | | | (\$1,301.15) | |
| | Other Item Adjustment - Total | | | | | | (\$1,301.15) | |
| 0070 - | Total | | | | | | (\$1,301.15) | |
| 0800 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | Material | | 8 | Jun 2, 2020 | SYSTEM | (\$5,787.00) | |
| | | | | 8 | Jun 2, 2020 | SYSTEM | \$5,787.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | Other Item Adjustment | ACAD | 8 | Jun 2, 2020 | chronf1 | (\$116.80) | ACAD for 53.7 Tons of SL20-25. |
| | | | | 10 | Jul 1, 2020 | chronf1 | (\$189.23) | ACAD for 58.0 Tons of SL20-25. |
| | | | | 10 | Jul 1, 2020 | chronf1 | \$33.93 | ACAD for -15.6 Tons of SL20-25. Overpayment was made on Estimate No. 8. Estimate No. 8 Price Index used for calculation. 38.1 Tons should have been used for ACAD instead of 53.7 Tons (38.1 - 53.7 = -15.6). |
| | | | | 13 | Aug 17, 2020 | chronf1 | (\$1,942.10) | ACAD for 73.19 Tons of SL20-25. |
| | | | | 15 | Sep 16, 2020 | chronf1 | (\$87.15) | ACAD for 41.01 Tons of SL20-37. |
| | | | | 16 | Oct 1, 2020 | chronf1 | \$1,942.10 | ACAD correction for 73.19 Tons of SL20-25 on Estimate No. 13. Actual adjustment is -\$265.31. |
| | | | | 16 | Oct 1, 2020 | chronf1 | (\$265.31) | ACAD correction for 73.19 Tons of SL20-25. |
| | | | ACAD - Tota | al | | | (\$624.56) | |
| | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | | OTHR | | Sep 16, 2020 | chronf1 | | Withheld pending performance of segregated areas under traffic. |
| | | | OTHR - Tota | al | | | (\$2,500.00) | |
| | Other Item Adjustment - Total | | | | | | (\$3,124.56) | |
| 0080 - | Total | | | | | | (\$3,124.56) | |
| 0090 | MISC. OPTIONAL PAVEMENT | Material | | 8 | Jun 2, 2020 | SYSTEM | (\$6,186.28) | |
| | | | | 8 | Jun 2, 2020 | SYSTEM | \$6,186.28 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | MISC. OPTIONAL PAVEMENT | Other Item Adjustment | ACAD | 8 | Jun 2, 2020 | chronf1 | (\$105.81) | ACAD for 106.66 SY (BB17-41 and SL20-25). |
| | | | | 10 | Jul 1, 2020 | chronf1 | (\$155.75) | ACAD for 106.66 SY. |
| | | | | 13 | Aug 17, 2020 | chronf1 | (\$1,266.77) | ACAD for 106.66 SY. |

Revision 4/1/2020 Page 12 of 29



| Remarks |
|--|
| nomano |
| r 106.66 SY on Estimate No. 13. Actual i.09. |
| r 106.66 SY plus 0.02 SY rounding correction. |
| |
| |
| |
| |
| sets the original system-generated Overrun tem Adjustment (0009) due to user chronf1 at Estimate Exception 7 on the current |
| |
| sets the original system-generated Overrun tem Adjustment (0010) due to user chronf1 nt Estimate Exception 4 on the current |
| |
| sets the original system-generated Overrun tem Adjustment (0004) due to user chronf1 nt Estimate Exception 6 on the current |
| |
| sets the original system-generated Overrun tem Adjustment (0001) due to user chronf1 nt Estimate Exception 1 on the current |
| |
| |
| |
| |
| |
| sets the original system-generated Overrun tem Adjustment (0030) due to user chronf1 nt Estimate Exception 11 on the current |
| tem Adjustment (0030) due to user chronf1 |
| tem Adjustment (0030) due to user chronf1 tt Estimate Exception 11 on the current ustment from this item on all previous payment |
| tem Adjustment (0030) due to user chronf1 It Estimate Exception 11 on the current ustment from this item on all previous payment 00' is applied (if non-zero). sets the original system-generated Overrun tem Adjustment (0001) due to user chronf1 It Estimate Exception 7 on the current |
| tem Adjustment (0030) due to user chronf1 It Estimate Exception 11 on the current ustment from this item on all previous payment 00' is applied (if non-zero). sets the original system-generated Overrun tem Adjustment (0001) due to user chronf1 It Estimate Exception 7 on the current |
| tem Adjustment (0030) due to user chronf1 It Estimate Exception 11 on the current ustment from this item on all previous payment 00' is applied (if non-zero). sets the original system-generated Overrun tem Adjustment (0001) due to user chronf1 It Estimate Exception 7 on the current |
| tem Adjustment (0030) due to user chronf1 at Estimate Exception 11 on the current ustment from this item on all previous payment 00' is applied (if non-zero). sets the original system-generated Overrun tem Adjustment (0001) due to user chronf1 at Estimate Exception 7 on the current |
| tem Adjustment (0030) due to user chronf1 It Estimate Exception 11 on the current ustment from this item on all previous payment 00' is applied (if non-zero). sets the original system-generated Overrun tem Adjustment (0001) due to user chronf1 It Estimate Exception 7 on the current |
| tem Adjustment (0030) due to user chronf1 at Estimate Exception 11 on the current ustment from this item on all previous payment 00' is applied (if non-zero). sets the original system-generated Overrun tem Adjustment (0001) due to user chronf1 at Estimate Exception 7 on the current sets the original system-generated Overrun tem Adjustment (0031) due to user chronf1 |
| tem Adjustment (0030) due to user chronf1 at Estimate Exception 11 on the current ustment from this item on all previous payment 00' is applied (if non-zero). sets the original system-generated Overrun tem Adjustment (0001) due to user chronf1 at Estimate Exception 7 on the current sets the original system-generated Overrun tem Adjustment (0031) due to user chronf1 at Estimate Exception 12 on the current |
| tem Adjustment (0030) due to user chronf1 It Estimate Exception 11 on the current ustment from this item on all previous payment 00' is applied (if non-zero). sets the original system-generated Overrun tem Adjustment (0001) due to user chronf1 Int Estimate Exception 7 on the current sets the original system-generated Overrun tem Adjustment (0031) due to user chronf1 Int Estimate Exception 12 on the current usustment from this item on all previous payment 00' is applied (if non-zero). sets the original system-generated Overrun tem Adjustment (0002) due to user chronf1 tem Adjustment (0002) due to user chronf1 |
| tem Adjustment (0030) due to user chronf1 It Estimate Exception 11 on the current ustment from this item on all previous payment 00' is applied (if non-zero). sets the original system-generated Overrun tem Adjustment (0001) due to user chronf1 Int Estimate Exception 7 on the current sets the original system-generated Overrun tem Adjustment (0031) due to user chronf1 Int Estimate Exception 12 on the current ustment from this item on all previous payment 00' is applied (if non-zero). sets the original system-generated Overrun tem Adjustment (0002) due to user chronf1 tem Adjustment (0002) due to user chronf1 |
| tem Adjustment (0030) due to user chronf1 It Estimate Exception 11 on the current ustment from this item on all previous payment 00' is applied (if non-zero). sets the original system-generated Overrun tem Adjustment (0001) due to user chronf1 Int Estimate Exception 7 on the current sets the original system-generated Overrun tem Adjustment (0031) due to user chronf1 Int Estimate Exception 12 on the current ustment from this item on all previous payment 00' is applied (if non-zero). sets the original system-generated Overrun tem Adjustment (0002) due to user chronf1 tem Adjustment (0002) due to user chronf1 |
| |

Revision 4/1/2020 Page 13 of 29



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------------------|--|--------------------|-----------------------------|----------------|--|----------------------|--|---|
| 0190 | CONSTRUCTION SIGNS | Material | | 2 | Mar 2, 2020 | SYSTEM | \$3,776.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0190 - | - Total | | | | | | \$0.00 | |
| 0200 | ADVANCED WARNING RAIL SYSTEM | Material | | 2 | Mar 2, 2020 | SYSTEM | (\$560.00) | |
| | | | | 2 | Mar 3, 2020 | SYSTEM | \$560.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 3 | Mar 17, 2020 | SYSTEM | (\$560.00) | |
| | | | - Total | | | | (\$560.00) | |
| | Material - Total | | | | | | (\$560.00) | |
| | ADVANCED WARNING RAIL SYSTEM | MaterialCredit | | 4 | Apr 2, 2020 | SYSTEM | \$560.00 | |
| | | | - Total | | | | \$560.00 | |
| | MaterialCredit - Total | | | | | | \$560.00 | |
| | ADVANCED WARNING RAIL SYSTEM | Overrun | Overrun | 2 | Mar 2, 2020 | SYSTEM | (\$280.00) | |
| | | | | 2 | Mar 2, 2020 | SYSTEM | \$280.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | 3 | Mar 17, 2020 | SYSTEM | (\$280.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | 3 | Mar 17, 2020 | SYSTEM | \$280.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | Overrun - To | otal | | | \$0.00 | |
| | Overrun - Total | | | | | | \$0.00 | |
| 0200 - | - Total | | | | | | \$0.00 | |
| 0210 | FLAG ASSEMBLY | Material | | 2 | Mar 2, 2020 | SYSTEM | (\$160.00) | |
| | | | | 2 | Mar 2, 2020 | SYSTEM | \$160.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridating Payment Estimate Exception 5 on the current |
| | | | - Total | | | | | Payment Estimate. |
| | Material - Total | | | | | | \$0.00 | Payment Esumate. |
| | | | | | | | \$0.00 \$0.00 | Payment Estimate. |
| | FLAG ASSEMBLY | Overrun | Overrun | 2 | Mar 2, 2020 | SYSTEM | | Payment Estimate. |
| | FLAG ASSEMBLY | Overrun | Overrun | 2 | | SYSTEM SYSTEM | \$0.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | FLAG ASSEMBLY | Overrun | Overrun | | 2020 Mar 2, | | \$0.00 (\$80.00) | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment |
| | FLAG ASSEMBLY | Overrun | Overrun | 2 | 2020 Mar 2, 2020 Mar 17, | SYSTEM | \$0.00 (\$80.00) \$80.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 9 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment |
| | FLAG ASSEMBLY | Overrun | Overrun - To | 3 | 2020 Mar 2, 2020 Mar 17, 2020 | SYSTEM SYSTEM | \$0.00 (\$80.00) \$80.00 (\$80.00) | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 9 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 6 on the current |
| | FLAG ASSEMBLY Overrun - Total | Overrun | | 3 | 2020 Mar 2, 2020 Mar 17, 2020 | SYSTEM SYSTEM | \$0.00 (\$80.00) \$80.00 (\$80.00) | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 9 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 6 on the current |
| 0210 - | | Overrun | | 3 | 2020 Mar 2, 2020 Mar 17, 2020 | SYSTEM SYSTEM | \$0.00 (\$80.00) \$80.00 (\$80.00) \$80.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 9 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 6 on the current |
| 0210 - 0240 | Overrun - Total | | | 3 | 2020 Mar 2, 2020 Mar 17, 2020 | SYSTEM SYSTEM | \$0.00 (\$80.00) \$80.00 (\$80.00) \$0.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 9 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 6 on the current |
| | Overrun - Total Total CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR | | | 2 3 3 3 Dotal | 2020 Mar 2, 2020 Mar 17, 2020 Mar 17, 2020 | SYSTEM SYSTEM SYSTEM | \$0.00 (\$80.00) \$80.00 (\$80.00) \$80.00 \$0.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 9 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 6 on the current |
| | Overrun - Total Total CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR | | Overrun - To | 2 3 3 3 Dotal | 2020 Mar 2, 2020 Mar 17, 2020 Mar 17, 2020 | SYSTEM SYSTEM SYSTEM | \$0.00 (\$80.00) \$80.00 (\$80.00) \$80.00 \$0.00 \$0.00 (\$6,000.00) | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 9 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 6 on the current |
| | Overrun - Total Total CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | Material | Overrun - To | 2 3 3 3 Dotal | 2020 Mar 2, 2020 Mar 17, 2020 Mar 17, 2020 | SYSTEM SYSTEM SYSTEM | \$0.00 (\$80.00) \$80.00 (\$80.00) \$80.00 \$0.00 \$0.00 (\$6,000.00) | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 9 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 6 on the current |

Revision 4/1/2020 Page 14 of 29



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|--|--------------------------|-----------------------------|----------------|-----------------|---------------|--------------|--|
| 0240 | INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | MaterialCredit | | | | | | |
| | | | - Total | | | | \$6,000.00 | |
| | MaterialCredit - Total | | | | | | \$6,000.00 | |
| 0240 - | · Total | | | | | | \$0.00 | |
| 0260 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P | Other Item Adjustment | OTHR | 9 | Jun 16, 2020 | chronf1 | (\$283.25) | 50% of payment withheld on this estimate pending retroreflectivity results. |
| | BEADS | | | 10 | Jul 1, 2020 | chronf1 | \$283.25 | Payment for 50% of posting that was previously withheld (retroreflectivity results accepted). |
| | | | | 14 | Sep 2, 2020 | chronf1 | (\$525.50) | 50% of payment withheld on this estimate pending retroreflectivity results. |
| | | | | 15 | Sep 16, 2020 | chronf1 | \$525.50 | Payment for 50% of posting that was previously withheld (retroreflectivity results accepted). |
| | | | | 16 | Oct 1, 2020 | chronf1 | (\$221.70) | 20% of payment withheld on this estimate pending retroreflectivity results. |
| | | | OTHR - Tota | al | | | (\$221.70) | |
| | Other Item Adjustment - Total | | | | | | (\$221.70) | |
| | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Overrun | Overrun | 16 | Sep 30, 2020 | SYSTEM | (\$612.50) | |
| | DEADO | | | 16 | Oct 1, 2020 | SYSTEM | \$612.50 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | Overrun - T | otal | | | \$0.00 | |
| | Overrun - Total | | | | | | \$0.00 | |
| 0260 - | Total | | | | | | (\$221.70) | |
| 0270 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING | Other Item Adjustment | OTHR | 9 | Jun 16, 2020 | chronf1 | (\$132.50) | 50% of payment withheld on this estimate pending retroreflectivity results. |
| | PAINT, TYPE P BEADS | | | 10 | Jul 1, 2020 | chronf1 | \$132.50 | Payment for 50% of posting that was previously withheld (retroreflectivity results accepted). |
| | | | | 14 | Sep 2, 2020 | chronf1 | (\$272.50) | 50% of payment withheld on this estimate pending retroreflectivity results. |
| | | | | 15 | Sep 16, 2020 | chronf1 | \$272.50 | Payment for 50% of posting that was previously withheld (retroreflectivity results accepted). |
| | | | | 16 | Oct 1, 2020 | chronf1 | (\$242.20) | 20% of payment withheld on this estimate pending retroreflectivity results. |
| | | | OTHR - Tota | al | | | (\$242.20) | |
| | Other Item Adjustment - Total | | | | | | (\$242.20) | |
| 0270 - | Total | | | | | | (\$242.20) | |
| 0280 | PAVEMENT MARKING REMOVAL | Overrun | Overrun | 16 | Sep 30, 2020 | SYSTEM | (\$509.00) | |
| | | | | 16 | Oct 1, 2020 | SYSTEM | \$509.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | Overrun - T | otal | | | \$0.00 | |
| | Overrun - Total | | | | | | \$0.00 | |
| 0280 - | Total | | | | | | \$0.00 | |
| 0290 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | Overrun | Overrun | 13 | Aug 17, 2020 | SYSTEM | (\$2,329.50) | |
| | | | | 13 | Aug 17, 2020 | SYSTEM | \$2,329.50 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | 14 | Sep 2, 2020 | SYSTEM | (\$2,329.50) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | 14 | Sep 2, 2020 | SYSTEM | \$2,329.50 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | 15 | Sep 17, 2020 | SYSTEM | (\$3,255.00) | |
| | | | | 15 | Sep 17, | SYSTEM | \$1,821.00 | This adjustment offsets the original system-generated Overrun |

Revision 4/1/2020 Page 15 of 29



| Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks |
|--------|---|------------|--------------------|------|-----------------|---------|------------------------------|--|
| Lille | Description | Type | Adjustment Type | | Date | By | Amount | iveinalis |
| 0290 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | Overrun | Overrun | | 2020 | | | Payment Estimate Item Adjustment (0032) due to user chronf1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | 15 | Sep 17, 2020 | SYSTEM | \$1,434.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user chronf1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | 16 | Sep 30, 2020 | SYSTEM | (\$3,255.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | 16 | Oct 1, 2020 | SYSTEM | \$3,255.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | Overrun - T | otal | | | \$0.00 | |
| | Overrun - Total | | | | | | \$0.00 | |
| 0290 - | - Total | | | | | | \$0.00 | |
| 0360 | SEEDING - COOL SEASON MIXTURES | Material | | 8 | Jun 2, 2020 | SYSTEM | (\$780.00) | |
| | | | | 8 | Jun 2, 2020 | SYSTEM | \$780.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0360 - | - Total | | | | | | \$0.00 | |
| 0400 | SILT FENCE | Material | | 7 | May 19, 2020 | SYSTEM | (\$1,635.00) | |
| | | | | 7 | May 19, 2020 | SYSTEM | \$1,635.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0400 - | - Total | | | | | | \$0.00 | |
| 0410 | TYPE C BERM | Material | | 13 | Aug 17, 2020 | SYSTEM | (\$782.00) | |
| | | | | 13 | Aug 17, 2020 | SYSTEM | \$782.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0410 - | - Total | | | | | | \$0.00 | |
| 0460 | CLASS 1 EXCAVATION | Overrun | Overrun | 14 | Sep 2, 2020 | SYSTEM | (\$1,240.00) | |
| | | | | 14 | Sep 2, 2020 | SYSTEM | \$1,240.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | Overrun - T | otal | | | \$0.00 | |
| | Overrun - Total | | | | | | \$0.00 | |
| 0460 - | - Total | | | | | | \$0.00 | |
| | l | Material | | 15 | Sep 17, 2020 | SYSTEM | (\$14,985.00) | |
| 0480 | BRIDGE APPROACH SLAB (MINOR ROAD) | iviaterial | | | 2020 | | | |
| 0480 | | iviaterial | | 15 | Sep 17, 2020 | SYSTEM | \$14,985.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| 0480 | | waterial | | 15 | Sep 17, | SYSTEM | \$14,985.00 (\$14,985.00) | Payment Estimate Item Adjustment (0034) due to user chronf1 overridding Payment Estimate Exception 1 on the current |
| 0480 | | waterial | | | Sep 17, 2020 | | | Payment Estimate Item Adjustment (0034) due to user chronf1 overridding Payment Estimate Exception 1 on the current |

Revision 4/1/2020 Page 16 of 29



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|--|--------------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| 0480 | Material - Total | | | | | | \$0.00 | |
| | BRIDGE APPROACH SLAB (MINOR ROAD) | Other Item Adjustment | ACAD | 15 | Sep 16, 2020 | chronf1 | (\$206.04) | ACAD for 111 SY. |
| | | | ACAD - Tota | al | | | (\$206.04) | |
| | Other Item Adjustment - Total | | | | | | (\$206.04) | |
| 0480 - | - Total | | | | | | (\$206.04) | |
| 0490 | GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN) | Material | | 13 | Aug 17, 2020 | SYSTEM | (\$50,125.00) | |
| | | | | 13 | Aug 17, 2020 | SYSTEM | \$50,125.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 14 | Sep 2, 2020 | SYSTEM | (\$50,125.00) | |
| | | | | 14 | Sep 2, 2020 | SYSTEM | \$50,125.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 15 | Sep 17, 2020 | SYSTEM | (\$50,125.00) | |
| | | | | 15 | Sep 17, 2020 | SYSTEM | \$50,125.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN) | Overrun | Overrun | 13 | Aug 17, 2020 | SYSTEM | (\$23,125.00) | |
| | | Overrun | | 13 | Aug 17, 2020 | SYSTEM | \$23,125.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | 14 | Sep 2, 2020 | SYSTEM | (\$23,125.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | 14 | Sep 2, 2020 | SYSTEM | \$23,125.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | Overrun - T | otal | | | \$0.00 | |
| | Overrun - Total | | | | | | \$0.00 | |
| 0490 - | - Total | | | | | | \$0.00 | |
| 0510 | CLASS B CONCRETE (SUBSTRUCTURE) | Material | | 14 | Sep 2, 2020 | SYSTEM | (\$30,380.00) | |
| | | | | 14 | Sep 2, 2020 | SYSTEM | \$30,380.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 15 | Sep 17, 2020 | SYSTEM | (\$30,380.00) | |
| | | | | 15 | Sep 17, 2020 | SYSTEM | \$30,380.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0510 - | - Total | | | | | | \$0.00 | |
| 0520 | SAFETY BARRIER CURB | Material | | 15 | Sep 17, 2020 | SYSTEM | (\$14,595.00) | |
| | | | | 15 | Sep 17, 2020 | SYSTEM | \$14,595.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | 16 | Sep 30, 2020 | SYSTEM | (\$14,595.00) | |
| | | | | 16 | Oct 1, 2020 | SYSTEM | \$14,595.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |

Revision 4/1/2020 Page 17 of 29



| Line | Description | Adjustment Type | Other Adjustment | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|-----------------------|--------------------|---------------------|----------------|-----------------|---------------|---------------|--|
| | | | Туре | | | , | | |
| 0520 | | Material | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0520 - | Total | | | | | | \$0.00 | |
| 0530 | SLAB ON CONCRETE BEAM | Material | | 14 | Sep 2, 2020 | SYSTEM | (\$63,640.00) | |
| | | | | 14 | Sep 2, 2020 | SYSTEM | \$63,640.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | 15 | Sep 17, 2020 | SYSTEM | (\$67,080.00) | |
| | | | | 15 | Sep 17, 2020 | SYSTEM | \$67,080.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user chronf1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0530 | · Total | | | | | | \$0.00 | |
| 0590 | SLAB ON STEEL | Material | | 6 | May 4, 2020 | SYSTEM | (\$33,750.00) | |
| | | | | 6 | May 5, 2020 | SYSTEM | \$33,750.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | 7 | May 19, 2020 | SYSTEM | (\$91,800.00) | |
| | | | | 7 | May 19, 2020 | SYSTEM | \$91,800.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | 8 | Jun 2, 2020 | SYSTEM | (\$96,750.00) | |
| | | | | 8 | Jun 2, 2020 | SYSTEM | \$96,750.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user chronf1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | 9 | Jun 16, 2020 | SYSTEM | (\$96,750.00) | |
| | | | | 9 | Jun 16, 2020 | SYSTEM | \$96,750.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | 10 | Jul 1, 2020 | SYSTEM | (\$96,750.00) | |
| | | | | 10 | Jul 1, 2020 | SYSTEM | \$96,750.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0590 | · Total | | | | | | \$0.00 | |
| 0600 | SAFETY BARRIER CURB | Material | | 8 | Jun 2, 2020 | SYSTEM | (\$14,500.00) | |
| | | | | 8 | Jun 2, 2020 | SYSTEM | \$14,500.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user chronf1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | 10 | Jul 1, 2020 | SYSTEM | (\$14,500.00) | |
| | | | | 10 | Jul 1, 2020 | SYSTEM | \$14,500.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0600 | · Total | | | | | | \$0.00 | |
| | | | | | | | | |

Revision 4/1/2020 Page 18 of 29



| Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks |
|----------------|---|------------|--------------------|-----------------------------------|--|--|---|--|
| | · | Туре | Adjustment Type | Number | Date | Ву | | |
| 0610 | SUBSTRUCTURE REPAIR (FORMED) | Material | | 7 | May 19, 2020 | SYSTEM | (\$690.00) | |
| | | | | 7 | May 19, 2020 | SYSTEM | \$690.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user chronf1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0610 - | - Total | | | | | | \$0.00 | |
| 0620 | CLEANING AND EPOXY COATING | Material | | 15 | Sep 17, 2020 | SYSTEM | (\$5,489.00) | |
| | | | | 15 | Sep 17, 2020 | SYSTEM | \$5,489.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user chronf1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | 16 | Sep 30, 2020 | SYSTEM | (\$5,489.00) | |
| | | | - Total | | | | (\$5,489.00) | |
| | Material - Total | | | | | | (\$5,489.00) | |
| | - Total | | | | | | (\$5,489.00) | |
| 0630 | FABRICATED STRUCTURAL LOW ALLOY STEEL (I-BEAM) A709, GRADE 50 | Material | | 6 | May 4, 2020 | SYSTEM | (\$55,430.00) | |
| | | | | 6 | May 5, 2020 | SYSTEM | \$55,430.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | 7 | May 19, 2020 | SYSTEM | (\$55,430.00) | |
| | | | | 7 | May 19, 2020 | SYSTEM | \$55,430.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user chronf1 overridding Payment Estimate Exception 9 on the current |
| | | | | | | | | Payment Estimate. |
| | | | - Total | | | | \$0.00 | Payment Estimate. |
| | Material - Total | | - Total | | | | \$0.00 \$0.00 | Payment Estimate. |
| 0630 - | Material - Total - Total | | - Total | | | | | Payment Estimate. |
| 0630 · 0670 | | Material | - Total | 7 | May 19, 2020 | SYSTEM | \$0.00 | Payment Estimate. |
| | Total LAMINATED NEOPRENE BEARING PAD | Material | - Total | 7 | | SYSTEM SYSTEM | \$0.00 \$0.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | Total LAMINATED NEOPRENE BEARING PAD | Material | - Total | | 2020 May 19, | | \$0.00 \$0.00 (\$10,400.00) | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 10 on the current |
| | Total LAMINATED NEOPRENE BEARING PAD | Material | - Total | 7 | 2020 May 19, 2020 Jun 2, | SYSTEM | \$0.00 \$0.00 (\$10,400.00) \$10,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 10 on the current |
| | Total LAMINATED NEOPRENE BEARING PAD | Material | - Total | 7 | 2020 May 19, 2020 Jun 2, 2020 Jun 2, | SYSTEM | \$0.00 \$0.00 (\$10,400.00) \$10,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 14 on the current |
| | Total LAMINATED NEOPRENE BEARING PAD | Material | - Total | 7 8 8 | 2020 May 19, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, | SYSTEM SYSTEM | \$0.00 \$0.00 (\$10,400.00) \$10,400.00 (\$10,400.00) | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 14 on the current |
| | Total LAMINATED NEOPRENE BEARING PAD | Material | - Total | 7 8 8 9 | 2020 May 19, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, | SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 (\$10,400.00) \$10,400.00 (\$10,400.00) (\$10,400.00) | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 10 on the current |
| | Total LAMINATED NEOPRENE BEARING PAD | Material | - Total | 7 8 8 8 9 | 2020 May 19, 2020 Jun 2, 2020 Jun 2, 2020 Jun 16, 2020 Jun 16, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 (\$10,400.00) \$10,400.00 (\$10,400.00) \$10,400.00 \$10,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 10 on the current |
| | Total LAMINATED NEOPRENE BEARING PAD | Material | - Total | 7 8 8 9 9 | 2020 May 19, 2020 Jun 2, 2020 Jun 16, 2020 Jul 1, 2020 Jul 1, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 (\$10,400.00) \$10,400.00 (\$10,400.00) \$10,400.00 (\$10,400.00) | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user chronf1 overridding Payment Estimate Item Adjustment (0011) due to user chronf1 overridding Payment Estimate Exception 15 on the current |
| | Total LAMINATED NEOPRENE BEARING PAD | Material | - Total | 7 8 8 9 9 10 | 2020 May 19, 2020 Jun 2, 2020 Jun 16, 2020 Jul 1, 2020 Jul 1, 2020 Jul 1, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 (\$10,400.00) \$10,400.00 (\$10,400.00) \$10,400.00 (\$10,400.00) \$10,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user chronf1 overridding Payment Estimate Item Adjustment (0011) due to user chronf1 overridding Payment Estimate Exception 15 on the current |
| | Total LAMINATED NEOPRENE BEARING PAD | Material | - Total | 7 8 8 9 9 10 10 | 2020 May 19, 2020 Jun 2, 2020 Jun 16, 2020 Jul 1, 2020 Jul 15, 2020 Jul 15, 2020 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 (\$10,400.00) \$10,400.00 (\$10,400.00) \$10,400.00 (\$10,400.00) \$10,400.00 (\$10,400.00) | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate. |

Revision 4/1/2020 Page 19 of 29



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|--|
| 0670 - | Total | | | | | | \$0.00 | |
| 0690 | SLAB ON STEEL | Material | | 9 | Jun 16, 2020 | SYSTEM | (\$62,300.00) | |
| | | | | 9 | Jun 16, 2020 | SYSTEM | \$62,300.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | 10 | Jul 1, 2020 | SYSTEM | (\$112,585.00) | |
| | | | | 10 | Jul 1, 2020 | SYSTEM | \$112,585.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0690 - | Total | | | | | | \$0.00 | |
| 0700 | SAFETY BARRIER CURB | Material | | 10 | Jul 1, 2020 | SYSTEM | (\$17,000.00) | |
| | | | | 10 | Jul 1, 2020 | SYSTEM | \$17,000.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0700 - | Total | | | | | | \$0.00 | |
| 0720 | CLEANING AND EPOXY COATING | Material | | 15 | Sep 17, 2020 | SYSTEM | (\$5,489.00) | |
| | | | | 15 | Sep 17, 2020 | SYSTEM | \$5,489.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | 16 | Sep 30, 2020 | SYSTEM | (\$5,489.00) | |
| | | | | 16 | Oct 1, 2020 | SYSTEM | \$5,489.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0720 - | Total | | | | | | \$0.00 | |
| 0770 | LAMINATED NEOPRENE BEARING PAD ASSEMBLY | Material | | 9 | Jun 16, 2020 | SYSTEM | (\$10,400.00) | |
| | | | | 9 | Jun 16, 2020 | SYSTEM | \$10,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | 10 | Jul 1, 2020 | SYSTEM | (\$10,400.00) | |
| | | | | 10 | Jul 1, 2020 | SYSTEM | \$10,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | 11 | Jul 15, 2020 | SYSTEM | (\$10,400.00) | |
| | | | | 11 | Jul 15, 2020 | SYSTEM | \$10,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0770 - | Total | | | | | | \$0.00 | |
| 0790 | SLAB ON STEEL | Material | | 12 | Jul 31, 2020 | SYSTEM | (\$87,420.00) | |
| | | | | 12 | Jul 31, 2020 | SYSTEM | \$87,420.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |

Revision 4/1/2020 Page 20 of 29



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| 0790 | SLAB ON STEEL | Material | , | 13 | Aug 17, 2020 | SYSTEM | (\$87,420.00) | |
| | | | | 13 | Aug 17, 2020 | SYSTEM | \$87,420.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0790 - | - Total | | | | | | \$0.00 | |
| 0800 | SAFETY BARRIER CURB | Material | | 13 | Aug 17, 2020 | SYSTEM | (\$13,965.00) | |
| | | | | 13 | Aug 17, 2020 | SYSTEM | \$13,965.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | 14 | Sep 2, 2020 | SYSTEM | (\$13,965.00) | |
| | | | | 14 | Sep 2, 2020 | SYSTEM | \$13,965.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 15 | Sep 17, 2020 | SYSTEM | (\$13,965.00) | |
| | | | | 15 | Sep 17, 2020 | SYSTEM | \$13,965.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0800 - | - Total | | | | | | \$0.00 | |
| 0810 | CLEANING AND EPOXY COATING | Material | | 15 | Sep 17, 2020 | SYSTEM | (\$5,489.00) | |
| | | | | 15 | Sep 17, 2020 | SYSTEM | \$5,489.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0042) due to user chronf1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | 16 | Sep 30, 2020 | SYSTEM | (\$5,489.00) | |
| | | | | 16 | Oct 1, 2020 | SYSTEM | \$5,489.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0810 - | - Total | | | | | | \$0.00 | |
| 0860 | LAMINATED NEOPRENE BEARING PAD ASSEMBLY | Material | | 11 | Jul 15, 2020 | SYSTEM | (\$10,400.00) | |
| | | | | 11 | Jul 15, 2020 | SYSTEM | \$10,400.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0860 - | | | | | | | \$0.00 | |
| 0880 | POROUS BACKFILL | Overrun | Overrun | | Jun 2, 2020 | SYSTEM | (\$1,530.00) | |
| | | | | 8 | Jun 2, 2020 | SYSTEM | \$1,530.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user chronf1 overridding Payment Estimate Exception 21 on the current Payment Estimate. |
| | | | | 9 | Jun 16, 2020 | SYSTEM | (\$1,530.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | 9 | Jun 16, 2020 | SYSTEM | \$1,530.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 14 on the current |
| | | | | | | | | Payment Estimate. |

Revision 4/1/2020 Page 21 of 29



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|---|--------------------------|---------------------------------------|----------------|-----------------|---------------|---------------|--|
| 0880 | Overrun - Total | | , , , , , , , , , , , , , , , , , , , | | | | \$0.00 | |
| 0880 - | · Total | | | | | | \$0.00 | |
| 0900 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Material | | 6 | May 4, 2020 | SYSTEM | (\$690.00) | |
| | | | | 6 | May 5, 2020 | SYSTEM | \$690.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0900 - | | | | _ | | | \$0.00 | |
| 0910 | MISC. TYPE 1 OR TYPE 5 AGGR BASE | Material | | 6 | May 4, 2020 | SYSTEM | (\$1,619.52) | |
| | | | | 6 | May 5, 2020 | SYSTEM | \$1,619.52 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | 10 | Jul 1, 2020 | SYSTEM | (\$2,947.20) | |
| | | | | 10 | Jul 1, 2020 | SYSTEM | \$2,947.20 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0910 - | Total | | | | | | \$0.00 | |
| 0920 | GRAVEL (A) OR CRUSHED STONE (B) | Material | | 6 | May 4, 2020 | SYSTEM | (\$2,695.00) | |
| | | | | 6 | May 5, 2020 | SYSTEM | \$2,695.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0920 - | Total | | | | | | \$0.00 | |
| 0930 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) | Material | | 6 | May 4, 2020 | SYSTEM | (\$26,910.00) | |
| | | | | 6 | May 5, 2020 | SYSTEM | \$26,910.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | 7 | May 19, 2020 | SYSTEM | (\$26,910.00) | |
| | | | | 7 | May 19, 2020 | SYSTEM | \$26,910.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) | Other Item Adjustment | ACAD | 6 | May 5, 2020 | chronf1 | \$68.77 | ACAD for 299 Tons of BB17-41. |
| | | | | 9 | Jun 16, 2020 | chronf1 | (\$546.74) | ACAD for 211.3 Tons of BB17-41. |
| | | | ACAD - Tota | al | | | (\$477.97) | |
| | Other Item Adjustment - Total | | | | | | (\$477.97) | |
| | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) | Overrun | Overrun | 9 | Jun 16, 2020 | SYSTEM | (\$10,017.00) | |
| | | | | 9 | Jun 16, 2020 | SYSTEM | \$9,081.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | 9 | Jun 16, 2020 | SYSTEM | \$936.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate. |

Revision 4/1/2020 Page 22 of 29



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|---|--------------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| 0930 | | Overrun | Overrun - T | otal | | | \$0.00 | |
| | Overrun - Total | | | | | | \$0.00 | |
| 0930 - | · Total | | | | | | (\$477.97) | |
| 0940 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | Material | | 6 | May 4, 2020 | SYSTEM | (\$4,725.00) | |
| | , | | | 6 | May 5, 2020 | SYSTEM | \$4,725.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | 7 | May 19, 2020 | SYSTEM | (\$4,725.00) | |
| | | | | 7 | May 19, 2020 | SYSTEM | \$4,725.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | Other Item Adjustment | ACAD | 6 | May 5, 2020 | chronf1 | \$15.23 | ACAD for 52.5 Tons of SL20-25. |
| | | | | 9 | Jun 16, 2020 | chronf1 | (\$144.86) | ACAD for 44.4 Tons of SL20-25. |
| | | | ACAD - Tota | al | | | (\$129.63) | |
| | Other Item Adjustment - Total | | | | | | (\$129.63) | |
| 0940 - | Total | | | | | | (\$129.63) | |
| 0950 | TACK COAT | Material | | 6 | May 4, 2020 | SYSTEM | (\$451.50) | |
| | | | | 6 | May 5, 2020 | SYSTEM | \$451.50 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 0950 - | Total | | | | | | \$0.00 | |
| 1020 | CONSTRUCTION SIGNS | Material | | 2 | Mar 2, 2020 | SYSTEM | (\$1,328.00) | |
| | | | | 2 | Mar 2, 2020 | SYSTEM | \$1,328.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 1020 - | Total | | | | | | \$0.00 | |
| 1030 | ADVANCED WARNING RAIL SYSTEM | Material | | 2 | Mar 2, 2020 | SYSTEM | (\$280.00) | |
| | | | | 2 | Mar 2, 2020 | SYSTEM | \$280.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | 3 | Mar 17, 2020 | SYSTEM | (\$280.00) | |
| | | | - Total | | | | (\$280.00) | |
| | Material - Total | | | | | | (\$280.00) | |
| | ADVANCED WARNING RAIL SYSTEM | MaterialCredit | | 4 | Apr 2, 2020 | SYSTEM | \$280.00 | |
| | | | - Total | | | | \$280.00 | |
| | MaterialCredit - Total | | | | | | \$280.00 | |
| 1030 - | Total | | | | | | \$0.00 | |
| 1040 | FLAG ASSEMBLY | Material | | 2 | Mar 2, 2020 | SYSTEM | (\$80.00) | |
| | | | | 2 | Mar 2, 2020 | SYSTEM | \$80.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |

Revision 4/1/2020 Page 23 of 29



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|---|--------------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| 1040 | | Material | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 1040 - | Total | | | | | | \$0.00 | |
| 1050 | TYPE III MOVEABLE BARRICADE | Overrun | Overrun | 3 | Mar 17, 2020 | SYSTEM | (\$750.00) | |
| | | | | 3 | Mar 17, 2020 | SYSTEM | \$750.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | Overrun - Total | | | | \$0.00 | |
| | Overrun - Total | | | | | | \$0.00 | |
| 1050 - | Total | | | | | | \$0.00 | |
| 1070 | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR | Material | | 2 | Mar 2, 2020 | SYSTEM | (\$6,000.00) | |
| | FURNISHED, CONTRACTOR RETAINED | | | 2 | Mar 2, 2020 | SYSTEM | \$6,000.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user chronf1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | 3 | Mar 17, 2020 | SYSTEM | (\$6,000.00) | |
| | | | - Total | | | | (\$6,000.00) | |
| | Material - Total | | | | | | (\$6,000.00) | |
| | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | MaterialCredit | | 4 | Apr 2, 2020 | SYSTEM | \$6,000.00 | |
| | | | - Total | | | | \$6,000.00 | |
| | MaterialCredit - Total | | | | | | \$6,000.00 | |
| 1070 - | Total | | | | | | \$0.00 | |
| 1090 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P | Other Item Adjustment | OTHR | 9 | Jun 16, 2020 | chronf1 | (\$1,606.50) | 50% of payment withheld on this estimate pending retroreflectivity results. |
| | BEADS | | | 10 | Jul 1, 2020 | chronf1 | \$1,606.50 | Payment for 50% of posting that was previously withheld (retroreflectivity results accepted). |
| | OTHR - Total | | | | | | \$0.00 | |
| | Other Item Adjustment - Total | | | | | | \$0.00 | |
| | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Overrun | Overrun | 9 | Jun 16, 2020 | SYSTEM | (\$1,343.00) | |
| | 55.60 | | | 9 | Jun 16, 2020 | SYSTEM | \$1,343.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | Overrun - T | otal | | | \$0.00 | |
| | Overrun - Total | | | | | | \$0.00 | |
| 1090 - | Total | | | | | | \$0.00 | |
| 1100 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Other Item Adjustment | OTHR | 9 | Jun 16, 2020 | chronf1 | (\$946.50) | 50% of payment withheld on this estimate pending retroreflectivity results. |
| | TAINT, TIFE F DEADS | | | 10 | Jul 1, 2020 | chronf1 | \$946.50 | Payment for 50% of posting that was previously withheld (retroreflectivity results accepted). |
| | | | OTHR - Tota | al | | | \$0.00 | |
| | Other Item Adjustment - Total | | | | | | \$0.00 | |
| | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Overrun | Overrun | | Jun 16, 2020 | SYSTEM | (\$805.00) | |
| | , | | | 9 | Jun 16, 2020 | SYSTEM | \$805.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user chronf1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | Overrun - T | otal | | | \$0.00 | |
| | Overrun - Total | | | | | | \$0.00 | |
| 1100 - | Total | | | | | | \$0.00 | |
| 1150 | 24 IN. PIPE GROUP C | Material | | 5 | Apr 15, 2020 | SYSTEM | (\$3,080.00) | |
| | | | | 5 | Apr 15, | SYSTEM | \$3,080.00 | This adjustment offsets the original system-generated Overrun |

Revision 4/1/2020 Page 24 of 29



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|--------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| 1150 | 24 IN. PIPE GROUP C | Material | , | | 2020 | | | Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | 24 IN. PIPE GROUP C | Overrun | Overrun | 8 | Jun 2, 2020 | SYSTEM | (\$1,650.00) | |
| | | | | 8 | Jun 2, 2020 | SYSTEM | \$1,650.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user chronf1 overridding Payment Estimate Exception 20 on the current Payment Estimate. |
| | | | | 9 | Jun 16, 2020 | SYSTEM | (\$1,650.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | 9 | Jun 16, 2020 | SYSTEM | \$1,650.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | Overrun - T | otal | | | \$0.00 | | |
| | Overrun - Total | | | | | | \$0.00 | |
| 1150 - | Total | | | | | | \$0.00 | |
| 1160 | 36 IN. PIPE GROUP C | Material | | 5 | Apr 15, 2020 | SYSTEM | (\$10,064.00) | |
| | | | | 5 | Apr 15, 2020 | SYSTEM | \$10,064.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user chronf1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 1160 - | Total | | | | | | \$0.00 | |
| 1170 | SEEDING - COOL SEASON MIXTURES | Material | | 6 | May 4, 2020 | SYSTEM | (\$975.00) | |
| | | | | 6 | May 5, 2020 | SYSTEM | \$975.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | 7 | May 19, 2020 | SYSTEM | (\$975.00) | |
| | | | | 7 | May 19, 2020 | SYSTEM | \$975.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 1170 - | Total | | | | | | \$0.00 | |
| 1220 | TYPE C BERM | Material | | 6 | May 4, 2020 | SYSTEM | (\$513.50) | |
| | | | | 6 | May 5, 2020 | SYSTEM | \$513.50 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | 7 | May 19, 2020 | SYSTEM | (\$513.50) | |
| | | | | 7 | May 19, 2020 | SYSTEM | \$513.50 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 1220 - | Total | | | | | | \$0.00 | |
| 1230 | 2 IN. PSST POST - 12 GA. | Material | | 6 | May 4, 2020 | SYSTEM | (\$504.00) | |
| | | | | 6 | May 5, 2020 | SYSTEM | \$504.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 20 on the current Payment Estimate. |
| | | | | 7 | May 19, | SYSTEM | (\$504.00) | |

Revision 4/1/2020 Page 25 of 29



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|--|--------------------------|-----------------------------|----------------|-----------------|---------------|------------|---|
| 1230 | 2 IN. PSST POST - 12 GA. | Material | | | 2020 | | | |
| | | | | 7 | May 19, 2020 | SYSTEM | \$504.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 1230 - | Total | | | | | | \$0.00 | |
| 1240 | POST ANCHOR FOR 2 IN. PSST - 12 GA. | Material | | 6 | May 4, 2020 | SYSTEM | (\$504.00) | |
| | | | | 6 | May 5, 2020 | SYSTEM | \$504.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user chronf1 overridding Payment Estimate Exception 21 on the current Payment Estimate. |
| | | | | 7 | May 19, 2020 | SYSTEM | (\$504.00) | |
| | | | | 7 | May 19, 2020 | SYSTEM | \$504.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user chronf1 overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 1240 - | Total | | | | | | \$0.00 | |
| 1250 | SH-FLAT SHEET | Material | | 6 | May 4, 2020 | SYSTEM | (\$324.00) | |
| | | | | 6 | May 5, 2020 | SYSTEM | \$324.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user chronf1 overridding Payment Estimate Exception 22 on the current Payment Estimate. |
| | | | | 7 | May 19, 2020 | SYSTEM | (\$324.00) | |
| | | | | 7 | May 19, 2020 | SYSTEM | \$324.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user chronf1 overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 1250 - | Total | | | | | | \$0.00 | |
| 1260 | SHF-FLAT SHEET FLUORESCENT | Material | | 6 | May 4, 2020 | SYSTEM | (\$648.00) | |
| | | | | 6 | May 5, 2020 | SYSTEM | \$648.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user chronf1 overridding Payment Estimate Exception 23 on the current Payment Estimate. |
| | | | | 7 | May 19, 2020 | SYSTEM | (\$648.00) | |
| | | | | 7 | May 19, 2020 | SYSTEM | \$648.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user chronf1 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 1260 - | Total | | | | | | \$0.00 | |
| 1270 | CLASS 1 EXCAVATION | Overrun | Overrun | 7 | May 19, 2020 | SYSTEM | (\$750.00) | |
| | | | | 7 | May 19, 2020 | SYSTEM | \$750.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | Overrun - T | otal | | | \$0.00 | |
| | Overrun - Total | | | | | | \$0.00 | |
| 1270 - | Total | | | | | | \$0.00 | |
| 1290 | BRIDGE APPROACH SLAB (MINOR ROAD) | Other Item Adjustment | ACAD | 9 | Jun 16, 2020 | chronf1 | (\$193.68) | ACAD for 111 SY (BB17-41 and SL20-25). |
| | | | ACAD - Tota | al | | | (\$193.68) | |

Revision 4/1/2020 Page 26 of 29



| Line | Description | Adjustment Type | Other Adjustment | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|--|--------------------------|---------------------|----------------|-----------------|---------------|---------------|--|
| 4000 | Other bear Adirestment Total | | Туре | | | | (0400.00) | |
| 1290 | Other Item Adjustment - Total | | | | | | (\$193.68) | |
| 1300 | GALVANIZED CAST-IN-PLACE | Material | | 6 | May 4, | SYSTEM | (\$193.68) | |
| 1300 | CONCRETE PILES (14 IN) | iviateriai | | U | 2020 | STSTEW | (\$30,040.00) | |
| | | | | 6 | May 5, 2020 | SYSTEM | \$38,040.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | 7 | May 19, 2020 | SYSTEM | (\$38,040.00) | |
| | | | | 7 | May 19, 2020 | SYSTEM | \$38,040.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | 8 | Jun 2, 2020 | SYSTEM | (\$38,040.00) | |
| | | | | 8 | Jun 2, 2020 | SYSTEM | \$38,040.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user chronf1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN) | Other Item Adjustment | OTHR | 6 | May 5, 2020 | chronf1 | \$3,840.00 | This is payment for the splices on Bent 1 and Bent 2 on Br. A8748. Bent 1: 3 splices x 8LF/splice = 24LF. Bent 2: 1 splice x 8LF/splice = 8LF. Total: 32LF x \$120/LF = \$3,840. |
| | | | OTHR - Tota | al | | | \$3,840.00 | |
| | Other Item Adjustment - Total | | | | | | \$3,840.00 | |
| | GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN) | Overrun | Overrun | 6 | May 4, 2020 | SYSTEM | \$14,520.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 24 on the current Payment Estimate. |
| | | | | 6 | May 4, 2020 | SYSTEM | (\$14,520.00) | |
| | | | | 7 | May 19, 2020 | SYSTEM | (\$14,520.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | 7 | May 19, 2020 | SYSTEM | \$14,520.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | Overrun - T | otal | | | \$0.00 | |
| | Overrun - Total | | | | | | \$0.00 | |
| 1300 - | ·Total | | | | | | \$3,840.00 | |
| 1320 | CLASS B CONCRETE (SUBSTRUCTURE) | Material | | 7 | May 19, 2020 | SYSTEM | (\$30,380.00) | |
| | | | | 7 | May 19, 2020 | SYSTEM | \$30,380.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 1320 - | Total | | | | | | \$0.00 | |
| 1330 | SAFETY BARRIER CURB | Material | | 8 | Jun 2, 2020 | SYSTEM | (\$13,900.00) | |
| | | | | 8 | Jun 2, 2020 | SYSTEM | \$13,900.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | 9 | Jun 16, 2020 | SYSTEM | (\$13,900.00) | |
| | | | | 9 | Jun 16, 2020 | SYSTEM | \$13,900.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user chronf1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | 10 | Jul 1, 2020 | SYSTEM | (\$13,900.00) | |
| | | | | 10 | Jul 1, 2020 | SYSTEM | \$13,900.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user chronf1 overridding Payment Estimate Exception 12 on the current |

Revision 4/1/2020 Page 27 of 29



| Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|--------|--|--------------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| 1330 | SAFETY BARRIER CURB | Material | | | | | | Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 1330 - | Total | | | | | | \$0.00 | |
| 1340 | SLAB ON CONCRETE BEAM | Material | | 8 | Jun 2, 2020 | SYSTEM | (\$66,600.00) | |
| | | | | 8 | Jun 2, 2020 | SYSTEM | \$66,600.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user chronf1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | 10 | Jul 1, 2020 | SYSTEM | (\$70,200.00) | |
| | | | | 10 | Jul 1, 2020 | SYSTEM | \$70,200.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user chronf1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 1340 - | · Total | | | | | | \$0.00 | |
| 1410 | BRIDGE APPROACH SLAB (MINOR ROAD) | Material | | 7 | May 19, 2020 | SYSTEM | (\$14,690.00) | |
| | | | | 7 | May 19, 2020 | SYSTEM | \$14,690.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | BRIDGE APPROACH SLAB (MINOR ROAD) | Other Item Adjustment | ACAD | 6 | May 5, 2020 | chronf1 | \$17.52 | ACAD for 113 SY. |
| | | | ACAD - Tota | al | | | \$17.52 | |
| | Other Item Adjustment - Total | | | | | | \$17.52 | |
| 1410 - | · Total | | | | | | \$17.52 | |
| 1420 | GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN) | Material | | 4 | Apr 2, 2020 | SYSTEM | (\$44,280.00) | |
| | | | | 4 | Apr 2, 2020 | SYSTEM | \$44,280.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | 5 | Apr 15, 2020 | SYSTEM | (\$44,280.00) | |
| | | | | 5 | Apr 15, 2020 | SYSTEM | \$44,280.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user chronf1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| | GALVANIZED CAST-IN-PLACE CONCRETE PILES (14 IN) | Other Item Adjustment | OTHR | 4 | Apr 2, 2020 | chronf1 | \$6,720.00 | chronf1 This is payment for the splices on Bent 1 and Bent 2 on Br. A8802. Bent 1: 3 splices x 8LF/splice = 24LF. Bent 2: 4 splices x |
| | | | | | | | | 8LF/splice = 32LF. Total: 56LF x \$120/LF = \$6,720 |
| | | | OTHR - Tota | al | | | \$6,720.00 | |
| | Other Item Adjustment - Total | | | | | | \$6,720.00 | |
| 1420 - | Total | | | | | | \$6,720.00 | |
| 1440 | CLASS B CONCRETE (SUBSTRUCTURE) | Material | | 4 | Apr 2, 2020 | SYSTEM | (\$30,240.00) | |
| | | | | 4 | Apr 2, 2020 | SYSTEM | \$30,240.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 5 | Apr 15, 2020 | SYSTEM | (\$30,240.00) | |
| | | | | 5 | Apr 15, 2020 | SYSTEM | \$30,240.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user chronf1 overridding Payment Estimate Exception 3 on the current |

Revision 4/1/2020 Page 28 of 29



| Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks |
|--------|------------------------------------|------------|--------------------|--------|-----------------|---------|---------------|--|
| | | Туре | Adjustment Type | Number | Date | Ву | | |
| 1440 | CLASS B CONCRETE (SUBSTRUCTURE) | Material | | | | | | Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 1440 - | - Total | | | | | | \$0.00 | |
| 1450 | SAFETY BARRIER CURB | Material | | 5 | Apr 15, 2020 | SYSTEM | (\$11,235.00) | |
| | | | | 5 | Apr 15, 2020 | SYSTEM | \$11,235.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user chronf1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | 6 | May 4, 2020 | SYSTEM | (\$11,235.00) | |
| | | | | 6 | May 5, 2020 | SYSTEM | \$11,235.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user chronf1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | - Total | | | | \$0.00 | |
| | Material - Total | | | | | | \$0.00 | |
| 1450 - | - Total | | | | | | \$0.00 | |
| 1460 | SLAB ON CONCRETE BEAM | Material | | 4 | Apr 2, 2020 | SYSTEM | (\$66,600.00) | |
| | | | | 4 | Apr 2, 2020 | SYSTEM | \$66,600.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user chronf1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | 5 | Apr 15, 2020 | SYSTEM | (\$70,200.00) | |
| | | | | 5 | Apr 15, 2020 | SYSTEM | \$70,200.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user chronf1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | 6 | May 4, 2020 | SYSTEM | (\$70,200.00) | |
| | | | | 6 | May 5, 2020 | SYSTEM | \$70,200.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user chronf1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | - Total | | | | | | |
| | Material - Total | | | | | | \$0.00 | |
| 1460 | - Total | | | | \$0.00 | | | |
| Overa | all - Total | | | | | | (\$1,243.06) | |

Revision 4/1/2020 Page 29 of 29