

## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 15, 2020

Progress 5	Estimate Number	Contract ID Prime Contractor	200117-C01  Don Schnieders Excava Inc.	ating Company,	Pay Period Start Pay Period End		Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,036,305.14 \$0.00 \$1,036,305.14	
Approval Date								By User	
October 15, 2020			Generated and A	pproved (and sh	ould be consider	ed Draft) at the F	Project Office Level by	mothee	
October 15, 2020			Reviewed and Approv	ved (and should	be considered D	raft) at the Resid	ent Engineer Level by	rileyr1	
October 19, 2020		Reviewed and Approved at the Central Office Controllers Office Level							
Original Comp	nal Completion Date Current Completion Date Actual Completion Date % of Current Contract Ar							nt Complete	
December	1, 2020	D	ecember 1, 2020				28.30%		

No Milestones Exist for Contract

Contract Total Pay For Estimate No. 5								
		This Estimate	Previous	To Date				
200117-C01	Total Posted Items Pay	\$97,405.70	\$195,865.19	\$293,270.89				
	Gross Item Adjustments	\$0.00	\$146,721.48	\$146,721.48				
	Incentive Disincentive	\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00				
	Liquidated Damage	\$0.00	\$0.00	\$0.00				
	Other Contract Adjustments	\$0.00	\$0.00 \$342.586.67	\$0.00 \$439.992.37				
Contract Total Pa	ayable This Estimate:	\$97,405.70	φυτ2,300.07	ψ <del>4</del> 03,332.31				

### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J3S3090	0270	8061050	TYPE C BERM	LF	\$15.000	65	\$975.00
	0380	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	LF	\$555.000	70.7	\$39,238.50
	0390	7011204	ROCK SOCKETS (3 FT 0 IN. DIA.)	LF	\$555.000	16.5	\$9,157.50
	0420	7011600	SONIC LOGGING TESTING	EA	\$2,240.000	6	\$13,440.00
	0460	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	CUYD	\$826.000	24	\$19,824.00
	0470	7034003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	CUYD	\$843.000	6.8	\$5,732.40
	0510	7061060	REINFORCING STEEL (BRIDGES)	LB	\$1.420	6,365	\$9,038.30
Project J3S309	D - Total						\$97,405.70
Overall - Total							\$97,405.70

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J3S3090	0380	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material			-117.1	\$555.00	(\$64,990.50)
	0380	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 1 on the current Payment Estimate.	117.1	\$555.00	\$64,990.50
	0390	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material			-36	\$555.00	(\$19,980.00)
	0390	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user mothee overridding Payment Estimate Exception 8 on the current Payment Estimate.	36	\$555.00	\$19,980.00
	0460	CLASS B CONCRETE	Material			-24	\$826.00	(\$19,824.00)

Revision 4/1/2020 Page 1 of 8



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 15, 2020

Progress Estimate Number	Contract ID	200117-C01	Pay Period Start	October 1 2020	Original Contract Amount	\$1,036,305.14
5	Prime Contractor	Don Schnieders Excavating Company, Inc.	Pay Period End	,	Net Change Order Amount	\$0.00
					Current Contract Amount	\$1,036,305.14

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J3S3090		(SUBSTRUCTURE)						
	0460	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate.	24	\$826.00	\$19,824.00
	0470	CLASS B-1 CONCRETE (SUBSTRUCTURE)	Material			-6.8	\$843.00	(\$5,732.40)
	0470	CLASS B-1 CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user mothee overridding Payment Estimate Exception 13 on the current Payment Estimate.	6.8	\$843.00	\$5,732.40
	0510	REINFORCING STEEL (BRIDGES)	Material			-11,412	\$1.42	(\$16,205.04)
	0510	REINFORCING STEEL (BRIDGES)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 16 on the current Payment Estimate.	11,412	\$1.42	\$16,205.04
Total								\$0.00

Revision 4/1/2020 Page 2 of 8



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information										
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work					
J3S3090	8090 FAS Bridge S301(76) replacement O PETTIS 2.7 miles north of Lee Road over Muddy Creek										
Totals by J	Job Numbe	rs									
J3S3090		d Item Pay Item Adjustm		s Item Pay	This Estimate \$97,405.70 \$0.00 \$97,405.70	Previous \$195,865.19 \$146,721.48 \$342,586.67	To Date \$293,270.89 \$146,721.48 \$439,992.37				
	Liquid	tive centive lated Damages Contract Adju		<b>.</b>	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				

Revision 4/1/2020 Page 3 of 8



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J3S3090, Item 7011105, Project Item Line Number 0380, Material Set 701110596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	All required samples have been taken. Waiting for results to be entered into AASHTOWARE.	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3090, Item 7011105, Project Item Line Number 0380, Material Set 701110596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	All required samples have been taken. Waiting for QC results to be entered into AASHTOWARE	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3090, Item 7011105, Project Item Line Number 0380, Material Set 701110596, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	All required samples have been taken. Waiting for QC results to be entered into AASHTOWARE	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3090, Item 7011105, Project Item Line Number 0380, Material Set 701110596, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	All required samples have been taken. Waiting for QC results to be entered into AASHTOWARE	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3090, Item 7011204, Project Item Line Number 0390, Material Set 701120496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	All required samples have been taken. Waiting for QC results to be entered into AASHTOWARE	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3090, Item 7011204, Project Item Line Number 0390, Material Set 701120496, Material 100510OPTLD1 - PCCP 1" Max LS/DO, Acceptance Action Generic 100510OPTLD1 is insufficient.	All required samples have been taken. Waiting for QC results to be entered into AASHTOWARE	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3090, Item 7011204, Project Item Line Number 0390, Material Set 701120496, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	All required samples have been taken. Waiting for QC results to be entered into AASHTOWARE	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3090, Item 7011204, Project Item Line Number 0390, Material Set 701120496, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	All required samples have been taken. Waiting for QC results to be entered into AASHTOWARE	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3090, Item 7011204, Project Item Line Number 0390, Material Set 701120496, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	All required samples have been taken. Waiting for QC results to be entered into AASHTOWARE	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3090, Item 7032003, Project Item Line Number 0460, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	All required samples have been taken. Waiting for QC results to be entered into AASHTOWARE	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3090, Item 7032003, Project Item Line Number 0460, Material Set 703200396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	All required samples have been taken. Waiting for QC results to be entered into AASHTOWARE	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3090, Item 7034003, Project Item Line Number 0470, Material Set 703400396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	All required samples have been taken. Waiting for QC results to be entered into AASHTOWARE	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3090, Item 7034003, Project Item Line Number 0470, Material Set 703400396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	All required samples have been taken. Waiting for QC results to be entered into AASHTOWARE	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3090, Item 7034003, Project Item Line Number 0470, Material Set 703400396, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	All required samples have been taken. Waiting for QC results to be entered into AASHTOWARE	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3090, Item 7034003, Project Item Line Number 0470, Material Set 703400396, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	All required samples have been taken. Waiting for QC results to be entered into AASHTOWARE	mothee	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3090, Item 7061060, Project Item Line Number 0510, Material Set 706106096, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	All reinforcing steel has been reported with the exception of the #6 bars. Will work with KC Materials to resolve.	mothee	Overridden

Revision 4/1/2020 Page 4 of 8



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-C01	J3S3090	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	1.00	\$2,640.00	\$2,640.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.10	\$18,522.00	\$1,852.20
		0001	0030	2031000	CLASS A EXCAVATION	712.00	0.00	712.00	CUYD	150.00	\$6.75	\$1,012.50
		0001	0040	2035500	EMBANKMENT IN PLACE	286.00	0.00	286.00	CUYD	0.00	\$39.40	\$0.00
		0001	0050	2036000	COMPACTING EMBANKMENT	609.00	0.00	609.00	CUYD	0.00	\$4.95	\$0.00
		0001	0060	2037075	COMPACTING IN CUT	4.10	0.00	4.10	STA	0.00	\$415.00	\$0.00
		0001	0070	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	793.00	0.00	793.00	SQYD	0.00	\$7.35	\$0.00
		0001	0080	3040163	TYPE 1 AGGREGATE FOR BASE (6 IN. THICK)	36.00	0.00	36.00	SQYD	0.00	\$23.75	\$0.00
		0001	0090	4019905	MISC.OPTIONAL PAVEMENT	793.40	0.00	793.40	SQYD	0.00	\$75.00	\$0.00
		0001	0100	6113020	FURNISHING TYPE 2 ROCK BLANKET	560.00	0.00	560.00	CUYD	77.80	\$44.85	\$3,489.33
		0001	0110	6113040	PLACING TYPE 2 ROCK BLANKET	560.00	0.00	560.00	CUYD	77.80	\$13.25	\$1,030.85
		0001	0120	6161005	CONSTRUCTION SIGNS	180.00	0.00	180.00	SQFT	173.00	\$6.25	\$1,081.25
		0001	0130	6161009	FLAG ASSEMBLY	2.00	0.00	2.00	EA	2.00	\$15.00	\$30.00
		0001	0140	6161030	TYPE III MOVEABLE BARRICADE	10.00	0.00	10.00	EA	10.00	\$125.00	\$1,250.00
		0001	0150	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$2,500.00	\$10,000.00
		0001	0160	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$75,000.00	\$37,500.00
		0001	0170	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	1,231.00	0.00	1,231.00	LF	0.00	\$0.12	\$0.00
			0400	62060046	PAINT, TYPE P BEADS		0.00	991.00	LF	0.00		
		0001	0180	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	991.00	0.00	991.00		0.00	\$0.12	\$0.00
		0001	0190	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	841.00	0.00	841.00	SQYD	116.70	\$2.65	\$309.26
		0001	0200	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.10	\$10,000.00	\$1,000.00
		0001	0210	8051000A	SEEDING - COOL SEASON MIXTURES	0.60	0.00	0.60	ACRE	0.00	\$4,200.00	\$0.00
		0001	0220	8061005	ROCK DITCH CHECK	36.00	0.00	36.00	LF	36.00	\$50.00	\$1,800.00
		0001	0230	8061006	ALTERNATE DITCH CHECK	72.00	0.00	72.00	LF	0.00	\$15.00	\$0.00
		0001	0240	8061016	SEDIMENT REMOVAL	17.00	0.00	17.00	CUYD	0.00	\$20.00	\$0.00
		0001	0250	8061017	TEMPORARY SEEDING AND MULCHING	0.60	0.00	0.60	ACRE	0.00	\$2,100.00	\$0.00
		0001	0260	8061019	SILT FENCE	791.00	0.00	791.00	LF	600.00	\$3.50	\$2,100.00
		0001	0270	8061050	TYPE C BERM	347.00	0.00	347.00	LF	65.00	\$15.00	\$975.00
		0001	0280	8064140	TYPE 3B EROSION CONTROL BLANKET	1,618.00	0.00	1,618.00	SQYD	0.00	\$2.75	\$0.00
		0010	0290	6061060	MGS GUARDRAIL	150.00	0.00	150.00	LF	0.00	\$19.00	\$0.00
		0010	0300	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	3.00	0.00	3.00	EA	0.00	\$2,750.00	\$0.00
		0010	0310	6062204A	BRIDGE ANCHOR SECTION, 6.5 FT. POSTS (SAFETY BARRIER CURB) (NEW CONSTRUCTION ONLY)	1.00	0.00	1.00	EA	0.00	\$1,995.00	\$0.00
		0010	0320	6062303	ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS	1.00	0.00	1.00	EA	0.00	\$375.00	\$0.00
		0010	0330	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	3.00	0.00	3.00	EA	0.00	\$2,450.00	\$0.00
		0010	0340	6063015	TYPE A CRASHWORTHY END TERMINAL	1.00	0.00	1.00	EA	0.00	\$2,450.00	\$0.00
		0040	0350	9039902	MISC.REMOVING AND REPLACING EXISTING SIGN ASSEMBLIES	2.00	0.00	2.00	EA	0.00	\$650.00	\$0.00
		0070	0360	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS		\$41,025.00	\$41,025.00
		0070	0370	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	107.00	0.00	107.00	SQYD	0.00	\$97.00	\$0.00
		0070	0380	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)		0.00	129.00	LF	117.10	\$555.00	\$64,990.50
		0070	0390	7011204	ROCK SOCKETS (3 FT 0 IN. DIA.)		0.00	36.00	LF	36.00	\$555.00	\$19,980.00
		0070	0400	7011300	VIDEO CAMERA INSPECTION		0.00	6.00	EA	6.00	\$600.00	\$3,600.00
		0070	0410	7011400	FOUNDATION INSPECTION HOLES		0.00	96.00	LF	96.00	\$109.00	\$10,464.00
		0070	0420	7011600			0.00	6.00	EA	6.00	\$2,240.00	\$13,440.00
		0070 0430 7021212 GALVANIZED STRUCTURAL STEEL PILES (12 IN)		235.00	0.00	235.00	LF	234.00	\$102.00	\$23,868.00		
		0070	0440	7026000	PRE-BORE FOR PILING	52.00	0.00	52.00	LF	52.00	\$238.00	\$12,376.00

Revision 4/1/2020 Page 5 of 8



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-C01	J3S3090	0070	0450	7027000	PILE POINT REINFORCEMENT	5.00	0.00	5.00	EA	5.00	\$105.00	\$525.00
		0070	0460	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	24.00	0.00	24.00	CUYD	24.00	\$826.00	\$19,824.00
		0070	0470	7034003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	43.10	0.00	43.10	CUYD	6.80	\$843.00	\$5,732.40
		0070	0480	7034219A	TYPE D BARRIER	447.00	0.00	447.00	LF	0.00	\$87.45	\$0.00
		0070	0490	7034222	SLAB ON CONCRETE BEAM	606.00	0.00	606.00	SQYD	0.00	\$312.00	\$0.00
		0070	0500	7056051A	33 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	603.00	0.00	603.00	LF	0.00	\$350.00	\$0.00
		0070	0510	7061060	REINFORCING STEEL (BRIDGES)	19,970.00	0.00	19,970.00	LB	11,412.00	\$1.42	\$16,205.04
		0070	0520	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$1,870.00	\$0.00
		0070	0530	7123610	SLAB DRAIN	40.00	0.00	40.00	EA	0.00	\$320.00	\$0.00
		0070	0540	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$0.00
		0070	0550	7161000	PLAIN NEOPRENE BEARING PAD	6.00	0.00	6.00	EA	0.00	\$200.00	\$0.00
		0070	0560	7161002	AMINATED NEOPRENE BEARING PAD 12.00 0.00 12.00 EA 0.00 \$232.00							
	Project J	3S3090 - To	tal Value	Posted to D	late as of Report Generated Date							\$298,100.32
200117-C01 Overall - Total Value Posted to Date as of Report Generated Date										\$298,100.32		

Revision 4/1/2020 Page 6 of 8



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0270	8061050	TYPE C BERM	10/15/20	10/15/20	65.00	LF	West side of Muddy Creek					
0380	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	10/2/20	10/2/20	70.70	LF	Bent 3 Shaft #9 648.5 - 625.2 = 23.3' Shaft #10 648.5 - 625.1 = 23.4' Shaft #11 648.5 - 624.5 = 24.0' Total = 70.7'					
0390	7011204	ROCK SOCKETS (3 FT 0 IN. DIA.)	10/2/20	10/2/20	16.50	LF	Bent 3 Socket #9 625.2 - 618.7 = 6.5' Socket #10 625.1 - 618.6 = 6.5' Socket #11 624.5 - 618.0 = 6.5' Total = 19.5					Will pay 3' overrun after change order is approved.
0420	7011600	SONIC LOGGING TESTING	10/6/20	10/6/20	6.00	EA	Bent 2 - Shafts 6,7,& 8 Bent 3 - Shafts 9,10,& 11					
0460	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	10/8/20	10/8/20	24.00	CUYD	Bent 1 & 4 Beams					
0470	7034003	CLASS B-1 CONCRETE (SUBSTR)	10/14/20	10/14/20	6.80	CUYD	Bent 3 Columns 9,10,11					
0510	7061060	REINFORCING STEEL (BRIDGES)	10/2/20	10/2/20	6,365.00	LB	Bent 3 Drilled Shafts P301 - 1171 V301 - 5194					

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 7 of 8



## Missouri Department of Transportation Contractor's Pay Estimate Summary Line Item Adjustments - All Estimates

Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0380	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material		4	Sep 30, 2020	SYSTEM	(\$25,752.00)	
				4	Sep 30, 2020	SYSTEM	\$25,752.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 1 on the current Payment Estimate.
				5	Oct 15, 2020	SYSTEM	(\$64,990.50)	
				5	Oct 15, 2020	SYSTEM	\$64,990.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user mothee overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0380 -	Total						\$0.00	
0390	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material		4	Sep 30, 2020	SYSTEM	(\$10,822.50)	
				4	Sep 30, 2020	SYSTEM	\$10,822.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user mothee overridding Payment Estimate Exception 5 on the current Payment Estimate.
				5	Oct 15, 2020	SYSTEM	(\$19,980.00)	
				5	Oct 15, 2020	SYSTEM	\$19,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user mothee overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0390 -	Total						\$0.00	
0460	CLASS B CONCRETE Material (SUBSTRUCTURE)			5	Oct 15, 2020	SYSTEM	(\$19,824.00)	
				5	Oct 15, 2020	SYSTEM	\$19,824.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0460 -	Total						\$0.00	
0470	CLASS B-1 CONCRETE (SUBSTRUCTURE)	Material		5	Oct 15, 2020	SYSTEM	(\$5,732.40)	
				5	Oct 15, 2020	SYSTEM	\$5,732.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user mothee overridding Payment Estimate Exception 13 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0470 -	Total						\$0.00	
0500	33 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM			1	Jun 15, 2020	SYSTEM	\$146,721.48	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$146,721.48	
	Construction Stockpile -	Total					\$146,721.48	
0500 -	Total						\$146,721.48	
0510	REINFORCING STEEL (BRIDGES)	Material		4	Sep 30, 2020	SYSTEM	(\$7,166.74)	
				4	Sep 30, 2020	SYSTEM	\$7,166.74	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user mothee overridding Payment Estimate Exception 9 on the current Payment Estimate.
				5	Oct 15, 2020	SYSTEM	(\$16,205.04)	
			5	Oct 15, 2020	SYSTEM	\$16,205.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user mothee overridding Payment Estimate Exception 16 on the current Payment Estimate.	
			- Total				\$0.00	
	Material - Total						\$0.00	
0510 -	Total						\$0.00	
Overa	II - Total						\$146,721.48	

Revision 4/1/2020 Page 8 of 8