

Progress Estim 10	ate Number	Contract ID Prime Contractor	200117-C04 Ideker, Inc.	Pay Period Start Pay Period End	November 16, 2020 December 1, 2020	Original Contract Amount Net Change Order Amount Current Contract Amount	\$10,026,824.17 \$23,245.33 \$10,050,069.50
Approval Date							By User
December 2, 2020			Generated an	d Approved (and sh	ould be considered [Draft) at the Project Office Level by	yostj1
December 2, 2020		Rev	viewed and Ap	proved (and should l	be considered Draft)	at the Resident Engineer Level by	warrem1
December 3, 2020				Reviewed and Ap	proved at the Centra	I Office Controllers Office Level by	greggd1
Original Compl	etion Date	Current Comple	etion Date	Actual Comp	oletion Date	% of Current Contract Amou	Int Complete
November 1	, 2020	November 1	, 2020	Novembe	r 1, 2020	95.55%	

No Milestones Exist for Contract

Contract Total Pa	ay For Estimate No. 10			
		This Estimate	Previous	To Date
200117-C04				
	Total Posted Items Pay	\$57,536.31	\$9,545,294.23	\$9,602,830.54
	Gross Item Adjustments	(\$53,638.48)	(\$475,546.64)	(\$529,185.12)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$9,069,747.59	\$9,073,645.42
Contract Total Pa	ayable This Estimate:	\$3,897.83		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4P3249	5005	1094000	FORCE ACCOUNT	EA	\$5,910.060	1	\$5,910.06
	5006	6069902	MISC.Drilling for Guardrail Posts	EA	\$194.250	66	\$12,820.50
	5007	6061074	MGS HEIGHT AND BLOCK TRANSITION	EA	\$635.250	3	\$1,905.75
	5008	9039902	MISC.Relocation of Existing Sign Assemblies	EA	\$1,706.250	4	\$6,825.00
Project J4P324	19 - Total						\$27,461.31
J4P3260	1470	9020811	SIGNAL HEAD, TYPE 1S, PEDESTRIAN	EA	\$1,964.000	2	\$3,928.00
	1510	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	LF	\$38.000	43	\$1,634.00
	1520	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	LF	\$38.000	24	\$912.00
	1530	9027400	CONDUIT, 4 IN., PUSHED WITH TRACER WIRE	LF	\$44.100	126	\$5,556.60
	1570	9028811	PULL BOX, PREFORMED CLASS 2	EA	\$2,341.000	2	\$4,682.00
	1580	9029100	BASE, CONCRETE	CUYD	\$3,736.000	0.9	\$3,362.40
	1600	9039902	MISC.RELOCATION OF EXISTING SIGN ASSEMBLIES	EA	\$2,500.000	4	\$10,000.00
Project J4P32	60 - Total						\$30,075.00
Overall - Total							\$57,536.31

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3249	0050	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-91	\$56.00	(\$5,096.00)
	0050	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0039) due to user yostj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	91	\$56.00	\$5,096.00
	0060	MISC.	Material			-877.6	\$61.91	(\$54,332.22)
	0060	MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0040) due to user yostj1 overridding Payment Estimate Exception 6 on		\$61.91	\$54,332.22

Prog	ress E	stimate Number 10	Contract Prime Co			ay Period Start ay Period End	November 16, 2020 December 1, 2020	Net Cha	Contract Ar Inge Order A Contract An	mount \$2	0,026,824.17 23,245.33 0,050,069.50
Project Number	Line No.	Item Descri	ption	Adjustment Type	Other Item Adjustment Type		Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
I4P3249							the current Payment E	Estimate.			
	0070	BITUMINOUS F MIXTURE PG64		Material					-18,298.85	\$68.64	(\$1,256,033.06
	0070	BITUMINOUS F MIXTURE PG64		Material		generated (Adjus	nent offsets the original Overrun Payment Estim stment (0041) due to us ayment Estimate Excep the current Payment E	er yostj1 tion 9 on	18,298.85	\$68.64	\$1,256,033.06
	0090	ASPHALTIC C MIXTURE PG 70-2		Material					-42,715	\$54.44	(\$2,325,404.60)
	0090	ASPHALTIC C MIXTURE PG 70-2		Material		generated (Adjus overridding	nent offsets the original Overrun Payment Estim tment (0042) due to us Payment Estimate Exce n the current Payment E	er yostj1 eption 11	42,715	\$54.44	\$2,325,404.60
	0150	CONCRE	TE MEDIAN	Material					-346	\$83.30	(\$28,821.80)
	0150	CONCRE	TE MEDIAN	Material		generated (Adjus overridding	nent offsets the original Overrun Payment Estim stment (0043) due to us Payment Estimate Exce n the current Payment E	er yostj1 eption 15	346	\$83.30	\$28,821.80
	0160	6 IN. CONCRE	TE MEDIAN STRIP	Material					-13	\$222.35	(\$2,890.55)
	0160	6 IN. CONCRE	TE MEDIAN STRIP	Material		generated (Adjus overridding	nent offsets the original Overrun Payment Estim stment (0046) due to us Payment Estimate Exce n the current Payment E	er yostj1 eption 19	13	\$222.35	\$2,890.55
	0170	INTEGRAL O HEIGHT AND UN		Material					-470	\$28.95	(\$13,606.50
	0170	INTEGRAL O HEIGHT AND UN		Material		generated (Adjus overridding	nent offsets the original Overrun Payment Estim stment (0044) due to us Payment Estimate Exce n the current Payment E	er yostj1 eption 24	470	\$28.95	\$13,606.50
	0210	FURNISHING AN CONCRETE MAT FULL DEPTH F	ERIAL FOR	Material					-1,486.6	\$275.30	(\$409,260.98
	0210	FURNISHING ANI CONCRETE MAT FULL DEPTH F	ERIAL FOR	Material		generated (Adjus overridding	nent offsets the original Overrun Payment Estim stment (0047) due to us Payment Estimate Exce n the current Payment E	er yostj1	1,486.6	\$275.30	\$409,260.98
	0260	FURNISHING AN BITUMINOUS FOR CLASS DEPTH PAVEME	MATERIAL B PARTIAL	Other Item Adjustment	Asphalt Cement Price Adjustment	betweer	ement price adjustment the dates 7/15/20 and				(\$298.08)
	0280	FURNISHING AN BITUMINOUS FOR CLASS DEPTH PAVEME	MATERIAL C PARTIAL	Other Item Adjustment	Asphalt Cement Price Adjustment	between the	ement price adjustment e dates 7/14/20 through				(\$676.72)
	0600	MGS G	UARDRAIL	Construction Stockpile		Payment Estin	nate Item Adjustment g Stockpile Tra				(\$6,057.95
	0610	MGS GUARD POSTS, (RAIL, 8 FT. 6 FT 3 IN. SPACING	Construction Stockpile		Payment Estin	nate Item Adjustment g Stockpile Tra				(\$38,675.46)
	0620	MGS BRIDGE A		Construction		Payment Estin	nate Item Adjustment g	enerated			(\$6,244.00)



Prog	ress E	stimate Number 10	Prime Contractor			Pay Period Start Pay Period End	November 16, 2020 December 1, 2020	Net Cha	l Contract Ar ange Order A Contract An	mount \$2	0,026,824.17 3,245.33 0,050,069.50
Project Number	Line No.	Item Descri	otion	Adjustment Type	Other Iten Adjustmer Type		Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3249		TRANSITION (EXTEND	N SECTION DED CURB)	Stockpile			Stockpile Tra	ansaction			
	0630	MGS ENI	O ANCHOR	Construction Stockpile		Payment Estin	nate Item Adjustment g Stockpile Tra				(\$2,000.00
	0650	CONDUIT, 3	IN. RIGID, PUSHED	Material					-99	\$43.50	(\$4,306.50
	0650	CONDUIT, 3	3 IN. RIGID, PUSHED	Material		generated (Adjus overridding	nent offsets the original Overrun Payment Estin stment (0048) due to us Payment Estimate Exca n the current Payment E	nate Item ser yostj1 eption 46	99	\$43.50	\$4,306.50
	0660	CABLE-CONDU CONDUCTORS AI NEUTR		Material					-130	\$8.80	(\$1,144.00)
	0660	CABLE-CONDU CONDUCTORS AI NEUTR		Material		generated (Adjus overridding	nent offsets the original Overrun Payment Estin stment (0049) due to us Payment Estimate Exce n the current Payment E	nate Item ser yostj1 eption 47	130	\$8.80	\$1,144.00
	5001	DOWEL BAR FURNIS INSTALLATION) DEPTH PAVEMEN	HING AND FOR FULL	Material					-1,734	\$5.46	(\$9,467.64
	5001	DOWEL BAR FURNIS INSTALLATION) DEPTH PAVEMEN	HING AND	Material		generated (Adjus overridding	nent offsets the original Overrun Payment Estin stment (0050) due to us Payment Estimate Exce n the current Payment E	nate Item ser yostj1 eption 38	1,734	\$5.46	\$9,467.64
J4P3260	0730		MPACTING BANKMENT	Material					-218	\$3.00	(\$654.00)
	0730		MPACTING BANKMENT	Material		generated (Adjus	nent offsets the original Overrun Payment Estin stment (0051) due to us ayment Estimate Excep the current Payment B	nate Item ser yostj1 ition 1 on	218	\$3.00	\$654.00
	0740	COMPACTI	NG IN CUT	Material					-35	\$357.00	(\$12,495.00
	0740	COMPACTI	NG IN CUT	Material		generated (Adjus	nent offsets the original Overrun Payment Estin stment (0052) due to us ayment Estimate Excep the current Payment B	nate Item ser yostj1 ition 2 on	35	\$357.00	\$12,495.00
	0790	TYPE 5 AGGRE BASE (6	GATE FOR IN. THICK)	Material					-796	\$20.00	(\$15,920.00)
	0790	TYPE 5 AGGRE BASE (6	GATE FOR IN. THICK)	Material		generated (Adjus	nent offsets the original Overrun Payment Estin stment (0053) due to us ayment Estimate Excep the current Payment E	nate Item ser yostj1 ition 4 on	796	\$20.00	\$15,920.00
	0800		MISC.	Material					-82	\$380.73	(\$31,219.86)
	0800		MISC.	Material		generated (Adjus	nent offsets the original Overrun Payment Estin stment (0054) due to us ayment Estimate Excep the current Payment B	nate Item ser yostj1 ition 5 on	82	\$380.73	\$31,219.86
	0810	TYPE A3 S	HOULDER	Material					-196	\$51.25	(\$10,045.00)
	0810	TYPE A3 S	HOULDER	Material		generated (Adjus	nent offsets the original Overrun Payment Estin stment (0055) due to us ayment Estimate Excep the current Payment B	nate Item ser yostj1 ition 7 on	196	\$51.25	\$10,045.00



Prog	jress E	stimate Number 10	Contract Prime Co			ay Period Start ay Period End	November 16, 2020 December 1, 2020	Net Cha	Contract Ar nge Order A Contract An	mount \$2	0,026,824.17 3,245.33 0,050,069.50
Project Number	Line No.	Item Descrip	otion	Adjustment Type	Other Item Adjustment Type		Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3260	0840	ASPHALTIC C MIXTURE PG 76-2		Overrun		generated C Adjustme	ent offsets the original overrun Payment Estim ent (0036) overridding F tion 65 on the current F E	ate Item Payment	1,686.46	\$62.65	\$105,658.00
	0840	ASPHALTIC C MIXTURE PG 76-2		Overrun			e Adjustment from this ment estimates of '-2.3 applied (if no	32924' is	-1,686.46	\$62.65	(\$105,658.00
	0840	ASPHALTIC C MIXTURE PG 76-2		Material					-14,049.46	\$64.98	(\$912,933.91
	0840	ASPHALTIC C MIXTURE PG 76-2		Material		generated C Adjust overridding P	ent offsets the original overrun Payment Estim ment (0037) due to us 'ayment Estimate Exce the current Payment E	ate Item er yostj1 ption 10	14,049.46	\$64.98	\$912,933.91
	0870	CONCRETE PAV IN. N	EMENT(8 ON-REINF)	Material					-12	\$200.60	(\$2,407.20
	0870	CONCRETE PAV IN. N	EMENT (8 ON-REINF)	Material		generated C Adjust overridding P	ent offsets the original overrun Payment Estim ment (0045) due to uso 'ayment Estimate Exce the current Payment E	ate Item er yostj1 ption 12	12	\$200.60	\$2,407.20
	0880	CONCRETE CU	JRB RAMP	Material					-10	\$445.80	(\$4,458.00
	0880	CONCRETE CU	JRB RAMP	Material		generated C Adjust overridding P	ent offsets the original overrun Payment Estim ment (0056) due to us 'ayment Estimate Exce the current Payment E	ate Item er yostj1 ption 16	10	\$445.80	\$4,458.00
	0890	TRUNCATE	ED DOMES	Material					-48	\$16.90	(\$811.20
	0890	TRUNCATE	ED DOMES	Material		generated C Adjust overridding P	ent offsets the original overrun Payment Estim ment (0057) due to usu 'ayment Estimate Exce the current Payment E	ate Item er yostj1 ption 18	48	\$16.90	\$811.20
	0900	CONCRETE SIE	DEWALK, 4 IN.	Material					-948.81	\$48.25	(\$45,780.08
	0900	CONCRETE SI	DEWALK, 4 IN.	Material		generated C Adjust overridding P	ent offsets the original overrun Payment Estim ment (0058) due to uso 'ayment Estimate Exce the current Payment E	ate Item er yostj1 ption 23	948.81	\$48.25	\$45,780.08
	0910		MISC.	Material					-313	\$31.90	(\$9,984.70
	0910		MISC.	Material		generated C Adjust overridding P	ent offsets the original overrun Payment Estim ment (0059) due to uso 'ayment Estimate Exce the current Payment E	ate Item er yostj1 ption 28	313	\$31.90	\$9,984.70
	0920		MISC.	Material					-56	\$55.10	(\$3,085.60
	0920		MISC.	Material		generated C Adjust overridding P	ent offsets the original overrun Payment Estim ment (0060) due to uso 'ayment Estimate Exce the current Payment E	ate Item er yostj1 ption 31	56	\$55.10	\$3,085.60
	0940	FURNISHING AND CONCRETE MATE FULL DEPTH P	ERIAL FOR	Material					-495.4	\$369.20	(\$182,901.68
	0940	FURNISHING AND CONCRETE MATE		Material			ent offsets the original verrun Payment Estim		495.4	\$369.20	\$182,901.68



Prog	ress Es	stimate Number 10	Contract I Prime Cor			ay Period Start ay Period End	November 16, 2020 December 1, 2020	Net Cha	Contract Ar nge Order A Contract An	mount \$2	0,026,824.17 3,245.33 0,050,069.50
Project Number	Line No.	Item Descript	tion	Adjustment Type	Other Item Adjustment Type		Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3260		FULL DEPTH PA	AVEMENT REPAIR			overridding	stment (0061) due to us Payment Estimate Exce n the current Payment E	ption 36			
	0980	DOWEL BAR (E FURNISH INSTALLATION) F DEPTH PAVEMEN	HING AND OR FULL	Material					-356	\$5.20	(\$1,851.20
	0980	DOWEL BAR (E FURNISH INSTALLATION) F DEPTH PAVEMEN	HING AND OR FULL	Material		generated Adjus overridding	nent offsets the original Overrun Payment Estim stment (0062) due to us Payment Estimate Exce n the current Payment E	er yostj1 eption 39	356	\$5.20	\$1,851.20
	1000	FURNISHING AND BITUMINOUS M FOR CLASS C DEPTH PAVEMEN	/ATERIAL	Other Item Adjustment	Asphalt Cement Price Adjustment	between the	ement price adjustment a dates 8/11/20 through				(\$368.10
	1310	24 IN. PIPE	GROUP B	Material					-3	\$209.00	(\$627.00
	1310	24 IN. PIPE	GROUP B	Material		generated Adjus overridding	nent offsets the original Overrun Payment Estim stment (0063) due to us Payment Estimate Exce n the current Payment E	er yostj1 eption 40	3	\$209.00	\$627.00
	1330	24 IN. OR A SUBSTITUTE FLARED END	GROUP A	Material					-1	\$1,415.00	(\$1,415.00
	1330	24 IN. OR A SUBSTITUTE FLARED END	GROUP A	Material		generated Adjus overridding	nent offsets the original Overrun Payment Estim stment (0064) due to us Payment Estimate Exce n the current Payment E	er yostj1 etion 41	1	\$1,415.00	\$1,415.00
	1340	SEEDING - COOL M	SEASON	Material					-1	\$3,070.00	(\$3,070.00
	1340	SEEDING - COOL M	. SEASON IIXTURES	Material		generated Adjus overridding	nent offsets the original Overrun Payment Estim stment (0065) due to us Payment Estimate Exce n the current Payment E	er yostj1 etion 42	1	\$3,070.00	\$3,070.00
	1420	MGS GU	JARDRAIL	Overrun		adjustn pre	rice based on averaged nents for installed quant vious payment estimate ents of ',18.50000 - 18.5 applied (if no	tity on all es. Price 0000, 'is	87	\$18.50	\$1,609.50
	1430	MGS GUARDR POSTS, 6		Construction Stockpile		Payment Estin	nate Item Adjustment g Stockpile Tra				(\$927.67
	1460	SIGNAL HEAD,	, TYPE 3S	Material					-1	\$2,449.00	(\$2,449.00
	1460	SIGNAL HEAD,	, TYPE 3S	Material		generated Adjus overridding	nent offsets the original Overrun Payment Estim stment (0066) due to us Payment Estimate Exce n the current Payment E	er yostj1 et ion 48	1	\$2,449.00	\$2,449.00
	1470	SIGNAL HEAD, PED	TYPE 1S, DESTRIAN	Material					-2	\$1,964.00	(\$3,928.00
	1470	SIGNAL HEAD, PED	TYPE 1S, DESTRIAN	Material		generated Adjus overridding	nent offsets the original Overrun Payment Estim stment (0067) due to us Payment Estimate Exce n the current Payment E	er yostj1 eption 49	2	\$1,964.00	\$3,928.00
	1500	POST, SIGNAL 8 F	T. OR 2.4 M	Material					-2	\$2,241.00	(\$4,482.00



Prog	ress Es	stimate Number 10	Contract Prime Cor			Pay Period Start Pay Period End	November 16, 2020 December 1, 2020	Net Cha	Contract Ar nge Order A Contract An	mount \$2	0,026,824.17 3,245.33 0,050,069.50
Project Number	Line No.	Item Descrip	otion	Adjustment Type	Other Iten Adjustmer Type		Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3260	1500	POST, SIGNAL 8	FT. OR 2.4 M	Material		generated (Adjus overridding I	nent offsets the original Overrun Payment Estim stment (0068) due to us Payment Estimate Exce n the current Payment E	ate Item er yostj1 ption 50	2	\$2,241.00	\$4,482.00
	1510	CONDUIT, 3 IN WITH TRA	,	Material					-43	\$38.00	(\$1,634.00
	1510	CONDUIT, 3 IN WITH TRA		Material		generated (Adjus overridding I	nent offsets the original Overrun Payment Estim stment (0069) due to us Payment Estimate Exce n the current Payment E	ate Item er yostj1 ption 53	43	\$38.00	\$1,634.00
	1520	CONDUIT, 4 IN WITH TRA		Material					-24	\$38.00	(\$912.00)
	1520	CONDUIT, 4 IN. WITH TRA		Material		generated (Adjus overridding I	nent offsets the original Overrun Payment Estim stment (0070) due to us Payment Estimate Exce n the current Payment E	ate Item er yostj1 ption 54	24	\$38.00	\$912.00
	1530	CONDUIT, 4 IN WITH TRA		Material					-126	\$44.10	(\$5,556.60)
	1530	CONDUIT, 4 IN WITH TRA	,	Material		generated (Adjus overridding I	nent offsets the original Overrun Payment Estim stment (0071) due to uso Payment Estimate Exce n the current Payment E	ate Item er yostj1 ption 55	126	\$44.10	\$5,556.60
	1540		16 AWG 2 NDUCTOR	Material					-270	\$2.80	(\$756.00)
	1540		16 AWG 2 NDUCTOR	Material		generated (Adjus overridding I	nent offsets the original Overrun Payment Estim stment (0072) due to uso Payment Estimate Exce n the current Payment E	ate Item er yostj1 ption 56	270	\$2.80	\$756.00
	1550		16 AWG 5 NDUCTOR	Material					-270	\$3.20	(\$864.00)
	1550		16 AWG 5 NDUCTOR	Material		generated (Adjus overridding I	nent offsets the original Overrun Payment Estim stment (0073) due to us Payment Estimate Exce n the current Payment E	ate Item er yostj1 ption 57	270	\$3.20	\$864.00
	1560		16 AWG 7 NDUCTOR	Material					-130	\$3.60	(\$468.00)
	1560		16 AWG 7 NDUCTOR	Material		generated (Adjus overridding I	nent offsets the original Overrun Payment Estim stment (0074) due to us Payment Estimate Exce n the current Payment E	ate Item er yostj1 ption 58	130	\$3.60	\$468.00
	1570	PULL BOX, PR	EFORMED CLASS 2	Material					-2	\$2,341.00	(\$4,682.00)
	1570	PULL BOX, PR	EFORMED CLASS 2	Material		generated (Adjus overridding I	nent offsets the original Overrun Payment Estim stment (0075) due to uso Payment Estimate Exce n the current Payment E	ate Item er yostj1 ption 59	2	\$2,341.00	\$4,682.00
	1580	BASE, C	ONCRETE	Material					-0.9	\$3,736.00	(\$3,362.40)
	1580	BASE, C	ONCRETE	Material		generated (Adjus overridding I	nent offsets the original Overrun Payment Estim stment (0076) due to us Payment Estimate Exce n the current Payment E	ate Item er yostj1 ption 60	0.9	\$3,736.00	\$3,362.40

Prog	ress Es	stimate Number 10	Contract I Prime Cor			November 16, 2020 December 1, 2020	Net Cha	I Contract Ar ange Order A Contract An	mount	\$10,026,824.17 \$23,245.33 \$10,050,069.50
Project Number	Line No.	Item Descript	tion	Adjustme Type	ent Other Ite Adjustme Type	Comments		Adjustment Quantity	Line Item Adjustmen Unit Price	
Total										(\$53,638.48)



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J4P3249	FAF 291-1(86)	Coldmill and resurface	291	CLAY	from Leonard St to Route 78
J4P3260	FAF 291-1(88)	Coldmill and resurface	291	CLAY	from I-435 to north of Kansas Street

Totals by Job Numbers

3249	This Estimate	Previous	To Date
Posted Item Pay	\$27,461.31	\$6,593,965.95	\$6,621,427.26
Gross Item Adjustments	(\$53,952.21)	(\$239,427.65)	(\$293,379.86)
Gross Item Pay	(\$26,490.90)	\$6,354,538.30	\$6,328,047.40
la section	* 0.00	* 0.00	* 0.00
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
3260	This Estimate	Previous	To Date
Posted Item Pay	\$30,075.00	\$2,951,328.28	\$2,981,403.28
Gross Item Adjustments	\$313.73	(\$236,118.99)	(\$235,805.26)
Gross Item Pav	\$30,388.73	\$2,715,209.29	\$2,745,598.02
	*• • • •	AO OO	*• • • •
Incentive	\$0.00	\$0.00	\$0.00
Incentive Disincentive	\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 2036000, Project Item Line Number 0730, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 2037075, Project Item Line Number 0740, Material Set 203707596, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3249, Item 3040506, Project Item Line Number 0050, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 3040506, Project Item Line Number 0790, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 3049910, Project Item Line Number 0800, Material Set 304991096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3249, Item 3049910, Project Item Line Number 0060, Material Set 304991096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 4010151, Project Item Line Number 0810, Material Set 401015196, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 4010151, Project Item Line Number 0810, Material Set 401015196, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3249, Item 4011209, Project Item Line Number 0070, Material Set 401120996, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 4030005, Project Item Line Number 0840, Material Set 403000596, Material 0403SP095CLG - Superpave 9.5 mm, Des C 80 Gyros, Acceptance Action Generic AspHigh is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3249, Item 4030114, Project Item Line Number 0090, Material Set 403011496, Material 0403SP095B - Superpave 9.5 mm, Des B, Acceptance Action Generic AspHigh is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 5021108, Project Item Line Number 0870, Material Set 502110896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 5021108, Project Item Line Number 0870, Material Set 502110896, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 5021108, Project Item Line Number 0870, Material Set 502110896, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3249, Item 6081000, Project Item Line Number 0150, Material Set 608100096, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 6081010, Project Item Line Number 0880, Material Set 608101096, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 6081010, Project Item Line Number 0880, Material Set 608101096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 6081012, Project Item Line Number 0890, Material Set 608101296, Material 1067TRDO - Truncated Domes for ADA, Acceptance Action Generic 1067TRDO is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3249, Item 6083006, Project Item Line Number 0160, Material Set 608300696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3249, Item 6083006, Project Item Line Number 0160, Material Set 608300696, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3249, Item 6083006, Project Item Line Number 0160, Material Set 608300696, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3249, Item 6083006, Project Item Line Number 0160, Material Set 608300696, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 6086004, Project Item Line Number 0900, Material Set 608600496, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3249, Item 6092011, Project Item Line Number 0170, Material Set 609201196, Material 1005FACCNSCA - Natural Sand for Conc Class A,	No Remark was entered by Engineer	yostj1	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period Exceptions / Discrepancies	Explanation	Entered	Status
		By	Oldido
Acceptance Action Generic 1005FACCNSCA is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J4P3249, Item 6092011, Project Item Line Number 0170, Material Set 609201196, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3249, Item 6092011, Project Item Line Number 0170, Material Set 609201196, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3249, Item 6092011, Project Item Line Number 0170, Material Set 609201196, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 6099903, Project Item Line Number 0910, Material Set 6099903, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 6099903, Project Item Line Number 0910, Material Set 6099903, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 6099903, Project Item Line Number 0910, Material Set 6099903, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 6099903, Project Item Line Number 0920, Material Set 6099903, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 6099903, Project Item Line Number 0920, Material Set 6099903, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 6099903, Project Item Line Number 0920, Material Set 6099903, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3249, Item 6131010, Project Item Line Number 0210, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3249, Item 6131010, Project Item Line Number 0210, Material Set 613101096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 6131010, Project Item Line Number 0940, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 6131010, Project Item Line Number 0940, Material Set 613101096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3249, Item 6131015, Project Item Line Number 5001, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 6131015, Project Item Line Number 0980, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 7250324A, Project Item Line Number 1310, Material Set 7250324A96, Material 1020CPCSAC0024 - CulvPipe Al Ctd Corrug Stl 24" 600mm, Acceptance Action Generic 1020CPCSAC0024 is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 7320624A, Project Item Line Number 1330, Material Set 7320624A96, Material 1032ESRCF - Conc End Section for Round Pipe, Acceptance Action Generic 1032ESRCF is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 8051000A, Project Item Line Number 1340, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 8051000A, Project Item Line Number 1340, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 8051000A, Project Item Line Number 1340, Material Set 8051000A96, Material 0802MLSP - Overspray Slick Paper, Acceptance Action Generic 0802MLSP is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 8051000A, Project Item Line Number 1340, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3249, Item 9014003, Project Item Line Number 0650, Material Set 901400396, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3249, Item 9017407, Project Item Line Number 0660, Material Set 901740796, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 9020213, Project Item Line	No Remark was entered by Engineer	yostj1	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Fenou			
Exceptions / Discrepencies	Explanation	Entered By	Status
Number 1460, Material Set 902021396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 9020811, Project Item Line Number 1470, Material Set 902081196, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 9022708, Project Item Line Number 1500, Material Set 902270896, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 9022708, Project Item Line Number 1500, Material Set 902270896, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 9022708, Project Item Line Number 1500, Material Set 902270896, Material 1092TSPS - Traffic Signal Post(s) - All Types, Acceptance Action Generic 1092TSPS is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 9025300, Project Item Line Number 1510, Material Set 902530096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 9025400, Project Item Line Number 1520, Material Set 902540096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 9027400, Project Item Line Number 1530, Material Set 902740096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 9028308, Project Item Line Number 1540, Material Set 902830896, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 9028310, Project Item Line Number 1550, Material Set 902831096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 9028311, Project Item Line Number 1560, Material Set 902831196, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 9028811, Project Item Line Number 1570, Material Set 902881196, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 9029100, Project Item Line Number 1580, Material Set 902910096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 9029100, Project Item Line Number 1580, Material Set 902910096, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3260, Item 9029100, Project Item Line Number 1580, Material Set 902910096, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Item Overrun: Contract 200117-C04, Contract Project J4P3249, Project Item Line Number 0100, Contract Line Item Number 0100, Item 4071005, Minor Item.	No Remark was entered by Engineer	yostj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 200117-C04, Contract Project J4P3249, Project Item Line Number 0300, Contract Line Item Number 0300, Item 6161005, Minor Item.	No Remark was entered by Engineer	yostj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 200117-C04, Contract Project J4P3260, Project Item Line Number 0840, Contract Line Item Number 0840, Item 4030005, Minor Item.	No Remark was entered by Engineer	yostj1	Overridden
Estimate Exception Type: Item Overrun: Contract 200117-C04, Contract Project J4P3260, Project Item Line Number 0850, Contract Line Item Number 0850, Item 4071005, Minor Item.	No Remark was entered by Engineer	yostj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 200117-C04, Contract Project J4P3260, Project Item Line Number 1150, Contract Line Item Number 1150, Item 6200015, Minor Item.	No Remark was entered by Engineer	yostj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 200117-C04, Contract Project J4P3260, Project Item Line Number 1270, Contract Line Item Number 1270, Item 6221001, Minor Item.	No Remark was entered by Engineer	yostj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 200117-C04, Contract Project J4P3260, Project Item Line Number 1380, Contract Line Item Number 1380, Item 8061007A, Minor Item.	No Remark was entered by Engineer	yostj1	Acknowledged



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Contract Nm.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-C04	J4P3249	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$89,601.00	\$89,601.00
		0001	0020	2063000	CLASS 3 EXCAVATION	17.00	-5.00	12.00	CUYD	12.00	\$12.00	\$144.00
		0001	0030	2072000	LINEAR GRADING CLASS 2	1.00	0.00	1.00	STA	1.00	\$6,000.00	\$6,000.00
		0001	0040	2153000	SHAPING SLOPES, CLASS III	41.00	-11.20	29.80	100F	29.80	\$950.00	\$28,310.00
		0001	0050	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	91.00	0.00	91.00	SQYD	91.00	\$56.00	\$5,096.00
		0001	0060	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	877.60	0.00	877.60	TONS	877.60	\$61.91	\$54,332.22
		0001	0070	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	20,808.00	0.00	20,808.00	TONS	18,298.85	\$68.64	\$1,256,033.06
		0001	0080	4019905	MISC.OPTIONAL PAVEMENT	85.00	0.00	85.00	SQYD	85.00	\$69.20	\$5,882.00
		0001	0090	4030114	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125B MIX)	44,254.00	0.00	44,254.00	TONS	42,715.00	\$54.44	\$2,325,404.60
		0001	0100	4071005	TACK COAT	44,581.00	0.00	44,581.00	GAL	48,327.00	\$2.25	\$108,735.75
		0001	0110	4079912	MISC.POLYMER MODIFIED EMULSION MEMBRANE	29,370.00	0.00	29,370.00	GAL	17,148.00	\$4.45	\$76,308.60
		0001	0120	4133100	ULTRATHIN BONDED WEARING SURFACE, TYPE B	27,112.00	0.00	27,112.00	SQYD	27,112.00	\$5.17	\$140,169.04
		0001	0130	5021108	CONCRETE PAVEMENT (8 IN. NON-REINF)	6.00	0.00	6.00	SQYD	6.00	\$156.40	\$938.40
		0001	0140	6044012	PIPE COLLAR, TYPE B	1.00	-1.00	0.00	EA	0.00	\$1,900.00	\$0.00
		0001	0150	6081000	CONCRETE MEDIAN	346.00	0.00	346.00	SQYD	346.00	\$83.30	\$28,821.80
		0001	0160	6083006	6 IN. CONCRETE MEDIAN STRIP	13.00	0.00	13.00	SQYD	13.00	\$222.35	\$2,890.55
		0001	0170	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	470.00	0.00	470.00	LF	470.00	\$28.95	\$13,606.50
		0001	0180	6113020	FURNISHING TYPE 2 ROCK BLANKET	123.00	0.00	123.00	CUYD	123.00	\$56.00	\$6,888.00
		0001	0190	6113040	PLACING TYPE 2 ROCK BLANKET	734.00	0.00	734.00	CUYD	734.00	\$31.00	\$22,754.00
		0001	0200	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1,500.00	\$0.00
		0001	0210	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	920.00	566.60	1,486.60	SQYD	1,486.60	\$275.30	\$409,260.98
		0001	0220	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	92.00	-92.00	0.00	SQYD	0.00	\$1.20	\$0.00
		0001	0230	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	92.00	-92.00	0.00	SQYD	0.00	\$1.20	\$0.00
		0001	0240	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	2,892.00	3,371.00	6,263.00	LF	6,263.00	\$5.00	\$31,315.00
		0001	0250	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	2,300.00	-2,099.00	201.00	EA	201.00	\$4.70	\$944.70
		0001	0260	6133018	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	193.10	-37.80	155.30	TONS	155.30	\$245.99	\$38,202.25
		0001	0270	6133019	REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	877.70	-57.80	819.90	SQYD	819.90	\$109.90	\$90,107.01
		0001	0280	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	427.70	-76.90	350.80	TONS	350.80	\$197.22	\$69,184.78
		0001	0290	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	1,944.40	-158.00	1,786.40	SQYD	1,786.40	\$74.29	\$132,711.66
		0001	0300	6161005	CONSTRUCTION SIGNS	1,457.00	0.00	1,457.00	SQFT	1,462.10	\$5.50	\$8,041.55
		0001	0310	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$80.00	\$320.00
		0001	0320	6161009	FLAG ASSEMBLY	14.00	0.00	14.00	EA	12.00	\$20.00	\$240.00
		0001	0330	6161025	CHANNELIZER (TRIM LINE)	350.00	0.00	350.00	EA	350.00	\$12.00	\$4,200.00
		0001	0340	6161030	TYPE III MOVEABLE BARRICADE	6.00	0.00	6.00	EA	6.00	\$125.00	\$750.00
		0001	0350	6161040	FLASHING ARROW PANEL	3.00	0.00	3.00	EA	2.00	\$750.00	\$1,500.00
		0001	0360	6161055	SEQUENTIAL FLASHING WARNING LIGHT	36.00	0.00	36.00	EA	14.00	\$65.00	\$910.00
		0001	0370	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$4,325.00	\$17,300.00
		0001	0380	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$372,690.08	\$372,690.08
		0001	0390	6200003	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	2,659.00	0.00	2,659.00	LF	2,248.00	\$3.30	\$7,418.40
		0001	0400	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	9,750.00	0.00	9,750.00	LF	9,750.00	\$3.65	\$35,587.50
		0001	0410	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	1,429.00	0.00	1,429.00	LF	1,398.00	\$18.00	\$25,164.00
		0001	0420	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	72.00	0.00	72.00	EA	61.00	\$180.00	\$10,980.00
		0001	0430	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	3.00	0.00	3.00	EA	3.00	\$400.00	\$1,200.00
		0001	0440	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN	84.00	0.00	84.00	EA	84.00	\$180.00	\$15,120.00



Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

sted Quan	itities a	and Valu	es are b	ased on R	eport Generated date and can differ from the posted amo	ount at the f	ime the E	stimate was	Genera	ited.		
	oject No.	Category	Line No.			Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
)4 J4F	93249				WHITE MIDBLOCK					any		
		0001	0460	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	159,738.00	0.00	159,738.00	LF	152,685.00	\$0.17	\$25,956.45
		0001	0470	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	128,862.00	0.00	128,862.00	LF	128,862.00	\$0.18	\$23,195.16
		0001	0480	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	4,769.00	0.00	4,769.00	LF	4,068.00	\$0.60	\$2,440.80
		0001	0490	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	44,480.00	0.00	44,480.00	LF	32,317.00	\$0.13	\$4,201.21
		0001	0495	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	42,911.00	0.00	42,911.00	LF	36,026.00	\$0.13	\$4,683.38
		0001	0500	6214600A	FLOWABLE BACKFILL	1.00	0.00	1.00	CUYD	1.00	\$1,005.00	\$1,005.00
		0001	0510	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	439,301.00	0.00	439,301.00	SQYD	425,315.00	\$0.91	\$387,036.65
		0001	0520	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	22,447.00	0.00	22,447.00	SQYD	19,428.00	\$5.81	\$112,876.68
		0001	0530	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	1,625.00	0.00	1,625.00	STA	1,625.00	\$20.83	\$33,848.75
		0001	0540	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.00
		0001	0550	7250312A	12 IN. PIPE GROUP B	17.00	-17.00	0.00	LF	0.00	\$91.00	\$0.00
		0001	0560	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	4.00	0.00	4.00	FT	4.00	\$903.00	\$3,612.00
		0001	0570	8061007A	CURB INLET CHECK	2.00	0.00	2.00	EA	1.00	\$154.00	\$154.00
		0001	0580	8061016	SEDIMENT REMOVAL	2.00	0.00	2.00	CUYD	0.00	\$175.00	\$0.00
		0001	0590	8064139	TYPE 3A EROSION CONTROL BLANKET	1,100.00	0.00	1,100.00	SQYD	1,100.00	\$3.40	\$3,740.00
		0010	0600	6061060	MGS GUARDRAIL	11,613.00	-575.00	11,038.00	LF	11,038.00	\$18.50	\$204,203.00
		0010	0610	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	8,613.00	-3,125.00	5,488.00	LF	5,488.00	\$21.50	\$117,992.00
		0010	0620	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	32.00	-4.00	28.00	EA	28.00	\$2,800.00	\$78,400.00
		0010	0630	6061080	MGS END ANCHOR	16.00	-4.00	12.00	EA	12.00	\$800.00	\$9,600.00
		0010	0640	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	39.00	0.00	39.00	EA	39.00	\$2,450.00	\$95,550.00
		0020	0650	9014003	CONDUIT, 3 IN. RIGID, PUSHED	99.00	0.00	99.00	LF	99.00	\$43.50	\$4,306.50
		0020	0660	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	130.00	0.00	130.00	LF	130.00	\$8.80	\$1,144.00
		0070	0670	2161502	REMOVAL OF CONCRETE WEARING SURFACE	6,238.00	0.00	6,238.00	SQFT	0.00	\$3.50	\$0.00
		0070	0680	7034600	CURB BLOCKOUT	364.00	0.00	364.00	LF	0.00	\$86.50	\$0.00
		0070	0690	7040104	HALF-SOLE REPAIR	600.00	0.00	600.00	SQFT	0.00	\$48.00	\$0.00
		0070	0700	7040106	FULL DEPTH REPAIR	100.00	0.00	100.00	SQFT	0.00	\$69.00	\$0.00
		0001	5001	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	0.00	1,734.00	1,734.00	EA	1,734.00	\$5.46	\$9,467.64
		0001	5002	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	0.00	380.00	380.00	EA	380.00	\$8.45	\$3,211.00
		0001	5003	6189902	MISC.Mobilization for Full Depth Pavement Repair	0.00	1.00	1.00	EA	1.00	\$5,040.00	\$5,040.00
		0001	5004	6169901	MISC.Traffic Control One-Lane Two-Way Operation with Flagger	0.00	1.00	1.00	LS	1.00	\$2,238.30	\$2,238.30
		0010	5005	1094000	FORCE ACCOUNT	0.00	1.00	1.00	EA	1.00	\$5,910.06	\$5,910.06
		0010	5006	6069902	MISC.Drilling for Guardrail Posts	0.00	66.00	66.00	EA	66.00	\$194.25	\$12,820.50
		0010	5007	6061074	MGS HEIGHT AND BLOCK TRANSITION	0.00	3.00	3.00	EA	3.00	\$635.25	\$1,905.75
		0010	5008	9039902	MISC.Relocation of Existing Sign Assemblies	0.00	4.00	4.00	EA	4.00	\$1,706.25	\$6,825.00
Pro	oject J4	P3249 - To	otal Value	e Posted to E	Date as of Report Generated Date							\$6,621,427.25
J4P	P3260	0001	0710	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$43,551.00	\$43,551.00
		0001	0720	2031000	CLASS A EXCAVATION	2,164.00	0.00	2,164.00	CUYD	2,164.00	\$39.00	\$84,396.00
		0001	0730	2036000	COMPACTING EMBANKMENT	218.00	0.00	218.00	CUYD	218.00	\$3.00	\$654.00
		0001	0740	2037075	COMPACTING IN CUT	35.00	0.00	35.00	STA	35.00	\$357.00	\$12,495.00
		0001	0750	2063000	CLASS 3 EXCAVATION	12.00	0.00	12.00	CUYD	12.00	\$12.00	\$144.00
		0001	0760	2071000	LINEAR GRADING CLASS 1	1.00	0.00	1.00	STA	1.00	\$1,895.00	\$1,895.00
		0001	0770	2072000	LINEAR GRADING CLASS 2	10.00	0.00	10.00	STA	1.20	\$1,045.00	\$1,254.00
		0001	0780	2153000	SHAPING SLOPES, CLASS III	5.00	-1.00	4.00	100F	4.00	\$950.00	\$3,800.00



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Contract Nm.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-C04	J4P3260	0001	0800	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	82.00	0.00	82.00	TONS	82.00	\$380.73	\$31,219.86
		0001	0810	4010151	TYPE A3 SHOULDER	533.00	0.00	533.00	SQYD	196.00	\$51.25	\$10,045.00
		0001	0820	4011211	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	5,299.00	0.00	5,299.00	TONS	5,095.91	\$64.53	\$328,839.07
		0001	0830	4019905	MISC.OPTIONAL PAVEMENT	800.00	0.00	800.00	SQYD	550.00	\$63.60	\$34,980.00
		0001	0840	4030005	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP095C MIX)	12,363.00	0.00	12,363.00	TONS	14,049.46	\$64.98	\$912,933.91
		0001	0850	4071005	TACK COAT	17,957.00	0.00	17,957.00	GAL	22,098.00	\$2.50	\$55,245.00
		0001	0860	4079912	MISC.POLYMER MODIFIED EMULSION MEMBRANE	1,340.00	0.00	1,340.00	GAL	0.00	\$2.50	\$0.00
		0001	0870	5021108	CONCRETE PAVEMENT (8 IN. NON-REINF)	12.00	0.00	12.00	SQYD	12.00	\$200.60	\$2,407.20
		0001	0880	6081010	CONCRETE CURB RAMP	10.00	0.00	10.00	SQYD	10.00	\$445.80	\$4,458.00
		0001	0890	6081012	TRUNCATED DOMES	48.00	0.00	48.00	SQFT	48.00	\$16.90	\$811.20
		0001	0900	6086004	CONCRETE SIDEWALK, 4 IN.	1,005.00	0.00	1,005.00	SQYD	948.81	\$48.25	\$45,780.08
		0001	0910	6099903	MISC.KCMO CURB & GUTTER TYPE CG-1	332.00	0.00	332.00	LF	313.00	\$31.90	\$9,984.70
		0001	0920	6099903	MISC.KCMO CURB & GUTTER TYPE CG-2	56.00	0.00	56.00	LF	56.00	\$55.10	\$3,085.60
		0001	0930	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$1,500.00	\$0.00
		0001	0940	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	739.00	-243.60	495.40	SQYD	495.40	\$369.20	\$182,901.68
		0001	0950	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	495.00	-495.00	0.00	SQYD	0.00	\$5.57	\$0.00
		0001	0960	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	495.00	-495.00	0.00	SQYD	0.00	\$23.08	\$0.00
		0001	0970	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	1,204.00	961.00	2,165.00	LF	2,165.00	\$5.00	\$10,825.00
		0001	0980	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	380.00	-24.00	356.00	EA	356.00	\$5.20	\$1,851.20
		0001	0990	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	230.00	-194.00	36.00	EA	36.00	\$7.05	\$253.80
		0001	1000	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	161.40	22.70	184.10	TONS	184.10	\$219.86	\$40,476.23
		0001	1010	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	734.20	161.60	895.80	SQYD	895.80	\$229.52	\$205,604.02
		0001	1020	6141024	GRATE AND BEARING PLATE (5 FT. X 3 FT. OR $$ 1524 MM X 914 MM)	1.00	0.00	1.00	EA	1.00	\$1,990.00	\$1,990.00
		0001	1030	6143013	MANHOLE FRAME AND COVER, TYPE 3	1.00	0.00	1.00	EA	1.00	\$628.00	\$628.00
		0001	1040	6161005	CONSTRUCTION SIGNS	1,491.00	0.00	1,491.00	SQFT	1,027.00	\$5.50	\$5,648.50
		0001	1050	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	0.00	\$80.00	\$0.00
		0001	1060	6161009	FLAG ASSEMBLY	14.00	0.00	14.00	EA	0.00	\$20.00	\$0.00
		0001	1070	6161025	CHANNELIZER (TRIM LINE)	350.00	0.00	350.00	EA	350.00	\$12.00	\$4,200.00
		0001	1080	6161030	TYPE III MOVEABLE BARRICADE	6.00	0.00	6.00	EA	6.00	\$125.00	\$750.00
		0001	1090	6161040	FLASHING ARROW PANEL	3.00	0.00	3.00	EA	1.00	\$750.00	\$750.00
		0001	1100	6161055	SEQUENTIAL FLASHING WARNING LIGHT	36.00	0.00	36.00	EA	0.00	\$65.00	\$0.00
		0001	1110	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	2.00	\$3,650.00	\$7,300.00
		0001	1120	6169902	MISC.ADA COMPLIANT MOVABLE BARRICADE	4.00	0.00	4.00	EA	0.00	\$65.00	\$0.00
		0001	1130	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$162,039.28	\$162,039.28
		0001	1140	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	12,914.00	0.00	12,914.00	LF	12,914.00	\$3.65	\$47,136.10
		0001	1150	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	1,650.00	0.00	1,650.00	LF	2,351.00	\$18.00	\$42,318.00
		0001	1160	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	172.00	0.00	172.00	EA	156.00	\$180.00	\$28,080.00
		0001	1170	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	5.00	0.00	5.00	EA	5.00	\$180.00	\$900.00
		0001	1180	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	6.00	0.00	6.00	EA	2.00	\$400.00	\$800.00
		0001	1185	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	8.00	0.00	8.00	EA	8.00	\$400.00	\$3,200.00
		0001	1190	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	195.00	0.00	195.00	EA	195.00	\$180.00	\$35,100.00
		0001	1200	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	90,209.00	0.00	90,209.00	LF	76,035.00	\$0.14	\$10,644.90
		0001	1210	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	69,551.00	0.00	69,551.00	LF	69,551.00	\$0.18	\$12,519.18

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Note: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted amo	ount at the t	ime the E	stimate was	Genera	ted.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-C04	J4P3260	0001	1220	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,466.00	0.00	7,466.00	LF	7,466.00	\$0.20	\$1,493.20
		0001	1230	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	237.00	0.00	237.00	LF	237.00	\$2.50	\$592.50
		0001	1240	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,834.00	0.00	1,834.00	LF	576.00	\$0.16	\$92.16
		0001	1244	6200003	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	2,379.00	0.00	2,379.00	LF	2,379.00	\$3.30	\$7,850.70
		0001	1248	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	2,014.00	0.00	2,014.00	LF	2,014.00	\$0.16	\$322.24
		0001	1250	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	350.00	0.00	350.00	LF	0.00	\$3.00	\$0.00
		0001	1260	6206125A	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	2,132.00	0.00	2,132.00	LF	0.00	\$3.00	\$0.00
		0001	1264	6207001	PAVEMENT MARKING REMOVAL	7,693.00	0.00	7,693.00	LF	7,258.00	\$1.00	\$7,258.00
		0001	1266	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	80.00	0.00	80.00	EA	79.00	\$45.00	\$3,555.00
		0001	1270	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	180,467.00	0.00	180,467.00	SQYD	185,948.78	\$1.96	\$364,459.61
		0001	1280	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	4,366.00	0.00	4,366.00	SQYD	3,336.64	\$5.50	\$18,351.52
		0001	1290	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	345.30	0.00	345.30	STA	284.70	\$23.21	\$6,607.89
		0001	1300	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$10,000.00	\$10,000.00
		0001	1310	7250324A	24 IN. PIPE GROUP B	6.00	0.00	6.00	LF	3.00	\$209.00	\$627.00
		0001	1320	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	2.00	0.00	2.00	FT	2.00	\$1,850.00	\$3,700.00
		0001	1330	7320624A	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$1,415.00	\$1,415.00
		0001	1340	8051000A	SEEDING - COOL SEASON MIXTURES	2.10	0.00	2.10	ACRE	1.00	\$3,070.00	\$3,070.00
		0001	1350	8061004	SEDIMENT TRAP ROCK	20.00	0.00	20.00	CUYD	5.00	\$73.00	\$365.00
		0001	1360	8061005	ROCK DITCH CHECK	36.00	0.00	36.00	LF	18.00	\$40.00	\$720.00
		0001	1370	8061006	ALTERNATE DITCH CHECK	1,013.00	0.00	1,013.00	LF	345.00	\$16.00	\$5,520.00
		0001	1380	8061007A	CURB INLET CHECK	4.00	0.00	4.00	EA	6.00	\$126.00	\$756.00
		0001	1390	8061016	SEDIMENT REMOVAL	146.00	0.00	146.00	CUYD	0.00	\$35.00	\$0.00
		0001	1400	8061019	SILT FENCE	7,156.00	0.00	7,156.00	LF	1,774.00	\$3.00	\$5,322.00
		0001	1410	8064129	TYPE 2 TURF REINFORCEMENT MAT	1,451.00	0.00	1,451.00	SQYD	1,451.00	\$4.96	\$7,196.96
		0010	1420	6061060	MGS GUARDRAIL	1,088.00	87.00	1,175.00	LF	1,175.00	\$18.50	\$21,737.50
		0010	1430	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	738.00	-75.00	663.00	LF	663.00	\$21.50	\$14,254.50
		0010	1440	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	3.00	0.00	3.00	EA	3.00	\$2,800.00	\$8,400.00
		0010	1450	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	7.00	0.00	7.00	EA	7.00	\$2,450.00	\$17,150.00
		0030	1460	9020213	SIGNAL HEAD, TYPE 3S	1.00	0.00	1.00	EA	1.00	\$2,449.00	\$2,449.00
		0030	1470	9020811	SIGNAL HEAD, TYPE 1S, PEDESTRIAN	2.00	0.00	2.00	EA	2.00	\$1,964.00	\$3,928.00
		0030	1480	9020833	SH-FLAT SHEET - SIGNAL SIGN	2.00	0.00	2.00	SQFT	0.00	\$277.00	\$0.00
		0030	1490	9020834	SIGNAL SIGN, MOUNTING HARDWARE	2.00	0.00	2.00	EA	0.00	\$220.00	\$0.00
		0030	1500	9022708	POST, SIGNAL 8 FT. OR 2.4 M	2.00	0.00	2.00	EA	2.00	\$2,241.00	\$4,482.00
		0030	1510	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	43.00	0.00	43.00	LF	43.00	\$38.00	\$1,634.00
		0030	1520	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	24.00	0.00	24.00	LF	24.00	\$38.00	\$912.00
		0030	1530	9027400	CONDUIT, 4 IN., PUSHED WITH TRACER WIRE	126.00	0.00	126.00	LF	126.00	\$44.10	\$5,556.60
		0030	1540	9028308	CABLE, 16 AWG 2 CONDUCTOR	270.00	0.00	270.00	LF	270.00	\$2.80	\$756.00
		0030	1550	9028310	CABLE, 16 AWG 5 CONDUCTOR	270.00	0.00	270.00	LF	270.00	\$3.20	\$864.00
		0030	1560	9028311	CABLE, 16 AWG 7 CONDUCTOR	130.00	0.00	130.00	LF	130.00	\$3.60	\$468.00
		0030	1570	9028811	PULL BOX, PREFORMED CLASS 2	2.00	0.00	2.00	EA	2.00	\$2,341.00	\$4,682.00
		0030	1580	9029100	BASE, CONCRETE	0.90	0.00	0.90	CUYD	0.90	\$3,736.00	\$3,362.40
		0030	1590	9029902	MISC.ACCESSIBLE PEDESTRIAN SIGNAL (PUSHBUTTONS)	2.00	0.00	2.00	EA	0.00	\$2,380.00	\$0.00
		0040	1600	9039902	MISC.RELOCATION OF EXISTING SIGN ASSEMBLIES	4.00	4.00	8.00	EA	8.00	\$2,500.00	\$20,000.00
		0001	5101	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	0.00	40.00	40.00	EA	40.00	\$8.45	\$338.00



Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					opent centerated date and can aller herr the peeted and							
Contract Nm.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-C04	J4P3260	0001	5102	6189902	MISC.MOBILIZATION FOR FULL DEPTH PAVEMENT REPAIR	0.00	1.00	1.00	EA	1.00	\$5,040.00	\$5,040.00
		0001	5103	6169902	MISC.SINGLE LANE CLOSURES FOR FULL DEPTH PAVEMENT REPAIR	0.00	2.00	2.00	EA	2.00	\$3,150.00	\$6,300.00
	Project J4	4P3260 - To	otal Value	Posted to D	Date as of Report Generated Date							\$2,981,403.28
200117-C04 Overall - Total Value Posted to Date as of Report Generated Date											\$9,602,830.53	



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4P3249

Line Number	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
5005	1094000	FORCE ACCOUNT	11/30/20	12/2/20	1.00	EA	Old Highway 291 (log miles for SB 291)	15.068		15.138		
5006	6069902	MISC. GUARDRAIL ITEM	11/30/20	12/2/20	66.00	EA	Bridge A4755, A2506, and longspan on Old HWY 291	18.269		41.166		
5007	6061074	MGS HEIGHT AND BLOCK TRANSITION	11/30/20	12/2/20	3.00	EA	291 NB at Bridge L0568 and Outer 291 South end of ROW	14.942		36.397		
5008	9039902	MISC.	11/30/20	12/2/20	4.00	EA	Turn Islands at Kentucky, Salisbury, Indpendence, and Sunset	15.647		18.697		

Project: J4P3260

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
1470	9020811	SIGNAL HEAD, TYPE 1S, PEDESTRIAN	11/30/20	12/2/20	2.00	EA	Flintlock Road crosswalk	50+38.7		118+49.52		Work done on 10/23
1510	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	11/30/20	12/2/20	43.00	LF	Flintlock and 291 between the pull box and pedestrian signal.	50+23.81		118+63.21		Work done on 10/23
1520	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	11/30/20	12/2/20	24.00	LF	Flintlock and 291 from pull box 1 to controller cabinet 1	118+63.21		118+75		work done on 10/23
1530	9027400	CONDUIT, 4 IN., PUSHED WITH TRACER WIRE	11/30/20	12/2/20	126.00	LF	Flintlock and 291 between pull box 1 and pull box 2.	50+23.81		118+63.21		work done on 10/23.
1570	9028811	PULL BOX, PREFORMED CLASS 2	11/30/20	12/2/20	2.00	EA	291 and Flintlock SW and NW quadrants	50+23.81		118+63.21		Work done on 10/23
1580	9029100	BASE, CONCRETE	11/30/20	12/2/20	0.90	CUYD	Flintlock Road crosswalk	50+38.7		118+49.52		Work done on 10/22
1600	9039902	MISC.	11/30/20	12/2/20	4.00	EA	291 SB between 112th and Wallace	100+00		5+42		

The information below this line are details from Line Item agency views. No Agency View Details Exist



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
050	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material	Type	7	Oct 16, 2020	SYSTEM	(\$5,096.00)	
				7	Oct 16, 2020	SYSTEM	\$5,096.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0002) due to user yostj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$5,096.00)	
				8	Nov 2, 2020	SYSTEM	\$5,096.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0008) due to user yostj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$5,096.00)	
				9	Nov 16, 2020	SYSTEM	\$5,096.00	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0005) due to user yostj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$5,096.00)	
				10	Dec 2, 2020	SYSTEM	\$5,096.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0039) due to user yostj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		7	Oct 16, 2020	SYSTEM	(\$14.02)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$14.02)	
	Price - Total						(\$14.02)	
050 -	·Total						(\$14.02)	
060	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material		7	Oct 16, 2020	SYSTEM	(\$54,332.22)	
				7	Oct 16, 2020	SYSTEM	\$54,332.22	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0004) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$54,332.22)	
				8	Nov 2, 2020	SYSTEM	\$54,332.22	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0009) due to user yostj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$54,332.22)	
				9	Nov 16, 2020	SYSTEM	\$54,332.22	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0006) due to user yostj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$54,332.22)	
				10	Dec 2, 2020	SYSTEM	\$54,332.22	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0040) due to user yostj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
060 -	Total						\$0.00	
070	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Material		5	Sep 16, 2020	SYSTEM	(\$599,503.13)	
				5	Sep 16, 2020	SYSTEM	\$599,503.13	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0006) due to user yostj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				6	Oct 1, 2020	SYSTEM	(\$840,921.00)	
				6	Oct 1, 2020	SYSTEM	\$840,921.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0041) due to user yostj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				7	Oct 16, 2020	SYSTEM	(\$1,162,467.13)	
				7	Oct 16, 2020	SYSTEM	\$1,162,467.13	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user yostj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				8	Nov 2,	SYSTEM	(\$1,256,033.06)	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
070	BITUMINOUS PAVEMENT	Material			2020						
	MIXTURE PG64-22, (BP-1)			8	Nov 2, 2020	SYSTEM	\$1,256,033.06	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0004) due to user yostj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
				9	Nov 16, 2020	SYSTEM	(\$1,256,033.06)				
				9	Nov 16, 2020	SYSTEM	\$1,256,033.06	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0007) due to user yostj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
				10	Dec 2, 2020	SYSTEM	(\$1,256,033.06)				
				10	Dec 2, 2020	SYSTEM	\$1,256,033.06	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0041) due to user yostj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
			- Total				\$0.00				
	Material - Total						\$0.00				
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Other Item Adjustment	ACAD	4	Sep 2, 2020	yostj1	(\$2,095.92)	Asphalt cement price adjustment for the dates 8/16/20 through 8/31/20 Adjustments for the dates 8/20, 8/24, and 9/1 are not included and will be corrected once quantities are agreed upon.			
				5	Sep 16, 2020	yostj1	(\$15,372.12)	Asphalt cement price adjustment for dates 9/1 through 9/15 with additional adjustments for 8/20 and 8/24 that were not included on the previous estimate.			
				6	Oct 1, 2020	yostj1	(\$7,034.32)	Asphalt cement price adjustment for dates 9/16 through 9/29.			
				7	Oct 16, 2020	yostj1	(\$9,369.06)	Asphalt cement price adjustment for the dates 10/01 to 10/15.			
			ACAD - To		8	Nov 2, 2020	yostj1	(\$2,726.28)			
			ACAD - Tota	al	_		(\$36,597.70)				
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)		FUEL	5	Sep 16, 2020	yostj1	(\$72.28)	Fuel price adjustment correction on items paid on 9/12, but the work was performed on 8/20 and 8/24. The system autogenerated the 332.7 tons using the factors for September instead of August.			
			FUEL - Total				(\$72.28)				
	Other Item Adjustment - Total						(\$36,669.98)				
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Price		4	Sep 2, 2020	SYSTEM	(\$2,435.46)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
				5	Sep 16, 2020	SYSTEM	(\$17,096.87)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
				6	Oct 1, 2020	SYSTEM	(\$7,823.57)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
				7	Oct 16, 2020	SYSTEM	(\$11,353.42)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
				8	Nov 2, 2020	SYSTEM	(, , , , , , , , , , , , , , , , , , ,	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
			- Total				(\$42,013.02)				
	Price - Total						(\$42,013.02)				
	- Total						(\$78,683.00)				
090	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125B MIX)	Material		3	Aug 17, 2020	SYSTEM	(\$998,823.75)				
				3	Aug 17, 2020	SYSTEM	\$998,823.75	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0010) due to user yostj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
				4	Sep 2, 2020	SYSTEM	(\$1,456,140.98)				
				4	Sep 2, 2020	SYSTEM	\$1,456,140.98	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0005) due to user yostj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
				5	Sep 16, 2020	SYSTEM	(\$1,503,695.41)				
			5	5	Ę	5	Sep 16, 2020	SYSTEM	\$1,503,695.41	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0010) due to user yostj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					6	Oct 1, 2020	SYSTEM	(\$2,072,681.60)			



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0090	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125B	Material			2020			Estimate Item Adjustment (0042) due to user yostj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
	MIX)			7	Oct 16, 2020	SYSTEM	(\$2,192,547.59)	
				7	Oct 16, 2020	SYSTEM	\$2,192,547.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user yostj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$2,325,404.60)	
				8	Nov 2, 2020	SYSTEM	\$2,325,404.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user yostj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$2,325,404.60)	
				9	Nov 16, 2020	SYSTEM	\$2,325,404.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user yostj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$2,325,404.60)	
				10	Dec 2, 2020	SYSTEM	\$2,325,404.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0042) due to user yostj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125B	Other Item Adjustment	ACAD	3	Aug 17, 2020	yostj1	(\$43,460.81)	Asphalt cement price adjustment for dates 7/28/20 through 8/15/20.
	MIX)			4	Sep 2, 2020	yostj1	(\$19,950.93)	Asphalt cement price adjustment for the dates 8/16/20 through 8/31/20. Adjustments for the dates 8/20, 8/24, and 9/1 are not included and will be corrected once quantities are agreed upon.
				5	Sep 16, 2020	yostj1	(\$2,074.61)	Asphalt cement price adjustment for dates 9/1 through 9/15 with additional adjustments for 8/20 and 8/24 that were not included on the previous estimate and a correction for 8/25.
				6	Oct 1, 2020	yostj1	(\$28,992.08)	Asphalt cement price adjustment for dates 9/16 through 9/29.
				7	Oct 16, 2020	yostj1	(\$1,059.79)	Asphalt cement price adjustment for the dates 10/01 to 10/15.
				8	Nov 2, 2020	yostj1	(\$5,796.02)	Asphalt cement price adjustment for dates 10/16 through 11/1.
			ACAD - Tota	al			(\$101,334.24)	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125B MIX)		FUEL	5	Sep 16, 2020	yostj1	(\$67.11)	Fuel price adjustment correction on items paid or correctied on 9/12, but the work was performed on 8/20, 8/24, or 8/25. The system autogenerated the 385.89 tons using the factors for September instead of August.
			FUEL - Tota	ıl			(\$67.11)	
	Other Item Adjustment - Total						(\$101,401.35)	
	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125B MIX)	Price		3	Aug 17, 2020	SYSTEM	(\$42,599.18)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
	WIX)			4	Sep 2, 2020	SYSTEM	(\$19,522.50)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				5	Sep 16, 2020	SYSTEM	(\$1,943.05)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				6	Oct 1, 2020	SYSTEM	(\$23,248.58)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				7	Oct 16, 2020	SYSTEM	(\$4,986.57)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				8	Nov 2, 2020	SYSTEM	(\$5,914.63)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$98,214.51)	
	Price - Total						(\$98,214.51)	
0090 -	Total						(\$199,615.86)	
0100	TACK COAT	Material		3	Aug 17, 2020	SYSTEM	(\$42,318.00)	
				3	Aug 17, 2020	SYSTEM	\$42,318.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user yostj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0100	TACK COAT	Material		4	Sep 2, 2020	SYSTEM	(\$67,666.50)	
				4	Sep 2, 2020	SYSTEM	\$67,666.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user yostj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				5	Sep 16, 2020	SYSTEM	(\$81,648.00)	
				5	Sep 16, 2020	SYSTEM	\$81,648.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user yostj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				6	Oct 1, 2020	SYSTEM	(\$89,703.00)	
				6	Oct 1, 2020	SYSTEM	\$89,703.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) due to user yostj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total					\$0.00		
	TACK COAT	Overrun	Overrun	8	Nov 2, 2020	SYSTEM	(\$8,428.50)	
		Overrun - Te	otal			(\$8,428.50)		
	Overrun - Total						(\$8,428.50)	
0100 -	Total						(\$8,428.50)	
0110	MISC. POLYMER MODIFIED EMULSION MEMBRANE	Material		6	Oct 1, 2020	SYSTEM	(\$64,805.35)	
				6	Oct 1, 2020	SYSTEM	\$64,805.35	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0044) due to user yostj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0110 -	·Total				_		\$0.00	
0120	ULTRATHIN BONDED WEARING SURFACE, TYPE B	Material		6	Oct 1, 2020	SYSTEM	(\$140,169.04)	
				6	Oct 1, 2020	SYSTEM	\$140,169.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0045) due to user yostj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				7	Oct 16, 2020	SYSTEM	(\$140,169.04)	
				7	Oct 16, 2020	SYSTEM	\$140,169.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user yostj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$140,169.04)	
				8	Nov 2, 2020	SYSTEM	\$140,169.04	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user yostj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	ULTRATHIN BONDED WEARING SURFACE, TYPE B		ACAD	6	Oct 1, 2020	yostj1	(\$3,145.42)	Asphalt cement price adjustment for dates 9/16 through 9/29.
			ACAD - Tota	ıl			(\$3,145.42)	
	Other Item Adjustment - Total						(\$3,145.42)	
	ULTRATHIN BONDED WEARING SURFACE, TYPE B	Price		6	Oct 1, 2020	SYSTEM	(\$2,487.80)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$2,487.80)	
	Price - Total						(\$2,487.80)	
	Total						(\$5,633.22)	
0120 -	CONCRETE PAVEMENT (8 IN.	Material		6	Oct 1, 2020	SYSTEM	(\$938.40)	
0120 - 0130	NON-REINF)							
				6	Oct 1, 2020	SYSTEM	\$938.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0046) due to user yostj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0130	CONCRETE PAVEMENT (8 IN. NON-REINF)	Material		7	Oct 16, 2020	SYSTEM	\$938.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user yostj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$938.40)	
				8	Nov 2, 2020	SYSTEM	\$938.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user yostj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	CONCRETE PAVEMENT (8 IN. NON-REINF)	Price		6	Oct 1, 2020	SYSTEM	(\$2.41)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$2.41)	
	Price - Total						(\$2.41)	
0130 -	Total						(\$2.41)	
0150	CONCRETE MEDIAN	Material		8	Nov 2, 2020	SYSTEM	(\$12,340.90)	
				8	Nov 2, 2020	SYSTEM	\$12,340.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user yostj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$28,821.80)	
				9	Nov 16, 2020	SYSTEM	\$28,821.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user yostj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$28,821.80)	
				10	Dec 2, 2020	SYSTEM	\$28,821.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) due to user yostj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0150 -	Total						\$0.00	
0160	6 IN. CONCRETE MEDIAN STRIP	Material		8	Nov 2, 2020	SYSTEM	(\$2,890.55)	
				8	Nov 2, 2020	SYSTEM	\$2,890.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user yostj1 overridding
					2020			Payment Estimate Exception 26 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$2,890.55)	Payment Estimate Exception 26 on the current Payment Estimate.
				9 9	Nov 16,	SYSTEM SYSTEM	(\$2,890.55) \$2,890.55	Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user yostj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					Nov 16, 2020 Nov 16,		,	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user yostj1 overridding
				9	Nov 16, 2020 Nov 16, 2020 Dec 2,	SYSTEM	\$2,890.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user yostj1 overridding
			- Total	9	Nov 16, 2020 Nov 16, 2020 Dec 2, 2020 Dec 2,	SYSTEM SYSTEM	\$2,890.55 (\$2,890.55)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user yostj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
	Material - Total		- Total	9	Nov 16, 2020 Nov 16, 2020 Dec 2, 2020 Dec 2,	SYSTEM SYSTEM	\$2,890.55 (\$2,890.55) \$2,890.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user yostj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
0160 -			- Total	9	Nov 16, 2020 Nov 16, 2020 Dec 2, 2020 Dec 2,	SYSTEM SYSTEM	\$2,890.55 (\$2,890.55) \$2,890.55 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user yostj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
0160 - 0170		Material	- Total	9	Nov 16, 2020 Nov 16, 2020 Dec 2, 2020 Dec 2,	SYSTEM SYSTEM	\$2,890.55 (\$2,890.55) \$2,890.55 \$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user yostj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
	Total INTEGRAL CURB (6 IN. HEIGHT	Material	- Total	9 10 10	Nov 16, 2020 Nov 16, 2020 Dec 2, 2020 Dec 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM	\$2,890.55 (\$2,890.55) \$2,890.55 \$0.00 \$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user yostj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
	Total INTEGRAL CURB (6 IN. HEIGHT	Material	- Total	9 10 10 8	Nov 16, 2020 Nov 16, 2020 Dec 2, 2020 Dec 2, 2020 Nov 2, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$2,890.55 (\$2,890.55) \$2,890.55 \$0.00 \$0.00 \$0.00 (\$8,233.67)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user yostj1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0046) due to user yostj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
	Total INTEGRAL CURB (6 IN. HEIGHT	Material	- Total	9 10 10 8 8	Nov 16, 2020 Dec 2, 2020 Dec 2, 2020 Nov 2, 2020 Nov 2, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,890.55 (\$2,890.55) \$2,890.55 \$0.00 \$0.00 (\$8,233.67) \$8,233.67	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user yostj1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0046) due to user yostj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
	Total INTEGRAL CURB (6 IN. HEIGHT	Material	- Total	9 10 10 8 8 8 9	Nov 16, 2020 Dec 2, 2020 Dec 2, 2020 Nov 2, 2020 Nov 2, 2020 Nov 2, 2020 Nov 2, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,890.55 (\$2,890.55) \$2,890.55 \$0.00 \$0.00 (\$8,233.67) \$8,233.67 (\$13,606.50)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user yostj1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0046) due to user yostj1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0046) due to user yostj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
0170	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material						Payment Estimate Exception 24 on the current Payment Estimate.		
			- Total				\$0.00			
	Material - Total						\$0.00			
0170 -	Total						\$0.00			
0210	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT	Material		1	Jul 17, 2020	SYSTEM	(\$147,057.00)			
	REPAIR			2	Aug 3, 2020	SYSTEM	(\$232,559.68)			
				3	Aug 17, 2020	SYSTEM	(\$256,441.95)			
				3	Aug 17, 2020	SYSTEM	\$256,441.95	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0014) due to user yostj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
				4	Sep 2, 2020	SYSTEM	(\$256,441.95)			
				4	Sep 2, 2020	SYSTEM	\$256,441.95	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0010) due to user yostj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
				5	Sep 16, 2020	SYSTEM	(\$256,441.95)			
				5	Sep 16, 2020	SYSTEM	\$256,441.95	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0013) due to user yostj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.		
				6	Oct 1, 2020	SYSTEM	(\$256,441.95)			
				6	Oct 1, 2020	SYSTEM	\$256,441.95	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0047) due to user yostj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.		
				7	Oct 16, 2020	SYSTEM	(\$256,441.95)			
						7	Oct 16, 2020	SYSTEM	\$256,441.95	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0015) due to user yostj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$256,441.95)			
				8	Nov 2, 2020	SYSTEM	\$256,441.95	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0019) due to user yostj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.		
				9	Nov 16, 2020	SYSTEM	(\$409,260.98)			
				9	Nov 16, 2020	SYSTEM	\$409,260.98	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0010) due to user yostj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.		
				10	Dec 2, 2020	SYSTEM	(\$409,260.98)			
				10	Dec 2, 2020	SYSTEM	\$409,260.98	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0047) due to user yostj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.		
			- Total				(\$379,616.68)			
	Material - Total						(\$379,616.68)			
	FURNISHING AND PLACING CONCRETE MATERIAL FOR	MaterialCredit		2	Aug 3, 2020	SYSTEM	\$147,057.00			
	FULL DEPTH PAVEMENT REPAIR			3	Aug 17, 2020	SYSTEM	\$232,559.68			
			- Total				\$379,616.68			
	MaterialCredit - Total						\$379,616.68			
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Adjustment	OTHR	6	Oct 1, 2020	yostj1	\$3,165.95	An adjustment was made on estimate 0003 to correct the autogenerated adjustment for an item that was an overrun and had insufficient materials testing. Now that the change order has processed that adjustment is no longer needed and therefore this adjustments makes that correction.		
			OTHR - Tota	al			\$3,165.95			
	FURNISHING AND PLACING CONCRETE MATERIAL FOR		PPPS	1	Jul 17, 2020	kinga1	\$147,057.00	Payment made for completed work. Working with Materials and QC to resolve exception related to system-generated deduction.		
	FULL DEPTH PAVEMENT			3	Aug 17,	yostj1	(\$147,057.00)	This adjustment offsets the partial payment for pending sample done or		



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0210	REPAIR	Other Item Adjustment	PPPS		2020			estimate 0002 and allows the override to control the material adjustment. Working with Materials and QC to resolve exception.
			PPPS - Tota	d.			\$0.00	
	Other Item Adjustment - Total						\$3,165.95	
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT	Overrun	Overrun	3	Aug 17, 2020	SYSTEM	(\$3,165.95)	
	REPAIR			3	Aug 17, 2020	SYSTEM	\$3,165.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 23 on the current Payment Estimate.
				3	Aug 17, 2020	yostj1	(\$3,165.95)	
				4	Sep 2, 2020	SYSTEM	(\$3,165.95)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				4	Sep 2, 2020	SYSTEM	\$3,165.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 16 on the current Payment Estimate.
				5	Sep 16, 2020	SYSTEM	(\$3,165.95)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				5	Sep 16, 2020	SYSTEM	\$3,165.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 21 on the current Payment Estimate.
			Overrun - T	otal			(\$3,165.95)	
	Overrun - Total						(\$3,165.95)	
0210 -	Total						\$0.00	
0240	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	Overrun	Overrun	2	Aug 3, 2020	SYSTEM	(\$2,892.00)	
	SAW CUTS)	2020		3		SYSTEM	(\$2,853.00)	
			SYSTEM	\$5,745.00	Unit price based on averaged overrun adjustments for installed quantity			
					2020			on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is applied (if non-zero).
			Overrun - T	otal	2020		\$0.00	on all previous payment estimates. Price Adjustments of ',5.00000 -
	Overrun - Total		Overrun - T	otal	2020		\$0.00 \$0.00	on all previous payment estimates. Price Adjustments of ',5.00000 -
0240 -	Overrun - Total Total		Overrun - T	otal	2020			on all previous payment estimates. Price Adjustments of ',5.00000 -
0240 - 0250	Total DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS)	Material	Overrun - T	otal	2020 Jul 17, 2020	SYSTEM	\$0.00	on all previous payment estimates. Price Adjustments of ',5.00000 -
	Total DOWEL BAR (FURNISHING AND	Material	Overrun - T		Jul 17,	SYSTEM	\$0.00 \$0.00	on all previous payment estimates. Price Adjustments of ',5.00000 -
	Total DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT	Material	Overrun - T	1	Jul 17, 2020 Aug 3,		\$0.00 \$0.00 (\$3,792.90)	on all previous payment estimates. Price Adjustments of ',5.00000 -
	Total DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT	Material	Overrun - T	1	Jul 17, 2020 Aug 3, 2020 Aug 17,	SYSTEM	\$0.00 \$0.00 (\$3,792.90) (\$5,687.00)	on all previous payment estimates. Price Adjustments of ',5.00000 -
	Total DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT	Material	Overrun - T	1 2 3	2020 Aug 3, 2020 Aug 17, 2020 Aug 17,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,792.90) (\$5,687.00) (\$7,397.80)	on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is applied (if non-zero).
	Total DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT	Material	Overrun - T	1 2 3 3	Jul 17, 2020 Aug 3, 2020 Aug 17, 2020 Aug 17, 2020 Sep 2,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,792.90) (\$5,687.00) (\$7,397.80) \$7,397.80	on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is applied (if non-zero).
	Total DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT	Material	Overrun - T	1 2 3 3 4	Jul 17, 2020 Aug 3, 2020 Aug 17, 2020 Aug 17, 2020 Sep 2, 2020 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,792.90) (\$5,687.00) (\$7,397.80) \$7,397.80 (\$7,397.80)	on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is applied (if non-zero).
	Total DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT	Material	Overrun - T	1 2 3 3 4 4 4	Jul 17, 2020 Aug 3, 2020 Aug 17, 2020 Aug 17, 2020 Sep 2, 2020 Sep 2, 2020 Sep 2, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,792.90) (\$5,687.00) (\$7,397.80) \$7,397.80 (\$7,397.80) \$7,397.80	on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user yostj1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user yostj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
	Total DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT	Material	Overrun - T	1 2 3 3 4 4 5	Jul 17, 2020 Aug 3, 2020 Aug 17, 2020 Aug 17, 2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,792.90) (\$5,687.00) (\$7,397.80) \$7,397.80 (\$7,397.80) \$7,397.80 (\$7,397.80)	on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is applied (if non-zero).
	Total DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT	Material	Overrun - T	1 2 3 3 4 4 4 5 5	Jul 17, 2020 Aug 3, 2020 Aug 17, 2020 Aug 17, 2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,792.90) (\$5,687.00) (\$7,397.80) \$7,397.80 (\$7,397.80 \$7,397.80 \$7,397.80	on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is applied (if non-zero).
	Total DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT	Material	Overrun - T	1 2 3 3 4 4 4 5 5 5 6	Jul 17, Jul 2020 Aug 3, 2020 Aug 17, 2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,792.90) (\$5,687.00) (\$7,397.80) \$7,397.80 (\$7,397.80) \$7,397.80 (\$7,397.80) \$7,397.80 (\$7,397.80) \$7,397.80	on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is applied (if non-zero).
	Total DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT	Material		1 2 3 3 4 4 4 5 5 5 6	Jul 17, Jul 2020 Aug 3, 2020 Aug 17, 2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,792.90) (\$5,687.00) (\$7,397.80) \$7,397.80 (\$7,397.80) \$7,397.80 (\$7,397.80) \$7,397.80 (\$263.20) \$263.20	on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is applied (if non-zero).
	Total DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR		- Total	1 2 3 3 4 4 4 5 5 5 6	Jul 17, Jul 2020 Aug 3, 2020 Aug 17, 2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$3,792.90) (\$5,687.00) (\$7,397.80) \$7,397.80 (\$7,397.80) \$7,397.80 (\$7,397.80) \$7,397.80 (\$263.20) \$263.20 (\$9,479.90)	on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is applied (if non-zero).



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0250		MaterialCredit	Type - Total				\$9,479.90	
0200	MaterialCredit - Total	Inatonaloroali					\$9,479.90	
	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS)	Other Item Adjustment	PPPS	1	Jul 17, 2020	kinga1	\$3,792.90	Payment made for completed work. Working with Materials and QC to resolve exception related to system-generated deduction.
	FOR FULL DEPTH PAVEMENT REPAIR			3	Aug 17, 2020	yostj1	(\$3,792.90)	This adjustment offsets the partial payment for pending sample done on estimate 0002 and allows the override to control the material adjustment. Working with Materials and QC to resolve exception.
			PPPS - Tota	ıl			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0250 -	Total						\$0.00	
0260	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	Other Item Adjustment	ACAD	10	Dec 2, 2020	yostj1	(\$298.08)	Asphalt cement price adjustment for work between the dates 7/15/20 and 7/18/20.
			ACAD - Tota	al			(\$298.08)	
	Other Item Adjustment - Total						(\$298.08)	
0260 -	Total						(\$298.08)	
0280	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	Other Item Adjustment	ACAD	10	Dec 2, 2020	yostj1	(\$676.72)	Asphalt cement price adjustment for work between the dates 7/14/20 through 8/26/20
			ACAD - Tota	al			(\$676.72)	
	Other Item Adjustment - Total						(\$676.72)	
0280 -	Total				_		(\$676.72)	
0300	CONSTRUCTION SIGNS	Material		1	Jul 17, 2020	SYSTEM	(\$3,673.45)	
				2	Aug 3, 2020	SYSTEM	(\$3,673.45)	
				3	Aug 17, 2020	SYSTEM	(\$3,673.45)	
				3	Aug 17, 2020	SYSTEM	\$3,673.45	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user yostj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
			- Total				(\$7,346.90)	
	Material - Total						(\$7,346.90)	
	CONSTRUCTION SIGNS	MaterialCredit		2	Aug 3, 2020	SYSTEM	\$3,673.45	
				3	Aug 17, 2020	SYSTEM	\$3,673.45	
			- Total				\$7,346.90	
	MaterialCredit - Total						\$7,346.90	
	CONSTRUCTION SIGNS	Other Item Adjustment	PPPS	1	Jul 17, 2020	kinga1	\$3,673.45	Payment made for completed work. Working with Materials and QC to resolve exception related to system-generated deduction.
				3	Aug 17, 2020	yostj1	(\$3,673.45)	This adjustment offsets the partial payment for pending sample done on estimate 0002 and allows the override to control the material adjustment. Working with Materials and QC to resolve exception.
			PPPS - Tota	ıl			\$0.00	
	Other Item Adjustment - Total						\$0.00	
	CONSTRUCTION SIGNS	Overrun	Overrun		Sep 16, 2020	SYSTEM	(\$28.05)	
			Overrun - To	otal			(\$28.05)	
	Overrun - Total						(\$28.05)	
0300 -							(\$28.05)	
0310	ADVANCED WARNING RAIL SYSTEM	Material		1	Jul 17, 2020	SYSTEM	(\$320.00)	
				2	Aug 3, 2020	SYSTEM	(\$320.00)	
				3	Aug 17, 2020	SYSTEM	(\$320.00)	
				3	Aug 17, 2020	SYSTEM	\$320.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0310		Material	- Total				(\$640.00)	
	Material - Total						(\$640.00)	
	ADVANCED WARNING RAIL SYSTEM	MaterialCredit		2	Aug 3, 2020	SYSTEM	\$320.00	
				3	Aug 17, 2020	SYSTEM	\$320.00	
			- Total				\$640.00	
	MaterialCredit - Total						\$640.00	
	ADVANCED WARNING RAIL SYSTEM	Other Item Adjustment	PPPS	1	Jul 17, 2020	kinga1	\$320.00	Payment made for completed work. Working with Materials and QC to resolve exception related to system-generated deduction.
				3	Aug 17, 2020	yostj1	(\$320.00)	This adjustment offsets the partial payment for pending sample done or estimate 0002 and allows the override to control the material adjustment. Working with Materials and QC to resolve exception.
			PPPS - Tota	ıl			\$0.00	
	Other Item Adjustment - Total					\$0.00		
0310 -	Total						\$0.00	
0320	FLAG ASSEMBLY	Material		1	Jul 17, 2020	SYSTEM	(\$240.00)	
				2	Aug 3, 2020	SYSTEM	(\$240.00)	
				3	Aug 17, 2020	SYSTEM	(\$240.00)	
				3	Aug 17, 2020	SYSTEM	\$240.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0023) due to user yostj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
			- Total				(\$480.00)	
	Material - Total						(\$480.00)	
	FLAG ASSEMBLY	MaterialCredit		2	Aug 3, 2020	SYSTEM	\$240.00	
				3	Aug 17, 2020	SYSTEM	\$240.00	
			- Total				\$480.00	
	MaterialCredit - Total						\$480.00	
	FLAG ASSEMBLY	Other Item Adjustment	PPPS		Jul 17, 2020	kinga1	\$240.00	Payment made for completed work. Working with Materials and QC to resolve exception related to system-generated deduction.
				3	Aug 17, 2020	yostj1	(\$240.00)	This adjustment offsets the partial payment for pending sample done or estimate 0002 and allows the override to control the material adjustment. Working with Materials and QC to resolve exception.
			PPPS - Total				\$0.00	
	Other Item Adjustment - Total						\$0.00	
0320 -	Total						\$0.00	
0330	CHANNELIZER (TRIM LINE)	Material		1	Jul 17, 2020	SYSTEM	(\$4,200.00)	
				2	Aug 3, 2020	SYSTEM	(\$4,200.00)	
				3	Aug 17, 2020	SYSTEM	(\$4,200.00)	
				3	Aug 17, 2020	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user yostj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
			- Total				(\$8,400.00)	
	Material - Total						(\$8,400.00)	
	CHANNELIZER (TRIM LINE)	MaterialCredit		2	Aug 3, 2020	SYSTEM	\$4,200.00	
				3	Aug 17, 2020	SYSTEM	\$4,200.00	
							\$8,400.00	
	MaterialCredit - Total						\$8,400.00	
	CHANNELIZER (TRIM LINE)	Other Item Adjustment	PPPS	1	Jul 17, 2020	kinga1	\$4,200.00	Payment made for completed work. Working with Materials and QC to resolve exception related to system-generated deduction.
				3	Aug 17,	yostj1	(\$4,200.00)	This adjustment offsets the partial payment for pending sample done on



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	Description	Туре	Adjustment Type	Number	Date	By	Amount	i kumerika
0330	CHANNELIZER (TRIM LINE)	Other Item Adjustment	PPPS		2020			estimate 0002 and allows the override to control the material adjustment. Working with Materials and QC to resolve exception.
			PPPS - Tota	ıl			\$0.00	
	Other Item Adjustment - Total						\$0.00	
0330 -	Total						\$0.00	
0340	TYPE III MOVEABLE BARRICADE	Material		1	Jul 17, 2020	SYSTEM	(\$750.00)	
				2	Aug 3, 2020	SYSTEM	(\$750.00)	
				3	Aug 17, 2020	SYSTEM	(\$750.00)	
				3	Aug 17, 2020	SYSTEM	\$750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user yostj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
			- Total				(\$1,500.00)	
	Material - Total						(\$1,500.00)	
	TYPE III MOVEABLE BARRICADE	MaterialCredit		2	Aug 3, 2020	SYSTEM	\$750.00	
				3	Aug 17, 2020	SYSTEM	\$750.00	
			- Total				\$1,500.00	
	MaterialCredit - Total						\$1,500.00	
	TYPE III MOVEABLE BARRICADE	Other Item Adjustment	PPPS	1	Jul 17, 2020	kinga1	\$750.00	Payment made for completed work. Working with Materials and QC to resolve exception related to system-generated deduction.
				3	Aug 17, 2020	yostj1	(\$750.00)	This adjustment offsets the partial payment for pending sample done on estimate 0002 and allows the override to control the material adjustment. Working with Materials and QC to resolve exception.
	PPPS - Total						\$0.00	
	Other Item Adjustment - Total						\$0.00	
0340 -	Total						\$0.00	
0350	FLASHING ARROW PANEL	Material		1	Jul 17, 2020	SYSTEM	(\$1,500.00)	
				2	Aug 3, 2020	SYSTEM	(\$1,500.00)	
				3	Aug 17,	SYSTEM	(\$1,500.00)	
					2020		(\$1,000.00)	
				3	2020 Aug 17, 2020	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user yostj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
			- Total	3	Aug 17,			Estimate Item Adjustment (0029) due to user yostj1 overridding
	Material - Total		- Total	3	Aug 17,		\$1,500.00	Estimate Item Adjustment (0029) due to user yostj1 overridding
	Material - Total FLASHING ARROW PANEL	MaterialCredit	- Total	3	Aug 17,		\$1,500.00 (\$3,000.00)	Estimate Item Adjustment (0029) due to user yostj1 overridding
		MaterialCredit	- Total		Aug 17, 2020 Aug 3,	SYSTEM	\$1,500.00 (\$3,000.00) (\$3,000.00)	Estimate Item Adjustment (0029) due to user yostj1 overridding
		MaterialCredit	- Total	2	Aug 17, 2020 Aug 3, 2020 Aug 17,	SYSTEM SYSTEM	\$1,500.00) (\$3,000.00) (\$3,000.00) \$1,500.00	Estimate Item Adjustment (0029) due to user yostj1 overridding
		MaterialCredit		2	Aug 17, 2020 Aug 3, 2020 Aug 17,	SYSTEM SYSTEM	\$1,500.00 (\$3,000.00) (\$3,000.00) \$1,500.00 \$1,500.00	Estimate Item Adjustment (0029) due to user yostj1 overridding
	FLASHING ARROW PANEL	MaterialCredit Other Item Adjustment		2 3	Aug 17, 2020 Aug 3, 2020 Aug 17,	SYSTEM SYSTEM	\$1,500.00 (\$3,000.00) (\$3,000.00) \$1,500.00 \$1,500.00 \$3,000.00	Estimate Item Adjustment (0029) due to user yostj1 overridding
	FLASHING ARROW PANEL MaterialCredit - Total	Other Item	- Total	2 3	Aug 17, 2020 Aug 3, 2020 Aug 17, 2020 Jul 17,	SYSTEM SYSTEM SYSTEM	\$1,500.00 (\$3,000.00) (\$3,000.00) \$1,500.00 \$1,500.00 \$3,000.00	Estimate Item Adjustment (0029) due to user yostj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
	FLASHING ARROW PANEL MaterialCredit - Total	Other Item	- Total	2 3 1 1 3 3	Aug 17, 2020 Aug 3, 2020 Aug 17, 2020 Jul 17, 2020 Aug 17,	SYSTEM SYSTEM SYSTEM kinga1	\$1,500.00 (\$3,000.00) (\$3,000.00) \$1,500.00 \$3,000.00 \$1,500.00	Estimate Item Adjustment (0029) due to user yostj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
	FLASHING ARROW PANEL MaterialCredit - Total FLASHING ARROW PANEL	Other Item	- Total PPPS	2 3 1 1 3 3	Aug 17, 2020 Aug 3, 2020 Aug 17, 2020 Jul 17, 2020 Aug 17,	SYSTEM SYSTEM SYSTEM kinga1	\$1,500.00 (\$3,000.00) (\$3,000.00) \$1,500.00 \$3,000.00 \$3,000.00 \$1,500.00 (\$1,500.00)	Estimate Item Adjustment (0029) due to user yostj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
0350-	FLASHING ARROW PANEL MaterialCredit - Total FLASHING ARROW PANEL Other Item Adjustment - Total	Other Item	- Total PPPS	2 3 1 1 3 3	Aug 17, 2020 Aug 3, 2020 Aug 17, 2020 Jul 17, 2020 Aug 17,	SYSTEM SYSTEM SYSTEM kinga1	\$1,500.00 (\$3,000.00) (\$3,000.00) \$1,500.00 \$3,000.00 \$3,000.00 (\$1,500.00 (\$1,500.00) (\$1,500.00 (\$1,500.00)	Estimate Item Adjustment (0029) due to user yostj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
0350 - 0370	FLASHING ARROW PANEL MaterialCredit - Total FLASHING ARROW PANEL Other Item Adjustment - Total	Other Item	- Total PPPS	2 3 1 1 3 3	Aug 17, 2020 Aug 3, 2020 Aug 17, 2020 Jul 17, 2020 Aug 17,	SYSTEM SYSTEM SYSTEM kinga1	\$1,500.00 (\$3,000.00) (\$3,000.00) \$1,500.00 \$3,000.00 \$3,000.00 \$1,500.00 (\$1,500.00) (\$1,500.00)	Estimate Item Adjustment (0029) due to user yostj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
	FLASHING ARROW PANEL MaterialCredit - Total FLASHING ARROW PANEL Other Item Adjustment - Total Total CHANGEABLE MESSAGE SIGN	Other Item Adjustment	- Total PPPS	2 3 1 3	Aug 17, 2020 Aug 3, 2020 Aug 17, 2020 Jul 17, 2020 Aug 17, 2020 Jul 17,	SYSTEM SYSTEM SYSTEM kinga1 yostj1	\$1,500.00 (\$3,000.00) \$1,500.00 \$1,500.00 \$3,000.00 \$3,000.00 \$1,500.00 (\$1,500.00) \$0.00 \$0.00	Estimate Item Adjustment (0029) due to user yostj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0370	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material		3	Aug 17, 2020	SYSTEM	\$8,650.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) due to user yostj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
			- Total				(\$17,300.00)	
	Material - Total						(\$17,300.00)	
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	MaterialCredit		2	Aug 3, 2020	SYSTEM	\$8,650.00	
	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED			3	Aug 17, 2020	SYSTEM	\$8,650.00	
			- Total				\$17,300.00	
	MaterialCredit - Total						\$17,300.00	
	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE CONTRACTOR	Other Item Adjustment	PPPS	1	Jul 17, 2020	kinga1	\$8,650.00	Payment made for completed work. Working with Materials and QC to resolve exception related to system-generated deduction.
	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED			3	Aug 17, 2020	yostj1	(\$8,650.00)	This adjustment offsets the partial payment for pending sample done on estimate 0002 and allows the override to control the material adjustment. Working with Materials and QC to resolve exception.
			PPPS - Tota				\$0.00	
	Other Item Adjustment - Total						\$0.00	
0370 -	Total						\$0.00	
0390	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN.,	Material		7	Oct 16, 2020	SYSTEM	(\$1,494.90)	
	WHITE			7	Oct 16, 2020	SYSTEM	\$1,494.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user yostj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$1,494.90)	
				8	Nov 2, 2020	SYSTEM	\$1,494.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user yostj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total		- Total				\$0.00 \$0.00	
0390 -			- Total					
0390 - 0400	Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN.	Material	- Total	7	Oct 16, 2020	SYSTEM	\$0.00	
	Total PREFORMED THERMOPLASTIC	Material	- Total	7 7		SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user yostj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
	Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN.	Material	- Total		2020 Oct 16,		\$0.00 \$0.00 (\$7,982.55)	Estimate Item Adjustment (0017) due to user yostj1 overridding
	Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN.	Material	- Total	7	2020 Oct 16, 2020 Nov 2,	SYSTEM	\$0.00 \$0.00 (\$7,982.55) \$7,982.55	Estimate Item Adjustment (0017) due to user yostj1 overridding
	Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN.	Material	- Total	7 8	2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$7,982.55) \$7,982.55 (\$7,982.55)	Estimate Item Adjustment (0017) due to user yostj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding
	Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN.	Material		7 8	2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$7,982.55) \$7,982.55 (\$7,982.55) \$7,982.55	Estimate Item Adjustment (0017) due to user yostj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding
	Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE Material - Total	Material		7 8	2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$7,982.55) \$7,982.55 (\$7,982.55) \$7,982.55 \$7,982.55 \$0.00	Estimate Item Adjustment (0017) due to user yostj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding
0400	Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE Material - Total Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	Material		7 8	2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$7,982.55) \$7,982.55 (\$7,982.55) \$7,982.55 \$0.00 \$0.00	Estimate Item Adjustment (0017) due to user yostj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding
0400 -	Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE Material - Total Total PREFORMED THERMOPLASTIC			7 8 8	2020 Oct 16, 2020 Nov 2, 2020 Nov 2, 2020 Oct 16,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$7,982.55) \$7,982.55 (\$7,982.55) \$7,982.55 \$7,982.55 \$0.00 \$0.00	Estimate Item Adjustment (0017) due to user yostj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding
0400 -	Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE Material - Total Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.			7 8 8 7 7 7	2020 Oct 16, 2020 Nov 2, 2020 Nov 2, 2020 Oct 16, 2020 Oct 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$7,982.55) \$7,982.55 (\$7,982.55) \$7,982.55 \$0.00 \$0.00 \$0.00 (\$8,334.00)	Estimate Item Adjustment (0017) due to user yostj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
0400 -	Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE Material - Total Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.			7 8 8 7 7 7	2020 Oct 16, 2020 Nov 2, 2020 Nov 2, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$7,982.55) \$7,982.55 (\$7,982.55) \$7,982.55 \$7,982.55 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0017) due to user yostj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
0400 -	Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE Material - Total Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.			7 8 8 7 7 8	2020 Oct 16, 2020 Nov 2, 2020 Nov 2, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$7,982.55) \$7,982.55 (\$7,982.55) \$7,982.55 \$0.00 \$0.00 \$0.00 \$0.00 (\$8,334.00) \$8,334.00 (\$8,334.00)	Estimate Item Adjustment (0017) due to user yostj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding Payment Estimate Exception 54 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user yostj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
0400 -	Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE Material - Total Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.		- Total	7 8 8 7 7 8	2020 Oct 16, 2020 Nov 2, 2020 Nov 2, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$7,982.55) \$7,982.55 (\$7,982.55) \$7,982.55 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$8,334.00 (\$8,334.00) \$8,334.00	Estimate Item Adjustment (0017) due to user yostj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding Payment Estimate Exception 54 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user yostj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
0400 -	Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE Material - Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE Material - Total		- Total	7 8 8 7 7 8	2020 Oct 16, 2020 Nov 2, 2020 Nov 2, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$7,982.55) \$7,982.55 (\$7,982.55 \$7,982.55 \$0.00 \$0.00 \$0.00 (\$8,334.00) \$8,334.00 (\$8,334.00) \$8,334.00	Estimate Item Adjustment (0017) due to user yostj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding Payment Estimate Exception 54 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user yostj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
0400 - 0400 - 0410	Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE Material - Total PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE Material - Total		- Total	7 8 8 7 7 8	2020 Oct 16, 2020 Nov 2, 2020 Nov 2, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$7,982.55) \$7,982.55 (\$7,982.55) \$7,982.55 \$0.00 \$0.00 \$0.00 (\$8,334.00) \$8,334.00 (\$8,334.00) \$8,334.00 \$8,334.00 \$8,334.00	Estimate Item Adjustment (0017) due to user yostj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding Payment Estimate Exception 54 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user yostj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0420	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			2020			Estimate Item Adjustment (0019) due to user yostj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0420 -	Total						\$0.00	
0430	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	Material		7	Oct 16, 2020	SYSTEM	(\$400.00)	
	00			7	Oct 16, 2020	SYSTEM	\$400.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user yostj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0430 -	Total						\$0.00	
0440	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	Material		7	Oct 16, 2020	SYSTEM	(\$10,980.00)	
	WHITE MIDDLOCK			7	Oct 16, 2020	SYSTEM	\$10,980.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0440 -	Total						\$0.00	
0460	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT	Material		5	Sep 16, 2020	SYSTEM	(\$1,960.10)	
	MARKING PAINT, TYPE L BEADS			5	Sep 16, 2020	SYSTEM	\$1,960.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user yostj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				6	Oct 1, 2020	SYSTEM	(\$1,960.10)	
					6	Oct 1, 2020	SYSTEM	\$1,960.10
				7	Oct 16, 2020	SYSTEM	(\$3,508.80)	
				7	Oct 16, 2020	SYSTEM	\$3,508.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user yostj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$6,385.20)	
				8	Nov 2, 2020	SYSTEM	\$6,385.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user yostj1 overridding Payment Estimate Exception 59 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$25,956.45)	
				9	Nov 16, 2020	SYSTEM	\$25,956.45	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user yostj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0460 -	Total						\$0.00	
0470	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L	Material		7	Oct 16, 2020	SYSTEM	(\$1,351.80)	
	BEADS			7	Oct 16, 2020	SYSTEM	\$1,351.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user yostj1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$1,351.80)	
				8	Nov 2, 2020	SYSTEM	\$1,351.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user yostj1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$23,195.16)	
				9	Nov 16, 2020	SYSTEM	\$23,195.16	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user yostj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0470		Material	- Total				\$0.00	
	Material - Total						\$0.00	
0470 -	Total						\$0.00	
0480	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT	Material		9	Nov 16, 2020	SYSTEM	(\$2,440.80)	
	MARKING PAINT, TYPE L BEADS			9	Nov 16, 2020	SYSTEM	\$2,440.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user yostj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0480 -	Total						\$0.00	
0490	4 IN. WHITE STANDARD WATERBORNE PAVEMENT	Material		7	Oct 16, 2020	SYSTEM	(\$2,531.75)	
	MARKING PAINT, TYPE P BEADS			7	Oct 16, 2020	SYSTEM	\$2,531.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user yostj1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$2,607.15)	
				8	Nov 2, 2020	SYSTEM	\$2,607.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user yostj1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$4,201.21)	
				9	Nov 16, 2020	SYSTEM	\$4,201.21	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user yostj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0490 -	Total						\$0.00	
0495	4 IN. YELLOW STANDARD Material WATERBORNE PAVEMENT	Material		7	Oct 16, 2020	SYSTEM	(\$1,973.40)	
	MARKING PAINT, TYPE P BEADS			7	Oct 16, 2020	SYSTEM	\$1,973.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user yostj1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$4,585.10)	
				8	Nov 2, 2020	SYSTEM	\$4,585.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user yostj1 overridding Payment Estimate Exception 69 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$4,683.38)	
				9	Nov 16, 2020	SYSTEM	\$4,683.38	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user yostj1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0495 -	Total						\$0.00	
0500	FLOWABLE BACKFILL	Material		7	Oct 16, 2020	SYSTEM	(\$1,005.00)	
				7	Oct 16, 2020	SYSTEM	\$1,005.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) due to user yostj1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0500 -							\$0.00	
0570	CURB INLET CHECK	Material		7	Oct 16, 2020	SYSTEM	(\$154.00)	
				7	Oct 16, 2020	SYSTEM	\$154.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user yostj1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0.555								
0570 -	Total						\$0.00	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0590	TYPE 3A EROSION CONTROL BLANKET	Material		5	Sep 16, 2020	SYSTEM	(\$1,870.00)	
				5	Sep 16, 2020	SYSTEM	\$1,870.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user yostj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				6	Oct 1, 2020	SYSTEM	(\$3,740.00)	
				6	Oct 1, 2020	SYSTEM	\$3,740.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0050) due to user yostj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0590 -	Total						\$0.00	
0600	MGS GUARDRAIL	Construction Stockpile		4	Sep 2, 2020	SYSTEM	\$122,349.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				5	Sep 16, 2020	SYSTEM	(\$19,359.10)	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Oct 1, 2020	SYSTEM	(\$47,410.03)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Oct 16, 2020	SYSTEM	(\$34,240.59)	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Nov 2, 2020	SYSTEM	(\$15,281.83)	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Dec 2, 2020	SYSTEM	(\$6,057.95)	Payment Estimate Item Adjustment generated Stockpile Transaction
		- Total				\$0.00		
	Construction Stockpile - Total			_			\$0.00	
	MGS GUARDRAIL	Material		5	Sep 16, 2020	SYSTEM	(\$33,993.75)	
				5	Sep 16, 2020	SYSTEM	\$33,993.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				6	Oct 1, 2020	SYSTEM	(\$117,243.75)	
				6	Oct 1, 2020	SYSTEM	\$117,243.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0051) due to user yostj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0600 -	Total						\$0.00	
0610	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Construction Stockpile		4	Sep 2, 2020	SYSTEM	\$106,595.75	Payment Estimate Item Adjustment generated Stockpile Transaction
				5	Sep 16, 2020	SYSTEM	(\$5,259.86)	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Oct 1, 2020	SYSTEM	(\$21,039.45)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Oct 16, 2020	SYSTEM	(\$34,498.51)	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Nov 2, 2020	SYSTEM	(\$7,122.47)	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Dec 2, 2020	SYSTEM	(\$38,675.46)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material		5	Sep 16, 2020	SYSTEM	(\$9,137.50)	
				5	Sep 16, 2020	SYSTEM	\$9,137.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				6	Oct 1, 2020	SYSTEM	(\$45,687.50)	
				6	Oct 1, 2020	SYSTEM	\$45,687.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0052) due to user yostj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0610	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material		7	Oct 16, 2020	SYSTEM	(\$105,618.75)	
				7	Oct 16, 2020	SYSTEM	\$105,618.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user yostj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$117,992.00)	
				8	Nov 2, 2020	SYSTEM	\$117,992.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user yostj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0610 -	Total						\$0.00	
0620	MGS BRIDGE APPROACH TRANSITION SECTION	Construction Stockpile		4	Sep 2, 2020	SYSTEM	\$49,952.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	(EXTENDED CURB)			5	Sep 16, 2020	SYSTEM	(\$10,927.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Oct 1, 2020	SYSTEM	(\$18,732.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Oct 16, 2020	SYSTEM	(\$7,805.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Nov 2, 2020	SYSTEM	(\$6,244.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Dec 2, 2020	SYSTEM	(\$6,244.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
)620 -	Total						\$0.00	
0630		Construction Stockpile		4	Sep 2, 2020	SYSTEM	\$8,000.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				5	Sep 16, 2020	SYSTEM	(\$500.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Oct 1, 2020	SYSTEM	(\$1,000.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Oct 16, 2020	SYSTEM	(\$1,000.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Nov 2, 2020	SYSTEM	(\$3,500.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Dec 2, 2020	SYSTEM	(\$2,000.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0630 -							\$0.00	
0640		Construction Stockpile		4	Sep 2, 2020	SYSTEM	\$59,163.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				5	Sep 16, 2020	SYSTEM	(\$9,102.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Oct 1, 2020	SYSTEM	(\$21,238.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Oct 16, 2020	SYSTEM	(\$22,755.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Nov 2, 2020	SYSTEM	(\$6,068.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
0640	Construction Stockpile - Total						\$0.00	
0640 - 0650	CONDUIT, 3 IN. RIGID, PUSHED	Material		9	Nov 16,	SYSTEM	\$0.00 (\$4,306.50)	
				9	2020 Nov 16, 2020	SYSTEM	\$4,306.50	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0016) due to user yostj1 overridding Payment Estimate Exception 55 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0650	CONDUIT, 3 IN. RIGID, PUSHED	Material		10	Dec 2, 2020	SYSTEM	\$4,306.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0048) due to user yostj1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0650 -	Total						\$0.00	
0660	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	Material		9	Nov 16, 2020	SYSTEM	(\$1,144.00)	
				9	Nov 16, 2020	SYSTEM	\$1,144.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user yostj1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$1,144.00)	
				10	Dec 2, 2020	SYSTEM	\$1,144.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0049) due to user yostj1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0660 -	Total						\$0.00	
0720	CLASS A EXCAVATION	Price		7	Oct 16, 2020	SYSTEM	(\$315.95)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$315.95)	
	Price - Total						(\$315.95)	
0720 -							(\$315.95)	
0730		Material		7	Oct 16, 2020	SYSTEM	(\$652.50)	
				7	Oct 16, 2020	SYSTEM	\$652.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user yostj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$654.00)	
				8	Nov 2, 2020	SYSTEM	\$654.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) due to user yostj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$654.00)	
				9	Nov 16, 2020	SYSTEM	\$654.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user yostj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$654.00)	
				10	Dec 2, 2020	SYSTEM	\$654.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0051) due to user yostj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0730 -	Total						\$0.00	
0740	COMPACTING IN CUT Material	Material		7	Oct 16, 2020	SYSTEM	(\$12,495.00)	
				7	Oct 16, 2020	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user yostj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$12,495.00)	
				8	Nov 2, 2020	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user yostj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$12,495.00)	
				9	Nov 16, 2020	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user yostj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$12,495.00)	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0740	COMPACTING IN CUT	Material		10	Dec 2, 2020	SYSTEM	\$12,495.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0052) due to user yostj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0740 -	Total						\$0.00	
0790	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		7	Oct 16, 2020	SYSTEM	(\$26,660.00)	
				7	Oct 16, 2020	SYSTEM	\$26,660.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user yostj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$15,920.00)	
				8	Nov 2, 2020	SYSTEM	\$15,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0061) due to user yostj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$15,920.00)	
				9	Nov 16, 2020	SYSTEM	\$15,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user yostj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$15,920.00)	
				10	Dec 2, 2020	SYSTEM	\$15,920.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0053) due to user yostj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		7	Oct 16, 2020	SYSTEM	(\$223.81)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				8	Nov 2, 2020	SYSTEM	\$90.16	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$133.65)	
	Price - Total						(\$133.65)	
0790 -	Total						(\$133.65)	
0800	MISC. PERMANENT AGGREGATE EDGE TREATMENT	Material		7	Oct 16, 2020	SYSTEM	(\$31,219.86)	
				7	Oct 16, 2020	SYSTEM	\$31,219.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user yostj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$31,219.86)	
			8	Nov 2,	0) (0 T T 1 1	\$31,219.86	This adjustment offsets the original system-generated Overrun Payment	
					2020	SYSTEM		Estimate Item Adjustment (0035) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				9		SYSTEM	(\$31,219.86)	Estimate Item Adjustment (0035) due to user yostj1 overridding
					2020 Nov 16,			Estimate Item Adjustment (0035) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				9	2020 Nov 16, 2020 Nov 16,	SYSTEM	(\$31,219.86)	Estimate Item Adjustment (0035) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding
				9	2020 Nov 16, 2020 Nov 16, 2020 Dec 2,	SYSTEM SYSTEM	(\$31,219.86) \$31,219.86 (\$31,219.86) \$31,219.86	Estimate Item Adjustment (0035) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total	9 9 10	2020 Nov 16, 2020 Nov 16, 2020 Dec 2, 2020 Dec 2,	SYSTEM SYSTEM SYSTEM	(\$31,219.86) \$31,219.86 (\$31,219.86)	Estimate Item Adjustment (0035) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0054) due to user yostj1 overridding
	Material - Total		- Total	9 9 10	2020 Nov 16, 2020 Nov 16, 2020 Dec 2, 2020 Dec 2,	SYSTEM SYSTEM SYSTEM	(\$31,219.86) \$31,219.86 (\$31,219.86) \$31,219.86	Estimate Item Adjustment (0035) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0054) due to user yostj1 overridding
0800 -			- Total	9 9 10	2020 Nov 16, 2020 Nov 16, 2020 Dec 2, 2020 Dec 2,	SYSTEM SYSTEM SYSTEM	(\$31,219.86) \$31,219.86 (\$31,219.86) \$31,219.86 \$0.00	Estimate Item Adjustment (0035) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0054) due to user yostj1 overridding
<mark>0800 -</mark> 0810		Material	- Total	9 9 10	2020 Nov 16, 2020 Nov 16, 2020 Dec 2, 2020 Dec 2,	SYSTEM SYSTEM SYSTEM	(\$31,219.86) \$31,219.86 (\$31,219.86) \$31,219.86 \$0.00 \$0.00	Estimate Item Adjustment (0035) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0054) due to user yostj1 overridding
	Total	Material	- Total	9 9 10 10	2020 Nov 16, 2020 Nov 16, 2020 Dec 2, 2020 Dec 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$31,219.86) \$31,219.86 (\$31,219.86) \$31,219.86 \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0035) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0054) due to user yostj1 overridding



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0810	TYPE A3 SHOULDER	Material		9	Nov 16, 2020	SYSTEM	\$10,045.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0022) due to user yostj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$10,045.00)	
				10	Dec 2, 2020	SYSTEM	\$10,045.00	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0055) due to user yostj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total		1		\$0.00	
	Material - Total						\$0.00	
810 -	Total						\$0.00	
820	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	Other Item Adjustment	ACAD	6	Oct 1, 2020	yostj1	(\$9,554.41)	Asphalt cement price adjustment for dates 9/16 through 9/29.
				7	Oct 16, 2020	yostj1	(\$4,140.85)	Asphalt cement price adjustment for the dates 10/01 to 10/15.
			ACAD - Tota	al			(\$13,695.26)	
	Other Item Adjustment - Total						(\$13,695.26)	
	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	Price		6	Oct 1, 2020	SYSTEM	(\$7,570.42)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				7	Oct 16, 2020	SYSTEM	(\$4,071.84)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$11,642.26)	
0.00	Price - Total						(\$11,642.26)	
	Total						(\$25,337.52)	
840	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP095C MIX)	Material		6	Oct 1, 2020	SYSTEM	(\$524,539.35)	This adjustment facts the arising system generated Output Deve
				6	Oct 1, 2020	SYSTEM	\$524,539.35	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0055) due to user yostj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				7	Oct 16, 2020	SYSTEM	(\$912,933.91)	
				7	Oct 16, 2020	SYSTEM	\$912,933.91	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0053) due to user yostj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$912,933.91)	
				8	Nov 2, 2020	SYSTEM	\$912,933.91	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0038) due to user yostj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$912,933.91)	
				9	Nov 16, 2020	SYSTEM	\$912,933.91	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0024) due to user yostj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$912,933.91)	
				10	Dec 2, 2020	SYSTEM	\$912,933.91	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0037) due to user yostj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total					\$0.00		
		Other Item Adjustment	ACAD	4	Sep 2, 2020	yostj1	(\$9,357.41)	Asphalt cement price adjustment for the dates 8/16/20 through 8/31/20 Adjustment for the date 9/1 is not included and will be corrected once quantities are agreed upon.
				5	Sep 16, 2020	yostj1	(\$7,254.25)	Asphalt cement price adjustment for dates 9/1 through 9/15.
				6	Oct 1, 2020	yostj1	(\$3,873.95)	Asphalt cement price adjustment for dates 9/16 through 9/29. The date of 9/15 was left off the previous estimate, but was included in this adjustment.
				7	Oct 16, 2020	yostj1	(\$12,881.86)	Asphalt cement price adjustment for the dates 10/01 to 10/15.
			ACAD - Tota	al			(\$33,367.47)	
	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP095C MIX)		OTHR	7	Oct 16, 2020	yostj1	(\$109,586.17)	This adjustment offsets the autogenerated adjustment made on an iten that has insufficient materials and an overrun on quantity. This adjustment removes payment for the overrun amount.



ine	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
840		Other Item Adjustment	OTHR - Total				(\$109,586.17)	
	Other Item Adjustment - Total						(\$142,953.64)	
		Overrun	Overrun	7	Oct 16, 2020	SYSTEM	(\$105,609.06)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
	` MIX)			7	Oct 16, 2020	SYSTEM	\$34,716.40	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0050) overridding Payment Estimate Exception 59 on the current Payment Estimate.
				7	Oct 16, 2020	SYSTEM	\$40,278.81	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0051) overridding Payment Estimate Exception 59 on the current Payment Estimate.
				7	Oct 16, 2020	SYSTEM	\$30,613.85	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0052) overridding Payment Estimate Exception 59 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$105,658.00)	Averaged Price Adjustment from this item on all previous payment estimates of '-2.32924' is applied (if non-zero).
				8	Nov 2, 2020	SYSTEM	\$105,658.00	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0037) overridding Payment Estimate Exception 79 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$105,658.00)	Averaged Price Adjustment from this item on all previous payment estimates of '-2.32924' is applied (if non-zero).
				9	Nov 16, 2020	SYSTEM	\$105,658.00	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0023) overridding Payment Estimate Exception 66 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$105,658.00)	Averaged Price Adjustment from this item on all previous payment estimates of '-2.32924' is applied (if non-zero).
				10	Dec 2, 2020	SYSTEM	\$105,658.00	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0036) overridding Payment Estimate Exception 65 on the current Payment Estimate.
		Overrun - Total				\$0.00		
	Overrun - Total						\$0.00	
	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP095C MIX)	Price		4	Sep 2, 2020	SYSTEM	(\$9,156.47)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				5	Sep 16, 2020	SYSTEM	(\$6,794.25)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				6	Oct 1, 2020	SYSTEM	(\$2,397.77)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				7	Oct 16, 2020	SYSTEM	(\$14,376.01)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		- Total	- Total			(\$32,724.50)		
	Price - Total						(\$32,724.50)	
840 -	Total						(\$175,678.14)	
850	TACK COAT	Material	terial	3	Aug 17, 2020	SYSTEM	(\$302.50)	
				3	Aug 17, 2020	SYSTEM	\$302.50	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0032) due to user yostj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				4	Sep 2, 2020	SYSTEM	(\$10,760.00)	
				4	Sep 2, 2020	SYSTEM	\$10,760.00	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0020) due to user yostj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				5	Sep 16, 2020	SYSTEM	(\$19,947.50)	
				5	Sep 16, 2020	SYSTEM	\$19,947.50	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0027) due to user yostj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				6	Oct 1, 2020	SYSTEM	(\$28,892.50)	
				6	Oct 1, 2020	SYSTEM	\$28,892.50	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0056) due to user yostj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	



0800 Overrun Total Overrun Total (1913) (1913) (1913) 0 Overrun Total (1913) <	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
Material Total (19.3.37.40) 00170 CONCRETE PURCHENT (NUMPER) NON-HEIRENT (CONCRETE ADDREST) National ADDREST (NUMPER) NON-HEIRENT (CONCRETE ADDREST) National ADDREST (NUMPER) Purce ADDR	0850		Overrun		otal			(\$10,352.50)		
0000 Total (1993) CONCRETE INVENENT (0 IV		Overrun - Total						(\$10,352.50)		
BYP CONCRETE PARLEMENT (IN) NON-REINF) Material Material Partial (In) Non-RE YSTEM (In) (In) Addresses (In)	0850 -									
	0870	CONCRETE PAVEMENT (8 IN.	Material		9		SYSTEM			
Image: stand					9		SYSTEM	\$2,407.20		
Image: Second					10		SYSTEM	(\$2,407.20)		
Material - Total OUNCRETE FAVEMENT (SIN) NON-REINF) Price Non-REINF) Price - Total SYSTEM (6.5.11) Reference Item Price Adjustment Index Adjustment Type applied is PFL Price - Total - Total (6.5.11) Reference Item Price Adjustment Index Adjustment Operating Price Index In					10		SYSTEM	\$2,407.20		
CONCRETE PAYENT (2 II.) NON-REINF NON-REINF 2020 Price - Total 9 Nov. (6. 2020 SYSTEM (65.11) Reference hern Price Adjustment Index Adjustment Type applied is FUE Price - Total - Total (55.11) (55.11) 0000 CONCRETE CURB RAMP Material 8 Nov. 2, 2020 SYSTEM (64.458.00) 0000 CONCRETE CURB RAMP Material 8 Nov. 2, 2020 SYSTEM (54.458.00) 0000 CONCRETE CURB RAMP Material 8 Nov. 2, 2020 SYSTEM (54.458.00) 0 Nov. 16, 2020 SYSTEM (54.458.00) This adjustment officits the original system-priorited Overun Payment Estimate Exception 16 on the current Payment Estimate Exception 16 on the curent Payment Estimate Exception 16 on the current Payment				- Total				\$0.00		
NON-REINF Image: Concentration of the second s		Material - Total						\$0.00		
Price - Total (8.5.11) 0870 - Total (6.5.13) 0880 - CONCRETE CURB RAMP Material - Counce -			Price		9		SYSTEM	(\$5.11)		
0970 - Total (45.11) 0880 CONCRETE CURB RAMP Material 8 Nov 2, 2020, 9 SYSTEM (64,458,60) This adjustment offsets the original system-generated Overrun Payme Estimate item Adjustment (0059) due to user yost] + overriding Paymant Estimate Exception 20 on the current Paymant Estimate. 9 Nov 16, 2020, 9 SYSTEM (64,458,60) This adjustment offsets the original system-generated Overrun Payme Estimate Exception 20 on the current Paymant Estimate. 9 Nov 16, 2020, 9 SYSTEM (64,458,60) This adjustment offsets the original system-generated Overrun Payme Estimate Exception 16 on the current Payment Estimate Estimate Exception 16 on the current Payment Estimate Payment Estim				- Total				(\$5.11)		
CONCRETE CURB RAMP Material 0 Nov.2. 2020 SYSTEM (\$4.458.00) 0 Nov.2. 2020 SYSTEM \$4.458.00 This adjustment offsets the original system-generated Overtun Paym Payment Estimate Exception 20 on the current Payment Estimate Estimate Item Adjustment offsets the original system-generated Overtun Paym Estimate Item Adjustment offsets the original system-generated Overtun Paym Estimate Item Adjustment offsets the original system-generated Overtun Payment Estimate Item Adjustment offsets the original system-generated Overtun Payment Estimate Item Adjustment (0056) due to user yost] voerdiding Payment Estimate Exception 16 on the current Payment Estimate Estimate Item Adjustment (0056) due to user yost] voerdiding Payment Estimate Item Adjustment (0056) due to user yost] voerdiding Payment Estimate Item Adjustment (0056) due to user yost] voerdiding Payment Estimate Item Adjustment (0056) due to user yost] voerdiding Payment Estimate Item Adjustment (0056) due to user yost] voerdiding Payment Estimate Item Adjustment (0056) due to user yost] voerdiding Payment Estimate Item Adjustment (0056) due to user yost] voerdiding Payment Estimate Exception 16 on the current Payment Estimate Estimate Item Adjustment (0056) due to user yost] voerdiding Payment Estimate Exception 18 on the current Payment Estimate Estimate Item Adjustment (0056) due to user yost] voerdiding Payment Estimate Exception 18 on the current Payment Estimate Estimate Item Adjustment (0056) due to user yost] voerdiding Payment Estimate Exception 18 on the current Payment Estimate Estimate Item Adjustment (0057) due to user yost] voerdiding Payment Estimate Exception 18 on the current Payment Estimate Estimate Item Adjustment (0057) due to user yost] voerdiding Payment Estimate Exception 18 on the current Payment Estimate Estimate Item Adjustment (00		Price - Total						(\$5.11)		
Image: stand	0870 -	Total						(\$5.11)		
Image: space	0880	CONCRETE CURB RAMP	Material		8		SYSTEM	(\$4,458.00)		
Image: state in the state in thestate in the state in the state in the state in the st					8		SYSTEM	\$4,458.00		
Image: Second					9		SYSTEM	(\$4,458.00)		
Image: state in the s					9		SYSTEM	\$4,458.00		
Image: second					10		SYSTEM	(\$4,458.00)		
Material - Total S0.00 0880 - Total 90 Nov 16, 2020 SYSTEM (\$811.20) 0890 TRUNCATED DOMES Material 9 Nov 16, 2020 SYSTEM \$811.20) 9 Nov 16, 2020 SYSTEM \$811.20) This adjustment offsets the original system-generated Overrun Paym Estimate Item Adjustment (0026) due to user yosij1 overridding Payment Estimate Exception 18 on the current Payment Estimate. 10 Dec 2, 2020 SYSTEM (\$811.20) Interview offsets the original system-generated Overrun Payme Estimate Item Adjustment (0026) due to user yosij1 overridding Payment Estimate Exception 18 on the current Payment Estimate. Interview offsets the original system-generated Overrun Payme Estimate Item Adjustment (0057) due to user yosij1 overridding Payment Estimate Exception 18 on the current Payment Estimate. Interview offsets the original system-generated Overrun Payme Estimate Item Adjustment (0057) due to user yosij1 overridding Payment Estimate Exception 18 on the current Payment Estimate. Interview offsets the original system-generated Overrun Payme Estimate Item Adjustment (0050) due to user yosij1 overridding Payment Estimate Exception 17 on the current Payment Estimate. Interview offsets the original system-generated Overrun Payme Estimate Item Adjustment (0050) due to user yosij1 overridding Payment Estimate Item Adjustment (0050) due to user yosij1 overridding					10		SYSTEM	\$4,458.00		
0880 - Total \$0.00 0889 0 TRUNCATED DOMES Material 9 Nov 16, 2020 SYSTEM (\$811.20) 9 Nov 16, 2020 SYSTEM \$811.20 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) due to user yosij1 overridding Payment Estimate Exception 18 on the current Payment Estimate. 10 Dec 2, 2020 SYSTEM \$811.20 10 Dec 2, 2020 SYSTEM \$811.20 Total • Total • Total • Socoo • SYSTEM \$811.20 • Material - Total • Oct 16, 2020 • SYSTEM \$811.20 • Material - Total • Oct 16, 2020 SYSTEM \$811.20 • Oct 16, 2020 SYSTEM \$0.00 • Oct 16, 2020 SYSTEM \$0.00 • Oct 16, 2020 SYSTEM \$45,938.82 • Oct 16, 2020 SYSTEM \$45,938.82 • Oct 16, 2020 SYSTEM \$45,938.82 • Oct				- Total				\$0.00		
0890 TRUNCATED DOMES Material 9 Nov 16, 2020 SYSTEM (\$811.20) 9 Nov 16, 2020 SYSTEM \$811.20 This adjustment offsets the original system-generated Overrun Payment Estimate 10 Dec 2, 2020 SYSTEM (\$811.20) 100 Dec 2, 2020 SYSTEM (\$811.20) 100 Dec 2, 2020 SYSTEM (\$811.20) 100 Dec 2, 2020 SYSTEM S811.20 This adjustment offsets the original system-generated Overrun Payment Estimate • Total • Total • 00 <td colspa="</td"><td></td><td>Material - Total</td><td></td><td></td><td></td><td></td><td></td><td>\$0.00</td><td></td></td>	<td></td> <td>Material - Total</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>\$0.00</td> <td></td>		Material - Total						\$0.00	
4 2020 <t< td=""><td>0880 -</td><td>Total</td><td></td><td></td><td></td><td></td><td></td><td>\$0.00</td><td></td></t<>	0880 -	Total						\$0.00		
Image: state of the second	0890	TRUNCATED DOMES	Material		9		SYSTEM	(\$811.20)		
A 2020 Internal Interna					9		SYSTEM	\$811.20		
Image: Constraint of the constraint						2020		, ,		
Material - Total \$0.00 0890 - Total \$0.00 0900 CONCRETE SIDEWALK, 4 IN. Material 7 Oct 16, 2020 SYSTEM \$45,938.82) 7 Oct 16, 2020 SYSTEM \$45,938.82) 900 Nov 2, 2020 SYSTEM \$45,938.82 10 Substrate Item Adjustment (0059) due to user yostj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. 8 Nov 2, 2020 SYSTEM \$48,491.25 8 Nov 2, 2020 SYSTEM \$48,491.25 9 Nov 16, SYSTEM \$45,780.08)					10		SYSTEM	\$811.20	Estimate Item Adjustment (0057) due to user yostj1 overridding	
0890 - Total \$0.00 0900 - Total \$0.00 0900 - CONCRETE SIDEWALK, 4 IN. Material 7 Oct 16, 2020 SYSTEM \$\$45,938.82 7 Oct 16, 2020 SYSTEM \$\$45,938.82 8 Nov 2, 2020 SYSTEM \$\$45,938.82 8 Nov 2, 2020 SYSTEM \$\$48,491.25) 8 Nov 2, 2020 SYSTEM \$\$48,491.25) 8 Nov 2, 2020 SYSTEM \$\$48,491.25) 9 Nov 16, SYSTEM \$\$48,491.25] This adjustment (0040) due to user yostj1 overridding Payment Estimate Item Adjustment (0040) due to user yostj1 overridding Payment Estimate Item Adjustment (0040) due to user yostj1 overridding Payment Estimate Item Adjustment (0040) due to user yostj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.				- Total				\$0.00		
0900 CONCRETE SIDEWALK, 4 IN. Material 7 Oct 16, 2020 SYSTEM (\$45,938.82) This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0059) due to user yostj1 overridding Payment Estimate Exception 17 on the current Payment Estimate 0900 Nov 2, 2020 SYSTEM \$48,491.25) 0901 Nov 2, 2020 SYSTEM \$48,491.25) 0902 Nov 2, 2020 SYSTEM \$48,491.25) 0903 Nov 2, 2020 SYSTEM \$48,491.25) 0904 Nov 2, 2020 SYSTEM \$48,491.25) 0905 Nov 2, 2020 SYSTEM \$48,491.25) 0906 Nov 16, SYSTEM \$48,491.25) This adjustment (0040) due to user yostj1 overridding Payment Estimate Item Adjustment (0040) due to user yostj1 overridding Payment Estimate Exception 30 on the current Payment Estimate. 907 Nov 16, SYSTEM \$45,780.08)		Material - Total						\$0.00		
2020 2020 Ct 10, 2020 SYSTEM \$45,938.82 This adjustment offsets the original system-generated Overrun Paymer 7 Oct 16, 2020 SYSTEM \$45,938.82 This adjustment (0059) due to user yost]1 overridding 8 Nov 2, 2020 SYSTEM (\$48,491.25) 8 Nov 2, SYSTEM \$48,491.25) 9 Nov 16, SYSTEM (\$45,780.08)	0890 -	Total						\$0.00		
2020 2020 Estimate Item Adjustment (0059) due to user yostj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. 8 Nov 2, 2020 SYSTEM (\$48,491.25) 8 Nov 2, 2020 SYSTEM Initial adjustment offsets the original system-generated Overrun Payment Estimate. 8 Nov 2, 2020 SYSTEM \$48,491.25) This adjustment (0040) due to user yostj1 overridding Payment Estimate Item Adjustment (0040) due to user yostj1 overridding Payment Estimate Exception 30 on the current Payment Estimate. 9 Nov 16, SYSTEM (\$45,780.08)	0900	CONCRETE SIDEWALK, 4 IN.	Material		7		SYSTEM	(\$45,938.82)		
2020 2020 Constraints 8 Nov 2, 2020 SYSTEM \$48,491.25 This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0040) due to user yostj1 overridding Payment Estimate Exception 30 on the current Payment Estimate. 9 Nov 16, SYSTEM (\$45,780.08)					7		SYSTEM	\$45,938.82		
2020 Estimate Item Adjustment (0040) due to user yostj1 overridding Payment Estimate Exception 30 on the current Payment Estimate. 9 Nov 16, SYSTEM (\$45,780.08)					8		SYSTEM	(\$48,491.25)		
					8		SYSTEM	\$48,491.25		
					9		SYSTEM	(\$45,780.08)		



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0900	CONCRETE SIDEWALK, 4 IN.	Material	51	9	Nov 16, 2020	SYSTEM	\$45,780.08	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0050) due to user yostj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$45,780.08)	
				10	Dec 2, 2020	SYSTEM	\$45,780.08	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0058) due to user yostj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
			- Total		1		\$0.00	
	Material - Total						\$0.00	
0900 -	Total						\$0.00	
0910	MISC. KCMO CURB & GUTTER TYPE CG-1	Material		8	Nov 2, 2020	SYSTEM	(\$3,540.90)	
				8	Nov 2, 2020	SYSTEM	\$3,540.90	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0041) due to user yostj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$9,984.70)	
				9	Nov 16, 2020	SYSTEM	\$9,984.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) due to user yostj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$9,984.70)	
				10	Dec 2, 2020	SYSTEM	\$9,984.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0059) due to user yostj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0910 -	Total						\$0.00	
0920	MISC. KCMO CURB & GUTTER TYPE CG-2	Material		9	Nov 16, 2020	SYSTEM	(\$3,085.60)	
				9	Nov 16, 2020	SYSTEM	\$3,085.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user yostj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$3,085.60)	
				10	Dec 2, 2020	SYSTEM	\$3,085.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0060) due to user yostj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0920 -	Total						\$0.00	
0940	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT	Material		2	Aug 3, 2020	SYSTEM	(\$6,889.27)	
	REPAIR			3	Aug 17, 2020	SYSTEM	(\$161,931.12)	
				3	Aug 17, 2020	SYSTEM	\$161,931.12	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user yostj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				4	Sep 2, 2020	SYSTEM	(\$161,931.12)	
					Sep 2,	SYSTEM	\$161,931.12	This adjustment offsets the original system-generated Overrun Payment
				4	2020			Estimate Item Adjustment (0021) due to user yostj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				4		SYSTEM	(\$161,931.12)	
					2020 Sep 16,	SYSTEM	(\$161,931.12) \$161,931.12	
				5	2020 Sep 16, 2020 Sep 16,		,	Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user yostj1 overridding
				5	2020 Sep 16, 2020 Sep 16, 2020 Oct 1,	SYSTEM	\$161,931.12	Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) due to user yostj1 overridding



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0940	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT	Material		7	Oct 16, 2020	SYSTEM	\$182,901.68	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0060) due to user yostj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
	REPAIR			8	Nov 2, 2020	SYSTEM	(\$182,901.68)	
				8	Nov 2, 2020	SYSTEM	\$182,901.68	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0042) due to user yostj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$182,901.68)	
				9	Nov 16, 2020	SYSTEM	\$182,901.68	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user yostj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$182,901.68)	
				10	Dec 2, 2020	SYSTEM	\$182,901.68	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0061) due to user yostj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
			- Total				(\$6,889.27)	
	Material - Total						(\$6,889.27)	
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	MaterialCredit		3	Aug 17, 2020	SYSTEM	\$6,889.27	
			- Total				\$6,889.27	
	MaterialCredit - Total						\$6,889.27	
	FURNISHING AND PLACING CONCRETE MATERIAL FOR	Other Item Adjustment	PPPS	2	Aug 3, 2020	kinga1	\$6,889.27	Payment made for completed work. Working with Materials and QC to resolve exception related to system-generated deduction.
	FULL DEPTH PAVEMENT REPAIR			3	Aug 17, 2020	yostj1	(\$6,889.27)	This adjustment offsets the partial payment for pending sample done on estimate 0002 and allows the override to control the material adjustment. Working with Materials and QC to resolve exception.
			PPPS - Tota	I			\$0.00	
Q	Other Item Adjustment - Total						\$0.00	
0940 - T	Total						\$0.00	
0970	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL	Overrun	Overrun	3	Aug 17, 2020	SYSTEM	(\$3,560.00)	
	SAW CUTS)			6	Oct 1, 2020	SYSTEM	\$3,560.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',5.00000 - 5.00000, 'is applied (if non-zero).
			Overrun - To	otal			\$0.00	
4	Overrun - Total						\$0.00	
0970 - T	lotal						\$0.00	
0980	FURNISHING AND	Material		3	Aug 17, 2020	SYSTEM	(\$1,175.20)	
	INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR			3	Aug 17, 2020	SYSTEM	\$1,175.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) due to user yostj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				4	Sep 2, 2020	SYSTEM	(\$1,175.20)	
				4	Sep 2, 2020	SYSTEM	\$1,175.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) due to user yostj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				5	Sep 16, 2020	SYSTEM	(\$1,175.20)	
				5	Sep 16, 2020	SYSTEM	\$1,175.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) due to user yostj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				6	Oct 1, 2020	SYSTEM	(\$1,851.20)	
				6	Oct 1, 2020	SYSTEM	\$1,851.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0058) due to user yostj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				7	Oct 16, 2020	SYSTEM	(\$1,851.20)	
				7	Oct 16, 2020	SYSTEM	\$1,851.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0061) due to user yostj1 overridding
Revisior	1 4/1/2020				2020 Oct 16,			This adjustment offsets the original system-generated Overr



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0980	DOWEL BAR (DRILLING, FURNISHING AND	Material		8	Nov 2,	SYSTEM	(\$1,851.20)	Payment Estimate Exception 25 on the current Payment Estimate.
	INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR				2020	OTOTEN	(\$1,001.20)	
				8	Nov 2, 2020	SYSTEM	\$1,851.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) due to user yostj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$1,851.20)	
				9	Nov 16, 2020	SYSTEM	\$1,851.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user yostj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$1,851.20)	
				10	Dec 2, 2020	SYSTEM	\$1,851.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0062) due to user yostj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0980 -	· Total						\$0.00	
0990	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS)	Material		3	Aug 17, 2020	SYSTEM	(\$253.80)	
	FOR FULL DEPTH PAVEMENT REPAIR			3	Aug 17, 2020	SYSTEM	\$253.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) due to user yostj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				4	Sep 2, 2020	SYSTEM	(\$253.80)	
				4	Sep 2, 2020	SYSTEM	\$253.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) due to user yostj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				5	Sep 16, 2020	SYSTEM	(\$253.80)	
				5	Sep 16, 2020	SYSTEM	\$253.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0030) due to user yostj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				6	Oct 1, 2020	SYSTEM	(\$253.80)	
				6	Oct 1, 2020	SYSTEM	\$253.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0059) due to user yostj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0990 -	Total						\$0.00	
1000	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR		ACAD	10	Dec 2, 2020	yostj1	(\$368.10)	Asphalt cement price adjustment for work between the dates 8/11/20 through 8/19/20.
			ACAD - Tota	al			(\$368.10)	
	Other Item Adjustment - Total						(\$368.10)	
	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH	Overrun	Overrun	4	Sep 2, 2020	SYSTEM	(\$4,999.62)	
	PAVEMENT REPAIR			9	Nov 16, 2020	SYSTEM	\$4,999.62	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',219.86000 - 219.86000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
	- Total						(\$368.10)	
1010	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	Overrun	Overrun		Sep 2, 2020	SYSTEM	(\$37,090.43)	
				9	Nov 16, 2020	SYSTEM	\$37,090.43	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',229.52000 - 229.52000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
		туре	Туре	Number	Date	By		
1150	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	Material		7	Oct 16, 2020	SYSTEM	(\$21,618.00)	
	WHITE			7	Oct 16, 2020	SYSTEM	\$21,618.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0062) due to user yostj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$32,058.00)	
				8	Nov 2, 2020	SYSTEM	\$32,058.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0045) due to user yostj1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Other Item Adjustment	OADJ	8	Nov 2, 2020	yostj1	(\$2,358.00)	This adjustment offsets the autogenerated adjustment made on an item that has insufficient materials and an overrun on quantity. This adjustment removes payment for the overrun amount.
			OADJ - Tota	al			(\$2,358.00)	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE		OTHR	9	Nov 16, 2020	yostj1	\$2,358.00	This adjustment offsets the adjustment from estimate 008 for items that have insufficient materials and an overrun on quantity. Now that the materials exception has been resolved the adjustment on estimate 008 is no longer needed.
			OTHR - Tota	al			\$2,358.00	
	Other Item Adjustment - Total				_		\$0.00	
	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	Overrun	Overrun	8	Nov 2, 2020	SYSTEM	(\$2,358.00)	
	WHITE			8	Nov 2, 2020	SYSTEM	\$2,358.00	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0044) overridding Payment Estimate Exception 83 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$2,358.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				9	Nov 16, 2020	SYSTEM	(\$10,260.00)	
			Overrun - T	otal			(\$12,618.00)	
	Overrun - Total						(\$12,618.00)	
1150 -	Total						(\$12,618.00)	
1160	PREFORMED THERMOPLASTIC PAVEMENT MARKING,	Material		7	Oct 16, 2020	SYSTEM	(\$6,840.00)	
	LEFT/RIGHT ARROW			7	Oct 16, 2020	SYSTEM	\$6,840.00	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0063) due to user yostj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1160 -	Total						\$0.00	
1190	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	Material		7	Oct 16, 2020	SYSTEM	(\$7,560.00)	
				7	Oct 16, 2020	SYSTEM	\$7,560.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0064) due to user yostj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
			- Total				\$0.00	
							\$0.00	
	Material - Total							
1190 -	Total						\$0.00	
	Total 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT	Material		8	Nov 2, 2020	SYSTEM		
	Total 4 IN. YELLOW HIGH BUILD	Material		8		SYSTEM	\$0.00 (\$5,202.40) \$5,202.40	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0046) due to user yostj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
	Total 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L	Material			2020 Nov 2,		\$0.00 (\$5,202.40)	Estimate Item Adjustment (0046) due to user yostj1 overridding
<mark>1190 -</mark> 1200	Total 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L	Material		8	2020 Nov 2, 2020 Nov 16,	SYSTEM	\$0.00 (\$5,202.40) \$5,202.40	Estimate Item Adjustment (0046) due to user yostj1 overridding Payment Estimate Exception 57 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) due to user yostj1 overridding
	Total 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L	Material	Total	8	2020 Nov 2, 2020 Nov 16, 2020 Nov 16,	SYSTEM SYSTEM	\$0.00 (\$5,202.40) \$5,202.40 (\$10,644.90) \$10,644.90	Estimate Item Adjustment (0046) due to user yostj1 overridding Payment Estimate Exception 57 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment
	Total 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L	Material	- Total	8	2020 Nov 2, 2020 Nov 16, 2020 Nov 16,	SYSTEM SYSTEM	\$0.00 (\$5,202.40) \$5,202.40 (\$10,644.90)	Payment Estimate Exception 57 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0034) due to user yostj1 overridding



Image: Second	Lin	Decent f	Adhead	01	F (0	0	A	Dar
WATERBORNE FAULTY MMNNO RAIT: DEC SUB3 MANNO RAIT: DEC SUB3	Line	Description		Adjustment				Amount	Remarks
BEADS BEADS <th< td=""><td>1210</td><td>WATERBORNE PAVEMENT</td><td>Material</td><td></td><td>8</td><td></td><td>SYSTEM</td><td>(\$6,417.90)</td><td></td></th<>	1210	WATERBORNE PAVEMENT	Material		8		SYSTEM	(\$6,417.90)	
Image: second					8		SYSTEM	\$6,417.90	
Image: stands Stands <th< td=""><td></td><td></td><td></td><td></td><td>9</td><td></td><td>SYSTEM</td><td>(\$12,519.18)</td><td></td></th<>					9		SYSTEM	(\$12,519.18)	
Material - Total View 2000 SYSTEM 40.00 1210 - Total Material - Total Material - Total 50.00 MATERICONE PLANK ENDER MARKING PLANK ENDER BEADS Material - Materi					9		SYSTEM	\$12,519.18	
1210 - Total U 9.000 1220 V. B., YELLOV, HIGH BULD, MARKING PARMT, FYEL BEADS Material BEADS Material BEADS </td <td></td> <td></td> <td></td> <td>- Total</td> <td></td> <td></td> <td></td> <td>\$0.00</td> <td></td>				- Total				\$0.00	
120 IN FELCY MUCH BILLO Material Status IN Sec. SYSTEM (857.00) MARKING PART, TYPE L BEADS IN VI 2, SYSTEM SST.00 The adjustment offset the original system-generated Overtur Payment Estimate Payment Estimate Exception 83 on the current Payment Estimate. 0 Nov 16, 2000 SYSTEM (81.403.20) 0 Nov 16, 2000 SYSTEM (81.403.20) 0 Nov 16, 2000 SYSTEM (81.403.20) 10 Nov 16, 2000 SYSTEM (81.403.20) 11 Total SYSTEM (81.403.20) 11 Total Total Stress 1230 Total Nov 16, SYSTEM (8502.50) 1230 Total Nov 16, SYSTEM Stress 1230 Total Nov 16, SYSTEM Stress 1230 Total Nov 16, SYSTEM Stress 1230 Total Stress Stress 1240 Total Stress Stress 1240 Material - Total Stress Stress 1240 Material - Total		Material - Total						\$0.00	
WATERBORNE PAVEMENT MARKING PANT, TYPE BEADS Value (1) 2020 (2) Value (2)	1210 -	Total						\$0.00	
BEADS BEADS	1220	WATERBORNE PAVEMENT	Material		8		SYSTEM	(\$857.00)	
$ \begin{array}{ c c c } \hline c c \\ \hline $					8		SYSTEM	\$857.00	
Image: state in the					9		SYSTEM	(\$1,493.20)	
Material - Total Second <					9		SYSTEM	\$1,493.20	
1220 Total Stole 50.00 1238 VARKING PAINT, TYPE I BEADS 9 Nov 16, 2020 SYSTEM (\$592.50) 1240 VARKING PAINT, TYPE I BEADS 9 Nov 16, 2020 SYSTEM \$592.50 This adjustment offeets the original system-generated Overum Payment Estimate. 1240 VARKING PAINT, TYPE I BEADS - Total 50.00 SYSTEM \$50.00 1240 VARKING PAINT, TYPE I BEADS 9 Nov 16, 2020 SYSTEM \$50.00 1240 VARKING PAINT, TYPE P BEADS 9 Nov 16, 2020 SYSTEM \$92.16 This adjustment offeets the original system-generated Overum Payment Estimate. 1240 VARKING PAINT, TYPE P BEADS 9 Nov 16, 2020 SYSTEM \$92.16 This adjustment offeets the original system-generated Overun Payment Estimate. 1240 VARKING PAINT, TYPE P BEADS 9 Nov 16, 2020 SYSTEM \$92.16 This adjustment offeet the original system-generated Overun Payment Estimate. 1240 VARKING PAINT, TYPE P BEADS 9 Nov 16, 2020 SYSTEM \$92.242 This adjustment offeet the original system-generated Overun Payment Estimate. 1241 Total 9 Nov 16, 20200 SYSTEM \$322.24				- Total				\$0.00	
1230 12 IN. WHITE HIGH BUILD WATERBORKE PAYEMENT MARKING PAINT, TPEL BEADS Material Paint Status 9 Nov 16, 2020 SYSTEM (\$592.50) Marking Paint, TPEL BEADS - Total 9 Nov 16, 2020 SYSTEM \$592.50 This adjustment offsets the original system-generated Overun Payme Payment Estimate Exception 44 on the current Payment Estimate. 1230 - Total - Total 50.00 1230 - Total 50.00 1230 - Total 9 Nov 16, 2020 SYSTEM \$90.00 Marking Paint, TVPE P BEADS 9 Nov 16, 2020 SYSTEM \$92.10 Marking Paint, TVPE P BEADS 9 Nov 16, 2020 SYSTEM \$92.16 This adjustment offsets the original system-generated Overun Payme Estimate Exception 46 on the current Payment Estimate. 1240 4 IN. WHITE STANDARD Material - Total 9 Nov 16, 2020 SYSTEM \$92.00 1240 4 IN. VELLOW STANDARD MARKING PAINT, TVPE P BEADS 9 Nov 16, 2020 SYSTEM \$322.24 This adjustment offsets the original system-generated Overun Payme Estimate Exception 46 on the current Payment Estimate. 1248 4 IN. VELLOW STANDARD Marking Paint 9 Nov 16, 2020, 2020, 2020, 2020, 20		Material - Total						\$0.00	
WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS Waterial - Total 2020 Current - Status File adjustment offsets the original system-generated Overun Payment Estimate Estimate Ene Adjustment (0037) due to user joed] overriding Payment Estimate Exception 44 on the current Payment Estimate. 1230 - Total - Total 9 Nov 16, 2020 SYSTEM S592 50 This adjustment offsets the original system-generated Overun Payment Estimate Estimate Ene Adjustment (0037) due to user joed] overriding Payment Estimate Exception 44 on the current Payment Estimate. 1230 - Total - Total 9 Nov 16, 2020 SYSTEM (S92.16) 1240 4 IN, WHITE STANDARD BEADS Material - Total 9 Nov 16, 2020 SYSTEM S92.16 This adjustment offsets the original system-generated Overun Payment Estimate Estimate Exception 46 on the current Payment Estimate. 1240 - Total 9 Nov 16, 2020 SYSTEM S92.24 This adjustment offsets the original system-generated Overun Payment Estimate Exception 46 on the current Payment Estimate. 1240 4 IN, VELLOW STANDARD MARKING PAINT, TeAL 9 Nov 16, 2020 SYSTEM S322.24 This adjustment offsets the original system-generated Overun Payment Estimate Exception 46 on the current Payment Estimate. 1240 - Total - Total	1220 -	Total						\$0.00	
BEADS P Nov 16, 2020 SYSTEM S592.50 This adjustment offsets the original system-generated Overnun Payme Payment Estimate tex Adjustment (037) use to user yoist overdiding Payment Estimate Exception 44 on the current Payment Estimate. 1240 Atterial - Total 50.00 50.00 1240 4 N. WHITE STANDARD MARKING PAINT, TYPE P BEADS Material 9 Nov 16, 2020 SYSTEM (\$92.16) 1240 4 N. WHITE STANDARD MARKING PAINT, TYPE P BEADS Material 9 Nov 16, 2020 SYSTEM (\$92.16) 1240 4 N. WHITE STANDARD MARKING PAINT, TYPE P BEADS 9 Nov 16, 2020 SYSTEM (\$92.16) This adjustment offsets the original system-generated Overrun Payme Estimate texn Adjustment (042) due to user yoigt overridding. Payment Estimate texn Adjustment offsets the original system-generated Overrun Payme Estimate texn Adjustment offsets the original system-generated Overrun Payme Estimate texn Adjustment offsets the original system-generated Overrun Payme Estimate texn Adjustment offsets the original system-generated Overrun Payment Estimate Estimate texn Adjustment offsets the original system-generated Overrun Payment Estimate texn Adjustment offsets the original s	1230	WATERBORNE PAVEMENT	Material		9		SYSTEM	(\$592.50)	
Material - Total Source Source 1230 - Total 4 N. WHITE STANDARD Material - Total Source Source <t< td=""><td></td><td></td><td></td><td></td><td>9</td><td></td><td>SYSTEM</td><td>\$592.50</td><td></td></t<>					9		SYSTEM	\$592.50	
1230 - Total 4 IN WHTE STANDARD WATERBORKE PAVEMENT MARKING PAINT, TYPE P BEADS 9 Nov 16, 2020 SYSTEM (§92.16) 9 Nov 16, 2020 SYSTEM (§92.16) This adjustment offsets the original system-generated Overrun Payme Payment Estimate Exception 46 on the current Payment Estimate. 1240 - Total 1240 - Total 1240 - Total 9 Nov 16, 2020 SYSTEM S92.16 This adjustment offsets the original system-generated Overrun Payment Estimate. 1240 - Total 1240 - Total 9 Nov 16, 2020 SYSTEM (\$322.24) 9 Nov 16, 2020 SYSTEM (\$322.24) Total 1248 Material - Total 1248 Nov 16, 2020 SYSTEM (\$322.24) Total 1248 Material - Total 1248 Collpan="4">10000 1248 Colspan="4">16 1248 Colspan="4">16 16 16 16 124 Colspan="4"				- Total				\$0.00	
1240 4 IN. WHITE STANDARD WATERBORNE PAVEMENT BEADS Material Marking PAVEMENT BEADS Material Material 9 Nov 16. 2020 SYSTEM (\$92.16) 9 Nov 16. Nov 16. Nov 16. Nov 16. SYSTEM SYSTEM \$9.16 This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0042) due to user yositj overridding Payment Estimate Exception 46 on the current Payment Estimate S0.00 1240 - Total - Total 50.00 1244 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS Material 9 Nov 16. 2020 SYSTEM (\$322.24) 1248 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS Material 9 Nov 16. 2020 SYSTEM (\$322.24) 1248 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS Material 9 Nov 16. 2020 SYSTEM \$322.24 1248 Total - Total 50.00 SYSTEM \$30.00 1248 Collom/LING BITUMINOUS SURFACING (3 IN. THICK OR LESS) Overrun 7 Oct 16. 2020 SYSTEM \$10.00 1270 COLDMILING BITUMINOUS SURFACING (3 IN. THICK OR LESS) Overrun 7 Oct 16. 2020 SYSTEM \$(\$10,744.29) 1270 - Total Cotal SYSTEM \$(\$10,744.29) SYSTEM \$(\$10,744.29)		Material - Total						\$0.00	
$ \begin{array}{c c c c c } \hline WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS EADS BEADS BEA$	1230 -	Total				_		\$0.00	
BEADS P Nov 16, 2020 SYSTEM S82.16 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (Odd2) due to usery ovej11 overrinding Payment Estimate Exception 46 on the current Payment Estimate. 1240 - Total - Total 50.00 1240 - Total 9 Nov 16, 2020 SYSTEM \$0.00 1240 - Total 9 Nov 16, 2020 SYSTEM \$0.00 1248 4 IN, YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE PAVEMENT MARKING PAUL VERTIFIER TOTAL 9 Nov 16, 2020 SYSTEM \$322.24 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (Odd) due to user oversol 1 overrinding Payment Estimate Item Adjustment (Odd) due to user oversol 1 overrinding Payment Estimate Item Adjustment (Odd) due to user oversol 1 overrinding Payment Estimate Item Adjustment (Odd) due to user oversol 1 overrinding Payment Estimate Item Adjustment (Odd) due to user oversol 1 overrinding Payment Estimate Item Adjustment (Odd) due to user oversol 1 overrinding Payment Estimate Item Adjustment (Odd) due to user oversol 1 overrinding Payment Estimate Item Adjustment (Odd) due to user oversol 1 overrinding Payment Estimate Item Adjustment (Odd) due to user oversol 1 overrinding Payment Estimate Item Adjustment (Odd) due to user oversol 1 overrinding Payment Estimate Item Adjustment (Odd) due to user oversol 1 overrinding Payment Estimate Item Adjustment (Odd) due to user overind 1 over	1240	WATERBORNE PAVEMENT	Material			2020		. ,	
Material - Total\$0.001240 - Total\$0.001248 - Total 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADSMaterial9Nov 16, 2020SYSTEM\$(\$322.24)9Nov 16, 2020SYSTEM\$3322.24This adjustment offsets the original system-generated Overrun Payment Payment Estimate tem Adjustment(0041) due to user yostif overriding Payment Estimate tem Adjustment(0041) due to user yostif overriding Payment Estimate tem Adjustment (0041) due to user yostif overriding Payment Estimate tem Adjustment (0041) due to user yostif overriding Payment Estimate tem Adjustment (0041) due to user yostif overriding Payment Estimate tem Adjustment (0041) due to user yostif overriding Payment Estimate tem Adjustment (0041) due to user yostif overriding Payment Estimate tem Adjustment (0041) due to user yostif overriding Payment Estimate tem Adjustment (0041) due to user yostif overriding Payment Estimate tem Adjustment (0041) due to user yostif overriding Payment Estimate tem Adjustment (0041) due to user yostif overriding Payment Estimate tem Adjustment (0041) due to user yostif overriding Payment Estimate tem Adjustment (0041) due to user yostif overriding Payment Estimate tem Adjustment (0041) due to user yostif overriding Payment Estimate tem Adjustment (0041) due to user yostif overriding Payment Estimate tem Adjustment (0041) due to user yostif overriding Payment Estimate tem Adjustment (0041) due to user yostif overriding Payment Estimate tem Adjustment (0041) due to user yostif overriding Payment Estimate tem Adjustment (0041) due to user yostif overriding Payment Estimate tem Adjustment (0041) due to user yostif overriding Payment Estimate tem Adjustment (0041) due to user yostif overriding Payment Estimate tem Adjustment (0041) due to user yostif					9		SYSTEM	\$92.16	
1240 - Total \$0.00 1248 4 IN. YELLOW STANDARD MARKING PAINET, TYPE BEADS Material 9 Nov 16, 2020 SYSTEM (\$322.24) This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0041) due to user yostj1 overridding Payment Estimate Exception 48 on the current Payment Estimate. 1248 - Total - Total 50.00 1248 - Total Overrun Overrun 7 Oc1 6, 2020 SYSTEM (\$10,744.29) 1270 COLOMILLING BITUMINOUS SURFACING (3 IN. THICK OR LESS) Overrun - Total (\$10,744.29) (\$10,744.29) 1270 - Total Overrun - Total (\$10,744.29) (\$10,744.29) (\$10,744.29) 1270 - Total Surperson (\$10,744.29) (\$10,744.29) 1270 - Total (\$10,744.29) (\$10,744.29) (\$10,744.29) 1270 - Total (\$10,744.29) (\$10,744.29) (\$10,744.29) 1310 24 IN. PIPE GROUP B Material 8 Nov 2, 2020 SYSTEM (\$627.00) 1310 24 IN. PIPE GROUP B Material <td< td=""><td></td><td></td><td></td><td>- Total</td><td></td><td></td><td></td><td>\$0.00</td><td></td></td<>				- Total				\$0.00	
1248 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS Material 9 Nov 16, 2020 SYSTEM (\$322.24) 9 Nov 16, 2020 SYSTEM \$322.24 This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0041) due to user yosiji overridding Payment Estimate Exception 48 on the current Payment Estimate. 10 • Total • Total • Total \$0.00 1248 - Total • Total • Overrun 7 Oct 16, 2020 SYSTEM \$0.00 1248 - Total • Overrun 7 Oct 16, 2020 SYSTEM \$(\$10,744.29) 1270 • Overrun - Total • Overrun - Total • Overrun - Total • (\$10,744.29) 1270 - Total 24 IN. PIPE GROUP B Material • Nov 2, 2020 SYSTEM \$(\$10,744.29) 1210 24 IN. PIPE GROUP B Material • Nov 2, 2020 SYSTEM \$(\$27.00)		Material - Total						\$0.00	
WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 9 Nov 16, 2020 SYSTEM \$322.24 This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0041) due to user yosij1 overridding Payment Estimate Exception 48 on the current Payment Estimate Estimate Item Adjustment (0041) due to user yosij1 overridding Payment Estimate Exception 48 on the current Payment Estimate. 1244 - Total - Total \$0.00 1248 - Total - Total \$0.00 PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) Overrun 7 Oct 16, 2020 SYSTEM (\$10,744.29) 1270 - Total - Total	1240 -	Total						\$0.00	
BEADS 9 Nov 16, 2020 SYSTEM \$322.24 This adjustment offsets the original system-generated Overrun Payme Estimate tem Adjustment (0041) due to user yostj 1 overridding Payment Estimate tem Adjustment (0041) due to user yostj 1 overridding Payment Estimate Exception 48 on the current Payment Estimate. Intervision 1000000000000000000000000000000000000	1248	WATERBORNE PAVEMENT	Material		9				
Material - Total \$0.00 1248 - Total \$0.00 1270 COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) Overrun 7 Oct 16, 2020 SYSTEM (\$10,744.29) Overrun - Total Overrun - Total Overrun - Total (\$10,744.29) 1270 - Total (\$10,744.29) 1270 - Total (\$10,744.29) 1310 24 IN. PIPE GROUP B Material § Nov 2, 2020 SYSTEM (\$627.00) 1310 24 IN. PIPE GROUP B Material § Nov 2, 2020 SYSTEM (\$627.00) 1310 24 IN. PIPE GROUP B Material § Nov 2, 2020 SYSTEM SQL 2020 Total					9		SYSTEM	\$322.24	Estimate Item Adjustment (0041) due to user yostj1 overridding
1248 - Total \$0.00 1270 - COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) Overrun 7 Oct 16, 2020 SYSTEM (\$10,744.29) Overrun - Total Overrun - Total Overrun - Total (\$10,744.29) 1270 - Total (\$10,744.29) (\$10,744.29) 1310 24 IN. PIPE GROUP B Material 8 Nov 2, 2020 SYSTEM (\$627.00) 1310 24 IN. PIPE GROUP B Material 8 Nov 2, 2020 SYSTEM \$627.00)				- Total				\$0.00	
1270 COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) Overrun 7 Oct 16, 2020 SYSTEM (\$10,744.29) Overrun - Total Overrun - Total Overrun - Total 1270 - Total 1310 24 IN. PIPE GROUP B Material 8 Nov 2, 2020 SYSTEM (\$627.00) This adjustment offsets the original system-generated Overrun Paymer								\$0.00	
PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) 2020 Contrained Contrained <thcontrained< th=""> Contrained <</thcontrained<>	1248 -	Total						\$0.00	
Overrun - Total (\$10,744.29) 1270 - Total (\$10,744.29) 1310 24 IN. PIPE GROUP B Material 8 Nov 2, 2020 SYSTEM (\$627.00) 8 Nov 2, SYSTEM \$627.00 This adjustment offsets the original system-generated Overrun Payment			Overrun	Overrun	7		SYSTEM	(\$10,744.29)	
1270 - Total (\$10,744.29) 1310 24 IN. PIPE GROUP B Material 8 Nov 2, 2020 SYSTEM (\$627.00) 8 Nov 2, SYSTEM \$627.00 This adjustment offsets the original system-generated Overrun Payment	1270	PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR							
1310 24 IN. PIPE GROUP B Material 8 Nov 2, 2020 SYSTEM (\$627.00) 8 Nov 2, SYSTEM \$627.00 This adjustment offsets the original system-generated Overrun Payme	1270	PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR		Overrun - To	otal			(\$10,744.29)	
2020 SYSTEM \$627.00 This adjustment offsets the original system-generated Overrun Payment		PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)		Overrun - To	otal				
		PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) Overrun - Total		Overrun - To	otal			(\$10,744.29)	
Payment Estimate Exception 71 on the current Payment Estimate.	1270 - `	PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) Overrun - Total Total	Material	Overrun - To			SYSTEM	(\$10,744.29) (\$10,744.29)	
9 Nov 16, SYSTEM (\$627.00)	1270 - `	PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) Overrun - Total Total	Material	Overrun - T	8	2020		(\$10,744.29) (\$10,744.29) (\$627.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0049) due to user yostj1 overridding Payment Estimate Exception 71 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1310	24 IN. PIPE GROUP B	Material			2020			
				9	Nov 16, 2020	SYSTEM	\$627.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) due to user yostj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$627.00)	
				10	Dec 2, 2020	SYSTEM	\$627.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0063) due to user yostj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1310 -	Total						\$0.00	
1330	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED	Material		8	Nov 2, 2020	SYSTEM	(\$1,415.00)	
	END SECTION			8	Nov 2, 2020	SYSTEM	\$1,415.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0050) due to user yostj1 overridding Payment Estimate Exception 72 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$1,415.00)	
				9	Nov 16, 2020	SYSTEM	\$1,415.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) due to user yostj1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$1,415.00)	
				10	Dec 2, 2020	SYSTEM	\$1,415.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0064) due to user yostj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1330 -	- Total						\$0.00	
1340	SEEDING - COOL SEASON MIXTURES	Material		8	Nov 2, 2020	SYSTEM	(\$3,070.00)	
				8	Nov 2, 2020	SYSTEM	\$3,070.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0051) due to user yostj1 overridding Payment Estimate Exception 73 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$3,070.00)	
				9	Nov 16, 2020	SYSTEM	\$3,070.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) due to user yostj1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$3,070.00)	
				10	Dec 2, 2020	SYSTEM	\$3,070.00	This adjustment offsets the original system-generated Overrun Payment
								Estimate Item Adjustment (0065) due to user yostj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total		- Total				\$0.00 \$0.00	
1340 -	Material - Total - Total		- Total					
<mark>1340</mark> - 1350		Material	- Total	7	Oct 16, 2020	SYSTEM	\$0.00	
	- Total	Material	- Total	7 7		SYSTEM	\$0.00 \$0.00	
	- Total	Material	- Total		2020 Oct 16,		\$0.00 \$0.00 (\$365.00)	Payment Estimate Exception 42 on the current Payment Estimate.
	- Total	Material			2020 Oct 16,		\$0.00 \$0.00 (\$365.00) \$365.00	Payment Estimate Exception 42 on the current Payment Estimate.
1350	Total SEDIMENT TRAP ROCK	Material			2020 Oct 16,		\$0.00 \$0.00 (\$365.00) \$365.00 \$0.00	Payment Estimate Exception 42 on the current Payment Estimate.
1350	Total SEDIMENT TRAP ROCK Material - Total				2020 Oct 16,		\$0.00 \$0.00 (\$365.00) \$365.00 \$0.00	Payment Estimate Exception 42 on the current Payment Estimate.
1350 1350 -	Total SEDIMENT TRAP ROCK Material - Total Total			7	2020 Oct 16, 2020 Oct 16,	SYSTEM	\$0.00 \$0.00 (\$365.00) \$365.00 \$0.00 \$0.00	Payment Estimate Exception 42 on the current Payment Estimate.
1350 1350 -	Total SEDIMENT TRAP ROCK Material - Total Total			7 7	2020 Oct 16, 2020 Oct 16, 2020 Oct 16, 2020 Oct 16,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$365.00) \$365.00 \$0.00 \$0.00 (\$720.00)	Payment Estimate Exception 42 on the current Payment Estimate.
1350 1350 -	Total SEDIMENT TRAP ROCK Material - Total Total		- Total	7 7	2020 Oct 16, 2020 Oct 16, 2020 Oct 16, 2020 Oct 16,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$365.00) \$365.00 \$0.00 \$0.00 (\$720.00) \$720.00	Payment Estimate Exception 42 on the current Payment Estimate.



Other It Item 1 Item 2 <	CURB INLET CHECK		Adjustment Type - Total	Number 7 7 7 7	Date Oct 16, 2020 Oct 16, 2020	By SYSTEM SYSTEM	(\$756.00) \$756.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0069) due to user yostj1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
Materia Other It Other It Italian <	rial - Total CURB INLET CHECK	C Other Item		7	2020 Oct 16, 2020		\$756.00	Estimate Item Adjustment (0069) due to user yostj1 overridding
Other It Overrun 1380 - Total 1400 - Total 1420 - Total 1420 - Total	CURB INLET CHECK				2020	SYSTEM		Estimate Item Adjustment (0069) due to user yostj1 overridding
Other It Overrun 1380 - Total 1400 Materia 1400 - Total 1420	CURB INLET CHECK			7				. aymonic Excoption of on the outfort if aymonic Estimate.
Other It Overrun 1380 - Total 1400 Materia 1400 - Total 1420	CURB INLET CHECK		OTHR	7			\$0.00	
Overrun 1380 - Total 1400 1400 - Total 1420 Constru	r Item Adjustment - Total		OTHR	7			\$0.00	
Overrun 1380 - Total 1400 1400 - Total 1420 1420					Oct 16, 2020	yostj1	(\$252.00)	This adjustment offsets the autogenerated adjustment made on an item that has insufficient materials and an overrun on quantity. This adjustment removes payment for the overrun amount.
Overrun 1380 - Total 1400 1400 - Total 1420 1420				9	Nov 16, 2020	yostj1	\$252.00	This adjustment offsets the adjustment from estimate 007 for items that have insufficient materials and an overrun on quantity. Now that the materials exception has been resolved the adjustment on estimate 007 is no longer needed.
Overrun 1380 - Total 1400 - Total 1420 - Total 1420 - Total			OTHR - Tota	al		i i i i i i i i i i i i i i i i i i i	\$0.00	
1380 - Total 1400 Materia 1400 - Total 1420 Constru	CURB INLET CHECK						\$0.00	
1380 - Total 1400 1400 - Total 1420 Constru		C Overrun	Overrun	7	Oct 16, 2020	SYSTEM	(\$252.00)	
1380 - Total 1400 1400 - Total 1420 1420 - Constru				7	Oct 16, 2020	SYSTEM	\$252.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0068) overridding Payment Estimate Exception 64 on the current Payment Estimate.
1380 - Total 1400 1400 - Total 1420 1420 - Constru				8	Nov 2, 2020	SYSTEM	(\$252.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
1380 - Total 1400 1400 - Total 1420 1420 - Constru			Overrun - T	otal			(\$252.00)	
1400 Materia 1400 - Total 1420 Constru	run - Total						(\$252.00)	
Materia 1400 - Total 1420 Constru							(\$252.00)	
1400 - Total 1420 Constru	SILT FENCE	Material		7	Oct 16, 2020	SYSTEM	(\$3,222.00)	
1400 - Total 1420 Constru				7	Oct 16, 2020	SYSTEM	\$3,222.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0070) due to user yostj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
1400 - Total 1420 Constru			- Total				\$0.00	
Constru	rial - Total						\$0.00	
Constru							\$0.00	
	MGS GUARDRAIL	Construction Stockpile		4	Sep 2, 2020	SYSTEM	\$11,456.75	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Oct 16, 2020	SYSTEM	(\$11,456.75)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
Materia	truction Stockpile - Total MGS GUARDRAIL	_ Material		7	Oct 16, 2020	SYSTEM	\$0.00 (\$21,737.50)	
Materia				7	Oct 16, 2020	SYSTEM	\$21,737.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0073) due to user yostj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
Materia				8	Nov 2, 2020	SYSTEM	(\$21,737.50)	
Materia				8	Nov 2, 2020	SYSTEM	\$21,737.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0054) due to user yostj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
Materia			- Total				\$0.00	
							\$0.00	
	rial - Total	Other Item Adjustment	OTHR	7	Oct 16, 2020	yostj1	(\$1,609.50)	This adjustment offsets the autogenerated adjustment made on an item that has insufficient materials and an overrun on quantity. This adjustment removes payment for the overrun amount.
	ial - Total MGS GUARDRAIL			9	Nov 16, 2020	yostj1	\$1,609.50	This adjustment offsets the adjustment from estimate 007 for items that have insufficient materials and an overrun on quantity. Now that the materials exception has been resolved the adjustment on estimate 007 is no longer needed.
Other It			OTHR - Tota	al			\$0.00	
			OTHR - Tota	al			\$0.00 \$0.00	



			01	- .	0.11	0.11		
Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1420	MGS GUARDRAIL	Overrun	Overrun	7	Oct 16, 2020	SYSTEM	\$1,609.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0072) overridding Payment Estimate Exception 65 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$1,609.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				8	Nov 2, 2020	SYSTEM	\$1,609.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0053) overridding Payment Estimate Exception 86 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$1,609.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				10	Dec 2, 2020	SYSTEM	\$1,609.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',18.50000 - 18.50000, 'is applied (if non-zero).
			Overrun - Te	otal			\$0.00	
	Overrun - Total						\$0.00	
1420 -	Total						\$0.00	
1430	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Construction Stockpile		4	Sep 2, 2020	SYSTEM	\$9,128.25	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Oct 16, 2020	SYSTEM	(\$8,194.40)	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Nov 2, 2020	SYSTEM	(\$6.18)	Payment Estimate Item Adjustment generated Stockpile Transaction
				10	Dec 2, 2020	SYSTEM	(\$927.67)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material		7	Oct 16, 2020	SYSTEM	(\$14,243.75)	
				7	Oct 16, 2020	SYSTEM	\$14,243.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0075) due to user yostj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$14,254.50)	
				8	Nov 2, 2020	SYSTEM	\$14,254.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0056) due to user yostj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1430 -	Total						\$0.00	
1440	MGS BRIDGE APPROACH TRANSITION SECTION	Construction Stockpile		4	Sep 2, 2020	SYSTEM	\$4,683.00	Payment Estimate Item Adjustment generated Stockpile Transaction
	(EXTENDED CURB)			7	Oct 16, 2020	SYSTEM	(\$4,683.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
1440 -	Total						\$0.00	
1450	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		4	Sep 2, 2020	SYSTEM	\$10,619.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Oct 16, 2020	SYSTEM	(\$10,619.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
1450 -	Total						\$0.00	
1460	SIGNAL HEAD, TYPE 3S	Material		9	Nov 16, 2020	SYSTEM	(\$2,449.00)	
				9	Nov 16, 2020	SYSTEM	\$2,449.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) due to user yostj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$2,449.00)	
				10	Dec 2, 2020	SYSTEM	\$2,449.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0066) due to user yostj1 overridding Payment Estimate Exception 48 on the current Payment Estimate.



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
1460		Material	- Total				\$0.00	
	Material - Total						\$0.00	
1460 -	Total						\$0.00	
1470	SIGNAL HEAD, TYPE 1S, PEDESTRIAN	Material		10	Dec 2, 2020	SYSTEM	(\$3,928.00)	
				10	Dec 2, 2020	SYSTEM	\$3,928.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0067) due to user yostj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1470 -	Total						\$0.00	
1500	POST, SIGNAL 8 FT. OR 2.4 M	Material		9	Nov 16, 2020	SYSTEM	(\$4,482.00)	
				9	Nov 16, 2020	SYSTEM	\$4,482.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0045) due to user yostj1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$4,482.00)	
				10	Dec 2, 2020	SYSTEM	\$4,482.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0068) due to user yostj1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1500 -	Total						\$0.00	
1510	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material		10	Dec 2, 2020	SYSTEM	(\$1,634.00)	
				10	Dec 2, 2020	SYSTEM	\$1,634.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0069) due to user yostj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1510 -	Total						\$0.00	
1520	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	Material		10	Dec 2, 2020	SYSTEM	(\$912.00)	
				10	Dec 2, 2020	SYSTEM	\$912.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0070) due to user yostj1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1520 -	Total						\$0.00	
1530	CONDUIT, 4 IN., PUSHED WITH TRACER WIRE	Material		10	Dec 2, 2020	SYSTEM	(\$5,556.60)	
				10	Dec 2, 2020	SYSTEM	\$5,556.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0071) due to user yostj1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
1530 -	Total						\$0.00	
1540	CABLE, 16 AWG 2 CONDUCTOR	Material		9	Nov 16, 2020	SYSTEM	(\$756.00)	
				9	Nov 16, 2020	SYSTEM	\$756.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0046) due to user yostj1 overridding Payment Estimate Exception 61 on the current Payment Estimate.
							(\$756.00)	
				10	Dec 2, 2020	SYSTEM	(\$750.00)	
				10 10		SYSTEM	\$756.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0072) due to user yostj1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
			- Total		2020 Dec 2,		. ,	Estimate Item Adjustment (0072) due to user yostj1 overridding
	Material - Total		- Total		2020 Dec 2,		\$756.00	Estimate Item Adjustment (0072) due to user yostj1 overridding



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	By		
1550	CABLE, 16 AWG 5 CONDUCTOR	Material		9	Nov 16, 2020	SYSTEM	(\$864.00)	
				9	Nov 16, 2020	SYSTEM	\$864.00	This adjustment offsets the original system-generated Overrun Paymen Estimate Item Adjustment (0047) due to user yostj1 overridding Payment Estimate Exception 62 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$864.00)	
				10	Dec 2, 2020	SYSTEM	\$864.00	This adjustment offsets the original system-generated Overrun Paymer Estimate Item Adjustment (0073) due to user yostj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
550 -	- Total						\$0.00	
560	CABLE, 16 AWG 7 CONDUCTOR	Material		9	Nov 16, 2020	SYSTEM	(\$468.00)	
				9	Nov 16, 2020	SYSTEM	\$468.00	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0048) due to user yostj1 overridding Payment Estimate Exception 63 on the current Payment Estimate.
				10	Dec 2, 2020	SYSTEM	(\$468.00)	
				10	Dec 2, 2020	SYSTEM	\$468.00	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0074) due to user yostj1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
560 -	- Total						\$0.00	
570	PULL BOX, PREFORMED CLASS 2	Material		10	Dec 2, 2020	SYSTEM	(\$4,682.00)	
	2			10	Dec 2, 2020	SYSTEM	\$4,682.00	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0075) due to user yostj1 overridding Payment Estimate Exception 59 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
570 -	- Total						\$0.00	
580	BASE, CONCRETE	Material		10	Dec 2, 2020	SYSTEM	(\$3,362.40)	
				10	Dec 2, 2020	SYSTEM	\$3,362.40	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0076) due to user yostj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
580 -	- Total						\$0.00	
6001	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL	Material		6	Oct 1, 2020	SYSTEM	(\$7,005.18)	
	DEPTH PAVEMENT REPAIR			6	Oct 1, 2020	SYSTEM	\$7,005.18	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0053) due to user yostj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
				7	Oct 16, 2020	SYSTEM	(\$7,005.18)	
				7	Oct 16, 2020	SYSTEM	\$7,005.18	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0078) due to user yostj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$7,005.18)	
				8	Nov 2, 2020	SYSTEM	\$7,005.18	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0057) due to user yostj1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
				9	Nov 16, 2020	SYSTEM	(\$9,467.64)	
				9	Nov 16, 2020	SYSTEM	\$9,467.64	This adjustment offsets the original system-generated Overrun Payme Estimate Item Adjustment (0049) due to user yostj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
				10	Dec 2,	SYSTEM	(\$9,467.64)	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5001	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		10	Dec 2, 2020	SYSTEM	\$9,467.64	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0050) due to user yostj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
5001 -	- Total						\$0.00	
5002	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL	Material		6	Oct 1, 2020	SYSTEM	(\$1,335.10)	
	DEPTH PAVEMENT REPAIR (TYPE L JOINTS)			6	Oct 1, 2020	SYSTEM	\$1,335.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0054) due to user yostj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				7	Oct 16, 2020	SYSTEM	(\$1,335.10)	
				7	Oct 16, 2020	SYSTEM	\$1,335.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0079) due to user yostj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
				8	Nov 2, 2020	SYSTEM	(\$1,335.10)	
				8	Nov 2, 2020	SYSTEM	\$1,335.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0058) due to user yostj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
								Fayment Estimate Exception 49 on the current Fayment Estimate.
			- Total				\$0.00	r ayment Esumate Exception 49 on the current rayment Esumate.
	Material - Total		- Total				\$0.00 \$0.00	
5002 -	Material - Total - Total		- Total					
5002 - 5101	- Total TIE BAR (DRILLING, FURNISHING AND	Material	- Total	6	Oct 1, 2020	SYSTEM	\$0.00	
	- Total TIE BAR (DRILLING,	Material	- Total	6		SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0060) due to user yostj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material	- Total		2020 Oct 1,		\$0.00 \$0.00 (\$338.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0060) due to user yostj1 overridding
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material	- Total	6	2020 Oct 1, 2020 Oct 16,	SYSTEM	\$0.00 \$0.00 (\$338.00) \$338.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0060) due to user yostj1 overridding
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material	- Total	6 7	2020 Oct 1, 2020 Oct 16, 2020 Oct 16,	SYSTEM SYSTEM	\$0.00 \$0.00 (\$338.00) \$338.00 (\$338.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0060) due to user yostj1 overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0080) due to user yostj1 overridding
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material	- Total	6 7 7	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$338.00) \$338.00 (\$338.00) \$338.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0060) due to user yostj1 overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0080) due to user yostj1 overridding
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material	- Total	6 7 7 8	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$338.00) \$338.00 (\$338.00) \$338.00 (\$338.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0060) due to user yostj1 overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0080) due to user yostj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0059) due to user yostj1 overridding
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		6 7 7 8	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$338.00) \$338.00 (\$338.00) \$338.00 (\$338.00) \$338.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0060) due to user yostj1 overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0080) due to user yostj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0059) due to user yostj1 overridding
5101	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material		6 7 7 8	2020 Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 (\$338.00) \$338.00 (\$338.00) \$338.00 (\$338.00) \$338.00 \$338.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0060) due to user yostj1 overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0080) due to user yostj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0059) due to user yostj1 overridding