

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 18, 2021

Progress Estim	ate Number	Contract ID Prime Contractor	200117-C06 Phillips Hardy, Inc.	Pay Period Start Pay Period End	January 2, 2021 January 15, 2021	Original Contract Amount Net Change Order Amount Current Contract Amount	\$2,079,338.28 \$118,306.54 \$2,197,644.82		
Approval Date							By User		
January 21, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by								
January 21, 2021		Revi	ewed and Approved	(and should be con	sidered Draft) at th	e Resident Engineer Level by	sandis1		
January 21, 2021			Revi	ewed and Approved	at the Central Offi	ce Controllers Office Level by	greggd1		
Original Comp	pletion Date Current Completion Date Actual Completion Date % of Current Contract Amou								
November 2	2, 2020	November 2	er 2, 2020 33.24%						

No Milestones Exist for Contract

Contract Total Pa	ay For Estimate No. 13				
		This Estimate	Previous	To Date	
200117-C06					
	Total Posted Items Pay	\$220,982.00	\$509,508.89	\$730,490.89	
	Gross Item Adjustments	\$0.00	\$315,794.88	\$315,794.88	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$825,303.77	\$1,046,285.77	
Contract Total Pa	ayable This Estimate:	\$220,982.00			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4S3218	0910	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	LF	\$92.500	166	\$15,355.00
	0920	7025001	DYNAMIC PILE TESTING	EA	\$1,400.000	1	\$1,400.00
	0930	7027000	PILE POINT REINFORCEMENT	EA	\$95.000	7	\$665.00
	1080	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	SQFT	\$65.750	3,096	\$203,562.00
Project J4S321	18 - Total						\$220,982.00
Overall - Total							\$220,982.00

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	<u>Adjustr</u>	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3218	0160	PAVED APPROACH, 8 IN.	Material			-68.1	\$87.00	(\$5,924.70)
	0160	PAVED APPROACH, 8 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.	68.1	\$87.00	\$5,924.70
	0460	15 IN. PIPE GROUP B	Material			-195	\$52.00	(\$10,140.00)
	0460	15 IN. PIPE GROUP B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.	195	\$52.00	\$10,140.00
	0470	15 IN. PIPE GROUP C	Material			-33	\$57.00	(\$1,881.00)
	0470	15 IN. PIPE GROUP C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate.	33	\$57.00	\$1,881.00
	0540	SEEDING - COOL SEASON MIXTURES	Material			-0.403	\$3,170.00	(\$1,277.51)

Revision 4/1/2020 Page 1 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 18, 2021

				a., .,				
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3218	0540	SEEDING - COOL SEASON MIXTURES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate.	0.403	\$3,170.00	\$1,277.51
	0910	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Material			-166	\$92.50	(\$15,355.00
	0910	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.	166	\$92.50	\$15,355.00
	0930	PILE POINT REINFORCEMENT	Material			-7	\$95.00	(\$665.00
	0930	PILE POINT REINFORCEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.	7	\$95.00	\$665.00
	1080	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-3,096	\$65.75	(\$203,562.00
	1080	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.	3,096	\$65.75	\$203,562.00
	5004	WATER	Material			-80,458.9	\$1.00	(\$80,458.90
	5004	WATER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.	80,458.9	\$1.00	\$80,458.90
otal								\$0.00

Revision 4/1/2020 Page 2 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4S3218	FAS S301(72)	Bridge replacement	Blue Ridge Boulevard	JACKSON	over Route 78		
Totals by J	Job Numbe	rs					
J4S3218		d Item Pay Item Adjustm	ents Gross Ite	m Pay	This Estimate \$220,982.00 \$0.00 \$220,982.00	Previous \$509,508.89 \$315,794.88 \$825,303.77	To Date \$730,490.89 \$315,794.88 \$1,046,285.77
	Liquid	tive centive lated Damages Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 3 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4S3218, Item 6039902, Project Item Line Number 5004, Material Set 603990296, Material 0603WL - Material for Waterline, Acceptance Action Generic 0603WL is insufficient.	Waterline relocation was field inspected by MoDOT and the KC Water Department at the time of incorporation into the project. QA and QC staff are working on a resolution to the exception. frizzm 1/18/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3218, Item 6085008, Project Item Line Number 0160, Material Set 608500896, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Paved approach was field inspected at the time of placement. QA and QC staff are working on a resolution to the exception. frizzm 1/18/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3218, Item 6085008, Project Item Line Number 0160, Material Set 608500896, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Paved approach was field inspected at the time of placement. QA and QC staff are working on a resolution to the exception. frizzm 1/18/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3218, Item 7021212, Project Item Line Number 0910, Material Set 702121296, Material 0702PLSSMAZC - Bearing Piles Struct Steel Galvd, Acceptance Action Generic 0702PLSSMAZC is insufficient.	Galvanized pile was field inspected at the time of placement. QA and QC staff are working on a resolution to the exception. frizzm 1/18/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3218, Item 7027000, Project Item Line Number 0930, Material Set 702700096, Material 0702PLPT - Pile Point Reinforcement, Acceptance Action Generic 0702PLPT is insufficient.	Pile points were field inspected at the time of placement. QA and QC staff are working on a resolution to the exception. frizzm 1/18/21.P	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3218, Item 7201000, Project Item Line Number 1080, Material Set 720100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	MSE Walls were field inspected at the time of placement. QA and QC staff are working on a resolution to the exception. frizzm 1/18/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3218, Item 7201000, Project Item Line Number 1080, Material Set 720100096, Material 1052MSEWMETF - Metallic Fasteners for MSE soil reinforc, Acceptance Action Generic 1052MSEWMETF is insufficient.	MSE Walls were field inspected at the time of placement. QA and QC staff are working on a resolution to the exception. frizzm 1/18/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3218, Item 7201000, Project Item Line Number 1080, Material Set 720100096, Material 1052MSEWMETS - Metalic Reinforcement Strips for MSE, Acceptance Action Generic 1052MSEWMETS is insufficient.	MSE Walls were field inspected at the time of placement. QA and QC staff are working on a resolution to the exception. frizzm 1/18/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3218, Item 7201000, Project Item Line Number 1080, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	MSE Walls were field inspected at the time of placement. QA and QC staff are working on a resolution to the exception. frizzm 1/18/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3218, Item 7250315A, Project Item Line Number 0460, Material Set 7250315A96, Material 1020CPCSAC0015 - CulvPipe Al Ctd Corrug Stl 15" 375mm, Acceptance Action Generic 1020CPCSAC0015 is insufficient.	Drainage pipe was field inspected at the time of placement. QA and QC staff are working on a resolution to the exception. frizzm 1/18/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3218, Item 7250415, Project Item Line Number 0470, Material Set 725041596, Material 1020CPCSZC.015 - CulvPipe Zn Ctd Corrug Stl 15" 375mm, Acceptance Action Generic 1020CPCSZC.015 is insufficient.	Drainage pipe was field inspected at the time of placement. QA and QC staff are working on a resolution to the exception. frizzm 1/18/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3218, Item 8051000A, Project Item Line Number 0540, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Seeding was field inspected at the time of placement. QA and QC staff are working on a resolution to the exception. frizzm 1/18/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3218, Item 8051000A, Project Item Line Number 0540, Material Set 8051000A96, Material 0802MLSP - Overspray Slick Paper, Acceptance Action Generic 0802MLSP is insufficient.	Seeding was field inspected at the time of placement. QA and QC staff are working on a resolution to the exception. frizzm 1/18/21.	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3218, Item 8051000A, Project Item Line Number 0540, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	Seeding was field inspected at the time of placement. QA and QC staff are working on a resolution to the exception. frizzm 1/18/21.	frizzm	Overridden

Revision 4/1/2020 Page 4 of 18



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted ame Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-C06	J4S3218	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.35	\$53,000.00	\$18,550.00
		0001	0020	2035000	UNCLASSIFIED EXCAVATION	3,081.00	0.00	3,081.00	CUYD	916.50	\$22.00	\$20,163.00
		0001	0030	2036000	COMPACTING EMBANKMENT	1,574.00	0.00	1,574.00	CUYD	98.00	\$4.60	\$450.80
		0001	0040	2037075	COMPACTING IN CUT	4.40	0.00	4.40	STA	1.30	\$2,000.00	\$2,600.00
		0001	0050	2063000	CLASS 3 EXCAVATION	346.00	0.00	346.00	CUYD	183.00	\$23.50	\$4,300.50
		0001	0060	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	4,503.00	0.00	4,503.00	SQYD	1,320.22	\$12.50	\$16,502.75
		0001	0070	4019905	MISC.OPTIONAL PAVEMENT - MAINLINE	3,841.70	0.00	3,841.70	SQYD	1,012.35	\$48.75	\$49,352.06
		0001	0080	4019905	MISC.OPTIONAL PAVEMENT - ROUTE 78	64.00	0.00	64.00	SQYD	0.00	\$330.00	\$0.00
		0001	0090	4019905	MISC.OPTIONAL PAVEMENT SHOULDER	290.30	0.00	290.30	SQYD	45.30	\$42.00	\$1,902.60
		0001	0100	4030001	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP095C MIX)	241.60	0.00	241.60	TONS	0.00	\$145.00	\$0.00
		0001	0110	4079912	MISC.TACK COAT - LOW-TRACKING OR NON-TRACKING	606.00	0.00	606.00	GAL	0.00	\$4.25	\$0.00
		0001	0120	6071050	CHAIN-LINK FENCE (RETAINING WALLS)	281.00	0.00	281.00	LF	0.00	\$46.00	\$0.00
		0001	0130	6071102	MODIFIED CONCRETE GUTTER TYPE B	281.00	0.00	281.00	LF	0.00	\$48.00	\$0.00
		0001	0140	6081000	CONCRETE MEDIAN	161.20	0.00	161.20	SQYD	0.00	\$74.00	\$0.00
		0001	0150	6085007	PAVED APPROACH, 7 IN.	146.30	0.00	146.30	SQYD	0.00	\$87.00	\$0.00
		0001	0160	6085008	PAVED APPROACH, 8 IN.	68.10	0.00	68.10	SQYD	68.10	\$87.00	\$5,924.70
		0001	0170	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	99.00	6.00	105.00	LF	105.00	\$26.00	\$2,730.00
		0001	0180	6091052	CURB AND GUTTER TYPE B	40.00	0.00	40.00	LF	0.00	\$50.00	\$0.00
		0001	0190	6097000	ROCK LINING	14.00	0.00	14.00	CUYD	0.00	\$126.00	\$0.00
		0001	0200	6099903	MISC.CURB AND GUTTER APWA TYPE CG-1	342.00	0.00	342.00	LF	0.00	\$41.00	\$0.00
		0001	0210	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	2.00	\$2,100.00	\$4,200.00
		0001	0220	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	EA	0.00	\$800.00	\$0.00
		0001	0230	6141021	GRATE AND BEARING PLATE (3 FT. X 2 FT. OR 914 MM X 610	1.00	0.00	1.00	EA	0.00	\$1,300.00	\$0.00
		0001	0240	6141024	MM) GRATE AND BEARING PLATE (5 FT. X 3 FT. OR 1524 MM X 914 MM)	1.00	0.00	1.00	EA	1.00	\$1,950.00	\$1,950.00
		0001	0250	6143013	MANHOLE FRAME AND COVER, TYPE 3	1.00	0.00	1.00	EA	1.00	\$295.00	\$295.00
		0001	0260	6161005	CONSTRUCTION SIGNS	826.00	0.00	826.00	SQFT	767.00	\$4.00	\$3,068.00
		0001	0270	6161008	ADVANCED WARNING RAIL SYSTEM	3.00	0.00	3.00	EA	0.00	\$50.00	\$0.00
		0001	0280	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	3.00	\$20.00	\$60.00
		0001	0290	6161025	CHANNELIZER (TRIM LINE)	51.00	75.00	126.00	EA	126.00	\$33.00	\$4,158.00
		0001	0300	6161030	TYPE III MOVEABLE BARRICADE	29.00	0.00	29.00	EA	27.00	\$165.00	\$4,455.00
		0001	0305	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$2,100.00	\$4,200.00
		0001	0310	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$6,300.00	\$12,600.00
		0001	0320	6169902	MISC.ADA COMPLIANT MOVEABLE BARRICADE	2.00	0.00	2.00	EA	0.00	\$100.00	\$0.00
		0001	0330	6172000	CONCRETE TRAFFIC BARRIER, TYPE B	150.00	0.00	150.00	LF	0.00	\$162.00	\$0.00
		0001	0340	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	60.00	432.00	492.00	LF	492.00	\$40.00	\$19,680.00
		0001	0350	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$236,000.00	\$0.00
		0001	0351	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.50	\$224,819.00	\$112,409.50
		0001	0360	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	2.00	\$600.00	\$1,200.00
		0001	0370	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.00
		0001	0380	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	2,950.00	0.00	2,950.00	LF	0.00	\$1.20	\$0.00
		0001	0390	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	650.00	0.00	650.00	LF	0.00	\$1.00	\$0.00
		0001	0400		4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	2,454.00	0.00	2,454.00	LF LF	0.00	\$0.06	\$0.00
		0001	0410	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	3,652.00	0.00	3,652.00		0.00	\$0.06	\$0.00
		0001	0420	6206125A	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	21.00	0.00	21.00	LF	0.00	\$10.00	\$0.00

Page 5 of 18 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-C06	J4S3218	0001	0430	6207001	PAVEMENT MARKING REMOVAL	3,410.00	0.00	3,410.00	LF	0.00	\$0.50	\$0.00
		0001	0440	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	3,034.00	0.00	3,034.00	SQYD	0.00	\$5.30	\$0.00
		0001	0450	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$13,000.00	\$0.00
		0001	0460	7250315A	15 IN. PIPE GROUP B	396.00	0.00	396.00	LF	195.00	\$52.00	\$10,140.00
		0001	0470	7250415	15 IN. PIPE GROUP C	33.00	0.00	33.00	LF	33.00	\$57.00	\$1,881.00
		0001	0480	7310060	PRECAST CONCRETE MANHOLE - 60 IN.	9.00	0.00	9.00	FT	9.00	\$990.00	\$8,910.00
		0001	0490	7311033	PRECAST CONCRETE DROP INLET 3 FT X 3 FT	4.00	0.00	4.00	FT	0.00	\$1,180.00	\$0.00
		0001	0500	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	7.00	0.00	7.00	FT	7.00	\$835.00	\$5,845.00
		0001	0510	7319902	MISC.DROP INLET CLEANOUT	5.00	0.00	5.00	EA	0.00	\$835.00	\$0.00
		0001	0520	7320015A	15 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	3.00	0.00	3.00	EA	1.00	\$785.00	\$785.00
		0001	0530	7320815A	15 IN, OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$945.00	\$1,890.00
		0001	0540	8051000A	SEEDING - COOL SEASON MIXTURES	1.20	0.00	1.20	ACRE	0.40	\$3,170.00	\$1,277.51
		0001	0550	8061005	ROCK DITCH CHECK	24.00	0.00	24.00	LF	0.00	\$50.00	\$0.00
		0001	0560	8061006	ALTERNATE DITCH CHECK	348.00	0.00	348.00	LF	53.25	\$8.00	\$426.00
		0001	0570	8061007A	CURB INLET CHECK	5.00	1.00	6.00	EA	6.00	\$85.00	\$510.00
		0001	0580	8061016	SEDIMENT REMOVAL	42.00	0.00	42.00	CUYD	0.00	\$10.00	\$0.00
		0001	0590	8061017	TEMPORARY SEEDING AND MULCHING	0.20	0.00	0.20	ACRE	0.00	\$7,500.00	\$0.00
		0001	0600	8061019	SILT FENCE	605.00	499.00	1,104.00	LF	1,104.00	\$2.00	\$2,208.00
		0001	0610	8064129	TYPE 2 TURF REINFORCEMENT MAT	469.00	0.00	469.00	SQYD	300.00	\$5.00	\$1,500.00
		0001	0620	8064140	TYPE 3B EROSION CONTROL BLANKET	652.00	0.00	652.00	SQYD	127.00	\$3.50	\$444.50
		0010	0630	6061060	MGS GUARDRAIL	350.00	0.00	350.00	LF	0.00	\$21.00	\$0.00
		0010	0640	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	2.00	0.00	2.00	EA	0.00	\$2,726.00	\$0.00
		0010	0650	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	0.00	\$2,734.00	\$0.00
		0020	0660	9019902	MISC.CABLE RETAINER	6.00	0.00	6.00	EA	0.00	\$430.00	\$0.00
		0020	0670	9019902	MISC.CONCRETE POLE FOUNDATION	4.00	0.00	4.00	EA	0.00	\$1,540.00	\$0.00
		0020	0680	9019902	MISC.FUSEHOLDER	16.00	2.00	18.00	EA	0.00	\$93.13	\$0.00
		0020	0690	9019902	MISC.LED LUMINAIRE, KCMO TYPE B	1.00	0.00	1.00	EA	0.00	\$420.00	\$0.00
		0020	0700	9019902	MISC.LED LUMINAIRE, KCMO TYPE C	3.00	0.00	3.00	EA	0.00	\$606.67	\$0.00
		0020	0710	9019902	MISC.LED LUMINAIRE, KCMO TYPE D	2.00	0.00	2.00	EA	0.00	\$715.00	\$0.00
		0020	0720	9019902	MISC.LED LUMINAIRE, KCMO WALL MOUNTED	2.00	0.00	2.00	EA	0.00	\$1,230.00	\$0.00
		0020	0730	9019902	MISC.LIGHT POLE, 30 FT. M.H., 6 FT. BRACKET ARM	4.00	0.00	4.00	EA	0.00	\$2,045.00	\$0.00
		0020	0740	9019902	MISC.PULL BOX, TYPE II	5.00	0.00	5.00	EA	0.00	\$810.00	\$0.00
		0020	0750	9019902	MISC.RELOCATE EXISTING LIGHT POLE ASSEMBLY	1.00	0.00	1.00	EA	0.00	\$2,010.00	\$0.00
		0020	0760	9019903	MISC.CABLE, #6 AWG	3,600.00	825.00	4,425.00	LF	0.00	\$1.84	\$0.00
		0020	0770	9019903	MISC.CABLE, POLE AND BRACKET, #10 AWG	700.00	0.00	700.00	LF	0.00	\$1.04	\$0.00
		0020	0780	9019903	MISC.CONDUIT, 1" PVC, TRENCHED	20.00	0.00	20.00	LF	0.00	\$24.00	\$0.00
		0020	0790	9019903	MISC.CONDUIT, 2 IN. PVC, PUSHED	50.00	250.00	300.00	LF	0.00	\$34.40	\$0.00
		0020	0800	9019903	MISC.CONDUIT, 2 IN. PVC, TRENCHED	900.00	0.00	900.00	LF	0.00	\$18.56	\$0.00
		0040	0810	9031010	CONCRETE FOOTINGS, EMBEDDED	1.50	0.00	1.50	CUYD	0.00	\$1,027.00	\$0.00
		0040	0820	9031210	STRUCTURAL STEEL POSTS	170.00	0.00	170.00	LB	0.00	\$6.50	\$0.00
		0040	0830	9031220	PIPE POSTS	860.00	0.00	860.00	LB	0.00	\$4.70	\$0.00
		0040	0840	9031270A	2 IN. PSST POST - 12 GA.	56.00	0.00	56.00	LF	0.00	\$16.00	\$0.00
		0040	0850	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	15.00	0.00	15.00	LF	0.00	\$19.00	\$0.00
		0040	0860	9035004A	SH-FLAT SHEET	133.00	0.00	133.00	SQFT	0.00	\$23.00	\$0.00
		0040	0870	9039902	MISC.RELOCATION OF EXISTING SIGN ASSEMBLIES	1.00	0.00	1.00	EA	0.00	\$245.00	\$0.00

Page 6 of 18 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
00117-C06	J4S3218	0070	0880	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$85,000.00	\$85,000.00
		0070	0895	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	218.00	0.00	218.00	SQYD	0.00	\$195.00	\$0.00
		0070	0900	6071060	PEDESTRIAN FENCE (STRUCTURES)	88.00	0.00	88.00	LF	0.00	\$105.00	\$0.00
		0070	0910	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	322.00	0.00	322.00	LF	166.00	\$92.50	\$15,355.00
		0070	0920	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	1.00	\$1,400.00	\$1,400.00
		0070	0930	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	7.00	\$95.00	\$665.00
		0070	0940	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	38.40	0.00	38.40	CUYD	0.00	\$1,070.00	\$0.00
		0070	0950	7034215	SAFETY BARRIER CURB	178.00	0.00	178.00	LF	0.00	\$175.00	\$0.00
		0070	0960	7034222	SLAB ON CONCRETE BEAM	509.00	0.00	509.00	SQYD	0.00	\$363.00	\$0.00
		0070	0970	7056050A	27 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	609.00	0.00	609.00	LF	0.00	\$362.00	\$0.00
		0070	0980	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	0.00	\$8,500.00	\$0.00
		0070	0990	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$3,400.00	\$0.00
		0070	1000	7161000	PLAIN NEOPRENE BEARING PAD	7.00	0.00	7.00	EA	0.00	\$285.00	\$0.00
		0070	1010	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	7.00	0.00	7.00	EA	0.00	\$395.00	\$0.00
		0070	1020	7201300	PIPE PILE SPACERS	14.00	0.00	14.00	EA	7.00	\$0.01	\$0.07
		0071	1030	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$2,211.98	\$0.00
		0071	1040	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$2,211.98	\$0.00
		0071	1050	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	2,519.00	0.00	2,519.00	SQFT	0.00	\$65.75	\$0.00
		0072	1060	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$2,718.65	\$0.00
		0072	1070	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$2,718.65	\$0.00
		0072	1080	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	3,096.00	0.00	3,096.00	SQFT	3,096.00	\$65.75	\$203,562.00
		0001	5001	6189901	MISC.Bond	0.00	1.00	1.00	LS	1.00	\$11,181.00	\$11,181.00
		0001	5002	2029901	MISC.Asbestos Abatement	0.00	1.00	1.00	LS	1.00	\$6,300.00	\$6,300.00
		0020	5003	9019902	MISC.Waterproof Connectors	0.00	2.00	2.00	EA	0.00	\$124.69	\$0.00
	0001 5004 6039902 WATER 0.00 80,458.90								EA	80,458.90	\$1.00	\$80,458.90
	Project J	4S3218 - To	otal Value	Posted to D	ate as of Report Generated Date							\$730,490.89
117-C06 Ove	rall - Total	Value Post	ted to Da	te as of Repo	ort Generated Date							\$730,490.89

Page 7 of 18 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4S3218

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0910	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN	1/14/21	1/18/21	166.00	LF	Br. A8774 bent 2, Blue Ridge Blvd.	Sta. 120+44.33				
0920	7025001	DYNAMIC PILE TESTING	1/14/21	1/18/21	1.00	EA	Bridge A8774 bent 2, Blue ridge Blvd	Sta. 120+44.33				
0930	7027000	PILE POINT REINFORCEMENT	1/14/21	1/18/21	7.00	EA	Bridge A8774 bent 2, Blue Ridge Blvd.	Sta. 120+44.33				
1080	7201000	MECHANICALLY STABILIZED EARTH WALL SYS	1/11/21	1/18/21	3,096.00	SQFT	MSE Wall A8778	Sta. 30+41.04				

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 8 of 18



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		Туре	Adjustment Type	Number	Date	Ву		
0020	UNCLASSIFIED EXCAVATION	Price		7	Jul 6, 2020	SYSTEM	(\$96.62)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				9	Sep 30, 2020	SYSTEM	(\$32.71)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				11	Dec 16, 2020	SYSTEM	(\$59.15)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$188.48)	
	Price - Total						(\$188.48)	
0020 -	- Total						(\$188.48)	
0030	COMPACTING EMBANKMENT	Material		7	Jul 6, 2020	SYSTEM	(\$450.80)	
				7	Jul 6, 2020	SYSTEM	\$450.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user slaglv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				8	Jul 17, 2020	SYSTEM	(\$450.80)	
			- Total				(\$450.80)	
	Material - Total						(\$450.80)	
	COMPACTING EMBANKMENT	MaterialCredit		9	Sep 30, 2020	SYSTEM	\$450.80	
			- Total				\$450.80	
	MaterialCredit - Total						\$450.80	
0030 -	- Total						\$0.00	
0040	COMPACTING IN CUT	Material		7	Jul 6, 2020	SYSTEM	(\$2,600.00)	
				7	Jul 6, 2020	SYSTEM	\$2,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user slaglv1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				8	Jul 17, 2020	SYSTEM	(\$2,600.00)	
			- Total				(\$2,600.00)	
	Material - Total						(\$2,600.00)	
	COMPACTING IN CUT	MaterialCredit		9	Sep 30, 2020	SYSTEM	\$2,600.00	
			- Total				\$2,600.00	
	MaterialCredit - Total						\$2,600.00	
	- Total						\$0.00	
0060	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		7	Jul 6, 2020	SYSTEM	(\$850.00)	
				7	Jul 6, 2020	SYSTEM	\$850.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user slaglv1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				8	Jul 17, 2020	SYSTEM	(\$16,502.75)	
				8	Jul 17, 2020	SYSTEM	\$16,502.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user slaglv1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		7	Jul 6, 2020	SYSTEM	(\$14.86)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				8	Jul 17, 2020	SYSTEM	(\$273.61)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$288.47)	
	Price - Total						(\$288.47)	
0060	- Total						(\$288.47)	
0070	MISC. OPTIONAL PAVEMENT - MAINLINE	Other Item Adjustment	ACAD	8	Jul 17, 2020	slaglv1	(\$1,096.18)	ACPA for asphalt laid between 6/16/2020 and 6/30/2020

Revision 4/1/2020 Page 9 of 18



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0070		Other Item Adjustment	ACAD - Tota	al			(\$1,096.18)	
	Other Item Adjustment - Total						(\$1,096.18)	
0070 -	Total						(\$1,096.18)	
0090	MISC. OPTIONAL PAVEMENT SHOULDER		ACAD	8	Jul 17, 2020	slaglv1	(\$28.21)	ACPA for asphalt between 6/16/2020 and 6/30/2020
			ACAD - Tota	al			(\$28.21)	
	Other Item Adjustment - Total						(\$28.21)	
0090 -	Total						(\$28.21)	
0160	PAVED APPROACH, 8 IN.	Material		7	Jul 6, 2020	SYSTEM	(\$5,924.70)	
				7	Jul 6, 2020	SYSTEM	\$5,924.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user slaglv1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				8	Jul 17, 2020	SYSTEM	(\$5,924.70)	
				8	Jul 17, 2020	SYSTEM	\$5,924.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user slaglv1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				9	Sep 30, 2020	SYSTEM	(\$5,924.70)	
				9	Sep 30, 2020	SYSTEM	\$5,924.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user slaglv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				10	Oct 16, 2020	SYSTEM	(\$5,924.70)	
				10	Oct 16, 2020	SYSTEM	\$5,924.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user slaglv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				11	Dec 16, 2020	SYSTEM	(\$5,924.70)	
				11	Dec 16, 2020	SYSTEM	\$5,924.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate.
				12	Jan 4, 2021	SYSTEM	(\$5,924.70)	
				12	Jan 4, 2021	SYSTEM	\$5,924.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brookw1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				13	Jan 18, 2021	SYSTEM	(\$5,924.70)	
				13	Jan 18, 2021	SYSTEM	\$5,924.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	PAVED APPROACH, 8 IN.	Price		7	Jul 6, 2020	SYSTEM	(\$38.82)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			- Total				(\$38.82)	
	Price - Total						(\$38.82)	
0160 -	Total						(\$38.82)	
0170	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material		7	Jul 6, 2020	SYSTEM	(\$2,730.00)	
				7	Jul 6, 2020	SYSTEM	\$2,730.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user slaglv1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
				8	Jul 17, 2020	SYSTEM	(\$2,730.00)	

Revision 4/1/2020 Page 10 of 18



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0170	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Material		9	Sep 30, 2020	SYSTEM	(\$2,730.00)	
				9	Sep 30, 2020	SYSTEM	\$2,730.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user slaglv1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				(\$2,730.00)	
	Material - Total						(\$2,730.00)	
	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	MaterialCredit		9	Sep 30, 2020	SYSTEM	\$2,730.00	
			- Total				\$2,730.00	
	MaterialCredit - Total						\$2,730.00	
	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Other Item Adjustment	OVRN	7	Jul 6, 2020	slaglv1	(\$156.00)	Both a material exception and overrun exist so the system cancels both when the exception is overridden instead of withholding pay for the overrun quantity. This adjustment removes the payment for the overrun quantity.
				8	Jul 17, 2020	SYSTEM	\$156.00	Both a material exception and overrun exist so the system cancels both when the exception is overridden instead of withholding pay for the overrun quantity. This adjustment removes the payment for the overrun quantity.
			OVRN - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	Overrun	Overrun		Jul 6, 2020	SYSTEM	(\$156.00)	
				7	Jul 6, 2020	SYSTEM	\$156.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 17 on the current Payment Estimate.
				8	Jul 17, 2020	SYSTEM	(\$156.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				8	Jul 17, 2020	SYSTEM	\$156.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 23 on the current Payment Estimate.
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0170 -	Total						\$0.00	
0210	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	Material		3	May 4, 2020	SYSTEM	(\$4,200.00)	
				3	May 4, 2020	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user slaglv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0210 -	Total						\$0.00	
0240	GRATE AND BEARING PLATE (5 FT. X 3 FT. OR 1524 MM X 914 MM)	Material		6	Jun 16, 2020	SYSTEM	(\$1,950.00)	
				6	Jun 16, 2020	SYSTEM	\$1,950.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user slaglv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0240 -	Total						\$0.00	
0250	MANHOLE FRAME AND COVER, TYPE 3	Material		6	Jun 16, 2020	SYSTEM	(\$295.00)	
				6	Jun 16, 2020	SYSTEM	\$295.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user slaglv1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0250 -	Total						\$0.00	
0260	CONSTRUCTION SIGNS	Material		3	May 4, 2020	SYSTEM	(\$3,068.00)	

Revision 4/1/2020 Page 11 of 18



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0260	CONSTRUCTION SIGNS	Material		3	May 4, 2020	SYSTEM	\$3,068.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user slaglv1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0260 -	· Total						\$0.00	
0280	FLAG ASSEMBLY	Material		3	May 4, 2020	SYSTEM	(\$60.00)	
				3	May 4, 2020	SYSTEM	\$60.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user slaglv1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0280 -	l · Total						\$0.00	
0290	CHANNELIZER (TRIM LINE)	Overrun	Overrun	4	May 18, 2020	SYSTEM	(\$627.00)	
				9	Sep 30, 2020	SYSTEM	\$627.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',33.00000 - 33.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0290 -							\$0.00	
0300	TYPE III MOVEABLE BARRICADE	Material		3	May 4, 2020	SYSTEM	(\$4,455.00)	
				3	May 4, 2020	SYSTEM	\$4,455.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user slaglv1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0300 -							\$0.00	
0305	FLASHING ARROW PANEL	Material		3	May 4, 2020	SYSTEM	(\$4,200.00)	
				3	May 4, 2020	SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user slaglv1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0305 -	· Total						\$0.00	
0310	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE,	Material		2	Apr 16, 2020	SYSTEM	(\$12,600.00)	
	CONTRACTOR FURNISHED, CONTRACTOR RETAINED			2	Apr 16, 2020	SYSTEM	\$12,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user ngugis1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				3	May 4, 2020	SYSTEM	(\$12,600.00)	
			- Total				(\$12,600.00)	
	Material - Total						(\$12,600.00)	
	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	MaterialCredit		4	May 18, 2020	SYSTEM	\$12,600.00	
			- Total				\$12,600.00	
	MaterialCredit - Total						\$12,600.00	
0310 -	· Total						\$0.00	
0340	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED /	Material		3	May 4, 2020	SYSTEM	(\$19,680.00)	
	RETAINED			3	May 4, 2020	SYSTEM	\$19,680.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user slaglv1 overridding Payment Estimate Exception 7 on the current Payment

Revision 4/1/2020 Page 12 of 18



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0340	TEMPORARY TRAFFIC BARRIER,	Material						Estimate.
	CONTRACTOR FURNISHED / RETAINED			4	May 18, 2020	SYSTEM	(\$19,680.00)	
				5	Jun 3, 2020	SYSTEM	(\$19,680.00)	
				5	Jun 3, 2020	SYSTEM	\$19,680.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user slaglv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				(\$19,680.00)	
	Material - Total						(\$19,680.00)	
	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	MaterialCredit		5	Jun 3, 2020	SYSTEM	\$19,680.00	
			- Total				\$19,680.00	
	MaterialCredit - Total						\$19,680.00	
	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Other Item Adjustment	OVRN	3	May 4, 2020	slaglv1	(\$17,280.00)	The system generated material adjustment resulted in the system removing the overrun adjustment. This adjustment removes the pay for the overrun quantity until the change order is approved.
				4	May 18, 2020	SYSTEM	\$17,280.00	The system generated material adjustment resulted in the system removing the overrun adjustment. This adjustment removes the pay for the overrun quantity until the change order is approved.
			OVRN - Tota	al			\$0.00	
	Other Item Adjustment - Total						\$0.00	
	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	Overrun	Overrun	3	May 4, 2020	SYSTEM	\$17,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 10 on the current Payment Estimate.
				3	May 4, 2020	SYSTEM	(\$17,280.00)	
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0340 -	Overrun - Total - Total						\$0.00 \$0.00	
0340 - 0460	- Total	Material		6	Jun 16, 2020	SYSTEM		
	- Total	Material		6		SYSTEM SYSTEM	\$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user slaglv1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
	- Total	Material			2020 Jun 16,		\$0.00 (\$10,140.00)	Payment Estimate Item Adjustment (0003) due to user slagIv1 overridding Payment Estimate Exception 3 on the current Payment
	- Total	Material		6	2020 Jun 16, 2020 Jul 6,	SYSTEM	\$0.00 (\$10,140.00) \$10,140.00	Payment Estimate Item Adjustment (0003) due to user slagIv1 overridding Payment Estimate Exception 3 on the current Payment
	- Total	Material		7	2020 Jun 16, 2020 Jul 6, 2020 Jul 6,	SYSTEM	\$0.00 (\$10,140.00) \$10,140.00 (\$10,140.00)	Payment Estimate Item Adjustment (0003) due to user slaglv1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user slaglv1 overridding Payment Estimate Exception 12 on the current
	- Total	Material		6 7 7 8 9	2020 Jun 16, 2020 Jul 6, 2020 Jul 6, 2020 Jul 17, 2020 Sep 30, 2020	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$10,140.00) \$10,140.00 (\$10,140.00) \$10,140.00 (\$10,140.00)	Payment Estimate Item Adjustment (0003) due to user slaglv1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user slaglv1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
	- Total	Material		7 7 8	2020 Jun 16, 2020 Jul 6, 2020 Jul 6, 2020 Jul 17, 2020 Sep 30,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$10,140.00) \$10,140.00 (\$10,140.00) \$10,140.00	Payment Estimate Item Adjustment (0003) due to user slaglv1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user slaglv1 overridding Payment Estimate Exception 12 on the current
	- Total	Material		6 7 7 8 9	2020 Jun 16, 2020 Jul 6, 2020 Jul 6, 2020 Jul 6, 2020 Jul 17, 2020 Sep 30, 2020 Sep 30,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$10,140.00) \$10,140.00 (\$10,140.00) \$10,140.00 (\$10,140.00)	Payment Estimate Item Adjustment (0003) due to user slaglv1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user slaglv1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user slaglv1 overridding Payment Estimate Exception 6 on the current Payment
	- Total	Material		6 7 7 8 9	2020 Jun 16, 2020 Jul 6, 2020 Jul 6, 2020 Jul 7, 2020 Sep 30, 2020 Oct 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$10,140.00) \$10,140.00 (\$10,140.00) \$10,140.00 (\$10,140.00) \$10,140.00	Payment Estimate Item Adjustment (0003) due to user slaglv1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user slaglv1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user slaglv1 overridding Payment Estimate Exception 6 on the current Payment
	- Total	Material		6 7 7 7 8 8 9 9 10	2020 Jun 16, 2020 Jul 6, 2020 Jul 6, 2020 Jul 7, 2020 Sep 30, 2020 Oct 16, 2020 Oct 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$10,140.00) \$10,140.00 (\$10,140.00) (\$10,140.00) (\$10,140.00) (\$10,140.00)	Payment Estimate Item Adjustment (0003) due to user slaglv1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user slaglv1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user slaglv1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user slaglv1 overridding Payment Estimate Item Adjustment (0002) due to user slaglv1 overridding Payment Estimate Exception 4 on the current Payment
	- Total	Material		6 7 7 8 9 9	2020 Jun 16, 2020 Jul 6, 2020 Jul 6, 2020 Jul 7, 2020 Sep 30, 2020 Oct 16, 2020 Oct 16, 2020 Dec 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$10,140.00) \$10,140.00 (\$10,140.00) (\$10,140.00) (\$10,140.00) (\$10,140.00) (\$10,140.00)	Payment Estimate Item Adjustment (0003) due to user slaglv1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user slaglv1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user slaglv1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user slaglv1 overridding Payment Estimate Item Adjustment (0002) due to user slaglv1 overridding Payment Estimate Exception 4 on the current Payment

Revision 4/1/2020 Page 13 of 18



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0460	15 IN. PIPE GROUP B	Material	.,,,,	12	Jan 4, 2021	SYSTEM	\$10,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user brookw1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				13	Jan 18, 2021	SYSTEM	(\$10,140.00)	
				13	Jan 18, 2021	SYSTEM	\$10,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.
			- Total				(\$10,140.00)	
	Material - Total				0 00	OVOTEM	(\$10,140.00)	
	15 IN. PIPE GROUP B	MaterialCredit		9	Sep 30, 2020	SYSTEM	\$10,140.00	
	Manufal Over 116 Table		- Total				\$10,140.00	
0460 -	MaterialCredit - Total						\$10,140.00 \$0.00	
0470	15 IN. PIPE GROUP C	Material		6	Jun 16, 2020	SYSTEM	(\$1,881.00)	
				6	Jun 16, 2020	SYSTEM	\$1,881.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user slaglv1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				7	Jul 6, 2020	SYSTEM	(\$1,881.00)	
				7	Jul 6, 2020	SYSTEM	\$1,881.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user slaglv1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				8	Jul 17, 2020	SYSTEM	(\$1,881.00)	
				9	Sep 30, 2020	SYSTEM	(\$1,881.00)	
				9	Sep 30, 2020	SYSTEM	\$1,881.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user slaglv1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				10	Oct 16, 2020	SYSTEM	(\$1,881.00)	
				10	Oct 16, 2020	SYSTEM	\$1,881.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user slaglv1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				11	Dec 16, 2020	SYSTEM	(\$1,881.00)	
				11	Dec 16, 2020	SYSTEM	\$1,881.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.
				12	Jan 4, 2021	SYSTEM	(\$1,881.00)	
				12	Jan 4, 2021	SYSTEM	\$1,881.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brookw1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				13	Jan 18, 2021	SYSTEM	(\$1,881.00)	
				13	Jan 18, 2021	SYSTEM	\$1,881.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				(\$1,881.00)	
	Material - Total					01/05	(\$1,881.00)	
	15 IN. PIPE GROUP C	MaterialCredit		9	Sep 30, 2020	SYSTEM	\$1,881.00	
			- Total				\$1,881.00	
	MaterialCredit - Total						\$1,881.00	

Revision 4/1/2020 Page 14 of 18



Marie September Septembe	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
Fig. 2, ST	0470 -	Total						\$0.00	
2000	0500		Material		6		SYSTEM	(\$5,845.00)	
200					6		SYSTEM	\$5,845.00	Payment Estimate Item Adjustment (0005) due to user slagIv1 overridding Payment Estimate Exception 5 on the current Payment
Page					7		SYSTEM	(\$5,845.00)	
					7		SYSTEM	\$5,845.00	Payment Estimate Item Adjustment (0012) due to user slagIv1 overridding Payment Estimate Exception 14 on the current
Material - Total					8		SYSTEM	(\$5,845.00)	
PRECAST CONCRETE DROP INLET 6 FY X 3 FT Material Credit Total September Septem				- Total				(\$5,845.00)	
Total Tota		Material - Total						(\$5,845.00)	
Material Credit - Total S.5.845.00			MaterialCredit		9		SYSTEM	\$5,845.00	
15 N. OR ALLOWED SUBSTITUTE Material				- Total				\$5,845.00	
15 IN OR ALLOWED SUBSTITUTE Material		MaterialCredit - Total						\$5,845.00	
STATE STAT	0500 -	· Total						\$0.00	
2020 Payment Estimate Item Adjustment (0006) due to user slagivit overridding Payment Estimate Exception 6 on the current Payment Estimate. 7	0520		Material		6		SYSTEM	(\$785.00)	
2020					6		SYSTEM	\$785.00	Payment Estimate Item Adjustment (0006) due to user slagIv1 overridding Payment Estimate Exception 6 on the current Payment
2020 Payment Estimate Item Adjustment (013) due to user slaght overridding Payment Estimate Exception 15 on the current Payment Estimate Exception 15 on the current Payment Estimate.					7		SYSTEM	(\$785.00)	
Material - Total					7		SYSTEM	\$785.00	Payment Estimate Item Adjustment (0013) due to user slagIv1 overridding Payment Estimate Exception 15 on the current
Material - Total 15 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION MaterialCredit GROUP B FLARED END SECTION -Total 5785.00					8		SYSTEM	(\$785.00)	
15 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION				- Total				(\$785.00)	
STATE STAT		Material - Total						(\$785.00)	
Material Credit - Total \$785.00			MaterialCredit		9		SYSTEM	\$785.00	
15 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION 6 Jun 16, 2020 SYSTEM S1,890.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user slagly1 overridding Payment Estimate Exception 7 on the current Payment Estimate. 7 Jul 6, 2020 SYSTEM S1,890.00 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user slagly1 overridding Payment Estimate Item Adjustment (014) due to user slagly1 overridding Payment Estimate Item Adjustment (014) due to user slagly1 overridding Payment Estimate Item Adjustment (014) due to user slagly1 overridding Payment Estimate Item Adjustment (014) due to user slagly1 overridding Payment Estimate Item Adjustment (014) due to user slagly1 overridding Payment Estimate Item Adjustment (014) due to user slagly1 overridding Payment Estimate Item Adjustment forests the original system-generated Overrun Payment Estimate Item Adjustment (014) due to user slagly1 overridding Payment Estimate Item Adjustment offsets the original system-generated Overrun Payment Estimate. S1,890.00 SYSTEM S1,89				- Total				\$785.00	
15 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION Material 6		MaterialCredit - Total						\$785.00	
2020 SYSTEM \$1,890.00 This adjustment offsets the original system-generated Overrun Payment Estimate Exception 7 on the current Payment Estimate. 7	0520 -	Total						\$0.00	
2020 Payment Estimate Item Adjustment (0007) due to user slaglv1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	0530		Material		6		SYSTEM	(\$1,890.00)	
2020					6		SYSTEM	\$1,890.00	Payment Estimate Item Adjustment (0007) due to user slaglv1 overridding Payment Estimate Exception 7 on the current Payment
2020 Payment Estimate Item Adjustment (0014) due to user slaglv1 overridding Payment Estimate Exception 16 on the current Payment Estimate. 8					7		SYSTEM	(\$1,890.00)	
- Total (\$1,890.00) Material - Total (\$1,890.00) 15 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION - Total 9 Sep 30, 2020 \$1,890.00 - Total \$1,890.00 MaterialCredit - Total \$1,890.00					7		SYSTEM	\$1,890.00	Payment Estimate Item Adjustment (0014) due to user slaglv1 overridding Payment Estimate Exception 16 on the current
Material - Total (\$1,890.00) 15 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION MaterialCredit 9 Sep 30, 2020 SYSTEM \$1,890.00 - Total \$1,890.00 \$1,890.00					8		SYSTEM	(\$1,890.00)	
15 IN. OR ALLOWED SUBSTITUTE MaterialCredit 9 Sep 30, 2020 SYSTEM \$1,890.00				- Total				(\$1,890.00)	
2020 2020 2020		Material - Total						(\$1,890.00)	
MaterialCredit - Total \$1,890.00			MaterialCredit		9		SYSTEM		
MaterialCredit - Total \$1,890.00				- Total				\$1,890.00	
0530 - Total \$0,00		MaterialCredit - Total						\$1,890.00	
	0530 -	Total						\$0.00	

Revision 4/1/2020 Page 15 of 18



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0540	SEEDING - COOL SEASON MIXTURES	Material		8	Jul 17, 2020	SYSTEM	(\$1,277.51)	
				8	Jul 17, 2020	SYSTEM	\$1,277.51	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user slaglv1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				9	Sep 30, 2020	SYSTEM	(\$1,277.51)	
				9	Sep 30, 2020	SYSTEM	\$1,277.51	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user slaglv1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				10	Oct 16, 2020	SYSTEM	(\$1,277.51)	
				10	Oct 16, 2020	SYSTEM	\$1,277.51	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user slaglv1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				11	Dec 16, 2020	SYSTEM	(\$1,277.51)	
				11	Dec 16, 2020	SYSTEM	\$1,277.51	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.
				12	Jan 4, 2021	SYSTEM	(\$1,277.51)	
				12	Jan 4, 2021	SYSTEM	\$1,277.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brookw1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				13	Jan 18, 2021	SYSTEM	(\$1,277.51)	
				13	Jan 18, 2021	SYSTEM	\$1,277.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0540 -	- Total						\$0.00	
0560	ALTERNATE DITCH CHECK	Material		8	Jul 17, 2020	SYSTEM	(\$426.00)	
				8	Jul 17, 2020	SYSTEM	\$426.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user slaglv1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0560	- Total						\$0.00	
0570	CURB INLET CHECK	Material		3	May 4, 2020	SYSTEM	(\$255.00)	
				3	May 4, 2020	SYSTEM	\$255.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user slaglv1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				4	May 18, 2020	SYSTEM	(\$255.00)	
				4	May 18, 2020	SYSTEM	\$255.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user slaglv1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				5	Jun 3, 2020	SYSTEM	(\$255.00)	
				5	Jun 3, 2020	SYSTEM	\$255.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user slaglv1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	

Revision 4/1/2020 Page 16 of 18



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	Bees.ipao.i	Туре	Adjustment Type		Date	Ву	7 1110 1111	
0570 -	Total						\$0.00	
0600	SILT FENCE	Material		3	May 4, 2020	SYSTEM	(\$816.00)	
				3	May 4, 2020	SYSTEM	\$816.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user slaglv1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
				4	May 18, 2020	SYSTEM	(\$816.00)	
				4	May 18, 2020	SYSTEM	\$816.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user slaglv1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				5	Jun 3, 2020	SYSTEM	(\$816.00)	
				5	Jun 3, 2020	SYSTEM	\$816.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user slaglv1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	SILT FENCE	Overrun	Overrun	7	Jul 6, 2020	SYSTEM	(\$799.00)	
				9	Sep 30, 2020	SYSTEM	\$799.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.00000 - 2.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0600 -	Total						\$0.00	
0610	TYPE 2 TURF REINFORCEMENT MAT	Material		8	Jul 17, 2020	SYSTEM	(\$962.00)	
				8	Jul 17, 2020	SYSTEM	\$962.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user slaglv1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total						\$0.00	
0610 -							\$0.00	
0620	TYPE 3B EROSION CONTROL BLANKET	Material		8	Jul 17, 2020	SYSTEM	(\$444.50)	
				8	Jul 17, 2020	SYSTEM	\$444.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) due to user slaglv1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0620 -	Total						\$0.00	
0910	GALVANIZED STRUCTURAL STEEL PILES (12 IN)			8	Jul 17, 2020	SYSTEM	\$13,312.50	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$13,312.50	
	Construction Stockpile - Total						\$13,312.50	
	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Material		13	Jan 18, 2021	SYSTEM	(\$15,355.00)	
				13	Jan 18, 2021	SYSTEM	\$15,355.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0910 -	Total						\$13,312.50	
	PILE POINT REINFORCEMENT	Construction		8	Jul 17,	SYSTEM	\$1,330.00	Payment Estimate Item Adjustment generated Stockpile Transaction
0930		Stockpile			2020			Transaction
0930	Construction Stockpile - Total	Stockpile	- Total		2020		\$1,330.00 \$1,330.00	Hallsacuuli

Revision 4/1/2020 Page 17 of 18



Description Adjustment of System Adjustment of Stockylor	Lina	Description	A diverture a mt	Other	Fet.	Cuantad	Cuantad	Amazint	Downselle
2011 2011	Line	Description		Adjustment				Amount	Remarks
Payment Edimate Item Adjustment (2002) due to use fitzzon operationing Payment Edimate Exception 6 on the current Payment Edimate Edimate Exception 6 on the curr	0930	PILE POINT REINFORCEMENT	Material		13		SYSTEM	(\$665.00)	
Material - Total Substitution Stockpile - Total Substitution Substitution Stockpile - Total Substitution Subst					13		SYSTEM	\$665.00	Payment Estimate Item Adjustment (0002) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment
SAFETY BARRIER CUB Construction Stockpile - Total Security SYSTEM SPECIAL CUB Construction Stockpile - Total Security SYSTEM SPECIAL CUB SYSTEM SYSTEM SPECIAL CUB SYSTEM SysTe				- Total				\$0.00	
SAFETY BARRIER CURB Construction Stockpile Total Subspire		Material - Total						\$0.00	
Stockple	0930 -	Total						\$1,330.00	
Construction Stockpile - Total	0950	SAFETY BARRIER CURB			8		SYSTEM	\$2,257.20	
Substitution Stockpile - Total				- Total				\$2,257.20	
SILAB ON CONCRETE BEAM Construction Stockpile - Total		Construction Stockpile - Total						\$2,257.20	
Slock-pile	0950 -	Total						\$2,257.20	
Construction Stockpile - Total S26,669,80	0960	SLAB ON CONCRETE BEAM			8		SYSTEM	\$26,669.80	
\$27 IN., PRESTRESSED CONCRETE Social Stockpile Total System Syste				- Total				\$26,669.80	
27 IN, PRESTRESSED CONCRETE Construction Stockpile -Total Stockpile -Total Stockpile -Total Strat, 502_64 Payment Estimate Item Adjustment generated Stockpile -Total Strat, 502_64		Construction Stockpile - Total						\$26,669.80	
SPREAD BOX BEAM Slockpile -Total	0960 -	Total						\$26,669.80	
Construction Stockpile - Total S174, 502,64	0970				8		SYSTEM	\$174,502.64	
STATE STAT				- Total				\$174,502.64	
MECHANICALLY STABILIZED EARTH Construction WALL SYSTEMS Stockpile Fotal Fo		Construction Stockpile - Total						\$174,502.64	
WALL SYSTEMS Shockpile Total S44,174,360	0970 -	Total						\$174,502.64	
Construction Stockpile - Total	1050				8		SYSTEM	\$44,713.80	
1080 - Total 1080 - Total 1080 MECHANICALLY STABILIZED EARTH WALL SYSTEMS Stockpile				- Total				\$44,713.80	
1080 MECHANICALLY STABILIZED EARTH WALL SYSTEMS Slockpile Total S54,649.10 S64,649.10 S64,649.1		Construction Stockpile - Total						\$44,713.80	
MALL SYSTEMS Stockpile 2020 Transaction Transact	1050 -	Total						\$44,713.80	
Material - Total System	1080				8		SYSTEM	\$54,649.10	
MECHANICALLY STABILIZED EARTH WALL SYSTEMS Material WALL SYSTEM Material WALL SYSTEMS Material WALL SYSTEMS Material WALL SYSTEMS Material Payment Estimate Item Adjustment (0001) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate Testimate Testimate Exception 6 on the current Payment Estimate Statimate				- Total				\$54,649.10	
2021		Construction Stockpile - Total						\$54,649.10	
2021 Payment Estimate Item Adjustment (0001) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate. S0.00			Material		13		SYSTEM	(\$203,562.00)	
Material - Total S0.00					13		SYSTEM	\$203,562.00	Payment Estimate Item Adjustment (0001) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment
1080 - Total				- Total				\$0.00	
WATER Material 12		Material - Total						\$0.00	
2021 12 Jan 4, 2021 13 Jan 18, 2021 13 Jan 18, 2021 13 Jan 18, 2021 14 SYSTEM \$80,458.90 15 Jan 18, 2021 16 SYSTEM \$80,458.90 17 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brookw1 overridding Payment Estimate Exception 1 on the current Payment Estimate. 18 SYSTEM \$80,458.90 19 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate. 19 Sound System Sys	1080 -	Total						\$54,649.10	
Payment Estimate Item Adjustment (0005) due to user brookw1 overridding Payment Estimate Exception 1 on the current Payment Estimate. 13 Jan 18, 2021 13 Jan 18, 2021 13 Jan 18, 2021 13 SYSTEM \$80,458.90 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00	5004	WATER	Material		12		SYSTEM	(\$80,458.90)	
2021 13 Jan 18, 2021 13 Jan 18, 2021 13 SYSTEM \$80,458.90 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00 5004 - Total \$0.00					12		SYSTEM	\$80,458.90	Payment Estimate Item Adjustment (0005) due to user brookw1 overridding Payment Estimate Exception 1 on the current Payment
Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00 5004 - Total \$0.00					13		SYSTEM	(\$80,458.90)	
Material - Total \$0.00 5004 - Total \$0.00					13		SYSTEM	\$80,458.90	Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 1 on the current Payment
5004 - Total \$0.00				- Total				\$0.00	
		Material - Total						\$0.00	
Overall - Total \$315,794.88	5004 -	Total						\$0.00	
	Overa	II - Total						\$315,794.88	

Revision 4/1/2020 Page 18 of 18