Pay Estimate Created Date: November 2, 2020

Progress I 11	Estimate Number	Contract ID Prime Contractor	200117-D02 Don Schnieders Excava Inc.	ating Company,	Pay Period Start Pay Period End	October 16, 2020 November 1, 2020	Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,634,467.90 \$0.00 \$1,634,467.90
Approval Date								By User
November 2, 2020			Generated and A	Approved (and s	hould be consid	dered Draft) at the I	Project Office Level by	stokez1
November 3, 2020			Reviewed and Appro	ved (and should	l be considered	Draft) at the Resid	lent Engineer Level by	browns1
November 4, 2020			F	Reviewed and A	pproved at the	Central Office Con	trollers Office Level by	greggd1
Original Compl	etion Date	Curre	ent Completion Date	Actual Co	mpletion Date	% of C	urrent Contract Amour	nt Complete
December 1	, 2020	C	ecember 1, 2020				92.26%	

No Milestones Exist for Contract

Contract Total	Pay For Est	imate No. 1	1					
				This Estimate	Previous		To Date	
200117-D02	Gros Ince Disir Liqu	Il Posted Iten ss Item Adjus ntive ncentive idated Dama er Contract A	stments	\$111,760.30 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$1,396,211 (\$3,254.40) \$0.00 \$0.00 \$0.00 \$0.00 \$1,392,956	)	\$1,507,971.6 (\$3,254.40) \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$1,504,717.1	
Contract Total	Payable This	s Estimate:		\$111,760.30				
ems Paid This	Estimate Pe	eriod						
Project Number	Line Number	ltem Code		Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5S3250	0450	2022010	REMOVAL	OF IMPROVEMENTS	LS	\$5,476.000	0.5	\$2,738.00
	0520	6113020	FURNISHIN	G TYPE 2 ROCK BLANKET	CUYD	\$41.400	392	\$16,228.80
	0530	6113040	PLACING T	YPE 2 ROCK BLANKET	CUYD	\$12.850	392	\$5,037.20
	0620	6240103A	PERMANEN	IT EROSION CONTROL GEOTEXTIL	E SQYD	\$3.750	538	\$2,017.50
	0630	6274000	CONTRACT STAKING	OR FURNISHED SURVEYING AND	LS	\$10,500.000	0.5	\$5,250.00
	0860	7034215	SAFETY BA	RRIER CURB	LF	\$91.950	313	\$28,780.35
	0870	7034222	SLAB ON C	ONCRETE BEAM	SQYD	\$329.000	148.05	\$48,708.45
	0900	7151001	VERTICAL	DRAIN AT END BENTS	EA	\$1,500.000	2	\$3,000.00
Project 1583	250 - Total							\$111,760.30
110,0000								

### No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3242	0080	MISC.	Material			-255.6	\$70.00	(\$17,892.00)
	0080	MISC.	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	255.6	\$70.00	\$17,892.00
	0310	BRIDGE APPROACH SLAB (MINOR ROAD)	Material			-121	\$95.00	(\$11,495.00)
	0310	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	121	\$95.00	\$11,495.00



### Pay Estimate Created Date: November 2, 2020

	Progre 11	ss Estimate Number	Contract ID Prime Contractor	200117-D02 Don Schnied Inc.	ers Excavatir	ng Company,	Pay Period Start Pay Period End	October 16, 2020 November 1, 2020	Original Con Amount Net Change ( Amount Current Cont Amount	Order	\$1,634,467.90 \$0.00 \$1,634,467.90
Project Number	Line No.	Item I	Description	Adjustment Type	Other Item Adjustment Type		Comment	is	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3242	0350	SLAB (	ON CONCRETE I- GIRDER	Material					-331.5	\$285.00	(\$94,477.50
	0350	SLAB (	DN CONCRETE I- GIRDER	Material		generate Adju	ed Overrun Pay stment (0003) o Payment Estirr	the original system- ment Estimate Item due to user stokez1 nate Exception 7 on Payment Estimate.		\$285.00	\$94,477.50
J5S3250	0520	FURNISHIN	IG TYPE 2 ROCK BLANKET	Material					-692	\$41.40	(\$28,648.80
	0520	FURNISHIN	IG TYPE 2 ROCK BLANKET	Material		generate Adju	ed Overrun Pay stment (0006) o Payment Estirr	the original system- ment Estimate Item due to user stokez1 nate Exception 3 on Payment Estimate.		\$41.40	\$28,648.80
	0770	DRILLED	SHAFTS (3 FT. 6 IN. DIA.)	Material					-12	\$940.00	(\$11,280.00
	0770	DRILLED	SHAFTS (3 FT. 6 IN. DIA.)	Material		generate Adju	ed Overrun Pay stment (0007) o Payment Estim	the original system- ment Estimate Item due to user stokez1 nate Exception 4 on Payment Estimate.		\$940.00	\$11,280.00
	0780	ROCK SOC	KETS (3 FT 0 IN. DIA.)	Material					-24	\$620.00	(\$14,880.00
	0780	ROCK SOC	KETS (3 FT 0 IN. DIA.)	Material		generate Adju	ed Overrun Pay stment (0008) o Payment Estirr	the original system- ment Estimate Item due to user stokez1 nate Exception 5 on Payment Estimate.		\$620.00	\$14,880.00
	0850		SS B CONCRETE UBSTRUCTURE)	Material					-49.4	\$732.00	(\$36,160.80
	0850		SS B CONCRETE UBSTRUCTURE)	Material		generate Adju	ed Overrun Pay stment (0009) o Payment Estirr	the original system- ment Estimate Item due to user stokez1 nate Exception 6 on Payment Estimate.		\$732.00	\$36,160.80
	0860	SAFETY	BARRIER CURB	Material					-313	\$91.95	(\$28,780.35
	0860	SAFETY	BARRIER CURB	Material		generate Adju	ed Overrun Pay stment (0004) o Payment Estirr	the original system- ment Estimate Item due to user stokez1 nate Exception 8 on Payment Estimate.		\$91.95	\$28,780.3
	0870	SLAB ON C	ONCRETE BEAM	Material					-338.4	\$329.00	(\$111,333.60
	0870	SLAB ON C	ONCRETE BEAM	Material		generate Adju	ed Overrun Pay stment (0005) o Payment Estim	the original system- ment Estimate Item due to user stokez1 nate Exception 9 on Payment Estimate.		\$329.00	\$111,333.60
Total		1						-			\$0.0



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J5S3242	FAS S401(79)	Bridge replacement	A	GASCONADE	over Third Creek, 4.2 miles south of Mount Sterling
J5S3250	FAS S401(80)	Bridge replacement	D	OSAGE	over Mistaken Creek, 0.2 miles west of Cooper Hill

### Totals by Job Numbers

3242	This Estimate	Previous	To Date
Posted Item Pay	\$0.00	\$919,151.50	\$919,151.50
Gross Item Adjustments	\$0.00	(\$3,074.40)	(\$3,074.40)
Gross Item Pay	\$0.00	\$916,077.10	\$916,077.10
	<b>AA AA</b>	<b>AA AA</b>	<b>AA AA</b>
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
3250	This Estimate	Previous	To Date
		¢477 0E0 70	\$588,820.00
Posted Item Pay	\$111,760.30	\$477,059.70	\$366,6ZU.UU
Posted Item Pay Gross Item Adjustments	\$111,760.30 \$0.00	(\$180.00)	(\$180.00)
Gross Item Adjustments Gross Item Pay	\$0.00 <b>\$111,760.30</b>	(\$180.00) <b>\$476,879.70</b>	(\$180.00) <b>\$588,640.00</b>
Gross Item Adjustments Gross Item Pay Incentive	\$0.00 <b>\$111,760.30</b> \$0.00	(\$180.00) <b>\$476,879.70</b> \$0.00	(\$180.00) <b>\$588,640.00</b> \$0.00
Gross Item Adjustments Gross Item Pay Incentive Disincentive	\$0.00 <b>\$111,760.30</b> \$0.00 \$0.00	(\$180.00) <b>\$476,879.70</b> \$0.00 \$0.00	(\$180.00) \$588,640.00 \$0.00 \$0.00
Gross Item Adjustments Gross Item Pay Incentive	\$0.00 <b>\$111,760.30</b> \$0.00	(\$180.00) <b>\$476,879.70</b> \$0.00	(\$180.00) <b>\$588,640.00</b> \$0.00



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5S3242, Item 4019905, Project Item Line Number 0080, Material Set 401990596, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient.	Certification needs to be entered	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3242, Item 5031011A, Project Item Line Number 0310, Material Set 5031011A96, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient.	Core information needed	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3250, Item 6113020, Project Item Line Number 0520, Material Set 611302096, Material 0611EPM - Embankment Protection Material, Acceptance Action Generic 0611EPM is insufficient.	Material is on Job site. Inspection will be made as soon as possible.	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3250, Item 7011105, Project Item Line Number 0770, Material Set 701110596, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	QA test information needs to be entered.	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3250, Item 7011204, Project Item Line Number 0780, Material Set 701120496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	QA test information needs to be entered.	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3250, Item 7032003, Project Item Line Number 0850, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	QA test information needs to be entered.	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3242, Item 7034213, Project Item Line Number 0350, Material Set 703421396, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	AASHTOWare Error. No remaining test shown on Sampling Checklist.	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3250, Item 7034215, Project Item Line Number 0860, Material Set 703421596, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on 7 day and 28 day cylinder breaks	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3250, Item 7034222, Project Item Line Number 0870, Material Set 703422296, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	Waiting on 28 day cylinder breaks	stokez1	Overridden
Estimate Exception Type: Item Overrun: Contract 200117-D02, Contract Project J5S3242, Project Item Line Number 0220, Contract Line Item Number 0220, Item 8061005, Minor Item.	Waiting on change order to be completed.	stokez1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 200117-D02, Contract Project J5S3242, Project Item Line Number 0240, Contract Line Item Number 0240, Item 8061019, Minor Item.	Waiting on change order to be completed.	stokez1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 200117-D02, Contract Project J5S3242, Project Item Line Number 0250, Contract Line Item Number 0250, Item 8061050, Minor Item.	Waiting on change order to be completed.	stokez1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 200117-D02, Contract Project J5S3250, Project Item Line Number 0540, Contract Line Item Number 0540, Item 6161005, Minor Item.	Waiting on change order to be completed.	stokez1	Acknowledged

### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities			ased on R	eport Generated date and can differ from the posted am	ount at th	e time the	e Estimate v	vas Gen	erated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-D02	J5S3242	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	1.00	\$2,640.00	\$2,640.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$5,067.00	\$5,067.00
		0001	0030	2031000	CLASS A EXCAVATION	932.00	0.00	932.00	CUYD	932.00	\$6.45	\$6,011.40
		0001	0040	2035500	EMBANKMENT IN PLACE	2,390.00	0.00	2,390.00	CUYD	2,390.00	\$17.70	\$42,303.00
		0001	0050	2036000	COMPACTING EMBANKMENT	746.00	0.00	746.00	CUYD	746.00	\$5.35	\$3,991.10
		0001	0060	2037075	COMPACTING IN CUT	6.00	0.00	6.00	STA	0.00	\$453.00	\$0.00
		0001	0070	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	368.00	0.00	368.00	SQYD	368.00	\$10.50	\$3,864.00
		0001	0080	4019905	MISC.OPTIONAL PAVEMENT	371.10	0.00	371.10	SQYD	255.60	\$70.00	\$17,892.00
		0001	0090	6113020	FURNISHING TYPE 2 ROCK BLANKET	925.00	0.00	925.00	CUYD	925.00	\$41.40	\$38,295.00
		0001	0100	6113040	PLACING TYPE 2 ROCK BLANKET	925.00	0.00	925.00	CUYD	925.00	\$11.20	\$10,360.00
		0001	0110	6161005	CONSTRUCTION SIGNS	793.00	0.00	793.00	SQFT	778.00	\$6.00	\$4,668.00
		0001	0120	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$35.00	\$140.00
		0001	0130	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	4.00	\$20.00	\$80.00
		0001	0140	6161030	TYPE III MOVEABLE BARRICADE	10.00	0.00	10.00	EA	10.00	\$135.00	\$1,350.00
		0001	0150	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00
		0001	0160	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$59,000.00	\$59,000.00
		0001	0170	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	748.00	0.00	748.00	LF	748.00	\$1.50	\$1,122.00
		0001	0180	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	748.00	0.00	748.00	LF	748.00	\$1.50	\$1,122.00
		0001	0190	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,388.00	0.00	1,388.00	SQYD	1,388.00	\$2.80	\$3,886.40
		0001	0200	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$12,200.00	\$12,200.00
		0001	0210	8051000A	SEEDING - COOL SEASON MIXTURES	0.50	0.00	0.50	ACRE	0.50	\$4,000.00	\$2,000.00
		0001	0220	8061005	ROCK DITCH CHECK	34.00	0.00	34.00	LF	49.00	\$25.00	\$1,225.00
		0001	0230	8061016	SEDIMENT REMOVAL	10.00	0.00	10.00	CUYD	0.00	\$20.00	\$0.00
		0001	0240	8061019	SILT FENCE	678.00	0.00	678.00	LF	914.10	\$4.00	\$3,656.40
		0001	0250	8061050	TYPE C BERM	313.00	0.00	313.00	LF	430.00	\$15.00	\$6,450.00
		0010	0255	6061060	MGS GUARDRAIL	125.00	0.00	125.00	LF	125.00	\$34.00	\$4,250.00
		0010	0270	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$2,900.00	\$11,600.00
		0010	0280	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	4.00	\$2,800.00	\$11,200.00
		0070	0290	2061000	CLASS 1 EXCAVATION	90.00	0.00	90.00	CUYD	90.00	\$32.90	\$2,961.00
		0070	0300	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$54,820.00	\$54,820.00
		0070	0310	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	121.00	0.00	121.00	SQYD	121.00	\$95.00	\$11,495.00
		0070	0320	7021214	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	1,015.00	0.00	1,015.00	LF	913.00	\$81.20	\$74,135.60
		0070	0330	7027000	PILE POINT REINFORCEMENT	23.00	0.00	23.00	EA	23.00	\$140.00	\$3,220.00
		0070	0340	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	51.70	0.00	51.70	CUYD	51.70	\$875.00	\$45,237.50
		0070	0350	7034213	SLAB ON CONCRETE I-GIRDER	741.00	0.00	741.00	SQYD	741.00	\$285.00	\$211,185.00
		0070	0360	7034215	SAFETY BARRIER CURB	495.00	0.00	495.00	LF	495.00	\$74.80	\$37,026.00
		0070	0370	7056000	TYPE 2 (32 IN.), PRESTRESSED CONCRETE I-GIRDER	916.00	0.00	916.00	LF	916.00	\$200.00	\$183,200.00
		0070	0380	7061060	REINFORCING STEEL (BRIDGES)	4,590.00	0.00	4,590.00	LB	4,590.00	\$1.59	\$7,298.10
		0070	0390	7123301	STEEL INTERMEDIATE DIAPHRAGM FOR P/S CONCRETE GIRDERS	12.00	0.00	12.00	EA	12.00	\$860.00	\$10,320.00
		0070	0400	7123610	SLAB DRAIN	28.00	0.00	28.00	EA	28.00	\$315.00	\$8,820.00
		0070	0410	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	1.00	\$1,500.00	\$1,500.00
		0070	0420	7161002	LAMINATED NEOPRENE BEARING PAD	24.00	0.00	24.00	EA	24.00	\$215.00	\$5,160.00
		0070	0430	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	8.00	0.00	8.00	EA	8.00	\$300.00	\$2,400.00
	Project J	5S3242 - To	otal Value	Posted to D	ate as of Report Generated Date							\$919,151.50

# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted amo	ount at th	e time the	e Estimate v	vas Gen	erated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-D02	J5S3250	0001	0440	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	1.00	\$2,640.00	\$2,640.00
		0001	0450	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$5,476.00	\$5,476.00
		0001	0460	2031000	CLASS A EXCAVATION	293.00	0.00	293.00	CUYD	293.00	\$8.20	\$2,402.60
		0001	0470	2035500	EMBANKMENT IN PLACE	875.00	0.00	875.00	CUYD	0.00	\$17.70	\$0.00
		0001	0480	2036000	COMPACTING EMBANKMENT	235.00	0.00	235.00	CUYD	0.00	\$4.25	\$0.00
		0001	0490	2037075	COMPACTING IN CUT	2.90	0.00	2.90	STA	0.00	\$470.00	\$0.00
		0001	0500	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	394.00	0.00	394.00	SQYD	0.00	\$9.85	\$0.00
		0001	0510	4019905	MISC.OPTIONAL PAVEMENT	396.80	0.00	396.80	SQYD	0.00	\$70.00	\$0.00
		0001	0520	6113020	FURNISHING TYPE 2 ROCK BLANKET	692.00	0.00	692.00	CUYD	692.00	\$41.40	\$28,648.80
		0001	0530	6113040	PLACING TYPE 2 ROCK BLANKET	692.00	0.00	692.00	CUYD	692.00	\$12.85	\$8,892.20
		0001	0540	6161005	CONSTRUCTION SIGNS	688.00	0.00	688.00	SQFT	718.00	\$6.00	\$4,308.00
		0001	0550	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$35.00	\$140.00
		0001	0560	6161009	FLAG ASSEMBLY	4.00	0.00	4.00	EA	4.00	\$20.00	\$80.00
		0001	0570	6161030	TYPE III MOVEABLE BARRICADE	10.00	0.00	10.00	EA	10.00	\$130.00	\$1,300.00
		0001	0580	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00
		0001	0590	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$59,000.00	\$59,000.00
		0001	0600	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	586.00	0.00	586.00	LF	0.00	\$1.75	\$0.00
		0001	0610	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	586.00	0.00	586.00	LF	0.00	\$1.75	\$0.00
		0001	0620	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,038.00	0.00	1,038.00	SQYD	1,038.00	\$3.75	\$3,892.50
		0001	0630	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.75	\$10,500.00	\$7,875.00
		0001	0640	8051000A	SEEDING - COOL SEASON MIXTURES	0.50	0.00	0.50	ACRE	0.00	\$4,000.00	\$0.00
		0001	0650	8061005	ROCK DITCH CHECK	144.00	0.00	144.00	LF	120.00	\$25.00	\$3,000.00
		0001	0660	8061016	SEDIMENT REMOVAL	13.00	0.00	13.00	CUYD	0.00	\$20.00	\$0.00
		0001	0670	8061019	SILT FENCE	66.00	0.00	66.00	LF	66.00	\$4.00	\$264.00
		0001	0680	8061050	TYPE C BERM	269.00	0.00	269.00	LF	269.00	\$15.00	\$4,035.00
		0001	0690	8064133	TYPE 1C EROSION CONTROL BLANKET	136.00	0.00	136.00	SQYD	0.00	\$5.00	\$0.00
		0040	0700	9031010	CONCRETE FOOTINGS, EMBEDDED	1.10	0.00	1.10	CUYD	0.00	\$2,500.00	\$0.00
		0040	0710	9031270A	2 IN. PSST POST - 12 GA.	120.00	0.00	120.00	LF	0.00	\$12.00	\$0.00
		0040	0725	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	36.00	0.00	36.00	LF	0.00	\$30.00	\$0.00
		0040	0730	9035069A	SHF-FLAT SHEET FLUORESCENT	36.00	0.00	36.00	SQFT	0.00	\$24.00	\$0.00
		0070	0740	2061000	CLASS 1 EXCAVATION	105.00	0.00	105.00	CUYD	105.00	\$28.20	\$2,961.00
		0070	0750	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$48,660.00	\$48,660.00
		0070	0760	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	112.00	0.00	112.00	SQYD	0.00	\$96.00	\$0.00
		0070	0770	7011105	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	12.00	0.00	12.00	LF	12.00	\$940.00	\$11,280.00
		0070	0780	7011204	ROCK SOCKETS (3 FT 0 IN. DIA.)	24.00	0.00	24.00	LF	24.00	\$620.00	\$14,880.00
		0070	0790	7011300	VIDEO CAMERA INSPECTION	2.00	0.00	2.00	EA	2.00	\$700.00	\$1,400.00
		0070	0800	7011400	FOUNDATION INSPECTION HOLES	44.00	0.00	44.00	LF	44.00	\$112.00	\$4,928.00
		0070	0810	7011600	SONIC LOGGING TESTING	2.00	0.00	2.00	EA	0.00	\$2,550.00	\$0.00
		0070	0820	7021214	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	248.00	0.00	248.00	LF	235.05	\$103.00	\$24,210.15
		0070	0830	7026000	PRE-BORE FOR PILING	80.00	0.00	80.00	LF	80.00	\$155.00	\$12,400.00
		0070	0840	7027000	PILE POINT REINFORCEMENT	8.00	0.00	8.00	EA	8.00	\$140.00	\$1,120.00
		0070	0850	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	49.40	0.00	49.40	CUYD	49.40	\$732.00	\$36,160.80
		0070	0860	7034215	SAFETY BARRIER CURB	313.00	0.00	313.00	LF	313.00	\$91.95	\$28,780.35
		0070	0870	7034222	SLAB ON CONCRETE BEAM	423.00	0.00	423.00	SQYD	338.40	\$329.00	\$111,333.60



### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

### Total Paid / All Items / All Estimates (Including this Estimate)

Note:	Posted Quantities and	Values are based on Repor	t Generated date and ca	an differ from the posted	amount at the time the E	stimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-D02	J5S3250	0070	0880	7056050A	27 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	421.00	0.00	421.00	LF	421.00	\$312.00	\$131,352.00
		0070	0890	7061060	REINFORCING STEEL (BRIDGES)	7,000.00	0.00	7,000.00	LB	7,000.00	\$1.60	\$11,200.00
		0070	0900	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.00
		0070	0910	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	12.00	0.00	12.00	EA	12.00	\$600.00	\$7,200.00
	Project J	5S3250 - To	otal Value	Posted to D	ate as of Report Generated Date							\$588,820.00
200117-D02 Ove	rall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$1,507,971.50



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0450	2022010	REMOVAL OF IMPROVEMENTS	10/30/20	11/2/20	0.50	LS	NA					Pavement Has been removed
0520	6113020	FURNISHING TYPE 2 ROCK BLANKET	10/30/20	11/2/20	392.00	CUYD		468+97		469+79		
0530	6113040	PLACING TYPE 2 ROCK BLANKET	10/30/20	11/2/20	392.00	CUYD	to	468+97		469+79		
0620	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	10/30/20	11/2/20	538.00	SQYD		468+97		469+79		
0630	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	10/30/20	11/2/20	0.50	LS	NA					
0860	7034215	SAFETY BARRIER CURB	10/29/20	11/2/20	313.00	LF	N Section: 469+20 to 470+64 S Section: 469+20 to 470+64					
0870	7034222	SLAB ON CONCRETE BEAM	10/20/20	11/2/20	148.05	SQYD		469+20.82		470+64.54		35% pay for concrete
0900	7151001	VERTICAL DRAIN AT END BENTS	10/30/20	11/2/20	2.00	EA	End Bent 1 469+20 End Bent 3 470+64					

The information below this line are details from Line Item agency views. No Agency View Details Exist



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0040	EMBANKMENT IN PLACE	Material	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	6	Aug 17, 2020	SYSTEM	(\$42,303.00)	
				6	Aug 17, 2020	SYSTEM	\$42,303.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0040 -	Total						\$0.00	
0050	COMPACTING EMBANKMENT	Material		6	Aug 17, 2020	SYSTEM	(\$3,991.10)	
				6	Aug 17, 2020	SYSTEM	\$3,991.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0050 -	Total						\$0.00	
0070	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		6	Aug 17, 2020	SYSTEM	(\$2,683.80)	
				6	Aug 17, 2020	SYSTEM	\$2,683.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				7	Sep 2, 2020	SYSTEM	(\$2,683.80)	
				7	Sep 2, 2020	SYSTEM	\$2,683.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0070 -	Total						\$0.00	
0080	MISC. OPTIONAL PAVEMENT	Material		8	Sep 16, 2020	SYSTEM	(\$17,892.00)	
				8	Sep 16, 2020	SYSTEM	\$17,892.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				9	Oct 1, 2020	SYSTEM	(\$17,892.00)	
				9	Oct 1, 2020	SYSTEM	\$17,892.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				10	Oct 16, 2020	SYSTEM	(\$17,892.00)	
				10	Oct 16, 2020	SYSTEM	\$17,892.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				11	Nov 2, 2020	SYSTEM	(\$17,892.00)	
				11	Nov 2, 2020	SYSTEM	\$17,892.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0080 -	Total						\$0.00	
0090	FURNISHING TYPE 2 ROCK BLANKET	Material		3	Jun 30, 2020	SYSTEM	(\$25,212.60)	
				3	Jun 30, 2020	SYSTEM	\$25,212.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				4	Jul 16, 2020	SYSTEM	(\$25,212.60)	
				4	Jul 16, 2020	SYSTEM	\$25,212.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				5	Aug 3,	SYSTEM	(\$25,212.60)	



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
		.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Туре	. tumbor	Duto	29		
0090	FURNISHING TYPE 2 ROCK BLANKET	Material		5	Aug 3, 2020	SYSTEM	\$25,212.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				6	Aug 17, 2020	SYSTEM	(\$38,295.00)	
				6	Aug 17, 2020	SYSTEM	\$38,295.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
		- Total				\$0.00		
	Material - Total						\$0.00	
0090 -	Total						\$0.00	
0170	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		6	Aug 17, 2020	SYSTEM	(\$1,122.00)	
	BEADS			6	Aug 17, 2020	SYSTEM	\$1,122.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				7	Sep 2, 2020	SYSTEM	(\$1,122.00)	
				7	Sep 2, 2020	SYSTEM	\$1,122.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				8	Sep 16, 2020	SYSTEM	(\$1,122.00)	
				8	Sep 16, 2020	SYSTEM	\$1,122.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0170 -	Total						\$0.00	
0180	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	MARKING PAINT, TYPE P		6	Aug 17, 2020	SYSTEM	(\$1,122.00)	
				6	Aug 17, 2020	SYSTEM	\$1,122.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				7	Sep 2, 2020	SYSTEM	(\$1,122.00)	
				7	Sep 2, 2020	SYSTEM	\$1,122.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				8	Sep 16, 2020	SYSTEM	(\$1,122.00)	
				8	Sep 16, 2020	SYSTEM	\$1,122.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total	Fotal			\$0.00	
	Material - Total						\$0.00	
0180 -	Total						\$0.00	
0210	SEEDING - COOL SEASON MIXTURES	Material		6	Aug 17, 2020	SYSTEM	(\$2,000.00)	
				6	Aug 17, 2020	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
	- Total						\$0.00	
	Material - Total						\$0.00	
0210 -	Total						\$0.00	
0220	ROCK DITCH CHECK	Overrun	Overrun	1	Jun 4, 2020	SYSTEM	(\$375.00)	
			Overrun - T	otal			(\$375.00)	
	Overrun - Total						(\$375.00)	
0220 -	Total						(\$375.00)	
0240	SILT FENCE	Overrun	Overrun	6	Aug 17, 2020	SYSTEM	(\$944.40)	
			Overrun - T				(\$944.40)	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0240	Overrun - Total						(\$944.40)	
0240 -	Total						(\$944.40)	
0250		ERM Overrun	Overrun	2	Jun 16, 2020	SYSTEM	(\$900.00)	
				6	Aug 17, 2020	SYSTEM	(\$855.00)	
			Overrun - T	otal			(\$1,755.00)	
	Overrun - Total						(\$1,755.00)	
0250 -	Total						(\$1,755.00)	
0255	MGS GUARDF	RAIL Construction Stockpile		1	Jun 4, 2020	SYSTEM	\$1,332.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Aug 17, 2020	SYSTEM	(\$1,332.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Tot	tal					\$0.00	
	MGS GUARDF	RAIL Material		6	Aug 17, 2020	SYSTEM	(\$4,250.00)	
				6	Aug 17, 2020	SYSTEM	\$4,250.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				7	Sep 2, 2020	SYSTEM	(\$4,250.00)	
				7	Sep 2, 2020	SYSTEM	\$4,250.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			8	Sep 16, 2020	SYSTEM	(\$4,250.00)		
				8	Sep 16, 2020	SYSTEM	\$4,250.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0255 -	Total						\$0.00	
0270	MGS BRIDGE APPROACH Construct TRANSITION SECTION Stockpile (REGULAR/NO CURB)	ION Stockpile			Jun 4, 2020	SYSTEM	\$5,996.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Aug 17, 2020	SYSTEM	(\$5,996.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Tot	tal					\$0.00	
0270 -	Total						\$0.00	
0280	TYPE A CRASHWORTHY E TERMINAL (MA			1	Jun 4, 2020	SYSTEM	\$6,040.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				6	Aug 17, 2020	SYSTEM	(\$6,040.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Tot	tal					\$0.00	
0280 -	Total						\$0.00	
0310	BRIDGE APPROACH S (MINOR RO			6	Aug 17, 2020	SYSTEM	(\$11,495.00)	
				6	Aug 17, 2020	SYSTEM	\$11,495.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
				7	Sep 2, 2020	SYSTEM	(\$11,495.00)	
				7	Sep 2, 2020	SYSTEM	\$11,495.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				8	Sep 16, 2020	SYSTEM	(\$11,495.00)	
				8	Sep 16, 2020	SYSTEM	\$11,495.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks			
0310	BRIDGE APPROACH SLAB (MINOR ROAD)	Material	Туре	9	Oct 1, 2020	SYSTEM	(\$11,495.00)				
				9	Oct 1, 2020	SYSTEM	\$11,495.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
				10	Oct 16, 2020	SYSTEM	(\$11,495.00)				
				10	Oct 16, 2020	SYSTEM	\$11,495.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
				11	Nov 2, 2020	SYSTEM	(\$11,495.00)				
				11	Nov 2, 2020	SYSTEM	\$11,495.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
			- Total				\$0.00				
	Material - Total						\$0.00				
0310 -	- Total						\$0.00				
0340	CLASS B CONCRETE (SUBSTRUCTURE)	Material		2	Jun 16, 2020	SYSTEM	(\$21,350.00)				
				2	Jun 16, 2020	SYSTEM	\$21,350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
				3	Jun 30, 2020	SYSTEM	(\$45,237.50)				
				3	Jun 30, 2020	SYSTEM	\$45,237.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
				4	Jul 16, 2020	SYSTEM	(\$45,237.50)				
				4	Jul 16, 2020	SYSTEM	\$45,237.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
				5	Aug 3, 2020	SYSTEM	(\$45,237.50)				
				5	Aug 3, 2020	SYSTEM	\$45,237.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
			- Total				\$0.00				
	Material - Total						\$0.00				
0340 -	- Total						\$0.00				
0350	SLAB ON CONCRETE I-GIRDER	Material		4	Jul 16, 2020	SYSTEM	(\$42,180.00)				
				4	Jul 16, 2020	SYSTEM	\$42,180.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.			
				5	Aug 3, 2020	SYSTEM	(\$200,355.00)				
							5	Aug 3, 2020	SYSTEM	\$200,355.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
								6	Aug 17, 2020	SYSTEM	(\$200,355.00)
				6	Aug 17, 2020	SYSTEM	\$200,355.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.			
				7	Sep 2, 2020	SYSTEM	(\$83,647.50)				
						7	Sep 2, 2020	SYSTEM	\$83,647.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
				8	Sep 16, 2020	SYSTEM	(\$83,647.50)				
				8	Sep 16, 2020	SYSTEM	\$83,647.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 14 on the current Payment Estimate.			



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0350	SLAB ON CONCRETE I-GIRDER	Material		9	Oct 1, 2020	SYSTEM	(\$83,647.50)	
				9	Oct 1, 2020	SYSTEM	\$83,647.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				10	Oct 16, 2020	SYSTEM	(\$94,477.50)	
				10	Oct 16, 2020	SYSTEM	\$94,477.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				11	Nov 2, 2020	SYSTEM	(\$94,477.50)	
				11	Nov 2, 2020	SYSTEM	\$94,477.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0350	- Total						\$0.00	
0360	SAFETY BARRIER CURB	Material		6	Aug 17, 2020	SYSTEM	(\$37,026.00)	
				6	Aug 17, 2020	SYSTEM	\$37,026.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user stokez1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0360	- Total						\$0.00	
0380	REINFORCING STEEL (BRIDGES)	Material		5	Aug 3, 2020	SYSTEM	(\$7,298.10)	
				5	Aug 3, 2020	SYSTEM	\$7,298.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Paymen Estimate Exception 10 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0380	Total						\$0.00	
0520	FURNISHING TYPE 2 ROCK BLANKET	Material		9	Oct 1, 2020	SYSTEM	(\$12,420.00)	
					2020		(0.2,120.00)	
				9	Oct 1, 2020	SYSTEM	\$12,420.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Paymen Estimate Exception 3 on the current Payment Estimate.
				9	Oct 1,	SYSTEM SYSTEM		Estimate Item Adjustment (0004) due to user stokez1 overridding Paymen
					Oct 1, 2020 Oct 16,		\$12,420.00	Estimate Item Adjustment (0004) due to user stokez1 overridding Paymen Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment
				10	Oct 1, 2020 Oct 16, 2020 Oct 16,	SYSTEM	\$12,420.00	Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment
				10	Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2,	SYSTEM SYSTEM	\$12,420.00 (\$12,420.00) \$12,420.00	Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment
			- Total	10 10 11	Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM	\$12,420.00 (\$12,420.00) \$12,420.00 (\$28,648.80)	Estimate Item Adjustment (0004) due to user stokez1 overridding Paymen Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Paymen Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Paymen
	Material - Total		- Total	10 10 11	Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM	\$12,420.00 (\$12,420.00) \$12,420.00 (\$28,648.80) \$28,648.80	Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment
0520	Material - Total		- Total	10 10 11	Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM	\$12,420.00 (\$12,420.00) \$12,420.00 (\$28,648.80) \$28,648.80 \$0.00	Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment
		Overrun	- Total Overrun	10 10 11 11	Oct 1, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM	\$12,420.00 (\$12,420.00) \$12,420.00 (\$28,648.80) \$28,648.80 \$0.00 \$0.00	Estimate Item Adjustment (0004) due to user stokez1 overridding Paymen Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Paymen Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Paymen
	- Total	Overrun		10 10 11 11 7	Oct 1,   2020   Oct 16,   2020   Oct 16,   2020   Nov 2,   2020   Nov 2,   2020   Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$12,420.00 (\$12,420.00) \$12,420.00 (\$28,648.80) \$28,648.80 \$28,648.80 \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0004) due to user stokez1 overridding Paymen Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Paymen Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Paymen
	- Total	Overrun	Overrun	10 10 11 11 7	Oct 1,   2020   Oct 16,   2020   Oct 16,   2020   Nov 2,   2020   Nov 2,   2020   Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$12,420.00 (\$12,420.00) \$12,420.00 (\$28,648.80) \$28,648.80 \$28,648.80 \$0.00 \$0.00 \$0.00 \$0.00 (\$180.00)	Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment
0540	Total CONSTRUCTION SIGNS	Overrun	Overrun	10 10 11 11 7	Oct 1,   2020   Oct 16,   2020   Oct 16,   2020   Nov 2,   2020   Nov 2,   2020   Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$12,420.00 (\$12,420.00) \$12,420.00 (\$28,648.80) \$28,648.80 \$28,648.80 \$0.00 \$0.00 (\$180.00) (\$180.00)	Estimate Item Adjustment (0004) due to user stokez1 overridding Paymer Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Paymer Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Paymer
0540	Total CONSTRUCTION SIGNS Overrun - Total		Overrun	10 10 11 11 7	Oct 1,   2020   Oct 16,   2020   Oct 16,   2020   Nov 2,   2020   Nov 2,   2020   Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$12,420.00 (\$12,420.00) \$12,420.00 (\$28,648.80) \$28,648.80 \$28,648.80 \$0.00 \$0.00 (\$180.00) (\$180.00) (\$180.00)	Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment
0540 0540	Total CONSTRUCTION SIGNS Overrun - Total Total		Overrun	10 10 11 11 7 7	Oct 1, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2, 2020 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$12,420.00 (\$12,420.00) \$12,420.00 (\$28,648.80) \$28,648.80 \$0.00 \$0.00 (\$180.00) (\$180.00) (\$180.00) (\$180.00)	Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
0650	ROCK DITCH CHECK	Material			2020				
				8	Sep 16, 2020	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0650 -	Total						\$0.00		
0680	TYPE C BERM	Material		7	Sep 2, 2020	SYSTEM	(\$4,035.00)		
				8	Sep 16, 2020	SYSTEM	(\$4,035.00)		
				8	Sep 16, 2020	SYSTEM	\$4,035.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
			- Total				(\$4,035.00)		
	Material - Total						(\$4,035.00)		
	TYPE C BERM	MaterialCredit		8	Sep 16, 2020	SYSTEM	\$4,035.00		
			- Total				\$4,035.00		
	MaterialCredit - Total						\$4,035.00		
0680 -	Total						\$0.00		
0770	DRILLED SHAFTS (3 FT. 6 IN. DIA.)	Material	Material		8	Sep 16, 2020	SYSTEM	(\$11,280.00)	
				8	Sep 16, 2020	SYSTEM	\$11,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
				9	Oct 1, 2020	SYSTEM	(\$11,280.00)		
				9	Oct 1, 2020	SYSTEM	\$11,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
				10	Oct 16, 2020	SYSTEM	(\$11,280.00)		
				10	Oct 16, 2020	SYSTEM	\$11,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
				11	Nov 2, 2020	SYSTEM	(\$11,280.00)		
				11	Nov 2, 2020	SYSTEM	\$11,280.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
			- Total				\$0.00		
	Material - Total						\$0.00		
0770 -	Total						\$0.00		
0780	ROCK SOCKETS (3 FT 0 IN. DIA.)	Material		8	Sep 16, 2020	SYSTEM	(\$14,880.00)		
				8	Sep 16, 2020	SYSTEM	\$14,880.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
				9	Oct 1, 2020	SYSTEM	(\$14,880.00)		
				9	Oct 1, 2020	SYSTEM	\$14,880.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
				10	Oct 16, 2020	SYSTEM	(\$14,880.00)		
				10	Oct 16, 2020	SYSTEM	\$14,880.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
				11	Nov 2, 2020	SYSTEM	(\$14,880.00)		
				11	Nov 2, 2020	SYSTEM	\$14,880.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0780		Material	- Total				\$0.00	
	Material - Total						\$0.00	
0780 -	Total						\$0.00	
0820	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	Material		8	Sep 16, 2020	SYSTEM	(\$24,210.15)	
	(,			8	Sep 16, 2020	SYSTEM	\$24,210.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0820 -	Total						\$0.00	
0840	PILE POINT REINFORCEMENT	Material		8	Sep 16, 2020	SYSTEM	(\$1,120.00)	
				8	Sep 16, 2020	SYSTEM	\$1,120.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user stokez1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total	1	1		\$0.00	
	Material - Total						\$0.00	
0840 -	Total						\$0.00	
0850	CLASS B CONCRETE (SUBSTRUCTURE)	Material		8	Sep 16, 2020	SYSTEM	(\$8,930.40)	
	(,			8	Sep 16, 2020	SYSTEM	\$8,930.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				9	Oct 1, 2020	SYSTEM	(\$36,160.80)	
				9	Oct 1, 2020	SYSTEM	\$36,160.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				10	Oct 16, 2020	SYSTEM	(\$36,160.80)	
				10	Oct 16, 2020	SYSTEM	\$36,160.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				11	Nov 2, 2020	SYSTEM	(\$36,160.80)	
				11	Nov 2, 2020	SYSTEM	\$36,160.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0850 -	Total						\$0.00	
0860	SAFETY BARRIER CURB	Material		11	Nov 2, 2020	SYSTEM	(\$28,780.35)	
				11	Nov 2, 2020	SYSTEM	\$28,780.35	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0860 -	Total						\$0.00	
0870	SLAB ON CONCRETE BEAM	Material		10	Oct 16, 2020	SYSTEM	(\$62,625.15)	
				10	Oct 16, 2020	SYSTEM	\$62,625.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
				11	Nov 2, 2020	SYSTEM	(\$111,333.60)	
				11	Nov 2, 2020	SYSTEM	\$111,333.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0870 -							\$0.00	
- 0010 -	Total						\$0.00	



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
Overall - Total							(\$3,254.40)	