

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 3, 2020

Progress Estimate Number	Contract ID	200117-F06	Pay Period Start	November 16, 2020	Original Contract Amount	\$3,235,828.41
16	Prime Contractor	r Parking Lot Maintenance, LLC	Pay Period End	November 30, 2020	Net Change Order Amount	\$146,476.64
10					Current Contract Amount	\$3,382,305.05

By User		Approval Date
dukesm1	Generated and Approved (and should be considered Draft) at the Project Office Level by	December 3, 2020
lewisj1	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	December 3, 2020
greggd1	Reviewed and Approved at the Central Office Controllers Office Level by	December 4, 2020

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2020	December 1, 2020	December 1, 2020	99.94%

Contract Informational Dates Milestones

\$90,815.39

Date Description	Original Completion Date	Current Completion Date
Acceptance Date		
Awarded Date	February 5, 2020	February 5, 2020
Letting Date	January 17, 2020	January 17, 2020
Notice to Proceed Date	April 6, 2020	April 6, 2020
Open to Traffic Date		
Work Began Date	April 20, 2020	April 20, 2020

Date Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days
Milestone - Calendar Time	July 21, 2020	July 21, 2020	Milestone Complete	
Total days allowed once bridge work begins				

Contract Total P	ay For Estimate No. 16			
		This Estimate	Previous	To Date
200117-F06				
	Total Posted Items Pay	\$58,660.69	\$3,321,503.68	\$3,380,164.37
	Gross Item Adjustments	\$32,154.70	(\$44,272.55)	(\$12,117.85)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	·		¢3 277 231 13	\$3,368,046,52

Items Paid This Estimate Period

Contract Total Payable This Estimate:

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3319	0130	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	SQYD	\$165.000	103	\$16,995.00
	0310	6181000	MOBILIZATION	LS	\$168,321.540	0.25	\$42,080.39
	0410	8051000A	SEEDING - COOL SEASON MIXTURES	ACRE	\$10,000.000	-0.02	(\$200.00)
	0440	8061019	SILT FENCE	LF	\$2.260	-95	(\$214.70)
Project J69	33319 - Tot	al					\$58,660,69

Project J6S3319 - Total \$58,660.69

Overall - Total \$58,660.69

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjustr	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3319	0040	CONCRETE APPROACH PAVEMENT	Material			-920.3	\$75.00	(\$69,022.50)
	0040	CONCRETE APPROACH PAVEMENT	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	920.3	\$75.00	\$69,022.50
	0800	SLOPE PROTECTION	MaterialCredit			112	\$110.00	\$12,320.00

Revision 4/1/2020 Page 1 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 3, 2020

Progress Estimate Number
16 Contract ID 200117-F06 Pay Period Start November 16, 2020 Original Contract Amount \$3,235,828.41
Prime Contractor Parking Lot Maintenance, LLC Pay Period End November 30, 2020 Net Change Order Amount \$146,476.64
Current Contract Amount \$3,382,305.05

ect ber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
319	0800	SLOPE PROTECTION	Material			-112	\$110.00	(\$12,320.00
	0130	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-1,388.775	\$165.00	(\$229,147.88
	0130	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	1,388.775	\$165.00	\$229,147.8
	0170	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-4,450	\$5.75	(\$25,587.5
	0170	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	4,450	\$5.75	\$25,587.50
	0180	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material			-28	\$3.75	(\$105.00
C	0180	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	28	\$3.75	\$105.00
	0190	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material			-451	\$2.45	(\$1,104.9
	0190	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) due to user dukesm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	451	\$2.45	\$1,104.9
	0410	SEEDING - COOL SEASON MIXTURES	MaterialCredit			0.02	\$10,000.00	\$200.0
	0440	SILT FENCE	MaterialCredit			95	\$2.26	\$214.7
	0540	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material			-330	\$275.00	(\$90,750.0
	0540	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	330	\$275.00	\$90,750.0
	0610	CLEANING AND EPOXY COATING	MaterialCredit			2,116	\$15.00	\$31,740.0
	0610	CLEANING AND EPOXY COATING	Material			-2,116	\$15.00	(\$31,740.0
	0610	CLEANING AND EPOXY COATING	Material		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	2,116	\$15.00	\$31,740.0

Revision 4/1/2020 Page 2 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					С	ontract Project Informatio	n						
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work						
J6S3319	FAS S501(60)	Resurface and bridge rehabilitation	A	ST CHARLES	from Route 61 to I-70	Route 61 to I-70							
Γotals by J	Job Numbe	rs											
J6S3319		d Item Pay Item Adjustm		Item Pay	This Estimate \$58,660.69 \$32,154.70 \$90,815.39	Previous \$3,321,503.68 (\$44,272.55) \$3,277,231.13	To Date \$3,380,164.37 (\$12,117.85) \$3,368,046.52						
	Liquio	tive centive lated Damages Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00						

Revision 4/1/2020 Page 3 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5031010A, Project Item Line Number 0540, Material Set 5031010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5031010A, Project Item Line Number 0540, Material Set 5031010A96, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Working with a material rep to resolve the exception.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5031010A, Project Item Line Number 0540, Material Set 5031010A96, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with a material rep to resolve the exception.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5031010A, Project Item Line Number 0540, Material Set 5031010A96, Material 1036RSDFEC42M22 - Rein Steel EC No. 7/M22 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5041000, Project Item Line Number 0040, Material Set 504100096, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5041000, Project Item Line Number 0040, Material Set 504100096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with a material rep to resolve the exception.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5041000, Project Item Line Number 0040, Material Set 504100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Working with a material rep to resolve the exception.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5041000, Project Item Line Number 0040, Material Set 504100096, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6116010A, Project Item Line Number 0080, Material Set 6116010A96, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6116010A, Project Item Line Number 0080, Material Set 6116010A96, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on the QC CRE20 report to resolve the exception.	dukesm1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6131010, Project Item Line Number 0130, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with a material rep to resolve the exception.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6131015, Project Item Line Number 0170, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6131015, Project Item Line Number 0170, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6131017, Project Item Line Number 0180, Material Set 613101796, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6131017, Project Item Line Number 0180, Material Set 613101796, Material 1057JMDBEC6.11 - Dowel Bar Epoxy Ctd Gr60 1 1/4 @, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6131018, Project Item Line Number 0190, Material Set 613101896, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6131018, Project Item Line Number 0190, Material Set 613101896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 6131018, Project Item Line Number 0190, Material Set 613101896, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL approval from Jeff City.	dukesm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 7040113, Project Item Line Number 0610, Material Set 704011396, Material 1039ERBCT3 - Type III Epoxy Resin for Conc Patch Cmp, Acceptance Action Generic 1039ERBCT3 is insufficient.	Working with a material rep to resolve the exception.	dukesm1	Overridden

Revision 4/1/2020 Page 4 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
00117-F06	J6S3319	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$56,000.00	\$56,000.00
		0001	0020	2063000	CLASS 3 EXCAVATION	12.00	-8.00	4.00	CUYD	4.00	\$75.00	\$300.00
		0001	0030	2153000	SHAPING SLOPES, CLASS III	5.00	0.00	5.00	100F	5.00	\$900.00	\$4,500.00
		0001	0040	5041000	CONCRETE APPROACH PAVEMENT	920.30	0.00	920.30	SQYD	920.30	\$75.00	\$69,022.50
		0001	0050	6094010	DRAIN BASIN	2.00	0.00	2.00	EA	2.00	\$4,400.00	\$8,800.00
		0001	0060	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	7.00	0.00	7.00	CUYD	7.00	\$27.00	\$189.00
		0001	0070	6096041	PLACING TYPE 1 ROCK DITCH LINER	7.00	0.00	7.00	CUYD	7.00	\$105.00	\$735.00
		0001	0080	6116010A	SLOPE PROTECTION	222.00	-110.00	112.00	SQYD	112.00	\$110.00	\$12,320.00
		0001	0090	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	2.00	\$3,010.00	\$6,020.00
		0001	0100	6122020	REPLACEMENT SAND BARREL	3.00	-3.00	0.00	EA	0.00	\$396.00	\$0.00
		0001	0110	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	0.00	2.00	EA	2.00	\$687.00	\$1,374.00
		0001	0120	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$6,000.00	\$12,000.00
		0001	0130	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	3,536.00	103.00	3,639.00	SQYD	3,639.00	\$165.00	\$600,435.00
		0001	0140	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	444.00	-444.00	0.00	SQYD	0.00	\$20.00	\$0.00
		0001	0150	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)	354.00	-354.00	0.00	SQYD	0.00	\$2.50	\$0.00
			0160	6131014	(PAVEMENT REPAIR) FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER	14,694.00	0.00	14,694.00	LF	14,694.00	\$3.00	\$44,082.00
		0001			AND INTERNAL SAW CUTS)							
		0001	0170	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	4,450.00	0.00	4,450.00	EA	4,450.00	\$5.75	\$25,587.50
		0001	0180	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	28.00	0.00	28.00	EA	28.00	\$3.75	\$105.00
		0001	0190	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	451.00	0.00	451.00	EA	451.00	\$2.45	\$1,104.9
		0001	0200	6139911	MISC.REMOVAL, FURNISHING AND PLACING HOT POLYMER CONCRETE PATCHING FOR CLASS A PARTIAL DEPTH PVMT REPAIR	401,792.00	49,342.00	451,134.00	LB	451,134.00	\$3.35	\$1,511,298.90
		0001	0210	6161005	CONSTRUCTION SIGNS	798.00	0.00	798.00	SQFT	798.00	\$8.00	\$6,384.0
		0001	0220	6161008	ADVANCED WARNING RAIL SYSTEM	22.00	0.00	22.00	EA	22.00	\$35.00	\$770.0
		0001	0230	6161009	FLAG ASSEMBLY	15.00	-15.00	0.00	EA	0.00	\$25.00	\$0.0
		0001	0240	6161025	CHANNELIZER (TRIM LINE)	364.00	0.00	364.00	EA	364.00	\$20.00	\$7,280.0
		0001	0250	6161030	TYPE III MOVEABLE BARRICADE	8.00	-8.00	0.00	EA	0.00	\$100.00	\$0.0
		0001	0260	6161033	DIRECTIONAL INDICATOR BARRICADE	44.00	0.00	44.00	EA	44.00	\$65.00	\$2,860.0
		0001	0270	6161040	FLASHING ARROW PANEL	3.00	0.00	3.00	EA	3.00	\$850.00	\$2,550.0
		0001	0280	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED / RETAINED	2.00	0.00	2.00	EA	2.00	\$2,800.00	\$5,600.00
		0001	0290	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,050.00	0.00	1,050.00	LF	1,050.00	\$21.94	\$23,037.0
		0001	0300	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	1,050.00	0.00	1,050.00	LF	1,050.00	\$7.02	\$7,369.9
		0001	0310	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$168,321.54	\$168,321.5
		0001	0320	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	3.00	0.00	3.00	EA	3.00	\$350.00	\$1,050.00
		0001	0330	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	5,511.00	0.00	5,511.00	LF	5,511.00	\$1.00	\$5,511.0
		0001	0340	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	8,663.00	0.00	8,663.00	LF	8,663.00	\$1.00	\$8,663.0
		0001	0350	6205440A	TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT ARROW	1.00	0.00	1.00	EA	1.00	\$300.00	\$300.0
		0001	0360	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6,220.00	0.00	6,220.00	LF	6,220.00	\$0.25	\$1,555.0
		0001	0370	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	9,952.00	0.00	9,952.00	LF	9,952.00	\$0.25	\$2,488.0
		0001	0380	6207001	PAVEMENT MARKING REMOVAL	25,370.00	0.00	25,370.00	LF	25,370.00	\$0.75	\$19,027.5
		0001	0390	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	5.00	0.00	5.00	EA	5.00	\$100.00	\$500.0
		0001	0400	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$1,500.00	\$0.0
		0001	0410	8051000A	SEEDING - COOL SEASON MIXTURES	0.10	-0.08	0.02	ACRE	0.00	\$10,000.00	\$0.00
		0001	0420	8061005	ROCK DITCH CHECK	60.00	-60.00	0.00	LF	0.00	\$50.00	\$0.00
		0001	0430	8061016	SEDIMENT REMOVAL	8.00	-8.00	0.00	CUYD	0.00	\$31.25	\$0.00

Revision 4/1/2020 Page 5 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-F06	J6S3319	0001	0440	8061019	SILT FENCE	405.00	-210.00	195.00	LF	0.00	\$2.26	\$0.00
		0010	0450	6061060	MGS GUARDRAIL	213.00	0.00	213.00	LF	213.00	\$21.00	\$4,473.00
		0010	0460	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	2,650.00	0.00	2,650.00	LF	2,650.00	\$23.00	\$60,950.00
		0010	0470	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	4.00	0.00	4.00	EA	4.00	\$3,000.00	\$12,000.00
		0010	0480	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	1.00	\$1,000.00	\$1,000.00
		0010	0490	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	5.00	0.00	5.00	EA	5.00	\$2,800.00	\$14,000.00
		0070	0500	2161000	SCARIFICATION OF BRIDGE DECK	3,003.00	0.00	3,003.00	SQYD	3,003.00	\$6.67	\$20,030.01
		0070	0510	2161503	REMOVAL OF EXISTING DECK REPAIR	25.00	0.00	25.00	SQFT	25.00	\$71.00	\$1,775.00
		0070	0520	2169903	MISC.Remove and Replace Barrier Curb	10.00	1.00	11.00	LF	11.00	\$350.00	\$3,850.00
		0070	0530	2169904	MISC.Removal of Existing Approach Slab	4,784.00	0.00	4,784.00	SQFT	4,784.00	\$6.00	\$28,704.00
		0070	0540	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	330.00	0.00	330.00	SQYD	330.00	\$275.00	\$90,750.00
		0070	0550	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	3,003.00	0.00	3,003.00	SQYD	3,003.00	\$85.00	\$255,255.00
		0070	0560	7031004	DIAMOND GRINDING	3,003.00	-3,003.00	0.00	SQYD	0.00	\$6.32	\$0.00
		0070	0570	7039902	MISC.Pile Encasement	25.00	0.00	25.00	EA	25.00	\$2,300.00	\$57,500.00
		0070	0580	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	200.00	-195.50	4.50	SQFT	4.50	\$15.00	\$67.50
		0070	0590	7040106	FULL DEPTH REPAIR	200.00	-200.00	0.00	SQFT	0.00	\$40.00	\$0.00
		0070	0600	7040109	TOTAL SURFACE HYDRO DEMOLITION	3,003.00	0.00	3,003.00	SQYD	3,003.00	\$43.00	\$129,129.00
		0070	0610	7040113	CLEANING AND EPOXY COATING	2,116.00	0.00	2,116.00	SQFT	2,116.00	\$15.00	\$31,740.00
		0070	0620	7040117	MONOLITHIC DECK REPAIR	41.00	33.00	74.00	CUYD	74.00	\$700.00	\$51,800.00
	Project J	6S3319 - To	otal Value	Posted to D	late as of Report Generated Date							\$3,380,164.35
200117-F06 Ove	rall - Total	Value Post	ed to Dat	e as of Repo	ort Generated Date							\$3,380,164.35

Revision 4/1/2020 Page 6 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6S3319

Line Number	Item Code	Description	DWR Date	DWR Approval Date		Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0130	6131010	FURN & PLACE CONC MATL FOR FULL DEPTH	11/27/20	12/1/20	103.00	SQYD		6+33		144+00		
0310	6181000	MOBILIZATION	11/30/20	12/3/20	0.25	LS		6+33		145+50		
0410	8051000A	SEEDING - COOL SEASON MIXTURES	11/30/20	12/3/20	-0.02	ACRE		6+33		145+50		
0440	8061019	SILT FENCE	11/30/20	12/3/20	-95.00	LF		6+33				

The information below this line are details from Line Item agency views. No Agency View Details Exist

Revision 4/1/2020 Page 7 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0040	CONCRETE APPROACH PAVEMENT	Material	.,	5	Jun 15, 2020	SYSTEM	(\$34,509.75)	
				6	Jul 1, 2020	SYSTEM	(\$34,509.75)	
				7	Jul 16, 2020	SYSTEM	(\$69,022.50)	
				8	Aug 4, 2020	SYSTEM	(\$69,022.50)	
				9	Aug 18, 2020	SYSTEM	(\$69,022.50)	
				10	Sep 2, 2020	SYSTEM	(\$69,022.50)	
				11	Sep 16, 2020	SYSTEM	(\$69,022.50)	
				11	Sep 16, 2020	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dukesm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$69,022.50)	
				12	Oct 2, 2020	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dukesm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$69,022.50)	
				13	Oct 16, 2020	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$69,022.50)	
				14	Nov 2, 2020	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				15	Nov 16, 2020	SYSTEM	(\$69,022.50)	
				15	Nov 16, 2020	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				16	Dec 3, 2020	SYSTEM	(\$69,022.50)	
				16	Dec 3, 2020	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
			- Total				(\$345,109.50)	
	Material - Total						(\$345,109.50)	
	CONCRETE APPROACH PAVEMENT	MaterialCredit		6	Jul 1, 2020	SYSTEM	\$34,509.75	
				7	Jul 16, 2020	SYSTEM	\$34,509.75	
				8	Aug 4, 2020	SYSTEM	\$69,022.50	
				9	Aug 18, 2020	SYSTEM	\$69,022.50	
				10	Sep 2, 2020	SYSTEM	\$69,022.50	
				11	Sep 16, 2020	SYSTEM	\$69,022.50	
			- Total				\$345,109.50	
	MaterialCredit - Total						\$345,109.50	
0040	- Total						\$0.00	
0050	DRAIN BASIN	Material		11	Sep 16, 2020	SYSTEM	(\$8,800.00)	

Revision 4/1/2020 Page 8 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0050	DRAIN BASIN	Material		11	Sep 16, 2020	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$8,800.00)	
				12	Oct 2, 2020	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$8,800.00)	
				13	Oct 16, 2020	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				\$0.00	
0050	Material - Total						\$0.00	
0050 - 0060	FURNISHING TYPE 1 ROCK DITCH LINER	Material		11	Sep 16,	SYSTEM	\$0.00 (\$189.00)	
0000	FURNISHING TYPE I ROCK DITCH LINER	iviateriai		11	2020	SYSTEM	(\$169.00)	
				11	Sep 16, 2020	SYSTEM	\$189.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$189.00)	
				12	Oct 2, 2020	SYSTEM	\$189.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0060 -	·Total						\$0.00	
0800	SLOPE PROTECTION	Material		8	Aug 4, 2020	SYSTEM	(\$12,320.00)	
				9	Aug 18, 2020	SYSTEM	(\$12,320.00)	
					2020			
				10	Sep 2, 2020	SYSTEM	(\$12,320.00)	
				10	Sep 2,	SYSTEM SYSTEM	(\$12,320.00)	
					Sep 2, 2020 Sep 16,			
				11	Sep 2, 2020 Sep 16, 2020 Oct 1,	SYSTEM	(\$12,320.00)	
				11 12	Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 16,	SYSTEM SYSTEM	(\$12,320.00) (\$12,320.00)	
				11 12 13	Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM	(\$12,320.00) (\$12,320.00) (\$12,320.00)	
				11 12 13 14	Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Nov 2, 2020 Nov 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00)	
			- Total	11 12 13 14	Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Nov 2, 2020 Nov 16, 2020 Dec 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00)	
	Material - Total		- Total	11 12 13 14	Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Nov 2, 2020 Nov 16, 2020 Dec 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00)	
	Material - Total SLOPE PROTECTION	MaterialCredit	- Total	11 12 13 14	Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Nov 2, 2020 Nov 16, 2020 Dec 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00) (\$110,880.00)	
		MaterialCredit	- Total	11 12 13 14 15 16	Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Nov 2, 2020 Nov 16, 2020 Dec 3, 2020 Aug 18,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00) (\$110,880.00) (\$110,880.00)	
		MaterialCredit	- Total	11 12 13 14 15 16	Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Nov 2, 2020 Nov 16, 2020 Dec 3, 2020 Aug 18, 2020 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00) (\$110,880.00) (\$110,880.00)	
		MaterialCredit	- Total	11 12 13 14 15 16	Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Nov 2, 2020 Dec 3, 2020 Aug 18, 2020 Sep 2, 2020 Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00) (\$110,880.00) (\$110,880.00) \$12,320.00	
		MaterialCredit	- Total	11 12 13 14 15 16	Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 16, 2020 Nov 2, 2020 Dec 3, 2020 Aug 18, 2020 Sep 2, 2020 Sep 16, 2020 Oct 1,	SYSTEM	(\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00) (\$12,320.00) (\$110,880.00) (\$110,880.00) \$12,320.00 \$12,320.00	

Revision 4/1/2020 Page 9 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0080	SLOPE PROTECTION	MaterialCredit		15	Nov 16, 2020	SYSTEM	\$12,320.00	
				16	Dec 3, 2020	SYSTEM	\$12,320.00	
			- Total				\$98,560.00	
	MaterialCredit - Total						\$98,560.00	
0080 -	Total						(\$12,320.00)	
0130	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		10	Sep 2, 2020	SYSTEM	(\$583,440.00)	
	REPAIR			11	Sep 16, 2020	SYSTEM	(\$583,440.00)	
				11	Sep 16, 2020	SYSTEM	\$583,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$583,440.00)	
				12	Oct 2, 2020	SYSTEM	\$583,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user dukesm1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$583,440.00)	
				13	Oct 16, 2020	SYSTEM	\$583,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$583,440.00)	
				14	Nov 2, 2020	SYSTEM	\$583,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				15	Nov 16, 2020	SYSTEM	(\$583,440.00)	
				15	Nov 16, 2020	SYSTEM	\$583,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				16	Dec 3, 2020	SYSTEM	(\$229,147.88)	
				16	Dec 3, 2020	SYSTEM	\$229,147.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				(\$583,440.00)	
	Material - Total						(\$583,440.00)	
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	MaterialCredit		11	Sep 16, 2020	SYSTEM	\$583,440.00	
			- Total				\$583,440.00	
	MaterialCredit - Total						\$583,440.00	
0130 -	Total						\$0.00	
0170	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		9	Aug 18, 2020	SYSTEM	(\$9,890.00)	
	PAVEINENT REPAIR			10	Sep 2, 2020	SYSTEM	(\$25,587.50)	
				10	Sep 2, 2020	SYSTEM	\$25,587.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$25,587.50)	
				11	Sep 16, 2020	SYSTEM	\$25,587.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 23 on the current Payment Estimate.

Revision 4/1/2020 Page 10 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
0170	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		12	Oct 1, 2020	SYSTEM	(\$25,587.50)				
	PAVEMENT REPAIR			12	Oct 2, 2020	SYSTEM	\$25,587.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 22 on the current Payment Estimate.			
				13	Oct 16, 2020	SYSTEM	(\$25,587.50)				
				13	Oct 16, 2020	SYSTEM	\$25,587.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 20 on the current Payment Estimate.			
				14	Nov 2, 2020	SYSTEM	(\$25,587.50)				
				14	Nov 2, 2020	SYSTEM	\$25,587.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.			
				15	Nov 16, 2020	SYSTEM	(\$25,587.50)				
				15	Nov 16, 2020	SYSTEM	\$25,587.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 15 on the current Payment Estimate.			
				16	Dec 3, 2020	SYSTEM	(\$25,587.50)				
				16	Dec 3, 2020	SYSTEM	\$25,587.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.			
			- Total				(\$9,890.00)				
	Material - Total						(\$9,890.00)				
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	MaterialCredit		10	Sep 2, 2020	SYSTEM	\$9,890.00				
			- Total				\$9,890.00				
	MaterialCredit - Total						\$9,890.00				
	- Total						\$0.00				
0180	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material		9	Aug 18, 2020	SYSTEM	(\$45.00)				
				10	Sep 2, 2020	SYSTEM	(\$105.00)				
				10	Sep 2, 2020	SYSTEM	\$105.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 21 on the current Payment Estimate.			
				11	Sep 16, 2020	SYSTEM	(\$105.00)				
							11	Sep 16, 2020	SYSTEM	\$105.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$105.00)				
				12	Oct 2, 2020	SYSTEM	\$105.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate.			
				13	Oct 16, 2020	SYSTEM	(\$105.00)				
				13	Oct 16, 2020	SYSTEM	\$105.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 22 on the current Payment Estimate.			
				14	Nov 2, 2020	SYSTEM	(\$105.00)				
				14	Nov 2, 2020	SYSTEM	\$105.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 18 on the current			

Revision 4/1/2020 Page 11 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0180	DOWEL BAR (FURNISHING AND	Material						Payment Estimate.
	INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR			15	Nov 16, 2020	SYSTEM	(\$105.00)	
				15	Nov 16, 2020	SYSTEM	\$105.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				16	Dec 3, 2020	SYSTEM	(\$105.00)	
				16	Dec 3, 2020	SYSTEM	\$105.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
			- Total				(\$45.00)	
	Material - Total						(\$45.00)	
	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	MaterialCredit		10	Sep 2, 2020	SYSTEM	\$45.00	
			- Total				\$45.00	
	MaterialCredit - Total						\$45.00	
	- Total						\$0.00	
0190	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material		9	Aug 18, 2020	SYSTEM	(\$485.10)	
				10	Sep 2, 2020	SYSTEM	(\$1,104.95)	
				10	Sep 2, 2020	SYSTEM	\$1,104.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$1,104.95)	
				11	Sep 16, 2020	SYSTEM	\$1,104.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$1,104.95)	
				12	Oct 2, 2020	SYSTEM	\$1,104.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$1,104.95)	
				13	Oct 16, 2020	SYSTEM	\$1,104.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
				14	Nov 2, 2020	SYSTEM	(\$1,104.95)	
				14	Nov 2, 2020	SYSTEM	\$1,104.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
				15	Nov 16, 2020	SYSTEM	(\$1,104.95)	
				15	Nov 16, 2020	SYSTEM	\$1,104.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
				16	Dec 3, 2020	SYSTEM	(\$1,104.95)	
				16	Dec 3, 2020	SYSTEM	\$1,104.95	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user dukesm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
			- Total				(\$485.10)	
	Material - Total						(\$485.10)	
	TIE BAR (DRILLING, FURNISHING AND	MaterialCredit		10	Sep 2,	SYSTEM	\$485.10	

Revision 4/1/2020 Page 12 of 19



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Line	Description	Туре	Adjustment Type		Date	By	Amount	Neillains
0190	INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	MaterialCredit			2020			
			- Total				\$485.10	
	MaterialCredit - Total						\$485.10	
0190 -	- Total						\$0.00	
0200	MISC. REMOVAL, FURNISHING AND PLACING HOT POLYMER CONCRETE	Overrun	Overrun	8	Aug 4, 2020	SYSTEM	(\$117,819.50)	
	PATCHING FOR CLASS A PARTIAL DEPTH PVMT REPAIR			9	Aug 18, 2020	SYSTEM	(\$47,476.20)	
				12	Oct 1, 2020	SYSTEM	\$165,295.70	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3.35000 - 3.35000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0200 -	· Total						\$0.00	
0320	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT	Material		11	Sep 16, 2020	SYSTEM	(\$1,050.00)	
	ARROW			11	Sep 16, 2020	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$1,050.00)	
				12	Oct 2, 2020	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$1,050.00)	
				13	Oct 16, 2020	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0320 -	- Total						\$0.00	
0330	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		3	May 18, 2020	SYSTEM	(\$2,591.00)	
			- Total				(\$2,591.00)	
	Material - Total						(\$2,591.00)	
	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	MaterialCredit		4	Jun 2, 2020	SYSTEM	\$2,591.00	
			- Total				\$2,591.00	
	MaterialCredit - Total						\$2,591.00	
0330	- Total						\$0.00	
0340	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material		3	May 18, 2020	SYSTEM	(\$4,163.00)	
			- Total				(\$4,163.00)	
	Material - Total						(\$4,163.00)	
	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	MaterialCredit		4	Jun 2, 2020	SYSTEM	\$4,163.00	
			- Total				\$4,163.00	
	MaterialCredit - Total						\$4,163.00	
0340	- Total						\$0.00	
0350	TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT ARROW	Material		3	May 18, 2020	SYSTEM	(\$300.00)	
			- Total				(\$300.00)	
	Material - Total						(\$300.00)	
	TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT ARROW	MaterialCredit		4	Jun 2, 2020	SYSTEM	\$300.00	
			- Total				\$300.00	

Revision 4/1/2020 Page 13 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0350	MaterialCredit - Total						\$300.00	
0350 -	- Total						\$0.00	
0360	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P	Material		11	Sep 16, 2020	SYSTEM	(\$1,555.00)	
	BEADS			11	Sep 16, 2020	SYSTEM	\$1,555.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user dukesm1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$1,555.00)	
				12	Oct 2, 2020	SYSTEM	\$1,555.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL	15	Nov 16, 2020	dukesm1	\$77.75	This item adjustment is to pay a bonus for the Retroreflectivity results.
			REFL - Tota	ı			\$77.75	
	Other Item Adjustment - Total						\$77.75	
0360 -	- Total						\$77.75	
0370	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING	Material		11	Sep 16, 2020	SYSTEM	(\$2,488.00)	
	PAINT, TYPE P BEADS			11	Sep 16, 2020	SYSTEM	\$2,488.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user dukesm1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$2,488.00)	
				12	Oct 2, 2020	SYSTEM	\$2,488.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user dukesm1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL	15	Nov 16, 2020	dukesm1	\$124.40	This item adjustment is to pay a bonus for the Retroreflectivity results.
			REFL - Tota	ıl			\$124.40	
	Other Item Adjustment - Total						\$124.40	
0370 -	- Total						\$124.40	
0410	SEEDING - COOL SEASON MIXTURES	Material		11	Sep 16, 2020	SYSTEM	(\$200.00)	
				12	Oct 1, 2020	SYSTEM	(\$200.00)	
				13	Oct 16, 2020	SYSTEM	(\$200.00)	
				14	Nov 2, 2020	SYSTEM	(\$200.00)	
				15	Nov 16, 2020	SYSTEM	(\$200.00)	
	Material Total		- Total				(\$1,000.00)	
	Material - Total	Mata: 16		40	0.1.1	OVOTELL	(\$1,000.00)	
	SEEDING - COOL SEASON MIXTURES	MaterialCredit		12	Oct 1, 2020	SYSTEM	\$200.00	
				13	Oct 16, 2020	SYSTEM	\$200.00	
				14	Nov 2, 2020	SYSTEM	\$200.00	
				15	Nov 16, 2020	SYSTEM	\$200.00	
				16	Dec 3, 2020	SYSTEM	\$200.00	

Revision 4/1/2020 Page 14 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0410		MaterialCredit	- Total				\$1,000.00	
	MaterialCredit - Total						\$1,000.00	
0410 -	Total						\$0.00	
0440	SILT FENCE	Material		11	Sep 16, 2020	SYSTEM	(\$214.70)	
				12	Oct 1, 2020	SYSTEM	(\$214.70)	
				13	Oct 16, 2020	SYSTEM	(\$214.70)	
				14	Nov 2, 2020	SYSTEM	(\$214.70)	
				15	Nov 16, 2020	SYSTEM	(\$214.70)	
			- Total				(\$1,073.50)	
	Material - Total						(\$1,073.50)	
	SILT FENCE	MaterialCredit		12	Oct 1, 2020	SYSTEM	\$214.70	
				13	Oct 16, 2020	SYSTEM	\$214.70	
				14	Nov 2, 2020	SYSTEM	\$214.70	
				15	Nov 16, 2020	SYSTEM	\$214.70	
				16	Dec 3, 2020	SYSTEM	\$214.70	
			- Total				\$1,073.50	
	MaterialCredit - Total						\$1,073.50	
0440 -	·Total						\$0.00	
0450	MGS GUARDRAIL	Construction Stockpile		2	May 4, 2020	SYSTEM	\$2,270.58	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Aug 4, 2020	SYSTEM	(\$2,270.58)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0450 -							\$0.00	
0460	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Construction Stockpile		2	May 4, 2020	SYSTEM	\$33,204.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				5	Jun 15, 2020	SYSTEM	(\$11,602.78)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Jul 16, 2020	SYSTEM	(\$20,048.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Aug 4, 2020	SYSTEM	(\$1,553.72)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0460 -	·Total						\$0.00	
0470	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	Construction Stockpile		2	May 4, 2020	SYSTEM	\$6,200.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				5	Jun 15, 2020	SYSTEM	(\$3,100.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Jul 16, 2020	SYSTEM	(\$3,100.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0470 -	· Total						\$0.00	
0480	MGS END ANCHOR	Construction Stockpile		2	May 4, 2020	SYSTEM	\$535.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Jul 16, 2020	SYSTEM	(\$535.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	

Revision 4/1/2020 Page 15 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
0480	Construction Stockpile - Total		31				\$0.00														
0480 -	Total						\$0.00														
0490	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		2	May 4, 2020	SYSTEM	\$7,550.00	Payment Estimate Item Adjustment generated Stockpile Transaction													
				5	Jun 15, 2020	SYSTEM	(\$1,510.00)	Payment Estimate Item Adjustment generated Stockpile Transaction													
				8	Aug 4, 2020	SYSTEM	(\$6,040.00)	Payment Estimate Item Adjustment generated Stockpile Transaction													
			- Total				\$0.00														
	Construction Stockpile - Total						\$0.00														
0490 -							\$0.00														
0520	MISC. Remove and Replace Barrier Curb	Overrun	Overrun	4	Jun 2, 2020	SYSTEM	(\$350.00)														
				4	Jun 2, 2020	SYSTEM	\$350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.													
				5	Jun 15, 2020	SYSTEM	(\$350.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).													
				12	Oct 1, 2020	SYSTEM	\$350.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',350.00000 - 350.00000, 'is applied (if non-zero).													
			Overrun - T	otal			\$0.00														
	Overrun - Total						\$0.00														
0520 -	Total						\$0.00														
0540	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		5	Jun 15, 2020	SYSTEM	(\$45,375.00)														
				6	Jul 1, 2020	SYSTEM	(\$45,375.00)														
				7	Jul 16, 2020	SYSTEM	(\$90,750.00)														
				8	Aug 4, 2020	SYSTEM	(\$90,750.00)														
				9	Aug 18, 2020	SYSTEM	(\$90,750.00)														
				10	Sep 2, 2020	SYSTEM	(\$90,750.00)														
				10	Sep 2, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.													
				11	Sep 16, 2020	SYSTEM	(\$90,750.00)														
				11	Sep 16, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
				12	Oct 1, 2020	SYSTEM	(\$90,750.00)														
																	12	Oct 2, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$90,750.00)														
				13	Oct 16, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
				14	Nov 2, 2020	SYSTEM	(\$90,750.00)														
				14	Nov 2, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
				15	Nov 16,	SYSTEM	(\$90,750.00)														

Revision 4/1/2020 Page 16 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
0540	BRIDGE APPROACH SLAB (MAJOR	Material			2020														
	ROAD)			15	Nov 16, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.											
				16	Dec 3, 2020	SYSTEM	(\$90,750.00)												
				16	Dec 3, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.											
			- Total				(\$363,000.00)												
	Material - Total						(\$363,000.00)												
	BRIDGE APPROACH SLAB (MAJOR ROAD)	MaterialCredit		6	Jul 1, 2020	SYSTEM	\$45,375.00												
				7	Jul 16, 2020	SYSTEM	\$45,375.00												
				8	Aug 4, 2020	SYSTEM	\$90,750.00												
				9	Aug 18, 2020	SYSTEM	\$90,750.00												
				10	Sep 2, 2020	SYSTEM	\$90,750.00												
			- Total				\$363,000.00												
	MaterialCredit - Total						\$363,000.00												
0540 -	Total						\$0.00												
0550	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		4	Jun 2, 2020	SYSTEM	(\$127,627.50)												
				5	Jun 15, 2020	SYSTEM	(\$127,627.50)												
				6	Jul 1, 2020	SYSTEM	(\$255,255.00)												
				7	Jul 16, 2020	SYSTEM	(\$102,101.83)												
				8	Aug 4, 2020	SYSTEM	(\$102,101.83)												
				8	Aug 4, 2020	SYSTEM	\$102,101.83	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 17 on the current Payment Estimate.											
				9	Aug 18, 2020	SYSTEM	(\$102,101.83)												
				9	Aug 18, 2020	SYSTEM	\$102,101.83	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user brookw1 overridding Payment Estimate Exception 16 on the current Payment Estimate.											
														10	Sep 2, 2020	SYSTEM	(\$102,101.83)		
					10	Sep 2, 2020	SYSTEM	\$102,101.83	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.										
				11	Sep 16, 2020	SYSTEM	(\$102,101.83)												
																11	Sep 16, 2020	SYSTEM	\$102,101.83
				12	Oct 1, 2020	SYSTEM	(\$102,101.83)												
					12	Oct 2, 2020	SYSTEM	\$102,101.83	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user dukesm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.										
				13	Oct 16, 2020	SYSTEM	(\$102,101.83)												
				13	Oct 16,	SYSTEM	\$102,101.83	This adjustment offsets the original system-generated Overrun											

Revision 4/1/2020 Page 17 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0550	LATEX MODIFIED CONCRETE WEARING SURFACE	Material			2020			Payment Estimate Item Adjustment (0015) due to user dukesm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				(\$612,611.83)	
	Material - Total						(\$612,611.83)	
	LATEX MODIFIED CONCRETE WEARING SURFACE	MaterialCredit		5	Jun 15, 2020	SYSTEM	\$127,627.50	
				6	Jul 1, 2020	SYSTEM	\$127,627.50	
				7	Jul 16, 2020	SYSTEM	\$255,255.00	
			Takal	8	Aug 4, 2020	SYSTEM	\$102,101.83	
	44 · 1 · 10 · 10 · 17 · 1	- Total				\$612,611.83		
0.00	MaterialCredit - Total					\$612,611.83		
0550 - 0580	SUBSTRUCTURE REPAIR (UNFORMED)	Material		11	Sep 16, 2020	SYSTEM	\$0.00 (\$67.50)	
			- Total		2020		(\$67.50)	
	Material - Total						(\$67.50)	
	SUBSTRUCTURE REPAIR (UNFORMED)	MaterialCredit		12	Oct 1, 2020	SYSTEM	\$67.50	
			- Total				\$67.50	
	MaterialCredit - Total						\$67.50	
0580 -	l · Total						\$0.00	
0610	CLEANING AND EPOXY COATING	Material		11	Sep 16, 2020	SYSTEM	(\$31,740.00)	
				12	Oct 1, 2020	SYSTEM	(\$31,740.00)	
				13	Oct 16, 2020	SYSTEM	(\$31,740.00)	
				14	Nov 2, 2020	SYSTEM	(\$31,740.00)	
				15	Nov 16, 2020	SYSTEM	(\$31,740.00)	
				16	Dec 3, 2020	SYSTEM	(\$31,740.00) \$31,740.00	This adjustment offsets the original system-generated Overrun
				10	2020	STSTEM	φ31,740.00	Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
		- Total				(\$158,700.00)		
	Material - Total						(\$158,700.00)	
	CLEANING AND EPOXY COATING MaterialCr	MaterialCredit		12	Oct 1, 2020	SYSTEM	\$31,740.00	
				13	Oct 16, 2020	SYSTEM	\$31,740.00	
				14	Nov 2, 2020	SYSTEM	\$31,740.00	
				15	Nov 16, 2020	SYSTEM	\$31,740.00 \$31,740.00	
			- Total	10	2020	SISIEW	\$1,740.00	
	MaterialCredit - Total						\$158,700.00	
0610 -							\$0.00	
0620	MONOLITHIC DECK REPAIR	Overrun	Overrun	8	Aug 4, 2020	SYSTEM	(\$23,100.00)	
				11	Sep 16, 2020	SYSTEM	\$23,100.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',700.00000 - 700.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	

Revision 4/1/2020 Page 18 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0620	Overrun - Total						\$0.00	
0620 -	Total				\$0.00			
Overa	II - Total				(\$12,117.85)			

Revision 4/1/2020 Page 19 of 19