

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: February 2, 2021

April 6, 2020

April 20, 2020

April 6, 2020

April 20, 2020

\$3,235,828.41 \$146,276.64 \$3,382,105.05	inge Order Amount	ate Number Contract ID 200117-F06 Pay Period Start January 16, 2021 Original Contract Amount Prime Contractor Parking Lot Maintenance, LLC Pay Period End February 1, 2021 Net Change Order Amount Current Contract Amount							
By User							,	Approval Date	
dukesm1	t Office Level by	Draft) at the Projec	nould be considered	nd Approved (and s	Generated and			February 2, 2021	
lewisj1		February 2, 2021							
greggd1	Reviewed and Approved at the Central Office Controllers Office Level by gregge								
Complete	t Contract Amount C	% of Curren	on Date Actual Completion Date			Original Completion Date Current Compl			
	100.00%		er 1, 2020	Decemb	, 2020	December 1,	r 1, 2020	Decembe	
		estones	Mil			Dates	tract Informational	Con	
Charge	Days Remaining on Milestone	Current Completion Date	Original Completion Date	e Description	Date I	Current Completion Date	Original Completion Date	Date Description	
Days	Milestone Complete	July 21, 2020	July 21, 2020	- Calendar Time	Milestone - C	December 1, 2020	December 1, 2020	Acceptance Date	
				allowed once	Total days allowed once		February 5, 2020	Awarded Date	
					bridge work l	January 17, 2020	January 17, 2020	Letting Date	

Contract Total Pay For Estimate No. 20			
	This Estimate	Previous	To Date
200117-F06			
Total Posted Items Pay	\$0.00	\$3,382,105.07	\$3,382,105.07
Gross Item Adjustments	\$202.17	(\$0.02)	\$202.15
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damage	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
		\$3,382,105.05	\$3,382,307.22
Contract Total Payable This Estimate:	\$202.17		
Items Paid This Estimate Period			

No Data Available

Notice to Proceed Date

Open to Traffic Date Work Began

Date

Contract Adjustments This Estimate

		stments Exist on Contract						
Line item /	<u>Aajusti</u>	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3319	0040	CONCRETE APPROACH PAVEMENT	Material			-920.3	\$75.00	(\$69,022.50)
	0040	CONCRETE APPROACH PAVEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	920.3	\$75.00	\$69,022.50
	0360	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	Retroreflectivity Adjustment	This item adjustment is to pay the retroreflectivity bonus			\$77.76
	0370	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	Retroreflectivity Adjustment	This item adjustment is to pay the retroreflectivity bonus			\$124.41
Total								\$202.17

Page 1 of 19 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					C	ontract Project Information	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J6S3319	FAS S501(60)	Resurface and bridge rehabilitation	A	ST CHARLES	from Route 61 to I-70		
Totals by J	Job Numbe	rs					
J6S3319		d Item Pay Item Adjustm		Item Pay	This Estimate \$0.00 \$202.17 \$202.17	Previous \$3,382,105.07 (\$0.02) \$3,382,105.05	To Date \$3,382,105.07 \$202.15 \$3,382,307.22
	Liquid	tive entive lated Damages Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 2 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3319, Item 5041000, Project Item Line Number 0040, Material Set 504100096, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with a material rep to resolve the exception.	dukesm1	Overridden

Revision 4/1/2020 Page 3 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-F06	J6S3319	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$56,000.00	\$56,000.00
		0001	0020	2063000	CLASS 3 EXCAVATION	12.00	-8.00	4.00	CUYD	4.00	\$75.00	\$300.00
		0001	0030	2153000	SHAPING SLOPES, CLASS III	5.00	0.00	5.00	100F	5.00	\$900.00	\$4,500.00
		0001	0040	5041000	CONCRETE APPROACH PAVEMENT	920.30	0.00	920.30	SQYD	920.30	\$75.00	\$69,022.50
		0001	0050	6094010	DRAIN BASIN	2.00	0.00	2.00	EA	2.00	\$4,400.00	\$8,800.00
		0001	0060	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	7.00	0.00	7.00	CUYD	7.00	\$27.00	\$189.00
		0001	0070	6096041	PLACING TYPE 1 ROCK DITCH LINER	7.00	0.00	7.00	CUYD	7.00	\$105.00	\$735.00
		0001	0080	6116010A	SLOPE PROTECTION	222.00	-110.00	112.00	SQYD	112.00	\$110.00	\$12,320.00
		0001	0090	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	2.00	\$3,010.00	\$6,020.00
		0001	0100	6122020	REPLACEMENT SAND BARREL	3.00	-3.00	0.00	EA	0.00	\$396.00	\$0.00
		0001	0110	6122030	IMPACT ATTENUATOR (RELOCATION)	2.00	0.00	2.00	EA	2.00	\$687.00	\$1,374.00
		0001	0120	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$6,000.00	\$12,000.00
		0001	0130	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL	3,536.00	103.00	3,639.00	SQYD	3,639.00	\$165.00	\$600,435.00
		0001	0140	6131012	DEPTH PAVEMENT REPAIR SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	444.00	-444.00	0.00	SQYD	0.00	\$20.00	\$0.00
		0001	0150	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK)	354.00	-354.00	0.00	SQYD	0.00	\$2.50	\$0.00
			0160	6131014	(PAVEMENT REPAIR) FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER	14,694.00	0.00	14,694.00	LF	14,694.00	\$3.00	\$44,082.00
		0001			AND INTERNAL SAW CUTS)							
		0001	0170	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	4,450.00	0.00	4,450.00	EA	4,450.00	\$5.75	\$25,587.50
		0001	0180	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	28.00	0.00	28.00	EA	28.00	\$3.75	\$105.00
		0001	0190	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	451.00	0.00	451.00	EA	451.00	\$2.45	\$1,104.95
		0001	0200	6139911	MISC.REMOVAL, FURNISHING AND PLACING HOT POLYMER CONCRETE PATCHING FOR CLASS A PARTIAL DEPTH PVMT REPAIR	401,792.00	49,342.00	451,134.00	LB	451,134.00	\$3.35	\$1,511,298.90
		0001	0210	6161005	CONSTRUCTION SIGNS	798.00	0.00	798.00	SQFT	798.00	\$8.00	\$6,384.00
		0001	0220	6161008	ADVANCED WARNING RAIL SYSTEM	22.00	0.00	22.00	EA	22.00	\$35.00	\$770.00
		0001	0230	6161009	FLAG ASSEMBLY	15.00	-15.00	0.00	EA	0.00	\$25.00	\$0.00
		0001	0240	6161025	CHANNELIZER (TRIM LINE)	364.00	0.00	364.00	EA	364.00	\$20.00	\$7,280.00
		0001	0250	6161030	TYPE III MOVEABLE BARRICADE	8.00	-8.00	0.00	EA	0.00	\$100.00	\$0.00
		0001	0260	6161033	DIRECTIONAL INDICATOR BARRICADE	44.00	0.00	44.00	EA	44.00	\$65.00	\$2,860.00
		0001	0270	6161040	FLASHING ARROW PANEL	3.00	0.00	3.00	EA	3.00	\$850.00	\$2,550.00
		0001	0280	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN (CONTRACTOR FURNISHED / RETAINED	2.00	0.00	2.00	EA	2.00	\$2,800.00	\$5,600.00
		0001	0290	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,050.00	0.00	1,050.00	LF	1,050.00	\$21.94	\$23,037.00
		0001	0300	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	1,050.00	0.00	1,050.00	LF	1,050.00	\$7.02	\$7,369.95
		0001	0310	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$168,321.54	\$168,321.54
		0001	0320	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	3.00	0.00	3.00	EA	3.00	\$350.00	\$1,050.00
		0001	0330	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	5,511.00	0.00	5,511.00	LF	5,511.00	\$1.00	\$5,511.00
		0001	0340	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	8,663.00	0.00	8,663.00	LF	8,663.00	\$1.00	\$8,663.00
		0001	0350	6205440A	TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT ARROW	1.00	0.00	1.00	EA	1.00	\$300.00	\$300.00
		0001	0360	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6,220.00	0.00	6,220.00	LF	6,220.00	\$0.25	\$1,555.00
		0001	0370	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	9,952.00	0.00	9,952.00	LF	9,952.00	\$0.25	\$2,488.00
		0001	0380	6207001	PAVEMENT MARKING REMOVAL	25,370.00	0.00	25,370.00	LF	25,370.00	\$0.75	\$19,027.50
		0001	0390	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	5.00	0.00	5.00	EA	5.00	\$100.00	\$500.00
		0001	0400	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$1,500.00	\$1,500.00
		0001	0410	8051000A	SEEDING - COOL SEASON MIXTURES	0.10	-0.10	0.00	ACRE	0.00	\$10,000.00	\$0.00
		0001	0420	8061005	ROCK DITCH CHECK	60.00	-60.00	0.00	LF	0.00	\$50.00	\$0.00
		0001	0430	8061016	SEDIMENT REMOVAL	8.00	-8.00	0.00	CUYD	0.00	\$31.25	\$0.00

Revision 4/1/2020 Page 4 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
200117-F06	J6S3319	0001	0440	8061019	SILT FENCE	405.00	-210.00	195.00	LF	195.00	\$2.26	\$440.70
		0010	0450	6061060	MGS GUARDRAIL	213.00	0.00	213.00	LF	213.00	\$21.00	\$4,473.00
		0010	0460	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	2,650.00	0.00	2,650.00	LF	2,650.00	\$23.00	\$60,950.00
		0010	0470	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	4.00	0.00	4.00	EA	4.00	\$3,000.00	\$12,000.00
		0010	0480	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	1.00	\$1,000.00	\$1,000.00
		0010	0490	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	5.00	0.00	5.00	EA	5.00	\$2,800.00	\$14,000.00
		0070	0500	2161000	SCARIFICATION OF BRIDGE DECK	3,003.00	0.00	3,003.00	SQYD	3,003.00	\$6.67	\$20,030.01
		0070	0510	2161503	REMOVAL OF EXISTING DECK REPAIR	25.00	0.00	25.00	SQFT	25.00	\$71.00	\$1,775.00
		0070	0520	2169903	MISC.Remove and Replace Barrier Curb	10.00	1.00	11.00	LF	11.00	\$350.00	\$3,850.00
		0070	0530	2169904	MISC.Removal of Existing Approach Slab	4,784.00	0.00	4,784.00	SQFT	4,784.00	\$6.00	\$28,704.00
		0070	0540	5031010A	BRIDGE APPROACH SLAB (MAJOR ROAD)	330.00	0.00	330.00	SQYD	330.00	\$275.00	\$90,750.00
		0070	0550	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	3,003.00	0.00	3,003.00	SQYD	3,003.00	\$85.00	\$255,255.00
		0070	0560	7031004	DIAMOND GRINDING	3,003.00	-3,003.00	0.00	SQYD	0.00	\$6.32	\$0.00
		0070	0570	7039902	MISC.Pile Encasement	25.00	0.00	25.00	EA	25.00	\$2,300.00	\$57,500.00
		0070	0580	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	200.00	-195.50	4.50	SQFT	4.50	\$15.00	\$67.50
		0070	0590	7040106	FULL DEPTH REPAIR	200.00	-200.00	0.00	SQFT	0.00	\$40.00	\$0.00
		0070	0600	7040109	TOTAL SURFACE HYDRO DEMOLITION	3,003.00	0.00	3,003.00	SQYD	3,003.00	\$43.00	\$129,129.00
		0070	0610	7040113	CLEANING AND EPOXY COATING	2,116.00	0.00	2,116.00	SQFT	2,116.00	\$15.00	\$31,740.00
		0070	0620	7040117	MONOLITHIC DECK REPAIR	41.00	33.00	74.00	CUYD	74.00	\$700.00	\$51,800.00
	Project J	6S3319 - To	otal Value	Posted to D	late as of Report Generated Date							\$3,382,105.05
200117-F06 Ove	rall - Total	Value Post	ed to Dat	te as of Repo	ort Generated Date							\$3,382,105.05

Revision 4/1/2020 Page 5 of 19



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 6 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																																				
0040	CONCRETE APPROACH PAVEMENT	Material		5	Jun 15, 2020	SYSTEM	(\$34,509.75)																																					
				6	Jul 1, 2020	SYSTEM	(\$34,509.75)																																					
				7	Jul 16, 2020	SYSTEM	(\$69,022.50)																																					
				8	Aug 4, 2020	SYSTEM	(\$69,022.50)																																					
				9	Aug 18, 2020	SYSTEM	(\$69,022.50)																																					
				10	Sep 2, 2020	SYSTEM	(\$69,022.50)																																					
				11	Sep 16, 2020	SYSTEM	(\$69,022.50)																																					
				11	Sep 16, 2020	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dukesm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																																				
				12	Oct 1, 2020	SYSTEM	(\$69,022.50)																																					
				12	Oct 2, 2020	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user dukesm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																																				
				13	Oct 16, 2020	SYSTEM	(\$69,022.50)																																					
				13	Oct 16, 2020	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																																				
				14	Nov 2, 2020	SYSTEM	(\$69,022.50)																																					
				14	Nov 2, 2020	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																																				
				15	Nov 16, 2020	SYSTEM	(\$69,022.50)																																					
				15	Nov 16, 2020	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																																				
				16	Dec 3, 2020	SYSTEM	(\$69,022.50)																																					
				16	Dec 3, 2020	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																																				
				17	Dec 16, 2020	SYSTEM	(\$69,022.50)																																					
				17	Dec 16, 2020	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																																				
				18	Jan 4, 2021	SYSTEM	(\$69,022.50)																																					
				18	Jan 4, 2021	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																																				
				19	Jan 19, 2021	SYSTEM	(\$69,022.50)																																					
																													19	19	18	1	1	15	19	19	19			19	Jan 19, 2021	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				20	Feb 2, 2021	SYSTEM	(\$69,022.50)																																					
				20	Feb 2, 2021	SYSTEM	\$69,022.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user dukesm1																																				

Revision 4/1/2020 Page 7 of 19



Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
0040	CONCRETE APPROACH PAVEMENT	Material	Туре					overridding Payment Estimate Exception 1 on the current
			- Total				(\$345,109.50)	Payment Estimate.
	Material - Total		- I Otal				(\$345,109.50)	
	CONCRETE APPROACH PAVEMENT	MaterialCredit		6	Jul 1,	SYSTEM	\$34,509.75	
					2020		**********	
				7	Jul 16, 2020	SYSTEM	\$34,509.75	
				8	Aug 4, 2020	SYSTEM	\$69,022.50	
				9	Aug 18, 2020	SYSTEM	\$69,022.50	
				10	Sep 2, 2020	SYSTEM	\$69,022.50	
				11	Sep 16, 2020	SYSTEM	\$69,022.50	
			- Total				\$345,109.50	
	MaterialCredit - Total						\$345,109.50	
0040 -	Total						\$0.00	
0050	DRAIN BASIN	Material		11	Sep 16, 2020	SYSTEM	(\$8,800.00)	
				11	Sep 16, 2020	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$8,800.00)	
				12	Oct 2, 2020	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$8,800.00)	
				13	Oct 16, 2020	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0050 -							\$0.00	
0060	FURNISHING TYPE 1 ROCK DITCH LINER	Material		11	Sep 16, 2020	SYSTEM	(\$189.00)	
				11	Sep 16, 2020	SYSTEM	\$189.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$189.00)	
				12	Oct 2, 2020	SYSTEM	\$189.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
0060 -							\$0.00	
0800	SLOPE PROTECTION	Material		8	Aug 4, 2020	SYSTEM	(\$12,320.00)	
				9	Aug 18, 2020	SYSTEM	(\$12,320.00)	
				10	Sep 2, 2020	SYSTEM	(\$12,320.00)	
				11	Sep 16, 2020	SYSTEM	(\$12,320.00)	
				12	Oct 1, 2020	SYSTEM	(\$12,320.00)	

Revision 4/1/2020 Page 8 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
0800	SLOPE PROTECTION	Material		13	Oct 16, 2020	SYSTEM	(\$12,320.00)						
				14	Nov 2, 2020	SYSTEM	(\$12,320.00)						
				15	Nov 16, 2020	SYSTEM	(\$12,320.00)						
				16	Dec 3, 2020	SYSTEM	(\$12,320.00)						
				17	Dec 16, 2020	SYSTEM	(\$12,320.00)						
				18	Jan 4, 2021	SYSTEM	(\$12,320.00)						
				18	Jan 4, 2021	SYSTEM	\$12,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.					
				19	Jan 19, 2021	SYSTEM	(\$12,320.00)						
				19	Jan 19, 2021	SYSTEM	\$12,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 9 on the current Payment Estimate.					
			- Total				(\$123,200.00)						
	Material - Total						(\$123,200.00)						
	SLOPE PROTECTION	MaterialCredit		9	Aug 18, 2020	SYSTEM	\$12,320.00						
				10	Sep 2, 2020	SYSTEM	\$12,320.00						
				11	Sep 16, 2020	SYSTEM	\$12,320.00						
									12	Oct 1, 2020	SYSTEM	\$12,320.00	
													13
				14	Nov 2, 2020	SYSTEM	\$12,320.00						
				15	Nov 16, 2020	SYSTEM	\$12,320.00						
				16	Dec 3, 2020	SYSTEM	\$12,320.00						
				17	Dec 16, 2020	SYSTEM	\$12,320.00						
				18	Jan 4, 2021	SYSTEM	\$12,320.00						
			- Total				\$123,200.00						
0000	MaterialCredit - Total						\$123,200.00						
	- Total	Material		40	0- 6	OVOTTO	\$0.00						
0130	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		10	Sep 2, 2020	SYSTEM	(\$583,440.00)						
				11	Sep 16, 2020	SYSTEM	(\$583,440.00) \$583,440.00	This adjustment effects the original system research of comme					
				11	Sep 16, 2020			This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 21 on the current Payment Estimate.					
				12	Oct 1, 2020	SYSTEM	(\$583,440.00)						
				12	Oct 2, 2020	SYSTEM	\$583,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user dukesm1 overridding Payment Estimate Exception 20 on the current Payment Estimate.					
				13	Oct 16, 2020	SYSTEM	(\$583,440.00)						
				13	Oct 16, 2020	SYSTEM	\$583,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 18 on the current					

Revision 4/1/2020 Page 9 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
0130	FURNISHING AND PLACING CONCRETE	Material	.,,,,,					Payment Estimate.			
	MATERIAL FOR FULL DEPTH PAVEMENT REPAIR			14	Nov 2, 2020	SYSTEM	(\$583,440.00)	,			
				14	Nov 2, 2020	SYSTEM	\$583,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 14 on the current Payment Estimate.			
				15	Nov 16, 2020	SYSTEM	(\$583,440.00)				
				15	Nov 16, 2020	SYSTEM	\$583,440.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.			
				16	Dec 3, 2020	SYSTEM	(\$229,147.88)				
							16	Dec 3, 2020	SYSTEM	\$229,147.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$229,147.88)				
				17	Dec 16, 2020	SYSTEM	\$229,147.88	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.			
			- Total				(\$583,440.00)				
	Material - Total						(\$583,440.00)				
	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	MaterialCredit		11	Sep 16, 2020	SYSTEM	\$583,440.00				
			- Total				\$583,440.00				
	MaterialCredit - Total						\$583,440.00				
0400											
0130 -	Total						\$0.00				
0130 -	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		9	Aug 18, 2020	SYSTEM	\$0.00 (\$9,890.00)				
	DOWEL BAR (DRILLING, FURNISHING	Material		9		SYSTEM SYSTEM					
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material			2020 Sep 2,		(\$9,890.00)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate.			
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10	2020 Sep 2, 2020 Sep 2,	SYSTEM	(\$9,890.00) (\$25,587.50)	Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current			
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10	2020 Sep 2, 2020 Sep 2, 2020 Sep 16,	SYSTEM	(\$9,890.00) (\$25,587.50) \$25,587.50	Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current			
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM	(\$9,890.00) (\$25,587.50) \$25,587.50 (\$25,587.50)	Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 23 on the current			
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Oct 1,	SYSTEM SYSTEM SYSTEM	(\$9,890.00) (\$25,587.50) \$25,587.50 (\$25,587.50) \$25,587.50	Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 23 on the current			
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11 12	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$9,890.00) (\$25,587.50) \$25,587.50 (\$25,587.50) \$25,587.50	Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 22 on the current			
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11 12 12	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2, 2020 Oct 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$9,890.00) (\$25,587.50) \$25,587.50 (\$25,587.50) \$25,587.50 (\$25,587.50)	Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 22 on the current			
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11 11 12 12 13	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2, 2020 Oct 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$9,890.00) (\$25,587.50) \$25,587.50 (\$25,587.50) \$25,587.50 (\$25,587.50) (\$25,587.50)	Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 20 on the current			
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11 11 12 12 13 13 13	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2, 2020 Oct 16, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$9,890.00) (\$25,587.50) \$25,587.50 (\$25,587.50) \$25,587.50 (\$25,587.50) \$25,587.50 (\$25,587.50)	Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 20 on the current			
	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11 11 12 12 13 13 14	2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$9,890.00) (\$25,587.50) \$25,587.50 (\$25,587.50) \$25,587.50 (\$25,587.50) \$25,587.50 (\$25,587.50) \$25,587.50	Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate.			

Revision 4/1/2020 Page 10 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
0170	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material						overridding Payment Estimate Exception 15 on the current Payment Estimate.		
	PAVEMENT REPAIR			16	Dec 3, 2020	SYSTEM	(\$25,587.50)			
				16	Dec 3, 2020	SYSTEM	\$25,587.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.		
				17	Dec 16, 2020	SYSTEM	(\$25,587.50)			
				17	Dec 16, 2020	SYSTEM	\$25,587.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		
							18	Jan 4, 2021	SYSTEM	(\$25,587.50)
				18	Jan 4, 2021	SYSTEM	\$25,587.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.		
				19	Jan 19, 2021	SYSTEM	(\$25,587.50)			
				19	Jan 19, 2021	SYSTEM	\$25,587.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user dukesm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.		
			- Total				(\$9,890.00)			
	Material - Total DOWEL BAR (DRILLING, FURNISHING	MaterialCredit		10	Sep 2,	SYSTEM	(\$9,890.00) \$9,890.00			
	AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Waterlaiorean		10	2020	OTOTEM	ψ0,000.00			
			- Total				\$9,890.00			
	MaterialCredit - Total						\$9,890.00			
0170 -	- Total DOWEL BAR (FURNISHING AND	Material		9	Aug 18,	SYSTEM	\$0.00 (\$45.00)			
0100	INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Widterfal		10	2020 Sep 2,	SYSTEM	, ,			
				10	2020		(\$105.00)			
					10	Sep 2, 2020	SYSTEM	\$105.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	
				11	Sep 16, 2020	SYSTEM	(\$105.00)			
				11	Sep 16, 2020	SYSTEM	\$105.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1		
								overridding Payment Estimate Exception 25 on the current Payment Estimate.		
				12	Oct 1, 2020	SYSTEM	(\$105.00)			
				12		SYSTEM	(\$105.00) \$105.00			
					2020 Oct 2,		, ,	Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 24 on the current		
				12	2020 Oct 2, 2020 Oct 16,	SYSTEM	\$105.00	Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 24 on the current		
				12	2020 Oct 2, 2020 Oct 16, 2020 Oct 16,	SYSTEM	\$105.00 (\$105.00)	Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 22 on the current		
				12 13	2020 Oct 2, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2,	SYSTEM SYSTEM	\$105.00 (\$105.00) \$105.00	Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 22 on the current		
				12 13 13	2020 Oct 2, 2020 Oct 16, 2020 Oct 16, 2020 Nov 2, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM	\$105.00 (\$105.00) \$105.00	Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 18 on the current		

Revision 4/1/2020 Page 11 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0180	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material			2020			Payment Estimate Item Adjustment (0006) due to user dukesm1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				16	Dec 3, 2020	SYSTEM	(\$105.00)	
				16	Dec 3, 2020	SYSTEM	\$105.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				17	Dec 16, 2020	SYSTEM	(\$105.00)	
				17	Dec 16, 2020	SYSTEM	\$105.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
				18	Jan 4, 2021	SYSTEM	(\$105.00)	
				18	Jan 4, 2021	SYSTEM	\$105.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user dukesm1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
				19	Jan 19, 2021	SYSTEM	(\$105.00)	
				19	Jan 19, 2021	SYSTEM	\$105.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user dukesm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				(\$45.00)	
	Material - Total						(\$45.00)	
	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	MaterialCredit		10	Sep 2, 2020	SYSTEM	\$45.00	
			- Total				\$45.00	
	AND A STATE OF THE						C4E 00	
	MaterialCredit - Total						\$45.00	
0180 -	Total						\$45.00	
0180 · 0190	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		9	Aug 18, 2020	SYSTEM		
	Total TIE BAR (DRILLING, FURNISHING AND	Material		9	Aug 18, 2020 Sep 2, 2020	SYSTEM SYSTEM	\$0.00	
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material			2020 Sep 2,		\$0.00 (\$485.10)	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10	2020 Sep 2, 2020 Sep 2,	SYSTEM	\$0.00 (\$485.10) (\$1,104.95)	Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10	2020 Sep 2, 2020 Sep 2, 2020 Sep 16,	SYSTEM SYSTEM	\$0.00 (\$485.10) (\$1,104.95) \$1,104.95	Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16,	SYSTEM SYSTEM SYSTEM	\$0.00 (\$485.10) (\$1,104.95) \$1,104.95	Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 27 on the current
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020	SYSTEM SYSTEM SYSTEM	\$0.00 (\$485.10) (\$1,104.95) \$1,104.95 (\$1,104.95)	Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 27 on the current
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11 11	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$485.10) (\$1,104.95) \$1,104.95 (\$1,104.95)	Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 26 on the current
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11 12 12	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2, 2020 Oct 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$485.10) (\$1,104.95) \$1,104.95 (\$1,104.95) \$1,104.95 \$1,104.95	Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 26 on the current
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11 11 12 12 13	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2, 2020 Oct 16, 2020 Oct 16, 2020	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$485.10) (\$1,104.95) \$1,104.95 (\$1,104.95) \$1,104.95 (\$1,104.95)	Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user dukesm1 overridding Payment Estimate Item Adjustment (0008) due to user dukesm1 overridding Payment Estimate Exception 24 on the current
	Total TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH	Material		10 10 11 11 12 12 13	2020 Sep 2, 2020 Sep 2, 2020 Sep 16, 2020 Oct 1, 2020 Oct 2, 2020 Oct 16, 2020 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$485.10) (\$1,104.95) \$1,104.95 (\$1,104.95) \$1,104.95 (\$1,104.95) \$1,104.95	Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user dukesm1 overridding Payment Estimate Exception 26 on the current Payment Estimate. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user dukesm1 overridding Payment Estimate Item Adjustment (0008) due to user dukesm1 overridding Payment Estimate Exception 24 on the current

Revision 4/1/2020 Page 12 of 19



15 No. 76 275 27	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
10	0190	INSTALLATION) FOR FULL DEPTH	Material	, , , ,	15		SYSTEM	\$1,104.95	Payment Estimate Item Adjustment (0007) due to user dukesm1 overridding Payment Estimate Exception 19 on the current
Peprioric Estimate in Application (2008) disk to user duterant servicing Peyment Estimate Exception 1 do not neutreant servicing Peyment Estimate the negligibility of ordinary the control of perment Estimate the negligibility of ordinary the control of peyment Estimate Internal permental Management (2004) disk to sour duterant servicing Peyment Estimate Internal					16		SYSTEM	(\$1,104.95)	
17					16		SYSTEM	\$1,104.95	Payment Estimate Item Adjustment (0008) due to user dukesm1 overridding Payment Estimate Exception 16 on the current
2000 Poyment Estimate Item Adjustment (0.08) due to user obterning in Poyment Estimate Exception 12 on the current Poyment Cellshable. Poyment Estimate Exception 13 on the current Poyment Estimate Exception 30 on the current Poyment Estimat					17		SYSTEM	(\$1,104.95)	
2021 18					17		SYSTEM	\$1,104.95	Payment Estimate Item Adjustment (0008) due to user dukesm1 overridding Payment Estimate Exception 15 on the current
2021 Payment Estimate Energy Payment Estimate Exception 17 on the ourrent Payment Estimate Esception 17 on the ourrent Payment Estimate Esception 17 on the ourrent Payment Estimate Esception 12 on the ourrent Payment Estimate Esception 13 on the ourrent Payment Estimate Exception 13 on the ourrent Payment Estimate Esception 13 on the ourrent Payment Estimate Esception 13 on					18		SYSTEM	(\$1,104.95)	
2021 19					18		SYSTEM	\$1,104.95	Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 17 on the current
2021 Payment Estimate Item Adjustment (004) due to user dukerant overriding Payment Estimate Exception 12 on the current Payment Estimate Exception 22 on the current Payment Estimate Exception 23 on the current Payment Estimate Item Adjustment for installed Quantity or all province payment estimates Price Adjustments for installed Quantity or all province payment estimates Price Adjustments for installed Quantity or all province payment estimates Price Adjustments for installed Quantity or all province payment estimates Price Adjustments for installed Quantity or all province payment estimates Price Adjustments for installed Quantity or all province payment estimates Price Adjustments for installed Quantity or all province payment estimates Price Adjustments for installed Quantity or all province payment estimates Price Adjustments for installed Quantity or all province payment estimates Price Adjustments for installed Quantity or all province payment estimates Price Adjustment (DR) Quantity or all province payment estimates from Adjustment (DR) Quantity or all province payment estimates from Adjustment (DR) Quantity or all province payment estimate Item Adjustment (DR) Quantity or all province payment estimate Item Adjustment (DR) Quantity or all province payment estimate Item Adjustment (DR) Quantity or all province payment estimate Item Adjustment (DR) Quantity or all province payment estimate Item Adjustment (DR) Quantity or all province payment estimate Item Adjustment (DR) Quantity or all province payment estimate Item Adjustment (DR) Quantity or all province payment estimate Item Adjustment (DR) Quantit					19		SYSTEM	(\$1,104.95)	
Material - Total Tile BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)					19		SYSTEM	\$1,104.95	Payment Estimate Item Adjustment (0004) due to user dukesm1 overridding Payment Estimate Exception 12 on the current
TIE DAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOHNTS) PAVEMEN				- Total				(\$485.10)	
NSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS) -Total \$485.10		Material - Total						(\$485.10)	
Material Credit - Total \$485.10		INSTALLATION) FOR FULL DEPTH	MaterialCredit		10		SYSTEM	\$485.10	
Overrun - Total Overrun -				- Total				\$485.10	
MISC. REMOVAL, FURNISHING AND PLACING HOT POLYMER CONCRETE PATCHING FOR CLASS A PARTIAL DEPTH PVMT REPAIR S		MaterialCredit - Total						\$485.10	
PLACING FOR CLASS A PARTIAL	0190 -	- Total						\$0.00	
DEPTH PVMT REPAIR 9 Aug 18, SYSTEM (\$47,476.20)	0200	PLACING HOT POLYMER CONCRETE	Overrun	Overrun	8		SYSTEM	(\$117,819.50)	
2020 Quantity on all previous payment estimates. Price Adjustments of ',3.35000 - 3.35000, 'is applied (if non-zero). 2020 - Total					9		SYSTEM	(\$47,476.20)	
Overrun - Total S0.00					12		SYSTEM	\$165,295.70	quantity on all previous payment estimates. Price Adjustments
11				Overrun - T	otal			·	
PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW ARROW								· ·	
PAVEMENT MARKING, LEFT/RIGHT ARROW 11 Sep 16, 2020 SYSTEM 21,050.00 This adjustment offsets the original system-generated Overrun Payment Estimate let lem Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 30 on the current Payment Estimate Exception 30 on the current Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 29 on the current Payment Estimate Exception 29 on the current Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 27 on the current Payment Estimate Exception 27 on the current Payment Estimate Exception 27 on the current Payment Estimate So.00 Material - Total So.00									
11	0320	PAVEMENT MARKING, LEFT/RIGHT	Material		11			(\$1,050.00)	
2020 12 Oct 2, 2020 13 Oct 16, 2020 13 Oct 16, 2020 14 SYSTEM \$1,050.00 15 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 29 on the current Payment Estimate. 13 Oct 16, 2020 14 SYSTEM (\$1,050.00) 15 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 27 on the current Payment Estimate. 16 SySTEM \$0.00 17 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 27 on the current Payment Estimate.		, auton			11		SYSTEM	\$1,050.00	Payment Estimate Item Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 30 on the current
Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 29 on the current Payment Estimate. 13					12		SYSTEM	(\$1,050.00)	
2020 13 Oct 16, 2020 13 Oct 16, 2020 14 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 27 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00					12		SYSTEM	\$1,050.00	Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 29 on the current
Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 27 on the current Payment Estimate. - Total \$0.00 Material - Total \$0.00					13		SYSTEM	(\$1,050.00)	
Material - Total \$0.00					13		SYSTEM	\$1,050.00	Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 27 on the current
				- Total				\$0.00	
0320 - Total \$0.00		Material - Total						\$0.00	
	0220	- Total						\$0.00	

Revision 4/1/2020 Page 13 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0330	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		3	May 18, 2020	SYSTEM	(\$2,591.00)	
			- Total				(\$2,591.00)	
	Material - Total						(\$2,591.00)	
	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	MaterialCredit		4	Jun 2, 2020	SYSTEM	\$2,591.00	
			- Total				\$2,591.00	
	MaterialCredit - Total						\$2,591.00	
0330 -	Total						\$0.00	
0340	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material		3	May 18, 2020	SYSTEM	(\$4,163.00)	
			- Total				(\$4,163.00)	
	Material - Total						(\$4,163.00)	
	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	MaterialCredit		4	Jun 2, 2020	SYSTEM	\$4,163.00	
			- Total				\$4,163.00	
	MaterialCredit - Total						\$4,163.00	
0340 -	Total						\$0.00	
0350	TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT ARROW	Material		3	May 18, 2020	SYSTEM	(\$300.00)	
			- Total				(\$300.00)	
	Material - Total						(\$300.00)	
	TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT ARROW	MaterialCredit		4	Jun 2, 2020	SYSTEM	\$300.00	
			- Total				\$300.00	
	MaterialCredit - Total						\$300.00	
0350 -	Total						\$0.00	
0360	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Material		11	Sep 16, 2020	SYSTEM	(\$1,555.00)	
	BENDO			11	Sep 16, 2020	SYSTEM	\$1,555.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user dukesm1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$1,555.00)	
				12	Oct 2, 2020	SYSTEM	\$1,555.00	This adjustment offsets the original system-generated Overrun Payment Estimate Ilem Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
			- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	REFL	15	Nov 16, 2020	dukesm1	\$77.75	This item adjustment is to pay a bonus for the Retroreflectivity results.
	BEADS			18	Jan 4, 2021	dukesm1	(\$77.76)	
				20	Feb 2, 2021	dukesm1	\$77.76	This item adjustment is to pay the retroreflectivity bonus
			REFL - Tota	ı			\$77.75	
	Other Item Adjustment - Total						\$77.75	
0360 -							\$77.75	
0370	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT. TYPE P BEADS	Material		11	Sep 16, 2020	SYSTEM	(\$2,488.00)	
	PAINT, TYPE P BEADS			11	Sep 16, 2020	SYSTEM	\$2,488.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user dukesm1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$2,488.00)	
				12	Oct 2, 2020	SYSTEM	\$2,488.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user dukesm1 overridding Payment Estimate Exception 32 on the current Payment Estimate.

Revision 4/1/2020 Page 14 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0370		Material	- Total				\$0.00	
	Material - Total						\$0.00	
	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING	Other Item Adjustment	REFL	15	Nov 16, 2020	dukesm1	\$124.40	This item adjustment is to pay a bonus for the Retroreflectivity results.
	PAINT, TYPE P BEADS			18	Jan 4, 2021	dukesm1	(\$124.41)	
				20	Feb 2, 2021	dukesm1	\$124.41	This item adjustment is to pay the retroreflectivity bonus
			REFL - Tota	ı			\$124.40	
	Other Item Adjustment - Total						\$124.40	
0370 -							\$124.40	
0410	SEEDING - COOL SEASON MIXTURES	Material		11	Sep 16, 2020	SYSTEM	(\$200.00)	
				12	Oct 1, 2020	SYSTEM	(\$200.00)	
				13	Oct 16, 2020	SYSTEM	(\$200.00)	
				14	Nov 2, 2020	SYSTEM	(\$200.00)	
			- Total	10	2020	SISIEM	(\$200.00)	
	Material - Total		Total				(\$1,000.00)	
	SEEDING - COOL SEASON MIXTURES	MaterialCredit		12	Oct 1, 2020	SYSTEM	\$200.00	
				13	Oct 16, 2020	SYSTEM	\$200.00	
				14	Nov 2, 2020	SYSTEM	\$200.00	
				15	Nov 16, 2020	SYSTEM	\$200.00	
				16	Dec 3, 2020	SYSTEM	\$200.00	
	44 · 1 · 10 · 10 · 17 · 1		- Total				\$1,000.00	
0410 -	MaterialCredit - Total						\$1,000.00	
0410		Material		11	Sep 16, 2020	SYSTEM	\$0.00 (\$214.70)	
				12	Oct 1, 2020	SYSTEM	(\$214.70)	
				13	Oct 16, 2020	SYSTEM	(\$214.70)	
				14	Nov 2, 2020	SYSTEM	(\$214.70)	
				15	Nov 16, 2020	SYSTEM	(\$214.70)	
				17	Dec 16, 2020	SYSTEM	(\$440.70)	
				17	Dec 16, 2020	SYSTEM	\$440.70	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user dukesm1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
			- Total				(\$1,073.50)	
	Material - Total						(\$1,073.50)	
	SILT FENCE	MaterialCredit		12	Oct 1, 2020	SYSTEM	\$214.70	
				13	Oct 16, 2020	SYSTEM	\$214.70	
				14	Nov 2, 2020	SYSTEM	\$214.70	
				15	Nov 16, 2020	SYSTEM	\$214.70	

Revision 4/1/2020 Page 15 of 19



Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	·	Туре	Adjustment Type	Number	Date	Ву		
0440	SILT FENCE	MaterialCredit		16	Dec 3, 2020	SYSTEM	\$214.70	
			- Total				\$1,073.50	
	MaterialCredit - Total						\$1,073.50	
0440 -	Total						\$0.00	
0450	MGS GUARDRAIL	Construction Stockpile		2	May 4, 2020	SYSTEM	\$2,270.58	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Aug 4, 2020	SYSTEM	(\$2,270.58)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0450 -	Total						\$0.00	
0460	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Construction Stockpile		2	May 4, 2020	SYSTEM	\$33,204.50	Payment Estimate Item Adjustment generated Stockpile Transaction
				5	Jun 15, 2020	SYSTEM	(\$11,602.78)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Jul 16, 2020	SYSTEM	(\$20,048.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Aug 4, 2020	SYSTEM	(\$1,553.72)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0460 -	Total						\$0.00	
0470	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	Construction Stockpile		2	May 4, 2020	SYSTEM	\$6,200.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				5	Jun 15, 2020	SYSTEM	(\$3,100.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Jul 16, 2020	SYSTEM	(\$3,100.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0470 -	Total						\$0.00	
0480	MGS END ANCHOR	Construction Stockpile		2	May 4, 2020	SYSTEM	\$535.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				7	Jul 16, 2020	SYSTEM	(\$535.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0480 -	Total						\$0.00	
0490	TYPE A CRASHWORTHY END TERMINAL (MASH)	Construction Stockpile		2	May 4, 2020	SYSTEM	\$7,550.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				5	Jun 15, 2020	SYSTEM	(\$1,510.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				8	Aug 4, 2020	SYSTEM	(\$6,040.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$0.00	
	Construction Stockpile - Total						\$0.00	
0490 -	Total						\$0.00	
0520	MISC. Remove and Replace Barrier Curb	Overrun	Overrun	4	Jun 2, 2020	SYSTEM	(\$350.00)	
				4	Jun 2, 2020	SYSTEM	\$350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user dukesm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				5	Jun 15, 2020	SYSTEM	(\$350.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				12	Oct 1, 2020	SYSTEM	\$350.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',350.00000 - 350.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	

Revision 4/1/2020 Page 16 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
0520 -	Total						\$0.00					
0540	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		5	Jun 15, 2020	SYSTEM	(\$45,375.00)					
				6	Jul 1, 2020	SYSTEM	(\$45,375.00)					
				7	Jul 16, 2020	SYSTEM	(\$90,750.00)					
				8	Aug 4, 2020	SYSTEM	(\$90,750.00)					
				9	Aug 18, 2020	SYSTEM	(\$90,750.00)					
				10	Sep 2, 2020	SYSTEM	(\$90,750.00)					
				10	Sep 2, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.				
				11	Sep 16, 2020	SYSTEM	(\$90,750.00)					
				11	Sep 16, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
				12	Oct 1, 2020	SYSTEM	(\$90,750.00)					
				12	Oct 2, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
				13	Oct 16, 2020	SYSTEM	(\$90,750.00)					
				13	Oct 16, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
						14	Nov 2, 2020	SYSTEM	(\$90,750.00)			
				14	Nov 2, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
				15	Nov 16, 2020	SYSTEM	(\$90,750.00)					
				15	Nov 16, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
								16	Dec 3, 2020	SYSTEM	(\$90,750.00)	
							16	Dec 3, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
				17	Dec 16, 2020	SYSTEM	(\$90,750.00)					
					17	Dec 16, 2020	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
				18	Jan 4, 2021	SYSTEM	(\$90,750.00)					
					18	Jan 4, 2021	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
				19	Jan 19, 2021	SYSTEM	(\$90,750.00)					
				19	Jan 19, 2021	SYSTEM	\$90,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user dukesm1 overridding Payment Estimate Exception 2 on the current				

Revision 4/1/2020 Page 17 of 19



Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0540	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material						Payment Estimate.
			- Total				(\$363,000.00)	
	Material - Total						(\$363,000.00)	
	BRIDGE APPROACH SLAB (MAJOR ROAD)	MaterialCredit		6	Jul 1, 2020	SYSTEM	\$45,375.00	
				7	Jul 16, 2020	SYSTEM	\$45,375.00	
				8	Aug 4, 2020	SYSTEM	\$90,750.00	
				9	Aug 18, 2020	SYSTEM	\$90,750.00	
				10	Sep 2, 2020	SYSTEM	\$90,750.00	
	Metaric Condit. Total		- Total				\$363,000.00	
0540	MaterialCredit - Total						\$363,000.00	
0540 -		Material		4	lun 2	QVCTFAA	\$0.00	
0550	LATEX MODIFIED CONCRETE WEARING SURFACE	iviaterial		5	Jun 2, 2020 Jun 15,	SYSTEM	(\$127,627.50) (\$127,627.50)	
				3	2020	STSTEM	(φ121,021.30)	
				6	Jul 1, 2020	SYSTEM	(\$255,255.00)	
				7	Jul 16, 2020	SYSTEM	(\$102,101.83)	
				8	Aug 4, 2020	SYSTEM	(\$102,101.83)	
				8	Aug 4, 2020	SYSTEM	\$102,101.83	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user dukesm1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
				9	Aug 18, 2020	SYSTEM	(\$102,101.83)	
				9	Aug 18, 2020	SYSTEM	\$102,101.83	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user brookw1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
				10	Sep 2, 2020	SYSTEM	(\$102,101.83)	
				10	Sep 2, 2020	SYSTEM	\$102,101.83	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				11	Sep 16, 2020	SYSTEM	(\$102,101.83)	
				11	Sep 16, 2020	SYSTEM	\$102,101.83	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user dukesm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
				12	Oct 1, 2020	SYSTEM	(\$102,101.83)	
				12	Oct 2, 2020	SYSTEM	\$102,101.83	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user dukesm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
				13	Oct 16, 2020	SYSTEM	(\$102,101.83)	
				13	Oct 16, 2020	SYSTEM	\$102,101.83	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user dukesm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
			- Total				(\$612,611.83)	
	Material - Total						(\$612,611.83)	
	LATEX MODIFIED CONCRETE WEARING SURFACE	MaterialCredit		5	Jun 15, 2020	SYSTEM	\$127,627.50	
				6	Jul 1,	SYSTEM	\$127,627.50	

Revision 4/1/2020 Page 18 of 19



Lina	Description	A diverture and	Other	Fet.	Created	Cuantad	Amazumt	Damanka
Line	Description	Adjustment Type	Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
0550	LATEX MODIFIED CONCRETE WEARING	MaterialCredit			2020			
	SURFACE			7	Jul 16, 2020	SYSTEM	\$255,255.00	
				8	Aug 4, 2020	SYSTEM	\$102,101.83	
			- Total				\$612,611.83	
	MaterialCredit - Total						\$612,611.83	
0550 -	Total						\$0.00	
0580	SUBSTRUCTURE REPAIR (UNFORMED)	Material		11	Sep 16, 2020	SYSTEM	(\$67.50)	
			- Total				(\$67.50)	
	Material - Total						(\$67.50)	
	SUBSTRUCTURE REPAIR (UNFORMED)	MaterialCredit		12	Oct 1, 2020	SYSTEM	\$67.50	
			- Total				\$67.50	
	MaterialCredit - Total						\$67.50	
0580 -	Total						\$0.00	
0610	CLEANING AND EPOXY COATING	Material		11	Sep 16, 2020	SYSTEM	(\$31,740.00)	
				12	Oct 1, 2020	SYSTEM	(\$31,740.00)	
				13	Oct 16, 2020	SYSTEM	(\$31,740.00)	
				14	Nov 2, 2020	SYSTEM	(\$31,740.00)	
				15	Nov 16, 2020	SYSTEM	(\$31,740.00)	
				16	Dec 3, 2020	SYSTEM	(\$31,740.00)	
				16	Dec 3, 2020	SYSTEM	\$31,740.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) due to user dukesm1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
			- Total				(\$158,700.00)	
	Material - Total						(\$158,700.00)	
	CLEANING AND EPOXY COATING	MaterialCredit		12	Oct 1, 2020	SYSTEM	\$31,740.00	
				13	Oct 16, 2020	SYSTEM	\$31,740.00	
				14	Nov 2, 2020	SYSTEM	\$31,740.00	
				15	Nov 16, 2020	SYSTEM	\$31,740.00	
				16	Dec 3, 2020	SYSTEM	\$31,740.00	
			- Total				\$158,700.00	
	MaterialCredit - Total						\$158,700.00	
0610 -							\$0.00	
0620	MONOLITHIC DECK REPAIR	Overrun	Overrun		Aug 4, 2020	SYSTEM	(\$23,100.00)	
				11	Sep 16, 2020	SYSTEM	\$23,100.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',700.00000 - 700.00000, 'is applied (if non-zero).
			Overrun - T	otal			\$0.00	
	Overrun - Total						\$0.00	
0620 -	Total						\$0.00	
Overa	II - Total				\$202.15			

Revision 4/1/2020 Page 19 of 19